MOVE YOUR ENVIRONMENT FORWARD

PHASE I ENVIRONMENTAL SITE ASSESSMENT REPORT

STONE ACADEMY
745 Burnside Avenue
East Hartford, CT 06108

Prepared For:

Town of East Hartford
c/o Carlene Shaw
720 Main Street
East Hartford, CT 06108

Prepared By:

HRP Associates, Inc.
197 Scott Swamp Road
Farmington, CT 06032

HRP# COL4100.P2

Issued On: February 25, 2026

TABLE OF CONTENTS

1.0 EXECUTIVE SUMMARY 1

2.0 INTRODUCTION 4

2.1 Purpose 4
2.2 Definitions 4
2.3 Scope of Services 5
2.4 Significant Assumptions 5
2.5 Limitations and Exceptions 5
2.6 User Reliance 6
2.7 Phase I Environmental Site Assessment Continued Viability 6

3.0 SUBJECT PROPERTY AND AREA DESCRIPTION 8

3.1 Legal Description and Ownership 8
3.2 Description of Improvements 8
3.3 Utilities 9
3.4 Physical Setting 9
3.4.1 Geological Characteristics 9
3.4.2 Hydrogeological Characteristics 9
3.4.3 Topographic Characteristics 10
3.4.4 Other Physical Setting Information 10
3.5 Site Reconnaissance 10
3.5.1 Methodology and Limiting Conditions 10
3.5.2 Current and Past Uses of the Subject Property 11
3.5.3 Raw Material Storage and Handling 11
3.5.4 Waste Generation and Handling 11
3.5.5 Current and Past Uses of Adjoining and Surrounding Properties 11
3.5.6 Exterior Observations 11
3.5.7 Interior Observations 12
3.5.8 Storage Tank Summary 12
3.6 American Society for Testing and Materials Non-Scope Considerations 13

4.0 USER PROVIDED INFORMATION 15

5.0 ENVIRONMENTAL RECORDS REVIEW 17

5.1 Environmental Database Records 17
5.2 Regulatory Agency File and Records Review 20
5.3 Previous Environmental Investigations 21
5.4 Other Environmental Record Sources 21

6.0 HISTORICAL RECORDS REVIEW 22

6.1 Aerial Photographs 22
6.2 Topographic Maps 23
6.3 Sanborn Fire Insurance Maps 24
6.4 City Directories 25

6.5 Summary of Historical Records Review 27
6.6 Other Historical Sources Reviewed 27

7.0 INTERVIEWS 28

8.0 DATA GAPS 29

9.0 FINDINGS AND OPINIONS 31

10.0 CONCLUSIONS 32

11.0 REFERENCES 34

Figures

Figure 1 Subject Property Location
Figure 2 Site Plan

Appendices

Appendix A Subject Property Photographs
Appendix B User Questionnaire
Appendix C Recorded Land Title Records
Appendix D Regulatory Database Record Search
Appendix E Supporting Documentation
Appendix F Aerial Photographs
Appendix G Topographic Maps
Appendix H Sanborn Fire Insurance Maps
Appendix I City Directories
Appendix J Qualifications of Assessors

GENERAL INFORMATION

Subject Property Information:
Stone Academy
745 Burnside Avenue
East Hartford, CT 06108

Access Contact:
Carlene Shaw, Town Planner

Client Information:
Town of East Hartford
720 Main Street
East Hartford, CT 06108

Consultant Information:
HRP Associates, Inc.
197 Scott Swamp Road
Farmington, CT 06032
www.hrpassociates.com
Phone: (860) 674-9570
Fax: (860) 674-9624
Project Number: COL4100.P2

Inspection Date: December 23, 2025
Report Date: February 25, 2026

Report Author: Joy Waters
Project Consultant

Report Author: A. Sasha Isenberg
Senior Consultant

Client Manager: Cassy George
Project Manager

Environmental Professional Certification

I declare that, to the best of my professional knowledge and belief, I meet the definition of Environmental Professional as defined in 40 CFR Part 312.10.

I have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the subject property. I have developed and performed the all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR Part 312.

Jason A. Beach, NY PG, CPG, LEP
Principal & Regional Office Manger

1.0 EXECUTIVE SUMMARY

HRP Associates, Inc. (HRP) has completed a Phase I Environmental Site Assessment (ESA) of Stone Academy located 745 Burnside Avenue in East Hartford, Connecticut (herein referred to as the "Subject Property"). HRP completed this assessment in conformance with the scope and limitations of American Society for Testing and Materials (ASTM) *Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process E1527-21*. In addition, this report is consistent with the form and content recommended for a Phase I ESA described in the Connecticut Department of Energy and Environmental Protection's (CT DEEP) Site Characterization Guidance Document (SCGD), dated September 2007 (rev. December 2010).

Findings

The following is a summary of the key findings of this assessment:

- The 2.45-acre Subject Property consists of a single parcel identified by the East Hartford Tax Assessor as Map 47, Lot 65. The property is improved with two buildings connected by a covered walkway. The northern building is a two-story, 4,481-square-foot office building (formerly residential) with a full basement, constructed around 1909. The southern building is a two-story, slab-on-grade structure totaling approximately 12,768 square feet, constructed in 1988. Parking areas are located to the west and south of the buildings; the remainder of the property consists of a manicured lawn and landscaped areas. The Subject Property is serviced by public water, public sewer, and natural gas.
- The Subject Property is currently vacant, and no waste generation occurs onsite. Access to the building interiors was not provided; therefore, it is unknown whether any petroleum products and/or hazardous substances are stored within the buildings.
- Prior to 1988, the Subject Property was used for residential purposes since at least 1909 and contained one residence and two outbuildings. In 1988, the outbuildings were demolished and a commercial classroom building was constructed on the site. Since that time, the Subject Property has been used as an educational facility and has, over the years, housed a daycare center, Goodwin College, and Stone Academy. Stone Academy ceased operations in February 2023, and the property has remained vacant since.
- Based on the limited available information, one tank is currently located at the Subject Property. An underground storage tank (UST) on the southwestern side of the northern building, positioned between two air-conditioning units, was abandoned in place in 2020. One soil sample collected from beneath the tank was analyzed for extractable total petroleum hydrocarbons (ETPH), polycyclic aromatic hydrocarbons (PAHs), and volatile organic compounds (VOCs), and no constituents were detected above laboratory reporting limits. No additional details, such as the tank's content, size, age, or condition, were available in the records.
- Fill and vent pipes likely associated with an aboveground tank were observed on the southeastern side of the northern building. Based on this observation, there is a possibility that a storage tank is located in the basement of that building.
- The Subject Property is not listed in any of the environmental databases or CT DEEP records.

Conclusions

This assessment has revealed the following recognized environmental conditions (RECs) in connection with the Subject Property.

- REC-1: Abandoned UST

  A UST reportedly abandoned in place in 2020 is located on the southwestern side of the northern building. A limited subsurface investigation was conducted, consisting of one soil sample collected from beneath the tank and analyzed for ETPH, PAHs, and VOCs. No analytes were detected above laboratory reporting limits. No additional information regarding the UST, such as size, age, construction, or condition, was available in the reviewed records. Due to the incomplete characterization of the tank and its potential for having impacted subsurface media, this condition is considered a REC.

The following areas of concern (AOCs) were identified at the Subject Property during this investigation. These AOCs may not meet the ASTM definition of a REC but are considered potential environmental issues associated with the Subject Property as outlined in CT DEEP's SCGD.

- AOC-1: Potential Tank in Basement

  Fill and vent pipes typically associated with an oil storage tank were observed on the southeastern side of the northern building. This observation suggests the potential presence of an oil tank within the building's basement. Due to the possibility of a release from such a tank and the lack of confirmation regarding its presence, size, age, or condition, this is considered an AOC.

- AOC-2: Electrical Transformer

  A pad-mounted electrical transformer was observed on the western side of Subject Property. The transformer had a sticker indicating that the transformer contained dielectric oil with less than two parts per million (2 ppm) of polychlorinated biphenyls (PCBs). No obvious staining was observed on and/or beneath the transformer. Due to the potential for a release, this location is considered an AOC.

- AOC-3: Historical Outbuildings

  An outbuilding and a garage building that occupied the Subject Property from the early twentieth century until redevelopment in 1988 represent an AOC. It is unclear whether these structures were properly demolished, raising the concern that remnants such as hazardous materials, drums, or USTs could remain buried onsite. Additionally, historical garage uses may have involved storage or use of petroleum products, solvents, and other chemicals commonly associated with vehicle maintenance.

This assessment has revealed the following significant data gaps in connection with the Subject Property:

- Access to the interior of the buildings was not granted; therefore, an inspection of the building interiors could not be performed.
- The presence of snow on the ground prevented thorough observation of the site conditions.

This assessment has revealed no controlled recognized environmental conditions (CRECs), historical recognized environmental conditions (HRECs), and/or de minimis conditions in connection with the Subject Property.

In HRP's opinion, no information was found to suggest that the Subject Property or business operating on the property meets the definition of an "establishment" pursuant to Connecticut's "Transfer Act" (Connecticut General Statutes (CGS) 22a-134). This opinion should be confirmed by counsel prior to any qualifying transfer of ownership of the property or business.

Based on reviewed available information, it is HRP's opinion that additional investigation is warranted to evaluate the presence of hazardous substances and/or petroleum products in the environment as a result of the AOCs identified in this assessment and detailed above.

2.0 INTRODUCTION

2.1 Purpose

This assessment was prepared for the Town of East Hartford (the "User") in conformance with the scope and limitations of ASTM Standard Practice E1527-21. The U.S. Environmental Protection Agency (EPA) has published a direct Final Rule adopting ASTM Practice E1527-21 as a standard satisfying the "all appropriate inquiries" (AAI) requirements for landowner liability protections (LLPs) under the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 (CERCLA) as specified in the Code of Federal Regulations (CFR), 40 CFR Part 312, *Standards and Practices for All Appropriate Inquiries*. These include the innocent landowner, contiguous property owner, and bona fide prospective purchaser liability defenses. In addition, this report is consistent with the form and content recommended for a Phase I ESA described in CT DEEP's SCGD, dated September 2007 (rev. December 2010).

2.2 Definitions

ASTM Practice E1527-21 establishes that the goal of the Phase I ESA process is to identify recognized environmental conditions in connection with the Subject Property. This, and other related terms utilized throughout this report, are defined by ASTM Practice E1527-21 as listed below.

A recognized environmental condition (REC) is defined as: 1) the presence of hazardous substances or petroleum products in, on, or at the Subject Property due to a release to the environment; 2) the likely presence of hazardous substances or petroleum products in, on, or at the Subject Property due to a release or likely release to the environment; or 3) the presence of hazardous substances or petroleum products in, on, or at the Subject Property under conditions that pose a material threat of a future release to the environment.

A controlled recognized environmental condition (CREC) is defined as a REC affecting the Subject Property that has been addressed to the satisfaction of the applicable regulatory authority or authorities, with hazardous substances or petroleum products allowed to remain in place subject to implementation of required controls (for example, activity and use limitations (AULs) or other property use limitations).

A historical recognized environmental condition (HREC) is defined as a previous release of hazardous substances or petroleum products affecting the Subject Property that has been addressed to the satisfaction of the applicable regulatory authority or authorities, and meeting unrestricted use criteria established by the applicable regulatory authority or authorities without subjecting the Subject Property to any controls (for example, AULs or other property use limitations).

A de minimis condition is defined as a condition related to a release that generally does not present a threat to human health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies.

A data gap is defined as a lack of or inability to obtain information required by this practice despite good faith efforts by the environmental professional to gather such information. A significant data

gap is defined as a data gap that affects the ability of the environmental professional to identify a REC.

As requested, this document also conforms to the guidance contained in CT DEEP's SCGD, which defines an area of concern (AOC) as locations or areas at a Subject Property where hazardous waste and/or hazardous substances (including petroleum products) have been or may have been used, stored, treated, handled, disposed, spilled, and/or released to environment.

2.3 Scope of Services

In conformance with ASTM Practice E1527-21, the scope of services for this assessment included the following components:

- A review of practically reviewable and reasonably ascertainable records from standard environmental sources and other environmental records. Records that may be reviewed as part of this assessment include state, municipal, and federal regulatory agency record sources, standard historical records, recorded land title records, previous environmental reports, and other sources as applicable.
- A site reconnaissance.
- Interviews with the present and/or past owners, operators, and occupants as available, as well as state and local government officials and others familiar with the Subject Property, as necessary.
- Evaluation and report preparation.

2.4 Significant Assumptions

No significant assumptions were made during completion of this assessment other than the normal reliance on the validity and/or accuracy of the information obtained from various sources pursuant to ASTM Practice E1527-21.

2.5 Limitations and Exceptions

All work conducted by HRP in connection with the performance of this Phase I ESA, all work performed under the Terms and Conditions as outlined in the Project Agreement for Subconsultant Services ("Agreement") Community Economic Development (CED), Project Number 25003308A dated July 11, 2025, and any follow-up work is subject to the following limitations:

- The observations described in this report are made under the stated conditions. The findings, opinions, and conclusions presented in the report are based solely upon the indicated services, and not on scientific tasks or procedures beyond the scope of the described services, including those identified in **Section 2.3**.
- In preparing Project Reports, HRP relies on certain information provided by state and local officials, and information and representations made by other parties referenced therein, and on reasonably ascertainable and practically reviewable information contained in the files and records of state, federal, and local agencies made available to HRP at the time of the Phase I ESA. To the extent that such files or records are missing, incomplete, or

were not provided to HRP, we are not responsible. Although there may be some degree of overlap in the information provided by these various sources, HRP did not attempt to independently verify the accuracy or completeness of all information reviewed or provided during the course of this Phase I ESA.

- A subsurface investigation of the Subject Property was not completed as part of this Phase I ESA. As such, the geological and hydrogeological characteristics of the Subject Property are based solely on available documentation and information, including published sources pertaining to the area of the Subject Property. The information from these sources may vary from actual site-specific conditions. Actual data pertaining to the subsurface characteristics of the Subject Property can only be obtained through a subsurface investigation.

2.6 User Reliance

This report has been prepared by the staff of HRP for the User under the professional supervision of the environmental professional whose signature appears herein. Neither HRP, nor any staff member assigned to this investigation has any interest or contemplated interest, financial or otherwise, in the subject or surrounding properties, or in any entity which owns, leases, or occupies the subject or surrounding properties or which may be responsible for environmental issues identified during the course of this investigation, and has no personal bias with respect to the parties involved.

The information contained in this report has received appropriate technical review and approval. The opinions and conclusions represent professional judgments and are founded upon the findings of the investigations identified in the report and the interpretation of such data based on our experience and expertise according to the existing standard of care. No other warranty or limitation exists, either expressed or implied.

The investigation was prepared in conformance with the ASTM Practice E1527-21 Phase I ESA scope of work for the use and benefit of the User. It is based, in part, upon documents, writings, and information owned, possessed, or secured by the User. Neither this report, nor any information contained herein shall be used or relied upon for any purpose by any other person or entity without the express written permission of HRP.

2.7 Phase I Environmental Site Assessment Continued Viability

This Phase I ESA report is presumed to be viable if the report was completed no more than 180 days prior to the date of property acquisition or other transaction, or up to one year if the following components have been updated:

Phase I ESA Component	Source	Date Completed
Visual Inspection of the Subject Property and Adjoining Properties	A. Sasha Isenberg	December 23, 2025
Interviews with Owners, Operators, and Occupants	Not available for interview	n/a
Government Records Review	Environmental Database Resources, Inc. (EDR) Radius Report	October 20, 2025

Phase I ESA Component	Source	Date Completed
Environmental Liens or Activity Use Limitations Search	Not Provided by The User	Not Provided by User
Environmental Professional Certification	Jason A. Beach, NY PG, CPG, LEP	February 20, 2026

3.0 SUBJECT PROPERTY AND AREA DESCRIPTION

HRP has completed a Phase I ESA of the Stone Academy located at 745 Burnside Avenue in East Hartford, Connecticut. The Subject Property is further defined below and depicted on **Figure 1** (Subject Property Location) and **Figure 2** (Site Plan).

The following Subject Property and area description is based on HRP's observations, interviews with knowledgeable parties, research conducted at pertinent state and local offices, and information provided by the User. Topographic, geologic and hydrogeologic information is based on HRP's review of the sources listed herein.

3.1 Legal Description and Ownership

Current and Former Subject Property Address(es)	745 Burnside Avenue
Current Subject Property Owner	Burnside Gardens LLC
Date of Ownership	1/22/2024
Parcel ID No.	Map 47, Lot 65 (Alternative ID: 630-745)
Parcel Area and Shape	2.45 acres and rectangular
Zoning	R-4 – Single-family and two-family district
Latitude/Longitude	41.7792000/ 72.6066850

3.2 Description of Improvements

Building(s)	Northern Building – A two-story office building totaling approximately 4,481 square feet, with a full basement, and a footprint of about 1,798 square feet. Constructed around 1909, the building is primarily made of wood and concrete blocks and features a gable roof finished with asphalt shingles. Southern Building – A two-story building totaling approximately 12,768 square feet, with a footprint of about 7,746 square feet. Constructed around 1988, the building is primarily made of wood and stucco/masonry and features a gable roof finished with asphalt shingles and is built on a slab foundation.
Roads	Burnside Avenue adjoins the Subject Property from the north; Scotland Road adjoins the Subject Property to the west. An unnamed road off of Scotland Road provides access to the Subject Property.
Parking Areas	Parking areas are located to the west of the northern building and to the southern building.
Ancillary Structures	A covered walkway connects the two buildings.

3.3 Utilities

Potable Water Source	Public water is provided by Metropolitan District (MDC).
Sanitary Sewage Disposal	The Subject Property is connected to the municipal sanitary sewer.
Electricity	Electricity is provided to the Subject Property by Eversource.
Heat Type and Provider	Natural gas is provided by Connecticut Natural Gas (CNG).
Solid Waste Disposal	No waste is currently generated at the Subject Property.
Other Pertinent Features	A pad-mounted electrical transformer is located west of the onsite buildings. A "2 ppm non-PCB" sticker was observed. No staining was observed on or around the unit.

3.4 Physical Setting

3.4.1 Geological Characteristics

Soils	Windsor – moderately decomposed plant material and loamy sands.
Surficial Geology	Windsor – Sand overlying fines.
Bedrock Geology	Portland Arkose – reddish-brown arkose (brownstone), Newark Terrane / Hartford and Pomperaug Mesozoic Basins (Rodgers, 1985).
Bedrock Outcrops	Bedrock outcrops were not observed on the Subject Property.

3.4.2 Hydrogeological Characteristics

Groundwater Classification	Groundwater at the Subject Property is classified as GA. GA – Groundwater within the area of existing private water supply wells or an area with the potential to provide water to public or private supply wells. The DEEP presumes that groundwater in such an area is, at a minimum, suitable for drinking or other domestic uses without treatment.
Estimated Depth to Groundwater	0-15 feet below ground surface (ft bgs), based on the monitoring well data in the area.
Inferred Groundwater Flow Direction	South-southwest, based on proximity to the Hockanum River.
Nearest Known Water Supply Well	The nearest known private well is Bohemian Society of Lodge Pola, located approximately 0.3 miles northwest of the Subject Property. The nearest known monitoring well is U.S. Geological Survey (USGS) monitoring well CT-EH 22, located approximately 0.2 miles southwest of the Subject Property.

*The flow direction and depth to groundwater may vary depending upon seasonal variations in precipitation and other hydrogeological factors. Without the benefit of onsite groundwater monitoring wells surveyed to a datum, groundwater depth and flow direction on the Subject Property cannot be conclusively determined.

3.4.3 Topographic Characteristics

Topographic Map	Manchester, CT 2021 Hartford North, CT 2021
Approximate Elevation	75 feet above sea level.
Slope	Topography on the Subject Property slopes to the west-southwest; regional topography slopes generally to the southwest.

A topographic map of the Subject Property and surrounding area is included as **Figure 1**.

3.4.4 Other Physical Setting Information

FEMA Flood Zone	The Subject Property does not appear to be located within the 100-year or 500-year Federal Emergency Management Agency (FEMA) flood zones.
Wetland Inventory Listing	The Subject Property does not appear to be mapped as having designated National Wetland Inventory (NWI) wetland areas.
Suspected Wetlands	Suspected wetlands were not observed on the Subject Property.
Surface Water Bodies Onsite	Surface water bodies were not observed on the Subject Property.
Nearest Surface Water Body	The Hockanum River and Hockanum River Reservoir are located approximately 765 feet to the south of the Subject Property.
Surface Water Classification	The nearest surface water body to the Subject Property, the Hockanum River, is classified as B. B – Surface water considered to be of adequate quality to support fishing, swimming, recreation, aquatic habitats, and agricultural or industrial supply.

3.5 Site Reconnaissance

3.5.1 Methodology and Limiting Conditions

A. Sasha Isenberg of HRP conducted the site reconnaissance on December 23, 2025. HRP was provided site access and accompanied by Carlene Shaw, Town Planner for the Town of East Hartford. Ms. Shaw was unable to answer questions regarding the site's features and environmentally significant operations during the reconnaissance. Current owners, occupants, and operators were not available for interview.

Information obtained through interviews and during the reconnaissance is presented in the following sections. Photographs of key Subject Property features are presented in **Appendix A**.

Conditions that limited the site reconnaissance are listed below.

- Access to the interior of the buildings was not granted; therefore, an inspection of the building interiors could not be performed.
- The presence of snow on the ground prevented thorough observation of the site conditions.

3.5.2 Current and Past Uses of the Subject Property

The Subject Property is currently vacant. From approximately 1909 until 1988, the property was used for residential purposes and contained one residence and two outbuildings. In 1988, the outbuildings were demolished and a commercial classroom building was constructed on the site. Since that time, the property has been used as an educational facility and has, over the years, housed a daycare, Goodwin College, and Stone Academy. Stone Academy ceased operations in February 2023, and the property has remained vacant since.

3.5.3 Raw Material Storage and Handling

No storage of raw materials was observed. Fill and vent pipes typically associated with an oil tank were observed on the southeastern side of the northern building. Based on this observation, there is a possibility that an above-ground tank is located in the basement of that building.

3.5.4 Waste Generation and Handling

The Subject Property is vacant; therefore, no waste generation is occurring.

3.5.5 Current and Past Uses of Adjoining and Surrounding Properties

Adjoining Properties	North: Burnside Ave followed by residences (736-754 Burnside Avenue) South: Residential condominiums (50 Scotland Road) East: Office building, formerly part of the Subject Property (763 Burnside Avenue) West: Scotland Rd, followed by an apartment building (763 Burnside Avenue) and a parking lot

The general area use is mostly residential and light commercial/retail. Significant nearby features/properties of concern were not identified.

3.5.6 Exterior Observations

An inspection was performed of exterior areas of the Subject Property to obtain information that may indicate the presence of RECs or other potential environmental concerns. During the inspection, most of the exterior areas were covered with snow, which limited the ability to inspect the ground surface.

The Subject Property is improved with two buildings connected by a covered walkway and surrounded by parking areas to the south and west. The remainder of the site consists of a manicured lawn and landscaped areas.

A summary of specific exterior observations is provided below:

Features	Description
Hazardous Substances and Petroleum Products in Connection with Identified Uses	None observed
Hazardous Substances and Petroleum Products *Not* in Connection with Identified Uses	None observed
Unidentified Substance Containers	None observed
Storage Tanks	Based on municipal records, a UST was abandoned in place on the southwestern side of the northern building. No additional information, including tank content, size, age, or condition, was available in the records. See **Section 5.2** for the summary of available records.
PCB-Containing Equipment	An electrical transformer with a "2 ppm non-PCB" sticker was observed located west of the onsite buildings. No staining was observed on or around the unit.
Unusual Odors	None observed
Pools of Liquid	None observed
Pits, Ponds, Lagoons	None observed
Stained Soil or Pavement	None observed
Stressed Vegetation	None observed
Solid Waste Disposal/Fill	None observed
Wastewater/Stormwater	Several stormwater catch basins were observed within the parking areas.
Wells	None observed
Patched Asphalt/Concrete Areas	None observed
Railroad Spurs	None observed
Other Issues of Environmental Concern	No other exterior issues of concern were identified.

3.5.7 Interior Observations

Access to the buildings was not provided and, therefore, the interior of the onsite buildings was not inspected.

3.5.8 Storage Tank Summary

Based on the limited available information, one tank is currently located at the Subject Property. A UST on the southwestern side of the northern building, positioned between two air-conditioning units, was abandoned in place in 2020. One soil sample collected from beneath the tank was analyzed for ETPH, PAHs, and VOCs, and no constituents were detected above laboratory reporting

limits. No additional details, such as the tank's content, size, age, or condition, were available in the records.

Fill and vent pipes likely associated with an aboveground tank were observed on the southeastern side of the northern building. Based on this observation, there is a possibility that a storage tank is located in the basement of that building.

3.6 American Society for Testing and Materials Non-Scope Considerations

ASTM Practice E1527-21 recognizes that some environmental conditions may be present at a property that do not present potential CERCLA liability and are beyond the scope of the practice. Environmental issues or conditions that parties may wish to assess that are outside the scope of the practice are referred to as non-scope considerations.

At the request of the User, HRP conducted a cursory evaluation of the following non-scope considerations, in conjunction with the Phase I ESA site reconnaissance. It should be noted that the interior of the buildings was not inspected; HRP's opinions are based solely on an exterior inspection and a desktop review. This limited evaluation of the applicable conditions should not be construed as a thorough assessment or a compliance review with respect to federal, state, or local regulations. Unless otherwise specified, no testing was conducted as part of this evaluation. A thorough assessment of each non-scope consideration may be warranted, as appropriate, by a qualified professional.

Asbestos-Containing Materials	• Sampling and testing were not requested or performed. • Based on the approximate dates of construction of the northern building (in circa 1909), the potential for asbestos-containing materials (ACM) to be present is considered high.
Lead-Based Paint	• Sampling and testing were not requested or performed. • Based on the approximate dates of construction of the northern building (in circa 1909), the potential for lead-based paint (LBP) to be present is high.
Lead in Drinking Water	• Sampling and testing were not requested or performed. • Based on the approximate dates of construction of the northern building (in circa 1909), the potential for lead water pipes to be present is considered high. Municipal supply lines may also be a source of lead in drinking water.
Radon	• Sampling and testing were not requested or performed. • The Subject Property is located within EPA Radon Zone 3 where average predicted radon levels are less than 2.0 picocuries per liter (pCi/L). • Based on the average radon levels, the potential for elevated radon levels at the Subject Property is considered to be low.
Mold/Water Intrusion	• Sampling and testing were not requested or performed.

Wetlands	• According to the NWI database, federal or state wetlands are not mapped on the Subject Property. • Suspected wetlands were not observed on the Subject Property.

Per- and Polyfluoroalkyl Substances

- Per- and polyfluoroalkyl substances (PFAS) are a group of manufactured chemicals used to make fluoropolymer coatings and products that resist heat, oil, stains, grease, and water. Fluoropolymer coatings are blends of high-performance resins and lubricants, and are used in products such as water-repellent fabrics, furniture, adhesives, paint and varnish, food packaging, non-stick cookware, and electrical insulation. PFAS is also used in firefighting foam products.
- PFAS chemicals perfluorooctanoic acid (PFOA) and perfluorooctanesulfonic acid (PFOS) are recognized under CERCLA as hazardous substances and are considered hazardous substances in the State of Connecticut.
- There is no evidence of PFAS being handled, generated, stored, disposed of, or used at this location, either historically or currently.

4.0 USER PROVIDED INFORMATION

ASTM Practice E1527-21 defines the User as "the party seeking to use Practice E1527 to complete an ESA of the Subject Property." A User may include, without limitation, a potential purchaser of the Subject Property, a potential tenant of the Subject Property, an owner of the Subject Property, a lender, or a property manager.

The AAI Final Rule (40 CFR Part 312) requires that the following tasks be performed by or on behalf of a party seeking to qualify for an LLP to CERCLA liability, as well as EPA Brownfield Assessment and Characterization grantees. Although the information is not required to be provided to the environmental professional, the information can assist in the identification of RECs and has been requested of the User for this purpose.

The User of this Phase I ESA was identified as Carlene Shaw, Town Planner, Town of East Hartford. Information provided by the User is presented below:

Information Type	Provided by User	Concern Identified	Comments
User Questionnaire	Yes	N/A	Completed by Carlene Shaw, Town Planner, Town of East Hartford on October 15, 2025; provided as **Appendix B**.
Recorded Land Title Records	No	N/A	A review of recorded land title records was not conducted at the time of this report.
Environmental Liens or AULs	No	N/A	A review of environmental liens and AULs was not conducted at the time of this report.
Specialized or Actual Knowledge or Experience	No	N/A	The User did not indicate specialized knowledge or experience that is related to the Subject Property or nearby properties.
Valuation Reduction for Environmental Issues	Yes	N/A	The User has no reason to believe that the purchase price for the Subject Property has been reduced in comparison with the fair market value due to contamination known or believed to be present at the Subject Property.
Commonly Known or Reasonable Ascertainable Information	Yes	Yes	The User has stated that they are not aware of the past uses of the Subject Property. However, later the User stated that 745 Burnside Avenue previously was home to Stone Academy nursing college. The User reports having no knowledge of specific chemicals that are present or once were present at the Subject Property. The User reports having no knowledge of any spills or chemical releases on the Subject Property; however, due to the age of the northern building (constructed in 1909), the User anticipates the potential presence of contaminants or other environmental concerns. The User is not aware of any environmental cleanups that have taken place on the Subject Property.

Information Type	Provided by User	Concern Identified	Comments
Degree of Obviousness of the Presence of Contamination	No	N/A	The User has no knowledge or experience that indicates the presence or likely presence of releases or threatened releases of hazardous substances or petroleum at the Subject Property.
Reason for Performing Phase I ESA	Yes	Yes	It is HRP's understanding that the reason the User is performing this Phase I ESA is for potential redevelopment of the Subject Property. The User indicated due to the age of the original building there may be contaminants and other environmental concerns.

5.0 ENVIRONMENTAL RECORDS REVIEW

HRP obtained and evaluated records from standard environmental record sources and other environmental state, municipal, and federal regulatory agency record sources in conformance with ASTM Practice E1527-21. These sources may include various files and databases concerning the Subject Property, adjoining properties, and/or properties in the surrounding area. Records and information were obtained from a commercial database provider, on-line searches, specific record searches, interviews, and/or inquiries to state, federal, and local agencies, as necessary.

5.1 Environmental Database Records

Standard environmental records sources were obtained via EDR, a commercial database provider, for the Subject Property and properties within the applicable ASTM Practice E1527-21 minimum search distance. The following table lists the standard environmental record sources required to be researched in conformance with ASTM Practice E1527-21, and the associated minimum search distances identified for each applicable database.

Source	Search Distance (miles)	Source	Search Distance (miles)
Federal		***State and Tribal***	
NPL	1.0	"Superfund" Equivalent Sites	1.0
De-listed NPL	0.5	Hazardous Waste Sites	0.5
CERCLIS	0.5	Solid Waste Disposal and/or Landfill Sites	0.5
CERCLIS NFRAP Sites	0.5	Leaking Underground Storage Tanks (LUSTs)	0.5
RCRA CORRACTS Facilities	1.0	Registered Storage Tanks	Subject Property and adjoining properties
RCRA TSD Facilities	0.5	Institutional/Engineering Control Registries	Subject Property only
RCRA Generators	Subject Property and adjoining properties	Voluntary Cleanup Sites	0.5
Institutional/Engineering Control Registries	Subject Property only	Brownfield Sites	0.5
ERNS	Subject Property only	Spills	Subject Property and adjoining properties

CERCLIS: Comprehensive Environmental Response, Compensation, and Liability Information System
CORRACTS: Corrective Actions
ERNS: Emergency Response Notification System
NFRAP: No Further Remedial Action Planned
NPL: National Priorities List
RCRA: Resource Conservation and Recovery Act
TSD: Treatment, Storage, and Disposal

EDR's database report includes additional database records beyond the standard environmental records sources listed above. HRP has used all pertinent information compiled in the EDR Radius Map Report (**Appendix D**) to help identify RECs in connection with the Subject Property.

The following summarizes HRP's evaluation of the pertinent database listings, which is presented in order from closest to furthest from the Subject Property.

Subject Property

The Subject Property is not listed on any standard environmental record source databases provided by EDR.

Adjoining Properties

The adjoining properties are not listed on any standard environmental record source databases provided by EDR.

Additional Database Listings of Concern

Based on the details provided in the listing, relative distance from the Subject Property, area topography, inferred direction of groundwater flow, and/or other factors, none of the remaining facilities listed in the regulatory database records search is likely to have current or former releases of hazardous substances and/or petroleum products with the potential to migrate to the Subject Property, except for the following:

Name:	**East Hartford Middle School**
Facility ID(s):	43-5189 (UST), 55473 (Asbestos)
Database(s):	UST, LUST, Spills, Asbestos, CPCS, NPDES
Address(es):	777 Burnside Avenue
Distance from Subject Property:	165 feet
Direction from Subject Property:	East-southeast
Inferred Hydrology to Subject Property:	Upgradient
Elevation relative to the Subject Property:	Higher

East Hartford Middle School is listed the UST database with the following USTs:

- A 20,000-gallon heating oil UST, installed in 1955 and last used in July 1989. The UST was removed from the ground and listed as permanently closed.
- A 12,000-gallon heating oil UST, installed in 1989 and last used in April 2015. The UST was removed from the ground and listed as permanently closed.
- A 12,000-gallon heating oil UST, installed in 1989 and last used in July 2017. The UST was removed from the ground and listed as permanently closed.

The property is on the LUST database from May 2018 with a "LUST completed" status. No additional information is available. Due to the property being part of the LUST program, the property is also a part of the Contaminated or Potentially Contaminated Sites (CPCS) database. The property is also on the Spills database as of 2010 due to a motor vehicle accident causing a spill of antifreeze from a radiator. The spill was sanded, and the investigation has been terminated.

The property is listed on the Asbestos database from 2014 to 2022 for inspections.

Multiple National Pollutant Discharge Elimination System (NPDES) permits have been issued to the property starting in July 2010 and remaining active for the discharge of swimming pool wastewater.

Based on limited release information and the direction of the groundwater flow in the area, 777 Burnside Avenue does not represent a REC for the Subject Property.

Name:	**Sunset Cleaners**
Facility ID(s):	110044804860 (FINDS/ECHO), CTD021816541 (EPA – Sunset Cleaners), CT$000028870 (EPA – Waltawolk), 56824 (Asbestos), 7617 (Remediation)
Database(s):	CT Property, RCRA, FINDS, ECHO, Manifest, CPCS, Spills, Asbestos, Drycleaners
Address(es):	700 Burnside Avenue
Distance from Subject Property:	290 ft
Direction from Subject Property:	Northwest
Inferred Hydrology to Subject Property:	Cross-gradient
Elevation relative to the Subject Property:	Lower

Sunset Cleaners entered the Connecticut Property Transfer Program in October 2005. A Form III, Environmental Condition Assessment Form (ECAF), and ECAF Addendum were filed for the transfer of ownership. Specific details about conditions at the property were not provided by the EDR.

Sunset Cleaners was listed in the RCRA database as a verified non-generator. However, between 1986 and 2011, Sunset Cleaners was listed as a small quantity generator. Waste codes included F002, spent halogenated solvents. The site was included in the Facility Index System (FINDS) and Enforcement and Compliance History Online (ECHO) databases for its participation in the RCRA program.

Manifests from the property documented shipments of approximately 180 pounds of waste perchloroethylene (F002) in 1986, 280 pounds of waste perchloroethylene in 1990, 490 pounds of waste perchloroethylene in 1991, and 200 pounds of tetrachlorethylene (F002) in 1997.

Manifests under Waltawolk documented shipments of two gallons of waste silver (D011), associated with dental work, in 1990, and an additional two gallons of waste silver in 1992.

The property was listed in the CPCS database in 2006.

Several minor spills related to motor vehicle accidents were listed with a closed status.

In December 2015, an unknown quantity of asbestos was removed from the property building during remodeling activities, which entered the property in the Asbestos database.

The property was also listed in the Historic Drycleaners database due to previous drycleaning operations between 1980 and 2009.

Based on the regional groundwater flow direction, 700 Burnside Avenue does not represent a REC for the Subject Property.

Orphan Summary

Orphan sites are properties that, due to an inadequate or incomplete address in the government database or base map files, are not able to be geographically located (i.e., mapped, or geocoded). The EDR Radius Map Report identified no orphan sites.

5.2 Regulatory Agency File and Records Review

To supplement the standard environmental record sources identified in **Section 5.1**, HRP requested or searched practically reviewable and reasonably ascertainable local and state agency records, as detailed below, to help identify RECs associated with the Subject Property. Copies of pertinent records obtained are included in **Appendix E**.

Regulatory Agency	Type of Communication and Date	Summary of Information
CT DEEP	Website 11/7/2025	No records were identified.
EPA ECHO Database	Website 11/7/2025	No records were identified.
East Hartford Tax Assessor's Office	Website 10/20/2025	The Subject Property is owned by Burnside Gardens LLC and identified as Map 47 Lot 65 (Alternative ID: 0630-0745). Historical ownership records reviewed are summarized in **Section 6.5**.
Town of East Hartford	Available electronic documents were provided by Carlene Shaw on November 4, 2025. An in-person file review was conducted on November 21, 2025	Town files included historic deeds, permits, and property cards.
East Hartford Fire Department / Fire Marshal's Office	Website 10/20/2025	Several fire and emergency reports were available regarding the Subject Property and are summarized below.
City/Town Building Department	In person, 12/23/2025	March 2020 Tank Abandonment Records (summarized below).

Agency/Source Records

East Hartford Fire Marshal

- March 2020 Tank Abandonment Records

  Records from the Fire Marshal's office included a CD and a laboratory report; however, no formal summary report was available. Based on photographs saved on the CD (included in **Appendix E**), a UST located on the southwestern side of the northern building, between two air conditioning units, was abandoned in place. The tank was reportedly washed and pumped out.

  One soil sample, collected on March 25, 2020, and labeled "Bottom 5.5–6 ft," was analyzed for ETPH, PAHs, and VOCs. No detections above laboratory reporting limits were identified.

  No additional information regarding the tank, such as tank content, size, age, or condition, was available in the records.

Fire and Utility Incident History

- In 1992, a brush fire was reported near Burnside Avenue (the northern side of the Subject Property). Details regarding ignition and extinguishment were not provided.
- In October 2008, a vehicle fire occurred in one of the parking areas of the Subject Property. The cause of ignition and method of extinguishment are unknown.
- A natural gas leak was reported in 2015. No additional details were available.
- A downed power line was reported in 2020 along Burnside Avenue No further information was provided.
- Two trash receptacle fires were reported in 2017 and 2022. Ignition and extinguishment details were not provided.

Should relevant files or other regulatory information become available following the issuance of this report that changes the conclusions of this Phase I ESA, the User will be notified and an addendum to this report will be issued.

5.3 Previous Environmental Investigations

No previous environmental reports or investigations were provided or otherwise identified associated with the Subject Property during this assessment.

5.4 Other Environmental Record Sources

No other environmental record sources were identified as part of this Phase I ESA.

6.0 HISTORICAL RECORDS REVIEW

According to ASTM Practice E1527-21, the objective of compiling and analyzing historical property information is to help identify the likelihood of past uses having led to RECs in connection with the Subject Property. The following standard historical sources were used to obtain information regarding the previous uses of the Subject Property, adjoining properties, and surrounding area, and the findings obtained from those sources are discussed in the following sections.

Historical Record Source	Provider	Date Range Reviewed
Aerial Photographs	EDR	1934-2023
Topographic Maps	EDR	1892-2021
Sanborn Fire Insurance Maps	EDR	1920-1968
City Directories	EDR	1925-2022

6.1 Aerial Photographs

Historical aerial photographs showing the Subject Property and surrounding area were obtained from EDR (**Appendix F**). Pertinent information obtained from review of the aerial photography is summarized below.

Year	Scale	Description of Key Features of Subject Property and Surrounding Area
1934 1943*	1"= 500'	Subject Property: The Subject Property is developed with the present-day northern building and an outbuilding. Walking paths are visible north, south, and west of the building. The northern boundary of the Subject Property near Burnside Avenue and the southern boundary are vegetated. Surrounding area: Much of the surrounding area is developed with residential or agricultural properties. Improved roads are present. A railroad is visible in the area to the north. Hockanum River and Hockanum Reservoir are located to the south. *The 1943 image quality does not allow for detailed observation.
1952	1"= 500'	Subject Property: A small garage structure has been developed south of the existing building. No other significant changes are evident. Surrounding area: No significant changes are evident.
1957 1962	1"= 500'	Subject Property: No significant changes are evident. Surrounding area: A school has been developed to the southeast of the Subject Property. Some additional residential and commercial development has occurred west of the Subject Property. No other significant changes are evident.

Year	Scale	Description of Key Features of Subject Property and Surrounding Area
1968 1970 1972* 1985	1″= 500′	Subject Property: No significant changes are evident. Surrounding area: An apartment building and a paved parking lot have been constructed on the adjoining parcel west of the Subject Property. Commercial structures have been developed to the northwest and southwest of the Subject Property. No other significant changes are evident. *The 1972 image quality does not allow for detailed observation.
1990 1995	1″= 500′	Subject Property: A large building has been constructed on the southern portion of the Subject Property, south of the original building. Paved parking is visible to the south of the new building and west of the original building. Surrounding area: Residential condominiums have been developed on the parcel south of the Subject Property.
2006 2010 2014 2018 2023	1″= 500′	The Subject Property and surrounding area appear similar to the present-day condition.

6.2 Topographic Maps

Historical topographic maps showing the Subject Property and surrounding area were obtained from EDR (**Appendix G**). Pertinent information obtained from review of the topographic maps is summarized below.

Year	Description of Key Features of Subject Property and Surrounding Area
1892 1906	Subject Property: No structures are depicted on the Subject Property. Topography slopes south toward Hockanum River. Surrounding area: Structures are sparsely developed in the surrounding area. General topography slopes to the south-southwest towards Hockanum River.
1928	Subject Property: No significant changes are evident. Surrounding area: Structures are not depicted in the surrounding area on the 1928 map. Vegetated/wooded areas are depicted south of the Subject Property. The Hockanum River appears to have been expanded into a reservoir to the southeast of the Subject Property.
1944 1952	Subject Property: A structure is depicted in the central portion of the Subject Property. Surrounding area: The surrounding area has become more densely developed with residential structures, churches, schools, and commercial structures.

Year	Description of Key Features of Subject Property and Surrounding Area
1963	Subject Property: No significant changes are evident. Surrounding area: Scotland Road has been developed along the eastern border of the Subject Property. A school has been developed to the west. A police station has been developed to the northwest. A larger school has been developed to the east-southeast of the Subject Property. No other significant changes are evident.
1968 1984 1992	Subject Property: No significant changes are evident. Surrounding area: The surrounding area to the north and west is depicted as developed; the individual features are no longer depicted. The school to the southeast has been expanded.
2012	No structures are depicted on the 2012 topographic map. Subject Property: No significant changes are evident. Surrounding area: An unnamed road has been developed along the southern border of the Subject Property. A fire station is depicted to the northwest of the Subject Property. No other significant changes are evident.
2015	Subject Property: Goodwin College is depicted on the Subject Property. Surrounding area: Schools are depicted to the west and southeast of the Subject Property. A police station and a fire station are depicted to the northwest.
2018 2021	Subject Property: No significant changes are evident. Surrounding area: The school to the west of the Subject Property is no longer depicted. No other significant changes are evident.

6.3 Sanborn Fire Insurance Maps

Historical Sanborn Fire Insurance Maps showing the Subject Property and surrounding area were obtained from EDR (**Appendix H**). Pertinent information obtained from review of the Sanborn Fire Insurance Maps is summarized below.

Year	Description of Key Features of Subject Property and Surrounding Area
1920	Subject Property: A dwelling is depicted in the north-central portion of the Subject Property. Surrounding area: Burnside Avenue is depicted along the northern property boundary of the Subject Property. Dwellings are sparsely located in the surrounding area.
1927	Subject Property: A small shed or garage is depicted to the southwest of the Subject Property building. Surrounding area: Goodwin Lane has been developed along the western property boundary of the Subject Property. A filling station has been developed to the northwest of the Subject Property. No other significant changes are evident.

Year	Description of Key Features of Subject Property and Surrounding Area
1949	Subject Property: No significant changes are evident. Surrounding area: The filling station is depicted as a store. A new store has been constructed to the west of the Subject Property. No other significant changes are evident.
1968	Subject Property: An auto garage has been added to the Subject Property. Surrounding area: An apartment building has been developed to the west of the Subject Property. A large commercial building has replaced the former filling station/store to the northwest. A large school has been constructed to the east of the Subject Property. Additional residential development is depicted to the southwest. Goodwin Lane is also identified as Scotland Road.

6.4 City Directories

Historical city directories for the Subject Property and a limited selection of surrounding properties were obtained at approximate five-year intervals from EDR (**Appendix I**). Pertinent information obtained from review of the city directories is provided below.

Date	Subject Property and Nearby Address Listings
1925 1936	Subject Property: Henry C. Olmsted Surrounding area: Residential listings
1941	Subject Property: Henry C. Olmsted Surrounding area: 712 Burnside Ave – J. E. McCauley Gasoline; Residential listings
1946	Subject Property: Henry C. Olmsted Surrounding area: Commercial listings; Residential listings
1951	Subject Property: Henry C. Olmsted Surrounding area: 716 Burnside Ave – Let & Gene Cleaners; Commercial listings; Residential listings
1960	Subject Property: Mary E. G. Olmsted Surrounding area: 716 Burnside Ave – Let & Gene Cleaners; Commercial listings; Residential listings
1965	Subject Property: Mary E. G. Olmsted Surrounding area: Commercial listings; Residential listings
1971 1977	Subject Property: Mary E. G. Olmsted Surrounding area: 700 Burnside Ave – Sunset Cleaners; Commercial listings; Residential listings

Date	Subject Property and Nearby Address Listings
1992	Subject Property: BS Services, Career Line, Data Institute School, Data Institute Daycare Surrounding area: 700 Burnside Ave – Sunset Cleaners; Commercial listings; Residential listings
1995	Subject Property: BS Services, Career Line, Data Institute Business School, YWCA Child Care Surrounding area: 700 Burnside Ave – Sunset Cleaners; Commercial listings; Residential listings
2000	Subject Property: BS Services, Connecticut Training Center, Data Institute Business School, Data Institute Career Line, East Hartford Child Care Center, YWCA Child Care Surrounding area: 700 Burnside Ave – Sunset Cleaners; Commercial listings; Residential listings
2005	Subject Property: 211 Riverside LLC, Goodwin College, River Campus Inc, Steel Buildings Systems LLC Surrounding area: 700 Burnside Ave – Sunset Cleaners; Commercial listings; Residential listings
2010	Subject Property: Stone Academy Surrounding area: 700 Burnside Ave – Sunset Cleaners; Kennady Fried Chicken; Commercial listings; Residential listings
2014	Subject Property: Connecticut Training Center Inc.; Goodwin College; Stone Academy Surrounding area: Commercial listings; Residential listings
2017	Subject Property: Connecticut Training Center Inc.; Stone Academy Surrounding area: Commercial listings; Residential listings
2022	Subject Property: Breakthrough Entertainment Media LLC; Goodwin College; Stone Academy; Residential listings Surrounding area: Brothers Home Improvement LLC; Commercial listings; Residential listings

6.5 Summary of Historical Records Review

The history of the Subject Property and surrounding area was reviewed through the sources described above. Based on the information reviewed, the following table summarizes the Subject Property's historical use, and that of notable surrounding properties.

Year(s)	Subject Property	Notable Surrounding Properties
1892-1909	Undeveloped land.	The surrounding area is a mix of residences and agricultural land.
1909-1988	The Subject Property is improved with one residential building and an outbuilding(s) / garage.	The surrounding area is residential/ light commercial, with churches, schools, and commercial structures. A filling station was located to the northwest of the Subject Property in the 1920s. By the 1940s, the filing station was replaced with a store, and later with a commercial shopping center.
1988-Present	An additional school building was added to the south of the original building. The two outbuildings/ garages were razed in 1988.	The surrounding area remains residential/ light commercial

6.6 Other Historical Sources Reviewed

Limited historical ownership records were obtained on October 6, 2025 via the East Hartford Assessor's online database records and are summarized in the table below. The property cards are included in **Appendix C**.

Deed Book/Page	Date	Ownership
4226/246	1/22/2024	Burnside Gardens LLC
2799/74	9/5/2006	Olmsted Realty LLC
2677/258	12/20/2005	Olmsted Realty LLC
1021/187	12/31/1986	Mark E. Scheinberg
953/3	2/14/1986	Mark E. Scheinberg & Raymond J. Ransom

Historical ownership records did not indicate obvious historical ownership or uses that are believed to have adversely impacted the environmental quality of the Subject Property. However, a complete review of the chain of title and other recorded land title records was not conducted by HRP or provided by the User. HRP does not consider the lack of a complete chain of title and other recorded land title records to be a significant data gap that prevented the identification of RECs at the Subject Property.

7.0 INTERVIEWS

A summary of the current and/or past owners, operators, or occupants, as well as regulatory officials who were contacted for interviews or information during the course of this assessment are summarized in the table below. Information obtained from the interviews is incorporated throughout applicable portions of this report. Current and/or past owners, operators, and occupants were not available for interview.

Individual Interviewed	Type of Communication and Date	Relationship to Subject Property
Carlene Shaw	In-person 12/23/2025	Town Planner, Town of East Hartford
Sara Kennedy	In-person 12/23/2025	Fire Marshal Administrative Operations Coordinator

8.0 DATA GAPS

The following table lists key components of the Phase I ESA and whether sufficient information was available to complete and/or evaluate them. Any items not completed, or completed with limitations, represent data gaps that are described with comments as indicated. Significant data gaps that may have affected our ability to identify RECs are discussed below.

Requirement	Completed	Comment
Environmental Professional involved in planning, review, and interpretation of material	Yes	
Records Review		
Title Records:		
• On-line or in person review of available basic title information	Yes	Limited historical ownership records were available from the Tax Assessor dating back to 1986.
• User-provided review of recorded land title records	No	Not provided by User
Environmental Liens/Activity Use Limitations	No	Not provided by User
Other User Provided Information	No	Not provided by User
Standard Environmental Record Sources	Yes	
Historical Aerial Photographs	Yes	
Historical Sanborn Fire Insurance Maps	Yes	
Historical Topographic Maps	Yes	
Historical City Directories	Yes	
Tax Assessor's Office	Yes	
Fire Department	Yes	
Building/Engineering Department	Yes	
Health Department	No	A response has not been received
Public Works Department	Yes	
Planning and Zoning Department	Yes	
Site Reconnaissance		
Visual Inspection	Yes	
Limiting Conditions	Yes	• Access to the interior of the buildings was not granted; therefore, an inspection of the building interiors could not be performed. • The presence of snow on the ground prevented thorough observation of the site conditions.
Uses of Adjoining Properties	Yes	
Interviews		
Current Owner	No	
Current Operator	No	
Current Occupant	No	
Past Owner	No	

Requirement	Completed	Comment
Past Operator	No	
Past Occupant	No	

The following data gaps limited HRP's ability to identify RECs and are therefore considered significant:

- Access to the interior of the buildings was not granted; therefore, an inspection of the building interiors could not be performed.
- The presence of snow on the ground prevented thorough observation of the site conditions.

9.0 FINDINGS AND OPINIONS

HRP has completed a Phase I ESA of the Stone Academy property located at 745 Burnside Avenue in East Hartford, Connecticut. Any exceptions to, or deletions from, this practice are described in **Sections 2.0** and **8.0** of this report.

The following is a summary of the key findings of this assessment:

- The 2.45-acre Subject Property consists of a single parcel identified by the East Hartford Tax Assessor as Map 47, Lot 65. The property is improved with two buildings connected by a covered walkway. The northern building is a two-story, 4,481-square-foot office building (formerly residential) with a full basement, constructed around 1909. The southern building is a two-story, slab-on-grade structure totaling approximately 12,768 square feet, constructed in 1988. Parking areas are located to the west and south of the buildings; the remainder of the property consists of a manicured lawn and landscaped areas. The Subject Property is serviced by public water, public sewer, and natural gas.
- The Subject Property is currently vacant, and no waste generation occurs onsite. Access to the building interiors was not provided; therefore, it is unknown whether any petroleum products and/or hazardous substances are stored within the buildings.
- Prior to 1988, the Subject Property was used for residential purposes since at least 1909 and contained one residence and two outbuildings. In 1988, the outbuildings were demolished and a commercial classroom building was constructed on the site. Since that time, the Subject Property has been used as an educational facility and has, over the years, housed a daycare center, Goodwin College, and Stone Academy. Stone Academy ceased operations in February 2023, and the property has remained vacant since.
- Based on the limited available information, one tank is currently located at the Subject Property. A UST on the southwestern side of the northern building, positioned between two air-conditioning units, was abandoned in place in 2020. One soil sample collected from beneath the tank was analyzed for ETPH, PAHs, and VOCs, and no constituents were detected above laboratory reporting limits. No additional details, such as the tank's content, size, age, or condition, were available in the records.
- Fill and vent pipes likely associated with an aboveground tank were observed on the southeastern side of the northern building. Based on this observation, there is a possibility that a storage tank is located in the basement of that building.
- The Subject Property is not listed in any of the environmental databases or CT DEEP records.

10.0 CONCLUSIONS

HRP has completed a Phase I ESA in conformance with the scope and limitations of ASTM Practice E1527-21 and in accordance with the CT DEEP SCGD of the Stone Academy property located at 745 Burnside Avenue in East Hartford, Connecticut, the Subject Property. Any exceptions to, or deletions from, this practice are described in **Sections 2.0** and **8.0** of this report.

This assessment has revealed the following REC in connection with the Subject Property.

- REC-1: Abandoned UST

  A UST reportedly abandoned in place in 2020 is located on the southwestern side of the northern building. A limited subsurface investigation was conducted, consisting of one soil sample collected from beneath the tank and analyzed for ETPH, PAHs, and VOCs. No analytes were detected above laboratory reporting limits. No additional information regarding the UST, such as size, age, construction, or condition, was available in the reviewed records. Due to the incomplete characterization of the tank and its potential for having impacted subsurface media, this condition is considered a REC.

The following AOCs were identified at the Subject Property during this investigation. These AOCs may not meet the ASTM definition of a REC but are considered potential environmental issues associated with the Subject Property as outlined in CT DEEP's SCGD.

- AOC-1: Potential Tank in Basement

  Fill and vent pipes typically associated with an oil storage tank were observed on the southeastern side of the northern building. This observation suggests the potential presence of an oil tank within the building's basement. Due to the possibility of a release from such a tank and the lack of confirmation regarding its presence, size, age, or condition, this is considered an AOC.

- AOC-2: Electrical Transformer

  A pad-mounted electrical transformer was observed on the western side of Subject Property. The transformer had a sticker indicating that the transformer contained dielectric oil with less than 2 ppm of PCBs. No obvious staining was observed on and/or beneath the transformer. Due to the potential for a release, this location is considered an AOC.

- AOC-3: Historical Outbuildings

  An outbuilding and a garage building that occupied the Subject Property from the early twentieth century until redevelopment in 1988 represent an AOC. It is unclear whether these structures were properly demolished, raising the concern that remnants such as hazardous materials, drums, or USTs could remain buried onsite. Additionally, historical garage uses may have involved storage or use of petroleum products, solvents, and other chemicals commonly associated with vehicle maintenance.

This assessment has revealed the following significant data gaps in connection with the Subject Property:

- Access to the interior of the buildings was not granted; therefore, an inspection of the building interiors could not be performed.

- The presence of snow on the ground prevented thorough observation of the site conditions.

This assessment has revealed no CRECs, HRECs, and/or de minimis conditions in connection with the Subject Property.

In HRP's opinion, no information was found to suggest that the Subject Property or business operating on the property meets the definition of an "establishment" pursuant to Connecticut's "Transfer Act" (CGS 22a-134). This opinion should be confirmed by counsel prior to any qualifying transfer of ownership of the property or business.

Based on reviewed available information, it is HRP's opinion that additional investigation is warranted to evaluate the presence of hazardous substances and/or petroleum products in the environment as a result of the AOCs identified in this assessment and detailed above.

11.0 REFERENCES

Published Sources

American Society for Testing and Materials, Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process, ASTM Designation E1527-21.

Connecticut Department of Environmental Protection (CT DEP; now CT DEEP), 1982, The Atlas of Public Water Supply Sources and Drainage Basins of Connecticut; CT DEP Natural Resources Center.

Rodgers, J., 1985, Bedrock Geological Map of Connecticut; CT DEP, Natural Resources Center, Connecticut Geological and Natural History Survey, in cooperation with the U.S. Department of the Interior, U.S. Geological Survey.

Stone, J. R., Schafer, J. P., London, E. H. and Thompson, W. B., 1992, Surficial Materials Map of Connecticut; prepared in cooperation with CT DEP, Geological and Natural History Survey.

U.S. Geological Survey Topographic Map, Manchester, 7.5 Minute Series, 2021.

U.S. Geological Survey Topographic Map, Hartford North, 7.5 Minute Series, 2021.

Environmental Database Provider

Environmental Database Resources, Inc.

- Radius Map Report with GeoCheck (**Appendix D**)
- Aerial Photo Decade Package (**Appendix F**)
- Historical Topographic Map Report (**Appendix G**)
- Certified Sanborn Map Report (**Appendix H**)
- City Directory Image Report (**Appendix I**)

Regulatory Agency Files

Connecticut Department of Energy and Environmental Protection (CT DEEP)

Town of East Hartford Records and Interviews

Other Information Sources, Including Web-based Sources (as applicable)

CT DEEP, 2025, Connecticut Environmental Conditions Online, prepared in cooperation with the University of Connecticut Center for Land Use Education and Research. Retrieved online from http://cteco.uconn.edu. Accessed: January 2026.

CT DEEP Document Online Search Portal. Retrieved online from https://filings.deep.ct.gov/DEEPDocumentSearchPortal/. Accessed: December 2025.

CT DEEP Hazardous Waste Portal Manifest Metadata. Retrieved online from https://data.ct.gov/Environment-and-Natural-Resources/Hazardous-Waste-Portal-Manifest-Metadata/x2z6-swxe/about_data. Accessed: December 2025.

CT DEEP Hazardous Waste Manifest Data (1984-2008). Retrieved online from https://data.ct.gov/Environment-and-Natural-Resources/Hazardous-Waste-Manifest-Data-CT-1984-2008/h6d8-qiar/data. Accessed: December 2025.


Federal Emergency Management Agency, Federal Insurance Administration, National Flood Insurance Program, Flood Insurance Map. Accessed: October 2025.


U.S. Department of Agriculture, Natural Resources Conservation Service, Web Soil Survey. Accessed: October 2025.

U.S. Fish and Wildlife Service, National Wetlands Inventory Wetlands Map. Accessed: November 6, 2025.

UST Facility and Tank Details. Retrieved online from https://data.ct.gov/Environment-and-Natural-Resources/Underground-Storage-Tanks-USTs-Facility-and-Tank-D/utni-rddb/data. Accessed: December 2025.

FIGURES





USGS Quadrangle Information
Quad ID: 41072-G5
Quad Name: Manchester, Connecticut

Figure 1
Subject Property Location Map
745 Burnside Avenue
East Hartford, Connecticut
HRP # COL4100.P2
Scale 1" = 2,000'

MOVE YOUR ENVIRONMENT FORWARD
ONE FAIRCHILD SQUARE
SUITE 110
CLIFTON PARK, NY 12065
(518) 877-7101
HRPASSOCIATES.COM

Path: S:\Data\C\COLEN - COLLIER'S ENGINEERING & DESIGN, ARCHITECTURE, LANDSCAPE, SURVEYING, CT PC\VARIOUS\COL4100P2 - East Hartford BAR\GIS\745 Burnside\Figures.aprx



HRP
MOVE YOUR ENVIRONMENT FORWARD
ONE FAIRCHILD SQUARE
SUITE 110
CLIFTON PARK, NY 12065
(518) 877-7101
HRPASSOCIATES.COM

North

0 20 40
Feet

Revisions					
No.	Date				

Designed By: ASI	Drawn By: BOB	Reviewed By: CG
Issue Date: 12/22/2025	Project No: COL4100.P2	Sheet Size: 11x17

Site Plan
Stone Academy
745 Burnside Avenue
East Hartford, Connecticut

Figure No.
2

Path: S:\Data\COLLEN - COLLIER'S ENGINEERING & DESIGN, ARCHITECTURE, LANDSCAPE, SURVEYING, CT PC\VARIOUS\COL4100P2 - East Hartford BAR\GIS\745 Burnside\Figures.aprx

APPENDIX A
Subject Property Photographs



Photo 1: Northern building, western façade. Facing ENE.



Photo 2: View of the southern building (left) and northern building (right). Facing west.



Photo 3: Southern building. Facing north.



Photo 4: Southern parking lot. Facing east.



Photo 5: View of the southeastern façade of the northern building. Facing northwest.



Photo 6: Fill/vent pipes on southeastern side of northern building.



Photo 7: Electrical transformer to the west of the buildings.




Photo 8: Non-PCB sticker on the electrical transformer.

APPENDIX B
User Questionnaire

PHASE I ENVIRONMENTAL SITE ASSESSMENT
USER QUESTIONNAIRE

Please answer the following questions as completely as possible. Attach additional pages as needed.

1. Subject Property Information.

Property Name: Stone Academy
Property Address: 745 Burnside Ave, East Hartford, CT
Property Owner Name: BURNSIDE GARDENS LLC

2. Previous Environmental Reports. Are you aware of previous environmental site assessment reports, other environmental reports, documents, correspondence, etc. concerning the Subject Property and its environmental condition?

☐ Yes ☑ No

If yes, please identify and provide copies, if available.

3. Reason the Phase I is Being Performed. Including the type of transaction, if any (sale, purchase, exchange, etc.)

745 Burnside Avenue previously was home to Stone Academy nursing college and has now been vacated. This building has potential for redevelopment. Since it was originally constructed in 1909, there may be contaminants or other environmental concerns due to the age of the building.

In order to qualify for one of the Landowner Liability Protections (LLPs) as an innocent landowner, bona fide prospective purchaser, or contiguous property owner under the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA) or the Small Business Liability Relief and Brownfields Revitalization Act of 2001 (the "Brownfields Amendments"), ASTM Standard Practice E1527-21 and the federal All Appropriate Inquiries (AAI) final rule (40 CFR Part 312) require that the User of the Phase I Environmental Site Assessment (ESA) report conduct the following inquiries required by 40 CFR §§ 312.25, 312.28, 312.29, 312.30, and 312.31. These inquiries must also be conducted by EPA Brownfield Assessment and Characterization grantees. The User should provide the following information to the Environmental Professional. Failure to conduct these inquiries could result in a determination that "all appropriate inquiries" is not complete. Information that is not or cannot be provided to the Environmental Professional may be identified as a "data gap" in the Phase I ESA report.

4. Environmental Liens. Did a search of land title records (or judicial records where appropriate) identify any environmental liens filed or recorded against the Subject Property under federal, tribal, state or local law?

☐ Yes ☐ No

If yes, describe or attach details of the lien.
N/a, a title search has not been conducted at this time.

5. **Activity and Use Limitations.** Did a search of land title records (or judicial records where appropriate) identify any activity and use limitations (AULs), such as engineering controls, land use restrictions, or institutional controls that are in place at the Subject Property and/or have been filed or recorded against the Subject Property under federal, tribal, state or local law?

☐ Yes ☐ No

If yes, describe or attach details of the AULs.
N/a, a title search has not been conducted at this time.

6. **Specialized Knowledge or Experience.** As the User of this ESA, do you have any specialized knowledge or experience related to the Subject Property or nearby properties? For example, are you involved in the same line of business as the current or former occupants of the Subject Property or an adjoining property, such that you would have specialized knowledge of the chemicals and processes used by this type of business?

☐ Yes ☑ No

If yes, describe or attach details of your specialized knowledge or experience.

7. **Relationship of Purchase Price to Fair Market Value of the Subject Property.** Does the purchase price being paid for this Subject Property reasonably reflect the fair market value of the property?

☐ Yes ☐ No

If you conclude that there is a difference, have you considered whether the lower purchase price is because contamination is known or believed to be present at the Subject Property?

☐ Yes ☐ No

☑ Not applicable. User is not involved in a purchase of the Subject Property.

8. **Commonly Known or Reasonably Ascertainable Information.** Are you aware of commonly known or reasonably ascertainable information about the Subject Property that would help the Environmental Professional to identify conditions indicative of releases or threatened releases of hazardous substances or petroleum products? For example:

Do you know the past uses of the Subject Property?

☐ Yes (describe) _____

_____

☑ No

Do you know of chemicals, hazardous substances or petroleum products that are present or once were present at the Subject Property?

☐ Yes (describe) _____

_____

☑ No

Do you know of spills or other releases of chemicals, hazardous substances or petroleum products that have taken place at the Subject Property?

☐ Yes (describe) _____

_____

☑ No

Do you know of any environmental cleanups that have taken place at the Subject Property?

☐ Yes (describe) _____

_____

☑ No

9. **The Degree of Obviousness of Contamination.** E1527-21 and the federal AAI rule (40 CFR 312) require that the Phase I ESA consider the degree of obviousness of the presence or likely presence of contamination at the Subject Property, and the ability to detect the contamination by appropriate investigation. Based on your knowledge and experience related to the Subject Property, are there any obvious indicators that point to the presence or likely presence of contamination at the property?

☐ Yes (describe) _____
N/a, I am not sure.

☐ No

Signature: Carlene Shaw

Name (printed): Carlene Shaw

Title: Town Planner, Town of East Hartford

Relationship to Subject Property: Project Manager of BAR project for Burnside Church Street Neighborhood

Date: 10/15/2025

APPENDIX C
Recorded Land Title Records

Property Location 745 BURNSIDE AVE | Map ID 47/ / 65/ / | Bldg Name | State Use 201
Vision ID 1916 | Account # 1916 | Bldg # 1 | Sec # 1 of 1 | Card # 1 of 2 | Print Date 5/1/2025 8:56:44 AM

CURRENT OWNER

BURNSIDE GARDENS LLC

330 GREAT NECK ROAD FL 2

GREAT NECK NY 11021

TOPO	UTILITIES	STRT / ROAD	LOCATION
A Good	1 All	1 Paved	

SUPPLEMENTAL DATA

Alt Prcl ID	0630-0745	Locn Suffix	
Homeown		Zoning	R-4
Census	5104	Res Area	16364
VCS	2304	Non Res A	0
# Units	2	Lot Size	2.53
Class	Com		
GIS ID		Assoc Pid#	

CURRENT ASSESSMENT

Description	Code	Appraised	Assessed
COM LAND	2-1	160,940	112,660
COM BLDG	2-2	2,033,700	1,423,590
COM OUTBL	2-5	289,240	202,460
	Total	2,483,880	1,738,710

6043

EAST HARTFORD, CT

VISION

RECORD OF OWNERSHIP

RECORD OF OWNERSHIP	BK-VOL/PAGE		SALE DATE	Q/U	V/I	SALE PRIC	VC
BURNSIDE GARDENS LLC	4226	0246	01-22-2024	U	I	600,000	B03
OLMSTED REALTY L L C	2796	0074	09-05-2006	U	I	0	B25
OLMSTEAD REALTY L L C	2677	0258	12-20-2005	U	I	0	B03
SCHEINBERG MARK E	1021	0187	12-31-1986	Q	I	200,000	NC
RANSOM RAYMOND J & SCHEINBER MARK	0953	0003	02-14-1986	Q	I	196,350	NC

PREVIOUS ASSESSMENTS (HISTORY)

Year	Code	Assessed	Year	Code	Assessed	Year	Code	Assessed
2024	2-1	112,660	2023	2-1	115,550	2022	2-1	115,550
	2-2	1,423,590		2-2	1,423,590		2-2	1,423,590
	2-5	202,460		2-5	202,460		2-5	202,460
	Total	1,738,710		Total	1,741,600		Total	1,741,600

EXEMPTIONS

Year	Code	Description	Amount
		Total	0.00

OTHER ASSESSMENTS

Code	Description	Number	Amount	Comm Int

This signature acknowledges a visit by a Data Collector or Assessor

ASSESSING NEIGHBORHOOD

Nbhd	Nbhd Name	B	Tracing	Batch
0001				

NOTES

INT REN, $65,000, N/C, 2003. BAA/COC COMBINED 0.038 FROM 763 BSA.
2003. ADD 4 RELOCATABLE CLASSROOMS,
2005. ADD FIN ATTIC & 60% FIN BSMT,
REVAL 2006. ADD I&E PENALTY 2006.
REMOVE I&E PENALTY 2007. ADD I&E
PENALTY 2009. GL24: LOT LINE AMENDMENT,

APPRAISED VALUE SUMMARY

Appraised Bldg. Value (Card)	2,006,290
Appraised Xf (B) Value (Bldg)	27,410
Appraised Ob (B) Value (Bldg)	289,240
Appraised Land Value (Bldg)	160,940
Special Land Value	0
Total Appraised Parcel Value	2,483,880
Valuation Method	C
Total Appraised Parcel Value	2,483,880

BUILDING PERMIT RECORD

Permit Id	Issue Date	Type	Description	Amount	Insp Date	% Comp	Date Comp	Comments
B-16-779	10-03-2016	RP	Repair	6,000		0		Replace sheetrock on bottom
E-16-764	09-15-2016	EL	Electric	5,000		0		Emergency repairs due to wat
52569	09-11-2008	BLD		0				Installation of temporary tent 2
52429	09-04-2008	BLD		3,880				Installation of exterior concrete

VISIT / CHANGE HISTORY

Date	Id	Type	Is	Cd	Purpost/Result
06-29-2016	BJR			62	Estimated
09-09-2005	TM			63	Verified

LAND LINE VALUATION SECTION

B	Use Code	Description	Zone	Land Type	Land Units		Unit Price	I. Factor	Site Index	Cond.	Nbhd.	Nhbd Adj	Notes	Location Adjustment		Adj Unit Pric	Land Value
1	201	Commercial	R4		2.450	AC	135,000.00	0.57244	C	1.00	3200	0.850			0		160,940
				Total Card Land Units	2.4500	AC	Parcel Total Land Area:	2.4500								Total Land Value	160,940

Property Location 745 BURNSIDE AVE | Map ID 47/ / 65/ / | Bldg Name | State Use 201
Vision ID 1916 | Account # 1916 | Bldg # 1 | Sec # 1 of 1 | Card # 1 of 2 | Print Date 5/1/2025 8:56:45 AM

CONSTRUCTION DETAIL

Element	Cd	Description
Style:	23	Office - Low Rise
Model	94	Comm/Ind
Grade	57	1.05
Stories:	2.0	
Occupancy	1.00	
Exterior Wall 1	15	Concr/Cinder
Exterior Wall 2		
Roof Structure	03	Gable
Roof Cover	03	Asphalt
Interior Wall 1	03	Plaster
Interior Wall 2		
Interior Floor 1	12	Hardwood
Interior Floor 2		
Heating Fuel	10	Other
Heating Type	06	Steam
AC Type	03	Central
Finished %	100	
Bldg Use	201	Commercial
Total Bedrooms	0	
Total Baths		
Num Fixtures	0	
Total Rooms	12	
Basement %	100	
Heat/AC	1	Separate
Frame Type	1	Wood Joist
Baths/Plumbing	02	Average
Common Wall	F	None
Wall Height	0.00	
Perimeter	184.00	
1st Floor Use:		

CONSTRUCTION DETAIL (CONTINUED)


Element	Cd	Description

MIXED USE

Code	Description	Percentage
201	Commercial	100
		0
		0

COST / MARKET VALUATION

RCN	560,954
Year Built	1909
Effective Year Built	1986
Depreciation Code	A
Remodel Rating	
Year Remodeled	2003
Depreciation %	35
Functional Obsol	
External Obsol	
Trend Factor	1
Condition	
Condition %	
Percent Good	65
RCNLD	364,620
Dep % Ovr	
Dep Ovr Comment	
Misc Imp Ovr	
Misc Imp Ovr Comment	
Cost to Cure Ovr	
Cost to Cure Ovr Comment	





OB - OUTBUILDING & YARD ITEMS(L) / XF - BUILDING EXTRA FEATURES(B)

Code	Description	L/B	Units	Unit Price	Yr Blt	Cond. Cd	% Good	Grade	Grade Adj	Appr. Value
FPL	Fireplace	B	1	5000.00	1986		65		0.00	3,250
FBM	Fin Bsmt	B	1,062	35.00	1986		65		0.00	24,160
PAV1	Paving	L	22,400	3.10	1985		60	C	1.00	41,660
GAZ	Gazebo	L	128	15.80	1985		60	C	1.00	1,210
CLS1	Class Room	L	1,680	70.00	1985		60	C	1.00	70,560
CLS1	Class Room	L	1,380	70.00	1985		60	C	1.00	57,960
CLS1	Class Room	L	1,380	70.00	1985		60	C	1.00	57,960
CLS1	Class Room	L	1,380	70.00	1985		60	C	1.00	57,960

BUILDING SUB-AREA SUMMARY SECTION

Code	Description	Living Area	Floor Area	Eff Area	Unit Cost	Undeprec Value
BAS	First Floor	1,798	1,798	1,798	117.53	211,313
BSM	Basement	0	1,798	90	5.88	10,577
FEA	Finished 50%	885	1,770	885	58.76	104,011
FOP	Open Porch	0	1,012	202	23.46	23,740
FUS	Finished Upper Story	1,798	1,798	1,798	117.53	211,313
	Ttl Gross Liv / Lease Area	4,481	8,176	4,773		560,954

Property Location 745 BURNSIDE AVE | Map ID 47/ / 65/ / | Bldg Name | State Use 201
Vision ID 1916 | Account # 1916 | Bldg # 2 | Sec # 1 of 1 | Card # 2 of 2 | Print Date 5/1/2025 8:56:45 AM

CURRENT OWNER

BURNSIDE GARDENS LLC

330 GREAT NECK ROAD FL 2

GREAT NECK NY 11021

TOPO	UTILITIES	STRT / ROAD	LOCATION
A Good	1 All	1 Paved	

SUPPLEMENTAL DATA

Alt Prcl ID	0630-0745	Locn Suffix	
Homeown		Zoning	R-4
Census	5104	Res Area	16364
VCS	2304	Non Res A	0
# Units	2	Lot Size	2.53
Class	Com		
GIS ID		Assoc Pid#	

CURRENT ASSESSMENT

Description	Code	Appraised	Assessed
COM LAND	2-1	160,940	112,660
COM BLDG	2-2	2,033,700	1,423,590
COM OUTBL	2-5	289,240	202,460
	Total	2,483,880	1,738,710

6043

EAST HARTFORD, CT

VISION

RECORD OF OWNERSHIP

RECORD OF OWNERSHIP	BK-VOL/PAGE		SALE DATE	Q/U	V/I	SALE PRIC	VC
BURNSIDE GARDENS LLC	4226	0246	01-22-2024	U	I	600,000	B03
OLMSTED REALTY L L C	2796	0074	09-05-2006	U	I	0	B25
OLMSTEAD REALTY L L C	2677	0258	12-20-2005	U	I	0	B03
SCHEINBERG MARK E	1021	0187	12-31-1986	Q	I	200,000	NC
RANSOM RAYMOND J & SCHEINBER MARK	0953	0003	02-14-1986	Q	I	196,350	NC

PREVIOUS ASSESSMENTS (HISTORY)

Year	Code	Assessed	Year	Code	Assessed	Year	Code	Assessed
2024	2-1	112,660	2023	2-1	115,550	2022	2-1	115,550
	2-2	1,423,590		2-2	1,423,590		2-2	1,423,590
	2-5	202,460		2-5	202,460		2-5	202,460
	Total	1,738,710		Total	1,741,600		Total	1,741,600

EXEMPTIONS

Year	Code	Description	Amount
		Total	0.00

OTHER ASSESSMENTS

Code	Description	Number	Amount	Comm Int

This signature acknowledges a visit by a Data Collector or Assessor

ASSESSING NEIGHBORHOOD

Nbhd	Nbhd Name	B	Tracing	Batch
0001				

APPRAISED VALUE SUMMARY

Appraised Bldg. Value (Card)	2,006,290
Appraised Xf (B) Value (Bldg)	27,410
Appraised Ob (B) Value (Bldg)	289,240
Appraised Land Value (Bldg)	160,940
Special Land Value	0
Total Appraised Parcel Value	2,483,880
Valuation Method	C
Total Appraised Parcel Value	2,483,880

NOTES

HRNG V/D, COURT JUDGMENT, 1997. DBA

GOODWIN COLLEGE.

BUILDING PERMIT RECORD

Permit Id	Issue Date	Type	Description	Amount	Insp Date	% Comp	Date Comp	Comments

VISIT / CHANGE HISTORY

Date	Id	Type	Is	Cd	Purpost/Result

LAND LINE VALUATION SECTION

B	Use Code	Description	Zone	Land Type	Land Units		Unit Price	I. Factor	Site Index	Cond.	Nbhd.	Nhbd Adj	Notes	Location Adjustment		Adj Unit Pric	Land Value
2	201	Commercial			0.000	AC	0.00	1.00000	C	1.00	2000	1.000			0		0
					Total Card Land Units	0.0000	AC	Parcel Total Land Area:		2.4500						Total Land Value	160,940

Property Location 745 BURNSIDE AVE | Map ID 47/ / 65/ / | Bldg Name | State Use 201
Vision ID 1916 | Account # 1916 | Bldg # 2 | Sec # 1 of 1 | Card # 2 of 2 | Print Date 5/1/2025 8:56:46 AM

CONSTRUCTION DETAIL

Element	Cd	Description
Style:	28	School
Model	94	Comm/Ind
Grade	55	1.00
Stories:	2.0	
Occupancy	1.00	
Exterior Wall 1	17	Stucco/Masonry
Exterior Wall 2		
Roof Structure	03	Gable
Roof Cover	03	Asphalt
Interior Wall 1	05	Drywall
Interior Wall 2		
Interior Floor 1	14	Carpet
Interior Floor 2		
Heating Fuel	10	Other
Heating Type	04	Forced Hot Air
AC Type	04	Unit
Finished %	100	
Bldg Use	201	Commercial
Total Bedrooms	0	
Total Baths		
Num Fixtures	0	
Total Rooms	0	
Basement %	0	
Heat/AC	3	Unit AC
Frame Type	1	Wood Joist
Baths/Plumbing	02	Average
Common Wall	F	None
Wall Height	0.00	
Perimeter	382.00	
1st Floor Use:		

CONSTRUCTION DETAIL (CONTINUED)


Element	Cd	Description

MIXED USE

Code	Description	Percentage
201	Commercial	100
		0
		0

COST / MARKET VALUATION

RCN	2,078,060
Year Built	1988
Effective Year Built	2000
Depreciation Code	A
Remodel Rating	
Year Remodeled	
Depreciation %	21
Functional Obsol	
External Obsol	
Trend Factor	1
Condition	
Condition %	
Percent Good	79
RCNLD	1,641,670
Dep % Ovr	
Dep Ovr Comment	
Misc Imp Ovr	
Misc Imp Ovr Comment	
Cost to Cure Ovr	
Cost to Cure Ovr Comment	





OB - OUTBUILDING & YARD ITEMS(L) / XF - BUILDING EXTRA FEATURES(B)

Code	Description	L/B	Units	Unit Price	Yr Blt	Cond. Cd	% Good	Grade	Grade Adj	Appr. Value
GAZ	Gazebo	L	140	15.80	2000		90	C	1.00	1,930

BUILDING SUB-AREA SUMMARY SECTION

Code	Description	Living Area	Floor Area	Eff Area	Unit Cost	Undeprec Value
BAS	First Floor	7,746	7,746	7,746	161.04	1,247,416
CAN	Canopy	0	1,048	105	16.13	16,909
FOP	Open Porch	0	156	31	32.00	4,992
FUS	Finished Upper Story	5,022	5,022	5,022	161.04	808,743
SLB	Slab	0	5,022	0	0.00	0
	Ttl Gross Liv / Lease Area	12,768	18,994	12,904		2,078,060

APPENDIX D
Regulatory Database Record Search

Stone Academy
745 Burnside Avenue
East Hartford, CT 06108

Inquiry Number: 8145281.2s
October 20, 2025

The EDR Radius Map™ Report with GeoCheck®

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

LIGHTBOX LIVE

Open LightBox Live to access data, tools, and advanced analytics in one online platform.

http://www.web.edrnet.com/ordering/switchboard/login.aspx?s=goto_lightbox&pguid=BE1EC827-5C9C-4F81-A521-FC190A1564E2

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	8
Orphan Summary	594
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting SSURGO Soil Map	A-6
Physical Setting Source Map	A-21
Physical Setting Source Map Findings	A-23
Physical Setting Source Records Searched	PSGR-1

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. **NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA) INFORMATION PROVIDED IN THIS REPORT.** Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2025 by Environmental Data Resources, LLC. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, LLC, or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E1527 - 21), the ASTM Standard Practice for Environmental Site Assessments for Forestland or Rural Property (E2247 - 23), the ASTM Standard Practice for Limited Environmental Due Diligence: Transaction Screen Process (E1528 - 22) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

745 BURNSIDE AVENUE
EAST HARTFORD, CT 06108

COORDINATES

Latitude (North):	41.7792000 - 41° 46' 45.12''
Longitude (West):	72.6066850 - 72° 36' 24.06''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	698904.4
UTM Y (Meters):	4627817.0
Elevation:	75 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	20024050 MANCHESTER, CT
Version Date:	2021
Northwest Map:	20024046 HARTFORD NORTH, CT
Version Date:	2021

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from:	20230702
Source:	USDA

MAPPED SITES SUMMARY

Target Property Address:
745 BURNSIDE AVENUE
EAST HARTFORD, CT 06108

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
1	EUARTS MFG COMPANY	21 FRANCIS ST.	CT CPCS	Lower	379, 0.072, NNW
A2	SUNSET CLEANERS	700 BURNSIDE AVENUE	EDR Hist Cleaner	Lower	415, 0.079, WNW
A3	SUNSET CLEANERS	700 BURNSIDE AVE	CT MANIFEST	Lower	415, 0.079, WNW
A4	SUNSET CLEANERS	700 BURNSIDE AVE	CT MANIFEST	Lower	415, 0.079, WNW
A5	WALTAWOLK	700 BURNSIDE AVE	CT PROPERTY, CT SPILLS, CT CPCS, CT MANIFEST	Lower	415, 0.079, WNW
A6	FAMS GROUP - SUNSET	700 BURNSIDE AVENUE	CT DRYCLEANERS, CT MANIFEST	Lower	415, 0.079, WNW
A7	SUNSET CLEANERS	700 BURNSIDE AVE	CT MANIFEST	Lower	415, 0.079, WNW
A8	SUNSET CLEANERS	700 BURNSIDE AVE	CT MANIFEST	Lower	415, 0.079, WNW
A9	SUNSET CLEANERS	700 BURNSIDE AVE	RCRA NonGen / NLR	Lower	415, 0.079, WNW
B10	EAST HARTFORD MIDDLE	777 BURNSIDE AVE	CT UST	Higher	674, 0.128, East
B11	EAST HARTFORD MIDDLE	777 BURNSIDE AVE	CT LUST, CT SPILLS, CT ASBESTOS, CT CPCS, CT NPDES	Higher	674, 0.128, East
12	SAINT ROSE CHURCH CO	21 CHURCH ST	CT UST	Lower	680, 0.129, WSW
C13	EAST HARTFORD HOUSIN	COLUMBUS CIRCLE EXT.	CT LUST, CT CPCS	Lower	751, 0.142, West
C14	EAST HARTFORD NEW EN	10 SCHOOL STREET (FO	CT CPCS	Lower	810, 0.153, WNW
C15	EAST HARTFORD NEW EN	10 SCHOOL STREET (FO	UST FINDER RELEASE	Lower	810, 0.153, WNW
C16	EAST HARTFORD NEW EN	672 BURNSIDE AVE	CT UST	Lower	853, 0.162, West
C17		672 BURNSIDE AVENUE	CT LUST, CT SPILLS	Lower	853, 0.162, West
C18	GIBBS OIL	672 BURNSIDE AVE E	CT MANIFEST	Lower	853, 0.162, West
C19	CHARLOTTE COHEN	665 BURNSIDE	CT LUST	Lower	927, 0.176, West
C20	CHARLOTTE COHEN	665 BURNSIDE	CT CPCS	Lower	927, 0.176, West
C21	COHEN	665 BURNSIDE AVENUE	CT LUST	Lower	927, 0.176, West
C22	COHEN	665 BURNSIDE AVENUE	CT SPILLS, CT CPCS	Lower	927, 0.176, West
23	DERRICK WEIR	64 HANMER ST	RCRA-VSQG	Lower	1049, 0.199, NW
D24	WICKHAM MEMORIAL LIB	656 BURNSIDE AVE	CT UST	Lower	1060, 0.201, West
D25	CHUCKS AUTOMOTIVE LL	653 BURNSIDE AVE	CT UST	Lower	1085, 0.205, West
D26	CHARLIES TIRE	653 BURNSIDE AVE	CT MANIFEST	Lower	1085, 0.205, West
D27	CHUCKS AUTOMOTIVE LL	653 BURNSIDE AVE	CT LUST, CT SPILLS, CT CPCS, CT ENF	Lower	1085, 0.205, West
D28	CHARLES TIRE	653 BURNSIDE AVE	CT MANIFEST	Lower	1085, 0.205, West
E29	CELLU-TISSUE, LLC	40 FORBES STREET (AK	CT PROPERTY, CT CPCS	Lower	1097, 0.208, South
E30	DUNN PAPER - EAST HA	40 FORBES ST	CT PROPERTY, CT CPCS, CT ENF, CT NPDES	Lower	1097, 0.208, South
E31	DUNN PAPER - EAST HA	40 FORBES STREET	FINDS, PFAS ECHO	Lower	1097, 0.208, South
E32	DUNN PAPER - EAST HA	40 FORBES ST	CT UST	Lower	1097, 0.208, South
E33	CELLU TISSUE CORP	2 FORBES STREET	CT SPILLS, FTTS, HIST FTTS, CT LWDS	Lower	1110, 0.210, South
E34	DUNN PAPER - EAST HA	2 FORBES STREET	CT LUST, CT SPILLS, CT CPCS	Lower	1110, 0.210, South
E35	DUNN PAPER	2 2 FORBES STREET	E MANIFEST	Lower	1110, 0.210, South
E36	CELLU TISSUE CORP	2 FORBES ST	CT MANIFEST	Lower	1110, 0.210, South
E37	CELLU TISSUE	2 FORBES STREET	NY MANIFEST	Lower	1110, 0.210, South
E38	BIORIGIN SPECIALTY P	40 FORBES ST	RCRA-VSQG, CT SDADB, CT PROPERTY, CT SPILLS, ICIS,...	Lower	1110, 0.210, South
E39	CELLU TISSUE LLC	2 FORBES ST	CT ENF, CT MANIFEST	Lower	1110, 0.210, South

MAPPED SITES SUMMARY

Target Property Address:
745 BURNSIDE AVENUE
EAST HARTFORD, CT 06108

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
E40	CELLU TISSUE	2 FORBES ST	CT SPILLS, CT MANIFEST	Lower	1110, 0.210, South
41	CHUCKS AUTOMOTIVE	635 BURNSIDE AVE	RCRA-VSQG, FINDS, ECHO	Lower	1259, 0.238, West
42	BERNIE BODINE, ESTAT	66 SCHOOL ST.	CT LUST, CT SPILLS, CT CPCS	Lower	1341, 0.254, WNW
43	POLICE DEPARTMENT	497 TOLLAND STREET	CT LUST, CT CPCS	Lower	1357, 0.257, WNW
F44	CRESTWOOD PRODUCTS (	672 TOLLAND STREET	CT PROPERTY, CT CPCS	Higher	1396, 0.264, North
F45	CRESTWOOD PRODUCTS	672 TOLLAND STREET	CT PROPERTY, CT CPCS	Higher	1396, 0.264, North
F46	NEWMAN CHRYSLER JEEP	630 TOLLAND STREET	CT PROPERTY, CT CPCS	Lower	1409, 0.267, North
F47	GENGRAS COLLISION CE	630 TOLLAND ST	CT CPCS	Lower	1409, 0.267, North
F48	CRESTWOOD PRODUCTS	654 & 672 TOLLDAND S	CT SDADB	Lower	1555, 0.295, North
F49	CRESTWOOD PRODUCTS	654 TOLLAND STREET	CT PROPERTY, CT CPCS	Lower	1555, 0.295, North
F50	CRESTWOOD PRODUCTS (	654 & 672 TOLLAND ST	CT PROPERTY, CT CPCS	Lower	1555, 0.295, North
51	TOLLAND CORPORATION	676-678 TOLLAND STRE	CT SDADB, CT PROPERTY, CT CPCS	Lower	1685, 0.319, NNE
G52	590 BURNSIDE AVENUE	590 BURNSIDE AVENUE	CT BROWNFIELDS	Lower	1914, 0.363, West
G53	DALEY COURT	590 BURNSIDE AVE	US BROWNFIELDS, FINDS	Lower	1914, 0.363, West
G54	DALEY COURT	590 BURNSIDE AVENUE	CT BROWNFIELDS	Lower	1914, 0.363, West
G55	590 BURNSIDE AVENUE	590 BURNSIDE AVENUE	CT BROWNFIELDS	Lower	1914, 0.363, West
H56	SHELL FACILITY #1363	123 SCHOOL STREET	CT LUST, CT PROPERTY, CT SPILLS, CT CPCS	Lower	2057, 0.390, NW
H57	SHELL SERVICE STATIO	123 SCHOOL ST	CT SPILLS, CT CPCS, CT ENF, CT MANIFEST	Lower	2057, 0.390, NW
H58	SHELL SERVICE STATIO	123 SCHOOL STREET	UST FINDER RELEASE	Lower	2057, 0.390, NW
59	STANDARD WELDING	470 TOLLAND STREET	CT SDADB	Lower	2079, 0.394, WNW
I60	LTV STEEL CO., INC.	164 SCHOOL STREET	CT CPCS	Lower	2145, 0.406, NW
I61	UNITED STEEL INC.	164 164 SCHOOL STREE	SEMS-ARCHIVE, RCRA NonGen / NLR, E MANIFEST, RI...	Lower	2145, 0.406, NW
I62	LTV STEEL CO., INC.	164 SCHOOL STREET	CT AUL, CT PROPERTY	Lower	2145, 0.406, NW
I63	UNITED STEEL	164 SCHOOL STREEET	CT SDADB, US BROWNFIELDS, ICIS, US AIRS, FINDS,...	Lower	2145, 0.406, NW
J64	EBL PRODUCTS INC	91 PRESTIGE PARK CIR	CT PROPERTY, RCRA NonGen / NLR, E MANIFEST, CT...	Lower	2168, 0.411, NNE
J65	STAVELEY SENSORS, IN	91 PRESTIGE PARK CIR	CT PROPERTY, CT CPCS	Lower	2168, 0.411, NNE
K66	FORMER BURNSIDE APAR	550 BURNSIDE AVENUE/	CT BROWNFIELDS	Lower	2254, 0.427, West
K67	VACANT LOT	550 BURNSIDE AVENUE	US BROWNFIELDS	Lower	2254, 0.427, West
68	EBL PRODUCTS INC.	22 PRESTIGE PARK CIR	CT PROPERTY, CT CPCS, CT ENF, CT MANIFEST, CT...	Lower	2319, 0.439, North
L69	ENERGY NETWORKS INC	111 PRESTIGE PARK RD	CT PROPERTY, CT CPCS, CT MANIFEST	Lower	2362, 0.447, NNW
L70	PRESTIGE INDUSTRIAL	121 PRESTIGE PARK RO	UST FINDER RELEASE	Lower	2391, 0.453, NNW
L71		121 PRESTIGE PARK RO	CT LUST	Lower	2391, 0.453, NNW
L72	PRESTIGE INDUSTRIAL	121 PRESTIGE PARK RO	CT CPCS	Lower	2391, 0.453, NNW
M73	ATLAS OIL	422 TOLLAND STREET	CT SDADB, CT CPCS	Lower	2393, 0.453, WNW
M74		422 TOLLAND ST	CT LUST, CT SPILLS	Lower	2393, 0.453, WNW
N75	ADAPTIVE OPTICS ASSO	121 PRESTIGE PARK CI	CT PROPERTY, RCRA NonGen / NLR, FINDS, ECHO, E...	Lower	2400, 0.455, NNE
O76	CHESTER/FORBES PROPE	10 CHESTER STREET AN	US BROWNFIELDS	Higher	2416, 0.458, SSE
O77	CHESTER/FORBES PROPE	10 CHESTER STREET AN	CT BROWNFIELDS	Higher	2416, 0.458, SSE
P78	QUALEX, INC.	88 PRESTIGE PARK CIR	CT CPCS	Lower	2522, 0.478, NNE

MAPPED SITES SUMMARY

Target Property Address:
745 BURNSIDE AVENUE
EAST HARTFORD, CT 06108

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
P79	QUALEX INC.	88 PRESTIGE PARK CIR	CT SDADB	Lower	2522, 0.478, NNE
N80	CT BUSINESS SYSTEMS	265 PRESTIGE PARK RD	CT PROPERTY, RCRA NonGen / NLR, FINDS, ECHO, CT...	Lower	2581, 0.489, NNE
N81	BAUSCH & LOMB ASTRON	135 PRESTIGE PK CIR	CT PROPERTY, RCRA NonGen / NLR, FINDS, ECHO, CT...	Lower	2581, 0.489, NNE
Q82	ATLAS OIL	414 TOLLAND STREET	UST FINDER RELEASE	Lower	2619, 0.496, WNW
Q83	THE ATLAS OIL CO.	414 TOLLAND ST	CT LUST, CT SPILLS, CT CPCS, CT ENF	Lower	2619, 0.496, WNW

EXECUTIVE SUMMARY

TARGET PROPERTY SEARCH RESULTS

The target property was not listed in any of the databases searched by EDR.

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal NPL (Superfund) sites

NPL ---------- National Priority List
Proposed NPL ---------- Proposed National Priority List Sites
NPL LIENS ---------- Federal Superfund Liens

Lists of Federal Delisted NPL sites

Delisted NPL ---------- National Priority List Deletions

Lists of Federal sites subject to CERCLA removals and CERCLA orders

FEDERAL FACILITY ---------- Federal Facility Site Information listing
SEMS ---------- Superfund Enterprise Management System

Lists of Federal RCRA facilities undergoing Corrective Action

CORRACTS ---------- Corrective Action Report

Lists of Federal RCRA TSD facilities

RCRA-TSDF ---------- RCRA - Treatment, Storage and Disposal

Lists of Federal RCRA generators

RCRA-LQG ---------- RCRA - Large Quantity Generators
RCRA-SQG ---------- RCRA - Small Quantity Generators

Federal institutional controls / engineering controls registries

LUCIS ---------- Land Use Control Information System
US ENG CONTROLS ---------- Engineering Controls Sites List
US INST CONTROLS ---------- Institutional Controls Sites List

Federal ERNS list

ERNS ---------- Emergency Response Notification System

EXECUTIVE SUMMARY

Lists of state- and tribal hazardous waste facilities

CT SHWS ..... Inventory of Hazardous Disposal Sites

Lists of state and tribal landfills and solid waste disposal facilities

CT SWF/LF ..... List of Landfills/Transfer Stations

Lists of state and tribal leaking storage tanks

INDIAN LUST ..... Leaking Underground Storage Tanks on Indian Land

Lists of state and tribal registered storage tanks

FEMA UST ..... Underground Storage Tank Listing
CT AST ..... Marine Terminals and Tank Information
INDIAN UST ..... Underground Storage Tanks on Indian Land

State and tribal institutional control / engineering control registries

CT ENG CONTROLS ..... Engineering Controls Listing

Lists of state and tribal voluntary cleanup sites

CT VCP ..... Voluntary Remediation Sites
INDIAN VCP ..... Voluntary Cleanup Priority Listing

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Landfill / Solid Waste Disposal Sites

CT SWRCY ..... Recycling Facilities
INDIAN ODI ..... Report on the Status of Open Dumps on Indian Lands
DEBRIS REGION 9 ..... Torres Martinez Reservation Illegal Dump Site Locations
ODI ..... Open Dump Inventory
IHS OPEN DUMPS ..... Open Dumps on Indian Land

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL ..... Delisted National Clandestine Laboratory Register
CT CDL ..... Clandestine Drug Lab Listing
US CDL ..... National Clandestine Laboratory Register

Local Land Records

CT LIENS ..... Environmental Liens Listing
LIENS 2 ..... CERCLA Lien Information

Records of Emergency Release Reports

HMIRS ..... Hazardous Materials Information Reporting System
CT SPILLS 90 ..... SPILLS 90 data from FirstSearch

Other Ascertainable Records

FUDS ..... Formerly Used Defense Sites

DOD ---- Department of Defense Sites
SCRD DRYCLEANERS ---- State Coalition for Remediation of Drycleaners Listing
US FIN ASSUR ---- Financial Assurance Information
EPA WATCH LIST ---- EPA WATCH LIST
2020 COR ACTION ---- 2020 Corrective Action Program List
TSCA ---- Toxic Substances Control Act
TRIS ---- Toxic Chemical Release Inventory System
SSTS ---- Section 7 Tracking Systems
ROD ---- Records Of Decision
RMP ---- Risk Management Plans
RAATS ---- RCRA Administrative Action Tracking System
PRP ---- Potentially Responsible Parties
PADS ---- PCB Activity Database System
MLTS ---- Material Licensing Tracking System
COAL ASH DOE ---- Steam-Electric Plant Operation Data
COAL ASH EPA ---- Coal Combustion Residues Surface Impoundments List
PCB TRANSFORMER ---- PCB Transformer Registration Database
RADINFO ---- Radiation Information Database
DOT OPS ---- Incident and Accident Data
CONSENT ---- Superfund (CERCLA) Consent Decrees
INDIAN RESERV ---- Indian Reservations
FUSRAP ---- Formerly Utilized Sites Remedial Action Program
UMTRA ---- Uranium Mill Tailings Sites
LEAD SMELTERS ---- Lead Smelter Sites
US MINES ---- Mines Master Index File
MINES MRDS ---- Mineral Resources Data System
ABANDONED MINES ---- Abandoned Mines
UXO ---- Unexploded Ordnance Sites
DOCKET HWC ---- Hazardous Waste Compliance Docket Listing
FUELS PROGRAM ---- EPA Fuels Program Registered Listing
PFAS NPL ---- Superfund Sites with PFAS Detections Information
PFAS FEDERAL SITES ---- Federal Sites PFAS Information
PFAS TSCA ---- PFAS Manufacture and Imports Information
PFAS TRIS ---- List of PFAS Added to the TRI
PFAS RCRA MANIFEST ---- PFAS Transfers Identified In the RCRA Database Listing
PFAS ATSDR ---- PFAS Contamination Site Location Listing
PFAS WQP ---- Ambient Environmental Sampling for PFAS
PFAS PROJECT ---- NORTHEASTERN UNIVERSITY PFAS PROJECT
PFAS NPDES ---- Clean Water Act Discharge Monitoring Information
PFAS ECHO FIRE TRAIN ---- Facilities in Industries that May Be Handling PFAS Listing
PFAS PT 139 AIRPORT ---- All Certified Part 139 Airports PFAS Information Listing
AQUEOUS FOAM NRC ---- Aqueous Foam Related Incidents Listing
BIOSOLIDS ---- ICIS-NPDES Biosolids Facility Data
UST FINDER ---- UST Finder Database
CT PFAS ---- PFAS Contamination Site Listing
CT AIRS ---- Permitted Air Sources Listing
CT Financial Assurance ---- Financial Assurance Information Listing
CT LEAD ---- Lead Inspection Database
CT SEH ---- List of Significant Environmental Hazards Report to DEEP
CT UIC ---- Underground Injection Control Listing

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP ---- EDR Proprietary Manufactured Gas Plants

EXECUTIVE SUMMARY

EDR Hist Auto..... EDR Exclusive Historical Auto Stations

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

CT RGA HWS..... Recovered Government Archive State Hazardous Waste Facilities List
CT RGA LUST..... Recovered Government Archive Leaking Underground Storage Tank

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal CERCLA sites with NFRAP

SEMS-ARCHIVE: SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

A review of the SEMS-ARCHIVE list, as provided by EDR, and dated 06/26/2025 has revealed that there is 1 SEMS-ARCHIVE site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
UNITED STEEL INC. Site ID: 0100050 EPA Id: CTD001159490	***164 164 SCHOOL STREE***	***NW 1/4 - 1/2 (0.406 mi.)***	***I61***	***446***

EXECUTIVE SUMMARY

Lists of Federal RCRA generators

RCRA-VSQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-VSQG list, as provided by EDR, and dated 06/02/2025 has revealed that there are 3 RCRA-VSQG sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
DERRICK WEIR EPA ID:: CTP000035503	64 HANMER ST	NW 1/8 - 1/4 (0.199 mi.)	23	75
BIORIGIN SPECIALTY P EPA ID:: CTD047714142	***40 FORBES ST***	***S 1/8 - 1/4 (0.210 mi.)***	***E38***	***350***
CHUCKS AUTOMOTIVE EPA ID:: CTR000505032	***635 BURNSIDE AVE***	***W 1/8 - 1/4 (0.238 mi.)***	***41***	***381***

Lists of state- and tribal hazardous waste facilities

CT SDADB: Site Discovery and Assessment Database.

A review of the CT SDADB list, as provided by EDR, and dated 04/23/2010 has revealed that there are 7 CT SDADB sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
BIORIGIN SPECIALTY P Facility Id: 4081	***40 FORBES ST***	***S 1/8 - 1/4 (0.210 mi.)***	***E38***	***350***
CRESTWOOD PRODUCTS Facility Id: 5562	654 & 672 TOLLDAND S	N 1/4 - 1/2 (0.295 mi.)	F48	406
TOLLAND CORPORATION Facility Id: 4100	***676-678 TOLLAND STRE***	***NNE 1/4 - 1/2 (0.319 mi.)***	***51***	***416***
STANDARD WELDING Facility Id: 1825	470 TOLLAND STREET	WNW 1/4 - 1/2 (0.394 mi.)	59	443
UNITED STEEL Facility Id: 586	***164 SCHOOL STREEET***	***NW 1/4 - 1/2 (0.406 mi.)***	***I63***	***481***
ATLAS OIL Facility Id: 2505	***422 TOLLAND STREET***	***WNW 1/4 - 1/2 (0.453 mi.)***	***M73***	***542***
QUALEX INC. Facility Id: 5551	88 PRESTIGE PARK CIR	NNE 1/4 - 1/2 (0.478 mi.)	P79	573

Lists of state and tribal leaking storage tanks

CT LUST: The Leaking Underground Storage Tank Incident Reports contain an inventory of reported leaking underground storage tank incidents. The data come from the Department of Environmental Protection's Leaking Underground Storage Tank List.

A review of the CT LUST list, as provided by EDR, and dated 06/13/2025 has revealed that there are 13 CT LUST sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
EAST HARTFORD MIDDLE LUST Id: 61409	***777 BURNSIDE AVE***	***E 1/8 - 1/4 (0.128 mi.)***	***B11***	***42***

Lower Elevation	Address	Direction / Distance	Map ID	Page
EAST HARTFORD HOUSIN LUST Id: 29496	***COLUMBUS CIRCLE EXT.***	***W 1/8 - 1/4 (0.142 mi.)***	***C13***	***56***
Not reported LUST Id: 48682	***672 BURNSIDE AVENUE***	***W 1/8 - 1/4 (0.162 mi.)***	***C17***	***64***
CHARLOTTE COHEN LUST Id: 29305	665 BURNSIDE	W 1/8 - 1/4 (0.176 mi.)	C19	71
COHEN LUST Id: 31975	665 BURNSIDE AVENUE	W 1/8 - 1/4 (0.176 mi.)	C21	72
CHUCKS AUTOMOTIVE LL LUST Id: 59401	***653 BURNSIDE AVE***	***W 1/8 - 1/4 (0.205 mi.)***	***D27***	***281***
DUNN PAPER - EAST HA LUST Id: 32398	***2 FORBES STREET***	***S 1/8 - 1/4 (0.210 mi.)***	***E34***	***325***
BERNIE BODINE, ESTAT LUST Id: 34294	***66 SCHOOL ST.***	***WNW 1/4 - 1/2 (0.254 mi.)***	***42***	***385***
POLICE DEPARTMENT LUST Id: 60747	***497 TOLLAND STREET***	***WNW 1/4 - 1/2 (0.257 mi.)***	***43***	***390***
SHELL FACILITY #1363 LUST Id: 48752	***123 SCHOOL STREET***	***NW 1/4 - 1/2 (0.390 mi.)***	***H56***	***428***
Not reported LUST Id: 35517	121 PRESTIGE PARK RO	NNW 1/4 - 1/2 (0.453 mi.)	L71	538
Not reported LUST Id: 35512	***422 TOLLAND ST***	***WNW 1/4 - 1/2 (0.453 mi.)***	***M74***	***544***
THE ATLAS OIL CO. LUST Id: 35511	***414 TOLLAND ST***	***WNW 1/4 - 1/2 (0.496 mi.)***	***Q83***	***588***

Lists of state and tribal registered storage tanks

CT UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Protection's "Town Inventory" UST Listing.

A review of the CT UST list, as provided by EDR, and dated 05/13/2025 has revealed that there are 6

CT UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
EAST HARTFORD MIDDLE Facility Id: 43-5189 Tank Status: Permanently Closed	777 BURNSIDE AVE	E 1/8 - 1/4 (0.128 mi.)	B10	36

Lower Elevation	Address	Direction / Distance	Map ID	Page
SAINT ROSE CHURCH CO Facility Id: 43-9128 Tank Status: Permanently Closed	21 CHURCH ST	WSW 1/8 - 1/4 (0.129 mi.)	12	54
EAST HARTFORD NEW EN Facility Id: 43-5522 Tank Status: Permanently Closed	672 BURNSIDE AVE	W 1/8 - 1/4 (0.162 mi.)	C16	61
WICKHAM MEMORIAL LIB Facility Id: 43-9896 Tank Status: Permanently Closed	656 BURNSIDE AVE	W 1/8 - 1/4 (0.201 mi.)	D24	77
CHUCKS AUTOMOTIVE LL Facility Id: 43-5508 Tank Status: Permanently Closed Tank Status: Currently In Use	653 BURNSIDE AVE	W 1/8 - 1/4 (0.205 mi.)	D25	78
DUNN PAPER - EAST HA Facility Id: 43-5066 Tank Status: Permanently Closed	40 FORBES ST	S 1/8 - 1/4 (0.208 mi.)	E32	310

State and tribal institutional control / engineering control registries

CT AUL: Environmental Land Use Restriction sites .

A review of the CT AUL list, as provided by EDR, and dated 06/03/2025 has revealed that there is 1 CT AUL site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
LTV STEEL CO., INC. Facility Id: 1640	***164 SCHOOL STREET***	***NW 1/4 - 1/2 (0.406 mi.)***	***I62***	***477***

Lists of state and tribal brownfield sites

Brownfields Inventory From Connecticut Brownfields Redevelopment Authority.

A review of the CT BROWNFIELDS list, as provided by EDR, has revealed that there are 5 CT BROWNFIELDS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CHESTER/FORBES PROPE Database: BROWNFIELDS 2, Date of Government Version: 06/11/2024	10 CHESTER STREET AN	SSE 1/4 - 1/2 (0.458 mi.)	O77	571

Lower Elevation	Address	Direction / Distance	Map ID	Page
590 BURNSIDE AVENUE Database: BROWNFIELDS, Date of Government Version: 02/11/2025	590 BURNSIDE AVENUE	W 1/4 - 1/2 (0.363 mi.)	G52	420

Lower Elevation	Address	Direction / Distance	Map ID	Page
DALEY COURT Database: BROWNFIELDS 2, Date of Government Version: 06/11/2024	590 BURNSIDE AVENUE	W 1/4 - 1/2 (0.363 mi.)	G54	427
590 BURNSIDE AVENUE Database: BROWNFIELDS, Date of Government Version: 02/11/2025	590 BURNSIDE AVENUE	W 1/4 - 1/2 (0.363 mi.)	G55	427
FORMER BURNSIDE APAR Database: BROWNFIELDS 2, Date of Government Version: 06/11/2024	550 BURNSIDE AVENUE/	W 1/4 - 1/2 (0.427 mi.)	K66	522

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: The EPA's listing of Brownfields properties from the Cleanups in My Community program, which provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

A review of the US BROWNFIELDS list, as provided by EDR, and dated 09/09/2024 has revealed that there are 4 US BROWNFIELDS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CHESTER/FORBES PROPE	10 CHESTER STREET AN	SSE 1/4 - 1/2 (0.458 mi.)	O76	563

Lower Elevation	Address	Direction / Distance	Map ID	Page
DALEY COURT Cleanup Completion Date: 10/16/2018	***590 BURNSIDE AVE***	***W 1/4 - 1/2 (0.363 mi.)***	***G53***	***420***
UNITED STEEL	***164 SCHOOL STREEET***	***NW 1/4 - 1/2 (0.406 mi.)***	***I63***	***481***
VACANT LOT	550 BURNSIDE AVENUE	W 1/4 - 1/2 (0.427 mi.)	K67	522

Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 06/02/2025 has revealed that there is 1 RCRA NonGen / NLR site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
SUNSET CLEANERS EPA ID:: CTD021816541	700 BURNSIDE AVE	WNW 0 - 1/8 (0.079 mi.)	A9	33

EXECUTIVE SUMMARY

PFAS ECHO: Regulators and the public have expressed interest in knowing which regulated entities may be using PFAS. EPA has developed a dataset from various sources that show which industries may be handling PFAS. Approximately 120,000 facilities subject to federal environmental programs have operated or currently operate in industry sectors with processes that may involve handling and/or release of PFAS.

A review of the PFAS ECHO list, as provided by EDR, and dated 06/23/2025 has revealed that there is 1 PFAS ECHO site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
DUNN PAPER - EAST HA	***40 FORBES STREET***	***S 1/8 - 1/4 (0.208 mi.)***	***E31***	***308***

UST FINDER RELEASE: US EPA's UST Finder data is a national composite of leaking underground storage tanks. This data contains information about, and locations of, leaking underground storage tanks. Data was collected from state sources and standardized into a national profile by EPA's Office of Underground Storage Tanks, Office of Research and Development, and the Association of State and Territorial Solid Waste Management Officials.

A review of the UST FINDER RELEASE list, as provided by EDR, and dated 06/08/2023 has revealed that there are 4 UST FINDER RELEASE sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
EAST HARTFORD NEW EN	10 SCHOOL STREET (FO	WNW 1/8 - 1/4 (0.153 mi.)	C15	60
SHELL SERVICE STATIO	123 SCHOOL STREET	NW 1/4 - 1/2 (0.390 mi.)	H58	442
PRESTIGE INDUSTRIAL	121 PRESTIGE PARK RO	NNW 1/4 - 1/2 (0.453 mi.)	L70	537
ATLAS OIL	414 TOLLAND STREET	WNW 1/4 - 1/2 (0.496 mi.)	Q82	587

E MANIFEST: EPA established a national system for tracking hazardous waste shipments electronically. This system, known as ?e-Manifest,? will modernize the nation?s cradle-to-grave hazardous waste tracking process while saving valuable time, resources, and dollars for industry and states.

A review of the E MANIFEST list, as provided by EDR, and dated 06/02/2025 has revealed that there is 1 E MANIFEST site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
DUNN PAPER	2 2 FORBES STREET	S 1/8 - 1/4 (0.210 mi.)	E35	332

CT CPCS: A list of Contaminated or Potentially Contaminated Sites within Connecticut. This list represents the "Hazardous Waste Facilities," as defined in Section 22a-134f of the Connecticut General Statutes (CGS). The list contains the following types of sites: Sites listed on the Inventory of Hazardous Waste Disposal Sites; Sites subject to the Property Transfer Act; Sites at which underground storage tanks are known to have leaked; Sites at which hazardous waste subject to the RCRA; Sites that are included in EPA's (CERCLIS); Sites that are the subject of an order issued by the Commissioner of DEP that requires investigation and remediation of a potential or known source of pollution; and Sites that have entered into one of the Department's Voluntary Remediation Programs.

A review of the CT CPCS list, as provided by EDR, and dated 07/21/2025 has revealed that there are 35 CT CPCS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
EAST HARTFORD MIDDLE	***777 BURNSIDE AVE***	***E 1/8 - 1/4 (0.128 mi.)***	***B11***	***42***
CRESTWOOD PRODUCTS (	***672 TOLLAND STREET***	***N 1/4 - 1/2 (0.264 mi.)***	***F44***	***394***
CRESTWOOD PRODUCTS	***672 TOLLAND STREET***	***N 1/4 - 1/2 (0.264 mi.)***	***F45***	***396***

EXECUTIVE SUMMARY

Lower Elevation	Address	Direction / Distance	Map ID	Page
EUARTS MFG COMPANY	21 FRANCIS ST.	NNW 0 - 1/8 (0.072 mi.)	1	8
Lust Status: LUST Completed (DEP's significant hazard definition)				
WALTAWOLK	***700 BURNSIDE AVE***	***WNW 0 - 1/8 (0.079 mi.)***	***A5***	***14***
EAST HARTFORD HOUSIN	***COLUMBUS CIRCLE EXT.***	***W 1/8 - 1/4 (0.142 mi.)***	***C13***	***56***
Lust Status: LUST Completed (DEP's significant hazard definition)				
EAST HARTFORD NEW EN	10 SCHOOL STREET (FO	WNW 1/8 - 1/4 (0.153 mi.)	C14	60
CHARLOTTE COHEN	665 BURNSIDE	W 1/8 - 1/4 (0.176 mi.)	C20	72
Lust Status: Pending				
COHEN	***665 BURNSIDE AVENUE***	***W 1/8 - 1/4 (0.176 mi.)***	***C22***	***72***
Lust Status: LUST Completed (DEP's significant hazard definition)				
CHUCKS AUTOMOTIVE LL	***653 BURNSIDE AVE***	***W 1/8 - 1/4 (0.205 mi.)***	***D27***	***281***
CELLU-TISSUE, LLC	***40 FORBES STREET (AK***	***S 1/8 - 1/4 (0.208 mi.)***	***E29***	***291***
DUNN PAPER - EAST HA	***40 FORBES ST***	***S 1/8 - 1/4 (0.208 mi.)***	***E30***	***293***
DUNN PAPER - EAST HA	***2 FORBES STREET***	***S 1/8 - 1/4 (0.210 mi.)***	***E34***	***325***
BIORIGIN SPECIALTY P	***40 FORBES ST***	***S 1/8 - 1/4 (0.210 mi.)***	***E38***	***350***
BERNIE BODINE, ESTAT	***66 SCHOOL ST.***	***WNW 1/4 - 1/2 (0.254 mi.)***	***42***	***385***
Lust Status: LUST Completed (DEP's significant hazard definition)				
POLICE DEPARTMENT	***497 TOLLAND STREET***	***WNW 1/4 - 1/2 (0.257 mi.)***	***43***	***390***
NEWMAN CHRYSLER JEEP	***630 TOLLAND STREET***	***N 1/4 - 1/2 (0.267 mi.)***	***F46***	***399***
GENGRAS COLLISION CE	630 TOLLAND ST	N 1/4 - 1/2 (0.267 mi.)	F47	406
CRESTWOOD PRODUCTS	***654 TOLLAND STREET***	***N 1/4 - 1/2 (0.295 mi.)***	***F49***	***408***
CRESTWOOD PRODUCTS (	***654 & 672 TOLLAND ST***	***N 1/4 - 1/2 (0.295 mi.)***	***F50***	***413***
TOLLAND CORPORATION	***676-678 TOLLAND STRE***	***NNE 1/4 - 1/2 (0.319 mi.)***	***51***	***416***
SHELL FACILITY #1363	***123 SCHOOL STREET***	***NW 1/4 - 1/2 (0.390 mi.)***	***H56***	***428***
SHELL SERVICE STATIO	***123 SCHOOL ST***	***NW 1/4 - 1/2 (0.390 mi.)***	***H57***	***436***
LTV STEEL CO., INC.	164 SCHOOL STREET	NW 1/4 - 1/2 (0.406 mi.)	I60	445
EBL PRODUCTS INC	***91 PRESTIGE PARK CIR***	***NNE 1/4 - 1/2 (0.411 mi.)***	***J64***	***495***
STAVELEY SENSORS, IN	***91 PRESTIGE PARK CIR***	***NNE 1/4 - 1/2 (0.411 mi.)***	***J65***	***513***
EBL PRODUCTS INC.	***22 PRESTIGE PARK CIR***	***N 1/4 - 1/2 (0.439 mi.)***	***68***	***529***
ENERGY NETWORKS INC	***111 PRESTIGE PARK RD***	***NNW 1/4 - 1/2 (0.447 mi.)***	***L69***	***534***
PRESTIGE INDUSTRIAL	121 PRESTIGE PARK RO	NNW 1/4 - 1/2 (0.453 mi.)	L72	541
ATLAS OIL	***422 TOLLAND STREET***	***WNW 1/4 - 1/2 (0.453 mi.)***	***M73***	***542***
ADAPTIVE OPTICS ASSO	***121 PRESTIGE PARK CI***	***NNE 1/4 - 1/2 (0.455 mi.)***	***N75***	***549***
QUALEX, INC.	88 PRESTIGE PARK CIR	NNE 1/4 - 1/2 (0.478 mi.)	P78	572
CT BUSINESS SYSTEMS	***265 PRESTIGE PARK RD***	***NNE 1/4 - 1/2 (0.489 mi.)***	***N80***	***574***
BAUSCH & LOMB ASTRON	***135 PRESTIGE PK CIR***	***NNE 1/4 - 1/2 (0.489 mi.)***	***N81***	***579***
THE ATLAS OIL CO.	***414 TOLLAND ST***	***WNW 1/4 - 1/2 (0.496 mi.)***	***Q83***	***588***

CT DRYCLEANERS: A listing of drycleaner facility locations.

A review of the CT DRYCLEANERS list, as provided by EDR, has revealed that there is 1 CT DRYCLEANERS site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
FAMS GROUP - SUNSET	***700 BURNSIDE AVENUE***	***WNW 0 - 1/8 (0.079 mi.)***	***A6***	***19***
Database: DRYCLEANERS 2, Date of Government Version: 02/11/2025				

EXECUTIVE SUMMARY

CT LWDS: The Leachate and Waste Water Discharge Inventory Data Layer (LWDS) includes point locations digitized from Leachate and Wastewater Discharge Source maps compiled by the Connecticut DEP.

A review of the CT LWDS list, as provided by EDR, and dated 07/17/2009 has revealed that there is 1 CT LWDS site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
CELLU TISSUE CORP	***2 FORBES STREET***	***S 1/8 - 1/4 (0.210 mi.)***	***E33***	***311***
Leachate and Wastewater Number: 4500036				
Leachate and Wastewater Number: 4500037				

CT MANIFEST: Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

A review of the CT MANIFEST list, as provided by EDR, and dated 07/30/2025 has revealed that there are 12 CT MANIFEST sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
SUNSET CLEANERS	700 BURNSIDE AVE	WNW 0 - 1/8 (0.079 mi.)	A3	9
EPA Id: CTP000005742				
SUNSET CLEANERS	700 BURNSIDE AVE	WNW 0 - 1/8 (0.079 mi.)	A4	13
EPA Id: CTP000005177				
WALTAWOLK	***700 BURNSIDE AVE***	***WNW 0 - 1/8 (0.079 mi.)***	***A5***	***14***
EPA Id: CT$000028870				
FAMS GROUP - SUNSET	***700 BURNSIDE AVENUE***	***WNW 0 - 1/8 (0.079 mi.)***	***A6***	***19***
EPA Id: CTP000001770				
SUNSET CLEANERS	700 BURNSIDE AVE	WNW 0 - 1/8 (0.079 mi.)	A7	23
EPA Id: CTP000005054				
SUNSET CLEANERS	700 BURNSIDE AVE	WNW 0 - 1/8 (0.079 mi.)	A8	24
EPA Id: CTD021816541				
GIBBS OIL	672 BURNSIDE AVE E	W 1/8 - 1/4 (0.162 mi.)	C18	70
EPA Id: CT8602827701				
CHARLIES TIRE	653 BURNSIDE AVE	W 1/8 - 1/4 (0.205 mi.)	D26	280
EPA Id: CTP000007998				
CHARLES TIRE	653 BURNSIDE AVE	W 1/8 - 1/4 (0.205 mi.)	D28	290
EPA Id: CTP000007897				
CELLU TISSUE CORP	2 FORBES ST	S 1/8 - 1/4 (0.210 mi.)	E36	340
EPA Id: CTD047714142				
EPA Id: CTP000016453				
CELLU TISSUE LLC	***2 FORBES ST***	***S 1/8 - 1/4 (0.210 mi.)***	***E39***	***377***
EPA Id: CTD04771412				
CELLU TISSUE	***2 FORBES ST***	***S 1/8 - 1/4 (0.210 mi.)***	***E40***	***378***
EPA Id: CTP000005096				

NY MANIFEST: Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

A review of the NY MANIFEST list, as provided by EDR, and dated 12/31/2019 has revealed that there is 1 NY MANIFEST site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
CELLU TISSUE EPA ID: CTP000005096	2 FORBES STREET	S 1/8 - 1/4 (0.210 mi.)	E37	348

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR Hist Cleaner: EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.


A review of the EDR Hist Cleaner list, as provided by EDR, has revealed that there is 1 EDR Hist Cleaner site within approximately 0.125 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
SUNSET CLEANERS	700 BURNSIDE AVENUE	WNW 0 - 1/8 (0.079 mi.)	A2	8

EXECUTIVE SUMMARY

There were no unmapped sites in this report.

OVERVIEW MAP - 8145281.2S



Target Property

Sites at elevations higher than or equal to the target property

Sites at elevations lower than the target property

Manufactured Gas Plants

National Priority List Sites

Dept. Defense Sites

0 1/4 1/2 1 Miles

Indian Reservations BIA

Power transmission lines

Pipelines

Special Flood Hazard Area (1%)

0.2% Annual Chance Flood Hazard

National Wetland Inventory


State Wetlands

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	Stone Academy	CLIENT:	HRP Associates, Inc.
ADDRESS:	745 Burnside Avenue East Hartford CT 06108	CONTACT:	Joy Waters
		INQUIRY #:	8145281.2s
LAT/LONG:	41.7792 / 72.606685	DATE:	October 20, 2025 1:37 pm

Copyright © 2025 EDR, Inc. © 2015 TomTom Rel. 2015.

DETAIL MAP - 8145281.2S



0 1/16 1/8 1/4 Miles

- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- Sensitive Receptors
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- Special Flood Hazard Area (1%)
- 0.2% Annual Chance Flood Hazard
- National Wetland Inventory
- State Wetlands

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME: Stone Academy	CLIENT: HRP Associates, Inc.
ADDRESS: 745 Burnside Avenue East Hartford CT 06108	CONTACT: Joy Waters INQUIRY #: 8145281.2s
LAT/LONG: 41.7792 / 72.606685	DATE: October 20, 2025 1:39 pm

Copyright © 2025 EDR, Inc. © 2015 TomTom Rel. 2015.

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Lists of Federal NPL (Superfund) sites								
NPL	1.000		0	0	0	0	NR	0
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	1.000		0	0	0	0	NR	0
Lists of Federal Delisted NPL sites								
Delisted NPL	1.000		0	0	0	0	NR	0
Lists of Federal sites subject to CERCLA removals and CERCLA orders								
FEDERAL FACILITY	0.500		0	0	0	NR	NR	0
SEMS	0.500		0	0	0	NR	NR	0
Lists of Federal CERCLA sites with NFRAP								
SEMS-ARCHIVE	0.500		0	0	1	NR	NR	1
Lists of Federal RCRA facilities undergoing Corrective Action								
CORRACTS	1.000		0	0	0	0	NR	0
Lists of Federal RCRA TSD facilities								
RCRA-TSDF	0.500		0	0	0	NR	NR	0
Lists of Federal RCRA generators								
RCRA-LQG	0.250		0	0	NR	NR	NR	0
RCRA-SQG	0.250		0	0	NR	NR	NR	0
RCRA-VSQG	0.250		0	3	NR	NR	NR	3
Federal institutional controls / engineering controls registries								
LUCIS	0.500		0	0	0	NR	NR	0
US ENG CONTROLS	0.500		0	0	0	NR	NR	0
US INST CONTROLS	0.500		0	0	0	NR	NR	0
Federal ERNS list								
ERNS	TP		NR	NR	NR	NR	NR	0
Lists of state- and tribal hazardous waste facilities								
CT SHWS	1.000		0	0	0	0	NR	0
CT SDADB	0.500		0	1	6	NR	NR	7
Lists of state and tribal landfills and solid waste disposal facilities								
CT SWF/LF	0.500		0	0	0	NR	NR	0
Lists of state and tribal leaking storage tanks								
CT LUST	0.500		0	7	6	NR	NR	13

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
INDIAN LUST	0.500		0	0	0	NR	NR	0
Lists of state and tribal registered storage tanks								
FEMA UST	0.250		0	0	NR	NR	NR	0
CT UST	0.250		0	6	NR	NR	NR	6
CT AST	0.250		0	0	NR	NR	NR	0
INDIAN UST	0.250		0	0	NR	NR	NR	0
State and tribal institutional control / engineering control registries								
CT ENG CONTROLS	0.500		0	0	0	NR	NR	0
CT AUL	0.500		0	0	1	NR	NR	1
Lists of state and tribal voluntary cleanup sites								
CT VCP	0.500		0	0	0	NR	NR	0
INDIAN VCP	0.500		0	0	0	NR	NR	0
Lists of state and tribal brownfield sites								
CT BROWNFIELDS	0.500		0	0	5	NR	NR	5
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500		0	0	4	NR	NR	4
Local Lists of Landfill / Solid Waste Disposal Sites								
CT SWRCY	0.500		0	0	0	NR	NR	0
INDIAN ODI	0.500		0	0	0	NR	NR	0
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
ODI	0.500		0	0	0	NR	NR	0
IHS OPEN DUMPS	0.500		0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US HIST CDL	TP		NR	NR	NR	NR	NR	0
CT CDL	TP		NR	NR	NR	NR	NR	0
US CDL	TP		NR	NR	NR	NR	NR	0
Local Land Records								
CT PROPERTY	TP		NR	NR	NR	NR	NR	0
CT LIENS	TP		NR	NR	NR	NR	NR	0
LIENS 2	TP		NR	NR	NR	NR	NR	0
Records of Emergency Release Reports								
HMIRS	TP		NR	NR	NR	NR	NR	0
CT SPILLS	TP		NR	NR	NR	NR	NR	0
CT SPILLS 90	TP		NR	NR	NR	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	0.250		1	0	NR	NR	NR	1

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
FUDS	1.000		0	0	0	0	NR	0
DOD	1.000		0	0	0	0	NR	0
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
US FIN ASSUR	TP		NR	NR	NR	NR	NR	0
EPA WATCH LIST	TP		NR	NR	NR	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0
TSCA	TP		NR	NR	NR	NR	NR	0
TRIS	TP		NR	NR	NR	NR	NR	0
SSTS	TP		NR	NR	NR	NR	NR	0
ROD	1.000		0	0	0	0	NR	0
RMP	TP		NR	NR	NR	NR	NR	0
RAATS	TP		NR	NR	NR	NR	NR	0
PRP	TP		NR	NR	NR	NR	NR	0
PADS	TP		NR	NR	NR	NR	NR	0
ICIS	TP		NR	NR	NR	NR	NR	0
FTTS	TP		NR	NR	NR	NR	NR	0
MLTS	TP		NR	NR	NR	NR	NR	0
COAL ASH DOE	TP		NR	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
PCB TRANSFORMER	TP		NR	NR	NR	NR	NR	0
RADINFO	TP		NR	NR	NR	NR	NR	0
HIST FTTS	TP		NR	NR	NR	NR	NR	0
DOT OPS	TP		NR	NR	NR	NR	NR	0
CONSENT	1.000		0	0	0	0	NR	0
INDIAN RESERV	1.000		0	0	0	0	NR	0
FUSRAP	1.000		0	0	0	0	NR	0
UMTRA	0.500		0	0	0	NR	NR	0
LEAD SMELTERS	TP		NR	NR	NR	NR	NR	0
US AIRS	TP		NR	NR	NR	NR	NR	0
US MINES	0.250		0	0	NR	NR	NR	0
MINES MRDS	0.250		0	0	NR	NR	NR	0
ABANDONED MINES	0.250		0	0	NR	NR	NR	0
FINDS	TP		NR	NR	NR	NR	NR	0
UXO	1.000		0	0	0	0	NR	0
ECHO	TP		NR	NR	NR	NR	NR	0
DOCKET HWC	TP		NR	NR	NR	NR	NR	0
FUELS PROGRAM	0.250		0	0	NR	NR	NR	0
PFAS NPL	0.250		0	0	NR	NR	NR	0
PFAS FEDERAL SITES	0.250		0	0	NR	NR	NR	0
PFAS TSCA	0.250		0	0	NR	NR	NR	0
PFAS TRIS	0.250		0	0	NR	NR	NR	0
PFAS RCRA MANIFEST	0.250		0	0	NR	NR	NR	0
PFAS ATSDR	0.250		0	0	NR	NR	NR	0
PFAS WQP	0.250		0	0	NR	NR	NR	0
PFAS PROJECT	0.250		0	0	NR	NR	NR	0
PFAS NPDES	0.250		0	0	NR	NR	NR	0
PFAS ECHO	0.250		0	1	NR	NR	NR	1
PFAS ECHO FIRE TRAIN	0.250		0	0	NR	NR	NR	0
PFAS PT 139 AIRPORT	0.250		0	0	NR	NR	NR	0
AQUEOUS FOAM NRC	0.250		0	0	NR	NR	NR	0
BIOSOLIDS	TP		NR	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
UST FINDER RELEASE	0.500		0	1	3	NR	NR	4
UST FINDER	0.250		0	0	NR	NR	NR	0
E MANIFEST	0.250		0	1	NR	NR	NR	1
CT PFAS	0.250		0	0	NR	NR	NR	0
CT AIRS	TP		NR	NR	NR	NR	NR	0
CT ASBESTOS	TP		NR	NR	NR	NR	NR	0
CT CPCS	0.500		2	10	23	NR	NR	35
CT DRYCLEANERS	0.250		1	0	NR	NR	NR	1
CT ENF	TP		NR	NR	NR	NR	NR	0
CT Financial Assurance	TP		NR	NR	NR	NR	NR	0
CT LEAD	TP		NR	NR	NR	NR	NR	0
CT LWDS	0.250		0	1	NR	NR	NR	1
CT MANIFEST	0.250		6	6	NR	NR	NR	12
RI MANIFEST	0.250		0	0	NR	NR	NR	0
NY MANIFEST	0.250		0	1	NR	NR	NR	1
CT NPDES	TP		NR	NR	NR	NR	NR	0
CT SEH	0.500		0	0	0	NR	NR	0
CT UIC	TP		NR	NR	NR	NR	NR	0
EDR HIGH RISK HISTORICAL RECORDS								
EDR Exclusive Records								
EDR MGP	1.000		0	0	0	0	NR	0
EDR Hist Auto	0.125		0	NR	NR	NR	NR	0
EDR Hist Cleaner	0.125		1	NR	NR	NR	NR	1
EDR RECOVERED GOVERNMENT ARCHIVES								
Exclusive Recovered Govt. Archives								
CT RGA HWS	TP		NR	NR	NR	NR	NR	0
CT RGA LUST	TP		NR	NR	NR	NR	NR	0
- Totals --		0	11	38	49	0	0	98

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

1
NNW
< 1/8
0.072 mi.
379 ft.

EUARTS MFG COMPANY
21 FRANCIS ST.
HARTFORD, CT 06103

CT CPCS **S101640073**
N/A

Relative:
Lower

Actual:
74 ft.

CPCS:

Name:	Euarts Mfg Company
Address:	21 FRANCIS ST.
City,State,Zip:	HARTFORD, CT 06103
Site Type:	Not reported
Lust Status code:	4
Lust Status:	Lust Completed (DEP's significant hazard definition)
PTP Form:	Not reported
Program:	LUST
Comments:	Not reported
Site Type Definition:	Leaking Underground Storage Tanks Completed
Invesigation Start:	Yes
Invesigation Start Date:	Not reported
Remediation Start:	Yes
Remediation Start Date:	Not reported
Remediation Completed:	Yes
ELUR:	Not reported
Date Data Updated:	07/24/1995

A2
WNW
< 1/8
0.079 mi.
415 ft.

SUNSET CLEANERS
700 BURNSIDE AVENUE
EAST HARTFORD, CT 06108

Site 1 of 8 in cluster A

EDR Hist Cleaner **1018962358**
N/A

Relative:
Lower

Actual:
54 ft.

EDR Hist Cleaner

Year:	Name:	Type:
1980	SUNSET CLEANERS	Drycleaning Plants, Except Rugs
1982	SUNSET CLEANERS	Drycleaning Plants, Except Rugs
1983	SUNSET CLEANERS	Drycleaning Plants, Except Rugs
1985	SUNSET CLEANERS	Drycleaning Plants, Except Rugs
1986	SUNSET CLEANERS	Drycleaning Plants, Except Rugs
1987	SUNSET CLEANERS	Drycleaning Plants, Except Rugs
1988	SUNSET CLEANERS	Drycleaning Plants, Except Rugs
1989	SUNSET CLEANERS	Drycleaning Plants, Except Rugs
1990	SUNSET CLEANERS	Drycleaning Plants, Except Rugs
1991	SUNSET CLEANERS	Drycleaning Plants, Except Rugs
1992	SUNSET CLEANERS	Drycleaning Plants, Except Rugs
1993	SUNSET CLEANERS	Drycleaning Plants, Except Rugs
1994	SUNSET CLEANERS	Drycleaning Plants, Except Rugs
1995	SUNSET CLEANERS	Drycleaning Plants, Except Rugs
1996	SUNSET CLEANERS	Drycleaning Plants, Except Rugs
1997	SUNSET CLEANERS	Drycleaning Plants, Except Rugs
1998	SUNSET CLEANERS	Drycleaning Plants, Except Rugs
1999	SUNSET CLEANERS	Drycleaning Plants, Except Rugs
2000	SUNSET CLEANERS	Drycleaning Plants, Except Rugs
2001	SUNSET CLEANERS	Drycleaning Plants, Except Rugs
2002	SUNSET CLEANERS	Drycleaning Plants, Except Rugs
2003	SUNSET CLEANERS & TAILORS	Drycleaning Plants, Except Rugs
2004	SUNSET CLEANERS & TAILORS	Drycleaning Plants, Except Rugs
2005	SUNSET CLEANERS & TAILORS	Drycleaning Plants, Except Rugs
2006	SUNSET CLEANERS & TAILORS	Drycleaning Plants, Except Rugs
2007	SUNSET CLEANERS & TAILORS	Drycleaning Plants, Except Rugs

SUNSET CLEANERS (Continued) **1018962358**

2008	SUNSET CLEANERS & TAILORS	Drycleaning Plants, Except Rugs
2009	SUNSET CLEANERS & TAILORS	Drycleaning Plants, Except Rugs

---

A3 **SUNSET CLEANERS** **CT MANIFEST** **S130461058**
WNW **700 BURNSIDE AVE** **N/A**
< 1/8 **EAST HARTFORD, CT 06108**
0.079 mi.
415 ft. **Site 2 of 8 in cluster A**

Relative:
Lower

Actual:
54 ft.

CT MANIFEST:

Name:	SUNSET CLEANERS
Address:	700 BURNSIDE AVE
City,State,Zip:	EAST HARTFORD, CT 06108
Phone:	Not reported
Country:	Not reported
Manifest ID:	CTB0078113
EPA ID:	CTP000005742

Hazardous Waste Manifest:

Year:	1987
Manifest:	CTB0061677
EPA ID:	CTP000005742
Generator Mailing Address:	700 BURNSIDE AVE
Generator City,State,Zip:	EAST HARTFORD, CT 06108
Discrepancies:	N
Date Shipped:	1987-03-03
Date Received:	1987-03-03
Transporter 2 Date:	Not reported
TSDF EPA ID:	CTD000845982
TSDF Name:	SAFETY KLEEN CORP 2-070-01
TSDF Address:	24 BRIXTON ST
TSDF City,State,Zip:	WEST HARTFORD, CT 06107
TSDF Country:	USA
Transporter EPA ID:	CTD000845982
Transporter Name:	SAFETY KLEEN CORP 2-070-01
Transporter Address:	Not reported
Transporter City,State,Zip:	CT
Transporter Country:	USA
Transporter 2 EPA ID:	Not reported
Transporter 2 Name:	Not reported
Transporter 2 Address:	Not reported
Transporter 2 City,State,Zip:	CT
Transporter 2 Country:	USA
US DOT Description:	WASTE PERCHLOROETHYLENE
Number of Containers:	002
Container Type:	DM
Quantity/Weight/Volume:	120/P
Batch Number:	999999
EPA Waste Codes:	F002 - THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

SUNSET CLEANERS (Continued) **S130461058**

Copies:	1
Alternate Facility Name:	Not reported
Alternate Facility Address:	Not reported
Alternate Facility State:	Not reported
Alternate Facility Date:	Not reported
Year:	1987
Manifest:	CTB0078113
EPA ID:	CTP000005742
Generator Mailing Address:	700 BURNSIDE AVE
Generator City,State,Zip:	EAST HARTFORD, CT 06108
Discrepancies:	N
Date Shipped:	1987-04-27
Date Received:	1987-04-27
Transporter 2 Date:	Not reported
TSDF EPA ID:	CTD000845982
TSDF Name:	SAFETY KLEEN CORP 2-070-01
TSDF Address:	24 BRIXTON ST
TSDF City,State,Zip:	WEST HARTFORD, CT 06107
TSDF Country:	USA
Transporter EPA ID:	CTD000845982
Transporter Name:	SAFETY KLEEN CORP 2-070-01
Transporter Address:	Not reported
Transporter City,State,Zip:	CT
Transporter Country:	USA
Transporter 2 EPA ID:	Not reported
Transporter 2 Name:	Not reported
Transporter 2 Address:	Not reported
Transporter 2 City,State,Zip:	CT
Transporter 2 Country:	USA
US DOT Description:	WASTE PERCHLOROETHYLENE
Number of Containers:	001
Container Type:	DM
Quantity/Weight/Volume:	70/P
Batch Number:	999999
EPA Waste Codes:	F002 - THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Copies:	1
Alternate Facility Name:	Not reported
Alternate Facility Address:	Not reported
Alternate Facility State:	Not reported
Alternate Facility Date:	Not reported
Year:	1987
Manifest:	CTB0073408
EPA ID:	CTP000005742
Generator Mailing Address:	700 BURNSIDE AVE
Generator City,State,Zip:	EAST HARTFORD, CT 06108
Discrepancies:	N
Date Shipped:	1987-02-06

SUNSET CLEANERS (Continued) **S130461058**

Date Received:	1987-02-06
Transporter 2 Date:	Not reported
TSDF EPA ID:	CTD000845982
TSDF Name:	SAFETY KLEEN CORP 2-070-01
TSDF Address:	24 BRIXTON ST
TSDF City,State,Zip:	WEST HARTFORD, CT 06107
TSDF Country:	USA
Transporter EPA ID:	CTD000845982
Transporter Name:	SAFETY KLEEN CORP 2-070-01
Transporter Address:	Not reported
Transporter City,State,Zip:	CT
Transporter Country:	USA
Transporter 2 EPA ID:	Not reported
Transporter 2 Name:	Not reported
Transporter 2 Address:	Not reported
Transporter 2 City,State,Zip:	CT
Transporter 2 Country:	USA
US DOT Description:	WASTE PERCHLOROETHYLENE
Number of Containers:	003
Container Type:	DM
Quantity/Weight/Volume:	180/P
Batch Number:	999999
EPA Waste Codes:	F002 - THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Copies:	1
Alternate Facility Name:	Not reported
Alternate Facility Address:	Not reported
Alternate Facility State:	Not reported
Alternate Facility Date:	Not reported

Year:	1987
Manifest:	CTB0068547
EPA ID:	CTP000005742
Generator Mailing Address:	700 BURNSIDE AVE
Generator City,State,Zip:	HARTFORD, CT 06108
Discrepancies:	N
Date Shipped:	1987-01-05
Date Received:	1987-01-09
Transporter 2 Date:	1987-01-08
TSDF EPA ID:	OHD980587364
TSDF Name:	SAFETY-KLEEN CORP
TSDF Address:	581 MILLIKEN DR SE
TSDF City,State,Zip:	HEBRON, OH 43205
TSDF Country:	USA
Transporter EPA ID:	CTD000845982
Transporter Name:	SAFETY KLEEN CORP 2-070-01
Transporter Address:	Not reported
Transporter City,State,Zip:	CT
Transporter Country:	USA
Transporter 2 EPA ID:	OHD981188840

SUNSET CLEANERS (Continued) **S130461058**

Transporter 2 Name:	Not reported
Transporter 2 Address:	Not reported
Transporter 2 City,State,Zip:	CT
Transporter 2 Country:	USA
US DOT Description:	WASTE PERCHLOROETHYLENE
Number of Containers:	002
Container Type:	DM
Quantity/Weight/Volume:	120/P
Batch Number:	999999
EPA Waste Codes:	F002 - THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Copies:	2
Alternate Facility Name:	Not reported
Alternate Facility Address:	Not reported
Alternate Facility State:	Not reported
Alternate Facility Date:	Not reported

Year:	1986
Manifest:	CTB0038102
EPA ID:	CTP000005742
Generator Mailing Address:	700 BURNSIDE AVE
Generator City,State,Zip:	EAST HARTFORD, CT 06108
Discrepancies:	N
Date Shipped:	1986-11-12
Date Received:	1986-11-18
Transporter 2 Date:	1986-11-17
TSDF EPA ID:	OHD980587364
TSDF Name:	SAFETY-KLEEN CORP
TSDF Address:	581 MILLIKEN DR SE
TSDF City,State,Zip:	HEBRON, OH 43205
TSDF Country:	USA
Transporter EPA ID:	CTD000845982
Transporter Name:	SAFETY KLEEN CORP 2-070-01
Transporter Address:	Not reported
Transporter City,State,Zip:	CT
Transporter Country:	USA
Transporter 2 EPA ID:	NJD069039626
Transporter 2 Name:	SAFETY-KLEEN CORP.
Transporter 2 Address:	Not reported
Transporter 2 City,State,Zip:	CT
Transporter 2 Country:	USA
US DOT Description:	WASTE PERCHLOROETHYLENE
Number of Containers:	003
Container Type:	DM
Quantity/Weight/Volume:	180/P
Batch Number:	999999
EPA Waste Codes:	F002 - THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2,

SUNSET CLEANERS (Continued) **S130461058**

TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Copies:	2
Alternate Facility Name:	Not reported
Alternate Facility Address:	Not reported
Alternate Facility State:	Not reported
Alternate Facility Date:	Not reported

A4 **SUNSET CLEANERS** **CT MANIFEST** **S130461048**
WNW **700 BURNSIDE AVE** **N/A**
< 1/8 **EAST HARTFORD, CT 06108**
0.079 mi.
415 ft. **Site 3 of 8 in cluster A**

Relative:
Lower

Actual:
54 ft.

CT MANIFEST:

Name:	SUNSET CLEANERS
Address:	700 BURNSIDE AVE
City,State,Zip:	EAST HARTFORD, CT 06108
Phone:	Not reported
Country:	Not reported
Manifest ID:	CTB0035852
EPA ID:	CTP000005177

Hazardous Waste Manifest:

Year:	1986
Manifest:	CTB0035852
EPA ID:	CTP000005177
Generator Mailing Address:	700 BURNSIDE AVE
Generator City,State,Zip:	EAST HARTFORD, CT 06108
Discrepancies:	N
Date Shipped:	1986-06-24
Date Received:	1986-07-02
Transporter 2 Date:	1986-06-27
TSDF EPA ID:	OHD980587364
TSDF Name:	SAFETY-KLEEN CORP
TSDF Address:	581 MILLIKEN DR SE
TSDF City,State,Zip:	HEBRON, OH 43205
TSDF Country:	USA
Transporter EPA ID:	CTD000845982
Transporter Name:	SAFETY KLEEN CORP 2-070-01
Transporter Address:	Not reported
Transporter City,State,Zip:	CT
Transporter Country:	USA
Transporter 2 EPA ID:	Not reported
Transporter 2 Name:	Not reported
Transporter 2 Address:	Not reported
Transporter 2 City,State,Zip:	CT
Transporter 2 Country:	USA
US DOT Description:	WASTE PERCHLOROETHYLENE
Number of Containers:	003
Container Type:	DM
Quantity/Weight/Volume:	150/P
Batch Number:	999999
EPA Waste Codes:	F002 - THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE,

SUNSET CLEANERS (Continued) **S130461048**

METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Copies:	2
Alternate Facility Name:	Not reported
Alternate Facility Address:	Not reported
Alternate Facility State:	Not reported
Alternate Facility Date:	Not reported

A5 **WALTAWOLK** **CT PROPERTY** **S109726438**
WNW **700 BURNSIDE AVE** **CT SPILLS** **N/A**
< 1/8 **EAST HARTFORD, CT 06108** **CT CPCS**
0.079 mi. **CT MANIFEST**
415 ft. **Site 4 of 8 in cluster A**

Relative: **Lower**
Actual: **54 ft.**

CT Property:

Name:	SUNSET DRY CLEANERS
Address:	700 BURNSIDE AVENUE
City,state,zip:	EAST HARTFORD, CT
Seller Name:	Leonard J. Mecca
Buyer Name:	Fams Group Inc.
Certifying Party:	Fams Group Inc.
Certifying Attention Person:	Shaukathusein G. Dalal
Title Of Certifying Person:	Vice President
Certifying Person Address:	943 Silas Deane Highway
Certifying Person City,St,Zip:	Wethersfield, CT 06109
Property Transfer Forms:	Form III (DEP-PERD-PTP-203) when a discharge, spillage, uncontrolled loss, seepage or filtration of hazardous waste has occurred at the parcel that has not been fully remediated or the environmental conditions at the parcel are unknown. The person signing the Form III certification agrees to investigate and remediate the site in accordance with the remediation standards. The statute does not require completion of remediation before the parcel is transferred. Any person submitting a Form III shall simultaneously submit a completed Environmental Condition Assessment Form (ECAF)(DEP-PERD-PTP-200).
Date Recieved:	10/13/2005
Ackn Date:	01/27/2006
Determination Date:	02/15/2006
LEP Verified/DEP Approval Date:	Not reported
Rem Id:	7617
Remediation Location Id:	7357
Date Entered:	10/31/2005
Program:	Property Transfer Program
GAO Site:	False
Staff Full Name:	Tom Oconnor
Super/Date:	01/30/2006
Stage Of Project:	Not reported
RP Level Of Activity:	Not reported
RP Needed Level Of Activity:	Not reported
Staff Level Of Activity:	Not reported
Staff Needed Level Of Activity:	Not reported
Public Intrest:	Not reported

WALTAWOLK (Continued) **S109726438**

PRP Cooperation:	Not reported
Enforcement Status:	Not reported
Level Of Complexity:	Not reported
Complex Eng Or Sci:	False
Complex Due To Public Involvement:	False
Politically Complex:	False
Complex Enforcement:	False
Coordination With Other Bureaus:	False
EPA Involvement:	False
Staff Prefrence:	Not reported
Readiness For Transfer:	Not reported
Project Transfer Time:	Not reported
Transfer Comments:	Not reported
Staff As Of July 2000:	Not reported
Initial Staff:	Not reported
Type Of Transfer:	Real Estate
Salutation:	Mr. Dalal
Relationship To Transfer:	transferee
Audit Date:	Not reported
Verif Type:	Not reported
Audit Outcome:	Not reported
GW:	GB
Basin:	Not reported
1st Payment:	3000
Pay Tag1:	5302580
2nd Payment:	Not reported
Pay Tag2:	Not reported
RTN:	12/15/2005
Revised:	12/19/2005
ECAF Received:	Not reported
Old Determination Date:	Not reported
Redeterminationdate:	Not reported
Previous Determination:	Not reported
Monitoringoption:	Not reported
Postremedialmonitoring:	Not reported
Schedule Of I/R:	03/16/2006
Schedule Overdue:	Not reported
Aprvl Sched:	Not reported
Yr 1 Report:	Not reported
Yr 2 Report:	Not reported
Report Overdue:	Not reported
Ext Aprvl Sched:	Not reported
License #:	Not reported
Project Phase:	Not reported
PT Comments:	Not reported
EPA Id Number:	Not reported
GW Class:	Not reported
SW Class:	Not reported
AO/C0:	Not reported
Water Lead(Y Or N):	Not reported
Priority:	Not reported
Project Status(A, I Or D):	Not reported
Last Updated:	Not reported
SR Comments:	Not reported
Priority Or Work-Load:	Not reported
Status:	Not reported
Notes:	Not reported

WALTAWOLK (Continued) **S109726438**

Special Project Name:	Not reported
Special Project Comments:	Not reported
DOT Project:	Not reported
Pt Counter:	0
Project Complete:	False
Project Inactive:	False
Int Deposit #:	06-147
Deposit #:	Not reported
Spill Case #:	Not reported
Diversion Id:	0
Public Notice:	Not reported
RAP Received:	Not reported
RAP Approved:	Not reported
Compliance Category:	B
Delete Record:	False
ECAF Reviewed By:	Not reported
Not Locatable:	False
Primary Address:	True
AKA Site Name:	False
Primary Site Name:	True
AKA Site Address:	False
Lead:	LEP

SPILLS:

Name:	Not reported
Address:	700 BURNSIDE AVE
City,State,Zip:	EAST HARTFORD, CT
Year of Database:	2006
Case Number:	200602450
Who Took Spill:	206
Assigned To:	No Response
Report Date:	04/27/2006
Report Time:	12:00:00 AM
Date Release:	04/27/2006
Release Time:	12:00:00 AM
Reported By:	EAST HARTFORD FIRE
Phone:	860 5284401
Qty:	3.00 (Gallons)
Telephone:	Not reported
Representing:	Self
Facility Status:	CLOSED
Continuous Spill:	False
Release Substance:	MOTOR VEHICLE FLUIDS
Emergency Measure:	Not reported
Discharger:	Not reported
Waterbody Affected:	Other (NA)
Responsible Party:	Not reported
Responsible Party Address:	Not reported
RP City,St,Zip:	CT
Terminated:	YES
Recovered Total:	0
Total Water:	0
Historic:	False
Waterbody:	NA
User Stamp:	ckinney
Stamp Time:	2006-04-27 21:22:18
SR Inspector:	Kinney, Clarence

WALTAWOLK (Continued) **S109726438**

AT Inspector:	**NO RESPONSE
Corrective Action Taken:	Sanded
Cause Info:	MV Accident
Media Info:	Ground Surface
Release Type:	petroleum
Incident Description:	Not reported
Cost Recovery Case?:	Not reported
DEMHS Region:	Not reported
Lat/Long:	Not reported
Company Name:	Not reported
Last Updated:	Not reported

Action:

Action:	Sanded
Other Action:	Not reported

Agency:

Agency ID:	DEP Dispatch
Other Agency:	Not reported
DEP Bureau:	Not reported
DEP Agency:	Not reported

Agency ID:	LOCAL FIRE DEPARTMENT
Other Agency:	Not reported
DEP Bureau:	Not reported
DEP Agency:	Not reported

Cause:

Cause ID:	MV Accident
Other Cause:	Not reported

Media:

Media ID:	Ground Surface
Other Media:	Not reported

Release Class:

Class ID:	Private
Other Class:	Not reported

Release Type:

Release Type:	petroleum
Other Release:	Not reported

Waterbody:

Waterbody:	Other
Other Waterbody:	NA

CPCS:

Name:	Sunset Dry Cleaners
Address:	700 BURNSIDE AVENUE
City,State,Zip:	EAST HARTFORD, CT

WALTAWOLK (Continued) **S109726438**

Site Type:	Not reported
Lust Status code:	Not reported
Lust Status:	Not reported
PTP Form:	Not reported
Program:	Property Transfer Program
Comments:	Not reported
Site Type Definition:	Not reported
Invesigation Start:	Not reported
Invesigation Start Date:	01/27/2006
Remediation Start:	Not reported
Remediation Start Date:	Not reported
Remediation Completed:	No
ELUR:	No
Date Data Updated:	Not reported

CT MANIFEST:

Name:	WALTAWOLK
Address:	700 BURNSIDE AVE
City,State,Zip:	EAST HARTFORD, CT 06108
Phone:	Not reported
Country:	Not reported
Manifest ID:	CTF0034476
EPA ID:	CT$000028870

Hazardous Waste Manifest:

Year:	1990
Manifest:	CTF0034476
EPA ID:	CT$000028870
Generator Mailing Address:	700 BURNSIDE AVE
Generator City,State,Zip:	EAST HARTFORD, CT 06108
Discrepancies:	N
Date Shipped:	1990-12-10
Date Received:	Not reported
Transporter 2 Date:	Not reported
TSDF EPA ID:	MAD981206774
TSDF Name:	JOSEPH FREEDMAN CO INC
TSDF Address:	40 ALBANY ST
TSDF City,State,Zip:	SPRINGFIELD, MA 01105
TSDF Country:	USA
Transporter EPA ID:	MAD985276369
Transporter Name:	MED WASTE MGT INC (TRANSPORTER)
Transporter Address:	Not reported
Transporter City,State,Zip:	CT
Transporter Country:	USA
Transporter 2 EPA ID:	Not reported
Transporter 2 Name:	Not reported
Transporter 2 Address:	Not reported
Transporter 2 City,State,Zip:	CT
Transporter 2 Country:	USA
US DOT Description:	HAZARDOUS WASTE LIQUID, NOS
Number of Containers:	001
Container Type:	CF
Quantity/Weight/Volume:	2/G
Batch Number:	Not reported
EPA Waste Codes:	D011 - SILVER
Copies:	Not reported

WALTAWOLK (Continued) **S109726438**

Alternate Facility Name:	Not reported
Alternate Facility Address:	Not reported
Alternate Facility State:	Not reported
Alternate Facility Date:	Not reported
Year:	1990
Manifest:	MAC893475
EPA ID:	CT$000028870
Generator Mailing Address:	700 BURNSIDE AVE
Generator City,State,Zip:	EAST HARTFORD, CT 06108
Discrepancies:	N
Date Shipped:	1990-09-10
Date Received:	1990-09-11
Transporter 2 Date:	Not reported
TSDF EPA ID:	MAD981206774
TSDF Name:	JOSEPH FREEDMAN CO INC
TSDF Address:	40 ALBANY ST
TSDF City,State,Zip:	SPRINGFIELD, MA 01105
TSDF Country:	USA
Transporter EPA ID:	MAD982545436
Transporter Name:	OIL RECOVERY CORP
Transporter Address:	Not reported
Transporter City,State,Zip:	CT
Transporter Country:	USA
Transporter 2 EPA ID:	Not reported
Transporter 2 Name:	Not reported
Transporter 2 Address:	Not reported
Transporter 2 City,State,Zip:	CT
Transporter 2 Country:	USA
US DOT Description:	HAZARDOUS WASTE LIQUID, NOS
Number of Containers:	001
Container Type:	CM
Quantity/Weight/Volume:	2/G
Batch Number:	999999
EPA Waste Codes:	D011 - SILVER
Copies:	2
Alternate Facility Name:	Not reported
Alternate Facility Address:	Not reported
Alternate Facility State:	Not reported
Alternate Facility Date:	Not reported

A6 **FAMS GROUP - SUNSET CLEANERS** **CT DRYCLEANERS** **S109734809**
WNW **700 BURNSIDE AVENUE** **CT MANIFEST** **N/A**
< 1/8 **EAST HARTFORD, CT 06108**
0.079 mi.
415 ft. **Site 5 of 8 in cluster A**

Relative: DRYCLEANERS 2:
Lower

Region:	2
Name:	FAMS GROUP - SUNSET CLEANERS
Address:	700 BURNSIDE AVENUE
City,State,Zip:	EAST HARTFORD, CT 06108
Fiscal Year:	2017
Applicant:	Fams Group, Inc. - Sunset Cleaners
Applicant Address:	700 Burnside Avenue
Applicant Municipality:	East Hartford
Applicant State:	CT
Applicant Zip Code:	06108

Actual:
54 ft.

FAMS GROUP - SUNSET CLEANERS (Continued) **S109734809**

Contract Execution Date:	10/05/2017
Grant Assistance:	35000
Other Project Funds:	10000
Total Project Cost:	45000
Funding Source:	Dry Cleaning Establishment Remediation Fund/Account
Statutory Reference:	CGS Sec. 12-263m
Count:	1
New Georeferenced Column:	POINT (-72.60885 41.77966)

Region:	2
Name:	SUNSET CLEANERS
Address:	700 BURNSIDE AVENUE
City,State,Zip:	EAST HARTFORD, CT 06108
Fiscal Year:	2009
Applicant:	Sunset Cleaners
Applicant Address:	700 Burnside Avenue
Applicant Municipality:	East Hartford
Applicant State:	CT
Applicant Zip Code:	06108
Contract Execution Date:	07/01/2008
Grant Assistance:	60000
Other Project Funds:	10000
Total Project Cost:	70000
Funding Source:	Dry Cleaning Establishment Remediation Fund/Account
Statutory Reference:	CGS Sec. 12-263m
Count:	1
New Georeferenced Column:	POINT (-72.60885 41.77966)

CT MANIFEST:

Name:	SUNSET CLEANERS
Address:	700 BURNSIDE AVE
City,State,Zip:	EAST HARTFORD, CT 06108
Phone:	Not reported
Country:	Not reported
Manifest ID:	MAC142796
EPA ID:	CTP000001770

Hazardous Waste Manifest:

Year:	1986
Manifest:	MAC142796
EPA ID:	CTP000001770
Generator Mailing Address:	700 BURNSIDE AVE
Generator City,State,Zip:	EAST HARTFORD, CT 06108
Discrepancies:	N
Date Shipped:	1986-10-17
Date Received:	1986-10-23
Transporter 2 Date:	1986-10-22
TSDF EPA ID:	OHD980587364
TSDF Name:	SAFETY-KLEEN CORP
TSDF Address:	581 MILLIKEN DR SE
TSDF City,State,Zip:	HEBRON, OH 43205
TSDF Country:	USA
Transporter EPA ID:	ILD000805911
Transporter Name:	SAFETY-KLEEN CORP
Transporter Address:	Not reported
Transporter City,State,Zip:	CT

FAMS GROUP - SUNSET CLEANERS (Continued) **S109734809**

Transporter Country:	USA
Transporter 2 EPA ID:	ILD000805911
Transporter 2 Name:	SAFETY-KLEEN CORP.
Transporter 2 Address:	Not reported
Transporter 2 City,State,Zip:	CT
Transporter 2 Country:	USA
US DOT Description:	WASTE PERCHLOROETHYLENE
Number of Containers:	002
Container Type:	DM
Quantity/Weight/Volume:	120/P
Batch Number:	999999
EPA Waste Codes:	F002 - THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Copies:	2
Alternate Facility Name:	Not reported
Alternate Facility Address:	Not reported
Alternate Facility State:	Not reported
Alternate Facility Date:	Not reported

Year:	1986
Manifest:	CTA0079415
EPA ID:	CTP000001770
Generator Mailing Address:	700 BURNSIDE AVE
Generator City,State,Zip:	EAST HARTFORD, CT 06108
Discrepancies:	N
Date Shipped:	1986-03-06
Date Received:	1986-03-13
Transporter 2 Date:	1986-03-11
TSDF EPA ID:	OHD980587364
TSDF Name:	SAFETY-KLEEN CORP
TSDF Address:	581 MILLIKEN DR SE
TSDF City,State,Zip:	HEBRON, OH 43205
TSDF Country:	USA
Transporter EPA ID:	CTD000845982
Transporter Name:	SAFETY KLEEN CORP 2-070-01
Transporter Address:	Not reported
Transporter City,State,Zip:	CT
Transporter Country:	USA
Transporter 2 EPA ID:	MAD019371079
Transporter 2 Name:	GENERAL CHEMICAL CORPORATION,
Transporter 2 Address:	Not reported
Transporter 2 City,State,Zip:	CT
Transporter 2 Country:	USA
US DOT Description:	WASTE PERCHLOROETHYLENE
Number of Containers:	002
Container Type:	DM
Quantity/Weight/Volume:	240/P
Batch Number:	999999
EPA Waste Codes:	F002 - THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE,

FAMS GROUP - SUNSET CLEANERS (Continued) **S109734809**

CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Copies: 2
Alternate Facility Name: Not reported
Alternate Facility Address: Not reported
Alternate Facility State: Not reported
Alternate Facility Date: Not reported

Year: 1986
Manifest: CTB0035767
EPA ID: CTP000001770
Generator Mailing Address: 700 BURNSIDE AVE
Generator City,State,Zip: EAST HARTFORD, CT 06108
Discrepancies: N
Date Shipped: 1986-01-28
Date Received: 1986-02-06
Transporter 2 Date: 1986-02-04
TSDF EPA ID: OHD980587364
TSDF Name: SAFETY-KLEEN CORP
TSDF Address: 581 MILLIKEN DR SE
TSDF City,State,Zip: HEBRON, OH 43205
TSDF Country: USA
Transporter EPA ID: ILD000805911
Transporter Name: SAFETY-KLEEN CORP
Transporter Address: Not reported
Transporter City,State,Zip: CT
Transporter Country: USA
Transporter 2 EPA ID: NYD046765574
Transporter 2 Name: PRICE TRUCKING CORP.,
Transporter 2 Address: Not reported
Transporter 2 City,State,Zip: CT
Transporter 2 Country: USA
US DOT Description: WASTE PERCHLOROETHYLENE STILL BTMS/FLTRS
Number of Containers: 003
Container Type: DM
Quantity/Weight/Volume: 180/P
Batch Number: 999999
EPA Waste Codes: F002 - THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Copies: 2
Alternate Facility Name: Not reported
Alternate Facility Address: Not reported
Alternate Facility State: Not reported
Alternate Facility Date: Not reported

FAMS GROUP - SUNSET CLEANERS (Continued) **S109734809**

Year:	1985
Manifest:	CTA0076374
EPA ID:	CTP000001770
Generator Mailing Address:	700 BURNSIDE AVE
Generator City,State,Zip:	EAST HARTFORD, CT 06108
Discrepancies:	N
Date Shipped:	1985-12-13
Date Received:	Not reported
Transporter 2 Date:	Not reported
TSDF EPA ID:	OHD980587364
TSDF Name:	SAFETY-KLEEN CORP
TSDF Address:	581 MILLIKEN DR SE
TSDF City,State,Zip:	HEBRON, OH 43205
TSDF Country:	USA
Transporter EPA ID:	MAD060095569
Transporter Name:	SAFETY-KLEEN CORP. (TRANSPORTER)
Transporter Address:	Not reported
Transporter City,State,Zip:	CT
Transporter Country:	USA
Transporter 2 EPA ID:	MAD019371079
Transporter 2 Name:	GENERAL CHEMICAL CORPORATION,
Transporter 2 Address:	Not reported
Transporter 2 City,State,Zip:	CT
Transporter 2 Country:	USA
US DOT Description:	WASTE PERCHLOROETHYLENE
Number of Containers:	002
Container Type:	DM
Quantity/Weight/Volume:	120/P
Batch Number:	999999
EPA Waste Codes:	F002 - THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Copies:	2
Alternate Facility Name:	Not reported
Alternate Facility Address:	Not reported
Alternate Facility State:	Not reported
Alternate Facility Date:	Not reported

A7 **SUNSET CLEANERS** **CT MANIFEST** **S109735401**
WNW **700 BURNSIDE AVE** **N/A**
< 1/8 **EAST HARTFORD, CT 06108**
0.079 mi.
415 ft. **Site 6 of 8 in cluster A**

Relative: CT MANIFEST:
Lower

Name:	SUNSET CLEANERS
Address:	700 BURNSIDE AVE
City,State,Zip:	EAST HARTFORD, CT 06108
Phone:	Not reported
Country:	Not reported
Manifest ID:	CTB0030452
EPA ID:	CTP000005054

Actual:
54 ft.

SUNSET CLEANERS (Continued) **S109735401**

Hazardous Waste Manifest:

Year:	1986
Manifest:	CTB0030452
EPA ID:	CTP000005054
Generator Mailing Address:	700 BURNSIDE AVE
Generator City,State,Zip:	EAST HARTFORD, CT 06108
Discrepancies:	N
Date Shipped:	1986-05-09
Date Received:	1986-05-20
Transporter 2 Date:	1986-05-19
TSDF EPA ID:	OHD980587364
TSDF Name:	SAFETY-KLEEN CORP
TSDF Address:	581 MILLIKEN DR SE
TSDF City,State,Zip:	HEBRON, OH 43205
TSDF Country:	USA
Transporter EPA ID:	CTD000845982
Transporter Name:	SAFETY KLEEN CORP 2-070-01
Transporter Address:	Not reported
Transporter City,State,Zip:	CT
Transporter Country:	USA
Transporter 2 EPA ID:	MAD019371079
Transporter 2 Name:	GENERAL CHEMICAL CORPORATION,
Transporter 2 Address:	Not reported
Transporter 2 City,State,Zip:	CT
Transporter 2 Country:	USA
US DOT Description:	WASTE PERCHLOROETHYLENE
Number of Containers:	003
Container Type:	DM
Quantity/Weight/Volume:	180/P
Batch Number:	999999
EPA Waste Codes:	F002 - THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Copies:	2
Alternate Facility Name:	Not reported
Alternate Facility Address:	Not reported
Alternate Facility State:	Not reported
Alternate Facility Date:	Not reported

A8 **SUNSET CLEANERS** **CT MANIFEST** **S129121664**
WNW **700 BURNSIDE AVE** **N/A**
< 1/8 **EAST HARTFORD, CT 06108**
0.079 mi.
415 ft. **Site 7 of 8 in cluster A**

Relative: CT MANIFEST:
Lower

Name:	SUNSET CLEANERS
Address:	700 BURNSIDE AVE
City,State,Zip:	EAST HARTFORD, CT 06108
Phone:	Not reported
Country:	Not reported

Actual:
54 ft.

SUNSET CLEANERS (Continued) **S129121664**

Manifest ID: CTC0114823
EPA ID: CTD021816541

Hazardous Waste Manifest:
Year: 2003
Manifest: NYG2738187
EPA ID: CTD021816541
Generator Mailing Address: 700 BURNSIDE AVE
Generator City,State,Zip: EAST HARTFORD, CT 06108
Discrepancies: Not reported
Date Shipped: 2003-07-05
Date Received: 2003-07-07
Transporter 2 Date: Not reported
TSDF EPA ID: NYD080469935
TSDF Name: NORLITE CORP
TSDF Address: PO BOX 694
TSDF City,State,Zip: COHOES, NY 12047
TSDF Country: USA
Transporter EPA ID: CTD021816889
Transporter Name: UNITED OIL RECOVERY INC
Transporter Address: 14 WEST MAIN ST
Transporter City,State,Zip: MERIDEN, CT 06451
Transporter Country: USA
Transporter 2 EPA ID: Not reported
Transporter 2 Name: Not reported
Transporter 2 Address: Not reported
Transporter 2 City,State,Zip: CT
Transporter 2 Country: USA
US DOT Description: FLAMMABLE LIQUIDS, N.O.S.
Number of Containers: 1
Container Type: TT
Quantity/Weight/Volume: 5000/G
Batch Number: 5792, 5792
EPA Waste Codes: F002 - THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Copies: 2, 7
Alternate Facility Name: Not reported
Alternate Facility Address: Not reported
Alternate Facility State: Not reported
Alternate Facility Date: Not reported

Year: 1997
Manifest: RIG0100783
EPA ID: CTD021816541
Generator Mailing Address: 700 BURNSIDE AVE
Generator City,State,Zip: EAST HARTFORD, CT 06108
Discrepancies: Not reported
Date Shipped: 1997-02-12
Date Received: 1997-02-12
Transporter 2 Date: Not reported

SUNSET CLEANERS (Continued) **S129121664**

TSDF EPA ID:	RID084802842
TSDF Name:	CHEM-PAK CORP
TSDF Address:	167 MILL ST
TSDF City,State,Zip:	CRANSTON, RI 02905
TSDF Country:	USA
Transporter EPA ID:	RID982194987
Transporter Name:	CYCLE SOLVE CORP
Transporter Address:	Not reported
Transporter City,State,Zip:	CT
Transporter Country:	USA
Transporter 2 EPA ID:	Not reported
Transporter 2 Name:	Not reported
Transporter 2 Address:	Not reported
Transporter 2 City,State,Zip:	CT
Transporter 2 Country:	USA
US DOT Description:	tetrachorethylene
Number of Containers:	002
Container Type:	DM
Quantity/Weight/Volume:	200/P
Batch Number:	1906, 1906
EPA Waste Codes:	F002 - THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Copies:	2, 7
Alternate Facility Name:	Not reported
Alternate Facility Address:	Not reported
Alternate Facility State:	Not reported
Alternate Facility Date:	Not reported

Year:	1991
Manifest:	CTF0003006
EPA ID:	CTD021816541
Generator Mailing Address:	700 BURNSIDE AVE
Generator City,State,Zip:	EAST HARTFORD, CT 06108
Discrepancies:	N
Date Shipped:	1991-03-25
Date Received:	1991-03-25
Transporter 2 Date:	Not reported
TSDF EPA ID:	CTD000845982
TSDF Name:	SAFETY KLEEN CORP 2-070-01
TSDF Address:	24 BRIXTON ST
TSDF City,State,Zip:	WEST HARTFORD, CT 06107
TSDF Country:	USA
Transporter EPA ID:	ILD051060408
Transporter Name:	SAFETY-KLEEN CORP (TRANSPORTER ONLY)
Transporter Address:	Not reported
Transporter City,State,Zip:	CT
Transporter Country:	USA
Transporter 2 EPA ID:	Not reported
Transporter 2 Name:	Not reported
Transporter 2 Address:	Not reported

SUNSET CLEANERS (Continued) **S129121664**

Transporter 2 City,State,Zip:	CT
Transporter 2 Country:	USA
US DOT Description:	WASTE PERCHLOROETHYLENE
Number of Containers:	001
Container Type:	DM
Quantity/Weight/Volume:	70/P
Batch Number:	999999
EPA Waste Codes:	F002 - THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Copies:	1
Alternate Facility Name:	Not reported
Alternate Facility Address:	Not reported
Alternate Facility State:	Not reported
Alternate Facility Date:	Not reported

Year:	1991
Manifest:	CTF0044964
EPA ID:	CTD021816541
Generator Mailing Address:	700 BURNSIDE AVE
Generator City,State,Zip:	EAST HARTFORD, CT 06108
Discrepancies:	N
Date Shipped:	1991-01-28
Date Received:	1991-01-28
Transporter 2 Date:	Not reported
TSDF EPA ID:	CTD000845982
TSDF Name:	SAFETY KLEEN CORP 2-070-01
TSDF Address:	24 BRIXTON ST
TSDF City,State,Zip:	WEST HARTFORD, CT 06107
TSDF Country:	USA
Transporter EPA ID:	ILD051060408
Transporter Name:	SAFETY-KLEEN CORP (TRANSPORTER ONLY)
Transporter Address:	Not reported
Transporter City,State,Zip:	CT
Transporter Country:	USA
Transporter 2 EPA ID:	Not reported
Transporter 2 Name:	Not reported
Transporter 2 Address:	Not reported
Transporter 2 City,State,Zip:	CT
Transporter 2 Country:	USA
US DOT Description:	WASTE PERCHLOROETHYLENE
Number of Containers:	001
Container Type:	DM
Quantity/Weight/Volume:	70/P
Batch Number:	999999
EPA Waste Codes:	F002 - THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE

SUNSET CLEANERS (Continued) **S129121664**

ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Copies:	1
Alternate Facility Name:	Not reported
Alternate Facility Address:	Not reported
Alternate Facility State:	Not reported
Alternate Facility Date:	Not reported
Year:	1991
Manifest:	CTF0066410
EPA ID:	CTD021816541
Generator Mailing Address:	700 BURNSIDE AVE
Generator City,State,Zip:	EAST HARTFORD, CT 06108
Discrepancies:	N
Date Shipped:	1991-05-23
Date Received:	1991-05-23
Transporter 2 Date:	Not reported
TSDF EPA ID:	CTD000845982
TSDF Name:	SAFETY KLEEN CORP 2-070-01
TSDF Address:	24 BRIXTON ST
TSDF City,State,Zip:	WEST HARTFORD, CT 06107
TSDF Country:	USA
Transporter EPA ID:	ILD051060408
Transporter Name:	SAFETY-KLEEN CORP (TRANSPORTER ONLY)
Transporter Address:	Not reported
Transporter City,State,Zip:	CT
Transporter Country:	USA
Transporter 2 EPA ID:	Not reported
Transporter 2 Name:	Not reported
Transporter 2 Address:	Not reported
Transporter 2 City,State,Zip:	CT
Transporter 2 Country:	USA
US DOT Description:	WASTE PERC
Number of Containers:	001
Container Type:	DM
Quantity/Weight/Volume:	70/P
Batch Number:	999999
EPA Waste Codes:	F002 - THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Copies:	1
Alternate Facility Name:	Not reported
Alternate Facility Address:	Not reported
Alternate Facility State:	Not reported
Alternate Facility Date:	Not reported
Year:	1991
Manifest:	CTF0098982
EPA ID:	CTD021816541
Generator Mailing Address:	700 BURNSIDE AVE

SUNSET CLEANERS (Continued) **S129121664**

Generator City,State,Zip:	EAST HARTFORD, CT 06108
Discrepancies:	N
Date Shipped:	1991-01-03
Date Received:	1991-01-03
Transporter 2 Date:	Not reported
TSDF EPA ID:	CTD000845982
TSDF Name:	SAFETY KLEEN CORP 2-070-01
TSDF Address:	24 BRIXTON ST
TSDF City,State,Zip:	WEST HARTFORD, CT 06107
TSDF Country:	USA
Transporter EPA ID:	ILD051060408
Transporter Name:	SAFETY-KLEEN CORP (TRANSPORTER ONLY)
Transporter Address:	Not reported
Transporter City,State,Zip:	CT
Transporter Country:	USA
Transporter 2 EPA ID:	Not reported
Transporter 2 Name:	Not reported
Transporter 2 Address:	Not reported
Transporter 2 City,State,Zip:	CT
Transporter 2 Country:	USA
US DOT Description:	WASTE PERC
Number of Containers:	001
Container Type:	DM
Quantity/Weight/Volume:	70/P
Batch Number:	999999
EPA Waste Codes:	F002 - THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Copies:	1
Alternate Facility Name:	Not reported
Alternate Facility Address:	Not reported
Alternate Facility State:	Not reported
Alternate Facility Date:	Not reported

Year:	1991
Manifest:	CTF0068872
EPA ID:	CTD021816541
Generator Mailing Address:	700 BURNSIDE AVE
Generator City,State,Zip:	EAST HARTFORD, CT 06108
Discrepancies:	N
Date Shipped:	1991-06-24
Date Received:	1991-06-24
Transporter 2 Date:	Not reported
TSDF EPA ID:	CTD000845982
TSDF Name:	SAFETY KLEEN CORP 2-070-01
TSDF Address:	24 BRIXTON ST
TSDF City,State,Zip:	WEST HARTFORD, CT 06107
TSDF Country:	USA
Transporter EPA ID:	ILD051060408
Transporter Name:	SAFETY-KLEEN CORP (TRANSPORTER ONLY)
Transporter Address:	Not reported

SUNSET CLEANERS (Continued) **S129121664**

Transporter City,State,Zip:	CT
Transporter Country:	USA
Transporter 2 EPA ID:	Not reported
Transporter 2 Name:	Not reported
Transporter 2 Address:	Not reported
Transporter 2 City,State,Zip:	CT
Transporter 2 Country:	USA
US DOT Description:	WASTE PERCHLOROETHYLENE
Number of Containers:	001
Container Type:	DM
Quantity/Weight/Volume:	70/P
Batch Number:	999999
EPA Waste Codes:	F002 - THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Copies:	1
Alternate Facility Name:	Not reported
Alternate Facility Address:	Not reported
Alternate Facility State:	Not reported
Alternate Facility Date:	Not reported

Year:	1991
Manifest:	CTF0074753
EPA ID:	CTD021816541
Generator Mailing Address:	700 BURNSIDE AVE
Generator City,State,Zip:	EAST HARTFORD, CT 06108
Discrepancies:	N
Date Shipped:	1991-02-25
Date Received:	1991-02-25
Transporter 2 Date:	Not reported
TSDF EPA ID:	CTD000845982
TSDF Name:	SAFETY KLEEN CORP 2-070-01
TSDF Address:	24 BRIXTON ST
TSDF City,State,Zip:	WEST HARTFORD, CT 06107
TSDF Country:	USA
Transporter EPA ID:	ILD051060408
Transporter Name:	SAFETY-KLEEN CORP (TRANSPORTER ONLY)
Transporter Address:	Not reported
Transporter City,State,Zip:	CT
Transporter Country:	USA
Transporter 2 EPA ID:	Not reported
Transporter 2 Name:	Not reported
Transporter 2 Address:	Not reported
Transporter 2 City,State,Zip:	CT
Transporter 2 Country:	USA
US DOT Description:	WASTE PQECHLOROETHYLENE
Number of Containers:	001
Container Type:	DM
Quantity/Weight/Volume:	70/P
Batch Number:	999999
EPA Waste Codes:	F002 - THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE,

SUNSET CLEANERS (Continued) **S129121664**

METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Copies: 1
Alternate Facility Name: Not reported
Alternate Facility Address: Not reported
Alternate Facility State: Not reported
Alternate Facility Date: Not reported

Year: 1991
Manifest: CTF0090204
EPA ID: CTD021816541
Generator Mailing Address: 700 BURNSIDE AVE
Generator City,State,Zip: EAST HARTFORD, CT 06108
Discrepancies: N
Date Shipped: 1991-05-03
Date Received: 1991-05-03
Transporter 2 Date: Not reported
TSDF EPA ID: CTD000845982
TSDF Name: SAFETY KLEEN CORP 2-070-01
TSDF Address: 24 BRIXTON ST
TSDF City,State,Zip: WEST HARTFORD, CT 06107
TSDF Country: USA
Transporter EPA ID: ILD051060408
Transporter Name: SAFETY-KLEEN CORP (TRANSPORTER ONLY)
Transporter Address: Not reported
Transporter City,State,Zip: CT
Transporter Country: USA
Transporter 2 EPA ID: Not reported
Transporter 2 Name: Not reported
Transporter 2 Address: Not reported
Transporter 2 City,State,Zip: CT
Transporter 2 Country: USA
US DOT Description: WASTE PERCHLOROETHYLENE
Number of Containers: 001
Container Type: DM
Quantity/Weight/Volume: 70/P
Batch Number: 999999
EPA Waste Codes: F002 - THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Copies: 1
Alternate Facility Name: Not reported
Alternate Facility Address: Not reported
Alternate Facility State: Not reported
Alternate Facility Date: Not reported

SUNSET CLEANERS (Continued) **S129121664**

Year:	1990
Manifest:	MAF113652
EPA ID:	CTD021816541
Generator Mailing Address:	700 BURNSIDE AVE
Generator City,State,Zip:	EAST HARTFORD, CT 06108
Discrepancies:	N
Date Shipped:	1990-06-19
Date Received:	1990-06-19
Transporter 2 Date:	Not reported
TSDF EPA ID:	CTD000845982
TSDF Name:	SAFETY KLEEN CORP 2-070-01
TSDF Address:	24 BRIXTON ST
TSDF City,State,Zip:	WEST HARTFORD, CT 06107
TSDF Country:	USA
Transporter EPA ID:	ILD051060408
Transporter Name:	SAFETY-KLEEN CORP (TRANSPORTER ONLY)
Transporter Address:	Not reported
Transporter City,State,Zip:	CT
Transporter Country:	USA
Transporter 2 EPA ID:	Not reported
Transporter 2 Name:	Not reported
Transporter 2 Address:	Not reported
Transporter 2 City,State,Zip:	CT
Transporter 2 Country:	USA
US DOT Description:	WASTE PERCHLOROETHYLENE
Number of Containers:	002
Container Type:	DM
Quantity/Weight/Volume:	140/P
Batch Number:	999999
EPA Waste Codes:	F002 - THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Copies:	1
Alternate Facility Name:	Not reported
Alternate Facility Address:	Not reported
Alternate Facility State:	Not reported
Alternate Facility Date:	Not reported

Year:	1990
Manifest:	CTC0284809
EPA ID:	CTD021816541
Generator Mailing Address:	700 BURNSIDE AVE
Generator City,State,Zip:	EAST HARTFORD, CT 06108
Discrepancies:	N
Date Shipped:	1990-01-30
Date Received:	1990-01-30
Transporter 2 Date:	Not reported
TSDF EPA ID:	CTD000845982
TSDF Name:	SAFETY KLEEN CORP 2-070-01
TSDF Address:	24 BRIXTON ST
TSDF City,State,Zip:	WEST HARTFORD, CT 06107

SUNSET CLEANERS (Continued) **S129121664**

TSDF Country:	USA
Transporter EPA ID:	ILD051060408
Transporter Name:	SAFETY-KLEEN CORP (TRANSPORTER ONLY)
Transporter Address:	Not reported
Transporter City,State,Zip:	CT
Transporter Country:	USA
Transporter 2 EPA ID:	Not reported
Transporter 2 Name:	Not reported
Transporter 2 Address:	Not reported
Transporter 2 City,State,Zip:	CT
Transporter 2 Country:	USA
US DOT Description:	WASTE PERC
Number of Containers:	002
Container Type:	DM
Quantity/Weight/Volume:	140/P
Batch Number:	999999
EPA Waste Codes:	F002 - THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Copies:	1
Alternate Facility Name:	Not reported
Alternate Facility Address:	Not reported
Alternate Facility State:	Not reported
Alternate Facility Date:	Not reported

A9 **SUNSET CLEANERS** **RCRA NonGen / NLR** **1000380508**
WNW **700 BURNSIDE AVE** **CTD021816541**
< 1/8 **EAST HARTFORD, CT 06108**
0.079 mi.
415 ft. **Site 8 of 8 in cluster A**

Relative: **Lower**

Actual: **54 ft.**

RCRA Listings:

Date Form Received by Agency:	20111108
Handler Name:	Sunset Cleaners
Handler Address:	Burnside Ave
Handler City,State,Zip:	EAST HARTFORD, CT 06108
EPA ID:	CTD021816541
Contact Name:	LAMBROS PAPPAS
Contact Address:	700 BURNSIDE AVE
Contact City,State,Zip:	EAST HARTFORD, CT 06108
Contact Telephone:	203-289-1302
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	01
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported

SUNSET CLEANERS (Continued) **1000380508**

State District:		Not reported
Mailing Address:		BURNSIDE AVE
Mailing City,State,Zip:		EAST HARTFORD, CT 06108
Owner Name:	Pappas Lambros	
Owner Type:		Private
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20150414
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No
Sub-Part P Indicator:		No

Hazardous Waste Summary:

Waste Code:	F002
Waste Description:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The

SUNSET CLEANERS (Continued) **1000380508**

Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: PAPPAS LAMBROS	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	OWNERSTREET
Owner/Operator City,State,Zip:	OWNERCITY, CT 99999
Owner/Operator Telephone:	203-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: PAPPAS LAMBROS	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	OWNERSTREET
Owner/Operator City,State,Zip:	OWNERCITY, CT 99999
Owner/Operator Telephone:	203-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20111108
Handler Name: SUNSET CLEANERS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19870115
Handler Name: SUNSET CLEANERS	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

SUNSET CLEANERS (Continued) **1000380508**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

B10 **EAST HARTFORD MIDDLE SCHOOL** **CT UST** **U002028374**
East **777 BURNSIDE AVE** **N/A**
1/8-1/4 **EAST HARTFORD, CT 06108**
0.128 mi.
674 ft. **Site 1 of 2 in cluster B**

Relative:
Higher

Actual:
84 ft.

UST:

Name:	EAST HARTFORD MIDDLE SCHOOL
Address:	777 BURNSIDE AVE
Address 2:	Not reported
City,State,Zip:	EAST HARTFORD 06108
Facility ID:	43-5189
Substance:	Heating Oil(on-site consumption)
Last Use Date:	07/01/1989
Tank ID:	EHN1
Closure Status:	Tank was Removed From Ground
Compartment ID:	a
Tank Status:	Permanently Closed
Secondary Material:	Not reported
Tank Material:	Asphalt Coated or Bare Steel
Capacity:	20000
Install Date:	01/01/1955
Overfill Installed:	Not reported
Pipe Material:	Bare Steel
Pipe Mode Description:	Not reported
Spill Installed:	Not reported
Latitude:	41.780101
Longitude:	-72.604753
Tank Latitude:	41.780101
Tank Longitude:	-72.604753

Contact:

Facility ID:	43-5189
Owner Name:	TOWN OF EAST HARTFORD
Owner Address:	734 Tolland St
Owner Address 2:	PUBLIC SCHOOLS FACILITIES DEPARTMENT
Owner Phone:	(860) 622-5952
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT 061082727
Affiliation Type:	Billing Contact
Contact Name:	Benjamin Whittaker
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5189
Owner Name:	TOWN OF EAST HARTFORD
Owner Address:	734 Tolland St

EAST HARTFORD MIDDLE SCHOOL (Continued) **U002028374**

Owner Address 2:	PUBLIC SCHOOLS FACILITIES DEPARTMENT
Owner Phone:	(860) 622-5952
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT 061082727
Affiliation Type:	Off Site Records
Contact Name:	Benjamin Whittaker
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5189
Owner Name:	TOWN OF EAST HARTFORD
Owner Address:	734 Tolland St
Owner Address 2:	PUBLIC SCHOOLS FACILITIES DEPARTMENT
Owner Phone:	(860) 622-5952
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT 061082727
Affiliation Type:	Operator
Contact Name:	Benjamin Whittaker
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5189
Owner Name:	AARON ENVIRONMENTAL LLC
Owner Address:	189 ATWATER ST
Owner Address 2:	Not reported
Owner Phone:	(860) 276-1201
Owner Phone Ext:	Not reported
Owner City/State/Zip:	PLANTSVILLE, CT 064791674
Affiliation Type:	Other
Contact Name:	Joe Paterak
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5189
Owner Name:	TOWN OF EAST HARTFORD
Owner Address:	734 Tolland St
Owner Address 2:	PUBLIC SCHOOLS FACILITIES DEPARTMENT
Owner Phone:	(860) 622-5952
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT 061082727
Affiliation Type:	Owner
Contact Name:	Benjamin Whittaker
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5189
Owner Name:	TOWN OF EAST HARTFORD
Owner Address:	734 Tolland St
Owner Address 2:	PUBLIC SCHOOLS FACILITIES DEPARTMENT
Owner Phone:	(860) 622-5952
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT 061082727
Affiliation Type:	Primary Contact
Contact Name:	Benjamin Whittaker
Contact Title:	Not reported
Contact Email:	Not reported

EAST HARTFORD MIDDLE SCHOOL (Continued) **U002028374**

Facility ID:	43-5189
Owner Name:	TOWN OF EAST HARTFORD
Owner Address:	734 Tolland St
Owner Address 2:	PUBLIC SCHOOLS FACILITIES DEPARTMENT
Owner Phone:	(860) 622-5952
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT 061082727
Affiliation Type:	Property Owner
Contact Name:	Benjamin Whittaker
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5189
Owner Name:	TOWN OF EAST HARTFORD
Owner Address:	734 Tolland St
Owner Address 2:	PUBLIC SCHOOLS FACILITIES DEPARTMENT
Owner Phone:	(860) 622-5952
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT 061082727
Affiliation Type:	Registrant
Contact Name:	Benjamin Whittaker
Contact Title:	Not reported
Contact Email:	Not reported

Name:	EAST HARTFORD MIDDLE SCHOOL
Address:	777 BURNSIDE AVE
Address 2:	Not reported
City,State,Zip:	EAST HARTFORD 06108
Facility ID:	43-5189
Substance:	Heating Oil(on-site consumption)
Last Use Date:	07/31/2017
Tank ID:	EHNR1
Closure Status:	Tank was Removed From Ground
Compartment ID:	Not reported
Tank Status:	Permanently Closed
Secondary Material:	Double Walled
Tank Material:	Coated & Cathodically Protected Steel (sti-P3)
Capacity:	12000
Install Date:	08/01/1989
Overfill Installed:	Not reported
Pipe Material:	Epoxy Coated Steel
Pipe Mode Description:	Cathodically Protected,Containment Sumps @ Tanks,Metallic fittings isolated from soil and water,Single Walled
Spill Installed:	Not reported
Latitude:	41.780101
Longitude:	-72.604753
Tank Latitude:	41.780101
Tank Longitude:	-72.604753

Contact:

Facility ID:	43-5189
Owner Name:	TOWN OF EAST HARTFORD
Owner Address:	734 Tolland St
Owner Address 2:	PUBLIC SCHOOLS FACILITIES DEPARTMENT
Owner Phone:	(860) 622-5952
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT 061082727

EAST HARTFORD MIDDLE SCHOOL (Continued) **U002028374**

Affiliation Type:	Billing Contact
Contact Name:	Benjamin Whittaker
Contact Title:	Not reported
Contact Email:	Not reported
Facility ID:	43-5189
Owner Name:	TOWN OF EAST HARTFORD
Owner Address:	734 Tolland St
Owner Address 2:	PUBLIC SCHOOLS FACILITIES DEPARTMENT
Owner Phone:	(860) 622-5952
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT 061082727
Affiliation Type:	Off Site Records
Contact Name:	Benjamin Whittaker
Contact Title:	Not reported
Contact Email:	Not reported
Facility ID:	43-5189
Owner Name:	TOWN OF EAST HARTFORD
Owner Address:	734 Tolland St
Owner Address 2:	PUBLIC SCHOOLS FACILITIES DEPARTMENT
Owner Phone:	(860) 622-5952
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT 061082727
Affiliation Type:	Operator
Contact Name:	Benjamin Whittaker
Contact Title:	Not reported
Contact Email:	Not reported
Facility ID:	43-5189
Owner Name:	AARON ENVIRONMENTAL LLC
Owner Address:	189 ATWATER ST
Owner Address 2:	Not reported
Owner Phone:	(860) 276-1201
Owner Phone Ext:	Not reported
Owner City/State/Zip:	PLANTSVILLE, CT 064791674
Affiliation Type:	Other
Contact Name:	Joe Paterak
Contact Title:	Not reported
Contact Email:	Not reported
Facility ID:	43-5189
Owner Name:	TOWN OF EAST HARTFORD
Owner Address:	734 Tolland St
Owner Address 2:	PUBLIC SCHOOLS FACILITIES DEPARTMENT
Owner Phone:	(860) 622-5952
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT 061082727
Affiliation Type:	Owner
Contact Name:	Benjamin Whittaker
Contact Title:	Not reported
Contact Email:	Not reported
Facility ID:	43-5189
Owner Name:	TOWN OF EAST HARTFORD
Owner Address:	734 Tolland St
Owner Address 2:	PUBLIC SCHOOLS FACILITIES DEPARTMENT

EAST HARTFORD MIDDLE SCHOOL (Continued) **U002028374**

Owner Phone:	(860) 622-5952
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT 061082727
Affiliation Type:	Primary Contact
Contact Name:	Benjamin Whittaker
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5189
Owner Name:	TOWN OF EAST HARTFORD
Owner Address:	734 Tolland St
Owner Address 2:	PUBLIC SCHOOLS FACILITIES DEPARTMENT
Owner Phone:	(860) 622-5952
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT 061082727
Affiliation Type:	Property Owner
Contact Name:	Benjamin Whittaker
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5189
Owner Name:	TOWN OF EAST HARTFORD
Owner Address:	734 Tolland St
Owner Address 2:	PUBLIC SCHOOLS FACILITIES DEPARTMENT
Owner Phone:	(860) 622-5952
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT 061082727
Affiliation Type:	Registrant
Contact Name:	Benjamin Whittaker
Contact Title:	Not reported
Contact Email:	Not reported

Name:	EAST HARTFORD MIDDLE SCHOOL
Address:	777 BURNSIDE AVE
Address 2:	Not reported
City,State,Zip:	EAST HARTFORD 06108
Facility ID:	43-5189
Substance:	Heating Oil(on-site consumption)
Last Use Date:	04/07/2015
Tank ID:	EHOR1
Closure Status:	Tank was Removed From Ground
Compartment ID:	Not reported
Tank Status:	Permanently Closed
Secondary Material:	Double Walled
Tank Material:	Coated & Cathodically Protected Steel (sti-P3)
Capacity:	12000
Install Date:	08/01/1989
Overfill Installed:	Flapper Device
Pipe Material:	Epoxy Coated Steel
Pipe Mode Description:	Cathodically Protected
Spill Installed:	Spill Bucket
Latitude:	41.780101
Longitude:	-72.604753
Tank Latitude:	41.780101
Tank Longitude:	-72.604753

EAST HARTFORD MIDDLE SCHOOL (Continued) **U002028374**

Contact:

Facility ID:	43-5189
Owner Name:	TOWN OF EAST HARTFORD
Owner Address:	734 Tolland St
Owner Address 2:	PUBLIC SCHOOLS FACILITIES DEPARTMENT
Owner Phone:	(860) 622-5952
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT 061082727
Affiliation Type:	Billing Contact
Contact Name:	Benjamin Whittaker
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5189
Owner Name:	TOWN OF EAST HARTFORD
Owner Address:	734 Tolland St
Owner Address 2:	PUBLIC SCHOOLS FACILITIES DEPARTMENT
Owner Phone:	(860) 622-5952
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT 061082727
Affiliation Type:	Off Site Records
Contact Name:	Benjamin Whittaker
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5189
Owner Name:	TOWN OF EAST HARTFORD
Owner Address:	734 Tolland St
Owner Address 2:	PUBLIC SCHOOLS FACILITIES DEPARTMENT
Owner Phone:	(860) 622-5952
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT 061082727
Affiliation Type:	Operator
Contact Name:	Benjamin Whittaker
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5189
Owner Name:	AARON ENVIRONMENTAL LLC
Owner Address:	189 ATWATER ST
Owner Address 2:	Not reported
Owner Phone:	(860) 276-1201
Owner Phone Ext:	Not reported
Owner City/State/Zip:	PLANTSVILLE, CT 064791674
Affiliation Type:	Other
Contact Name:	Joe Paterak
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5189
Owner Name:	TOWN OF EAST HARTFORD
Owner Address:	734 Tolland St
Owner Address 2:	PUBLIC SCHOOLS FACILITIES DEPARTMENT
Owner Phone:	(860) 622-5952
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT 061082727
Affiliation Type:	Owner

EAST HARTFORD MIDDLE SCHOOL (Continued) **U002028374**

Contact Name:	Benjamin Whittaker
Contact Title:	Not reported
Contact Email:	Not reported
Facility ID:	43-5189
Owner Name:	TOWN OF EAST HARTFORD
Owner Address:	734 Tolland St
Owner Address 2:	PUBLIC SCHOOLS FACILITIES DEPARTMENT
Owner Phone:	(860) 622-5952
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT 061082727
Affiliation Type:	Primary Contact
Contact Name:	Benjamin Whittaker
Contact Title:	Not reported
Contact Email:	Not reported
Facility ID:	43-5189
Owner Name:	TOWN OF EAST HARTFORD
Owner Address:	734 Tolland St
Owner Address 2:	PUBLIC SCHOOLS FACILITIES DEPARTMENT
Owner Phone:	(860) 622-5952
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT 061082727
Affiliation Type:	Property Owner
Contact Name:	Benjamin Whittaker
Contact Title:	Not reported
Contact Email:	Not reported
Facility ID:	43-5189
Owner Name:	TOWN OF EAST HARTFORD
Owner Address:	734 Tolland St
Owner Address 2:	PUBLIC SCHOOLS FACILITIES DEPARTMENT
Owner Phone:	(860) 622-5952
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT 061082727
Affiliation Type:	Registrant
Contact Name:	Benjamin Whittaker
Contact Title:	Not reported
Contact Email:	Not reported

B11 **EAST HARTFORD MIDDLE SCHOOL** **CT LUST** **S103156056**
East **777 BURNSIDE AVE** **CT SPILLS** **N/A**
1/8-1/4 **EAST HARTFORD, CT 06108** **CT ASBESTOS**
0.128 mi. **CT CPCS**
674 ft. **Site 2 of 2 in cluster B** **CT NPDES**

Relative: **Higher**
Actual: **84 ft.**

LUST:

Name:	EAST HARTFORD MIDDLE SCHOOL
Name 2:	Not reported
Address:	777 BURNSIDE AVENUE
Address 2:	Not reported
City,State,Zip:	EAST HARTFORD, CT 06108
LUST Case Id:	61409
Release Date:	Not reported
Site Case ID:	0
Substance:	Not reported
Release Source:	Not reported

EAST HARTFORD MIDDLE SCHOOL (Continued) **S103156056**

Release Cause:	Not reported
Release Identified:	Not reported
Case Number:	Not reported
Release Quantity:	Not reported
Facility City Number:	43

Detail As of 06/2020:

Name:	EAST HARTFORD MIDDLE SCHOOL
Name 2:	Not reported
Address:	777 BURNSIDE AVENUE
City,State,Zip:	EAST HARTFORD, CT 06108
Address 2:	Not reported
LUST Id:	0
UST Facility Id:	5189
LUST Case Id:	61409
Lust Status:	Lust Completed
Processing Status:	Not reported
EPA Reportable:	False
Motor Fuel:	False
Diesel:	False
Gasoline:	False
Other:	False
Other Release:	Not reported
No Release:	False
Leak:	False
Tank:	True
Piping:	False
Overfill:	False
Removal:	True
Incident Date:	08/23/2017
Entry Date:	05/16/2018
Site Case Id:	0
UST Site Id:	0
Cost Recovery Spill Case #:	0
Old SITS Number:	0
Case Log Id:	0
Monthly Report Id:	0
UST Owner Id:	6972
LUST Owner Id:	Not reported
UST Event Id:	0
Contact Info:	Not reported
Contact EMail:	Not reported
Site Contact City,St,Zip:	UNKNOWN
2nd Contact:	William Martin Black (Aaron Environmental)
2nd Contact EMail:	wmartin-black@aaronenvironmental.com
2nd Contact Address:	189 Atwater Street
2nd Contact City,St,Zip:	131, CT 06479
2nd Contact Address 2:	Not reported
2nd Contact City 2:	Plantsville
2nd Contact Phone Number:	8602761201
2nd Contact Fax Number:	8602761233
2nd Contact Type:	General Manager
Facility City Num:	43
Site Contact:	Not reported
Site Contact Address:	Not reported
Site Contact Add 2:	Not reported
Site Contact City 2:	Not reported
Site Contact Phone:	Not reported

EAST HARTFORD MIDDLE SCHOOL (Continued) **S103156056**

Site Contact Fax:	Not reported
Site Contact Type:	Not reported
Department Contact 1:	Not reported
Department Contact 2:	Not reported
Referral Source:	Not reported
Offsite Source:	False
Date Referred:	Not reported
Emergency:	False
Private Heating Fuel:	False
Commercial Heating Fuel:	True
Commercial HF < 2100 Gal.:	False
Commercial HF > 2100 Gal.:	True
Commercial HF - Size Unk:	False
No LUST Site:	False
Cost Recvry Prgm Candidate:	False
OCSRD Complete:	False
Follow Up Flag:	False
Alternate Water Supply:	False
Relocation:	False
Responsible Party:	False
Responsible EMail:	whittaker.bp@easthartford.org
Resp Party Name:	Town of East Hartford
Resp Party Address:	734 Tolland St
Resp Party City,St,Zip:	East Hartford, CT 061082727
Resp Party Town Number:	43
Resp Party Phone:	8606225952
Resp Party Fax:	Not reported
Resp Party Name 2:	PUBLIC SCHOOLS FACILITIES DEPARTMENT
Resp Party Address 2:	Not reported
Resp Party Phone 2:	Not reported
Investigator Id:	0
Follow Update:	Not reported
Area Lextent:	Not reported
Annual Precipitation:	Not reported
Affected Population:	Not reported
Population Setting:	Not reported
Ground Water Direction:	Not reported
Ground Water Gradient:	Not reported
Hydro Basin:	Not reported
Drastic:	Not reported
Geo Setting:	Not reported
Ground Water Classification:	GA
Receptor:	Not reported
Ground Water Flow Direction:	Not reported
Ground Water Depth:	Not reported
Areas Of Concern:	Not reported
Free Product Inches:	0
Fund Date:	Not reported
Fund Planned:	No
Fund Obligated:	No
Fund Outlayed:	No
Fund Judgment:	No
Fund Recovered:	No
Cellar Borings:	False
Install Micro Wells:	False
Ground Water Sample:	True
Soil Sample:	True

EAST HARTFORD MIDDLE SCHOOL (Continued) **S103156056**

Soil Gas:	False
Site Inspect:	False
Soil Excavate:	False
Geo Probe:	False
Survey:	False
Potable Well Sample:	False
Sample MWS:	False
Ground Water Gauging:	False
Soil Venting:	False
Active:	False
NOV Action:	None
NOV Issued:	Not reported
NOV Due:	Not reported
NOV Received:	Not reported
NOV Closed:	Not reported
NOV Disc Date:	Not reported
NOV Issued Date:	Not reported
NOV Compliance Sched:	Not reported
NOV Admin Order:	Not reported
NOV Referred To Ag:	Not reported
Stop All NOV Actions:	False
Release Invest Rpt:	False
DEP App Letter 1:	False
Correct Action Plan:	False
DEP App Letter 2:	False
Rem Sys Install:	False
Rem Sys Install Date:	Not reported
Closure Date:	Not reported
Rem Sys Monitoring Rpt:	False
Qrtly Gwater Mon Rpts:	False
Closure Req Rpt:	False
DEP Closure Letter:	False
Referred To:	Not reported
No Wells:	0
Lph Wells:	0
User Stamp:	ForrestA/forrestlaiuppaa
Date Stamp:	05/16/2018
Correspondence:	Not reported
Environmental Impact:	Not reported
FollowUp:	Not reported
GW Comments:	Site in area of public supply serviced by MDC. Note not all properties within 500 ft of site are in the areas shaded as supply service area in Envirodata Viewer on 5/16/2018.
Location Desc:	Not reported
NOV Comments:	Not reported
Release Desc:	Not reported
Running Comments:	UST Enforcement Files and FileNet
Work Performed:	Not reported

SPILLS:

Name:	Not reported
Address:	777 BURNSIDE AVE
City,State,Zip:	EAST HARTFORD, CT
Year of Database:	2010
Case Number:	201000357
Who Took Spill:	202

EAST HARTFORD MIDDLE SCHOOL (Continued) **S103156056**

Assigned To:	No Response
Report Date:	01/20/2010
Report Time:	12:00:00 AM
Date Release:	01/20/2010
Release Time:	12:00:00 AM
Reported By:	972
Phone:	860 5284401
Qty:	0.00 (Gallons)
Telephone:	Not reported
Representing:	fd
Facility Status:	CLOSED
Continuous Spill:	False
Release Substance:	ANTIFREEZE
Emergency Measure:	contents of a radiator
Discharger:	Not reported
Waterbody Affected:	Other (none)
Responsible Party:	Not reported
Responsible Party Address:	Not reported
RP City,St,Zip:	CT
Terminated:	YES
Recovered Total:	0
Total Water:	0
Historic:	False
Waterbody:	Not reported
User Stamp:	RLandry
Stamp Time:	2010-01-20 16:58:05
SR Inspector:	Landry, Robin
AT Inspector:	**NO RESPONSE
Corrective Action Taken:	Sanded
Cause Info:	MV Accident
Media Info:	Ground Surface
Release Type:	chemical
Incident Description:	Not reported
Cost Recovery Case?:	Not reported
DEMHS Region:	Not reported
Lat/Long:	Not reported
Company Name:	Not reported
Last Updated:	Not reported

Action:

Action:	Sanded
Other Action:	Not reported

Agency:

Agency ID:	DEP Dispatch
Other Agency:	Not reported
DEP Bureau:	Not reported
DEP Agency:	Not reported
Agency ID:	LOCAL FIRE DEPARTMENT
Other Agency:	Not reported
DEP Bureau:	Not reported
DEP Agency:	Not reported

Cause:

Cause ID:	MV Accident
Other Cause:	Not reported

EAST HARTFORD MIDDLE SCHOOL (Continued) **S103156056**

Media:
Media ID: Ground Surface
Other Media: Not reported

Release Class:
Class ID: Transportation
Other Class: Not reported

Class ID: Private
Other Class: Not reported

Release Type:
Release Type: chemical
Other Release: Not reported

Waterbody:
Waterbody: Other
Other Waterbody: none

Name: Not reported
Address: 777 BURNSIDE AVE
City,State,Zip: EAST HARTFORD, CT
Year of Database: 1996
Case Number: 9605124
Who Took Spill: 913
Assigned To: No Response
Report Date: 10/03/1996
Report Time: 12:00:00 AM
Date Release: 10/03/1996
Release Time: 12:00:00 AM
Reported By: ken locke
Phone: 2917367
Qty: 0.00 (Gallons)
Telephone: Not reported
Representing: town of east hartford
Facility Status: closed
Continuous Spill: False
Release Substance: hypro cloride solution
Emergency Measure: flushed down
Discharger: east hartford board of ed.
Waterbody Affected: River
Responsible Party: Not reported
Responsible Party Address: 777 burnside ave
RP City,St,Zip: EAST HARTFORD, CT 06108
Terminated: YES
Recovered Total: 0
Total Water: 0
Historic: False
Waterbody: hockanum river
User Stamp: Not reported
Stamp Time: 1997-01-10 09:05:17
SR Inspector: Alexander, Ed
AT Inspector: **NO RESPONSE
Corrective Action Taken: Not reported

EAST HARTFORD MIDDLE SCHOOL (Continued) **S103156056**

Cause Info:	Not reported
Media Info:	Surface Water
Release Type:	chemical
Incident Description:	Not reported
Cost Recovery Case?:	Not reported
DEMHS Region:	Not reported
Lat/Long:	Not reported
Company Name:	Not reported
Last Updated:	Not reported

Media:

Media ID:	Surface Water
Other Media:	Not reported

Release Type:

Release Type:	chemical
Other Release:	Not reported

Waterbody:

Waterbody:	River
Other Waterbody:	Not reported

ASBESTOS:

Name:	EAST HARTFORD PUBLIC SCHOOLS
Address:	777 BURNSIDE AVE
City,State,Zip:	EAST HARTFORD, CT 06108
ID:	55473
Trans Number:	90
Enter Date:	Not reported
Postmark Date:	08/06/2015
Check Amount:	$100.00
Check Number:	22670
Type of Notification (new):	Not reported
Type of Notification (cancel):	Not reported
Type of Notification (revised):	X
Type of Notification (blanket):	Not reported
Type of Notification (emergency):	Not reported
Project Type:	EAST HARTFORD MIDDLE SCHOOL
Start Date:	08/22/2015
End Date:	08/22/2015
Licence Number:	000055
Contractor:	HAZ-PROS, INC
Contractor Address:	125-A BROOK STREET
Contractor City:	WEST HARTFORD
Contractor State:	CT
Contractor Zip:	06110
Owner:	MINERVA
Hauler:	RED TECH
Location of Demo:	Not reported
Inspection Conducted:	Not reported
Inspector Name:	Not reported
Inspector License Number:	Not reported
Disposal Facility:	Not reported

EAST HARTFORD MIDDLE SCHOOL (Continued) **S103156056**

Name:	EST HARTFORD PUBLIC SCHOOLS
Address:	777 BURNSIDE AVE
City,State,Zip:	EAST HARTFORD, CT 06108
ID:	63542
Trans Number:	34
Enter Date:	Not reported
Postmark Date:	07/15/2017
Check Amount:	$282.50
Check Number:	24854
Type of Notification (new):	X
Type of Notification (cancel):	Not reported
Type of Notification (revised):	Not reported
Type of Notification (blanket):	Not reported
Type of Notification (emergency):	Not reported
Project Type:	Not reported
Start Date:	08/04/2017
End Date:	08/14/2017
Licence Number:	000055
Contractor:	HAZ-PROS, INC.
Contractor Address:	125-A BROOK STREET
Contractor City:	WEST HARTFORD
Contractor State:	CT
Contractor Zip:	06110
Owner:	MINERVA
Hauler:	RED
Location of Demo:	Not reported
Inspection Conducted:	Not reported
Inspector Name:	Not reported
Inspector License Number:	Not reported
Disposal Facility:	Not reported

Name:	EAST HARTFORD PUBLIC SCHOOLS
Address:	777 BURNSIDE AVENUE
City,State,Zip:	EAST HARTFORD, CT 06108
ID:	74411
Trans Number:	20-348
Enter Date:	Not reported
Postmark Date:	12/10/2019
Check Amount:	$164.59
Check Number:	27851
Type of Notification (new):	X
Type of Notification (cancel):	Not reported
Type of Notification (revised):	Not reported
Type of Notification (blanket):	Not reported
Type of Notification (emergency):	Not reported
Project Type:	Not reported
Start Date:	12/23/2019
End Date:	12/30/2019
Licence Number:	000055
Contractor:	HAZ-PROS, INC.
Contractor Address:	125 A BROOK ST
Contractor City:	WEST HARTFORD
Contractor State:	CT
Contractor Zip:	06110
Owner:	MINERVA
Hauler:	RED TECH
Location of Demo:	Not reported

EAST HARTFORD MIDDLE SCHOOL (Continued) **S103156056**

Inspection Conducted:	Not reported
Inspector Name:	Not reported
Inspector License Number:	Not reported
Disposal Facility:	Not reported
Name:	EAST HARTFORD PUBLIC SCHOOLS
Address:	777 BURNSIDE AVE
City,State,Zip:	EAST HARTFORD, CT 06108
ID:	63209
Trans Number:	742
Enter Date:	Not reported
Postmark Date:	06/16/2017
Check Amount:	$159.50
Check Number:	24774
Type of Notification (new):	X
Type of Notification (cancel):	Not reported
Type of Notification (revised):	Not reported
Type of Notification (blanket):	Not reported
Type of Notification (emergency):	Not reported
Project Type:	EAST HARTFORD MIDDLE SCH
Start Date:	06/23/2017
End Date:	06/27/2017
Licence Number:	000055
Contractor:	HAZ-PROS, INC.
Contractor Address:	125-A BROOK STREET
Contractor City:	WEST HARTFORD
Contractor State:	CT
Contractor Zip:	06110
Owner:	MINERVA
Hauler:	RED
Location of Demo:	Not reported
Inspection Conducted:	Not reported
Inspector Name:	Not reported
Inspector License Number:	Not reported
Disposal Facility:	Not reported
Name:	EAST HARTFORD PUBLIC SCHOOLS
Address:	777 BURNSIDE AVE ROOM 224
City,State,Zip:	EAST HARTFORD, CT 06108
ID:	83467
Trans Number:	22-410
Enter Date:	Not reported
Postmark Date:	02/17/2022
Check Amount:	164.59
Check Number:	31105
Type of Notification (new):	Not reported
Type of Notification (cancel):	Not reported
Type of Notification (revised):	X
Type of Notification (blanket):	Not reported
Type of Notification (emergency):	Not reported
Project Type:	EH MIDDLE SCHOOL
Start Date:	04/11/2022
End Date:	04/14/2022
Licence Number:	000055
Contractor:	HAZ-PROS
Contractor Address:	125 A BROOK STREET
Contractor City:	WEST HARTFORD

EAST HARTFORD MIDDLE SCHOOL (Continued) **S103156056**

Contractor State:	CT
Contractor Zip:	06110
Owner:	MINERVA
Hauler:	RED TECH
Location of Demo:	Not reported
Inspection Conducted:	Not reported
Inspector Name:	Not reported
Inspector License Number:	Not reported
Disposal Facility:	Not reported

Name:	EAST HARTFORD PUBLIC SCHOOLS
Address:	777 BURNSIDE AVE
City,State,Zip:	EAST HARTFORD, CT 06108
ID:	50623
Trans Number:	710
Enter Date:	Not reported
Postmark Date:	06/16/2014
Check Amount:	$348.80
Check Number:	21409
Type of Notification (new):	X
Type of Notification (cancel):	Not reported
Type of Notification (revised):	Not reported
Type of Notification (blanket):	Not reported
Type of Notification (emergency):	Not reported
Project Type:	EAST HARTFORD MIDDLE SCHOOL
Start Date:	06/24/2014
End Date:	07/11/2014
Licence Number:	000055
Contractor:	HAZ-PROS, INC
Contractor Address:	125-A BROOK STREET
Contractor City:	WEST HARTFORD
Contractor State:	CT
Contractor Zip:	06110
Owner:	MINERVA
Hauler:	RED TECH
Location of Demo:	Not reported
Inspection Conducted:	Not reported
Inspector Name:	Not reported
Inspector License Number:	Not reported
Disposal Facility:	Not reported

Name:	EAST HARTFORD PUBLIC SCHOOLS
Address:	777 BURNSIDE AVENUE
City,State,Zip:	EAST HARTFORD, CT 06108
ID:	80870
Trans Number:	Not reported
Enter Date:	Not reported
Postmark Date:	07/15/2021
Check Amount:	164.59
Check Number:	30234
Type of Notification (new):	X
Type of Notification (cancel):	Not reported
Type of Notification (revised):	Not reported
Type of Notification (blanket):	Not reported
Type of Notification (emergency):	Not reported
Project Type:	EAST HARTFORD MIDDLE SCHOOL
Start Date:	08/16/2021

EAST HARTFORD MIDDLE SCHOOL (Continued) **S103156056**

End Date:	08/20/2021
Licence Number:	000055
Contractor:	HAZ-PROS, INC.
Contractor Address:	125-A BROOK STREET
Contractor City:	WEST HARTFORD
Contractor State:	CT
Contractor Zip:	06110
Owner:	Not reported
Hauler:	RED TECHNOLOGIES
Location of Demo:	Not reported
Inspection Conducted:	Not reported
Inspector Name:	Not reported
Inspector License Number:	Not reported
Disposal Facility:	Not reported

Name:	EAST HARTFORD PUBLIC SCHOOLS
Address:	777 BURNSIDE AVENUE
City,State,Zip:	EAST HARTFORD, CT 06108
ID:	81156
Trans Number:	Not reported
Enter Date:	Not reported
Postmark Date:	08/02/2021
Check Amount:	164.59
Check Number:	30314
Type of Notification (new):	Not reported
Type of Notification (cancel):	X
Type of Notification (revised):	X
Type of Notification (blanket):	Not reported
Type of Notification (emergency):	Not reported
Project Type:	EAST HARTFORD MIDDLE SCHOOL
Start Date:	08/14/2021
End Date:	08/17/2021
Licence Number:	000055
Contractor:	HAZ-PROS, INC
Contractor Address:	125-A BROOK STREET
Contractor City:	WEST HARTFORD
Contractor State:	CT
Contractor Zip:	06110
Owner:	Not reported
Hauler:	RED TECHNOLOGIES
Location of Demo:	Not reported
Inspection Conducted:	Not reported
Inspector Name:	Not reported
Inspector License Number:	Not reported
Disposal Facility:	Not reported

Name:	EAST HARTFORD PUBLIC SCHOOLS
Address:	777 BURNSIDE AVENUE
City,State,Zip:	EAST HARTFORD, CT 06108
ID:	82418
Trans Number:	Not reported
Enter Date:	Not reported
Postmark Date:	11/12/2021
Check Amount:	164.59
Check Number:	30713
Type of Notification (new):	X
Type of Notification (cancel):	Not reported

EAST HARTFORD MIDDLE SCHOOL (Continued) **S103156056**

Type of Notification (revised):	X
Type of Notification (blanket):	Not reported
Type of Notification (emergency):	Not reported
Project Type:	MIDDLE SCHOOL ROOM 224
Start Date:	12/27/2021
End Date:	12/31/2021
Licence Number:	00055
Contractor:	HAZ-PROS INC
Contractor Address:	125-A BROOK STREET
Contractor City:	WEST HARTFORD
Contractor State:	CT
Contractor Zip:	06110
Owner:	Not reported
Hauler:	RED TECHNOLOGIES
Location of Demo:	Not reported
Inspection Conducted:	Not reported
Inspector Name:	Not reported
Inspector License Number:	Not reported
Disposal Facility:	Not reported

CPCS:

Name:	East Hartford Middle School
Address:	777 BURNSIDE AVENUE
City,State,Zip:	EAST HARTFORD, CT
Site Type:	Not reported
Lust Status code:	Not reported
Lust Status:	Not reported
PTP Form:	Not reported
Program:	LUST
Comments:	Not reported
Site Type Definition:	Not reported
Invesigation Start:	Yes
Invesigation Start Date:	Not reported
Remediation Start:	Yes
Remediation Start Date:	Not reported
Remediation Completed:	Yes
ELUR:	Not reported
Date Data Updated:	08/23/2017

NPDES:

Name:	EAST HARTFORD MIDDLE SCHOOL
Address:	777 BURNSIDE AVE
City:	EAST HARTFORD
Town Id:	Not reported
Company Name:	Not reported
Permit Number:	GPL000212
Permit Issued Date:	07/29/2010
Permit Expiration Date:	07/09/2014
Application Received Date:	Not reported
Affiliation Type:	Permittee
Permit EI Type:	Swimming Pool Wastewater-GP
App Id:	201004381
Site Address Description:	Not reported
Site Address Line 2:	Not reported
Permit Description:	Not reported
Status:	Expired

EAST HARTFORD MIDDLE SCHOOL (Continued) **S103156056**

Affiliate Address Line 1:	734 Tolland St
Affiliate Address Line 2:	Not reported
Affiliate City/State/Zip:	East Hartford, CT 06108-2727
Contact Name:	Not reported
Contact Title:	Not reported
Contact EMail:	Not reported
Name:	EAST HARTFORD MIDDLE SCHOOL
Address:	777 BURNSIDE AVE
City:	EAST HARTFORD
Town Id:	Not reported
Company Name:	Not reported
Permit Number:	GPL000212
Permit Issued Date:	10/03/2014
Permit Expiration Date:	08/09/2024
Application Received Date:	Not reported
Affiliation Type:	Registrant
Permit EI Type:	Swimming Pool Wastewater-GP
App Id:	201408562
Site Address Description:	Not reported
Site Address Line 2:	Not reported
Permit Description:	East Hartford Middle School - 777 Burnside Ave. East Hartford, CT. 06108
Status:	Active
Affiliate Address Line 1:	740 MAIN ST
Affiliate Address Line 2:	Not reported
Affiliate City/State/Zip:	EAST HARTFORD, CT 06108-3140
Contact Name:	Not reported
Contact Title:	Not reported
Contact EMail:	Not reported

12
WSW
1/8-1/4
0.129 mi.
680 ft.

SAINT ROSE CHURCH CORP. OF BURNSIDE **CT UST** **U004136333**
21 CHURCH ST **N/A**
EAST HARTFORD, CT 06108

Relative:
Lower

Actual:
58 ft.

UST:

Name:	SAINT ROSE CHURCH CORP. OF BURNSIDE
Address:	21 CHURCH ST
Address 2:	Not reported
City,State,Zip:	EAST HARTFORD 06108
Facility ID:	43-9128
Substance:	Heating Oil(on-site consumption)
Last Use Date:	Not reported
Tank ID:	A1
Closure Status:	Tank was Abandoned in Ground
Compartment ID:	a
Tank Status:	Permanently Closed
Secondary Material:	Not reported
Tank Material:	Asphalt Coated or Bare Steel
Capacity:	3000
Install Date:	06/01/1955
Overfill Installed:	Not reported
Pipe Material:	Bare Steel
Pipe Mode Description:	Not reported
Spill Installed:	Not reported
Latitude:	41.778716

SAINT ROSE CHURCH CORP. OF BURNSIDE (Continued) **U004136333**

Longitude:	-72.609196
Tank Latitude:	41.778716
Tank Longitude:	-72.609196

Contact:

Facility ID:	43-9128
Owner Name:	SAINT ROSE CHURCH CORP. OF BURNSIDE
Owner Address:	33 CHURCH ST
Owner Address 2:	Not reported
Owner Phone:	(203) 289-8616
Owner Phone Ext:	Not reported
Owner City/State/Zip:	EAST HARTFORD, CT 061083728
Affiliation Type:	Owner
Contact Name:	Not reported
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-9128
Owner Name:	SAINT ROSE CHURCH CORP. OF BURNSIDE
Owner Address:	33 CHURCH ST
Owner Address 2:	Not reported
Owner Phone:	Not reported
Owner Phone Ext:	Not reported
Owner City/State/Zip:	EAST HARTFORD, CT 061083728
Affiliation Type:	Registrant
Contact Name:	Not reported
Contact Title:	Not reported
Contact Email:	Not reported

Name:	SAINT ROSE CHURCH CORP. OF BURNSIDE
Address:	21 CHURCH ST
Address 2:	Not reported
City,State,Zip:	EAST HARTFORD 06108
Facility ID:	43-9128
Substance:	Heating Oil(on-site consumption)
Last Use Date:	07/07/2008
Tank ID:	A1R1
Closure Status:	Tank was Removed From Ground
Compartment ID:	a
Tank Status:	Permanently Closed
Secondary Material:	Not reported
Tank Material:	Asphalt Coated or Bare Steel
Capacity:	6000
Install Date:	11/01/1989
Overfill Installed:	Not reported
Pipe Material:	Rigid Fiberglass Reinforced Plastic
Pipe Mode Description:	Not reported
Spill Installed:	Not reported
Latitude:	41.778716
Longitude:	-72.609196
Tank Latitude:	41.77877
Tank Longitude:	-72.61018

Contact:

Facility ID:	43-9128
Owner Name:	SAINT ROSE CHURCH CORP. OF BURNSIDE
Owner Address:	33 CHURCH ST

SAINT ROSE CHURCH CORP. OF BURNSIDE (Continued) **U004136333**

Owner Address 2:	Not reported
Owner Phone:	(203) 289-8616
Owner Phone Ext:	Not reported
Owner City/State/Zip:	EAST HARTFORD, CT 061083728
Affiliation Type:	Owner
Contact Name:	Not reported
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-9128
Owner Name:	SAINT ROSE CHURCH CORP. OF BURNSIDE
Owner Address:	33 CHURCH ST
Owner Address 2:	Not reported
Owner Phone:	Not reported
Owner Phone Ext:	Not reported
Owner City/State/Zip:	EAST HARTFORD, CT 061083728
Affiliation Type:	Registrant
Contact Name:	Not reported
Contact Title:	Not reported
Contact Email:	Not reported

C13 **EAST HARTFORD HOUSING** **CT LUST** **S100998220**
West **COLUMBUS CIRCLE EXT.** **CT CPCS** **N/A**
1/8-1/4 **EAST HARTFORD, CT 06108**
0.142 mi.
751 ft. **Site 1 of 10 in cluster C**

Relative:
Lower

Actual:
50 ft.

LUST:

Name:	EAST HARTFORD HOUSING
Name 2:	Not reported
Address:	COLUMBUS CIRCLE EXT.
Address 2:	Not reported
City,State,Zip:	EAST HARTFORD, CT 06108
LUST Case Id:	29496
Release Date:	Not reported
Site Case ID:	Not reported
Substance:	Not reported
Release Source:	Not reported
Release Cause:	Not reported
Release Identified:	Not reported
Case Number:	Not reported
Release Quantity:	Not reported
Facility City Number:	43

Detail As of 06/2020:

Name:	EAST HARTFORD HOUSING
Name 2:	Not reported
Address:	COLUMBUS CIRCLE EXT.
City,State,Zip:	EAST HARTFORD, CT 06108
Address 2:	Not reported
LUST Id:	1387
UST Facility Id:	Not reported
LUST Case Id:	29496
Lust Status:	Lust Completed
Processing Status:	Not reported
EPA Reportable:	False
Motor Fuel:	False

EAST HARTFORD HOUSING (Continued) **S100998220**

Diesel:	False
Gasoline:	False
Other:	False
Other Release:	Not reported
No Release:	False
Leak:	False
Tank:	False
Piping:	False
Overfill:	False
Removal:	False
Incident Date:	08/31/1989
Entry Date:	Not reported
Site Case Id:	Not reported
UST Site Id:	Not reported
Cost Recovery Spill Case #:	Not reported
Old SITS Number:	Not reported
Case Log Id:	Not reported
Monthly Report Id:	0
UST Owner Id:	Not reported
LUST Owner Id:	Not reported
UST Event Id:	1386
Contact Info:	Not reported
Contact EMail:	Not reported
Site Contact City,St,Zip:	UNKNOWN
2nd Contact:	Not reported
2nd Contact EMail:	Not reported
2nd Contact Address:	Not reported
2nd Contact City,St,Zip:	UNKNOWN
2nd Contact Address 2:	Not reported
2nd Contact City 2:	Not reported
2nd Contact Phone Number:	Not reported
2nd Contact Fax Number:	Not reported
2nd Contact Type:	Not reported
Facility City Num:	43
Site Contact:	Not reported
Site Contact Address:	Not reported
Site Contact Add 2:	Not reported
Site Contact City 2:	Not reported
Site Contact Phone:	Not reported
Site Contact Fax:	Not reported
Site Contact Type:	Not reported
Department Contact 1:	Not reported
Department Contact 2:	Not reported
Referral Source:	Not reported
Offsite Source:	False
Date Referred:	Not reported
Emergency:	False
Private Heating Fuel:	True
Commercial Heating Fuel:	False
Commercial HF < 2100 Gal.:	False
Commercial HF > 2100 Gal.:	False
Commercial HF - Size Unk:	False
No LUST Site:	False
Cost Recvry Prgm Candidate:	False
OCSRD Complete:	False
Follow Up Flag:	False
Alternate Water Supply:	False

EAST HARTFORD HOUSING (Continued) **S100998220**

Relocation:	False
Responsible Party:	False
Responsible EMail:	Not reported
Resp Party Name:	Not reported
Resp Party Address:	Not reported
Resp Party City,St,Zip:	Not reported
Resp Party Town Number:	UNKNOWN
Resp Party Phone:	Not reported
Resp Party Fax:	Not reported
Resp Party Name 2:	Not reported
Resp Party Address 2:	Not reported
Resp Party Phone 2:	Not reported
Investigator Id:	14
Follow Update:	Not reported
Area Lextent:	Not reported
Annual Precipitation:	Not reported
Affected Population:	Not reported
Population Setting:	Not reported
Ground Water Direction:	Not reported
Ground Water Gradient:	Not reported
Hydro Basin:	Not reported
Drastic:	Not reported
Geo Setting:	Not reported
Ground Water Classification:	Not reported
Receptor:	Not reported
Ground Water Flow Direction:	Not reported
Ground Water Depth:	Not reported
Areas Of Concern:	Not reported
Free Product Inches:	Not reported
Fund Date:	Not reported
Fund Planned:	No
Fund Obligated:	No
Fund Outlayed:	No
Fund Judgment:	No
Fund Recovered:	No
Cellar Borings:	False
Install Micro Wells:	False
Ground Water Sample:	False
Soil Sample:	False
Soil Gas:	False
Site Inspect:	False
Soil Excavate:	False
Geo Probe:	False
Survey:	False
Potable Well Sample:	False
Sample MWS:	False
Ground Water Gauging:	False
Soil Venting:	False
Active:	False
NOV Action:	None
NOV Issued:	Not reported
NOV Due:	Not reported
NOV Received:	Not reported
NOV Closed:	Not reported
NOV Disc Date:	Not reported
NOV Issued Date:	Not reported
NOV Compliance Sched:	Not reported

EAST HARTFORD HOUSING (Continued) **S100998220**

NOV Admin Order:	Not reported
NOV Referred To Ag:	Not reported
Stop All NOV Actions:	False
Release Invest Rpt:	False
DEP App Letter 1:	False
Correct Action Plan:	False
DEP App Letter 2:	False
Rem Sys Install:	False
Rem Sys Install Date:	Not reported
Closure Date:	Not reported
Rem Sys Monitoring Rpt:	False
Qrtly Gwater Mon Rpts:	False
Closure Req Rpt:	False
DEP Closure Letter:	False
Referred To:	Not reported
No Wells:	Not reported
Lph Wells:	Not reported
User Stamp:	Not reported
Date Stamp:	Not reported
Correspondence:	Not reported
Environmental Impact:	Not reported
FollowUp:	Not reported
GW Comments:	Not reported
Location Desc:	Not reported
NOV Comments:	Not reported
Release Desc:	Not reported
Running Comments:	Should be Registered Facility
Work Performed:	Not reported

CPCS:

Name:	East Hartford Housing
Address:	COLUMBUS CIRCLE EXT.
City,State,Zip:	EAST HARTFORD, CT 06108
Site Type:	Not reported
Lust Status code:	4
Lust Status:	Lust Completed (DEP’s significant hazard definition)
PTP Form:	Not reported
Program:	LUST
Comments:	Should Be Registered Facility
Site Type Definition:	Leaking Underground Storage Tanks Completed
Invesigation Start:	Yes
Invesigation Start Date:	Not reported
Remediation Start:	Yes
Remediation Start Date:	Not reported
Remediation Completed:	Yes
ELUR:	Not reported
Date Data Updated:	08/31/1989

C14 **EAST HARTFORD NEW ENGLAND PETROLEUM (FORMER GULF S** **CT CPCS** **S130327871**
WNW **10 SCHOOL STREET (FORMERLY 672 BURNSIDE AVENUE)** **N/A**
1/8-1/4 **EAST HARTFORD, CT**
0.153 mi.
810 ft. **Site 2 of 10 in cluster C**

Relative: CPCS:
Lower

Name:	East Hartford New England Petroleum (Former Gulf Station)
Address:	10 SCHOOL STREET (FORMERLY 672 BURNSIDE AVENUE)
City,State,Zip:	EAST HARTFORD, CT
Site Type:	Not reported
Lust Status code:	Not reported
Lust Status:	Not reported
PTP Form:	Not reported
Program:	LUST
Comments:	Not reported
Site Type Definition:	Not reported
Invesigation Start:	Yes
Invesigation Start Date:	Not reported
Remediation Start:	Yes
Remediation Start Date:	Not reported
Remediation Completed:	Yes
ELUR:	Not reported
Date Data Updated:	08/18/1998

Actual:
50 ft.

C15 **EAST HARTFORD NEW ENGLAND PETROLEUM (FORMER GULF S** **UST FINDER RELEASE** **1028942569**
WNW **10 SCHOOL STREET (FORMERLY 672 BURNSIDE AVENUE)** **N/A**
1/8-1/4 **EAST HARTFORD, CT 61082**
0.153 mi.
810 ft. **Site 3 of 10 in cluster C**

Relative: UST FINDER RELEASE:
Lower

Object ID:	85373
Facility ID:	CT1180
Lust ID:	CT48682
Name:	EAST HARTFORD NEW ENGLAND PETROLEUM (FORMER GULF STATION)
Address:	10 SCHOOL STREET (FORMERLY 672 BURNSIDE AVENUE)
City,State,Zip:	EAST HARTFORD, CT 61082664
Address Match Type:	StreetAddress
Reported Date:	1998/08/18 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	2002
Domestic Wells within 1500ft:	0
Land Use:	Developed, Medium Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	1
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported

Actual:
50 ft.

EAST HARTFORD NEW ENGLAND PETROLEUM (FORMER GULF STATION) (Continued) **1028942569**

NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	Geocode
X Coord:	-72.6104099999999
Y Coord:	41.7793500000001
Latitude:	41.77935
Longitude:	-72.61041

C16 **EAST HARTFORD NEW ENGLAND PETROLEUM** **CT UST** **U002174432**
West **672 BURNSIDE AVE** **N/A**
1/8-1/4 **EAST HARTFORD, CT 06108**
0.162 mi.
853 ft. **Site 4 of 10 in cluster C**

Relative:
Lower

Actual:
52 ft.

UST:

Name:	EAST HARTFORD NEW ENGLAND PETROLEUM
Address:	672 BURNSIDE AVE
Address 2:	Not reported
City,State,Zip:	EAST HARTFORD 06108
Facility ID:	43-5522
Substance:	Gasoline
Last Use Date:	08/01/1998
Tank ID:	A1
Closure Status:	Tank was Removed From Ground
Compartment ID:	a
Tank Status:	Permanently Closed
Secondary Material:	Not reported
Tank Material:	Coated & Cathodically Protected Steel (sti-P3)
Capacity:	10000
Install Date:	04/01/1978
Overfill Installed:	Not reported
Pipe Material:	Bare Steel
Pipe Mode Description:	Cathodically Protected
Spill Installed:	Spill Bucket
Latitude:	41.779375
Longitude:	-72.610522
Tank Latitude:	41.779375
Tank Longitude:	-72.610522

Contact:

Facility ID:	43-5522
Owner Name:	MID-VALLEY OIL COMPANY, INC.
Owner Address:	PO BOX 4092
Owner Address 2:	Not reported
Owner Phone:	(845) 561-4000
Owner Phone Ext:	Not reported
Owner City/State/Zip:	NEW WINDSOR, NY 125530092
Affiliation Type:	Owner
Contact Name:	Tim Hall
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5522
Owner Name:	MID-VALLEY OIL COMPANY, INC.
Owner Address:	PO BOX 4092
Owner Address 2:	Not reported
Owner Phone:	Not reported

EAST HARTFORD NEW ENGLAND PETROLEUM (Continued) **U002174432**

Owner Phone Ext:	Not reported
Owner City/State/Zip:	NEW WINDSOR, NY 125530092
Affiliation Type:	Registrant
Contact Name:	Not reported
Contact Title:	Not reported
Contact Email:	Not reported

Name:	EAST HARTFORD NEW ENGLAND PETROLEUM
Address:	672 BURNSIDE AVE
Address 2:	Not reported
City,State,Zip:	EAST HARTFORD 06108
Facility ID:	43-5522
Substance:	Gasoline
Last Use Date:	08/01/1998
Tank ID:	B2
Closure Status:	Tank was Removed From Ground
Compartment ID:	a
Tank Status:	Permanently Closed
Secondary Material:	Not reported
Tank Material:	Coated & Cathodically Protected Steel (sti-P3)
Capacity:	10000
Install Date:	04/01/1978
Overfill Installed:	Not reported
Pipe Material:	Bare Steel
Pipe Mode Description:	Cathodically Protected
Spill Installed:	Spill Bucket
Latitude:	41.779375
Longitude:	-72.610522
Tank Latitude:	41.779375
Tank Longitude:	-72.610522

Contact:

Facility ID:	43-5522
Owner Name:	MID-VALLEY OIL COMPANY, INC.
Owner Address:	PO BOX 4092
Owner Address 2:	Not reported
Owner Phone:	(845) 561-4000
Owner Phone Ext:	Not reported
Owner City/State/Zip:	NEW WINDSOR, NY 125530092
Affiliation Type:	Owner
Contact Name:	Tim Hall
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5522
Owner Name:	MID-VALLEY OIL COMPANY, INC.
Owner Address:	PO BOX 4092
Owner Address 2:	Not reported
Owner Phone:	Not reported
Owner Phone Ext:	Not reported
Owner City/State/Zip:	NEW WINDSOR, NY 125530092
Affiliation Type:	Registrant
Contact Name:	Not reported
Contact Title:	Not reported
Contact Email:	Not reported

EAST HARTFORD NEW ENGLAND PETROLEUM (Continued) **U002174432**

Name:	EAST HARTFORD NEW ENGLAND PETROLEUM
Address:	672 BURNSIDE AVE
Address 2:	Not reported
City,State,Zip:	EAST HARTFORD 06108
Facility ID:	43-5522
Substance:	Gasoline
Last Use Date:	08/01/1998
Tank ID:	C3
Closure Status:	Tank was Removed From Ground
Compartment ID:	a
Tank Status:	Permanently Closed
Secondary Material:	Not reported
Tank Material:	Coated & Cathodically Protected Steel (sti-P3)
Capacity:	10000
Install Date:	04/01/1978
Overfill Installed:	Not reported
Pipe Material:	Bare Steel
Pipe Mode Description:	Cathodically Protected
Spill Installed:	Spill Bucket
Latitude:	41.779375
Longitude:	-72.610522
Tank Latitude:	41.779375
Tank Longitude:	-72.610522

Contact:

Facility ID:	43-5522
Owner Name:	MID-VALLEY OIL COMPANY, INC.
Owner Address:	PO BOX 4092
Owner Address 2:	Not reported
Owner Phone:	(845) 561-4000
Owner Phone Ext:	Not reported
Owner City/State/Zip:	NEW WINDSOR, NY 125530092
Affiliation Type:	Owner
Contact Name:	Tim Hall
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5522
Owner Name:	MID-VALLEY OIL COMPANY, INC.
Owner Address:	PO BOX 4092
Owner Address 2:	Not reported
Owner Phone:	Not reported
Owner Phone Ext:	Not reported
Owner City/State/Zip:	NEW WINDSOR, NY 125530092
Affiliation Type:	Registrant
Contact Name:	Not reported
Contact Title:	Not reported
Contact Email:	Not reported

Name:	EAST HARTFORD NEW ENGLAND PETROLEUM
Address:	672 BURNSIDE AVE
Address 2:	Not reported
City,State,Zip:	EAST HARTFORD 06108
Facility ID:	43-5522
Substance:	Gasoline
Last Use Date:	08/01/1998
Tank ID:	D4

EAST HARTFORD NEW ENGLAND PETROLEUM (Continued) **U002174432**

Closure Status:	Tank was Removed From Ground
Compartment ID:	a
Tank Status:	Permanently Closed
Secondary Material:	Not reported
Tank Material:	Coated & Cathodically Protected Steel (sti-P3)
Capacity:	10000
Install Date:	04/01/1978
Overfill Installed:	Not reported
Pipe Material:	Bare Steel
Pipe Mode Description:	Cathodically Protected
Spill Installed:	Spill Bucket
Latitude:	41.779375
Longitude:	-72.610522
Tank Latitude:	41.779375
Tank Longitude:	-72.610522

Contact:

Facility ID:	43-5522
Owner Name:	MID-VALLEY OIL COMPANY, INC.
Owner Address:	PO BOX 4092
Owner Address 2:	Not reported
Owner Phone:	(845) 561-4000
Owner Phone Ext:	Not reported
Owner City/State/Zip:	NEW WINDSOR, NY 125530092
Affiliation Type:	Owner
Contact Name:	Tim Hall
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5522
Owner Name:	MID-VALLEY OIL COMPANY, INC.
Owner Address:	PO BOX 4092
Owner Address 2:	Not reported
Owner Phone:	Not reported
Owner Phone Ext:	Not reported
Owner City/State/Zip:	NEW WINDSOR, NY 125530092
Affiliation Type:	Registrant
Contact Name:	Not reported
Contact Title:	Not reported
Contact Email:	Not reported

C17 **CT LUST** **S105441384**
West **672 BURNSIDE AVENUE (10 SCHOOL STREET)** **CT SPILLS** **N/A**
1/8-1/4 **EAST HARTFORD, CT**
0.162 mi.
853 ft. **Site 5 of 10 in cluster C**

Relative:
Lower

Actual:
52 ft.

LUST:

Name:	Not reported
Name 2:	Not reported
Address:	672 BURNSIDE AVENUE (10 SCHOOL STREET)
Address 2:	Not reported
City,State,Zip:	EAST HARTFORD, CT
LUST Case Id:	48682
Release Date:	08/18/1998
Site Case ID:	43-5522
Substance:	Gasoline

(Continued) **S105441384**

Release Source:	Dispenser
Release Cause:	Unknown
Release Identified:	Removal/Closure
Case Number:	1998-05536
Release Quantity:	Unknown
Facility City Number:	Not reported

Detail As of 06/2020:

Name:	EAST HARTFORD NEW ENGLAND PETROLEUM (FORMER GULF STATION)
Name 2:	Not reported
Address:	10 SCHOOL STREET (FORMERLY 672 BURNSIDE AVENUE)
City,State,Zip:	EAST HARTFORD, CT 061082664
Address 2:	Not reported
LUST Id:	0
UST Facility Id:	5522
LUST Case Id:	48682
Lust Status:	Lust Completed
Processing Status:	Not reported
EPA Reportable:	True
Motor Fuel:	True
Diesel:	False
Gasoline:	False
Other:	False
Other Release:	Not reported
No Release:	False
Leak:	False
Tank:	False
Piping:	False
Overfill:	False
Removal:	False
Incident Date:	08/18/1998
Entry Date:	10/17/2006
Site Case Id:	9805536
UST Site Id:	1180
Cost Recovery Spill Case #:	0
Old SITS Number:	0
Case Log Id:	0
Monthly Report Id:	0
UST Owner Id:	1010
LUST Owner Id:	PCC
UST Event Id:	0
Contact Info:	Not reported
Contact EMail:	Not reported
Site Contact City,St,Zip:	UNKNOWN
2nd Contact:	Robert Goode Jr. (Leggette, Brashears & Graham, Inc)
2nd Contact EMail:	Not reported
2nd Contact Address:	4 Research Drive
2nd Contact City,St,Zip:	126, CT 06484
2nd Contact Address 2:	Suite 301
2nd Contact City 2:	Shelton
2nd Contact Phone Number:	2039298555
2nd Contact Fax Number:	2039269140
2nd Contact Type:	LEP
Facility City Num:	43
Site Contact:	Not reported
Site Contact Address:	Not reported
Site Contact Add 2:	Not reported
Site Contact City 2:	Not reported

(Continued) **S105441384**

Site Contact Phone:	Not reported
Site Contact Fax:	Not reported
Site Contact Type:	Not reported
Department Contact 1:	Not reported
Department Contact 2:	Not reported
Referral Source:	Not reported
Offsite Source:	False
Date Referred:	Not reported
Emergency:	False
Private Heating Fuel:	False
Commercial Heating Fuel:	False
Commercial HF < 2100 Gal.:	False
Commercial HF > 2100 Gal.:	False
Commercial HF - Size Unk:	False
No LUST Site:	False
Cost Recvry Prgm Candidate:	False
OCSRD Complete:	False
Follow Up Flag:	False
Alternate Water Supply:	False
Relocation:	False
Responsible Party:	False
Responsible EMail:	Not reported
Resp Party Name:	Mid Valley Oil Company
Resp Party Address:	P. O. Box 4092
Resp Party City,St,Zip:	New Windsor, NY 125530092
Resp Party Town Number:	Not reported
Resp Party Phone:	8455614000
Resp Party Fax:	Not reported
Resp Party Name 2:	Tim Hall
Resp Party Address 2:	Not reported
Resp Party Phone 2:	Not reported
Investigator Id:	0
Follow Update:	Not reported
Area Lextent:	Not reported
Annual Precipitation:	Not reported
Affected Population:	Not reported
Population Setting:	Not reported
Ground Water Direction:	Not reported
Ground Water Gradient:	0.003
Hydro Basin:	Not reported
Drastic:	Not reported
Geo Setting:	Not reported
Ground Water Classification:	GB
Receptor:	Semi-annual
Ground Water Flow Direction:	south southwest
Ground Water Depth:	9.64
Areas Of Concern:	Not reported
Free Product Inches:	0
Fund Date:	Not reported
Fund Planned:	No
Fund Obligated:	No
Fund Outlayed:	No
Fund Judgment:	No
Fund Recovered:	No
Cellar Borings:	False
Install Micro Wells:	False
Ground Water Sample:	False

(Continued) **S105441384**

Soil Sample:	False
Soil Gas:	False
Site Inspect:	False
Soil Excavate:	True
Geo Probe:	False
Survey:	False
Potable Well Sample:	False
Sample MWS:	False
Ground Water Gauging:	False
Soil Venting:	False
Active:	True
NOV Action:	None
NOV Issued:	Not reported
NOV Due:	Not reported
NOV Received:	Not reported
NOV Closed:	Not reported
NOV Disc Date:	Not reported
NOV Issued Date:	Not reported
NOV Compliance Sched:	Not reported
NOV Admin Order:	Not reported
NOV Referred To Ag:	Not reported
Stop All NOV Actions:	False
Release Invest Rpt:	False
DEP App Letter 1:	False
Correct Action Plan:	False
DEP App Letter 2:	False
Rem Sys Install:	False
Rem Sys Install Date:	Not reported
Closure Date:	Not reported
Rem Sys Monitoring Rpt:	False
Qrtly Gwater Mon Rpts:	False
Closure Req Rpt:	False
DEP Closure Letter:	False
Referred To:	Not reported
No Wells:	5
Lph Wells:	0
User Stamp:	forresta/forresta
Date Stamp:	04/28/2015
Correspondence:	Not reported
Environmental Impact:	Not reported
FollowUp:	Not reported
GW Comments:	Hockanum River located 1000 feet south
Location Desc:	Site consists of a retail pharmaceutical store and parking areas.
NOV Comments:	Not reported
Release Desc:	In August 1998 LBG supervised the removal of the UST system from the site. Petroleum impacted soils were noted in the area of the dispenser line excavation and to a lesser degree to the south of the former USTs. Approx. 15 cubic yards of contaminated soil removed. Several test pits dug adjacent to UST systems. Observations made during the test pits indicated that areas beyond the USTs had been impacted. Lab analysis showed that SVOCs, TPH and leachable lead were present at concentrations above the DEP RSR Criteria.In 1998 LBG supervised a remedial excavation to removed petroleum impacted from above the water table along the NW portion of the former dispenser island and adjacent test pits to further determine the extend of impact. Approx. 70 tons contaminated soil removed. The lab results for soil samples collected identified additional areas with

(Continued) **S105441384**

concentrations of SVOCs and TPH above the DEP RSR Criteria. Two subsurface investigations were later completed in Sept. 1999 and Dec. 2000 and included the collection of soil samples and installation of GWMWs. The lab results from soil samples collected during these investigations confirmed the impacts outlined above. During the period from 1999-2004 LBG completed a quarterly GW monitoring program to assess potential GW impacts from the release. The lab results for the GW samples indicated that the GW quality met the RSR criteria however, and increasing trend in VOC and TPH was observed in MW4 located hydraulically down gradient from the former dispenser island. The data suggested that a residual source for these constituents was likely present in the soils upgradient of this MW.In January 2005 LBG completed a remedial investigation to determine the extent of the previous identified petroleum impacted soils. The results of the investigation identified two isolated areas where concentrations of TPH exceeded the DEPRDEC, I/CDEC, GB PMC or a combination of the three. Due to the results of the remedial investigation and the planned development of the parcel, in May 2005 NEP initiated a remedial excavation to remove petroleum impacted soils. Approx. 600 tons of contam. Soil removed from the two excavations. The lab results for post-excavation samples indicated that residual concentrations of 1,2-dichloroebenzene and ETPH remained in the sidewall adjacent to the roadway. Continued excavation in this area was not possible due to the potential for a collapse of a nearby sidewalk. In general the results of the post-excavation samples indicated that the remedial excavation was successful in removing a source for continued GW impact.In May 2006 the remedial excavations were completed related to previous UST systems. The remedial excavations resulted in the removal of Approx. 600 tons of contaminated soil.

Running Comments: Spills Files, UST Enforcement Files, Cleanup Fund Files, and LUST Files

Work Performed: 1950: Four 10,000-gallon gasoline USTs were installed on site.1978: Four 10,000-gallon gasoline USTs, installed in 1950, were removed from site.1998: Four 10,000-gallon gasoline UST s and associated pipes were removed from site. ~70 tons of impacted soils were removed.1999: In September, a subsurface investigation was conducted.2000: In December, a subsurface investigation was conducted.2005: In January, a subsurface investigation was conducted. ~600 tons of impacted soils were removed from site in response to the subsurface investigations.2010: The GW monitoring event in April showed that AVOCs, SVOCs, and dissolved lead have never exceeded the SWPC and Res VC established in 1996. ETPH exceeds the GWPC, but site is GB.

SPILLS:

Name:	Not reported
Address:	672 BURNSIDE AVENUE -GULF
City,State,Zip:	EAST HARTFORD, CT
Year of Database:	1998
Case Number:	9805536
Who Took Spill:	931
Assigned To:	No Response
Report Date:	08/18/1998
Report Time:	11:00:00 AM
Date Release:	08/18/1998

(Continued) **S105441384**

Release Time:	11:00:00 AM
Reported By:	ROBERT GOOD
Phone:	203 4523100
Qty:	0.00 (Gallons)
Telephone:	617 8899000
Representing:	L.B.G.
Facility Status:	closed
Continuous Spill:	False
Release Substance:	GASOLINE
Emergency Measure:	SOIL CONTAMINATION UNDER UMP ISLAND 216 PPM ON PID REPLACING DISPENSORS AND PUMPS ONE OF WHICH MAY HAVE LEAKED
Discharger:	GULF OIL (OR MAY LEASE) ANDY BELAND
Waterbody Affected:	Not reported
Responsible Party:	Not reported
Responsible Party Address:	Not reported
RP City,St,Zip:	CT
Terminated:	YES
Recovered Total:	0
Total Water:	0
Historic:	False
Waterbody:	Not reported
User Stamp:	Not reported
Stamp Time:	1998-08-19 13:18:22
SR Inspector:	Coss, Brian
AT Inspector:	**NO RESPONSE
Corrective Action Taken:	Not reported
Cause Info:	Transfer Line Failure, and Pump Failure
Media Info:	Ground Surface
Release Type:	petroleum
Incident Description:	Not reported
Cost Recovery Case?:	Not reported
DEMHS Region:	Not reported
Lat/Long:	Not reported
Company Name:	Not reported
Last Updated:	Not reported

Cause:

Cause ID:	Transfer Line Failure
Other Cause:	Not reported
Cause ID:	Pump Failure
Other Cause:	Not reported

Media:

Media ID:	Ground Surface
Other Media:	Not reported

Release Type:

Release Type:	petroleum
Other Release:	Not reported

C18
West
1/8-1/4
0.162 mi.
853 ft.

GIBBS OIL
672 BURNSIDE AVE E
HARTFORD, CT 06101

Site 6 of 10 in cluster C

CT MANIFEST **S109722123**
N/A

Relative:
Lower

Actual:
52 ft.

CT MANIFEST:

Name:	GIBBS OIL
Address:	672 BURNSIDE AVE E
City,State,Zip:	HARTFORD, CT 06101
Phone:	Not reported
Country:	Not reported
Manifest ID:	MAJ647745
EPA ID:	CT8602827701

Hazardous Waste Manifest:

Year:	1998
Manifest:	MAJ647745
EPA ID:	CT8602827701
Generator Mailing Address:	672 BURNSIDE AVE E
Generator City,State,Zip:	HARTFORD, CT 06101
Discrepancies:	N
Date Shipped:	1998-08-19
Date Received:	1998-08-20
Transporter 2 Date:	Not reported
TSDF EPA ID:	MAD052924495
TSDF Name:	ZECCO INC
TSDF Address:	345 WEST MAIN ST
TSDF City,State,Zip:	NORTHOROUGH, MA 01532
TSDF Country:	USA
Transporter EPA ID:	MAD052924495
Transporter Name:	ZECCO INC
Transporter Address:	Not reported
Transporter City,State,Zip:	CT
Transporter Country:	USA
Transporter 2 EPA ID:	Not reported
Transporter 2 Name:	Not reported
Transporter 2 Address:	Not reported
Transporter 2 City,State,Zip:	CT
Transporter 2 Country:	USA
US DOT Description:	FLAMMABLE LIQUID N.O.S.
Number of Containers:	001
Container Type:	TT
Quantity/Weight/Volume:	203/G
Batch Number:	2032
EPA Waste Codes:	D001 - IGNITABLE WASTE
Copies:	2
Alternate Facility Name:	Not reported
Alternate Facility Address:	Not reported
Alternate Facility State:	Not reported
Alternate Facility Date:	Not reported

Year:	1998
Manifest:	MAJ647729
EPA ID:	CT8602827701
Generator Mailing Address:	672 BURNSIDE AVE E
Generator City,State,Zip:	HARTFORD, CT 06101
Discrepancies:	N
Date Shipped:	1998-08-18

GIBBS OIL (Continued) **S109722123**

Date Received:	1998-08-20
Transporter 2 Date:	Not reported
TSDF EPA ID:	MAD052924495
TSDF Name:	ZECCO INC
TSDF Address:	345 WEST MAIN ST
TSDF City,State,Zip:	NORTHOROUGH, MA 01532
TSDF Country:	USA
Transporter EPA ID:	MAD052924495
Transporter Name:	ZECCO INC
Transporter Address:	Not reported
Transporter City,State,Zip:	CT
Transporter Country:	USA
Transporter 2 EPA ID:	Not reported
Transporter 2 Name:	Not reported
Transporter 2 Address:	Not reported
Transporter 2 City,State,Zip:	CT
Transporter 2 Country:	USA
US DOT Description:	FLAMMABLE LIQUID N.O.S.
Number of Containers:	001
Container Type:	TT
Quantity/Weight/Volume:	115/G
Batch Number:	2032
EPA Waste Codes:	D001 - IGNITABLE WASTE
Copies:	2
Alternate Facility Name:	Not reported
Alternate Facility Address:	Not reported
Alternate Facility State:	Not reported
Alternate Facility Date:	Not reported

C19 **CHARLOTTE COHEN** **CT LUST** **S127579911**
West **665 BURNSIDE** **N/A**
1/8-1/4 **EAST HARTFORD, CT 06108**
0.176 mi.
927 ft. **Site 7 of 10 in cluster C**

Relative: LUST:
Lower

Actual: Name:	CHARLOTTE COHEN
51 ft. Name 2:	Not reported
Address:	665 BURNSIDE
Address 2:	Not reported
City,State,Zip:	EAST HARTFORD, CT 06108
LUST Case Id:	29305
Release Date:	Not reported
Site Case ID:	Not reported
Substance:	Not reported
Release Source:	Not reported
Release Cause:	Not reported
Release Identified:	Not reported
Case Number:	Not reported
Release Quantity:	Not reported
Facility City Number:	43

C20 **CHARLOTTE COHEN** **CT CPCS** **S102414624**
West **665 BURNSIDE** **N/A**
1/8-1/4 **EAST HARTFORD, CT 06108**
0.176 mi.
927 ft. **Site 8 of 10 in cluster C**

Relative: CPCS:
Lower

Name:	Charlotte Cohen
Address:	665 BURNSIDE
City,State,Zip:	EAST HARTFORD, CT 06108
Site Type:	Not reported
Lust Status code:	1
Lust Status:	Pending
PTP Form:	Not reported
Program:	LUST
Comments:	Not reported
Site Type Definition:	Leaking Underground Storage Tanks Pending
Invesigation Start:	No
Invesigation Start Date:	Not reported
Remediation Start:	No
Remediation Start Date:	Not reported
Remediation Completed:	No
ELUR:	Not reported
Date Data Updated:	10/09/1996

Actual:
51 ft.

C21 **COHEN** **CT LUST** **S127580054**
West **665 BURNSIDE AVENUE** **N/A**
1/8-1/4 **EAST HARTFORD, CT 06108**
0.176 mi.
927 ft. **Site 9 of 10 in cluster C**

Relative: LUST:
Lower

Name:	COHEN
Name 2:	Not reported
Address:	665 BURNSIDE AVENUE
Address 2:	Not reported
City,State,Zip:	EAST HARTFORD, CT 06108
LUST Case Id:	31975
Release Date:	Not reported
Site Case ID:	9605549
Substance:	Not reported
Release Source:	Not reported
Release Cause:	Not reported
Release Identified:	Not reported
Case Number:	Not reported
Release Quantity:	Not reported
Facility City Number:	43

Actual:
51 ft.

C22 **COHEN** **CT SPILLS** **S103156431**
West **665 BURNSIDE AVENUE** **CT CPCS** **N/A**
1/8-1/4 **EAST HARTFORD, CT 06108**
0.176 mi.
927 ft. **Site 10 of 10 in cluster C**

Relative: SPILLS:
Lower

Name:	Not reported
Address:	665 BURNSIDE AVENUE
City,State,Zip:	EAST HARTFORD, CT

Actual:
51 ft.

COHEN (Continued) **S103156431**

Year of Database:	1996
Case Number:	9605549
Who Took Spill:	922
Assigned To:	Williamson, Matt
Report Date:	10/24/1996
Report Time:	08:30:00 AM
Date Release:	10/24/1996
Release Time:	08:30:00 AM
Reported By:	HARRY PLAUT
Phone:	860 8328415
Qty:	10.00 (Gallons)
Telephone:	Not reported
Representing:	H.S. PLAUT CEMETARY CO.
Facility Status:	Closed
Continuous Spill:	False
Release Substance:	#2 FUEL OIL
Emergency Measure:	REMOVAL OF 1 K TANK AND CONTAMINATED SOIL
Discharger:	COHEN
Waterbody Affected:	Groundwater
Responsible Party:	true
Responsible Party Address:	665 BURNSIDE AVENUE
RP City,St,Zip:	EAST HARTFORD, CT 06108
Terminated:	YES
Recovered Total:	0
Total Water:	0
Historic:	False
Waterbody:	Not reported
User Stamp:	Not reported
Stamp Time:	1997-04-28 12:00:42
SR Inspector:	Aceto, John
AT Inspector:	Williamson, Matt
Corrective Action Taken:	Pumped Out, and Removed Tank, and Soil Removed
Cause Info:	Inground Tank Failure
Media Info:	Ground Water
Release Type:	petroleum
Incident Description:	Not reported
Cost Recovery Case?:	Not reported
DEMHS Region:	Not reported
Lat/Long:	Not reported
Company Name:	Not reported
Last Updated:	Not reported

Action:

Action:	Pumped Out
Other Action:	Not reported
Action:	Removed Tank
Other Action:	Not reported
Action:	Soil Removed
Other Action:	Not reported

Agency:

Agency ID:	Local Fire Marshal
Other Agency:	Not reported
DEP Bureau:	Not reported
DEP Agency:	Not reported

COHEN (Continued) **S103156431**

Agency ID: DEP
Other Agency: Not reported
DEP Bureau: BUREAU OF WASTE MANAGEMENT
DEP Agency: OIL AND CHEMICAL SPILL RESPONSE

Cause:
Cause ID: Inground Tank Failure
Other Cause: Not reported

Media:
Media ID: Ground Water
Other Media: Not reported

Release Class:
Class ID: Commercial
Other Class: Not reported

Release Type:
Release Type: petroleum
Other Release: Not reported

Waterbody:
Waterbody: Groundwater
Other Waterbody: Not reported

CPCS:
Name: Cohen
Address: 665 BURNSIDE AVENUE
City,State,Zip: EAST HARTFORD, CT 06108
Site Type: Not reported
Lust Status code: 4
Lust Status: Lust Completed (DEP’s significant hazard definition)
PTP Form: Not reported
Program: LUST
Comments: Bureau Of Waste Management, Oil And Chemical Spill Response,
Site Type Definition: Leaking Underground Storage Tanks Completed
Invesigation Start: Yes
Invesigation Start Date: Not reported
Remediation Start: Yes
Remediation Start Date: Not reported
Remediation Completed: Yes
ELUR: Not reported
Date Data Updated: 10/25/1996

23
NW
1/8-1/4
0.199 mi.
1049 ft.

DERRICK WEIR
64 HANMER ST
EAST HARTFORD, CT 06108

RCRA-VSQG

1031783425
CTP000035503

Relative:
Lower

Actual:
56 ft.

RCRA Listings:

Date Form Received by Agency:		20250306
Handler Name:		Derrick Weir
Handler Address:		Hanmer St
Handler City,State,Zip:		EAST HARTFORD, CT 06108
EPA ID:		CTP000035503
Contact Name:		Not reported
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		JMEYERHANS@E-S-I.COM
Contact Title:		Not reported
EPA Region:		01
Land Type:		Not reported
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		Not reported
Mailing City,State,Zip:		Not reported
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		Yes
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No

DERRICK WEIR (Continued) **1031783425**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20250306
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	Lead

Historic Generators:

Receive Date:	20250306
Handler Name: DERRICK WEIR	
Federal Waste Generator Description:	Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

D24 **WICKHAM MEMORIAL LIBRARY** **CT UST** **U002031055**
West **656 BURNSIDE AVE** **N/A**
1/8-1/4 **EAST HARTFORD, CT 06108**
0.201 mi.
1060 ft. **Site 1 of 5 in cluster D**

Relative:
Lower

Actual:
48 ft.

UST:

Name:	WICKHAM MEMORIAL LIBRARY
Address:	656 BURNSIDE AVE
Address 2:	Not reported
City,State,Zip:	EAST HARTFORD 06108
Facility ID:	43-9896
Substance:	Heating Oil(on-site consumption)
Last Use Date:	05/01/1989
Tank ID:	A-1
Closure Status:	Tank was Removed From Ground
Compartment ID:	a
Tank Status:	Permanently Closed
Secondary Material:	Not reported
Tank Material:	Asphalt Coated or Bare Steel
Capacity:	1500
Install Date:	01/01/1950
Overfill Installed:	Not reported
Pipe Material:	Bare Steel
Pipe Mode Description:	Not reported
Spill Installed:	Not reported
Latitude:	41.779262
Longitude:	-72.61128
Tank Latitude:	41.779262
Tank Longitude:	-72.61128

Contact:

Facility ID:	43-9896
Owner Name:	TOWN OF EAST HARTFORD
Owner Address:	740 MAIN ST
Owner Address 2:	Not reported
Owner Phone:	860-291-7100
Owner Phone Ext:	Not reported
Owner City/State/Zip:	EAST HARTFORD, CT 061083140
Affiliation Type:	Owner
Contact Name:	Not reported
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-9896
Owner Name:	TOWN OF EAST HARTFORD
Owner Address:	740 MAIN ST
Owner Address 2:	Not reported
Owner Phone:	Not reported
Owner Phone Ext:	Not reported
Owner City/State/Zip:	EAST HARTFORD, CT 061083140
Affiliation Type:	Registrant
Contact Name:	Not reported
Contact Title:	Not reported
Contact Email:	Not reported

D25 **CHUCKS AUTOMOTIVE LLC** **CT UST** **U002174425**
West **653 BURNSIDE AVE** **N/A**
1/8-1/4 **EAST HARTFORD, CT 06108**
0.205 mi.
1085 ft. **Site 2 of 5 in cluster D**

Relative:
Lower

Actual:
52 ft.

UST:

Name:	CHUCKS AUTOMOTIVE LLC
Address:	653 BURNSIDE AVE
Address 2:	Not reported
City,State,Zip:	EAST HARTFORD 06108
Facility ID:	43-5508
Substance:	Gasoline
Last Use Date:	04/15/2009
Tank ID:	A1R1
Closure Status:	Tank was Removed From Ground
Compartment ID:	a
Tank Status:	Permanently Closed
Secondary Material:	Not reported
Tank Material:	Coated & Cathodically Protected Steel (sti-P3)
Capacity:	8000
Install Date:	08/01/1988
Overfill Installed:	Not reported
Pipe Material:	Bare Steel
Pipe Mode Description:	Cathodically Protected
Spill Installed:	Not reported
Latitude:	41.779012
Longitude:	-72.611473
Tank Latitude:	41.77892
Tank Longitude:	-72.61139

Contact:

Facility ID:	43-5508
Owner Name:	Branden Naraine
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Class B Operator
Contact Name:	.
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5508
Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Billing Contact
Contact Name:	Branden Naraine
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5508
Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Owner
Contact Name: Branden Naraine
Contact Title: Not reported
Contact Email: Not reported

Facility ID: 43-5508
Owner Name: CB AUTOMOTIVE, LLC
Owner Address: 653 Burnside Ave
Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Registrant
Contact Name: Branden Naraine
Contact Title: Not reported
Contact Email: Not reported

Facility ID: 43-5508
Owner Name: CB AUTOMOTIVE, LLC
Owner Address: 653 Burnside Ave
Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Operator
Contact Name: Branden Naraine
Contact Title: Not reported
Contact Email: Not reported

Facility ID: 43-5508
Owner Name: CB AUTOMOTIVE, LLC
Owner Address: 653 Burnside Ave
Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Primary Contact
Contact Name: Branden Naraine
Contact Title: Not reported
Contact Email: Not reported

Facility ID: 43-5508
Owner Name: CB AUTOMOTIVE, LLC
Owner Address: 653 Burnside Ave
Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Property Owner
Contact Name: Branden Naraine
Contact Title: Not reported
Contact Email: Not reported

Facility ID: 43-5508

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Owner Name: Branden Naraine
Owner Address: 653 Burnside Ave
Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Class A Operator
Contact Name: .
Contact Title: Not reported
Contact Email: Not reported

compilance:
Inspection Date: 04/18/2023
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true
Include in Red Tag: false
Field NOV ID: NOVUST-MC223-0056
Warning Letter ID: WLUST-MC223-0023
Violation Name: Failure to submitt an annual notification and/or annual fee
Violation Desc: The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).
AgencyTankId: Not reported
Compliance Date: 04/18/2023
Compliance Method: Warning Only
Compliance Notes: Not reported

Inspection Date: 05/31/2017
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true
Include in Red Tag: true
Field NOV ID: NOVUST-MC217-0025
Warning Letter ID: Not reported
Violation Name: Sensor Installed at Tank Sump
Violation Desc: The division inspector has determined that a piping sump sensor was not installed at the tank sump.
AgencyTankId: E6R1
Compliance Date: 06/20/2017
Compliance Method: Test Results
Compliance Notes: Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form

Inspection Date: 06/02/2014
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test Records
Violation Desc:	The passing annual line leak detector test documentation was not maintained.
AgencyTankId:	D5R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Sump Free of Liquid
Violation Desc:	The DepartmentG s inspector has determined that there is liquid or evidence of liquid accumulating in sump.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test Records
Violation Desc:	The passing annual line leak detector test documentation was not maintained.
AgencyTankId:	E6R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Failure to perform monthly visual inspections
Violation Desc:	The owner or operator has failed to perform, or has performed

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

	inadequately, the requisite monthly visual inspections at their UST facility or facilities.
AgencyTankId:	Not reported
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Operator retraining due to non-comliance
Violation Desc:	Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program.
AgencyTankId:	Not reported
Compliance Date:	06/20/2017
Compliance Method:	Documentation
Compliance Notes:	fax recd 6/20/17 included monthly inspection report (6/17 still needs sumps sensors) retraining certificates Gregory Tischofer A/B 6/4/17 API, Charles Tischofer Class C 6/4/17 API
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test
Violation Desc:	The passing annual line leak detector test had not been performed.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping
Violation Desc:	Annual Tightness Test for Pressurized Piping was not performed.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test
Violation Desc:	The passing annual line leak detector test had not been performed.
AgencyTankId:	E6R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Monthly Records
Violation Desc:	Monthly records of interstitial monitoring records were not available.
AgencyTankId:	E6R1
Compliance Date:	06/20/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met for tanks, interstice is being monitored but still need sensors installed for piping before close this violation Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form

Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Spill Prevention Device Not Functional
Violation Desc:	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.
AgencyTankId:	D5R1
Compliance Date:	10/02/2014

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Compliance Method:	Documentation
Compliance Notes:	Site pumped out and cleaned sumps. Multiple photos taken, see email
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Sensor Installed at Tank Sump
Violation Desc:	The division inspector has determined that a piping sump sensor was not installed at the tank sump.
AgencyTankId:	D5R1
Compliance Date:	06/20/2017
Compliance Method:	Test Results
Compliance Notes:	Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping Records
Violation Desc:	The annual tightness test documentation was not available for the piping.
AgencyTankId:	D5R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Updated UST notification information required
Violation Desc:	The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

AgencyTankId:	Not reported
Compliance Date:	05/03/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/3/23 Received updated ezFile notifcation with active insurance & AB operators
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing hydrostatic testing for regular, super & diesel tanks & dispenser sumps dated 4/21/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Release Detection Documentation Available
Violation Desc:	The release detection documentation was not available.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing ATG functionality testing, dated 3/13/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Release Detection Documentation Available
Violation Desc:	The release detection documentation was not available.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing ATG functionality testing, dated 3/13/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failure to Test Repaired Spill Prevention Equipment
Violation Desc:	Failed to test repaired spill prevention equipment (e.g., spill bucket) within 30 days of the repair in accordance with manufacturer specifications or a nationally recognized code of practice.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel tanks dated 4/21/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failed to Maintain Records of Tests for Secondary Containment
Violation Desc:	Owner or Operator failed to maintain records of testing results required to demonstrate compliance with secondary containment systems.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic testing for regular, super & diesel sumps dated 4/21/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Spill Bucket Testing Schedule
Violation Desc:	Failed to conduct requisite testing of spill buckets according to initial and 3-year schedule.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel spill buckets dated 4/21/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Spill Bucket Testing Schedule
Violation Desc:	Failed to conduct requisite testing of spill buckets according to initial and 3-year schedule.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel spill buckets dated 4/21/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failed to Maintain Records of Tests for Secondary Containment
Violation Desc:	Owner or Operator failed to maintain records of testing results required to demonstrate compliance with secondary containment systems.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic testing for regular, super & diesel sumps dated 4/21/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failure to Test Repaired Spill Prevention Equipment
Violation Desc:	Failed to test repaired spill prevention equipment (e.g., spill bucket) within 30 days of the repair in accordance with manufacturer specifications or a nationally recognized code of practice.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel tanks dated 4/21/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	D5R1

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing hydrostatic testing for regular, super & diesel tanks & dispenser sumps dated 4/21/23
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping
Violation Desc:	Annual Tightness Test for Pressurized Piping was not performed.
AgencyTankId:	E6R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Primary Overfill Identified
Violation Desc:	The primary overfill device was not identified.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met- ball float Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Primary Overfill Identified
Violation Desc:	The primary overfill device was not identified.
AgencyTankId:	E6R1

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met- ball float
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping Records
Violation Desc:	The annual tightness test documentation was not available for the piping.
AgencyTankId:	E6R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14
Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Updated UST notification information required
Violation Desc:	The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.
AgencyTankId:	Not reported
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported
Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Current Owner
Violation Desc:	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.
AgencyTankId:	Not reported
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported
Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	E6R1
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported

Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Spill Prevention Device Not Functional
Violation Desc:	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.
AgencyTankId:	E6R1
Compliance Date:	10/02/2014
Compliance Method:	Documentation
Compliance Notes:	Site pumped out and cleaned sumps. Multiple photos taken, see email

Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	D5R1
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Monthly Records
Violation Desc:	Monthly records of interstitial monitoring records were not available.
AgencyTankId:	D5R1

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Compliance Date:	06/20/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met for tanks, interstice is being monitored but still need sensors installed for piping before close this violation Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Dispenser Sump Free of Liquid
Violation Desc:	The dispenser sump contains liquid.
AgencyTankId:	Not reported
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14

Name:	CHUCKS AUTOMOTIVE LLC
Address:	653 BURNSIDE AVE
Address 2:	Not reported
City,State,Zip:	EAST HARTFORD 06108
Facility ID:	43-5508
Substance:	Gasoline
Last Use Date:	04/15/2009
Tank ID:	B3R1
Closure Status:	Tank was Removed From Ground
Compartment ID:	a
Tank Status:	Permanently Closed
Secondary Material:	Not reported
Tank Material:	Coated & Cathodically Protected Steel (sti-P3)
Capacity:	8000
Install Date:	08/01/1988
Overfill Installed:	Not reported
Pipe Material:	Bare Steel
Pipe Mode Description:	Cathodically Protected
Spill Installed:	Not reported
Latitude:	41.779012
Longitude:	-72.611473
Tank Latitude:	41.77892
Tank Longitude:	-72.61139

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Contact:

Facility ID:	43-5508
Owner Name:	Branden Naraine
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Class B Operator
Contact Name:	.
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5508
Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Billing Contact
Contact Name:	Branden Naraine
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5508
Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Owner
Contact Name:	Branden Naraine
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5508
Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Registrant
Contact Name:	Branden Naraine
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5508
Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Operator

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Contact Name:	Branden Naraine
Contact Title:	Not reported
Contact Email:	Not reported
Facility ID:	43-5508
Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Primary Contact
Contact Name:	Branden Naraine
Contact Title:	Not reported
Contact Email:	Not reported
Facility ID:	43-5508
Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Property Owner
Contact Name:	Branden Naraine
Contact Title:	Not reported
Contact Email:	Not reported
Facility ID:	43-5508
Owner Name:	Branden Naraine
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Class A Operator
Contact Name:	.
Contact Title:	Not reported
Contact Email:	Not reported

compilance:

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failure to submitt an annual notification and/or annual fee
Violation Desc:	The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).
AgencyTankId:	Not reported
Compliance Date:	04/18/2023
Compliance Method:	Warning Only
Compliance Notes:	Not reported

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Sensor Installed at Tank Sump
Violation Desc:	The division inspector has determined that a piping sump sensor was not installed at the tank sump.
AgencyTankId:	E6R1
Compliance Date:	06/20/2017
Compliance Method:	Test Results
Compliance Notes:	Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form

Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test Records
Violation Desc:	The passing annual line leak detector test documentation was not maintained.
AgencyTankId:	D5R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Sump Free of Liquid
Violation Desc:	The DepartmentG s inspector has determined that there is liquid or evidence of liquid accumulating in sump.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test Records
Violation Desc:	The passing annual line leak detector test documentation was not maintained.
AgencyTankId:	E6R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Failure to perform monthly visual inspections
Violation Desc:	The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.
AgencyTankId:	Not reported
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Operator retraining due to non-comliance
Violation Desc:	Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program.
AgencyTankId:	Not reported
Compliance Date:	06/20/2017
Compliance Method:	Documentation
Compliance Notes:	fax recd 6/20/17 included monthly inspection report (6/17 still needs sumps sensors) retraining certificates Gregory Tischofer A/B 6/4/17 API, Charles Tischofer Class C 6/4/17 API
Inspection Date:	05/31/2017

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test
Violation Desc:	The passing annual line leak detector test had not been performed.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping
Violation Desc:	Annual Tightness Test for Pressurized Piping was not performed.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test
Violation Desc:	The passing annual line leak detector test had not been performed.
AgencyTankId:	E6R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Monthly Records
Violation Desc:	Monthly records of interstitial monitoring records were not available.
AgencyTankId:	E6R1
Compliance Date:	06/20/2017
Compliance Method:	Documentation

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met for tanks, interstice is being monitored but still need sensors installed for piping before close this violation Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Spill Prevention Device Not Functional
Violation Desc:	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.
AgencyTankId:	D5R1
Compliance Date:	10/02/2014
Compliance Method:	Documentation
Compliance Notes:	Site pumped out and cleaned sumps. Multiple photos taken, see email
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Sensor Installed at Tank Sump
Violation Desc:	The division inspector has determined that a piping sump sensor was not installed at the tank sump.
AgencyTankId:	D5R1
Compliance Date:	06/20/2017
Compliance Method:	Test Results
Compliance Notes:	Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping Records
Violation Desc:	The annual tightness test documentation was not available for the piping.
AgencyTankId:	D5R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Updated UST notification information required
Violation Desc:	The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.
AgencyTankId:	Not reported
Compliance Date:	05/03/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/3/23 Received updated ezFile notifcation with active insurance & AB operators

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing hydrostatic testing for regular, super & diesel tanks & dispenser sumps dated 4/21/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Release Detection Documentation Available
Violation Desc:	The release detection documentation was not available.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing ATG functionality testing, dated 3/13/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Release Detection Documentation Available
Violation Desc:	The release detection documentation was not available.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing ATG functionality testing, dated 3/13/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failure to Test Repaired Spill Prevention Equipment
Violation Desc:	Failed to test repaired spill prevention equipment (e.g., spill bucket) within 30 days of the repair in accordance with manufacturer specifications or a nationally recognized code of practice.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel tanks dated 4/21/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failed to Maintain Records of Tests for Secondary Containment
Violation Desc:	Owner or Operator failed to maintain records of testing results required to demonstrate compliance with secondary containment systems.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic testing for regular, super & diesel sumps dated 4/21/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Spill Bucket Testing Schedule
Violation Desc:	Failed to conduct requisite testing of spill buckets according to initial and 3-year schedule.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel spill buckets dated 4/21/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Spill Bucket Testing Schedule
Violation Desc:	Failed to conduct requisite testing of spill buckets according to initial and 3-year schedule.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel spill buckets dated 4/21/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failed to Maintain Records of Tests for Secondary Containment
Violation Desc:	Owner or Operator failed to maintain records of testing results required to demonstrate compliance with secondary containment systems.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic testing for regular, super & diesel sumps dated 4/21/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failure to Test Repaired Spill Prevention Equipment
Violation Desc:	Failed to test repaired spill prevention equipment (e.g., spill bucket) within 30 days of the repair in accordance with manufacturer specifications or a nationally recognized code of practice.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel tanks dated 4/21/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing hydrostatic testing for regular, super & diesel tanks & dispenser sumps dated 4/21/23

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping
Violation Desc:	Annual Tightness Test for Pressurized Piping was not performed.
AgencyTankId:	E6R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Primary Overfill Identified

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Violation Desc: The primary overfill device was not identified.
AgencyTankId: D5R1
Compliance Date: 06/02/2017
Compliance Method: Documentation
Compliance Notes: Red tag hearing 6/2/17 per PW this violation has been met- ball float Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form

Inspection Date: 05/31/2017
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true
Include in Red Tag: false
Field NOV ID: NOVUST-MC217-0025
Warning Letter ID: Not reported
Violation Name: Primary Overfill Identified
Violation Desc: The primary overfill device was not identified.
AgencyTankId: E6R1
Compliance Date: 06/02/2017
Compliance Method: Documentation
Compliance Notes: Red tag hearing 6/2/17 per PW this violation has been met- ball float

Inspection Date: 06/02/2014
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true
Include in Red Tag: false
Field NOV ID: NOVUST-MC214-0052
Warning Letter ID: Not reported
Violation Name: Annual Tightness Test for Pressurized Piping Records
Violation Desc: The annual tightness test documentation was not available for the piping.
AgencyTankId: E6R1
Compliance Date: 10/02/2014
Compliance Method: Test Results
Compliance Notes: Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14

Inspection Date: 03/11/2025
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true
Include in Red Tag: false
Field NOV ID: NOVUST-BS25-0019
Warning Letter ID: Not reported

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Violation Name:	Updated UST notification information required
Violation Desc:	The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.
AgencyTankId:	Not reported
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported
Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Current Owner
Violation Desc:	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.
AgencyTankId:	Not reported
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported
Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	E6R1
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Spill Prevention Device Not Functional
Violation Desc:	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.
AgencyTankId:	E6R1
Compliance Date:	10/02/2014
Compliance Method:	Documentation
Compliance Notes:	Site pumped out and cleaned sumps. Multiple photos taken, see email

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	D5R1
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Monthly Records
Violation Desc:	Monthly records of interstitial monitoring records were not available.
AgencyTankId:	D5R1
Compliance Date:	06/20/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met for tanks, interstice is being monitored but still need sensors installed for piping before close this violation Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form

Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Dispenser Sump Free of Liquid
Violation Desc:	The dispenser sump contains liquid.
AgencyTankId:	Not reported
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

three lines and all passed 6/10/14

Name:	CHUCKS AUTOMOTIVE LLC
Address:	653 BURNSIDE AVE
Address 2:	Not reported
City,State,Zip:	EAST HARTFORD 06108
Facility ID:	43-5508
Substance:	Diesel
Last Use Date:	04/15/2009
Tank ID:	C4R1
Closure Status:	Tank was Removed From Ground
Compartment ID:	a
Tank Status:	Permanently Closed
Secondary Material:	Not reported
Tank Material:	Coated & Cathodically Protected Steel (sti-P3)
Capacity:	8000
Install Date:	08/01/1988
Overfill Installed:	Not reported
Pipe Material:	Bare Steel
Pipe Mode Description:	Cathodically Protected
Spill Installed:	Not reported
Latitude:	41.779012
Longitude:	-72.611473
Tank Latitude:	41.77892
Tank Longitude:	-72.61139

Contact:

Facility ID:	43-5508
Owner Name:	Branden Naraine
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Class B Operator
Contact Name:	.
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5508
Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Billing Contact
Contact Name:	Branden Naraine
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5508
Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Owner
Contact Name:	Branden Naraine
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5508
Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Registrant
Contact Name:	Branden Naraine
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5508
Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Operator
Contact Name:	Branden Naraine
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5508
Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Primary Contact
Contact Name:	Branden Naraine
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5508
Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Property Owner
Contact Name:	Branden Naraine
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5508
Owner Name:	Branden Naraine
Owner Address:	653 Burnside Ave

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Class A Operator
Contact Name: .
Contact Title: Not reported
Contact Email: Not reported

compilance:
Inspection Date: 04/18/2023
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true
Include in Red Tag: false
Field NOV ID: NOVUST-MC223-0056
Warning Letter ID: WLUST-MC223-0023
Violation Name: Failure to submitt an annual notification and/or annual fee
Violation Desc: The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).
AgencyTankId: Not reported
Compliance Date: 04/18/2023
Compliance Method: Warning Only
Compliance Notes: Not reported

Inspection Date: 05/31/2017
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true
Include in Red Tag: true
Field NOV ID: NOVUST-MC217-0025
Warning Letter ID: Not reported
Violation Name: Sensor Installed at Tank Sump
Violation Desc: The division inspector has determined that a piping sump sensor was not installed at the tank sump.
AgencyTankId: E6R1
Compliance Date: 06/20/2017
Compliance Method: Test Results
Compliance Notes: Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form

Inspection Date: 06/02/2014
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test Records
Violation Desc:	The passing annual line leak detector test documentation was not maintained.
AgencyTankId:	D5R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Sump Free of Liquid
Violation Desc:	The DepartmentG s inspector has determined that there is liquid or evidence of liquid accumulating in sump.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test Records
Violation Desc:	The passing annual line leak detector test documentation was not maintained.
AgencyTankId:	E6R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Failure to perform monthly visual inspections
Violation Desc:	The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

AgencyTankId: Not reported
Compliance Date: 06/02/2017
Compliance Method: Documentation
Compliance Notes: Red tag hearing 6/2/17 per PW this violation has been met

Inspection Date: 05/31/2017
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true
Include in Red Tag: true
Field NOV ID: NOVUST-MC217-0025
Warning Letter ID: Not reported
Violation Name: Operator retraining due to non-comliance
Violation Desc: Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program.
AgencyTankId: Not reported
Compliance Date: 06/20/2017
Compliance Method: Documentation
Compliance Notes: fax recd 6/20/17 included monthly inspection report (6/17 still needs sumps sensors) retraining certificates Gregory Tischofer A/B 6/4/17 API, Charles Tischofer Class C 6/4/17 API

Inspection Date: 05/31/2017
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true
Include in Red Tag: false
Field NOV ID: NOVUST-MC217-0025
Warning Letter ID: Not reported
Violation Name: Annual LLD Test
Violation Desc: The passing annual line leak detector test had not been performed.
AgencyTankId: D5R1
Compliance Date: 06/02/2017
Compliance Method: Documentation
Compliance Notes: Red tag hearing 6/2/17 per PW this violation has been met

Inspection Date: 05/31/2017
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true
Include in Red Tag: false
Field NOV ID: NOVUST-MC217-0025
Warning Letter ID: Not reported
Violation Name: Annual Tightness Test for Pressurized Piping
Violation Desc: Annual Tightness Test for Pressurized Piping was not performed.
AgencyTankId: D5R1
Compliance Date: 06/02/2017
Compliance Method: Documentation
Compliance Notes: Red tag hearing 6/2/17 per PW this violation has been met

Inspection Date: 05/31/2017
UST Site ID Number: 43-5508

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test
Violation Desc:	The passing annual line leak detector test had not been performed.
AgencyTankId:	E6R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Monthly Records
Violation Desc:	Monthly records of interstitial monitoring records were not available.
AgencyTankId:	E6R1
Compliance Date:	06/20/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met for tanks, interstice is being monitored but still need sensors installed for piping before close this violation Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form

Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Spill Prevention Device Not Functional
Violation Desc:	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.
AgencyTankId:	D5R1
Compliance Date:	10/02/2014
Compliance Method:	Documentation
Compliance Notes:	Site pumped out and cleaned sumps. Multiple photos taken, see email

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Sensor Installed at Tank Sump
Violation Desc:	The division inspector has determined that a piping sump sensor was not installed at the tank sump.
AgencyTankId:	D5R1
Compliance Date:	06/20/2017
Compliance Method:	Test Results
Compliance Notes:	Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form

Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping Records
Violation Desc:	The annual tightness test documentation was not available for the piping.
AgencyTankId:	D5R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Updated UST notification information required
Violation Desc:	The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.
AgencyTankId:	Not reported
Compliance Date:	05/03/2023
Compliance Method:	Documentation

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Compliance Notes:	ER 5/3/23 Received updated ezFile notifcation with active insurance & AB operators
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing hydrostatic testing for regular, super & diesel tanks & dispenser sumps dated 4/21/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Release Detection Documentation Available
Violation Desc:	The release detection documentation was not available.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing ATG functionality testing, dated 3/13/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Release Detection Documentation Available
Violation Desc:	The release detection documentation was not available.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing ATG functionality testing, dated 3/13/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failure to Test Repaired Spill Prevention Equipment
Violation Desc:	Failed to test repaired spill prevention equipment (e.g., spill bucket) within 30 days of the repair in accordance with manufacturer specifications or a nationally recognized code of practice.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel tanks dated 4/21/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failed to Maintain Records of Tests for Secondary Containment
Violation Desc:	Owner or Operator failed to maintain records of testing results required to demonstrate compliance with secondary containment systems.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic testing for regular, super & diesel sumps dated 4/21/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Spill Bucket Testing Schedule
Violation Desc:	Failed to conduct requisite testing of spill buckets according to initial and 3-year schedule.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel spill buckets dated 4/21/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Spill Bucket Testing Schedule
Violation Desc:	Failed to conduct requisite testing of spill buckets according to

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

initial and 3-year schedule.
AgencyTankId: D5R1
Compliance Date: 05/04/2023
Compliance Method: Documentation
Compliance Notes: ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel spill buckets dated 4/21/23

Inspection Date: 04/18/2023
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true
Include in Red Tag: false
Field NOV ID: NOVUST-MC223-0056
Warning Letter ID: WLUST-MC223-0023
Violation Name: Failed to Maintain Records of Tests for Secondary Containment
Violation Desc: Owner or Operator failed to maintain records of testing results required to demonstrate compliance with secondary containment systems.
AgencyTankId: E6R1
Compliance Date: 05/04/2023
Compliance Method: Documentation
Compliance Notes: ER 5/4/23 Received passing hydrostatic testing for regular, super & diesel sumps dated 4/21/23

Inspection Date: 04/18/2023
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true
Include in Red Tag: false
Field NOV ID: NOVUST-MC223-0056
Warning Letter ID: WLUST-MC223-0023
Violation Name: Failure to Test Repaired Spill Prevention Equipment
Violation Desc: Failed to test repaired spill prevention equipment (e.g., spill bucket) within 30 days of the repair in accordance with manufacturer specifications or a nationally recognized code of practice.
AgencyTankId: E6R1
Compliance Date: 05/04/2023
Compliance Method: Documentation
Compliance Notes: ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel tanks dated 4/21/23

Inspection Date: 04/18/2023
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true
Include in Red Tag: false
Field NOV ID: NOVUST-MC223-0056
Warning Letter ID: WLUST-MC223-0023
Violation Name: Record Keeping for Spill Prevention Equipment
Violation Desc: Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId: D5R1
Compliance Date: 05/04/2023
Compliance Method: Documentation
Compliance Notes: ER 5/4/23 Received documentation of passing hydrostatic testing for

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

regular, super & diesel tanks & dispenser sumps dated 4/21/23

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping
Violation Desc:	Annual Tightness Test for Pressurized Piping was not performed.
AgencyTankId:	E6R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Primary Overfill Identified
Violation Desc:	The primary overfill device was not identified.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met- ball float Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Primary Overfill Identified
Violation Desc:	The primary overfill device was not identified.
AgencyTankId:	E6R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met- ball float

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping Records
Violation Desc:	The annual tightness test documentation was not available for the piping.
AgencyTankId:	E6R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14

Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Updated UST notification information required
Violation Desc:	The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.
AgencyTankId:	Not reported
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported

Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Current Owner
Violation Desc:	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.
AgencyTankId:	Not reported
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported

Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	E6R1
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Spill Prevention Device Not Functional
Violation Desc:	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.
AgencyTankId:	E6R1
Compliance Date:	10/02/2014
Compliance Method:	Documentation
Compliance Notes:	Site pumped out and cleaned sumps. Multiple photos taken, see email
Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	D5R1
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Monthly Records
Violation Desc:	Monthly records of interstitial monitoring records were not available.
AgencyTankId:	D5R1
Compliance Date:	06/20/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met for tanks, interstice is being monitored but still need sensors installed for

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

piping before close this violation Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form

Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Dispenser Sump Free of Liquid
Violation Desc:	The dispenser sump contains liquid.
AgencyTankId:	Not reported
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14

Name:	CHUCKS AUTOMOTIVE LLC
Address:	653 BURNSIDE AVE
Address 2:	Not reported
City,State,Zip:	EAST HARTFORD 06108
Facility ID:	43-5508
Substance:	Gasoline
Last Use Date:	Not reported
Tank ID:	D5
Closure Status:	Tank was Removed From Ground
Compartment ID:	a
Tank Status:	Permanently Closed
Secondary Material:	Not reported
Tank Material:	Coated & Cathodically Protected Steel (sti-P3)
Capacity:	1000
Install Date:	08/01/1988
Overfill Installed:	Not reported
Pipe Material:	Bare Steel
Pipe Mode Description:	Not reported
Spill Installed:	Not reported
Latitude:	41.779012
Longitude:	-72.611473
Tank Latitude:	41.77892
Tank Longitude:	-72.61139

Contact:

Facility ID:	43-5508
Owner Name:	Branden Naraine
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Class B Operator
Contact Name: .
Contact Title: Not reported
Contact Email: Not reported

Facility ID: 43-5508
Owner Name: CB AUTOMOTIVE, LLC
Owner Address: 653 Burnside Ave
Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Billing Contact
Contact Name: Branden Naraine
Contact Title: Not reported
Contact Email: Not reported

Facility ID: 43-5508
Owner Name: CB AUTOMOTIVE, LLC
Owner Address: 653 Burnside Ave
Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Owner
Contact Name: Branden Naraine
Contact Title: Not reported
Contact Email: Not reported

Facility ID: 43-5508
Owner Name: CB AUTOMOTIVE, LLC
Owner Address: 653 Burnside Ave
Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Registrant
Contact Name: Branden Naraine
Contact Title: Not reported
Contact Email: Not reported

Facility ID: 43-5508
Owner Name: CB AUTOMOTIVE, LLC
Owner Address: 653 Burnside Ave
Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Operator
Contact Name: Branden Naraine
Contact Title: Not reported
Contact Email: Not reported

Facility ID: 43-5508

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Owner Name: CB AUTOMOTIVE, LLC
Owner Address: 653 Burnside Ave
Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Primary Contact
Contact Name: Branden Naraine
Contact Title: Not reported
Contact Email: Not reported

Facility ID: 43-5508
Owner Name: CB AUTOMOTIVE, LLC
Owner Address: 653 Burnside Ave
Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Property Owner
Contact Name: Branden Naraine
Contact Title: Not reported
Contact Email: Not reported

Facility ID: 43-5508
Owner Name: Branden Naraine
Owner Address: 653 Burnside Ave
Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Class A Operator
Contact Name: .
Contact Title: Not reported
Contact Email: Not reported

compilance:
Inspection Date: 04/18/2023
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true
Include in Red Tag: false
Field NOV ID: NOVUST-MC223-0056
Warning Letter ID: WLUST-MC223-0023
Violation Name: Failure to submitt an annual notification and/or annual fee
Violation Desc: The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).
AgencyTankId: Not reported
Compliance Date: 04/18/2023
Compliance Method: Warning Only
Compliance Notes: Not reported

Inspection Date: 05/31/2017
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Sensor Installed at Tank Sump
Violation Desc:	The division inspector has determined that a piping sump sensor was not installed at the tank sump.
AgencyTankId:	E6R1
Compliance Date:	06/20/2017
Compliance Method:	Test Results
Compliance Notes:	Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test Records
Violation Desc:	The passing annual line leak detector test documentation was not maintained.
AgencyTankId:	D5R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Sump Free of Liquid
Violation Desc:	The DepartmentG s inspector has determined that there is liquid or evidence of liquid accumulating in sump.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test Records
Violation Desc:	The passing annual line leak detector test documentation was not maintained.
AgencyTankId:	E6R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Failure to perform monthly visual inspections
Violation Desc:	The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.
AgencyTankId:	Not reported
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Operator retraining due to non-comliance
Violation Desc:	Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program.
AgencyTankId:	Not reported
Compliance Date:	06/20/2017
Compliance Method:	Documentation
Compliance Notes:	fax recd 6/20/17 included monthly inspection report (6/17 still needs sumps sensors) retraining certificates Gregory Tischofer A/B 6/4/17 API, Charles Tischofer Class C 6/4/17 API
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test
Violation Desc:	The passing annual line leak detector test had not been performed.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping
Violation Desc:	Annual Tightness Test for Pressurized Piping was not performed.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test
Violation Desc:	The passing annual line leak detector test had not been performed.
AgencyTankId:	E6R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Monthly Records
Violation Desc:	Monthly records of interstitial monitoring records were not available.
AgencyTankId:	E6R1
Compliance Date:	06/20/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met for tanks, interstice is being monitored but still need sensors installed for piping before close this violation Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form

Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Spill Prevention Device Not Functional
Violation Desc:	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.
AgencyTankId:	D5R1
Compliance Date:	10/02/2014
Compliance Method:	Documentation
Compliance Notes:	Site pumped out and cleaned sumps. Multiple photos taken, see email

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Sensor Installed at Tank Sump
Violation Desc:	The division inspector has determined that a piping sump sensor was not installed at the tank sump.
AgencyTankId:	D5R1
Compliance Date:	06/20/2017
Compliance Method:	Test Results
Compliance Notes:	Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form

Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping Records
Violation Desc:	The annual tightness test documentation was not available for the piping.
AgencyTankId:	D5R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Updated UST notification information required
Violation Desc:	The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.
AgencyTankId:	Not reported
Compliance Date:	05/03/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/3/23 Received updated ezFile notifcation with active insurance & AB operators

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing hydrostatic testing for regular, super & diesel tanks & dispenser sumps dated 4/21/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Release Detection Documentation Available
Violation Desc:	The release detection documentation was not available.

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing ATG functionality testing, dated 3/13/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Release Detection Documentation Available
Violation Desc:	The release detection documentation was not available.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing ATG functionality testing, dated 3/13/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failure to Test Repaired Spill Prevention Equipment
Violation Desc:	Failed to test repaired spill prevention equipment (e.g., spill bucket) within 30 days of the repair in accordance with manufacturer specifications or a nationally recognized code of practice.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel tanks dated 4/21/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failed to Maintain Records of Tests for Secondary Containment
Violation Desc:	Owner or Operator failed to maintain records of testing results required to demonstrate compliance with secondary containment systems.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic testing for regular, super & diesel sumps dated 4/21/23

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Spill Bucket Testing Schedule
Violation Desc:	Failed to conduct requisite testing of spill buckets according to initial and 3-year schedule.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel spill buckets dated 4/21/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Spill Bucket Testing Schedule
Violation Desc:	Failed to conduct requisite testing of spill buckets according to initial and 3-year schedule.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel spill buckets dated 4/21/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failed to Maintain Records of Tests for Secondary Containment
Violation Desc:	Owner or Operator failed to maintain records of testing results required to demonstrate compliance with secondary containment systems.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic testing for regular, super & diesel sumps dated 4/21/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failure to Test Repaired Spill Prevention Equipment
Violation Desc:	Failed to test repaired spill prevention equipment (e.g., spill bucket) within 30 days of the repair in accordance with manufacturer specifications or a nationally recognized code of practice.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel tanks dated 4/21/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing hydrostatic testing for regular, super & diesel tanks & dispenser sumps dated 4/21/23
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping
Violation Desc:	Annual Tightness Test for Pressurized Piping was not performed.
AgencyTankId:	E6R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Primary Overfill Identified
Violation Desc:	The primary overfill device was not identified.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met- ball float Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Primary Overfill Identified
Violation Desc:	The primary overfill device was not identified.
AgencyTankId:	E6R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met- ball float
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping Records
Violation Desc:	The annual tightness test documentation was not available for the piping.
AgencyTankId:	E6R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14
Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Updated UST notification information required
Violation Desc:	The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.
AgencyTankId:	Not reported

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported
Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Current Owner
Violation Desc:	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.
AgencyTankId:	Not reported
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported
Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	E6R1
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Spill Prevention Device Not Functional
Violation Desc:	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.
AgencyTankId:	E6R1
Compliance Date:	10/02/2014
Compliance Method:	Documentation
Compliance Notes:	Site pumped out and cleaned sumps. Multiple photos taken, see email
Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	D5R1
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Monthly Records
Violation Desc:	Monthly records of interstitial monitoring records were not available.
AgencyTankId:	D5R1
Compliance Date:	06/20/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met for tanks, interstice is being monitored but still need sensors installed for piping before close this violation Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form

Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Dispenser Sump Free of Liquid
Violation Desc:	The dispenser sump contains liquid.
AgencyTankId:	Not reported
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Name:	CHUCKS AUTOMOTIVE LLC
Address:	653 BURNSIDE AVE
Address 2:	Not reported
City,State,Zip:	EAST HARTFORD 06108
Facility ID:	43-5508
Substance:	Used Oil
Last Use Date:	Not reported
Tank ID:	E6
Closure Status:	Tank was Removed From Ground
Compartment ID:	a
Tank Status:	Permanently Closed
Secondary Material:	Not reported
Tank Material:	Coated & Cathodically Protected Steel (sti-P3)
Capacity:	1000
Install Date:	08/01/1988
Overfill Installed:	Not reported
Pipe Material:	Bare Steel
Pipe Mode Description:	Not reported
Spill Installed:	Not reported
Latitude:	41.779012
Longitude:	-72.611473
Tank Latitude:	41.77892
Tank Longitude:	-72.61139

Contact:

Facility ID:	43-5508
Owner Name:	Branden Naraine
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Class B Operator
Contact Name:	.
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5508
Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Billing Contact
Contact Name:	Branden Naraine
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5508
Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Owner
Contact Name:	Branden Naraine

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Contact Title: Not reported
Contact Email: Not reported

Facility ID: 43-5508
Owner Name: CB AUTOMOTIVE, LLC
Owner Address: 653 Burnside Ave
Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Registrant
Contact Name: Branden Naraine
Contact Title: Not reported
Contact Email: Not reported

Facility ID: 43-5508
Owner Name: CB AUTOMOTIVE, LLC
Owner Address: 653 Burnside Ave
Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Operator
Contact Name: Branden Naraine
Contact Title: Not reported
Contact Email: Not reported

Facility ID: 43-5508
Owner Name: CB AUTOMOTIVE, LLC
Owner Address: 653 Burnside Ave
Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Primary Contact
Contact Name: Branden Naraine
Contact Title: Not reported
Contact Email: Not reported

Facility ID: 43-5508
Owner Name: CB AUTOMOTIVE, LLC
Owner Address: 653 Burnside Ave
Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Property Owner
Contact Name: Branden Naraine
Contact Title: Not reported
Contact Email: Not reported

Facility ID: 43-5508
Owner Name: Branden Naraine
Owner Address: 653 Burnside Ave
Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Owner City/State/Zip: East Hartford, CT
Affiliation Type: Class A Operator
Contact Name: .
Contact Title: Not reported
Contact Email: Not reported

compilance:
Inspection Date: 04/18/2023
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true
Include in Red Tag: false
Field NOV ID: NOVUST-MC223-0056
Warning Letter ID: WLUST-MC223-0023
Violation Name: Failure to submitt an annual notification and/or annual fee
Violation Desc: The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).
AgencyTankId: Not reported
Compliance Date: 04/18/2023
Compliance Method: Warning Only
Compliance Notes: Not reported

Inspection Date: 05/31/2017
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true
Include in Red Tag: true
Field NOV ID: NOVUST-MC217-0025
Warning Letter ID: Not reported
Violation Name: Sensor Installed at Tank Sump
Violation Desc: The division inspector has determined that a piping sump sensor was not installed at the tank sump.
AgencyTankId: E6R1
Compliance Date: 06/20/2017
Compliance Method: Test Results
Compliance Notes: Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form

Inspection Date: 06/02/2014
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true
Include in Red Tag: false
Field NOV ID: NOVUST-MC214-0052
Warning Letter ID: Not reported

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Violation Name:	Annual LLD Test Records
Violation Desc:	The passing annual line leak detector test documentation was not maintained.
AgencyTankId:	D5R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Sump Free of Liquid
Violation Desc:	The DepartmentG s inspector has determined that there is liquid or evidence of liquid accumulating in sump.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test Records
Violation Desc:	The passing annual line leak detector test documentation was not maintained.
AgencyTankId:	E6R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Failure to perform monthly visual inspections
Violation Desc:	The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.
AgencyTankId:	Not reported
Compliance Date:	06/02/2017
Compliance Method:	Documentation

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Operator retraining due to non-comliance
Violation Desc:	Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program.
AgencyTankId:	Not reported
Compliance Date:	06/20/2017
Compliance Method:	Documentation
Compliance Notes:	fax recd 6/20/17 included monthly inspection report (6/17 still needs sumps sensors) retraining certificates Gregory Tischofer A/B 6/4/17 API, Charles Tischofer Class C 6/4/17 API
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test
Violation Desc:	The passing annual line leak detector test had not been performed.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping
Violation Desc:	Annual Tightness Test for Pressurized Piping was not performed.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test
Violation Desc:	The passing annual line leak detector test had not been performed.
AgencyTankId:	E6R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Monthly Records
Violation Desc:	Monthly records of interstitial monitoring records were not available.
AgencyTankId:	E6R1
Compliance Date:	06/20/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met for tanks, interstice is being monitored but still need sensors installed for piping before close this violation Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Spill Prevention Device Not Functional
Violation Desc:	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.
AgencyTankId:	D5R1
Compliance Date:	10/02/2014
Compliance Method:	Documentation
Compliance Notes:	Site pumped out and cleaned sumps. Multiple photos taken, see email
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Sensor Installed at Tank Sump
Violation Desc:	The division inspector has determined that a piping sump sensor was not installed at the tank sump.
AgencyTankId:	D5R1
Compliance Date:	06/20/2017
Compliance Method:	Test Results
Compliance Notes:	Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping Records
Violation Desc:	The annual tightness test documentation was not available for the piping.
AgencyTankId:	D5R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Updated UST notification information required
Violation Desc:	The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.
AgencyTankId:	Not reported
Compliance Date:	05/03/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/3/23 Received updated ezFile notifcation with active insurance & AB operators

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing hydrostatic testing for regular, super & diesel tanks & dispenser sumps dated 4/21/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Release Detection Documentation Available
Violation Desc:	The release detection documentation was not available.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing ATG functionality testing, dated 3/13/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Release Detection Documentation Available
Violation Desc:	The release detection documentation was not available.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing ATG functionality testing, dated 3/13/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Violation Name:	Failure to Test Repaired Spill Prevention Equipment
Violation Desc:	Failed to test repaired spill prevention equipment (e.g., spill bucket) within 30 days of the repair in accordance with manufacturer specifications or a nationally recognized code of practice.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel tanks dated 4/21/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failed to Maintain Records of Tests for Secondary Containment
Violation Desc:	Owner or Operator failed to maintain records of testing results required to demonstrate compliance with secondary containment systems.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic testing for regular, super & diesel sumps dated 4/21/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Spill Bucket Testing Schedule
Violation Desc:	Failed to conduct requisite testing of spill buckets according to initial and 3-year schedule.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel spill buckets dated 4/21/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Spill Bucket Testing Schedule
Violation Desc:	Failed to conduct requisite testing of spill buckets according to initial and 3-year schedule.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel spill buckets dated 4/21/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failed to Maintain Records of Tests for Secondary Containment
Violation Desc:	Owner or Operator failed to maintain records of testing results required to demonstrate compliance with secondary containment systems.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic testing for regular, super & diesel sumps dated 4/21/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failure to Test Repaired Spill Prevention Equipment
Violation Desc:	Failed to test repaired spill prevention equipment (e.g., spill bucket) within 30 days of the repair in accordance with manufacturer specifications or a nationally recognized code of practice.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel tanks dated 4/21/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing hydrostatic testing for regular, super & diesel tanks & dispenser sumps dated 4/21/23
Inspection Date:	05/31/2017

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping
Violation Desc:	Annual Tightness Test for Pressurized Piping was not performed.
AgencyTankId:	E6R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Primary Overfill Identified
Violation Desc:	The primary overfill device was not identified.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met- ball float Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Primary Overfill Identified
Violation Desc:	The primary overfill device was not identified.
AgencyTankId:	E6R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met- ball float

Inspection Date:	06/02/2014
UST Site ID Number:	43-5508

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping Records
Violation Desc:	The annual tightness test documentation was not available for the piping.
AgencyTankId:	E6R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14

Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Updated UST notification information required
Violation Desc:	The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.
AgencyTankId:	Not reported
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported

Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Current Owner
Violation Desc:	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.
AgencyTankId:	Not reported
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported

Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

	requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	E6R1
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Spill Prevention Device Not Functional
Violation Desc:	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.
AgencyTankId:	E6R1
Compliance Date:	10/02/2014
Compliance Method:	Documentation
Compliance Notes:	Site pumped out and cleaned sumps. Multiple photos taken, see email
Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	D5R1
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Monthly Records
Violation Desc:	Monthly records of interstitial monitoring records were not available.
AgencyTankId:	D5R1
Compliance Date:	06/20/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met for tanks, interstice is being monitored but still need sensors installed for piping before close this violation Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

& LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form

Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Dispenser Sump Free of Liquid
Violation Desc:	The dispenser sump contains liquid.
AgencyTankId:	Not reported
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14

Name:	CHUCKS AUTOMOTIVE LLC
Address:	653 BURNSIDE AVE
Address 2:	Not reported
City,State,Zip:	EAST HARTFORD 06108
Facility ID:	43-5508
Substance:	Not reported
Last Use Date:	01/18/2012
Tank ID:	10*
Closure Status:	Tank was Removed From Ground
Compartment ID:	a
Tank Status:	Permanently Closed
Secondary Material:	Not reported
Tank Material:	Not reported
Capacity:	1
Install Date:	Not reported
Overfill Installed:	Not reported
Pipe Material:	Other (Specify)
Pipe Mode Description:	Not reported
Spill Installed:	Not reported
Latitude:	41.779012
Longitude:	-72.611473
Tank Latitude:	41.779012
Tank Longitude:	-72.611473

Contact:

Facility ID:	43-5508
Owner Name:	Branden Naraine
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Owner City/State/Zip: East Hartford, CT
Affiliation Type: Class B Operator
Contact Name: .
Contact Title: Not reported
Contact Email: Not reported

Facility ID: 43-5508
Owner Name: CB AUTOMOTIVE, LLC
Owner Address: 653 Burnside Ave
Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Billing Contact
Contact Name: Branden Naraine
Contact Title: Not reported
Contact Email: Not reported

Facility ID: 43-5508
Owner Name: CB AUTOMOTIVE, LLC
Owner Address: 653 Burnside Ave
Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Owner
Contact Name: Branden Naraine
Contact Title: Not reported
Contact Email: Not reported

Facility ID: 43-5508
Owner Name: CB AUTOMOTIVE, LLC
Owner Address: 653 Burnside Ave
Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Registrant
Contact Name: Branden Naraine
Contact Title: Not reported
Contact Email: Not reported

Facility ID: 43-5508
Owner Name: CB AUTOMOTIVE, LLC
Owner Address: 653 Burnside Ave
Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Operator
Contact Name: Branden Naraine
Contact Title: Not reported
Contact Email: Not reported

Facility ID: 43-5508
Owner Name: CB AUTOMOTIVE, LLC
Owner Address: 653 Burnside Ave

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Primary Contact
Contact Name: Branden Naraine
Contact Title: Not reported
Contact Email: Not reported

Facility ID: 43-5508
Owner Name: CB AUTOMOTIVE, LLC
Owner Address: 653 Burnside Ave
Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Property Owner
Contact Name: Branden Naraine
Contact Title: Not reported
Contact Email: Not reported

Facility ID: 43-5508
Owner Name: Branden Naraine
Owner Address: 653 Burnside Ave
Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Class A Operator
Contact Name: .
Contact Title: Not reported
Contact Email: Not reported

compilance:
Inspection Date: 04/18/2023
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true
Include in Red Tag: false
Field NOV ID: NOVUST-MC223-0056
Warning Letter ID: WLUST-MC223-0023
Violation Name: Failure to submitt an annual notification and/or annual fee
Violation Desc: The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).
AgencyTankId: Not reported
Compliance Date: 04/18/2023
Compliance Method: Warning Only
Compliance Notes: Not reported

Inspection Date: 05/31/2017
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true
Include in Red Tag: true
Field NOV ID: NOVUST-MC217-0025

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Warning Letter ID:	Not reported
Violation Name:	Sensor Installed at Tank Sump
Violation Desc:	The division inspector has determined that a piping sump sensor was not installed at the tank sump.
AgencyTankId:	E6R1
Compliance Date:	06/20/2017
Compliance Method:	Test Results
Compliance Notes:	Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test Records
Violation Desc:	The passing annual line leak detector test documentation was not maintained.
AgencyTankId:	D5R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Sump Free of Liquid
Violation Desc:	The DepartmentG s inspector has determined that there is liquid or evidence of liquid accumulating in sump.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test Records
Violation Desc:	The passing annual line leak detector test documentation was not maintained.
AgencyTankId:	E6R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Failure to perform monthly visual inspections
Violation Desc:	The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.
AgencyTankId:	Not reported
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Operator retraining due to non-comliance
Violation Desc:	Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program.
AgencyTankId:	Not reported
Compliance Date:	06/20/2017
Compliance Method:	Documentation
Compliance Notes:	fax recd 6/20/17 included monthly inspection report (6/17 still needs sumps sensors) retraining certificates Gregory Tischofer A/B 6/4/17 API, Charles Tischofer Class C 6/4/17 API
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Violation Name:	Annual LLD Test
Violation Desc:	The passing annual line leak detector test had not been performed.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping
Violation Desc:	Annual Tightness Test for Pressurized Piping was not performed.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test
Violation Desc:	The passing annual line leak detector test had not been performed.
AgencyTankId:	E6R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Monthly Records
Violation Desc:	Monthly records of interstitial monitoring records were not available.
AgencyTankId:	E6R1
Compliance Date:	06/20/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met for tanks, interstice is being monitored but still need sensors installed for piping before close this violation Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms,

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form

Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Spill Prevention Device Not Functional
Violation Desc:	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.
AgencyTankId:	D5R1
Compliance Date:	10/02/2014
Compliance Method:	Documentation
Compliance Notes:	Site pumped out and cleaned sumps. Multiple photos taken, see email

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Sensor Installed at Tank Sump
Violation Desc:	The division inspector has determined that a piping sump sensor was not installed at the tank sump.
AgencyTankId:	D5R1
Compliance Date:	06/20/2017
Compliance Method:	Test Results
Compliance Notes:	Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form

Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping Records
Violation Desc:	The annual tightness test documentation was not available for the piping.
AgencyTankId:	D5R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Updated UST notification information required
Violation Desc:	The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.
AgencyTankId:	Not reported
Compliance Date:	05/03/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/3/23 Received updated ezFile notifcation with active insurance & AB operators
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing hydrostatic testing for regular, super & diesel tanks & dispenser sumps dated 4/21/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Release Detection Documentation Available
Violation Desc:	The release detection documentation was not available.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing ATG functionality testing, dated 3/13/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Release Detection Documentation Available
Violation Desc:	The release detection documentation was not available.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing ATG functionality testing, dated 3/13/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failure to Test Repaired Spill Prevention Equipment
Violation Desc:	Failed to test repaired spill prevention equipment (e.g., spill bucket) within 30 days of the repair in accordance with manufacturer specifications or a nationally recognized code of practice.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel tanks dated 4/21/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failed to Maintain Records of Tests for Secondary Containment
Violation Desc:	Owner or Operator failed to maintain records of testing results required to demonstrate compliance with secondary containment systems.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic testing for regular, super & diesel sumps dated 4/21/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Spill Bucket Testing Schedule
Violation Desc:	Failed to conduct requisite testing of spill buckets according to initial and 3-year schedule.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel spill buckets dated 4/21/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Spill Bucket Testing Schedule
Violation Desc:	Failed to conduct requisite testing of spill buckets according to initial and 3-year schedule.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel spill buckets dated 4/21/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failed to Maintain Records of Tests for Secondary Containment
Violation Desc:	Owner or Operator failed to maintain records of testing results required to demonstrate compliance with secondary containment systems.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic testing for regular, super & diesel sumps dated 4/21/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Violation Name:	Failure to Test Repaired Spill Prevention Equipment
Violation Desc:	Failed to test repaired spill prevention equipment (e.g., spill bucket) within 30 days of the repair in accordance with manufacturer specifications or a nationally recognized code of practice.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel tanks dated 4/21/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing hydrostatic testing for regular, super & diesel tanks & dispenser sumps dated 4/21/23
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping
Violation Desc:	Annual Tightness Test for Pressurized Piping was not performed.
AgencyTankId:	E6R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Primary Overfill Identified
Violation Desc:	The primary overfill device was not identified.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met- ball float Note: fax recd 6/20/17 with signed CS, includes red tag closure info

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Primary Overfill Identified
Violation Desc:	The primary overfill device was not identified.
AgencyTankId:	E6R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met- ball float

Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping Records
Violation Desc:	The annual tightness test documentation was not available for the piping.
AgencyTankId:	E6R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14

Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Updated UST notification information required
Violation Desc:	The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.
AgencyTankId:	Not reported
Compliance Date:	Not reported
Compliance Method:	Not reported

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Compliance Notes:	Not reported
Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Current Owner
Violation Desc:	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.
AgencyTankId:	Not reported
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported
Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	E6R1
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Spill Prevention Device Not Functional
Violation Desc:	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.
AgencyTankId:	E6R1
Compliance Date:	10/02/2014
Compliance Method:	Documentation
Compliance Notes:	Site pumped out and cleaned sumps. Multiple photos taken, see email
Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	D5R1
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Monthly Records
Violation Desc:	Monthly records of interstitial monitoring records were not available.
AgencyTankId:	D5R1
Compliance Date:	06/20/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met for tanks, interstice is being monitored but still need sensors installed for piping before close this violation Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form

Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Dispenser Sump Free of Liquid
Violation Desc:	The dispenser sump contains liquid.
AgencyTankId:	Not reported
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14

Name:	CHUCKS AUTOMOTIVE LLC
Address:	653 BURNSIDE AVE

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Address 2:	Not reported
City,State,Zip:	EAST HARTFORD 06108
Facility ID:	43-5508
Substance:	Not reported
Last Use Date:	01/18/2012
Tank ID:	11*
Closure Status:	Not reported
Compartment ID:	a
Tank Status:	Permanently Closed
Secondary Material:	Not reported
Tank Material:	Not reported
Capacity:	0
Install Date:	Not reported
Overfill Installed:	Not reported
Pipe Material:	Other (Specify)
Pipe Mode Description:	Not reported
Spill Installed:	Not reported
Latitude:	41.779012
Longitude:	-72.611473
Tank Latitude:	41.779012
Tank Longitude:	-72.611473

Contact:

Facility ID:	43-5508
Owner Name:	Branden Naraine
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Class B Operator
Contact Name:	.
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5508
Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Billing Contact
Contact Name:	Branden Naraine
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5508
Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Owner
Contact Name:	Branden Naraine
Contact Title:	Not reported
Contact Email:	Not reported

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Facility ID:	43-5508
Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Registrant
Contact Name:	Branden Naraine
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5508
Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Operator
Contact Name:	Branden Naraine
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5508
Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Primary Contact
Contact Name:	Branden Naraine
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5508
Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Property Owner
Contact Name:	Branden Naraine
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5508
Owner Name:	Branden Naraine
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Class A Operator
Contact Name:	.

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Contact Title: Not reported
Contact Email: Not reported

compilance:
Inspection Date: 04/18/2023
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true
Include in Red Tag: false
Field NOV ID: NOVUST-MC223-0056
Warning Letter ID: WLUST-MC223-0023
Violation Name: Failure to submitt an annual notification and/or annual fee
Violation Desc: The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).
AgencyTankId: Not reported
Compliance Date: 04/18/2023
Compliance Method: Warning Only
Compliance Notes: Not reported

Inspection Date: 05/31/2017
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true
Include in Red Tag: true
Field NOV ID: NOVUST-MC217-0025
Warning Letter ID: Not reported
Violation Name: Sensor Installed at Tank Sump
Violation Desc: The division inspector has determined that a piping sump sensor was not installed at the tank sump.
AgencyTankId: E6R1
Compliance Date: 06/20/2017
Compliance Method: Test Results
Compliance Notes: Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form

Inspection Date: 06/02/2014
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true
Include in Red Tag: false
Field NOV ID: NOVUST-MC214-0052
Warning Letter ID: Not reported
Violation Name: Annual LLD Test Records
Violation Desc: The passing annual line leak detector test documentation was not maintained.

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

AgencyTankId:	D5R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Sump Free of Liquid
Violation Desc:	The DepartmentG s inspector has determined that there is liquid or evidence of liquid accumulating in sump.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test Records
Violation Desc:	The passing annual line leak detector test documentation was not maintained.
AgencyTankId:	E6R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Failure to perform monthly visual inspections
Violation Desc:	The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.
AgencyTankId:	Not reported
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	05/31/2017

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Operator retraining due to non-comliance
Violation Desc:	Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program.
AgencyTankId:	Not reported
Compliance Date:	06/20/2017
Compliance Method:	Documentation
Compliance Notes:	fax recd 6/20/17 included monthly inspection report (6/17 still needs sumps sensors) retraining certificates Gregory Tischofer A/B 6/4/17 API, Charles Tischofer Class C 6/4/17 API

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test
Violation Desc:	The passing annual line leak detector test had not been performed.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping
Violation Desc:	Annual Tightness Test for Pressurized Piping was not performed.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Violation Name:	Annual LLD Test
Violation Desc:	The passing annual line leak detector test had not been performed.
AgencyTankId:	E6R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Monthly Records
Violation Desc:	Monthly records of interstitial monitoring records were not available.
AgencyTankId:	E6R1
Compliance Date:	06/20/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met for tanks, interstice is being monitored but still need sensors installed for piping before close this violation Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Spill Prevention Device Not Functional
Violation Desc:	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.
AgencyTankId:	D5R1
Compliance Date:	10/02/2014
Compliance Method:	Documentation
Compliance Notes:	Site pumped out and cleaned sumps. Multiple photos taken, see email
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Sensor Installed at Tank Sump
Violation Desc:	The division inspector has determined that a piping sump sensor was not installed at the tank sump.
AgencyTankId:	D5R1
Compliance Date:	06/20/2017
Compliance Method:	Test Results
Compliance Notes:	Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping Records
Violation Desc:	The annual tightness test documentation was not available for the piping.
AgencyTankId:	D5R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Updated UST notification information required
Violation Desc:	The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.
AgencyTankId:	Not reported
Compliance Date:	05/03/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/3/23 Received updated ezFile notifcation with active insurance & AB operators
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing hydrostatic testing for regular, super & diesel tanks & dispenser sumps dated 4/21/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Release Detection Documentation Available
Violation Desc:	The release detection documentation was not available.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing ATG functionality testing, dated 3/13/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Release Detection Documentation Available
Violation Desc:	The release detection documentation was not available.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing ATG functionality testing, dated 3/13/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failure to Test Repaired Spill Prevention Equipment
Violation Desc:	Failed to test repaired spill prevention equipment (e.g., spill

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

bucket) within 30 days of the repair in accordance with manufacturer specifications or a nationally recognized code of practice.
AgencyTankId: D5R1
Compliance Date: 05/04/2023
Compliance Method: Documentation
Compliance Notes: ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel tanks dated 4/21/23

Inspection Date: 04/18/2023
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true
Include in Red Tag: false
Field NOV ID: NOVUST-MC223-0056
Warning Letter ID: WLUST-MC223-0023
Violation Name: Failed to Maintain Records of Tests for Secondary Containment
Violation Desc: Owner or Operator failed to maintain records of testing results required to demonstrate compliance with secondary containment systems.
AgencyTankId: D5R1
Compliance Date: 05/04/2023
Compliance Method: Documentation
Compliance Notes: ER 5/4/23 Received passing hydrostatic testing for regular, super & diesel sumps dated 4/21/23

Inspection Date: 04/18/2023
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true
Include in Red Tag: false
Field NOV ID: NOVUST-MC223-0056
Warning Letter ID: WLUST-MC223-0023
Violation Name: Spill Bucket Testing Schedule
Violation Desc: Failed to conduct requisite testing of spill buckets according to initial and 3-year schedule.
AgencyTankId: E6R1
Compliance Date: 05/04/2023
Compliance Method: Documentation
Compliance Notes: ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel spill buckets dated 4/21/23

Inspection Date: 04/18/2023
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true
Include in Red Tag: false
Field NOV ID: NOVUST-MC223-0056
Warning Letter ID: WLUST-MC223-0023
Violation Name: Spill Bucket Testing Schedule
Violation Desc: Failed to conduct requisite testing of spill buckets according to initial and 3-year schedule.
AgencyTankId: D5R1
Compliance Date: 05/04/2023
Compliance Method: Documentation
Compliance Notes: ER 5/4/23 Received passing hydrostatic tests for regular, super &

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

diesel spill buckets dated 4/21/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failed to Maintain Records of Tests for Secondary Containment
Violation Desc:	Owner or Operator failed to maintain records of testing results required to demonstrate compliance with secondary containment systems.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic testing for regular, super & diesel sumps dated 4/21/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failure to Test Repaired Spill Prevention Equipment
Violation Desc:	Failed to test repaired spill prevention equipment (e.g., spill bucket) within 30 days of the repair in accordance with manufacturer specifications or a nationally recognized code of practice.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel tanks dated 4/21/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing hydrostatic testing for regular, super & diesel tanks & dispenser sumps dated 4/21/23

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping
Violation Desc:	Annual Tightness Test for Pressurized Piping was not performed.
AgencyTankId:	E6R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Primary Overfill Identified
Violation Desc:	The primary overfill device was not identified.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met- ball float Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Primary Overfill Identified
Violation Desc:	The primary overfill device was not identified.
AgencyTankId:	E6R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met- ball float

Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping Records
Violation Desc:	The annual tightness test documentation was not available for the piping.
AgencyTankId:	E6R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14

Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Updated UST notification information required
Violation Desc:	The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.
AgencyTankId:	Not reported
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported

Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Current Owner
Violation Desc:	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.
AgencyTankId:	Not reported
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported

Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	E6R1

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Spill Prevention Device Not Functional
Violation Desc:	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.
AgencyTankId:	E6R1
Compliance Date:	10/02/2014
Compliance Method:	Documentation
Compliance Notes:	Site pumped out and cleaned sumps. Multiple photos taken, see email
Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	D5R1
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Monthly Records
Violation Desc:	Monthly records of interstitial monitoring records were not available.
AgencyTankId:	D5R1
Compliance Date:	06/20/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met for tanks, interstice is being monitored but still need sensors installed for piping before close this violation Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted)

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form

Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Dispenser Sump Free of Liquid
Violation Desc:	The dispenser sump contains liquid.
AgencyTankId:	Not reported
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14

Name:	CHUCKS AUTOMOTIVE LLC
Address:	653 BURNSIDE AVE
Address 2:	Not reported
City,State,Zip:	EAST HARTFORD 06108
Facility ID:	43-5508
Substance:	Not reported
Last Use Date:	01/18/2012
Tank ID:	12*
Closure Status:	Not reported
Compartment ID:	a
Tank Status:	Permanently Closed
Secondary Material:	Not reported
Tank Material:	Not reported
Capacity:	0
Install Date:	Not reported
Overfill Installed:	Not reported
Pipe Material:	Other (Specify)
Pipe Mode Description:	Not reported
Spill Installed:	Not reported
Latitude:	41.779012
Longitude:	-72.611473
Tank Latitude:	41.779012
Tank Longitude:	-72.611473

Contact:

Facility ID:	43-5508
Owner Name:	Branden Naraine
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Class B Operator

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Contact Name: .
Contact Title: Not reported
Contact Email: Not reported

Facility ID: 43-5508
Owner Name: CB AUTOMOTIVE, LLC
Owner Address: 653 Burnside Ave
Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Billing Contact
Contact Name: Branden Naraine
Contact Title: Not reported
Contact Email: Not reported

Facility ID: 43-5508
Owner Name: CB AUTOMOTIVE, LLC
Owner Address: 653 Burnside Ave
Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Owner
Contact Name: Branden Naraine
Contact Title: Not reported
Contact Email: Not reported

Facility ID: 43-5508
Owner Name: CB AUTOMOTIVE, LLC
Owner Address: 653 Burnside Ave
Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Registrant
Contact Name: Branden Naraine
Contact Title: Not reported
Contact Email: Not reported

Facility ID: 43-5508
Owner Name: CB AUTOMOTIVE, LLC
Owner Address: 653 Burnside Ave
Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Operator
Contact Name: Branden Naraine
Contact Title: Not reported
Contact Email: Not reported

Facility ID: 43-5508
Owner Name: CB AUTOMOTIVE, LLC
Owner Address: 653 Burnside Ave
Owner Address 2: Not reported
Owner Phone: (860) 289-0081

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Primary Contact
Contact Name: Branden Naraine
Contact Title: Not reported
Contact Email: Not reported

Facility ID: 43-5508
Owner Name: CB AUTOMOTIVE, LLC
Owner Address: 653 Burnside Ave
Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Property Owner
Contact Name: Branden Naraine
Contact Title: Not reported
Contact Email: Not reported

Facility ID: 43-5508
Owner Name: Branden Naraine
Owner Address: 653 Burnside Ave
Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Class A Operator
Contact Name: .
Contact Title: Not reported
Contact Email: Not reported

compilance:
Inspection Date: 04/18/2023
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true
Include in Red Tag: false
Field NOV ID: NOVUST-MC223-0056
Warning Letter ID: WLUST-MC223-0023
Violation Name: Failure to submitt an annual notification and/or annual fee
Violation Desc: The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).
AgencyTankId: Not reported
Compliance Date: 04/18/2023
Compliance Method: Warning Only
Compliance Notes: Not reported

Inspection Date: 05/31/2017
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true
Include in Red Tag: true
Field NOV ID: NOVUST-MC217-0025
Warning Letter ID: Not reported
Violation Name: Sensor Installed at Tank Sump

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Violation Desc:	The division inspector has determined that a piping sump sensor was not installed at the tank sump.
AgencyTankId:	E6R1
Compliance Date:	06/20/2017
Compliance Method:	Test Results
Compliance Notes:	Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test Records
Violation Desc:	The passing annual line leak detector test documentation was not maintained.
AgencyTankId:	D5R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Sump Free of Liquid
Violation Desc:	The DepartmentG s inspector has determined that there is liquid or evidence of liquid accumulating in sump.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test Records
Violation Desc:	The passing annual line leak detector test documentation was not maintained.
AgencyTankId:	E6R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Failure to perform monthly visual inspections
Violation Desc:	The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.
AgencyTankId:	Not reported
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Operator retraining due to non-comliance
Violation Desc:	Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program.
AgencyTankId:	Not reported
Compliance Date:	06/20/2017
Compliance Method:	Documentation
Compliance Notes:	fax recd 6/20/17 included monthly inspection report (6/17 still needs sumps sensors) retraining certificates Gregory Tischofer A/B 6/4/17 API, Charles Tischofer Class C 6/4/17 API
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test
Violation Desc:	The passing annual line leak detector test had not been performed.

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping
Violation Desc:	Annual Tightness Test for Pressurized Piping was not performed.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test
Violation Desc:	The passing annual line leak detector test had not been performed.
AgencyTankId:	E6R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Monthly Records
Violation Desc:	Monthly records of interstitial monitoring records were not available.
AgencyTankId:	E6R1
Compliance Date:	06/20/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met for tanks, interstice is being monitored but still need sensors installed for piping before close this violation Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form

Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Spill Prevention Device Not Functional
Violation Desc:	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.
AgencyTankId:	D5R1
Compliance Date:	10/02/2014
Compliance Method:	Documentation
Compliance Notes:	Site pumped out and cleaned sumps. Multiple photos taken, see email

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Sensor Installed at Tank Sump
Violation Desc:	The division inspector has determined that a piping sump sensor was not installed at the tank sump.
AgencyTankId:	D5R1
Compliance Date:	06/20/2017
Compliance Method:	Test Results
Compliance Notes:	Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form

Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Violation Name:	Annual Tightness Test for Pressurized Piping Records
Violation Desc:	The annual tightness test documentation was not available for the piping.
AgencyTankId:	D5R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Updated UST notification information required
Violation Desc:	The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.
AgencyTankId:	Not reported
Compliance Date:	05/03/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/3/23 Received updated ezFile notifcation with active insurance & AB operators
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing hydrostatic testing for regular, super & diesel tanks & dispenser sumps dated 4/21/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Release Detection Documentation Available
Violation Desc:	The release detection documentation was not available.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing ATG functionality testing,

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

dated 3/13/23

Inspection Date: 04/18/2023
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true
Include in Red Tag: false
Field NOV ID: NOVUST-MC223-0056
Warning Letter ID: WLUST-MC223-0023
Violation Name: Release Detection Documentation Available
Violation Desc: The release detection documentation was not available.
AgencyTankId: D5R1
Compliance Date: 05/04/2023
Compliance Method: Documentation
Compliance Notes: ER 5/4/23 Received documentation of passing ATG functionality testing, dated 3/13/23

Inspection Date: 04/18/2023
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true
Include in Red Tag: false
Field NOV ID: NOVUST-MC223-0056
Warning Letter ID: WLUST-MC223-0023
Violation Name: Failure to Test Repaired Spill Prevention Equipment
Violation Desc: Failed to test repaired spill prevention equipment (e.g., spill bucket) within 30 days of the repair in accordance with manufacturer specifications or a nationally recognized code of practice.
AgencyTankId: D5R1
Compliance Date: 05/04/2023
Compliance Method: Documentation
Compliance Notes: ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel tanks dated 4/21/23

Inspection Date: 04/18/2023
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true
Include in Red Tag: false
Field NOV ID: NOVUST-MC223-0056
Warning Letter ID: WLUST-MC223-0023
Violation Name: Failed to Maintain Records of Tests for Secondary Containment
Violation Desc: Owner or Operator failed to maintain records of testing results required to demonstrate compliance with secondary containment systems.
AgencyTankId: D5R1
Compliance Date: 05/04/2023
Compliance Method: Documentation
Compliance Notes: ER 5/4/23 Received passing hydrostatic testing for regular, super & diesel sumps dated 4/21/23

Inspection Date: 04/18/2023
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Spill Bucket Testing Schedule
Violation Desc:	Failed to conduct requisite testing of spill buckets according to initial and 3-year schedule.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel spill buckets dated 4/21/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Spill Bucket Testing Schedule
Violation Desc:	Failed to conduct requisite testing of spill buckets according to initial and 3-year schedule.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel spill buckets dated 4/21/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failed to Maintain Records of Tests for Secondary Containment
Violation Desc:	Owner or Operator failed to maintain records of testing results required to demonstrate compliance with secondary containment systems.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic testing for regular, super & diesel sumps dated 4/21/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failure to Test Repaired Spill Prevention Equipment
Violation Desc:	Failed to test repaired spill prevention equipment (e.g., spill

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

bucket) within 30 days of the repair in accordance with manufacturer specifications or a nationally recognized code of practice.
AgencyTankId: E6R1
Compliance Date: 05/04/2023
Compliance Method: Documentation
Compliance Notes: ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel tanks dated 4/21/23

Inspection Date: 04/18/2023
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true
Include in Red Tag: false
Field NOV ID: NOVUST-MC223-0056
Warning Letter ID: WLUST-MC223-0023
Violation Name: Record Keeping for Spill Prevention Equipment
Violation Desc: Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId: D5R1
Compliance Date: 05/04/2023
Compliance Method: Documentation
Compliance Notes: ER 5/4/23 Received documentation of passing hydrostatic testing for regular, super & diesel tanks & dispenser sumps dated 4/21/23

Inspection Date: 05/31/2017
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true
Include in Red Tag: false
Field NOV ID: NOVUST-MC217-0025
Warning Letter ID: Not reported
Violation Name: Annual Tightness Test for Pressurized Piping
Violation Desc: Annual Tightness Test for Pressurized Piping was not performed.
AgencyTankId: E6R1
Compliance Date: 06/02/2017
Compliance Method: Documentation
Compliance Notes: Red tag hearing 6/2/17 per PW this violation has been met

Inspection Date: 05/31/2017
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true
Include in Red Tag: false
Field NOV ID: NOVUST-MC217-0025
Warning Letter ID: Not reported
Violation Name: Primary Overfill Identified
Violation Desc: The primary overfill device was not identified.
AgencyTankId: D5R1
Compliance Date: 06/02/2017
Compliance Method: Documentation
Compliance Notes: Red tag hearing 6/2/17 per PW this violation has been met- ball float Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Primary Overfill Identified
Violation Desc:	The primary overfill device was not identified.
AgencyTankId:	E6R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met- ball float

Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping Records
Violation Desc:	The annual tightness test documentation was not available for the piping.
AgencyTankId:	E6R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14

Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Updated UST notification information required
Violation Desc:	The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.
AgencyTankId:	Not reported
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Current Owner
Violation Desc:	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.
AgencyTankId:	Not reported
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported

Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	E6R1
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported

Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Spill Prevention Device Not Functional
Violation Desc:	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.
AgencyTankId:	E6R1
Compliance Date:	10/02/2014
Compliance Method:	Documentation
Compliance Notes:	Site pumped out and cleaned sumps. Multiple photos taken, see email

Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Warning Letter ID:	Not reported
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	D5R1
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Monthly Records
Violation Desc:	Monthly records of interstitial monitoring records were not available.
AgencyTankId:	D5R1
Compliance Date:	06/20/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met for tanks, interstice is being monitored but still need sensors installed for piping before close this violation Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Dispenser Sump Free of Liquid
Violation Desc:	The dispenser sump contains liquid.
AgencyTankId:	Not reported
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14
Name:	CHUCKS AUTOMOTIVE LLC
Address:	653 BURNSIDE AVE
Address 2:	Not reported
City,State,Zip:	EAST HARTFORD 06108

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Facility ID:	43-5508
Substance:	Gasoline
Last Use Date:	08/01/1988
Tank ID:	A1
Closure Status:	Tank was Removed From Ground
Compartment ID:	a
Tank Status:	Permanently Closed
Secondary Material:	Not reported
Tank Material:	Asphalt Coated or Bare Steel
Capacity:	3000
Install Date:	01/01/1950
Overfill Installed:	Not reported
Pipe Material:	Bare Steel
Pipe Mode Description:	Not reported
Spill Installed:	Not reported
Latitude:	41.779012
Longitude:	-72.611473
Tank Latitude:	41.779012
Tank Longitude:	-72.611473

Contact:

Facility ID:	43-5508
Owner Name:	Branden Naraine
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Class B Operator
Contact Name:	.
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5508
Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Billing Contact
Contact Name:	Branden Naraine
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5508
Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Owner
Contact Name:	Branden Naraine
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5508

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Registrant
Contact Name:	Branden Naraine
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5508
Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Operator
Contact Name:	Branden Naraine
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5508
Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Primary Contact
Contact Name:	Branden Naraine
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5508
Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Property Owner
Contact Name:	Branden Naraine
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5508
Owner Name:	Branden Naraine
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Class A Operator
Contact Name:	.
Contact Title:	Not reported

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Contact Email: Not reported

compilance:

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failure to submitt an annual notification and/or annual fee
Violation Desc:	The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).
AgencyTankId:	Not reported
Compliance Date:	04/18/2023
Compliance Method:	Warning Only
Compliance Notes:	Not reported

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Sensor Installed at Tank Sump
Violation Desc:	The division inspector has determined that a piping sump sensor was not installed at the tank sump.
AgencyTankId:	E6R1
Compliance Date:	06/20/2017
Compliance Method:	Test Results
Compliance Notes:	Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form

Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test Records
Violation Desc:	The passing annual line leak detector test documentation was not maintained.
AgencyTankId:	D5R1

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Sump Free of Liquid
Violation Desc:	The DepartmentG s inspector has determined that there is liquid or evidence of liquid accumulating in sump.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test Records
Violation Desc:	The passing annual line leak detector test documentation was not maintained.
AgencyTankId:	E6R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Failure to perform monthly visual inspections
Violation Desc:	The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.
AgencyTankId:	Not reported
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Operator retraining due to non-comliance
Violation Desc:	Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program.
AgencyTankId:	Not reported
Compliance Date:	06/20/2017
Compliance Method:	Documentation
Compliance Notes:	fax recd 6/20/17 included monthly inspection report (6/17 still needs sumps sensors) retraining certificates Gregory Tischofer A/B 6/4/17 API, Charles Tischofer Class C 6/4/17 API

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test
Violation Desc:	The passing annual line leak detector test had not been performed.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping
Violation Desc:	Annual Tightness Test for Pressurized Piping was not performed.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Violation Desc:	The passing annual line leak detector test had not been performed.
AgencyTankId:	E6R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Monthly Records
Violation Desc:	Monthly records of interstitial monitoring records were not available.
AgencyTankId:	E6R1
Compliance Date:	06/20/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met for tanks, interstice is being monitored but still need sensors installed for piping before close this violation Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Spill Prevention Device Not Functional
Violation Desc:	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.
AgencyTankId:	D5R1
Compliance Date:	10/02/2014
Compliance Method:	Documentation
Compliance Notes:	Site pumped out and cleaned sumps. Multiple photos taken, see email
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Sensor Installed at Tank Sump
Violation Desc:	The division inspector has determined that a piping sump sensor was not installed at the tank sump.
AgencyTankId:	D5R1
Compliance Date:	06/20/2017
Compliance Method:	Test Results
Compliance Notes:	Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping Records
Violation Desc:	The annual tightness test documentation was not available for the piping.
AgencyTankId:	D5R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Updated UST notification information required
Violation Desc:	The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.
AgencyTankId:	Not reported
Compliance Date:	05/03/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/3/23 Received updated ezFile notifcation with active insurance & AB operators
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing hydrostatic testing for regular, super & diesel tanks & dispenser sumps dated 4/21/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Release Detection Documentation Available
Violation Desc:	The release detection documentation was not available.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing ATG functionality testing, dated 3/13/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Release Detection Documentation Available
Violation Desc:	The release detection documentation was not available.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing ATG functionality testing, dated 3/13/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failure to Test Repaired Spill Prevention Equipment
Violation Desc:	Failed to test repaired spill prevention equipment (e.g., spill bucket) within 30 days of the repair in accordance with manufacturer

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

specifications or a nationally recognized code of practice.
AgencyTankId: D5R1
Compliance Date: 05/04/2023
Compliance Method: Documentation
Compliance Notes: ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel tanks dated 4/21/23

Inspection Date: 04/18/2023
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true
Include in Red Tag: false
Field NOV ID: NOVUST-MC223-0056
Warning Letter ID: WLUST-MC223-0023
Violation Name: Failed to Maintain Records of Tests for Secondary Containment
Violation Desc: Owner or Operator failed to maintain records of testing results required to demonstrate compliance with secondary containment systems.
AgencyTankId: D5R1
Compliance Date: 05/04/2023
Compliance Method: Documentation
Compliance Notes: ER 5/4/23 Received passing hydrostatic testing for regular, super & diesel sumps dated 4/21/23

Inspection Date: 04/18/2023
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true
Include in Red Tag: false
Field NOV ID: NOVUST-MC223-0056
Warning Letter ID: WLUST-MC223-0023
Violation Name: Spill Bucket Testing Schedule
Violation Desc: Failed to conduct requisite testing of spill buckets according to initial and 3-year schedule.
AgencyTankId: E6R1
Compliance Date: 05/04/2023
Compliance Method: Documentation
Compliance Notes: ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel spill buckets dated 4/21/23

Inspection Date: 04/18/2023
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true
Include in Red Tag: false
Field NOV ID: NOVUST-MC223-0056
Warning Letter ID: WLUST-MC223-0023
Violation Name: Spill Bucket Testing Schedule
Violation Desc: Failed to conduct requisite testing of spill buckets according to initial and 3-year schedule.
AgencyTankId: D5R1
Compliance Date: 05/04/2023
Compliance Method: Documentation
Compliance Notes: ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel spill buckets dated 4/21/23

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failed to Maintain Records of Tests for Secondary Containment
Violation Desc:	Owner or Operator failed to maintain records of testing results required to demonstrate compliance with secondary containment systems.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic testing for regular, super & diesel sumps dated 4/21/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failure to Test Repaired Spill Prevention Equipment
Violation Desc:	Failed to test repaired spill prevention equipment (e.g., spill bucket) within 30 days of the repair in accordance with manufacturer specifications or a nationally recognized code of practice.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel tanks dated 4/21/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing hydrostatic testing for regular, super & diesel tanks & dispenser sumps dated 4/21/23

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping
Violation Desc:	Annual Tightness Test for Pressurized Piping was not performed.
AgencyTankId:	E6R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Primary Overfill Identified
Violation Desc:	The primary overfill device was not identified.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met- ball float Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Primary Overfill Identified
Violation Desc:	The primary overfill device was not identified.
AgencyTankId:	E6R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met- ball float

Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping Records
Violation Desc:	The annual tightness test documentation was not available for the piping.
AgencyTankId:	E6R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14
Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Updated UST notification information required
Violation Desc:	The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.
AgencyTankId:	Not reported
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported
Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Current Owner
Violation Desc:	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.
AgencyTankId:	Not reported
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported
Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	E6R1
Compliance Date:	Not reported
Compliance Method:	Not reported

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Compliance Notes:	Not reported
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Spill Prevention Device Not Functional
Violation Desc:	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.
AgencyTankId:	E6R1
Compliance Date:	10/02/2014
Compliance Method:	Documentation
Compliance Notes:	Site pumped out and cleaned sumps. Multiple photos taken, see email
Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	D5R1
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Monthly Records
Violation Desc:	Monthly records of interstitial monitoring records were not available.
AgencyTankId:	D5R1
Compliance Date:	06/20/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met for tanks, interstice is being monitored but still need sensors installed for piping before close this violation Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form

Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Dispenser Sump Free of Liquid
Violation Desc:	The dispenser sump contains liquid.
AgencyTankId:	Not reported
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14

Name:	CHUCKS AUTOMOTIVE LLC
Address:	653 BURNSIDE AVE
Address 2:	Not reported
City,State,Zip:	EAST HARTFORD 06108
Facility ID:	43-5508
Substance:	Gasoline
Last Use Date:	08/01/1988
Tank ID:	A2
Closure Status:	Tank was Removed From Ground
Compartment ID:	a
Tank Status:	Permanently Closed
Secondary Material:	Not reported
Tank Material:	Asphalt Coated or Bare Steel
Capacity:	3000
Install Date:	01/01/1950
Overfill Installed:	Not reported
Pipe Material:	Bare Steel
Pipe Mode Description:	Not reported
Spill Installed:	Not reported
Latitude:	41.779012
Longitude:	-72.611473
Tank Latitude:	41.779012
Tank Longitude:	-72.611473

Contact:

Facility ID:	43-5508
Owner Name:	Branden Naraine
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Class B Operator
Contact Name:	.
Contact Title:	Not reported

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Contact Email: Not reported

Facility ID: 43-5508
Owner Name: CB AUTOMOTIVE, LLC
Owner Address: 653 Burnside Ave
Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Billing Contact
Contact Name: Branden Naraine
Contact Title: Not reported
Contact Email: Not reported

Facility ID: 43-5508
Owner Name: CB AUTOMOTIVE, LLC
Owner Address: 653 Burnside Ave
Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Owner
Contact Name: Branden Naraine
Contact Title: Not reported
Contact Email: Not reported

Facility ID: 43-5508
Owner Name: CB AUTOMOTIVE, LLC
Owner Address: 653 Burnside Ave
Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Registrant
Contact Name: Branden Naraine
Contact Title: Not reported
Contact Email: Not reported

Facility ID: 43-5508
Owner Name: CB AUTOMOTIVE, LLC
Owner Address: 653 Burnside Ave
Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Operator
Contact Name: Branden Naraine
Contact Title: Not reported
Contact Email: Not reported

Facility ID: 43-5508
Owner Name: CB AUTOMOTIVE, LLC
Owner Address: 653 Burnside Ave
Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Affiliation Type:	Primary Contact
Contact Name:	Branden Naraine
Contact Title:	Not reported
Contact Email:	Not reported
Facility ID:	43-5508
Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Property Owner
Contact Name:	Branden Naraine
Contact Title:	Not reported
Contact Email:	Not reported
Facility ID:	43-5508
Owner Name:	Branden Naraine
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Class A Operator
Contact Name:	.
Contact Title:	Not reported
Contact Email:	Not reported

compilance:

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failure to submitt an annual notification and/or annual fee
Violation Desc:	The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).
AgencyTankId:	Not reported
Compliance Date:	04/18/2023
Compliance Method:	Warning Only
Compliance Notes:	Not reported
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Sensor Installed at Tank Sump
Violation Desc:	The division inspector has determined that a piping sump sensor was not installed at the tank sump.

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

AgencyTankId:	E6R1
Compliance Date:	06/20/2017
Compliance Method:	Test Results
Compliance Notes:	Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test Records
Violation Desc:	The passing annual line leak detector test documentation was not maintained.
AgencyTankId:	D5R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Sump Free of Liquid
Violation Desc:	The DepartmentG s inspector has determined that there is liquid or evidence of liquid accumulating in sump.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test Records

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Violation Desc:	The passing annual line leak detector test documentation was not maintained.
AgencyTankId:	E6R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Failure to perform monthly visual inspections
Violation Desc:	The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.
AgencyTankId:	Not reported
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Operator retraining due to non-comliance
Violation Desc:	Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program.
AgencyTankId:	Not reported
Compliance Date:	06/20/2017
Compliance Method:	Documentation
Compliance Notes:	fax recd 6/20/17 included monthly inspection report (6/17 still needs sumps sensors) retraining certificates Gregory Tischofer A/B 6/4/17 API, Charles Tischofer Class C 6/4/17 API
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test
Violation Desc:	The passing annual line leak detector test had not been performed.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping
Violation Desc:	Annual Tightness Test for Pressurized Piping was not performed.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test
Violation Desc:	The passing annual line leak detector test had not been performed.
AgencyTankId:	E6R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Monthly Records
Violation Desc:	Monthly records of interstitial monitoring records were not available.
AgencyTankId:	E6R1
Compliance Date:	06/20/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met for tanks, interstice is being monitored but still need sensors installed for piping before close this violation Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump &

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form

Inspection Date: 06/02/2014
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true
Include in Red Tag: true
Field NOV ID: NOVUST-MC214-0052
Warning Letter ID: Not reported
Violation Name: Spill Prevention Device Not Functional
Violation Desc: Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.
AgencyTankId: D5R1
Compliance Date: 10/02/2014
Compliance Method: Documentation
Compliance Notes: Site pumped out and cleaned sumps. Multiple photos taken, see email

Inspection Date: 05/31/2017
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true
Include in Red Tag: true
Field NOV ID: NOVUST-MC217-0025
Warning Letter ID: Not reported
Violation Name: Sensor Installed at Tank Sump
Violation Desc: The division inspector has determined that a piping sump sensor was not installed at the tank sump.
AgencyTankId: D5R1
Compliance Date: 06/20/2017
Compliance Method: Test Results
Compliance Notes: Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form

Inspection Date: 06/02/2014
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true
Include in Red Tag: false
Field NOV ID: NOVUST-MC214-0052
Warning Letter ID: Not reported
Violation Name: Annual Tightness Test for Pressurized Piping Records
Violation Desc: The annual tightness test documentation was not available for the

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

	piping.
AgencyTankId:	D5R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Updated UST notification information required
Violation Desc:	The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.
AgencyTankId:	Not reported
Compliance Date:	05/03/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/3/23 Received updated ezFile notifcation with active insurance & AB operators
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing hydrostatic testing for regular, super & diesel tanks & dispenser sumps dated 4/21/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Release Detection Documentation Available
Violation Desc:	The release detection documentation was not available.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing ATG functionality testing, dated 3/13/23

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Release Detection Documentation Available
Violation Desc:	The release detection documentation was not available.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing ATG functionality testing, dated 3/13/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failure to Test Repaired Spill Prevention Equipment
Violation Desc:	Failed to test repaired spill prevention equipment (e.g., spill bucket) within 30 days of the repair in accordance with manufacturer specifications or a nationally recognized code of practice.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel tanks dated 4/21/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failed to Maintain Records of Tests for Secondary Containment
Violation Desc:	Owner or Operator failed to maintain records of testing results required to demonstrate compliance with secondary containment systems.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic testing for regular, super & diesel sumps dated 4/21/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Spill Bucket Testing Schedule
Violation Desc:	Failed to conduct requisite testing of spill buckets according to initial and 3-year schedule.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel spill buckets dated 4/21/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Spill Bucket Testing Schedule
Violation Desc:	Failed to conduct requisite testing of spill buckets according to initial and 3-year schedule.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel spill buckets dated 4/21/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failed to Maintain Records of Tests for Secondary Containment
Violation Desc:	Owner or Operator failed to maintain records of testing results required to demonstrate compliance with secondary containment systems.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic testing for regular, super & diesel sumps dated 4/21/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failure to Test Repaired Spill Prevention Equipment
Violation Desc:	Failed to test repaired spill prevention equipment (e.g., spill bucket) within 30 days of the repair in accordance with manufacturer specifications or a nationally recognized code of practice.

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel tanks dated 4/21/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing hydrostatic testing for regular, super & diesel tanks & dispenser sumps dated 4/21/23
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping
Violation Desc:	Annual Tightness Test for Pressurized Piping was not performed.
AgencyTankId:	E6R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Primary Overfill Identified
Violation Desc:	The primary overfill device was not identified.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met- ball float Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Primary Overfill Identified
Violation Desc:	The primary overfill device was not identified.
AgencyTankId:	E6R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met- ball float

Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping Records
Violation Desc:	The annual tightness test documentation was not available for the piping.
AgencyTankId:	E6R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14

Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Updated UST notification information required
Violation Desc:	The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.
AgencyTankId:	Not reported
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported

Inspection Date:	03/11/2025
UST Site ID Number:	43-5508

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Current Owner
Violation Desc:	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.
AgencyTankId:	Not reported
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported

Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	E6R1
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported

Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Spill Prevention Device Not Functional
Violation Desc:	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.
AgencyTankId:	E6R1
Compliance Date:	10/02/2014
Compliance Method:	Documentation
Compliance Notes:	Site pumped out and cleaned sumps. Multiple photos taken, see email

Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Record Keeping for Spill Prevention Equipment

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	D5R1
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Monthly Records
Violation Desc:	Monthly records of interstitial monitoring records were not available.
AgencyTankId:	D5R1
Compliance Date:	06/20/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met for tanks, interstice is being monitored but still need sensors installed for piping before close this violation Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Dispenser Sump Free of Liquid
Violation Desc:	The dispenser sump contains liquid.
AgencyTankId:	Not reported
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14
Name:	CHUCKS AUTOMOTIVE LLC
Address:	653 BURNSIDE AVE
Address 2:	Not reported
City,State,Zip:	EAST HARTFORD 06108
Facility ID:	43-5508
Substance:	Gasoline

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Last Use Date:	08/01/1988
Tank ID:	B3
Closure Status:	Tank was Removed From Ground
Compartment ID:	a
Tank Status:	Permanently Closed
Secondary Material:	Not reported
Tank Material:	Asphalt Coated or Bare Steel
Capacity:	4000
Install Date:	01/01/1950
Overfill Installed:	Not reported
Pipe Material:	Bare Steel
Pipe Mode Description:	Not reported
Spill Installed:	Not reported
Latitude:	41.779012
Longitude:	-72.611473
Tank Latitude:	41.779012
Tank Longitude:	-72.611473

Contact:

Facility ID:	43-5508
Owner Name:	Branden Naraine
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Class B Operator
Contact Name:	.
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5508
Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Billing Contact
Contact Name:	Branden Naraine
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5508
Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Owner
Contact Name:	Branden Naraine
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5508
Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Registrant
Contact Name:	Branden Naraine
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5508
Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Operator
Contact Name:	Branden Naraine
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5508
Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Primary Contact
Contact Name:	Branden Naraine
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5508
Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Property Owner
Contact Name:	Branden Naraine
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5508
Owner Name:	Branden Naraine
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Class A Operator
Contact Name:	.
Contact Title:	Not reported
Contact Email:	Not reported

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

compilance:

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failure to submitt an annual notification and/or annual fee
Violation Desc:	The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).
AgencyTankId:	Not reported
Compliance Date:	04/18/2023
Compliance Method:	Warning Only
Compliance Notes:	Not reported

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Sensor Installed at Tank Sump
Violation Desc:	The division inspector has determined that a piping sump sensor was not installed at the tank sump.
AgencyTankId:	E6R1
Compliance Date:	06/20/2017
Compliance Method:	Test Results
Compliance Notes:	Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form

Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test Records
Violation Desc:	The passing annual line leak detector test documentation was not maintained.
AgencyTankId:	D5R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Sump Free of Liquid
Violation Desc:	The DepartmentG s inspector has determined that there is liquid or evidence of liquid accumulating in sump.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test Records
Violation Desc:	The passing annual line leak detector test documentation was not maintained.
AgencyTankId:	E6R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Failure to perform monthly visual inspections
Violation Desc:	The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.
AgencyTankId:	Not reported
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Operator retraining due to non-comliance
Violation Desc:	Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program.
AgencyTankId:	Not reported
Compliance Date:	06/20/2017
Compliance Method:	Documentation
Compliance Notes:	fax recd 6/20/17 included monthly inspection report (6/17 still needs sumps sensors) retraining certificates Gregory Tischofer A/B 6/4/17 API, Charles Tischofer Class C 6/4/17 API

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test
Violation Desc:	The passing annual line leak detector test had not been performed.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping
Violation Desc:	Annual Tightness Test for Pressurized Piping was not performed.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test
Violation Desc:	The passing annual line leak detector test had not been performed.
AgencyTankId:	E6R1

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Monthly Records
Violation Desc:	Monthly records of interstitial monitoring records were not available.
AgencyTankId:	E6R1
Compliance Date:	06/20/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met for tanks, interstice is being monitored but still need sensors installed for piping before close this violation Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Spill Prevention Device Not Functional
Violation Desc:	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.
AgencyTankId:	D5R1
Compliance Date:	10/02/2014
Compliance Method:	Documentation
Compliance Notes:	Site pumped out and cleaned sumps. Multiple photos taken, see email
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Violation Name:	Sensor Installed at Tank Sump
Violation Desc:	The division inspector has determined that a piping sump sensor was not installed at the tank sump.
AgencyTankId:	D5R1
Compliance Date:	06/20/2017
Compliance Method:	Test Results
Compliance Notes:	Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping Records
Violation Desc:	The annual tightness test documentation was not available for the piping.
AgencyTankId:	D5R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Updated UST notification information required
Violation Desc:	The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.
AgencyTankId:	Not reported
Compliance Date:	05/03/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/3/23 Received updated ezFile notifcation with active insurance & AB operators
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing hydrostatic testing for regular, super & diesel tanks & dispenser sumps dated 4/21/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Release Detection Documentation Available
Violation Desc:	The release detection documentation was not available.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing ATG functionality testing, dated 3/13/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Release Detection Documentation Available
Violation Desc:	The release detection documentation was not available.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing ATG functionality testing, dated 3/13/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failure to Test Repaired Spill Prevention Equipment
Violation Desc:	Failed to test repaired spill prevention equipment (e.g., spill bucket) within 30 days of the repair in accordance with manufacturer specifications or a nationally recognized code of practice.
AgencyTankId:	D5R1

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel tanks dated 4/21/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failed to Maintain Records of Tests for Secondary Containment
Violation Desc:	Owner or Operator failed to maintain records of testing results required to demonstrate compliance with secondary containment systems.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic testing for regular, super & diesel sumps dated 4/21/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Spill Bucket Testing Schedule
Violation Desc:	Failed to conduct requisite testing of spill buckets according to initial and 3-year schedule.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel spill buckets dated 4/21/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Spill Bucket Testing Schedule
Violation Desc:	Failed to conduct requisite testing of spill buckets according to initial and 3-year schedule.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel spill buckets dated 4/21/23
Inspection Date:	04/18/2023

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failed to Maintain Records of Tests for Secondary Containment
Violation Desc:	Owner or Operator failed to maintain records of testing results required to demonstrate compliance with secondary containment systems.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic testing for regular, super & diesel sumps dated 4/21/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failure to Test Repaired Spill Prevention Equipment
Violation Desc:	Failed to test repaired spill prevention equipment (e.g., spill bucket) within 30 days of the repair in accordance with manufacturer specifications or a nationally recognized code of practice.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel tanks dated 4/21/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing hydrostatic testing for regular, super & diesel tanks & dispenser sumps dated 4/21/23

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping
Violation Desc:	Annual Tightness Test for Pressurized Piping was not performed.
AgencyTankId:	E6R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Primary Overfill Identified
Violation Desc:	The primary overfill device was not identified.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met- ball float Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Primary Overfill Identified
Violation Desc:	The primary overfill device was not identified.
AgencyTankId:	E6R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met- ball float
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping Records
Violation Desc:	The annual tightness test documentation was not available for the piping.
AgencyTankId:	E6R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14
Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Updated UST notification information required
Violation Desc:	The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.
AgencyTankId:	Not reported
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported
Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Current Owner
Violation Desc:	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.
AgencyTankId:	Not reported
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported
Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	E6R1
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Spill Prevention Device Not Functional
Violation Desc:	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.
AgencyTankId:	E6R1
Compliance Date:	10/02/2014
Compliance Method:	Documentation
Compliance Notes:	Site pumped out and cleaned sumps. Multiple photos taken, see email

Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	D5R1
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Monthly Records
Violation Desc:	Monthly records of interstitial monitoring records were not available.
AgencyTankId:	D5R1
Compliance Date:	06/20/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met for tanks, interstice is being monitored but still need sensors installed for piping before close this violation Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form

Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Dispenser Sump Free of Liquid
Violation Desc:	The dispenser sump contains liquid.
AgencyTankId:	Not reported
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14

Name:	CHUCKS AUTOMOTIVE LLC
Address:	653 BURNSIDE AVE
Address 2:	Not reported
City,State,Zip:	EAST HARTFORD 06108
Facility ID:	43-5508
Substance:	Gasoline
Last Use Date:	08/01/1988
Tank ID:	C4
Closure Status:	Tank was Removed From Ground
Compartment ID:	a
Tank Status:	Permanently Closed
Secondary Material:	Not reported
Tank Material:	Asphalt Coated or Bare Steel
Capacity:	4000
Install Date:	07/01/1975
Overfill Installed:	Not reported
Pipe Material:	Bare Steel
Pipe Mode Description:	Not reported
Spill Installed:	Not reported
Latitude:	41.779012
Longitude:	-72.611473
Tank Latitude:	41.779012
Tank Longitude:	-72.611473

Contact:

Facility ID:	43-5508
Owner Name:	Branden Naraine
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Class B Operator
Contact Name:	.
Contact Title:	Not reported
Contact Email:	Not reported

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Facility ID:	43-5508
Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Billing Contact
Contact Name:	Branden Naraine
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5508
Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Owner
Contact Name:	Branden Naraine
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5508
Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Registrant
Contact Name:	Branden Naraine
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5508
Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Operator
Contact Name:	Branden Naraine
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5508
Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Primary Contact
Contact Name:	Branden Naraine

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Contact Title:	Not reported
Contact Email:	Not reported
Facility ID:	43-5508
Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Property Owner
Contact Name:	Branden Naraine
Contact Title:	Not reported
Contact Email:	Not reported
Facility ID:	43-5508
Owner Name:	Branden Naraine
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Class A Operator
Contact Name:	.
Contact Title:	Not reported
Contact Email:	Not reported

compilance:

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failure to submitt an annual notification and/or annual fee
Violation Desc:	The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).
AgencyTankId:	Not reported
Compliance Date:	04/18/2023
Compliance Method:	Warning Only
Compliance Notes:	Not reported
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Sensor Installed at Tank Sump
Violation Desc:	The division inspector has determined that a piping sump sensor was not installed at the tank sump.
AgencyTankId:	E6R1
Compliance Date:	06/20/2017

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Compliance Method:	Test Results
Compliance Notes:	Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test Records
Violation Desc:	The passing annual line leak detector test documentation was not maintained.
AgencyTankId:	D5R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Sump Free of Liquid
Violation Desc:	The DepartmentG s inspector has determined that there is liquid or evidence of liquid accumulating in sump.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test Records
Violation Desc:	The passing annual line leak detector test documentation was not maintained.

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

AgencyTankId:	E6R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Failure to perform monthly visual inspections
Violation Desc:	The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.
AgencyTankId:	Not reported
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Operator retraining due to non-comliance
Violation Desc:	Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program.
AgencyTankId:	Not reported
Compliance Date:	06/20/2017
Compliance Method:	Documentation
Compliance Notes:	fax recd 6/20/17 included monthly inspection report (6/17 still needs sumps sensors) retraining certificates Gregory Tischofer A/B 6/4/17 API, Charles Tischofer Class C 6/4/17 API
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test
Violation Desc:	The passing annual line leak detector test had not been performed.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping
Violation Desc:	Annual Tightness Test for Pressurized Piping was not performed.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test
Violation Desc:	The passing annual line leak detector test had not been performed.
AgencyTankId:	E6R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Monthly Records
Violation Desc:	Monthly records of interstitial monitoring records were not available.
AgencyTankId:	E6R1
Compliance Date:	06/20/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met for tanks, interstice is being monitored but still need sensors installed for piping before close this violation Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Spill Prevention Device Not Functional
Violation Desc:	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.
AgencyTankId:	D5R1
Compliance Date:	10/02/2014
Compliance Method:	Documentation
Compliance Notes:	Site pumped out and cleaned sumps. Multiple photos taken, see email

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Sensor Installed at Tank Sump
Violation Desc:	The division inspector has determined that a piping sump sensor was not installed at the tank sump.
AgencyTankId:	D5R1
Compliance Date:	06/20/2017
Compliance Method:	Test Results
Compliance Notes:	Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form

Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping Records
Violation Desc:	The annual tightness test documentation was not available for the piping.
AgencyTankId:	D5R1
Compliance Date:	10/02/2014

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Updated UST notification information required
Violation Desc:	The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.
AgencyTankId:	Not reported
Compliance Date:	05/03/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/3/23 Received updated ezFile notifcation with active insurance & AB operators
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing hydrostatic testing for regular, super & diesel tanks & dispenser sumps dated 4/21/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Release Detection Documentation Available
Violation Desc:	The release detection documentation was not available.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing ATG functionality testing, dated 3/13/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Release Detection Documentation Available
Violation Desc:	The release detection documentation was not available.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing ATG functionality testing, dated 3/13/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failure to Test Repaired Spill Prevention Equipment
Violation Desc:	Failed to test repaired spill prevention equipment (e.g., spill bucket) within 30 days of the repair in accordance with manufacturer specifications or a nationally recognized code of practice.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel tanks dated 4/21/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failed to Maintain Records of Tests for Secondary Containment
Violation Desc:	Owner or Operator failed to maintain records of testing results required to demonstrate compliance with secondary containment systems.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic testing for regular, super & diesel sumps dated 4/21/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Spill Bucket Testing Schedule

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Violation Desc:	Failed to conduct requisite testing of spill buckets according to initial and 3-year schedule.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel spill buckets dated 4/21/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Spill Bucket Testing Schedule
Violation Desc:	Failed to conduct requisite testing of spill buckets according to initial and 3-year schedule.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel spill buckets dated 4/21/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failed to Maintain Records of Tests for Secondary Containment
Violation Desc:	Owner or Operator failed to maintain records of testing results required to demonstrate compliance with secondary containment systems.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic testing for regular, super & diesel sumps dated 4/21/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failure to Test Repaired Spill Prevention Equipment
Violation Desc:	Failed to test repaired spill prevention equipment (e.g., spill bucket) within 30 days of the repair in accordance with manufacturer specifications or a nationally recognized code of practice.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel tanks dated 4/21/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing hydrostatic testing for regular, super & diesel tanks & dispenser sumps dated 4/21/23
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping
Violation Desc:	Annual Tightness Test for Pressurized Piping was not performed.
AgencyTankId:	E6R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Primary Overfill Identified
Violation Desc:	The primary overfill device was not identified.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met- ball float Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17:

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form

Inspection Date: 05/31/2017
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true
Include in Red Tag: false
Field NOV ID: NOVUST-MC217-0025
Warning Letter ID: Not reported
Violation Name: Primary Overfill Identified
Violation Desc: The primary overfill device was not identified.
AgencyTankId: E6R1
Compliance Date: 06/02/2017
Compliance Method: Documentation
Compliance Notes: Red tag hearing 6/2/17 per PW this violation has been met- ball float

Inspection Date: 06/02/2014
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true
Include in Red Tag: false
Field NOV ID: NOVUST-MC214-0052
Warning Letter ID: Not reported
Violation Name: Annual Tightness Test for Pressurized Piping Records
Violation Desc: The annual tightness test documentation was not available for the piping.
AgencyTankId: E6R1
Compliance Date: 10/02/2014
Compliance Method: Test Results
Compliance Notes: Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14

Inspection Date: 03/11/2025
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true
Include in Red Tag: false
Field NOV ID: NOVUST-BS25-0019
Warning Letter ID: Not reported
Violation Name: Updated UST notification information required
Violation Desc: The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.
AgencyTankId: Not reported
Compliance Date: Not reported
Compliance Method: Not reported
Compliance Notes: Not reported

Inspection Date: 03/11/2025
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Current Owner
Violation Desc:	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.
AgencyTankId:	Not reported
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported
Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	E6R1
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Spill Prevention Device Not Functional
Violation Desc:	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.
AgencyTankId:	E6R1
Compliance Date:	10/02/2014
Compliance Method:	Documentation
Compliance Notes:	Site pumped out and cleaned sumps. Multiple photos taken, see email
Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	D5R1

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Monthly Records
Violation Desc:	Monthly records of interstitial monitoring records were not available.
AgencyTankId:	D5R1
Compliance Date:	06/20/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met for tanks, interstice is being monitored but still need sensors installed for piping before close this violation Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Dispenser Sump Free of Liquid
Violation Desc:	The dispenser sump contains liquid.
AgencyTankId:	Not reported
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14
Name:	CHUCKS AUTOMOTIVE LLC
Address:	653 BURNSIDE AVE
Address 2:	Not reported
City,State,Zip:	EAST HARTFORD 06108
Facility ID:	43-5508
Substance:	Gasoline
Last Use Date:	Not reported
Tank ID:	D5R1
Closure Status:	Not reported

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Compartment ID:	Not reported
Tank Status:	Currently In Use
Secondary Material:	Double Walled
Tank Material:	Fiberglass Reinforced Plastic
Capacity:	8000
Install Date:	10/01/2009
Overfill Installed:	Audible Alarm
Pipe Material:	Rigid Fiberglass Reinforced Plastic
Pipe Mode Description:	Containment Sumps @ Tanks,Double Walled,Metallic fittings isolated from soil and water
Spill Installed:	Spill Bucket
Latitude:	41.779012
Longitude:	-72.611473
Tank Latitude:	41.779012
Tank Longitude:	-72.611473

Contact:

Facility ID:	43-5508
Owner Name:	Branden Naraine
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Class B Operator
Contact Name:	.
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5508
Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Billing Contact
Contact Name:	Branden Naraine
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5508
Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Owner
Contact Name:	Branden Naraine
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5508
Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Registrant
Contact Name: Branden Naraine
Contact Title: Not reported
Contact Email: Not reported

Facility ID: 43-5508
Owner Name: CB AUTOMOTIVE, LLC
Owner Address: 653 Burnside Ave
Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Operator
Contact Name: Branden Naraine
Contact Title: Not reported
Contact Email: Not reported

Facility ID: 43-5508
Owner Name: CB AUTOMOTIVE, LLC
Owner Address: 653 Burnside Ave
Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Primary Contact
Contact Name: Branden Naraine
Contact Title: Not reported
Contact Email: Not reported

Facility ID: 43-5508
Owner Name: CB AUTOMOTIVE, LLC
Owner Address: 653 Burnside Ave
Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Property Owner
Contact Name: Branden Naraine
Contact Title: Not reported
Contact Email: Not reported

Facility ID: 43-5508
Owner Name: Branden Naraine
Owner Address: 653 Burnside Ave
Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Class A Operator
Contact Name: .
Contact Title: Not reported
Contact Email: Not reported

compilance:
Inspection Date: 04/18/2023

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failure to submitt an annual notification and/or annual fee
Violation Desc:	The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).
AgencyTankId:	Not reported
Compliance Date:	04/18/2023
Compliance Method:	Warning Only
Compliance Notes:	Not reported

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Sensor Installed at Tank Sump
Violation Desc:	The division inspector has determined that a piping sump sensor was not installed at the tank sump.
AgencyTankId:	E6R1
Compliance Date:	06/20/2017
Compliance Method:	Test Results
Compliance Notes:	Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form

Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test Records
Violation Desc:	The passing annual line leak detector test documentation was not maintained.
AgencyTankId:	D5R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Sump Free of Liquid
Violation Desc:	The DepartmentG s inspector has determined that there is liquid or evidence of liquid accumulating in sump.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met

Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test Records
Violation Desc:	The passing annual line leak detector test documentation was not maintained.
AgencyTankId:	E6R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Failure to perform monthly visual inspections
Violation Desc:	The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.
AgencyTankId:	Not reported
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Warning Letter ID:	Not reported
Violation Name:	Operator retraining due to non-comliance
Violation Desc:	Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program.
AgencyTankId:	Not reported
Compliance Date:	06/20/2017
Compliance Method:	Documentation
Compliance Notes:	fax recd 6/20/17 included monthly inspection report (6/17 still needs sumps sensors) retraining certificates Gregory Tischofer A/B 6/4/17 API, Charles Tischofer Class C 6/4/17 API
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test
Violation Desc:	The passing annual line leak detector test had not been performed.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping
Violation Desc:	Annual Tightness Test for Pressurized Piping was not performed.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test
Violation Desc:	The passing annual line leak detector test had not been performed.
AgencyTankId:	E6R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Monthly Records
Violation Desc:	Monthly records of interstitial monitoring records were not available.
AgencyTankId:	E6R1
Compliance Date:	06/20/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met for tanks, interstice is being monitored but still need sensors installed for piping before close this violation Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form

Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Spill Prevention Device Not Functional
Violation Desc:	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.
AgencyTankId:	D5R1
Compliance Date:	10/02/2014
Compliance Method:	Documentation
Compliance Notes:	Site pumped out and cleaned sumps. Multiple photos taken, see email

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Sensor Installed at Tank Sump
Violation Desc:	The division inspector has determined that a piping sump sensor was not installed at the tank sump.
AgencyTankId:	D5R1

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Compliance Date:	06/20/2017
Compliance Method:	Test Results
Compliance Notes:	Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping Records
Violation Desc:	The annual tightness test documentation was not available for the piping.
AgencyTankId:	D5R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Updated UST notification information required
Violation Desc:	The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.
AgencyTankId:	Not reported
Compliance Date:	05/03/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/3/23 Received updated ezFile notifcation with active insurance & AB operators
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Record Keeping for Spill Prevention Equipment

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing hydrostatic testing for regular, super & diesel tanks & dispenser sumps dated 4/21/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Release Detection Documentation Available
Violation Desc:	The release detection documentation was not available.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing ATG functionality testing, dated 3/13/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Release Detection Documentation Available
Violation Desc:	The release detection documentation was not available.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing ATG functionality testing, dated 3/13/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failure to Test Repaired Spill Prevention Equipment
Violation Desc:	Failed to test repaired spill prevention equipment (e.g., spill bucket) within 30 days of the repair in accordance with manufacturer specifications or a nationally recognized code of practice.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel tanks dated 4/21/23

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failed to Maintain Records of Tests for Secondary Containment
Violation Desc:	Owner or Operator failed to maintain records of testing results required to demonstrate compliance with secondary containment systems.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic testing for regular, super & diesel sumps dated 4/21/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Spill Bucket Testing Schedule
Violation Desc:	Failed to conduct requisite testing of spill buckets according to initial and 3-year schedule.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel spill buckets dated 4/21/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Spill Bucket Testing Schedule
Violation Desc:	Failed to conduct requisite testing of spill buckets according to initial and 3-year schedule.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel spill buckets dated 4/21/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failed to Maintain Records of Tests for Secondary Containment
Violation Desc:	Owner or Operator failed to maintain records of testing results required to demonstrate compliance with secondary containment systems.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic testing for regular, super & diesel sumps dated 4/21/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failure to Test Repaired Spill Prevention Equipment
Violation Desc:	Failed to test repaired spill prevention equipment (e.g., spill bucket) within 30 days of the repair in accordance with manufacturer specifications or a nationally recognized code of practice.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel tanks dated 4/21/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing hydrostatic testing for regular, super & diesel tanks & dispenser sumps dated 4/21/23
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping
Violation Desc:	Annual Tightness Test for Pressurized Piping was not performed.
AgencyTankId:	E6R1

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Primary Overfill Identified
Violation Desc:	The primary overfill device was not identified.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met- ball float Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Primary Overfill Identified
Violation Desc:	The primary overfill device was not identified.
AgencyTankId:	E6R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met- ball float
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping Records
Violation Desc:	The annual tightness test documentation was not available for the piping.
AgencyTankId:	E6R1

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14
Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Updated UST notification information required
Violation Desc:	The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.
AgencyTankId:	Not reported
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported
Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Current Owner
Violation Desc:	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.
AgencyTankId:	Not reported
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported
Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	E6R1
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Spill Prevention Device Not Functional
Violation Desc:	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.
AgencyTankId:	E6R1
Compliance Date:	10/02/2014
Compliance Method:	Documentation
Compliance Notes:	Site pumped out and cleaned sumps. Multiple photos taken, see email
Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	D5R1
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Monthly Records
Violation Desc:	Monthly records of interstitial monitoring records were not available.
AgencyTankId:	D5R1
Compliance Date:	06/20/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met for tanks, interstice is being monitored but still need sensors installed for piping before close this violation Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Dispenser Sump Free of Liquid
Violation Desc:	The dispenser sump contains liquid.
AgencyTankId:	Not reported
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14

Name:	CHUCKS AUTOMOTIVE LLC
Address:	653 BURNSIDE AVE
Address 2:	Not reported
City,State,Zip:	EAST HARTFORD 06108
Facility ID:	43-5508
Substance:	Diesel
Last Use Date:	Not reported
Tank ID:	E6R1
Closure Status:	Not reported
Compartment ID:	a
Tank Status:	Currently In Use
Secondary Material:	Double Walled
Tank Material:	Fiberglass Reinforced Plastic
Capacity:	4000
Install Date:	10/01/2009
Overfill Installed:	Audible Alarm
Pipe Material:	Rigid Fiberglass Reinforced Plastic
Pipe Mode Description:	Containment Sumps @ Tanks,Double Walled,Metallic fittings isolated from soil and water
Spill Installed:	Spill Bucket
Latitude:	41.779012
Longitude:	-72.611473
Tank Latitude:	41.779012
Tank Longitude:	-72.611473

Contact:

Facility ID:	43-5508
Owner Name:	Branden Naraine
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Class B Operator
Contact Name:	.
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5508
Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Billing Contact
Contact Name: Branden Naraine
Contact Title: Not reported
Contact Email: Not reported

Facility ID: 43-5508
Owner Name: CB AUTOMOTIVE, LLC
Owner Address: 653 Burnside Ave
Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Owner
Contact Name: Branden Naraine
Contact Title: Not reported
Contact Email: Not reported

Facility ID: 43-5508
Owner Name: CB AUTOMOTIVE, LLC
Owner Address: 653 Burnside Ave
Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Registrant
Contact Name: Branden Naraine
Contact Title: Not reported
Contact Email: Not reported

Facility ID: 43-5508
Owner Name: CB AUTOMOTIVE, LLC
Owner Address: 653 Burnside Ave
Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Operator
Contact Name: Branden Naraine
Contact Title: Not reported
Contact Email: Not reported

Facility ID: 43-5508
Owner Name: CB AUTOMOTIVE, LLC
Owner Address: 653 Burnside Ave
Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Primary Contact
Contact Name: Branden Naraine
Contact Title: Not reported
Contact Email: Not reported

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Facility ID:	43-5508
Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Property Owner
Contact Name:	Branden Naraine
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5508
Owner Name:	Branden Naraine
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Class A Operator
Contact Name:	.
Contact Title:	Not reported
Contact Email:	Not reported

compilance:

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failure to submitt an annual notification and/or annual fee
Violation Desc:	The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).
AgencyTankId:	Not reported
Compliance Date:	04/18/2023
Compliance Method:	Warning Only
Compliance Notes:	Not reported

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Sensor Installed at Tank Sump
Violation Desc:	The division inspector has determined that a piping sump sensor was not installed at the tank sump.
AgencyTankId:	E6R1
Compliance Date:	06/20/2017
Compliance Method:	Test Results
Compliance Notes:	Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form

Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test Records
Violation Desc:	The passing annual line leak detector test documentation was not maintained.
AgencyTankId:	D5R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Sump Free of Liquid
Violation Desc:	The DepartmentG s inspector has determined that there is liquid or evidence of liquid accumulating in sump.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met

Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test Records
Violation Desc:	The passing annual line leak detector test documentation was not maintained.
AgencyTankId:	E6R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Failure to perform monthly visual inspections
Violation Desc:	The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.
AgencyTankId:	Not reported
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Operator retraining due to non-comliance
Violation Desc:	Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program.
AgencyTankId:	Not reported
Compliance Date:	06/20/2017
Compliance Method:	Documentation
Compliance Notes:	fax recd 6/20/17 included monthly inspection report (6/17 still needs sumps sensors) retraining certificates Gregory Tischofer A/B 6/4/17 API, Charles Tischofer Class C 6/4/17 API
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test
Violation Desc:	The passing annual line leak detector test had not been performed.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping
Violation Desc:	Annual Tightness Test for Pressurized Piping was not performed.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test
Violation Desc:	The passing annual line leak detector test had not been performed.
AgencyTankId:	E6R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Monthly Records
Violation Desc:	Monthly records of interstitial monitoring records were not available.
AgencyTankId:	E6R1
Compliance Date:	06/20/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met for tanks, interstice is being monitored but still need sensors installed for piping before close this violation Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form

Inspection Date:	06/02/2014
UST Site ID Number:	43-5508

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Spill Prevention Device Not Functional
Violation Desc:	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.
AgencyTankId:	D5R1
Compliance Date:	10/02/2014
Compliance Method:	Documentation
Compliance Notes:	Site pumped out and cleaned sumps. Multiple photos taken, see email
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Sensor Installed at Tank Sump
Violation Desc:	The division inspector has determined that a piping sump sensor was not installed at the tank sump.
AgencyTankId:	D5R1
Compliance Date:	06/20/2017
Compliance Method:	Test Results
Compliance Notes:	Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping Records
Violation Desc:	The annual tightness test documentation was not available for the piping.
AgencyTankId:	D5R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

three lines and all passed 6/10/14

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Updated UST notification information required
Violation Desc:	The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.
AgencyTankId:	Not reported
Compliance Date:	05/03/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/3/23 Received updated ezFile notifcation with active insurance & AB operators

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing hydrostatic testing for regular, super & diesel tanks & dispenser sumps dated 4/21/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Release Detection Documentation Available
Violation Desc:	The release detection documentation was not available.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing ATG functionality testing, dated 3/13/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Release Detection Documentation Available
Violation Desc:	The release detection documentation was not available.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing ATG functionality testing, dated 3/13/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failure to Test Repaired Spill Prevention Equipment
Violation Desc:	Failed to test repaired spill prevention equipment (e.g., spill bucket) within 30 days of the repair in accordance with manufacturer specifications or a nationally recognized code of practice.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel tanks dated 4/21/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failed to Maintain Records of Tests for Secondary Containment
Violation Desc:	Owner or Operator failed to maintain records of testing results required to demonstrate compliance with secondary containment systems.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic testing for regular, super & diesel sumps dated 4/21/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Spill Bucket Testing Schedule
Violation Desc:	Failed to conduct requisite testing of spill buckets according to initial and 3-year schedule.

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel spill buckets dated 4/21/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Spill Bucket Testing Schedule
Violation Desc:	Failed to conduct requisite testing of spill buckets according to initial and 3-year schedule.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel spill buckets dated 4/21/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failed to Maintain Records of Tests for Secondary Containment
Violation Desc:	Owner or Operator failed to maintain records of testing results required to demonstrate compliance with secondary containment systems.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic testing for regular, super & diesel sumps dated 4/21/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failure to Test Repaired Spill Prevention Equipment
Violation Desc:	Failed to test repaired spill prevention equipment (e.g., spill bucket) within 30 days of the repair in accordance with manufacturer specifications or a nationally recognized code of practice.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel tanks dated 4/21/23

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing hydrostatic testing for regular, super & diesel tanks & dispenser sumps dated 4/21/23

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping
Violation Desc:	Annual Tightness Test for Pressurized Piping was not performed.
AgencyTankId:	E6R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Primary Overfill Identified
Violation Desc:	The primary overfill device was not identified.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met- ball float Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Primary Overfill Identified
Violation Desc:	The primary overfill device was not identified.
AgencyTankId:	E6R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met- ball float

Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping Records
Violation Desc:	The annual tightness test documentation was not available for the piping.
AgencyTankId:	E6R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14

Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Updated UST notification information required
Violation Desc:	The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.
AgencyTankId:	Not reported
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported

Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Current Owner

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Violation Desc:	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.
AgencyTankId:	Not reported
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported
Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	E6R1
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Spill Prevention Device Not Functional
Violation Desc:	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.
AgencyTankId:	E6R1
Compliance Date:	10/02/2014
Compliance Method:	Documentation
Compliance Notes:	Site pumped out and cleaned sumps. Multiple photos taken, see email
Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	D5R1
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Monthly Records
Violation Desc:	Monthly records of interstitial monitoring records were not available.
AgencyTankId:	D5R1
Compliance Date:	06/20/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met for tanks, interstice is being monitored but still need sensors installed for piping before close this violation Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form

Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Dispenser Sump Free of Liquid
Violation Desc:	The dispenser sump contains liquid.
AgencyTankId:	Not reported
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14

Name:	CHUCKS AUTOMOTIVE LLC
Address:	653 BURNSIDE AVE
Address 2:	Not reported
City,State,Zip:	EAST HARTFORD 06108
Facility ID:	43-5508
Substance:	Gasoline
Last Use Date:	Not reported
Tank ID:	E6R1
Closure Status:	Not reported
Compartment ID:	b
Tank Status:	Currently In Use
Secondary Material:	Double Walled
Tank Material:	Fiberglass Reinforced Plastic

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Capacity:	4000
Install Date:	10/01/2009
Overfill Installed:	Audible Alarm
Pipe Material:	Flexible Plastic
Pipe Mode Description:	Containment Sumps @ Dispensers,Containment Sumps @ Tanks,Double Walled
Spill Installed:	Spill Bucket
Latitude:	41.779012
Longitude:	-72.611473
Tank Latitude:	41.779012
Tank Longitude:	-72.611473

Contact:

Facility ID:	43-5508
Owner Name:	Branden Naraine
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Class B Operator
Contact Name:	.
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5508
Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Billing Contact
Contact Name:	Branden Naraine
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5508
Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Owner
Contact Name:	Branden Naraine
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5508
Owner Name:	CB AUTOMOTIVE, LLC
Owner Address:	653 Burnside Ave
Owner Address 2:	Not reported
Owner Phone:	(860) 289-0081
Owner Phone Ext:	Not reported
Owner City/State/Zip:	East Hartford, CT
Affiliation Type:	Registrant
Contact Name:	Branden Naraine
Contact Title:	Not reported

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Contact Email: Not reported

Facility ID: 43-5508
Owner Name: CB AUTOMOTIVE, LLC
Owner Address: 653 Burnside Ave
Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Operator
Contact Name: Branden Naraine
Contact Title: Not reported
Contact Email: Not reported

Facility ID: 43-5508
Owner Name: CB AUTOMOTIVE, LLC
Owner Address: 653 Burnside Ave
Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Primary Contact
Contact Name: Branden Naraine
Contact Title: Not reported
Contact Email: Not reported

Facility ID: 43-5508
Owner Name: CB AUTOMOTIVE, LLC
Owner Address: 653 Burnside Ave
Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Property Owner
Contact Name: Branden Naraine
Contact Title: Not reported
Contact Email: Not reported

Facility ID: 43-5508
Owner Name: Branden Naraine
Owner Address: 653 Burnside Ave
Owner Address 2: Not reported
Owner Phone: (860) 289-0081
Owner Phone Ext: Not reported
Owner City/State/Zip: East Hartford, CT
Affiliation Type: Class A Operator
Contact Name: .
Contact Title: Not reported
Contact Email: Not reported

compilance:
Inspection Date: 04/18/2023
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true
Include in Red Tag: false

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failure to submitt an annual notification and/or annual fee
Violation Desc:	The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).
AgencyTankId:	Not reported
Compliance Date:	04/18/2023
Compliance Method:	Warning Only
Compliance Notes:	Not reported
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Sensor Installed at Tank Sump
Violation Desc:	The division inspector has determined that a piping sump sensor was not installed at the tank sump.
AgencyTankId:	E6R1
Compliance Date:	06/20/2017
Compliance Method:	Test Results
Compliance Notes:	Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test Records
Violation Desc:	The passing annual line leak detector test documentation was not maintained.
AgencyTankId:	D5R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Sump Free of Liquid
Violation Desc:	The DepartmentG s inspector has determined that there is liquid or evidence of liquid accumulating in sump.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met

Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual LLD Test Records
Violation Desc:	The passing annual line leak detector test documentation was not maintained.
AgencyTankId:	E6R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Failure to perform monthly visual inspections
Violation Desc:	The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.
AgencyTankId:	Not reported
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met

Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Operator retraining due to non-comliance
Violation Desc:	Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program.
AgencyTankId: Not reported
Compliance Date: 06/20/2017
Compliance Method: Documentation
Compliance Notes: fax recd 6/20/17 included monthly inspection report (6/17 still needs sumps sensors) retraining certificates Gregory Tischofer A/B 6/4/17 API, Charles Tischofer Class C 6/4/17 API

Inspection Date: 05/31/2017
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true
Include in Red Tag: false
Field NOV ID: NOVUST-MC217-0025
Warning Letter ID: Not reported
Violation Name: Annual LLD Test
Violation Desc: The passing annual line leak detector test had not been performed.
AgencyTankId: D5R1
Compliance Date: 06/02/2017
Compliance Method: Documentation
Compliance Notes: Red tag hearing 6/2/17 per PW this violation has been met

Inspection Date: 05/31/2017
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true
Include in Red Tag: false
Field NOV ID: NOVUST-MC217-0025
Warning Letter ID: Not reported
Violation Name: Annual Tightness Test for Pressurized Piping
Violation Desc: Annual Tightness Test for Pressurized Piping was not performed.
AgencyTankId: D5R1
Compliance Date: 06/02/2017
Compliance Method: Documentation
Compliance Notes: Red tag hearing 6/2/17 per PW this violation has been met

Inspection Date: 05/31/2017
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE
Facility City: EAST HARTFORD
Include in FNOV or Warning: true
Include in Red Tag: false
Field NOV ID: NOVUST-MC217-0025
Warning Letter ID: Not reported
Violation Name: Annual LLD Test
Violation Desc: The passing annual line leak detector test had not been performed.
AgencyTankId: E6R1
Compliance Date: 06/02/2017
Compliance Method: Documentation
Compliance Notes: Red tag hearing 6/2/17 per PW this violation has been met

Inspection Date: 05/31/2017
UST Site ID Number: 43-5508
Facility Addr: 653 BURNSIDE AVE

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Monthly Records
Violation Desc:	Monthly records of interstitial monitoring records were not available.
AgencyTankId:	E6R1
Compliance Date:	06/20/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met for tanks, interstice is being monitored but still need sensors installed for piping before close this violation Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Spill Prevention Device Not Functional
Violation Desc:	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.
AgencyTankId:	D5R1
Compliance Date:	10/02/2014
Compliance Method:	Documentation
Compliance Notes:	Site pumped out and cleaned sumps. Multiple photos taken, see email
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Sensor Installed at Tank Sump
Violation Desc:	The division inspector has determined that a piping sump sensor was not installed at the tank sump.
AgencyTankId:	D5R1
Compliance Date:	06/20/2017
Compliance Method:	Test Results
Compliance Notes:	Note: fax recd 6/20/17 with signed CS, includes red tag closure info

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form

Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping Records
Violation Desc:	The annual tightness test documentation was not available for the piping.
AgencyTankId:	D5R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Updated UST notification information required
Violation Desc:	The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.
AgencyTankId:	Not reported
Compliance Date:	05/03/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/3/23 Received updated ezFile notifcation with active insurance & AB operators

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	E6R1

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing hydrostatic testing for regular, super & diesel tanks & dispenser sumps dated 4/21/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Release Detection Documentation Available
Violation Desc:	The release detection documentation was not available.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing ATG functionality testing, dated 3/13/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Release Detection Documentation Available
Violation Desc:	The release detection documentation was not available.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing ATG functionality testing, dated 3/13/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failure to Test Repaired Spill Prevention Equipment
Violation Desc:	Failed to test repaired spill prevention equipment (e.g., spill bucket) within 30 days of the repair in accordance with manufacturer specifications or a nationally recognized code of practice.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel tanks dated 4/21/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failed to Maintain Records of Tests for Secondary Containment
Violation Desc:	Owner or Operator failed to maintain records of testing results required to demonstrate compliance with secondary containment systems.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic testing for regular, super & diesel sumps dated 4/21/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Spill Bucket Testing Schedule
Violation Desc:	Failed to conduct requisite testing of spill buckets according to initial and 3-year schedule.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel spill buckets dated 4/21/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Spill Bucket Testing Schedule
Violation Desc:	Failed to conduct requisite testing of spill buckets according to initial and 3-year schedule.
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel spill buckets dated 4/21/23

Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Violation Name:	Failed to Maintain Records of Tests for Secondary Containment
Violation Desc:	Owner or Operator failed to maintain records of testing results required to demonstrate compliance with secondary containment systems.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic testing for regular, super & diesel sumps dated 4/21/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Failure to Test Repaired Spill Prevention Equipment
Violation Desc:	Failed to test repaired spill prevention equipment (e.g., spill bucket) within 30 days of the repair in accordance with manufacturer specifications or a nationally recognized code of practice.
AgencyTankId:	E6R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received passing hydrostatic tests for regular, super & diesel tanks dated 4/21/23
Inspection Date:	04/18/2023
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC223-0056
Warning Letter ID:	WLUST-MC223-0023
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	D5R1
Compliance Date:	05/04/2023
Compliance Method:	Documentation
Compliance Notes:	ER 5/4/23 Received documentation of passing hydrostatic testing for regular, super & diesel tanks & dispenser sumps dated 4/21/23
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping
Violation Desc:	Annual Tightness Test for Pressurized Piping was not performed.
AgencyTankId:	E6R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Primary Overfill Identified
Violation Desc:	The primary overfill device was not identified.
AgencyTankId:	D5R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met- ball float Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Primary Overfill Identified
Violation Desc:	The primary overfill device was not identified.
AgencyTankId:	E6R1
Compliance Date:	06/02/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met- ball float
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Annual Tightness Test for Pressurized Piping Records
Violation Desc:	The annual tightness test documentation was not available for the piping.
AgencyTankId:	E6R1
Compliance Date:	10/02/2014
Compliance Method:	Test Results

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14
Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Updated UST notification information required
Violation Desc:	The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.
AgencyTankId:	Not reported
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported
Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Current Owner
Violation Desc:	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.
AgencyTankId:	Not reported
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported
Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	E6R1
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Spill Prevention Device Not Functional
Violation Desc:	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.
AgencyTankId:	E6R1
Compliance Date:	10/02/2014
Compliance Method:	Documentation
Compliance Notes:	Site pumped out and cleaned sumps. Multiple photos taken, see email
Inspection Date:	03/11/2025
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-BS25-0019
Warning Letter ID:	Not reported
Violation Name:	Record Keeping for Spill Prevention Equipment
Violation Desc:	Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4).
AgencyTankId:	D5R1
Compliance Date:	Not reported
Compliance Method:	Not reported
Compliance Notes:	Not reported
Inspection Date:	05/31/2017
UST Site ID Number:	43-5508
Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	false
Field NOV ID:	NOVUST-MC217-0025
Warning Letter ID:	Not reported
Violation Name:	Monthly Records
Violation Desc:	Monthly records of interstitial monitoring records were not available.
AgencyTankId:	D5R1
Compliance Date:	06/20/2017
Compliance Method:	Documentation
Compliance Notes:	Red tag hearing 6/2/17 per PW this violation has been met for tanks, interstice is being monitored but still need sensors installed for piping before close this violation Note: fax recd 6/20/17 with signed CS, includes red tag closure info etc. Included: ine tightness testing & LLD testing passed Armor Pump Service LLC, 6/2/17, interstitial monitoring available (unreadable fax info- needs to be resubmitted) Ball floats primary overfill, A/B & C Operator retraining forms, monthly inspection form 6/17 & sump sensor estimate. 6/20/17 Still need sumps sensor installation information and readable interstitial monitoring test results recd email dated 6/20/17 containing passing 0.2 test results & sensor status report 6/17/17: inter / STP Sump & Disp Pan OK - can not print attachment states I need a different adobe package- forwarded to Carlos to see if he can print form
Inspection Date:	06/02/2014
UST Site ID Number:	43-5508

CHUCKS AUTOMOTIVE LLC (Continued) **U002174425**

Facility Addr:	653 BURNSIDE AVE
Facility City:	EAST HARTFORD
Include in FNOV or Warning:	true
Include in Red Tag:	true
Field NOV ID:	NOVUST-MC214-0052
Warning Letter ID:	Not reported
Violation Name:	Dispenser Sump Free of Liquid
Violation Desc:	The dispenser sump contains liquid.
AgencyTankId:	Not reported
Compliance Date:	10/02/2014
Compliance Method:	Test Results
Compliance Notes:	Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14

D26 **CHARLIES TIRE** **CT MANIFEST** **S109737686**
West **653 BURNSIDE AVE** **N/A**
1/8-1/4 **EAST HARTFORD, CT 06108**
0.205 mi.
1085 ft. **Site 3 of 5 in cluster D**

Relative: **Lower**
Actual: **52 ft.**

CT MANIFEST:

Name:	CHARLIES TIRE
Address:	653 BURNSIDE AVE
City,State,Zip:	EAST HARTFORD, CT 06108
Phone:	Not reported
Country:	Not reported
Manifest ID:	CTC0167041
EPA ID:	CTP000007998

Hazardous Waste Manifest:

Year:	1988
Manifest:	CTC0167041
EPA ID:	CTP000007998
Generator Mailing Address:	653 BURNSIDE AVE
Generator City,State,Zip:	EAST HARTFORD, CT 06108
Discrepancies:	Not reported
Date Shipped:	1988-08-22
Date Received:	Not reported
Transporter 2 Date:	Not reported
TSDF EPA ID:	CTD021816889
TSDF Name:	UNITED INDUSTRIAL SERVICES INC
TSDF Address:	136 GRACEY AVE
TSDF City,State,Zip:	MERIDEN, CT 06450
TSDF Country:	USA
Transporter EPA ID:	CTD021816889
Transporter Name:	UNITED INDUSTRIAL SERVICES INC
Transporter Address:	Not reported
Transporter City,State,Zip:	CT
Transporter Country:	USA
Transporter 2 EPA ID:	Not reported
Transporter 2 Name:	Not reported
Transporter 2 Address:	Not reported
Transporter 2 City,State,Zip:	CT
Transporter 2 Country:	USA
US DOT Description:	WASTE FLAMMABLE LIQUID NOS
Number of Containers:	001

CHARLIES TIRE (Continued) **S109737686**

Container Type:	TT
Quantity/Weight/Volume:	175/G
Batch Number:	Not reported
EPA Waste Codes:	D001 - IGNITABLE WASTE
Copies:	Not reported
Alternate Facility Name:	Not reported
Alternate Facility Address:	Not reported
Alternate Facility State:	Not reported
Alternate Facility Date:	Not reported

D27 **CHUCKS AUTOMOTIVE LLC** **CT LUST** **S106731616**
West **653 BURNSIDE AVE** **CT SPILLS** **N/A**
1/8-1/4 **EAST HARTFORD, CT 06108** **CT CPCS**
0.205 mi. **CT ENF**
1085 ft. **Site 4 of 5 in cluster D**

Relative: **Lower**

Actual: **52 ft.**

LUST:

Name:	CHUCK'S AUTOMOTIVE, LLC.
Name 2:	Not reported
Address:	653 BURNSIDE AVENUE
Address 2:	Not reported
City,State,Zip:	EAST HARTFORD, CT 06108
LUST Case Id:	59401
Release Date:	Not reported
Site Case ID:	0
Substance:	Not reported
Release Source:	Not reported
Release Cause:	Not reported
Release Identified:	Not reported
Case Number:	Not reported
Release Quantity:	Not reported
Facility City Number:	43

Detail As of 06/2020:

Name:	CHUCK'S AUTOMOTIVE, LLC.
Name 2:	Not reported
Address:	653 BURNSIDE AVENUE
City,State,Zip:	EAST HARTFORD, CT 06108
Address 2:	Not reported
LUST Id:	0
UST Facility Id:	5508
LUST Case Id:	59401
Lust Status:	Pending
Processing Status:	Not reported
EPA Reportable:	False
Motor Fuel:	True
Diesel:	True
Gasoline:	True
Other:	False
Other Release:	Not reported
No Release:	False
Leak:	False
Tank:	True
Piping:	False
Overfill:	False
Removal:	True
Incident Date:	01/14/2010
Entry Date:	03/03/2010

CHUCKS AUTOMOTIVE LLC (Continued) **S106731616**

Site Case Id:	0
UST Site Id:	0
Cost Recovery Spill Case #:	0
Old SITS Number:	0
Case Log Id:	0
Monthly Report Id:	0
UST Owner Id:	796
LUST Owner Id:	Not reported
UST Event Id:	0
Contact Info:	Not reported
Contact EMail:	Not reported
Site Contact City,St,Zip:	UNKNOWN
2nd Contact:	Not reported
2nd Contact EMail:	Not reported
2nd Contact Address:	Not reported
2nd Contact City,St,Zip:	UNKNOWN
2nd Contact Address 2:	Not reported
2nd Contact City 2:	Not reported
2nd Contact Phone Number:	Not reported
2nd Contact Fax Number:	Not reported
2nd Contact Type:	Not reported
Facility City Num:	43
Site Contact:	Not reported
Site Contact Address:	Not reported
Site Contact Add 2:	Not reported
Site Contact City 2:	Not reported
Site Contact Phone:	Not reported
Site Contact Fax:	Not reported
Site Contact Type:	Not reported
Department Contact 1:	Not reported
Department Contact 2:	Not reported
Referral Source:	Not reported
Offsite Source:	False
Date Referred:	Not reported
Emergency:	False
Private Heating Fuel:	False
Commercial Heating Fuel:	False
Commercial HF < 2100 Gal.:	False
Commercial HF > 2100 Gal.:	False
Commercial HF - Size Unk:	False
No LUST Site:	False
Cost Recvry Prgm Candidate:	False
OCSRD Complete:	False
Follow Up Flag:	False
Alternate Water Supply:	False
Relocation:	False
Responsible Party:	False
Responsible EMail:	Not reported
Resp Party Name:	MLG LLC
Resp Party Address:	653 Burnside Avenue
Resp Party City,St,Zip:	East Hartford, CT 06108
Resp Party Town Number:	43
Resp Party Phone:	8602890081
Resp Party Fax:	Not reported
Resp Party Name 2:	Charles Tischofer
Resp Party Address 2:	Not reported
Resp Party Phone 2:	Not reported

CHUCKS AUTOMOTIVE LLC (Continued) **S106731616**

Investigator Id:	0
Follow Update:	Not reported
Area Lextent:	Not reported
Annual Precipitation:	Not reported
Affected Population:	Not reported
Population Setting:	Not reported
Ground Water Direction:	Not reported
Ground Water Gradient:	Not reported
Hydro Basin:	Not reported
Drastic:	Not reported
Geo Setting:	Not reported
Ground Water Classification:	GB
Receptor:	Not reported
Ground Water Flow Direction:	Not reported
Ground Water Depth:	Not reported
Areas Of Concern:	Not reported
Free Product Inches:	0
Fund Date:	Not reported
Fund Planned:	No
Fund Obligated:	No
Fund Outlayed:	No
Fund Judgment:	No
Fund Recovered:	No
Cellar Borings:	False
Install Micro Wells:	False
Ground Water Sample:	False
Soil Sample:	False
Soil Gas:	False
Site Inspect:	False
Soil Excavate:	False
Geo Probe:	False
Survey:	False
Potable Well Sample:	False
Sample MWS:	False
Ground Water Gauging:	False
Soil Venting:	False
Active:	True
NOV Action:	None
NOV Issued:	Not reported
NOV Due:	Not reported
NOV Received:	Not reported
NOV Closed:	Not reported
NOV Disc Date:	Not reported
NOV Issued Date:	Not reported
NOV Compliance Sched:	Not reported
NOV Admin Order:	Not reported
NOV Referred To Ag:	Not reported
Stop All NOV Actions:	False
Release Invest Rpt:	False
DEP App Letter 1:	False
Correct Action Plan:	False
DEP App Letter 2:	False
Rem Sys Install:	False
Rem Sys Install Date:	Not reported
Closure Date:	Not reported
Rem Sys Monitoring Rpt:	False
Qrtly Gwater Mon Rpts:	False

CHUCKS AUTOMOTIVE LLC (Continued) **S106731616**

Closure Req Rpt:	False
DEP Closure Letter:	False
Referred To:	Not reported
No Wells:	0
Lph Wells:	0
User Stamp:	Allison Forrest/AForrest
Date Stamp:	03/03/2010
Correspondence:	Not reported
Environmental Impact:	Not reported
FollowUp:	Not reported
GW Comments:	Not reported
Location Desc:	Not reported
NOV Comments:	Not reported
Release Desc:	Not reported
Running Comments:	Not reported
Work Performed:	Not reported

SPILLS:

Name:	Not reported
Address:	653 BURNSIDE AVE
City,State,Zip:	EAST HARTFORD, CT
Year of Database:	2004
Case Number:	200407143
Who Took Spill:	925
Assigned To:	No Response
Report Date:	10/14/2004
Report Time:	12:00:00 AM
Date Release:	10/14/2004
Release Time:	12:00:00 AM
Reported By:	gary zalucki
Phone:	860 2917334
Qty:	0.00 (Gallons)
Telephone:	Not reported
Representing:	zoning enforcement, town
Facility Status:	Closed
Continuous Spill:	False
Release Substance:	WASTE OIL
Emergency Measure:	strange smell in area, unknown quantity of drums on property, FORMAL REFERAL TO WEED TO FOLLOW
Discharger:	superior auto
Waterbody Affected:	Other (na)
Responsible Party:	true
Responsible Party Address:	Not reported
RP City,St,Zip:	CT
Terminated:	YES
Recovered Total:	0
Total Water:	0
Historic:	False
Waterbody:	na
User Stamp:	Not reported
Stamp Time:	2004-10-14 10:52:17
SR Inspector:	LIANO, MARK
AT Inspector:	**NO RESPONSE
Corrective Action Taken:	Not reported
Cause Info:	Not reported
Media Info:	Ground Surface

CHUCKS AUTOMOTIVE LLC (Continued) **S106731616**

Release Type:	petroleum
Incident Description:	Not reported
Cost Recovery Case?:	Not reported
DEMHS Region:	Not reported
Lat/Long:	Not reported
Company Name:	Not reported
Last Updated:	Not reported

Agency:

Agency ID:	DEP
Other Agency:	Not reported
DEP Bureau:	BUREAU OF WASTE MANAGEMENT
DEP Agency:	OIL AND CHEMICAL SPILL RESPONSE

Media:

Media ID:	Ground Surface
Other Media:	Not reported

Release Type:

Release Type:	petroleum
Other Release:	Not reported

Waterbody:

Waterbody:	Other
Other Waterbody:	na

CPCS:

Name:	Chuck'S Automotive, Llc.
Address:	653 BURNSIDE AVENUE
City,State,Zip:	EAST HARTFORD, CT
Site Type:	Not reported
Lust Status code:	Not reported
Lust Status:	Not reported
PTP Form:	Not reported
Program:	LUST
Comments:	Not reported
Site Type Definition:	Not reported
Invesigation Start:	No
Invesigation Start Date:	Not reported
Remediation Start:	No
Remediation Start Date:	Not reported
Remediation Completed:	No
ELUR:	Not reported
Date Data Updated:	01/14/2010

ENFORCEMENT:

Name:	CHUCKS AUTOMOTIVE LLC
Address:	653 BURNSIDE AVE
City,State,Zip:	EAST HARTFORD, CT 06108
Enforcement Action ID:	NOVUST-MC214-0052
Enforcement Type Code:	Field Notice of Violation
Program Id:	Not reported

CHUCKS AUTOMOTIVE LLC (Continued) **S106731616**

Enforcement Action Date:	06/02/2014
Penalty Amount:	$0.00
Sep Amt:	Not reported
Bureau Name:	Materials Management & Compliance Assurance
Program:	Underground Storage Tank Enforcement
Status:	Closed
Date of Discovery:	06/02/2014
Resolution Date:	10/02/2014
Resolution Type:	Closed-Compliance Statement not submitted
Staff:	McShea Kelly
ENF Action Comment:	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The annual tightness test documentation was not available for the piping. . The dispenser sump contains liquid.. The passing annual line leak detector test documentation was not maintained.. Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14, Site pumped out and cleaned sumps
Number Violations:	10
Civil Penalty:	Not reported
SEP Description:	Not reported
Associated EIs:	Underground Storage Tank Notification (43-5508)
Client Affiliation Type:	Respondent
Affiliation Name:	CHARLES TISCHOFER, JR
Affiliation Address Line1:	247 PALEY FARMS RD
Affiliation Address Line2:	Not reported
Affiliation City/State/Zip:	PORTLAND, CT 06480 1082
Contact Title:	Not reported
Contact Name:	Not reported
Contact EMail:	Not reported

Name:	CHUCKS AUTOMOTIVE LLC
Address:	653 BURNSIDE AVE
City,State,Zip:	EAST HARTFORD, CT 06108
Enforcement Action ID:	NOVUST-MC217-0025
Enforcement Type Code:	Field Notice of Violation
Program Id:	Not reported
Enforcement Action Date:	05/31/2017
Penalty Amount:	$0.00
Sep Amt:	Not reported
Bureau Name:	Materials Management & Compliance Assurance
Program:	Underground Storage Tank Enforcement
Status:	Closed
Date of Discovery:	05/31/2017
Resolution Date:	06/20/2017
Resolution Type:	Closed-No further action required
Staff:	McShea Kelly
ENF Action Comment:	Annual Tightness Test for Pressurized Piping was not performed. Monthly records of interstitial monitoring records were not available. The passing annual line leak detector test had not been performed. The primary overfill device was not identified.
Number Violations:	11
Civil Penalty:	Not reported
SEP Description:	Not reported
Associated EIs:	Underground Storage Tank Notification (43-5508)
Client Affiliation Type:	Respondent

CHUCKS AUTOMOTIVE LLC (Continued) **S106731616**

Affiliation Name:	CHUCK'S AUTOMOTIVE, LLC
Affiliation Address Line1:	653 Burnside Ave
Affiliation Address Line2:	Not reported
Affiliation City/State/Zip:	East Hartford, CT 06108
Contact Title:	Not reported
Contact Name:	Not reported
Contact EMail:	Not reported

Name:	CHUCKS AUTOMOTIVE LLC
Address:	653 BURNSIDE AVE
City,State,Zip:	EAST HARTFORD, CT 06108
Enforcement Action ID:	AORTWSUST 17-026
Enforcement Type Code:	Red Tag Order
Program Id:	Not reported
Enforcement Action Date:	05/31/2017
Penalty Amount:	$0.00
Sep Amt:	Not reported
Bureau Name:	Materials Management & Compliance Assurance
Program:	Underground Storage Tank Enforcement
Status:	Closed
Date of Discovery:	05/31/2017
Resolution Date:	06/19/2017
Resolution Type:	Closed-No further action required
Staff:	Wilde Philip
ENF Action Comment:	Not reported
Number Violations:	Not reported
Civil Penalty:	Not reported
SEP Description:	Not reported
Associated EIs:	Not reported
Client Affiliation Type:	Respondent
Affiliation Name:	CHARLES TISCHOFER, JR
Affiliation Address Line1:	653 BURNSIDE AVE
Affiliation Address Line2:	Not reported
Affiliation City/State/Zip:	EAST HARTFORD, CT 06108 3540
Contact Title:	Not reported
Contact Name:	CHARLES TISCHOFER JR.
Contact EMail:	TISCH4@ATT.NET

Name:	CHUCKS AUTOMOTIVE LLC
Address:	653 BURNSIDE AVE
City,State,Zip:	EAST HARTFORD, CT 06108
Enforcement Action ID:	COAR2544--10001
Enforcement Type Code:	Consent Order
Program Id:	Not reported
Enforcement Action Date:	04/27/2021
Penalty Amount:	$4,000.00
Sep Amt:	Not reported
Bureau Name:	Air Management
Program:	Air Enforcement
Status:	Closed
Date of Discovery:	04/14/2020
Resolution Date:	11/26/2021
Resolution Type:	Returned to compliance
Staff:	Rackie Deanna
ENF Action Comment:	Chuck's Automotive, LLC dba Chuck's Automotive failed to conduct Stage I Vapor Recovery Testing in years 2016, 2017, 2018, and 2019. This station also failed to submit the 2015 Stage I Vapor Recovery test

CHUCKS AUTOMOTIVE LLC (Continued) **S106731616**

	report within ten days of test completion.
Number Violations:	Not reported
Civil Penalty:	$4,000.00
SEP Description:	Not reported
Associated EIs:	Not reported
Client Affiliation Type:	Respondent
Affiliation Name:	CHUCK'S AUTOMOTIVE, LLC
Affiliation Address Line1:	653 Burnside Ave
Affiliation Address Line2:	Not reported
Affiliation City/State/Zip:	East Hartford, CT 06108
Contact Title:	Not reported
Contact Name:	Not reported
Contact EMail:	Not reported
Name:	CHUCKS AUTOMOTIVE LLC
Address:	653 BURNSIDE AVE
City,State,Zip:	EAST HARTFORD, CT 06108
Enforcement Action ID:	NVAR18074--20001
Enforcement Type Code:	Notice Of Violation
Program Id:	Not reported
Enforcement Action Date:	05/11/2020
Penalty Amount:	$0.00
Sep Amt:	Not reported
Bureau Name:	Air Management
Program:	Air Enforcement
Status:	Closed
Date of Discovery:	04/14/2020
Resolution Date:	11/09/2020
Resolution Type:	Closed-Referred for other action
Staff:	Bouffard Rickey
ENF Action Comment:	DEEP records indicate that Chuck s Automotive, LLC failed to conduct all Stage I Vapor Recovery tests in 2016, 2017, 2018, and 2019.
Number Violations:	Not reported
Civil Penalty:	Not reported
SEP Description:	Not reported
Associated EIs:	Not reported
Client Affiliation Type:	Respondent
Affiliation Name:	CHUCK'S AUTOMOTIVE, LLC
Affiliation Address Line1:	653 Burnside Ave
Affiliation Address Line2:	Not reported
Affiliation City/State/Zip:	East Hartford, CT 06108
Contact Title:	Not reported
Contact Name:	Not reported
Contact EMail:	Not reported
Name:	CHUCKS AUTOMOTIVE LLC
Address:	653 BURNSIDE AVE
City,State,Zip:	EAST HARTFORD, CT 06108
Enforcement Action ID:	WLUST-MC223-0023
Enforcement Type Code:	Warning Letter
Program Id:	Not reported
Enforcement Action Date:	04/18/2023
Penalty Amount:	$0.00
Sep Amt:	Not reported
Bureau Name:	Materials Management & Compliance Assurance
Program:	Underground Storage Tank Enforcement
Status:	Closed

CHUCKS AUTOMOTIVE LLC (Continued) **S106731616**

Date of Discovery:	04/18/2023
Resolution Date:	04/18/2023
Resolution Type:	Closed-No further action required
Staff:	McShea Kelly
ENF Action Comment:	Not reported
Number Violations:	1
Civil Penalty:	Not reported
SEP Description:	Not reported
Associated EIs:	Underground Storage Tank Notification (43-5508)
Client Affiliation Type:	Respondent
Affiliation Name:	CHUCK'S AUTOMOTIVE, LLC
Affiliation Address Line1:	653 Burnside Ave
Affiliation Address Line2:	Not reported
Affiliation City/State/Zip:	East Hartford, CT 06108
Contact Title:	Not reported
Contact Name:	Not reported
Contact EMail:	Not reported

Name:	CHUCKS AUTOMOTIVE LLC
Address:	653 BURNSIDE AVE
City,State,Zip:	EAST HARTFORD, CT 06108
Enforcement Action ID:	NOVUST-MC223-0056
Enforcement Type Code:	Field Notice of Violation
Program Id:	Not reported
Enforcement Action Date:	04/18/2023
Penalty Amount:	$0.00
Sep Amt:	Not reported
Bureau Name:	Materials Management & Compliance Assurance
Program:	Underground Storage Tank Enforcement
Status:	Closed
Date of Discovery:	04/18/2023
Resolution Date:	05/04/2023
Resolution Type:	Closed-Compliance Statement not submitted
Staff:	Requardt Ethan
ENF Action Comment:	Failed to conduct requisite testing of spill buckets according to initial and 3-year schedule. . Failed to document compliance with spill prevention testing requirements in accordance with RCSA section 22a-449(d)-103(a)(4). . Failed to test repaired spill prevention equipment (e.g., spill bucket) within 30 days of the repair in accordance with manufacturer specifications or a nationally recognized code of practice. Owner or Operator failed to maintain records of testing results required to demonstrate compliance with secondary containment systems. The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information. The release detection documentation was not available.
Number Violations:	15
Civil Penalty:	Not reported
SEP Description:	ER 5/4/23 Received documentation of passing ATG functionality testing, dated 3/13/23. ER 5/4/23 Received documentation of passing hydrostatic testing for regular, super & diesel tanks & dispenser sumps dated 4/21/23. ER 5/3/23 Received updated ezFile notification on 4/20/23 with active insurance & AB operators
Associated EIs:	Underground Storage Tank Notification (43-5508)
Client Affiliation Type:	Respondent
Affiliation Name:	CHUCK'S AUTOMOTIVE, LLC
Affiliation Address Line1:	653 Burnside Ave
Affiliation Address Line2:	Not reported

CHUCKS AUTOMOTIVE LLC (Continued) **S106731616**

Affiliation City/State/Zip: East Hartford, CT 06108
Contact Title: Not reported
Contact Name: Not reported
Contact EMail: Not reported

D28 **CHARLES TIRE** **CT MANIFEST** **S109737620**
West **653 BURNSIDE AVE** **N/A**
1/8-1/4 **EAST HARTFORD, CT**
0.205 mi.
1085 ft. **Site 5 of 5 in cluster D**

Relative: **Lower**
Actual: **52 ft.**

CT MANIFEST:
Name: CHARLES TIRE
Address: 653 BURNSIDE AVE
City,State,Zip: EAST HARTFORD, CT
Phone: Not reported
Country: Not reported
Manifest ID: CTC0167068
EPA ID: CTP000007897

Hazardous Waste Manifest:
Year: 1988
Manifest: CTC0167068
EPA ID: CTP000007897
Generator Mailing Address: 653 BURNSIDE AVE
Generator City,State,Zip: EAST HARTFORD, CT
Discrepancies: N
Date Shipped: 1988-08-01
Date Received: 1988-08-01
Transporter 2 Date: Not reported
TSDF EPA ID: CTD021816889
TSDF Name: UNITED INDUSTRIAL SERVICES INC
TSDF Address: 136 GRACEY AVE
TSDF City,State,Zip: MERIDEN, CT 06450
TSDF Country: USA
Transporter EPA ID: CTD021816889
Transporter Name: UNITED INDUSTRIAL SERVICES INC
Transporter Address: Not reported
Transporter City,State,Zip: CT
Transporter Country: USA
Transporter 2 EPA ID: Not reported
Transporter 2 Name: Not reported
Transporter 2 Address: Not reported
Transporter 2 City,State,Zip: CT
Transporter 2 Country: USA
US DOT Description: WASTE FLAMMABLE LIQUID, NOS
Number of Containers: 001
Container Type: TT
Quantity/Weight/Volume: 300/G
Batch Number: 999999
EPA Waste Codes: D001 - IGNITABLE WASTE
Copies: 1
Alternate Facility Name: Not reported
Alternate Facility Address: Not reported
Alternate Facility State: Not reported
Alternate Facility Date: Not reported

E29 **CELLU-TISSUE, LLC** **CT PROPERTY** **S130308080**
South **40 FORBES STREET (AKA 2 FORBES STREET)** **CT CPCS** **N/A**
1/8-1/4 **EAST HARTFORD, CT**
0.208 mi.
1097 ft. **Site 1 of 12 in cluster E**

Relative: **Lower**

Actual: **52 ft.**

CT Property:

Name:	CELLU-TISSUE, LLC
Address:	40 FORBES STREET (AKA 2 FORBES STREET)
City,state,zip:	EAST HARTFORD, CT
Seller Name:	CT Holdings LLC
Buyer Name:	Complete Paper Inc.
Certifying Party:	Dunn Paper - East Hartford
Certifying Attention Person:	James Dickerson
Title Of Certifying Person:	Plant Manager
Certifying Person Address:	Two Forbes Street
Certifying Person City,St,Zip:	East Hartford, CT 06108
Property Transfer Forms:	Form III (DEP-PERD-PTP-203) when a discharge, spillage, uncontrolled loss, seepage or filtration of hazardous waste has occurred at the parcel that has not been fully remediated or the environmental conditions at the parcel are unknown. The person signing the Form III certification agrees to investigate and remediate the site in accordance with the remediation standards. The statute does not require completion of remediation before the parcel is transferred. Any person submitting a Form III shall simultaneously submit a completed Environmental Condition Assessment Form (ECAF)(DEP-PERD-PTP-200).
Date Recieved:	12/29/2022
Ackn Date:	05/25/2023
Determination Date:	Not reported
LEP Verified/DEP Approval Date:	Not reported
Rem Id:	22291
Remediation Location Id:	1596
Date Entered:	05/24/2023
Program:	Property Transfer Program
GAO Site:	False
Staff Full Name:	Claire Quinn
Super/Date:	05/25/2023
Stage Of Project:	Not reported
RP Level Of Activity:	Not reported
RP Needed Level Of Activity:	Not reported
Staff Level Of Activity:	Not reported
Staff Needed Level Of Activity:	Not reported
Public Intrest:	Not reported
PRP Cooperation:	Not reported
Enforcement Status:	Not reported
Level Of Complexity:	Not reported
Complex Eng Or Sci:	Not reported
Complex Due To Public Involvement:	Not reported
Politically Complex:	Not reported
Complex Enforcement:	Not reported
Coordination With Other Bureaus:	Not reported
EPA Involvement:	Not reported
Staff Prefrence:	Not reported
Readiness For Transfer:	Not reported
Project Transfer Time:	Not reported
Transfer Comments:	Not reported
Staff As Of July 2000:	Not reported
Initial Staff:	Not reported

CELLU-TISSUE, LLC (Continued) **S130308080**

Type Of Transfer:	Real Estate
Salutation:	Mr. Dickerson
Relationship To Transfer:	Transferor
Audit Date:	Not reported
Verif Type:	Not reported
Audit Outcome:	Not reported
GW:	GB
Basin:	Not reported
1st Payment:	3000
Pay Tag1:	8332
2nd Payment:	Not reported
Pay Tag2:	Not reported
RTN:	Not reported
Revised:	Not reported
ECAF Received:	Not reported
Old Determination Date:	Not reported
Redeterminationdate:	Not reported
Previous Determination:	Not reported
Monitoringoption:	Not reported
Postremedialmonitoring:	Not reported
Schedule Of I/R:	Not reported
Schedule Overdue:	Not reported
Aprvl Sched:	Not reported
Yr 1 Report:	Not reported
Yr 2 Report:	Not reported
Report Overdue:	Not reported
Ext Aprvl Sched:	Not reported
License #:	Not reported
Project Phase:	Not reported
PT Comments:	Not reported
EPA Id Number:	Not reported
GW Class:	Not reported
SW Class:	Not reported
AO/C0:	Not reported
Water Lead(Y Or N):	Not reported
Priority:	Not reported
Project Status(A, I Or D):	Not reported
Last Updated:	Not reported
SR Comments:	Not reported
Priority Or Work-Load:	Not reported
Status:	Not reported
Notes:	Not reported
Special Project Name:	Not reported
Special Project Comments:	Not reported
DOT Project:	Not reported
Pt Counter:	Not reported
Project Complete:	Not reported
Project Inactive:	Not reported
Int Deposit #:	Not reported
Deposit #:	Not reported
Spill Case #:	Not reported
Diversion Id:	Not reported
Public Notice:	Not reported
RAP Received:	Not reported
RAP Approved:	Not reported
Compliance Category:	Not reported
Delete Record:	Not reported

CELLU-TISSUE, LLC (Continued) **S130308080**

ECAF Reviewed By:	Not reported
Not Locatable:	Not reported
Primary Address:	Not reported
AKA Site Name:	Not reported
Primary Site Name:	Not reported
AKA Site Address:	Not reported
Lead:	LEP

CPCS:

Name:	Cellu-Tissue, Llc
Address:	40 FORBES STREET (AKA 2 FORBES STREET)
City,State,Zip:	EAST HARTFORD, CT
Site Type:	Not reported
Lust Status code:	Not reported
Lust Status:	Not reported
PTP Form:	Not reported
Program:	Property Transfer Program
Comments:	Not reported
Site Type Definition:	Not reported
Invesigation Start:	Not reported
Invesigation Start Date:	05/25/2023
Remediation Start:	Not reported
Remediation Start Date:	Not reported
Remediation Completed:	No
ELUR:	No
Date Data Updated:	Not reported

E30 **DUNN PAPER - EAST HARTFORD, LLC** **CT PROPERTY** **S120925881**
South **40 FORBES ST** **CT CPCS** **N/A**
1/8-1/4 **EAST HARTFORD, CT 06108** **CT ENF**
0.208 mi. **CT NPDES**
1097 ft. **Site 2 of 12 in cluster E**

Relative: **Lower**
Actual: **52 ft.**

CT Property:

Name:	CELLU TISSUE, LLC
Address:	40 FORBES STREET
City,state,zip:	EAST HARTFORD, CT
Seller Name:	Cellu Tissue Holdings, Inc.
Buyer Name:	CT Holdings, LLC
Certifying Party:	Cellu Tissue, LLC
Certifying Attention Person:	D'Arcy J. Schnekenburger
Title Of Certifying Person:	Vice-President
Certifying Person Address:	40 Forbes Street
Certifying Person City,St,Zip:	East Hartford, CT 06108
Property Transfer Forms:	Form III (DEP-PERD-PTP-203) when a discharge, spillage, uncontrolled loss, seepage or filtration of hazardous waste has occurred at the parcel that has not been fully remediated or the environmental conditions at the parcel are unknown. The person signing the Form III certification agrees to investigate and remediate the site in accordance with the remediation standards. The statute does not require completion of remediation before the parcel is transferred. Any person submitting a Form III shall simultaneously submit a completed Environmental Condition Assessment Form (ECAF)(DEP-PERD-PTP-200).
Date Recieved:	01/12/2015
Ackn Date:	03/27/2015
Determination Date:	03/27/2015

DUNN PAPER - EAST HARTFORD, LLC (Continued) **S120925881**

LEP Verified/DEP Approval Date:	Not reported
Rem Id:	12153
Remediation Location Id:	9399
Date Entered:	01/21/2015
Program:	Property Transfer Program
GAO Site:	False
Staff Full Name:	Tom Oconnor
Super/Date:	03/27/2015
Stage Of Project:	Not reported
RP Level Of Activity:	Not reported
RP Needed Level Of Activity:	Not reported
Staff Level Of Activity:	Not reported
Staff Needed Level Of Activity:	Not reported
Public Intrest:	Not reported
PRP Cooperation:	Not reported
Enforcement Status:	Not reported
Level Of Complexity:	Not reported
Complex Eng Or Sci:	False
Complex Due To Public Involvement:	False
Politically Complex:	False
Complex Enforcement:	False
Coordination With Other Bureaus:	False
EPA Involvement:	False
Staff Prefrence:	Not reported
Readiness For Transfer:	Not reported
Project Transfer Time:	Not reported
Transfer Comments:	Not reported
Staff As Of July 2000:	Not reported
Initial Staff:	Not reported
Type Of Transfer:	Real Estate
Salutation:	Ms. Schnekenburger
Relationship To Transfer:	transferor
Audit Date:	Not reported
Verif Type:	Not reported
Audit Outcome:	Not reported
GW:	GB
Basin:	Not reported
1st Payment:	3000
Pay Tag1:	20778
2nd Payment:	Not reported
Pay Tag2:	Not reported
RTN:	03/02/2015
Revised:	3/27/2015
ECAF Received:	Not reported
Old Determination Date:	Not reported
Redeterminationdate:	Not reported
Previous Determination:	Not reported
Monitoringoption:	Not reported
Postremedialmonitoring:	Not reported
Schedule Of I/R:	Not reported
Schedule Overdue:	Not reported
Aprvl Sched:	Not reported
Yr 1 Report:	Not reported
Yr 2 Report:	Not reported
Report Overdue:	Not reported
Ext Aprvl Sched:	Not reported
License #:	Not reported

DUNN PAPER - EAST HARTFORD, LLC (Continued) **S120925881**

Project Phase:	Not reported
PT Comments:	aka: 2 Forbes Street
EPA Id Number:	Not reported
GW Class:	Not reported
SW Class:	Not reported
AO/C0:	Not reported
Water Lead(Y Or N):	Not reported
Priority:	Not reported
Project Status(A, I Or D):	Not reported
Last Updated:	Not reported
SR Comments:	Not reported
Priority Or Work-Load:	Not reported
Status:	Not reported
Notes:	Not reported
Special Project Name:	Not reported
Special Project Comments:	Not reported
DOT Project:	Not reported
Pt Counter:	0
Project Complete:	False
Project Inactive:	False
Int Deposit #:	Not reported
Deposit #:	Not reported
Spill Case #:	Not reported
Diversion Id:	0
Public Notice:	Not reported
RAP Received:	Not reported
RAP Approved:	Not reported
Compliance Category:	Not reported
Delete Record:	False
ECAF Reviewed By:	Tom Oconnor
Not Locatable:	False
Primary Address:	False
AKA Site Name:	False
Primary Site Name:	False
AKA Site Address:	False
Lead:	LEP

CPCS:

Name:	Cellu Tissue, Llc
Address:	40 FORBES STREET
City,State,Zip:	EAST HARTFORD, CT
Site Type:	Not reported
Lust Status code:	Not reported
Lust Status:	Not reported
PTP Form:	Not reported
Program:	Property Transfer Program
Comments:	Not reported
Site Type Definition:	Not reported
Invesigation Start:	Not reported
Invesigation Start Date:	03/27/2015
Remediation Start:	Not reported
Remediation Start Date:	03/16/2017
Remediation Completed:	No
ELUR:	No
Date Data Updated:	Not reported

DUNN PAPER - EAST HARTFORD, LLC (Continued) **S120925881**

ENFORCEMENT:

Name:	DUNN PAPER - EAST HARTFORD, LLC
Address:	40 FORBES ST
City,State,Zip:	EAST HARTFORD, CT 06108
Enforcement Action ID:	NOVWRIN14018
Enforcement Type Code:	Notice Of Violation
Program Id:	Not reported
Enforcement Action Date:	10/22/2014
Penalty Amount:	$0.00
Sep Amt:	Not reported
Bureau Name:	Materials Management & Compliance Assurance
Program:	Industrial NPDES Enforcement
Status:	Closed
Date of Discovery:	09/15/2014
Resolution Date:	03/05/2015
Resolution Type:	Returned to compliance
Staff:	Langan Rita
ENF Action Comment:	Discharged process wastewater to surface waters without a permit. Failed to maintain practices and procedures to prevent spills, leaks, and/or unplanned releases. Failed to properly monitor their permitted wastewater discharge as required by CT0002127.
Number Violations:	Not reported
Civil Penalty:	Not reported
SEP Description:	Not reported
Associated EIs:	Surface Water Discharge (CT0002127)
Client Affiliation Type:	Respondent
Affiliation Name:	DUNN PAPER-EAST HARTFORD, LLC.
Affiliation Address Line1:	2 FORBES ST
Affiliation Address Line2:	Not reported
Affiliation City/State/Zip:	EAST HARTFORD, CT 06108 3727
Contact Title:	Not reported
Contact Name:	JAMES DICKERSON
Contact EMail:	james.dickerson@clearwaterpaper.com

Name:	DUNN PAPER - EAST HARTFORD, LLC
Address:	40 FORBES ST
City,State,Zip:	EAST HARTFORD, CT 06108
Enforcement Action ID:	NOVWRIN17009
Enforcement Type Code:	Notice Of Violation
Program Id:	Not reported
Enforcement Action Date:	04/27/2017
Penalty Amount:	$0.00
Sep Amt:	Not reported
Bureau Name:	Materials Management & Compliance Assurance
Program:	Industrial NPDES Enforcement
Status:	Closed
Date of Discovery:	04/05/2017
Resolution Date:	03/15/2023
Resolution Type:	Closed-No further action required
Staff:	Marshall Emily
ENF Action Comment:	Not reported
Number Violations:	Not reported
Civil Penalty:	Not reported
SEP Description:	Not reported
Associated EIs:	Facility or Process Modification-3(i)(2) (CT0002127), and Surface Water Discharge (CT0002127)
Client Affiliation Type:	Respondent
Affiliation Name:	DUNN PAPER-EAST HARTFORD, LLC.

DUNN PAPER - EAST HARTFORD, LLC (Continued) **S120925881**

Affiliation Address Line1:	2 FORBES ST
Affiliation Address Line2:	Not reported
Affiliation City/State/Zip:	EAST HARTFORD, CT 06108 3727
Contact Title:	Not reported
Contact Name:	Not reported
Contact EMail:	Not reported
Name:	DUNN PAPER - EAST HARTFORD, LLC
Address:	40 FORBES ST
City,State,Zip:	EAST HARTFORD, CT 06108
Enforcement Action ID:	NOVWRIN17001
Enforcement Type Code:	Notice Of Violation
Program Id:	Not reported
Enforcement Action Date:	01/05/2017
Penalty Amount:	$0.00
Sep Amt:	Not reported
Bureau Name:	Materials Management & Compliance Assurance
Program:	Industrial NPDES Enforcement
Status:	Closed
Date of Discovery:	12/23/2016
Resolution Date:	03/15/2023
Resolution Type:	Closed-No further action required
Staff:	Marshall Emily
ENF Action Comment:	Not reported
Number Violations:	Not reported
Civil Penalty:	Not reported
SEP Description:	Not reported
Associated EIs:	Facility or Process Modification-3(i)(2) (CT0002127), and Surface Water Discharge (CT0002127)
Client Affiliation Type:	Respondent
Affiliation Name:	DUNN PAPER-EAST HARTFORD, LLC.
Affiliation Address Line1:	2 Forbes St
Affiliation Address Line2:	Not reported
Affiliation City/State/Zip:	East Hartford, CT 06108 3727
Contact Title:	Not reported
Contact Name:	Not reported
Contact EMail:	Not reported
Name:	DUNN PAPER - EAST HARTFORD, LLC
Address:	40 FORBES ST
City,State,Zip:	EAST HARTFORD, CT 06108
Enforcement Action ID:	COAR2466--10001
Enforcement Type Code:	Consent Order
Program Id:	Not reported
Enforcement Action Date:	08/19/2016
Penalty Amount:	$29,520.00
Sep Amt:	Not reported
Bureau Name:	Air Management
Program:	Air Enforcement
Status:	Closed
Date of Discovery:	02/02/2016
Resolution Date:	09/20/2016
Resolution Type:	Returned to compliance
Staff:	Chagnon Teraesa
ENF Action Comment:	Failure to operate control equipment (urea injection) for 243 days. This violation was self-disclosed and has been corrected. Order is to recover economic benefit only (avoided cost of urea).
Number Violations:	Not reported

DUNN PAPER - EAST HARTFORD, LLC (Continued) **S120925881**

Civil Penalty:	$29,520.00
SEP Description:	Not reported
Associated EIs:	Not reported
Client Affiliation Type:	Respondent
Affiliation Name:	DUNN PAPER-EAST HARTFORD, LLC.
Affiliation Address Line1:	40 Forbes St
Affiliation Address Line2:	Not reported
Affiliation City/State/Zip:	East Hartford, CT 06108 3727
Contact Title:	Not reported
Contact Name:	Not reported
Contact EMail:	Not reported
Name:	DUNN PAPER - EAST HARTFORD, LLC
Address:	40 FORBES ST
City,State,Zip:	EAST HARTFORD, CT 06108
Enforcement Action ID:	NVAR17657--16097
Enforcement Type Code:	Notice Of Violation
Program Id:	Not reported
Enforcement Action Date:	07/26/2016
Penalty Amount:	$0.00
Sep Amt:	Not reported
Bureau Name:	Air Management
Program:	Air Enforcement
Status:	Active
Date of Discovery:	09/14/2015
Resolution Date:	Not reported
Resolution Type:	Not reported
Staff:	Chagnon Teraesa
ENF Action Comment:	During the period of time from 12/30/14 and 9/1/2015 (243) days), Dunn Paper did not operate their selective catalytic reduction control equipment as required by their NSR permit.
Number Violations:	Not reported
Civil Penalty:	Not reported
SEP Description:	Not reported
Associated EIs:	Not reported
Client Affiliation Type:	Respondent
Affiliation Name:	DUNN PAPER-EAST HARTFORD, LLC.
Affiliation Address Line1:	3079 Premiere Pkwy
Affiliation Address Line2:	Not reported
Affiliation City/State/Zip:	Duluth, GA 30097 5243
Contact Title:	Not reported
Contact Name:	Not reported
Contact EMail:	Not reported
Name:	DUNN PAPER - EAST HARTFORD, LLC
Address:	40 FORBES ST
City,State,Zip:	EAST HARTFORD, CT 06108
Enforcement Action ID:	NNCWRIN22011
Enforcement Type Code:	Notice of Non-Compliance
Program Id:	Not reported
Enforcement Action Date:	03/21/2022
Penalty Amount:	$0.00
Sep Amt:	Not reported
Bureau Name:	Materials Management & Compliance Assurance
Program:	Industrial Pre-Treatment Enforcement
Status:	Closed
Date of Discovery:	03/01/2022

DUNN PAPER - EAST HARTFORD, LLC (Continued) **S120925881**

Resolution Date:	03/21/2022
Resolution Type:	Closed-No further action required
Staff:	MacLaren Alexandra
ENF Action Comment:	Not reported
Number Violations:	Not reported
Civil Penalty:	Not reported
SEP Description:	Not reported
Associated EIs:	Miscellaneous Sewer Discharges-GP (CTMIU0036)
Client Affiliation Type:	Respondent
Affiliation Name:	DUNN PAPER-EAST HARTFORD, LLC.
Affiliation Address Line1:	Not reported
Affiliation Address Line2:	Not reported
Affiliation City/State/Zip:	Not reported
Contact Title:	Not reported
Contact Name:	Not reported
Contact EMail:	Not reported

Name:	DUNN PAPER - EAST HARTFORD, LLC
Address:	40 FORBES ST
City,State,Zip:	EAST HARTFORD, CT 06108
Enforcement Action ID:	NOVWRIN23006
Enforcement Type Code:	Notice Of Violation
Program Id:	Not reported
Enforcement Action Date:	04/04/2023
Penalty Amount:	$0.00
Sep Amt:	Not reported
Bureau Name:	Materials Management & Compliance Assurance
Program:	Industrial NPDES Enforcement
Status:	Closed
Date of Discovery:	04/04/2023
Resolution Date:	06/29/2023
Resolution Type:	Closed-Unilateral Order replaced by Consent Order
Staff:	Marshall Emily
ENF Action Comment:	Not reported
Number Violations:	Not reported
Civil Penalty:	Not reported
SEP Description:	Not reported
Associated EIs:	Surface Water Discharge (CT0002127)
Client Affiliation Type:	Respondent
Affiliation Name:	DUNN PAPER-EAST HARTFORD, LLC.
Affiliation Address Line1:	3079 Premiere Pkwy
Affiliation Address Line2:	Not reported
Affiliation City/State/Zip:	Duluth, GA 30097 5243
Contact Title:	Not reported
Contact Name:	Not reported
Contact EMail:	Not reported

Name:	DUNN PAPER - EAST HARTFORD, LLC
Address:	40 FORBES ST
City,State,Zip:	EAST HARTFORD, CT 06108
Enforcement Action ID:	NNCWRIN24021
Enforcement Type Code:	Notice of Non-Compliance
Program Id:	Not reported
Enforcement Action Date:	11/07/2024
Penalty Amount:	$0.00
Sep Amt:	Not reported
Bureau Name:	Materials Management & Compliance Assurance

DUNN PAPER - EAST HARTFORD, LLC (Continued) **S120925881**

Program:	Industrial NPDES Enforcement
Status:	Closed
Date of Discovery:	09/07/2024
Resolution Date:	11/07/2024
Resolution Type:	Returned to compliance
Staff:	Marshall Emily
ENF Action Comment:	A bypass of the UV treatment system.
Number Violations:	Not reported
Civil Penalty:	Not reported
SEP Description:	Not reported
Associated EIs:	Surface Water Discharge (CT0002127)
Client Affiliation Type:	Respondent
Affiliation Name:	DUNN PAPER-EAST HARTFORD, LLC.
Affiliation Address Line1:	2 FORBES ST
Affiliation Address Line2:	Not reported
Affiliation City/State/Zip:	EAST HARTFORD, CT 06108 3727
Contact Title:	Not reported
Contact Name:	JEFFREY BRASCHICH
Contact EMail:	BRASHICHJ@BIORIGINSP.COM

NPDES:

Name:	DUNN PAPER - EAST HARTFORD, LLC
Address:	40 FORBES ST
City:	EAST HARTFORD
Town Id:	Not reported
Company Name:	Not reported
Permit Number:	CT0002127
Permit Issued Date:	10/24/2002
Permit Expiration Date:	10/24/2007
Application Received Date:	Not reported
Affiliation Type:	Permittee
Permit EI Type:	Surface Water Discharge
App Id:	200103288
Site Address Description:	Not reported
Site Address Line 2:	Not reported
Permit Description:	RENEW PULP AND PAPER NPDES PERMIT
Status:	Expired
Affiliate Address Line 1:	2 FORBES ST
Affiliate Address Line 2:	Not reported
Affiliate City/State/Zip:	EAST HARTFORD, CT 06108-3727
Contact Name:	CHRIS FEIDLER
Contact Title:	MILL MANAGER
Contact EMail:	CHRISTOPHER.FIELDER@CLEARWATERPAPER.COM

Name:	DUNN PAPER - EAST HARTFORD, LLC
Address:	40 FORBES ST
City:	EAST HARTFORD
Town Id:	Not reported
Company Name:	Not reported
Permit Number:	CT0002127
Permit Issued Date:	04/30/1997
Permit Expiration Date:	04/30/2002
Application Received Date:	Not reported
Affiliation Type:	Permittee
Permit EI Type:	Surface Water Discharge
App Id:	199600982
Site Address Description:	Not reported

DUNN PAPER - EAST HARTFORD, LLC (Continued) **S120925881**

Site Address Line 2:	Not reported
Permit Description:	Not reported
Status:	Expired
Affiliate Address Line 1:	2 FORBES ST
Affiliate Address Line 2:	PO BOX 280096
Affiliate City/State/Zip:	EAST HARTFORD, CT 06108-3727
Contact Name:	STEPHEN MARTINEAU
Contact Title:	Not reported
Contact EMail:	Not reported
Name:	DUNN PAPER - EAST HARTFORD, LLC
Address:	40 FORBES ST
City:	EAST HARTFORD
Town Id:	Not reported
Company Name:	Not reported
Permit Number:	CT0002127
Permit Issued Date:	10/07/2008
Permit Expiration Date:	10/06/2013
Application Received Date:	Not reported
Affiliation Type:	Permittee
Permit EI Type:	Surface Water Discharge
App Id:	200701197
Site Address Description:	Not reported
Site Address Line 2:	Not reported
Permit Description:	RENEWAL APPLICATION FOR MILL NPDES #CT0002127 (EAST HARTFORD,CT)
Status:	Continued
Affiliate Address Line 1:	2 FORBES ST
Affiliate Address Line 2:	Not reported
Affiliate City/State/Zip:	EAST HARTFORD, CT 06108-3727
Contact Name:	MARTHA SMIGEL
Contact Title:	Not reported
Contact EMail:	Not reported
Name:	DUNN PAPER - EAST HARTFORD, LLC
Address:	40 FORBES ST
City:	EAST HARTFORD
Town Id:	Not reported
Company Name:	Not reported
Permit Number:	CT0002127
Permit Issued Date:	06/04/2020
Permit Expiration Date:	06/04/2020
Application Received Date:	Not reported
Affiliation Type:	Permittee
Permit EI Type:	Facility or Process Modification-3(i)(2)
App Id:	202006927
Site Address Description:	Not reported
Site Address Line 2:	Not reported
Permit Description:	Permit No. NPDES CT0002127 - 40 Forbes St East Hartford, CT. Proposal to install 3 new valves to prevent future bypass discharge to river [COVERED BY APPROVAL OF APPLICATION 202005965 ISSUED JUNE 4, 2020]
Status:	Expired
Affiliate Address Line 1:	2 FORBES ST
Affiliate Address Line 2:	Not reported
Affiliate City/State/Zip:	EAST HARTFORD, CT 06108-3727
Contact Name:	JAMES DICKERSON
Contact Title:	Not reported
Contact EMail:	DickersonJ@dunnpaper.com

DUNN PAPER - EAST HARTFORD, LLC (Continued) **S120925881**

Name:	DUNN PAPER - EAST HARTFORD, LLC
Address:	40 FORBES ST
City:	EAST HARTFORD
Town Id:	Not reported
Company Name:	Not reported
Permit Number:	SP0002347
Permit Issued Date:	08/05/2002
Permit Expiration Date:	08/05/2007
Application Received Date:	Not reported
Affiliation Type:	Permittee
Permit EI Type:	Sewer Discharge
App Id:	199803416
Site Address Description:	Not reported
Site Address Line 2:	Not reported
Permit Description:	NPDES PERMIT FOR DISCHARGE OF TISSUEPAPER MILL WASTE TO MDC SEWER SYSTEM.
Status:	Expired
Affiliate Address Line 1:	2 FORBES ST
Affiliate Address Line 2:	Not reported
Affiliate City/State/Zip:	EAST HARTFORD, CT 06108-3727
Contact Name:	CHRIS FEIDLER
Contact Title:	MILL MANAGER
Contact EMail:	CHRISTOPHER.FIELDER@CLEARWATERPAPER.COM

Name:	DUNN PAPER - EAST HARTFORD, LLC
Address:	40 FORBES ST
City:	EAST HARTFORD
Town Id:	Not reported
Company Name:	Not reported
Permit Number:	GWT000221
Permit Issued Date:	09/17/2010
Permit Expiration Date:	03/29/2018
Application Received Date:	Not reported
Affiliation Type:	Permittee
Permit EI Type:	Water Treatment Wastewater-GP
App Id:	201005680
Site Address Description:	Not reported
Site Address Line 2:	Not reported
Permit Description:	Not reported
Status:	Expired
Affiliate Address Line 1:	2 FORBES ST
Affiliate Address Line 2:	Not reported
Affiliate City/State/Zip:	EAST HARTFORD, CT 06108-3727
Contact Name:	CHRIS FEIDLER
Contact Title:	MILL MANAGER
Contact EMail:	CHRISTOPHER.FIELDER@CLEARWATERPAPER.COM

Name:	DUNN PAPER - EAST HARTFORD, LLC
Address:	40 FORBES ST
City:	EAST HARTFORD
Town Id:	Not reported
Company Name:	Not reported
Permit Number:	SP0002347
Permit Issued Date:	04/27/2011
Permit Expiration Date:	04/26/2016
Application Received Date:	Not reported
Affiliation Type:	Permittee

DUNN PAPER - EAST HARTFORD, LLC (Continued) **S120925881**

Permit EI Type:	Sewer Discharge
App Id:	200700271
Site Address Description:	Not reported
Site Address Line 2:	Not reported
Permit Description:	RENEW PERMIT DISCHARGE OF CERTAIN WASTES TO THE MDC (EAST HARTFORD,CT) ANNUAL FEE CHARGED UNDER NPDES CT0002127.
Status:	Expired
Affiliate Address Line 1:	2 FORBES ST
Affiliate Address Line 2:	Not reported
Affiliate City/State/Zip:	EAST HARTFORD, CT 06108-3727
Contact Name:	MARTHA SMIGEL
Contact Title:	Not reported
Contact EMail:	Not reported

Name:	DUNN PAPER - EAST HARTFORD, LLC
Address:	40 FORBES ST
City:	EAST HARTFORD
Town Id:	Not reported
Company Name:	Not reported
Permit Number:	SP0002347
Permit Issued Date:	07/01/2019
Permit Expiration Date:	06/30/2024
Application Received Date:	Not reported
Affiliation Type:	Permittee
Permit EI Type:	Sewer Discharge
App Id:	201508293
Site Address Description:	Not reported
Site Address Line 2:	Not reported
Permit Description:	RENEWAL PERMIT #SP0002347, 40 FORBES ST., EAST HARTFORD
Status:	Continued
Affiliate Address Line 1:	2 FORBES ST
Affiliate Address Line 2:	Not reported
Affiliate City/State/Zip:	EAST HARTFORD, CT 06108-3727
Contact Name:	JAMES DICKERSON
Contact Title:	Not reported
Contact EMail:	DickersonJ@dunnpaper.com

Name:	DUNN PAPER - EAST HARTFORD, LLC
Address:	40 FORBES ST
City:	EAST HARTFORD
Town Id:	Not reported
Company Name:	Not reported
Permit Number:	GMI000116
Permit Issued Date:	03/30/2006
Permit Expiration Date:	10/30/2013
Application Received Date:	Not reported
Affiliation Type:	Permittee
Permit EI Type:	Miscellaneous Discharges-GP >5000 GPD
App Id:	200502653
Site Address Description:	Not reported
Site Address Line 2:	Not reported
Permit Description:	PUMPING OUT BUILDING MAINTENANCE WASTEWATER CONTAINING LESS THAT 1% PAPER PULP
Status:	Expired
Affiliate Address Line 1:	2 FORBES ST
Affiliate Address Line 2:	Not reported
Affiliate City/State/Zip:	EAST HARTFORD, CT 06108-3727

DUNN PAPER - EAST HARTFORD, LLC (Continued) **S120925881**

Contact Name:	MITCHELL KIELBANIA
Contact Title:	Not reported
Contact EMail:	Not reported
Name:	DUNN PAPER - EAST HARTFORD, LLC
Address:	40 FORBES ST
City:	EAST HARTFORD
Town Id:	Not reported
Company Name:	Not reported
Permit Number:	GWT000221
Permit Issued Date:	08/22/2003
Permit Expiration Date:	05/01/2005
Application Received Date:	Not reported
Affiliation Type:	Permittee
Permit EI Type:	Water Treatment Wastewater-GP
App Id:	200301482
Site Address Description:	Not reported
Site Address Line 2:	Not reported
Permit Description:	IN PROCESS OF INSTALLING FILTER SYSTEM TO FILTER RIVER WATER FOR PLANT PROCESS USE. PERMIT FOR OFF QUALITY FLOW.
Status:	Expired
Affiliate Address Line 1:	2 FORBES ST
Affiliate Address Line 2:	Not reported
Affiliate City/State/Zip:	EAST HARTFORD, CT 06108-3727
Contact Name:	CHRIS FEIDLER
Contact Title:	MILL MANAGER
Contact EMail:	CHRISTOPHER.FIELDER@CLEARWATERPAPER.COM
Name:	DUNN PAPER - EAST HARTFORD, LLC
Address:	40 FORBES ST
City:	EAST HARTFORD
Town Id:	Not reported
Company Name:	Not reported
Permit Number:	GWT000212
Permit Issued Date:	09/20/2010
Permit Expiration Date:	03/29/2018
Application Received Date:	Not reported
Affiliation Type:	Permittee
Permit EI Type:	Water Treatment Wastewater-GP
App Id:	201005681
Site Address Description:	Not reported
Site Address Line 2:	Not reported
Permit Description:	Not reported
Status:	Expired
Affiliate Address Line 1:	2 FORBES ST
Affiliate Address Line 2:	Not reported
Affiliate City/State/Zip:	EAST HARTFORD, CT 06108-3727
Contact Name:	CHRIS FEIDLER
Contact Title:	MILL MANAGER
Contact EMail:	CHRISTOPHER.FIELDER@CLEARWATERPAPER.COM
Name:	DUNN PAPER - EAST HARTFORD, LLC
Address:	40 FORBES ST
City:	EAST HARTFORD
Town Id:	Not reported
Company Name:	Not reported
Permit Number:	GWT000212

DUNN PAPER - EAST HARTFORD, LLC (Continued) **S120925881**

Permit Issued Date:	05/03/2016
Permit Expiration Date:	03/29/2017
Application Received Date:	Not reported
Affiliation Type:	Registrant
Permit EI Type:	Water Treatment Wastewater-GP
App Id:	201505595
Site Address Description:	Not reported
Site Address Line 2:	Not reported
Permit Description:	Permit No. GWT000212
Status:	Expired
Affiliate Address Line 1:	2 FORBES ST
Affiliate Address Line 2:	Not reported
Affiliate City/State/Zip:	EAST HARTFORD, CT 06108-3727
Contact Name:	JAMES DICKERSON
Contact Title:	Not reported
Contact EMail:	DickersonJ@dunnpaper.com

Name:	DUNN PAPER - EAST HARTFORD, LLC
Address:	40 FORBES ST
City:	EAST HARTFORD
Town Id:	Not reported
Company Name:	Not reported
Permit Number:	GWT000221
Permit Issued Date:	07/01/2016
Permit Expiration Date:	03/29/2018
Application Received Date:	Not reported
Affiliation Type:	Registrant
Permit EI Type:	Water Treatment Wastewater-GP
App Id:	201505594
Site Address Description:	Not reported
Site Address Line 2:	Not reported
Permit Description:	Permit No. GWT000221
Status:	Expired
Affiliate Address Line 1:	2 FORBES ST
Affiliate Address Line 2:	Not reported
Affiliate City/State/Zip:	EAST HARTFORD, CT 06108-3727
Contact Name:	JAMES DICKERSON
Contact Title:	Not reported
Contact EMail:	DickersonJ@dunnpaper.com

Name:	DUNN PAPER - EAST HARTFORD, LLC
Address:	40 FORBES ST
City:	EAST HARTFORD
Town Id:	Not reported
Company Name:	Not reported
Permit Number:	CTMIU0036
Permit Issued Date:	01/28/2020
Permit Expiration Date:	10/30/2020
Application Received Date:	Not reported
Affiliation Type:	Registrant
Permit EI Type:	Miscellaneous Sewer Discharges-GP
App Id:	201814646
Site Address Description:	Not reported
Site Address Line 2:	Not reported
Permit Description:	MODIFICATION TO PERMIT #CTMIU0036, 40 FORBES ST., EAST HARTFORD
Status:	Expired
Affiliate Address Line 1:	2 FORBES ST

DUNN PAPER - EAST HARTFORD, LLC (Continued) **S120925881**

Affiliate Address Line 2:	Not reported
Affiliate City/State/Zip:	EAST HARTFORD, CT 06108-3727
Contact Name:	JAMES DICKERSON
Contact Title:	Not reported
Contact EMail:	DickersonJ@dunnpaper.com
Name:	DUNN PAPER - EAST HARTFORD, LLC
Address:	40 FORBES ST
City:	EAST HARTFORD
Town Id:	Not reported
Company Name:	Not reported
Permit Number:	CTCSW0043
Permit Issued Date:	10/20/2022
Permit Expiration Date:	04/01/2025
Application Received Date:	Not reported
Affiliation Type:	Registrant
Permit EI Type:	Comprehensive Wastewater Discharge GP-Surface water
App Id:	202206268
Site Address Description:	Not reported
Site Address Line 2:	Not reported
Permit Description:	TREATMENT OF RIVER WATER FOR USE IN PAPER MAKING. - EAST HARTFORD, CT
Status:	Active
Affiliate Address Line 1:	2 FORBES ST
Affiliate Address Line 2:	Not reported
Affiliate City/State/Zip:	EAST HARTFORD, CT 06108-3727
Contact Name:	JAMES DICKERSON
Contact Title:	Not reported
Contact EMail:	DickersonJ@dunnpaper.com
Name:	DUNN PAPER - EAST HARTFORD, LLC
Address:	40 FORBES ST
City:	EAST HARTFORD
Town Id:	Not reported
Company Name:	Not reported
Permit Number:	GSI001634
Permit Issued Date:	05/01/2003
Permit Expiration Date:	10/01/2007
Application Received Date:	Not reported
Affiliation Type:	Permittee
Permit EI Type:	Stormwater Industrial Activities - GP
App Id:	200301314
Site Address Description:	Not reported
Site Address Line 2:	Not reported
Permit Description:	STORMWATER INDUSTRIAL
Status:	Expired
Affiliate Address Line 1:	2 FORBES ST
Affiliate Address Line 2:	Not reported
Affiliate City/State/Zip:	EAST HARTFORD, CT 06108-3727
Contact Name:	CHRIS FEIDLER
Contact Title:	MILL MANAGER
Contact EMail:	CHRISTOPHER.FIELDER@CLEARWATERPAPER.COM
Name:	DUNN PAPER - EAST HARTFORD, LLC
Address:	40 FORBES ST
City:	EAST HARTFORD
Town Id:	Not reported
Company Name:	Not reported

DUNN PAPER - EAST HARTFORD, LLC (Continued) **S120925881**

Permit Number:	GSI001634
Permit Issued Date:	06/05/2009
Permit Expiration Date:	10/01/2011
Application Received Date:	Not reported
Affiliation Type:	Permittee
Permit EI Type:	Stormwater Industrial Activities - GP
App Id:	200901669
Site Address Description:	Not reported
Site Address Line 2:	Not reported
Permit Description:	Not reported
Status:	Expired
Affiliate Address Line 1:	2 FORBES ST
Affiliate Address Line 2:	Not reported
Affiliate City/State/Zip:	EAST HARTFORD, CT 06108-3727
Contact Name:	CHRIS FEIDLER
Contact Title:	MILL MANAGER
Contact EMail:	CHRISTOPHER.FIELDER@CLEARWATERPAPER.COM

Name:	DUNN PAPER - EAST HARTFORD, LLC
Address:	40 FORBES ST
City:	EAST HARTFORD
Town Id:	Not reported
Company Name:	Not reported
Permit Number:	GSI002727
Permit Issued Date:	08/29/2015
Permit Expiration Date:	09/30/2024
Application Received Date:	Not reported
Affiliation Type:	Registrant
Permit EI Type:	Stormwater Industrial Activities - GP
App Id:	201503959
Site Address Description:	Not reported
Site Address Line 2:	Not reported
Permit Description:	Paper manufacturing
Status:	Active
Affiliate Address Line 1:	2 FORBES ST
Affiliate Address Line 2:	Not reported
Affiliate City/State/Zip:	EAST HARTFORD, CT 06108-3727
Contact Name:	MARTHA SMIGEL
Contact Title:	Not reported
Contact EMail:	Not reported

Name:	DUNN PAPER - EAST HARTFORD, LLC
Address:	40 FORBES ST
City:	EAST HARTFORD
Town Id:	Not reported
Company Name:	Not reported
Permit Number:	GSI001634
Permit Issued Date:	11/05/2011
Permit Expiration Date:	09/30/2024
Application Received Date:	Not reported
Affiliation Type:	Permittee
Permit EI Type:	Stormwater Industrial Activities - GP
App Id:	201105475
Site Address Description:	Not reported
Site Address Line 2:	Not reported
Permit Description:	Not reported
Status:	Active

DUNN PAPER - EAST HARTFORD, LLC (Continued) **S120925881**

Affiliate Address Line 1:	2 FORBES ST
Affiliate Address Line 2:	Not reported
Affiliate City/State/Zip:	EAST HARTFORD, CT 06108-3727
Contact Name:	CHRIS FEIDLER
Contact Title:	MILL MANAGER
Contact EMail:	CHRISTOPHER.FIELDER@CLEARWATERPAPER.COM

E31 **DUNN PAPER - EAST HARTFORD. LLC** **FINDS** **1027117417**
South **40 FORBES STREET** **PFAS ECHO** **N/A**
1/8-1/4 **EAST HARTFORD, CT 06108**
0.208 mi.
1097 ft. **Site 3 of 12 in cluster E**

Relative:
Lower

Actual:
52 ft.

FINDS:
Registry ID: 110071147421

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The National Pollutant Discharge Elimination System (NPDES) module of the Integrated Compliance Information System (ICIS). Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.
THE ELECTRONIC GREENHOUSE GAS REPORTING TOOL (E-GGRT) IS ACCESSIBLE THROUGH AN EPA WEB PAGE AND USED TO SUBMIT ANNUAL REPORTS IN SUPPORT OF THE EPA RULE FOR MANDATORY REPORTING OF GREENHOUSE GASES (GHG) FROM LARGE GHG EMISSIONS SOURCES. IMPLEMENTATION OF 40 CFR PART 98 IS REFERRED TO AS THE GREENHOUSE GAS REPORTING PROGRAM (GHGRP). THIS COMPREHENSIVE, NATIONWIDE EMISSIONS DATA WILL PROVIDE A BETTER UNDERSTANDING OF THE SOURCES OF GHGS AND WILL GUIDE DEVELOPMENT OF THE POLICIES AND PROGRAMS TO REDUCE EMISSIONS. THE PUBLICALLY AVAILABLE DATA WILL ALLOW REPORTERS TO TRACK THEIR OWN EMISSIONS, COMPARE THEM TO SIMILAR FACILITIES, AND AID IN IDENTIFYING COST EFFECTIVE OPPORTUNITIES TO REDUCE EMISSIONS IN THE FUTURE.
CEDRI is a web application used by EPA programs and various stakeholders to manage environmental data transmitted to EPA in order to meet EPA's reporting requirements.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

PFAS ECHO:

Facility ID:	110071147421
Name:	Dunn Paper - East Hartford. Llc
Address:	40 FORBES STREET
City,State,Zip:	EAST HARTFORD, CT 06108
Latitude:	41.77566
Longitude:	-72.6072
Count:	1
County:	HARTFORD COUNTY
Status:	Active
Region:	01
Industry:	Paper Mills and Products

ECHO Facility Report:
Facility Percent Minority: 56.192

DUNN PAPER - EAST HARTFORD. LLC (Continued) **1027117417**

Facility Derived Tribes:	-
Facility Population:	2095.27
EPA Programs:	CWA
Federal Facility:	No
Federal Agency:	-
Facility FIPS Code:	09003
Facility Indian Country Flag:	N
Facility Collection Method:	ADDRESS MATCHING-HOUSE NUMBER
Facility Derived HUC:	01080205
Facility Derived WBD:	010802050402
Facility Derived CD113:	01
Facility Derived CB2010:	090035105001001
Facility Major Flag:	-
Facility Active Flag:	Y
Facility Inspection Count:	0
Facility Date Last Inspection:	-
Facility Days Last Inspection:	-
Facility Informal Count:	0
Facility Date Last Informal Action:	-
Facility Formal Action Count:	0
Facility Date Last Formal Action:	-
Facility Total Penalties:	0
Facility Penalty Count:	-
Facility Date Last Penalty:	-
Facility Last Penalty AMT:	0
Facility QTRS With NC:	0
Facility Programs With SNC:	0
Facility Compliance Status:	No Violation Identified
Facility SNC Flag:	N
AIR Flag:	N
NPDES Flag:	Y
SDWIS Flag:	N
RCRA Flag:	N
TRI Flag:	N
GHG Flag:	Y
AIR IDS:	-
CAA Permit Types:	-
CAA NAICS:	-
CAA SICS:	-
NPDES IDS:	CTCSW0043 CTGSI2727 CTSIU0085
CWA Permit Types:	Non-M
CWA NAICS:	-
CWA SICS:	-
RCRA IDS:	-
RCRA Permit Types:	-
RCRA NAICS:	-
SDWA IDS:	-
SDWA System Types:	-
SDWA Compliance Status:	-
SDWA SNC Flag:	N
TRI IDS:	-
TRI Releases Transfers:	-
TRI On Site Releases:	-
TRI Off Site Transfers:	-
TRI Reporter:	-
Facility IMP Water Flag:	Y

E32 **DUNN PAPER - EAST HARTFORD, LLC** **CT UST** **U002028261**
South **40 FORBES ST** **N/A**
1/8-1/4 **EAST HARTFORD, CT 06108**
0.208 mi.
1097 ft. **Site 4 of 12 in cluster E**

Relative:
Lower

Actual:
52 ft.

UST:

Name:	DUNN PAPER - EAST HARTFORD, LLC
Address:	40 FORBES ST
Address 2:	Not reported
City,State,Zip:	EAST HARTFORD 06108
Facility ID:	43-5066
Substance:	Heating Oil(on-site consumption)
Last Use Date:	05/01/1987
Tank ID:	A1
Closure Status:	Tank was Removed From Ground
Compartment ID:	a
Tank Status:	Permanently Closed
Secondary Material:	Not reported
Tank Material:	Asphalt Coated or Bare Steel
Capacity:	5000
Install Date:	01/01/1956
Overfill Installed:	Not reported
Pipe Material:	Bare Steel
Pipe Mode Description:	Not reported
Spill Installed:	Not reported
Latitude:	41.77583
Longitude:	-72.60668
Tank Latitude:	41.775724
Tank Longitude:	-72.60804

Contact:

Facility ID:	43-5066
Owner Name:	DUNN PAPER-EAST HARTFORD, LLC.
Owner Address:	2 FORBES ST
Owner Address 2:	Not reported
Owner Phone:	(203) 289-7496
Owner Phone Ext:	Not reported
Owner City/State/Zip:	EAST HARTFORD, CT 061083727
Affiliation Type:	Owner
Contact Name:	Not reported
Contact Title:	Not reported
Contact Email:	Not reported

Facility ID:	43-5066
Owner Name:	DUNN PAPER-EAST HARTFORD, LLC.
Owner Address:	2 FORBES ST
Owner Address 2:	Not reported
Owner Phone:	Not reported
Owner Phone Ext:	Not reported
Owner City/State/Zip:	EAST HARTFORD, CT 061083727
Affiliation Type:	Registrant
Contact Name:	Not reported
Contact Title:	Not reported
Contact Email:	Not reported

E33 **CELLU TISSUE CORP** **CT SPILLS** **1009511925**
South **2 FORBES STREET** **FTTS** **N/A**
1/8-1/4 **EAST HARTFORD, CT 06108** **HIST FTTS**
0.210 mi. **CT LWDS**
1110 ft. **Site 5 of 12 in cluster E**

Relative: **Lower**
Actual: **48 ft.**

SPILLS:

Name:	Not reported
Address:	2 FORBES STREET
City,State,Zip:	EAST HARTFORD, CT
Year of Database:	2003
Case Number:	200305339
Who Took Spill:	205
Assigned To:	Coss, Brian
Report Date:	07/18/2003
Report Time:	12:00:00 AM
Date Release:	07/18/2003
Release Time:	12:00:00 AM
Reported By:	anonymous
Phone:	860 0000000
Qty:	0.00 (Gallons)
Telephone:	Not reported
Representing:	Self
Facility Status:	Closed
Continuous Spill:	False
Release Substance:	UNKNOWN CHEMICAL
Emergency Measure:	papermill at above address, Sell-U Tissue, is dumping some type of chemical into CT River tributary, observed at 1648 hrs, parties are attempting to cover up situation.
Discharger:	Not reported
Waterbody Affected:	River
Responsible Party:	Not reported
Responsible Party Address:	Not reported
RP City,St,Zip:	CT
Terminated:	YES
Recovered Total:	0
Total Water:	0
Historic:	False
Waterbody:	ct
User Stamp:	Not reported
Stamp Time:	2004-04-15 14:48:25
SR Inspector:	caruolo,robert
AT Inspector:	Coss, Brian
Corrective Action Taken:	None Required
Cause Info:	Dumping
Media Info:	Surface Water
Release Type:	chemical
Incident Description:	Not reported
Cost Recovery Case?:	Not reported
DEMHS Region:	Not reported
Lat/Long:	Not reported
Company Name:	Not reported
Last Updated:	Not reported

Action:

Action:	None Required
Other Action:	Not reported

Agency:

CELLU TISSUE CORP (Continued) **1009511925**

Agency ID:	DEP Dispatch
Other Agency:	Not reported
DEP Bureau:	Not reported
DEP Agency:	Not reported

Cause:

Cause ID:	Dumping
Other Cause:	Not reported

Media:

Media ID:	Surface Water
Other Media:	Not reported

Release Class:

Class ID:	Commercial
Other Class:	Not reported

Release Type:

Release Type:	chemical
Other Release:	Not reported

Waterbody:

Waterbody:	River
Other Waterbody:	Not reported

Name:	Not reported
Address:	2 FORBES STREET
City,State,Zip:	EAST HARTFORD, CT
Year of Database:	2006
Case Number:	200602237
Who Took Spill:	202
Assigned To:	Thigpen, Donnell
Report Date:	04/20/2006
Report Time:	12:00:00 AM
Date Release:	04/20/2006
Release Time:	12:00:00 AM
Reported By:	mitch kielbania
Phone:	860 4664156
Qty:	100.00 (Gallons)
Telephone:	Not reported
Representing:	cell u tissue
Facility Status:	CLOSED
Continuous Spill:	False
Release Substance:	paper stock
Emergency Measure:	Not reported
Discharger:	Not reported
Waterbody Affected:	River
Responsible Party:	Not reported
Responsible Party Address:	Not reported
RP City,St,Zip:	CT
Terminated:	YES
Recovered Total:	0
Total Water:	0
Historic:	False

CELLU TISSUE CORP (Continued) **1009511925**

Waterbody:	hoccanum river
User Stamp:	mgranill
Stamp Time:	2006-04-28 15:13:13
SR Inspector:	Mazzoccolli,Christina
AT Inspector:	THIGPEN, DONNELL
Corrective Action Taken:	Other (937 called)
Cause Info:	Other (pipe overflow)
Media Info:	Surface Water, and Ground Surface
Release Type:	chemical
Incident Description:	Not reported
Cost Recovery Case?:	Not reported
DEMHS Region:	Not reported
Lat/Long:	Not reported
Company Name:	Not reported
Last Updated:	Not reported

Action:

Action:	Other
Other Action:	937 called

Agency:

Agency ID:	DEP Dispatch
Other Agency:	Not reported
DEP Bureau:	Not reported
DEP Agency:	Not reported

Cause:

Cause ID:	Other
Other Cause:	pipe overflow

Media:

Media ID:	Surface Water
Other Media:	Not reported
Media ID:	Ground Surface
Other Media:	Not reported

Release Class:

Class ID:	Industrial
Other Class:	Not reported

Release Type:

Release Type:	chemical
Other Release:	Not reported

Waterbody:

Waterbody:	River
Other Waterbody:	Not reported

Name:	Not reported
Address:	2 FORBES STREET
City,State,Zip:	EAST HARTFORD, CT
Year of Database:	2010
Case Number:	201003216

CELLU TISSUE CORP (Continued) **1009511925**

Who Took Spill:	205
Assigned To:	Emanuelson, Brian
Report Date:	06/01/2010
Report Time:	12:00:00 AM
Date Release:	06/01/2010
Release Time:	12:00:00 AM
Reported By:	Aaron Nidorno
Phone:	860 3292401
Qty:	< 5.00 (Gallons)
Telephone:	860 2802401
Representing:	CL&P
Facility Status:	CLOSED
Continuous Spill:	False
Release Substance:	TRANSFORMER OIL
Emergency Measure:	<10 ppm.
Discharger:	CL&P
Waterbody Affected:	Other (none)
Responsible Party:	true
Responsible Party Address:	410 SHELDEN STREET
RP City,St,Zip:	HARTFORD, CT 06103
Terminated:	YES
Recovered Total:	0
Total Water:	0
Historic:	False
Waterbody:	n/a
User Stamp:	mgranill
Stamp Time:	2010-06-30 13:40:13
SR Inspector:	Cox, Michael
AT Inspector:	Emanuelson, Brian
Corrective Action Taken:	Contracted, and Other (ESI)
Cause Info:	Trans/Capac.
Media Info:	Ground Surface
Release Type:	dielect
Incident Description:	Not reported
Cost Recovery Case?:	Not reported
DEMHS Region:	Not reported
Lat/Long:	Not reported
Company Name:	Not reported
Last Updated:	Not reported

Action:

Action:	Contracted
Other Action:	Not reported
Action:	Other
Other Action:	ESI

Agency:

Agency ID:	DEP Dispatch
Other Agency:	Not reported
DEP Bureau:	Not reported
DEP Agency:	Not reported

Cause:

Cause ID:	Trans/Capac.
Other Cause:	Not reported

CELLU TISSUE CORP (Continued) **1009511925**

Media:
Media ID: Ground Surface
Other Media: Not reported

Release Class:
Class ID: Utility
Other Class: Not reported

Release Type:
Release Type: dielect
Other Release: Not reported

Waterbody:
Waterbody: Other
Other Waterbody: none

Name: Not reported
Address: 2 FORBES STREET
City,State,Zip: EAST HARTFORD, CT
Year of Database: 1996
Case Number: 9604050
Who Took Spill: 916
Assigned To: Alexander, Ed
Report Date: Not reported
Report Time: Not reported
Date Release: Not reported
Release Time: Not reported
Reported By: ENVIRO SERVICES
Phone: 5289500
Qty: 0.00 (Gallons)
Telephone: 2897496
Representing: CELLA-TISSUE
Facility Status: CLOSED
Continuous Spill: False
Release Substance: #2 FUEL OIL
Emergency Measure: EXCAVATED SOIL
Discharger: JOE
Waterbody Affected: Not reported
Responsible Party: Not reported
Responsible Party Address: Not reported
RP City,St,Zip: CT
Terminated: YES
Recovered Total: 0
Total Water: 0
Historic: False
Waterbody: Not reported
User Stamp: Not reported
Stamp Time: 1997-07-02 10:25:34
SR Inspector: Stavola, Rosanne
AT Inspector: Alexander, Ed
Corrective Action Taken: Not reported
Cause Info: Not reported
Media Info: Not reported
Release Type: Not reported

CELLU TISSUE CORP (Continued) **1009511925**

Incident Description:	Not reported
Cost Recovery Case?:	Not reported
DEMHS Region:	Not reported
Lat/Long:	Not reported
Company Name:	Not reported
Last Updated:	Not reported

Action:

Action:	Soil Removed
Other Action:	Not reported

Cause:

Cause ID:	Inground Tank Failure
Other Cause:	Not reported

Media:

Media ID:	Ground Surface
Other Media:	Not reported

Release Class:

Class ID:	Industrial
Other Class:	Not reported

Release Type:

Release Type:	petroleum
Other Release:	Not reported

Name:	Not reported
Address:	2 FORBES STREET
City,State,Zip:	EAST HARTFORD, CT
Year of Database:	1996
Case Number:	9604050
Who Took Spill:	916
Assigned To:	Alexander, Ed
Report Date:	Not reported
Report Time:	Not reported
Date Release:	Not reported
Release Time:	Not reported
Reported By:	ENVIRO SERVICES
Phone:	5289500
Qty:	0.00 (Gallons)
Telephone:	2897496
Representing:	CELLA-TISSUE
Facility Status:	CLOSED
Continuous Spill:	False
Release Substance:	#2 FUEL OIL
Emergency Measure:	EXCAVATED SOIL
Discharger:	JOE
Waterbody Affected:	Not reported
Responsible Party:	Not reported
Responsible Party Address:	Not reported
RP City,St,Zip:	CT
Terminated:	YES
Recovered Total:	0
Total Water:	0

CELLU TISSUE CORP (Continued) **1009511925**

Historic:	False
Waterbody:	Not reported
User Stamp:	Not reported
Stamp Time:	1997-07-02 10:25:34
SR Inspector:	Stavola, Rosanne
AT Inspector:	Alexander, Ed
Corrective Action Taken:	Soil Removed
Cause Info:	Inground Tank Failure
Media Info:	Ground Surface
Release Type:	petroleum
Incident Description:	Not reported
Cost Recovery Case?:	Not reported
DEMHS Region:	Not reported
Lat/Long:	Not reported
Company Name:	Not reported
Last Updated:	Not reported

Action:

Action:	Soil Removed
Other Action:	Not reported

Cause:

Cause ID:	Inground Tank Failure
Other Cause:	Not reported

Media:

Media ID:	Ground Surface
Other Media:	Not reported

Release Class:

Class ID:	Industrial
Other Class:	Not reported

Release Type:

Release Type:	petroleum
Other Release:	Not reported

Name:	Not reported
Address:	2 FORBES STREET
City,State,Zip:	EAST HARTFORD, CT
Year of Database:	1996
Case Number:	9604050
Who Took Spill:	916
Assigned To:	Alexander, Ed
Report Date:	Not reported
Report Time:	Not reported
Date Release:	Not reported
Release Time:	Not reported
Reported By:	ENVIRO SERVICES
Phone:	5289500
Qty:	0.00 (Gallons)
Telephone:	2897496
Representing:	CELLA-TISSUE
Facility Status:	CLOSED
Continuous Spill:	False

CELLU TISSUE CORP (Continued) **1009511925**

Release Substance:	#2 FUEL OIL
Emergency Measure:	EXCAVATED SOIL
Discharger:	JOE
Waterbody Affected:	Not reported
Responsible Party:	Not reported
Responsible Party Address:	Not reported
RP City,St,Zip:	CT
Terminated:	YES
Recovered Total:	0
Total Water:	0
Historic:	False
Waterbody:	Not reported
User Stamp:	Not reported
Stamp Time:	1997-07-02 10:25:34
SR Inspector:	Stavola, Rosanne
AT Inspector:	Alexander, Ed
Corrective Action Taken:	Not reported
Cause Info:	Not reported
Media Info:	Not reported
Release Type:	Not reported
Incident Description:	Not reported
Cost Recovery Case?:	Not reported
DEMHS Region:	Not reported
Lat/Long:	Not reported
Company Name:	Not reported
Last Updated:	Not reported

Action:

Action:	Soil Removed
Other Action:	Not reported

Cause:

Cause ID:	Inground Tank Failure
Other Cause:	Not reported

Media:

Media ID:	Ground Surface
Other Media:	Not reported

Release Class:

Class ID:	Industrial
Other Class:	Not reported

Release Type:

Release Type:	petroleum
Other Release:	Not reported

Name:	Not reported
Address:	2 FORBES STREET
City,State,Zip:	EAST HARTFORD, CT
Year of Database:	1996
Case Number:	9604050
Who Took Spill:	916
Assigned To:	Alexander, Ed
Report Date:	Not reported

CELLU TISSUE CORP (Continued) **1009511925**

Report Time:	Not reported
Date Release:	Not reported
Release Time:	Not reported
Reported By:	ENVIRO SERVICES
Phone:	5289500
Qty:	0.00 (Gallons)
Telephone:	2897496
Representing:	CELLA-TISSUE
Facility Status:	CLOSED
Continuous Spill:	False
Release Substance:	#2 FUEL OIL
Emergency Measure:	EXCAVATED SOIL
Discharger:	JOE
Waterbody Affected:	Not reported
Responsible Party:	Not reported
Responsible Party Address:	Not reported
RP City,St,Zip:	CT
Terminated:	YES
Recovered Total:	0
Total Water:	0
Historic:	False
Waterbody:	Not reported
User Stamp:	Not reported
Stamp Time:	1997-07-02 10:25:34
SR Inspector:	Stavola, Rosanne
AT Inspector:	Alexander, Ed
Corrective Action Taken:	Not reported
Cause Info:	Not reported
Media Info:	Not reported
Release Type:	Not reported
Incident Description:	Not reported
Cost Recovery Case?:	Not reported
DEMHS Region:	Not reported
Lat/Long:	Not reported
Company Name:	Not reported
Last Updated:	Not reported

Action:

Action:	Soil Removed
Other Action:	Not reported

Cause:

Cause ID:	Inground Tank Failure
Other Cause:	Not reported

Media:

Media ID:	Ground Surface
Other Media:	Not reported

Release Class:

Class ID:	Industrial
Other Class:	Not reported

Release Type:

Release Type:	petroleum
Other Release:	Not reported

CELLU TISSUE CORP (Continued) **1009511925**

Name:	Not reported
Address:	2 FORBES STREET
City,State,Zip:	EAST HARTFORD, CT
Year of Database:	1996
Case Number:	9604050
Who Took Spill:	916
Assigned To:	Alexander, Ed
Report Date:	Not reported
Report Time:	Not reported
Date Release:	Not reported
Release Time:	Not reported
Reported By:	ENVIRO SERVICES
Phone:	5289500
Qty:	0.00 (Gallons)
Telephone:	2897496
Representing:	CELLA-TISSUE
Facility Status:	CLOSED
Continuous Spill:	False
Release Substance:	#2 FUEL OIL
Emergency Measure:	EXCAVATED SOIL
Discharger:	JOE
Waterbody Affected:	Not reported
Responsible Party:	Not reported
Responsible Party Address:	Not reported
RP City,St,Zip:	CT
Terminated:	YES
Recovered Total:	0
Total Water:	0
Historic:	False
Waterbody:	Not reported
User Stamp:	Not reported
Stamp Time:	1997-07-02 10:25:34
SR Inspector:	Stavola, Rosanne
AT Inspector:	Alexander, Ed
Corrective Action Taken:	Not reported
Cause Info:	Not reported
Media Info:	Not reported
Release Type:	Not reported
Incident Description:	Not reported
Cost Recovery Case?:	Not reported
DEMHS Region:	Not reported
Lat/Long:	Not reported
Company Name:	Not reported
Last Updated:	Not reported

Action:

Action:	Soil Removed
Other Action:	Not reported

Cause:

Cause ID:	Inground Tank Failure
Other Cause:	Not reported

Media:

Media ID:	Ground Surface
Other Media:	Not reported

CELLU TISSUE CORP (Continued) **1009511925**

Release Class:
Class ID: Industrial
Other Class: Not reported

Release Type:
Release Type: petroleum
Other Release: Not reported

Name: Not reported
Address: 2 FORBES STREET
City,State,Zip: EAST HARTFORD, CT
Year of Database: 1996
Case Number: 9604050
Who Took Spill: 916
Assigned To: Alexander, Ed
Report Date: Not reported
Report Time: Not reported
Date Release: Not reported
Release Time: Not reported
Reported By: ENVIRO SERVICES
Phone: 5289500
Qty: 0.00 (Gallons)
Telephone: 2897496
Representing: CELLA-TISSUE
Facility Status: CLOSED
Continuous Spill: False
Release Substance: #2 FUEL OIL
Emergency Measure: EXCAVATED SOIL
Discharger: JOE
Waterbody Affected: Not reported
Responsible Party: Not reported
Responsible Party Address: Not reported
RP City,St,Zip: CT
Terminated: YES
Recovered Total: 0
Total Water: 0
Historic: False
Waterbody: Not reported
User Stamp: Not reported
Stamp Time: 1997-07-02 10:25:34
SR Inspector: Stavola, Rosanne
AT Inspector: Alexander, Ed
Corrective Action Taken: Not reported
Cause Info: Not reported
Media Info: Not reported
Release Type: Not reported
Incident Description: Not reported
Cost Recovery Case?: Not reported
DEMHS Region: Not reported
Lat/Long: Not reported
Company Name: Not reported
Last Updated: Not reported

Action:
Action: Soil Removed
Other Action: Not reported

CELLU TISSUE CORP (Continued) **1009511925**

Cause:
Cause ID: Inground Tank Failure
Other Cause: Not reported

Media:
Media ID: Ground Surface
Other Media: Not reported

Release Class:
Class ID: Industrial
Other Class: Not reported

Release Type:
Release Type: petroleum
Other Release: Not reported

Name: Not reported
Address: 2 FORBES STREET
City,State,Zip: EAST HARTFORD, CT
Year of Database: 1996
Case Number: 9604050
Who Took Spill: 916
Assigned To: Alexander, Ed
Report Date: Not reported
Report Time: Not reported
Date Release: Not reported
Release Time: Not reported
Reported By: ENVIRO SERVICES
Phone: 5289500
Qty: 0.00 (Gallons)
Telephone: 2897496
Representing: CELLA-TISSUE
Facility Status: CLOSED
Continuous Spill: False
Release Substance: #2 FUEL OIL
Emergency Measure: EXCAVATED SOIL
Discharger: JOE
Waterbody Affected: Not reported
Responsible Party: Not reported
Responsible Party Address: Not reported
RP City,St,Zip: CT
Terminated: YES
Recovered Total: 0
Total Water: 0
Historic: False
Waterbody: Not reported
User Stamp: Not reported
Stamp Time: 1997-07-02 10:25:34
SR Inspector: Stavola, Rosanne
AT Inspector: Alexander, Ed
Corrective Action Taken: Not reported
Cause Info: Not reported
Media Info: Not reported
Release Type: Not reported

CELLU TISSUE CORP (Continued) **1009511925**

Incident Description:	Not reported
Cost Recovery Case?:	Not reported
DEMHS Region:	Not reported
Lat/Long:	Not reported
Company Name:	Not reported
Last Updated:	Not reported

Action:

Action:	Soil Removed
Other Action:	Not reported

Cause:

Cause ID:	Inground Tank Failure
Other Cause:	Not reported

Media:

Media ID:	Ground Surface
Other Media:	Not reported

Release Class:

Class ID:	Industrial
Other Class:	Not reported

Release Type:

Release Type:	petroleum
Other Release:	Not reported

Name:	Not reported
Address:	2 FORBES STREET
City,State,Zip:	EAST HARTFORD, CT
Year of Database:	1996
Case Number:	9604050
Who Took Spill:	916
Assigned To:	Alexander, Ed
Report Date:	Not reported
Report Time:	Not reported
Date Release:	Not reported
Release Time:	Not reported
Reported By:	ENVIRO SERVICES
Phone:	5289500
Qty:	0.00 (Gallons)
Telephone:	2897496
Representing:	CELLA-TISSUE
Facility Status:	CLOSED
Continuous Spill:	False
Release Substance:	#2 FUEL OIL
Emergency Measure:	EXCAVATED SOIL
Discharger:	JOE
Waterbody Affected:	Not reported
Responsible Party:	Not reported
Responsible Party Address:	Not reported
RP City,St,Zip:	CT
Terminated:	YES
Recovered Total:	0
Total Water:	0

CELLU TISSUE CORP (Continued) **1009511925**

Historic:	False
Waterbody:	Not reported
User Stamp:	Not reported
Stamp Time:	1997-07-02 10:25:34
SR Inspector:	Stavola, Rosanne
AT Inspector:	Alexander, Ed
Corrective Action Taken:	Not reported
Cause Info:	Not reported
Media Info:	Not reported
Release Type:	Not reported
Incident Description:	Not reported
Cost Recovery Case?:	Not reported
DEMHS Region:	Not reported
Lat/Long:	Not reported
Company Name:	Not reported
Last Updated:	Not reported

Action:

Action:	Soil Removed
Other Action:	Not reported

Cause:

Cause ID:	Inground Tank Failure
Other Cause:	Not reported

Media:

Media ID:	Ground Surface
Other Media:	Not reported

Release Class:

Class ID:	Industrial
Other Class:	Not reported

Release Type:

Release Type:	petroleum
Other Release:	Not reported

FTTS INSP:

Inspection Number:	19910522CT021 1
Region:	01
Inspection Date:	05/22/91
Inspector:	WILSON
Violation occurred:	No
Investigation Type:	Section 6 PCB State Conducted
Investigation Reason:	Neutral Scheme, State
Legislation Code:	TSCA
Facility Function:	User

HIST FTTS INSP:

Inspection Number:	19910522CT021 1
Region:	01

CELLU TISSUE CORP (Continued) **1009511925**

Inspection Date: Not reported
Inspector: WILSON
Violation occurred: No
Investigation Type: Section 6 PCB State Conducted
Investigation Reason: Neutral Scheme, State
Legislation Code: TSCA
Facility Function: User

LWDS:
Leachate and Wastewater Number: 4500036
Status of the Discharge Activity: Inactive
Leachate and Waste Flow: Ground
Alias: Cellu Tissue Corp
Alias2: Not reported

Leachate and Wastewater Number: 4500037
Status of the Discharge Activity: Active
Leachate and Waste Flow: Surface
Alias: Cellu Tissue Corp
Alias2: Not reported

E34 **DUNN PAPER - EAST HARTFORD, LLC** **CT LUST** **S109727068**
South **2 FORBES STREET** **CT SPILLS** **N/A**
1/8-1/4 **EAST HARTFORD, CT 06108** **CT CPCS**
0.210 mi.
1110 ft. **Site 6 of 12 in cluster E**

Relative:
Lower

Actual:
48 ft.

LUST:
Name: DUNN PAPER - EAST HARTFORD, LLC
Name 2: Not reported
Address: 2 FORBES STREET
Address 2: Not reported
City,State,Zip: EAST HARTFORD, CT 06108
LUST Case Id: 32398
Release Date: Not reported
Site Case ID: 9604050
Substance: Not reported
Release Source: Not reported
Release Cause: Not reported
Release Identified: Not reported
Case Number: Not reported
Release Quantity: Not reported
Facility City Number: 43

Detail As of 06/2020:
Name: DUNN PAPER - EAST HARTFORD, LLC
Name 2: Not reported
Address: 2 FORBES STREET
City,State,Zip: EAST HARTFORD, CT 06108
Address 2: Not reported
LUST Id: 4226
UST Facility Id: 5066
LUST Case Id: 32398
Lust Status: Investigation
Processing Status: Not reported
EPA Reportable: False
Motor Fuel: False

DUNN PAPER - EAST HARTFORD, LLC (Continued) **S109727068**

Diesel:	False
Gasoline:	False
Other:	False
Other Release:	Not reported
No Release:	False
Leak:	False
Tank:	False
Piping:	False
Overfill:	False
Removal:	False
Incident Date:	08/09/1996
Entry Date:	Not reported
Site Case Id:	9604050
UST Site Id:	Not reported
Cost Recovery Spill Case #:	Not reported
Old SITS Number:	Not reported
Case Log Id:	Not reported
Monthly Report Id:	0
UST Owner Id:	915
LUST Owner Id:	Not reported
UST Event Id:	4326
Contact Info:	Not reported
Contact EMail:	Not reported
Site Contact City,St,Zip:	UNKNOWN
2nd Contact:	Not reported
2nd Contact EMail:	Not reported
2nd Contact Address:	Not reported
2nd Contact City,St,Zip:	UNKNOWN
2nd Contact Address 2:	Not reported
2nd Contact City 2:	Not reported
2nd Contact Phone Number:	Not reported
2nd Contact Fax Number:	Not reported
2nd Contact Type:	Not reported
Facility City Num:	43
Site Contact:	Not reported
Site Contact Address:	Not reported
Site Contact Add 2:	Not reported
Site Contact City 2:	Not reported
Site Contact Phone:	Not reported
Site Contact Fax:	Not reported
Site Contact Type:	Not reported
Department Contact 1:	Not reported
Department Contact 2:	Not reported
Referral Source:	Not reported
Offsite Source:	False
Date Referred:	Not reported
Emergency:	False
Private Heating Fuel:	False
Commercial Heating Fuel:	True
Commercial HF < 2100 Gal.:	False
Commercial HF > 2100 Gal.:	False
Commercial HF - Size Unk:	True
No LUST Site:	False
Cost Recvry Prgm Candidate:	False
OCSRD Complete:	True
Follow Up Flag:	False
Alternate Water Supply:	False

DUNN PAPER - EAST HARTFORD, LLC (Continued) **S109727068**

Relocation:	False
Responsible Party:	False
Responsible EMail:	Not reported
Resp Party Name:	Cellu Tissue LLC
Resp Party Address:	2 Forbes Street
Resp Party City,St,Zip:	East Hartford, CT 061083727
Resp Party Town Number:	43
Resp Party Phone:	Not reported
Resp Party Fax:	Not reported
Resp Party Name 2:	JOE
Resp Party Address 2:	Not reported
Resp Party Phone 2:	Not reported
Investigator Id:	27
Follow Update:	Not reported
Area Lextent:	Not reported
Annual Precipitation:	Not reported
Affected Population:	Not reported
Population Setting:	Not reported
Ground Water Direction:	Not reported
Ground Water Gradient:	Not reported
Hydro Basin:	Not reported
Drastic:	Not reported
Geo Setting:	Not reported
Ground Water Classification:	Not reported
Receptor:	Not reported
Ground Water Flow Direction:	Not reported
Ground Water Depth:	Not reported
Areas Of Concern:	Not reported
Free Product Inches:	Not reported
Fund Date:	Not reported
Fund Planned:	No
Fund Obligated:	No
Fund Outlayed:	No
Fund Judgment:	No
Fund Recovered:	No
Cellar Borings:	False
Install Micro Wells:	False
Ground Water Sample:	False
Soil Sample:	False
Soil Gas:	False
Site Inspect:	False
Soil Excavate:	False
Geo Probe:	False
Survey:	False
Potable Well Sample:	False
Sample MWS:	False
Ground Water Gauging:	False
Soil Venting:	False
Active:	False
NOV Action:	None
NOV Issued:	Not reported
NOV Due:	Not reported
NOV Received:	Not reported
NOV Closed:	Not reported
NOV Disc Date:	Not reported
NOV Issued Date:	Not reported
NOV Compliance Sched:	Not reported

DUNN PAPER - EAST HARTFORD, LLC (Continued) **S109727068**

NOV Admin Order:	Not reported
NOV Referred To Ag:	Not reported
Stop All NOV Actions:	False
Release Invest Rpt:	False
DEP App Letter 1:	False
Correct Action Plan:	False
DEP App Letter 2:	False
Rem Sys Install:	False
Rem Sys Install Date:	Not reported
Closure Date:	Not reported
Rem Sys Monitoring Rpt:	False
Qrtly Gwater Mon Rpts:	False
Closure Req Rpt:	False
DEP Closure Letter:	False
Referred To:	Not reported
No Wells:	Not reported
Lph Wells:	Not reported
User Stamp:	ForrestA/forrestlaiuppaa
Date Stamp:	02/21/2017
Correspondence:	Not reported
Environmental Impact:	Not reported
FollowUp:	Not reported
GW Comments:	Not reported
Location Desc:	Not reported
NOV Comments:	Not reported
Release Desc:	Not reported
Running Comments:	#2 HEATING OIL, Industrial, EXCAVATED SOIL
Work Performed:	Not reported

SPILLS:

Name:	Not reported
Address:	2 FORBES STREET
City,State,Zip:	EAST HARTFORD, CT
Year of Database:	2016
Case Number:	201606963
Who Took Spill:	205
Assigned To:	No Response
Report Date:	12/22/2016
Report Time:	12:00:00 AM
Date Release:	12/22/2016
Release Time:	12:00:00 AM
Reported By:	james dickerson
Phone:	860 4664147
Qty:	0.00 (Gallons)
Telephone:	Not reported
Representing:	dunn paper
Facility Status:	CLOSED
Continuous Spill:	False
Release Substance:	PAPER FIBER
Emergency Measure:	unknown amount of fiber released in the ppm range to the river - systems have been normalized
Discharger:	saa
Waterbody Affected:	Not reported
Responsible Party:	true
Responsible Party Address:	Not reported
RP City,St,Zip:	CT

DUNN PAPER - EAST HARTFORD, LLC (Continued) **S109727068**

Terminated:	Not reported
Recovered Total:	0
Total Water:	0
Historic:	False
Waterbody:	Not reported
User Stamp:	Guzmanca
Stamp Time:	2016-12-23 12:26:21
SR Inspector:	Cox, Michael
AT Inspector:	**NO RESPONSE
Corrective Action Taken:	Not reported
Cause Info:	Not reported
Media Info:	Other (river)
Release Type:	chemical
Incident Description:	Not reported
Cost Recovery Case?:	Not reported
DEMHS Region:	Not reported
Lat/Long:	Not reported
Company Name:	Not reported
Last Updated:	Not reported

Media:

Media ID:	Other
Other Media:	river

Release Type:

Release Type:	chemical
Other Release:	Not reported

Name:	Not reported
Address:	2 FORBES STREET
City,State,Zip:	EAST HARTFORD, CT
Year of Database:	2017
Case Number:	201700829
Who Took Spill:	205
Assigned To:	No Response
Report Date:	02/20/2017
Report Time:	12:00:00 AM
Date Release:	02/20/2017
Release Time:	12:00:00 AM
Reported By:	james dickerson
Phone:	860 4664147
Qty:	1.00 (Gallons)
Telephone:	Not reported
Representing:	dunn paper
Facility Status:	CLOSED
Continuous Spill:	False
Release Substance:	DIESEL FUEL
Emergency Measure:	speedi dry
Discharger:	saa
Waterbody Affected:	Not reported
Responsible Party:	Not reported
Responsible Party Address:	Not reported
RP City,St,Zip:	CT
Terminated:	YES
Recovered Total:	0
Total Water:	0

DUNN PAPER - EAST HARTFORD, LLC (Continued) **S109727068**

Historic:	False
Waterbody:	Not reported
User Stamp:	Guzmanca
Stamp Time:	2017-02-22 11:34:44
SR Inspector:	Cox, Michael
AT Inspector:	**NO RESPONSE
Corrective Action Taken:	Contained
Cause Info:	OVERFILL
Media Info:	Ground Surface
Release Type:	petroleum
Incident Description:	Not reported
Cost Recovery Case?:	Not reported
DEMHS Region:	Not reported
Lat/Long:	Not reported
Company Name:	Not reported
Last Updated:	Not reported

Action:

Action:	Contained
Other Action:	Not reported

Agency:

Agency ID:	DEP Dispatch
Other Agency:	Not reported
DEP Bureau:	Not reported
DEP Agency:	Not reported

Cause:

Cause ID:	Overfill
Other Cause:	Not reported

Media:

Media ID:	Ground Surface
Other Media:	Not reported

Release Class:

Class ID:	Commercial
Other Class:	Not reported

Release Type:

Release Type:	petroleum
Other Release:	Not reported

Name:	Not reported
Address:	2 FORBES STREET
City,State,Zip:	EAST HARTFORD, CT
Year of Database:	2017
Case Number:	201701599
Who Took Spill:	201
Assigned To:	No Response
Report Date:	04/05/2017
Report Time:	09:50:00 PM
Date Release:	04/05/2017
Release Time:	09:50:00 PM

DUNN PAPER - EAST HARTFORD, LLC (Continued) **S109727068**

Reported By:	james dickerson
Phone:	860 4664147 - 860 7986472
Qty:	0.00 (Gallons)
Telephone:	Not reported
Representing:	dunn paper
Facility Status:	CLOSED
Continuous Spill:	False
Release Substance:	WATER & PH BETWEEN 9 & 11
Emergency Measure:	9,000 gallons treating water overflowed the system
Discharger:	Not reported
Waterbody Affected:	River
Responsible Party:	Not reported
Responsible Party Address:	Not reported
RP City,St,Zip:	CT
Terminated:	YES
Recovered Total:	0
Total Water:	0
Historic:	False
Waterbody:	hockanum river
User Stamp:	Guzmanca
Stamp Time:	2017-04-06 17:50:03
SR Inspector:	Burkey, Rachael
AT Inspector:	**NO RESPONSE
Corrective Action Taken:	None Required
Cause Info:	Other (overflow of water)
Media Info:	Surface Water, and Ground Surface
Release Type:	other (WATER)
Incident Description:	Not reported
Cost Recovery Case?:	Not reported
DEMHS Region:	Not reported
Lat/Long:	Not reported
Company Name:	Not reported
Last Updated:	Not reported

Action:

Action:	None Required
Other Action:	Not reported

Agency:

Agency ID:	DEP Dispatch
Other Agency:	Not reported
DEP Bureau:	Not reported
DEP Agency:	Not reported

Cause:

Cause ID:	Other
Other Cause:	overflow of water

Media:

Media ID:	Surface Water
Other Media:	Not reported
Media ID:	Ground Surface
Other Media:	Not reported

DUNN PAPER - EAST HARTFORD, LLC (Continued) **S109727068**

Release Class:
Class ID: Commercial
Other Class: Not reported

Release Type:
Release Type: other
Other Release: WATER

Waterbody:
Waterbody: River
Other Waterbody: Not reported

CPCS:

Name:	Dunn Paper - East Hartford, Llc
Address:	2 FORBES STREET
City,State,Zip:	EAST HARTFORD, CT
Site Type:	Not reported
Lust Status code:	Not reported
Lust Status:	Not reported
PTP Form:	Not reported
Program:	LUST
Comments:	Not reported
Site Type Definition:	Not reported
Invesigation Start:	Yes
Invesigation Start Date:	Not reported
Remediation Start:	Yes
Remediation Start Date:	Not reported
Remediation Completed:	No
ELUR:	Not reported
Date Data Updated:	08/09/1996

E35 **DUNN PAPER** **E MANIFEST** **1032024892**
South **2 2 FORBES STREET** **N/A**
1/8-1/4 **EAST HARTFORD, CT 06108**
0.210 mi.
1110 ft. **Site 7 of 12 in cluster E**

Relative: **Lower**

Actual: **48 ft.**

E MANIFEST:

Manifest Tracking Number:	023099863JJK
Last Updated Date:	20220830
Shipped Date:	20220825
Received Date:	20220825
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CTD047714142
Generator Name:	Dunn Paper
Generator Location Street Number:	2
Generator Location Street 1:	2 2 FORBES STREET
Generator Location Street 2:	Not reported
Generator Location City:	EAST HARTFORD
Generator Location State:	CT
Generator Location Zip:	06108

DUNN PAPER (Continued) **1032024892**

Generator Mail Street Number:	2
Generator Mail Street 1:	2 Forbes Street
Generator Mail Street 2:	Not reported
Generator Mail City:	East Hartford
Generator Mail Zip:	06108
Generator Mail State:	CT
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	CTD021816889
Designated Facility Name:	Tradebe T&R Northeast, Llc
Designated Facility Mail Street Number:	136
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	GRACEY AVE.
Designated Facility Mail City:	MERIDEN
Designated Facility Mail Zip:	06451
Designated Facility Mail State:	CT
Designated Facility Location Street Number:	136
Designated Facility Location Street 1:	136 GRACEY AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	MERIDEN
Designated Facility Location Zip:	06451
Designated Facility Location State:	CT
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	023100593JJK
Last Updated Date:	20240325
Shipped Date:	20240311
Received Date:	20240319
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CTD047714142
Generator Name:	Dunn Paper
Generator Location Street Number:	2
Generator Location Street 1:	2 2 FORBES STREET
Generator Location Street 2:	Not reported
Generator Location City:	EAST HARTFORD
Generator Location State:	CT
Generator Location Zip:	06108
Generator Mail Street Number:	2
Generator Mail Street 1:	2 Forbes Street
Generator Mail Street 2:	Not reported
Generator Mail City:	East Hartford
Generator Mail Zip:	06108
Generator Mail State:	CT
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	IND000646943
Designated Facility Name:	Tradebe Treatment And Recycling Llc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	4343 KENNEDY AVE
Designated Facility Mail City:	EAST CHICAGO
Designated Facility Mail Zip:	46312
Designated Facility Mail State:	IN
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	4343 KENNEDY AVENUE

DUNN PAPER (Continued) **1032024892**

Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	EAST CHICAGO
Designated Facility Location Zip:	46312
Designated Facility Location State:	IN
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N
Manifest Tracking Number:	019356408JJK
Last Updated Date:	20191216
Shipped Date:	20191119
Received Date:	20191122
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CTD047714142
Generator Name:	Dunn Paper
Generator Location Street Number:	2
Generator Location Street 1:	2 2 FORBES STREET
Generator Location Street 2:	Not reported
Generator Location City:	EAST HARTFORD
Generator Location State:	CT
Generator Location Zip:	06108
Generator Mail Street Number:	2
Generator Mail Street 1:	2 Forbes Street
Generator Mail Street 2:	Not reported
Generator Mail City:	East Hartford
Generator Mail Zip:	06108
Generator Mail State:	CT
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	IND000646943
Designated Facility Name:	Tradebe Treatment & Recycling Llc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	4343 KENNEDY AVE
Designated Facility Mail City:	EAST CHICAGO
Designated Facility Mail Zip:	46312
Designated Facility Mail State:	IN
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	4343 KENNEDY AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	EAST CHICAGO
Designated Facility Location Zip:	46312
Designated Facility Location State:	IN
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N
Manifest Tracking Number:	019359699JJK
Last Updated Date:	20190405
Shipped Date:	20190402
Received Date:	20190402
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CTD047714142
Generator Name:	Dunn Paper

DUNN PAPER (Continued) **1032024892**

Generator Location Street Number:	2
Generator Location Street 1:	2 2 FORBES STREET
Generator Location Street 2:	Not reported
Generator Location City:	EAST HARTFORD
Generator Location State:	CT
Generator Location Zip:	06108
Generator Mail Street Number:	2
Generator Mail Street 1:	2 Forbes Street
Generator Mail Street 2:	Not reported
Generator Mail City:	East Hartford
Generator Mail Zip:	06108
Generator Mail State:	CT
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	CTD021816889
Designated Facility Name:	Tradebe Treatment And Recycling Of Northeast Llc
Designated Facility Mail Street Number:	136
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	136 GRACEY AVE.
Designated Facility Mail City:	MERIDEN
Designated Facility Mail Zip:	06451
Designated Facility Mail State:	CT
Designated Facility Location Street Number:	136
Designated Facility Location Street 1:	136 GRACEY AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	MERIDEN
Designated Facility Location Zip:	06451
Designated Facility Location State:	CT
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	019360852JJK
Last Updated Date:	20210921
Shipped Date:	20210826
Received Date:	20210914
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CTD047714142
Generator Name:	Dunn Paper
Generator Location Street Number:	2
Generator Location Street 1:	2 2 FORBES STREET
Generator Location Street 2:	Not reported
Generator Location City:	EAST HARTFORD
Generator Location State:	CT
Generator Location Zip:	06108
Generator Mail Street Number:	2
Generator Mail Street 1:	2 Forbes Street
Generator Mail Street 2:	Not reported
Generator Mail City:	East Hartford
Generator Mail Zip:	06108
Generator Mail State:	CT
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	IND000646943
Designated Facility Name:	Tradebe Treatment And Recycling Llc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported

DUNN PAPER (Continued) **1032024892**

Designated Facility Mail Street 2:	4343 KENNEDY AVE
Designated Facility Mail City:	EAST CHICAGO
Designated Facility Mail Zip:	46312
Designated Facility Mail State:	IN
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	4343 KENNEDY AVENUE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	EAST CHICAGO
Designated Facility Location Zip:	46312
Designated Facility Location State:	IN
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	020941123JJK
Last Updated Date:	20220927
Shipped Date:	20220825
Received Date:	20220910
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CTD047714142
Generator Name:	Dunn Paper
Generator Location Street Number:	2
Generator Location Street 1:	2 2 FORBES STREET
Generator Location Street 2:	Not reported
Generator Location City:	EAST HARTFORD
Generator Location State:	CT
Generator Location Zip:	06108
Generator Mail Street Number:	2
Generator Mail Street 1:	2 Forbes Street
Generator Mail Street 2:	Not reported
Generator Mail City:	East Hartford
Generator Mail Zip:	06108
Generator Mail State:	CT
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	IND000646943
Designated Facility Name:	Tradebe Treatment And Recycling Llc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	4343 KENNEDY AVE
Designated Facility Mail City:	EAST CHICAGO
Designated Facility Mail Zip:	46312
Designated Facility Mail State:	IN
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	4343 KENNEDY AVENUE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	EAST CHICAGO
Designated Facility Location Zip:	46312
Designated Facility Location State:	IN
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	025183635JJK
Last Updated Date:	20241008
Shipped Date:	20240827

DUNN PAPER (Continued) **1032024892**

Received Date:	20240913
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CTD047714142
Generator Name:	Dunn Paper
Generator Location Street Number:	2
Generator Location Street 1:	2 2 FORBES STREET
Generator Location Street 2:	Not reported
Generator Location City:	EAST HARTFORD
Generator Location State:	CT
Generator Location Zip:	06108
Generator Mail Street Number:	2
Generator Mail Street 1:	2 FORBES STREET
Generator Mail Street 2:	Not reported
Generator Mail City:	EAST HARTFORD
Generator Mail Zip:	06108
Generator Mail State:	CT
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	IND000646943
Designated Facility Name:	Tradebe Treatment And Recycling Llc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	4343 KENNEDY AVE
Designated Facility Mail City:	EAST CHICAGO
Designated Facility Mail Zip:	46312
Designated Facility Mail State:	IN
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	4343 KENNEDY AVENUE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	EAST CHICAGO
Designated Facility Location Zip:	46312
Designated Facility Location State:	IN
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	025184342JJK
Last Updated Date:	20231030
Shipped Date:	20230523
Received Date:	20230605
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CTD047714142
Generator Name:	Dunn Paper
Generator Location Street Number:	2
Generator Location Street 1:	2 2 FORBES STREET
Generator Location Street 2:	Not reported
Generator Location City:	EAST HARTFORD
Generator Location State:	CT
Generator Location Zip:	06108
Generator Mail Street Number:	2
Generator Mail Street 1:	2 Forbes Street
Generator Mail Street 2:	Not reported
Generator Mail City:	East Hartford
Generator Mail Zip:	06108

DUNN PAPER (Continued) **1032024892**

Generator Mail State:	CT
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NYD080469935
Designated Facility Name:	Norlite, Llc
Designated Facility Mail Street Number:	628
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	SARATOGA STREET
Designated Facility Mail City:	COHOES
Designated Facility Mail Zip:	12047
Designated Facility Mail State:	NY
Designated Facility Location Street Number:	628
Designated Facility Location Street 1:	SARATOGA STREET
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	COHOES
Designated Facility Location Zip:	12047
Designated Facility Location State:	NY
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	025184343JJK
Last Updated Date:	20230614
Shipped Date:	20230523
Received Date:	20230523
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CTD047714142
Generator Name:	Dunn Paper
Generator Location Street Number:	2
Generator Location Street 1:	2 2 FORBES STREET
Generator Location Street 2:	Not reported
Generator Location City:	EAST HARTFORD
Generator Location State:	CT
Generator Location Zip:	06108
Generator Mail Street Number:	2
Generator Mail Street 1:	2 Forbes Street
Generator Mail Street 2:	Not reported
Generator Mail City:	East Hartford
Generator Mail Zip:	06108
Generator Mail State:	CT
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	CTD021816889
Designated Facility Name:	Tradebe T&R Northeast, Llc
Designated Facility Mail Street Number:	136
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	GRACEY AVE.
Designated Facility Mail City:	MERIDEN
Designated Facility Mail Zip:	06451
Designated Facility Mail State:	CT
Designated Facility Location Street Number:	136
Designated Facility Location Street 1:	136 GRACEY AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	MERIDEN
Designated Facility Location Zip:	06451
Designated Facility Location State:	CT
Designated Facility Contact Company Name:	Not reported

DUNN PAPER (Continued) **1032024892**

Manifest Residue Indicator: N
Rejection Indicator: N

Transporter:
Manifest Tracking Number: 025184343JJK
Transporter Line Number: 1
Transporter EPA ID: CTD021816889
Transporter Name: Tradebe Transportation, Llc

Waste Line:
Manifest Tracking Number: 025184343JJK
Waste Line Number: 1
U.S. DOT Hazardous Indicator: N
U.S. DOT ID Number: Not reported
U.S. DOT Description: Not reported
Non-Hazardous Waste Description: Non Dot / Non Rcra Regulated Material
Number of Containers: 9
Container Type Code: DM
Container Type Description: Metal drums, barrels, kegs
Waste Quantity: 495
Quantity Unit of Measure Code: G
Quantity Unit of Measure Description: Gallons
Waste Quantity, in Tons: 2.0642202
Acute Waste Quantity, in Tons: 0
Non-Acute Waste Quantity, in Tons: 2.0642202
Waste Quantity, in Kilograms: 1872.3097
Acute Waste Quantity, in Kilograms: 0
Non-Acute Waste Quantity, in Kilorgrams: 1872.3097
Management Method Code: H141
Management Method Description: STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator: N
Quantity Discrepancy Indicator: N
Waste Type Discrepancy Indicator: N
Waste Density: Not reported
Waste Density Unit of Measure Code: Not reported
Waste Density Unit of Measure Description: Not reported
Form Code: Not reported
Form Code Description: Not reported
Source Code: Not reported
Source Code Description: Not reported
Waste Minimization Code: Not reported
Waste Minimization Code Description: Not reported
Consent Number: Not reported
EPA Waste Indicator: N
Federal Waste Codes: Not reported
Quantity Haz Kg: Not reported
Quantity Haz Tons: Not reported
Quantity Non Haz Kg: 1872.3097
Quantity Non Haz Tons: 2.0642202
State Waste Codes: CT-CR02

Manifest Tracking Number: 025184343JJK
Waste Line Number: 2
U.S. DOT Hazardous Indicator: Y
U.S. DOT ID Number: UN3264
U.S. DOT Description: Un3264 Waste Corrosive Liquid, Acid, Inorganic, N.O.S. (Sulfuric Acid,

DUNN PAPER (Continued) **1032024892**

Phosphoric Acid) 8 Ii Rq (D002)

Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	TP
Container Type Description:	Portable tanks
Waste Quantity:	275
Quantity Unit of Measure Code:	G
Quantity Unit of Measure Description:	Gallons
Waste Quantity, in Tons:	1.146789
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	1.146789
Waste Quantity, in Kilograms:	1040.172
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	1040.172
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D002
Quantity Haz Kg:	1040.172
Quantity Haz Tons:	1.146789
Quantity Non Haz Kg:	Not reported
Quantity Non Haz Tons:	Not reported
State Waste Codes:	Not reported

E36 **CELLU TISSUE CORP** **CT MANIFEST** **S129122910**
South **2 FORBES ST** **N/A**
1/8-1/4 **EAST HARTFORD, CT 06108**
0.210 mi.
1110 ft. **Site 8 of 12 in cluster E**

Relative: CT MANIFEST:
Lower

Actual: Name:	CELLU TISSUE LLC
48 ft. Address:	2 FORBES ST
City,State,Zip:	EAST HARTFORD, CT 06108
Phone:	Not reported
Country:	Not reported
Manifest ID:	ctf1202345
EPA ID:	CTD047714142
Name:	CELLU TISSUE CORP
Address:	2 FORBES ST
City,State,Zip:	EAST HARTFORD, CT 06108
Phone:	Not reported
Country:	Not reported
Manifest ID:	CTF0243358

CELLU TISSUE CORP (Continued) **S129122910**

EPA ID: CTP000016453

Hazardous Waste Manifest:

Year:	2018
Manifest:	018258601JJK
EPA ID:	CTD047714142
Generator Mailing Address:	Not reported
Generator City,State,Zip:	Not reported
Discrepancies:	Not reported
Date Shipped:	2018-03-29
Date Received:	Not reported
Transporter 2 Date:	Not reported
TSDF EPA ID:	Not reported
TSDF Name:	Not reported
TSDF Address:	Not reported
TSDF City,State,Zip:	Not reported
TSDF Country:	Not reported
Transporter EPA ID:	Not reported
Transporter Name:	Not reported
Transporter Address:	Not reported
Transporter City,State,Zip:	Not reported
Transporter Country:	Not reported
Transporter 2 EPA ID:	Not reported
Transporter 2 Name:	Not reported
Transporter 2 Address:	Not reported
Transporter 2 City,State,Zip:	Not reported
Transporter 2 Country:	Not reported
US DOT Description:	Not reported
Number of Containers:	Not reported
Container Type:	Not reported
Quantity/Weight/Volume:	/
Batch Number:	Not reported
EPA Waste Codes:	- Not reported
Copies:	Not reported
Alternate Facility Name:	Not reported
Alternate Facility Address:	Not reported
Alternate Facility State:	Not reported
Alternate Facility Date:	Not reported

Year:	2017
Manifest:	008933190JJK
EPA ID:	CTD047714142
Generator Mailing Address:	Not reported
Generator City,State,Zip:	Not reported
Discrepancies:	Not reported
Date Shipped:	2017-03-07
Date Received:	Not reported
Transporter 2 Date:	Not reported
TSDF EPA ID:	Not reported
TSDF Name:	Not reported
TSDF Address:	Not reported
TSDF City,State,Zip:	Not reported
TSDF Country:	Not reported
Transporter EPA ID:	Not reported
Transporter Name:	Not reported
Transporter Address:	Not reported
Transporter City,State,Zip:	Not reported

CELLU TISSUE CORP (Continued) **S129122910**

Transporter Country:	Not reported
Transporter 2 EPA ID:	Not reported
Transporter 2 Name:	Not reported
Transporter 2 Address:	Not reported
Transporter 2 City,State,Zip:	Not reported
Transporter 2 Country:	Not reported
US DOT Description:	Not reported
Number of Containers:	Not reported
Container Type:	Not reported
Quantity/Weight/Volume:	/
Batch Number:	Not reported
EPA Waste Codes:	- Not reported
Copies:	Not reported
Alternate Facility Name:	Not reported
Alternate Facility Address:	Not reported
Alternate Facility State:	Not reported
Alternate Facility Date:	Not reported

Year:	2015
Manifest:	005147830SKS
EPA ID:	CTD047714142
Generator Mailing Address:	Not reported
Generator City,State,Zip:	Not reported
Discrepancies:	Not reported
Date Shipped:	2015-10-31
Date Received:	Not reported
Transporter 2 Date:	Not reported
TSDF EPA ID:	Not reported
TSDF Name:	Not reported
TSDF Address:	Not reported
TSDF City,State,Zip:	Not reported
TSDF Country:	Not reported
Transporter EPA ID:	Not reported
Transporter Name:	Not reported
Transporter Address:	Not reported
Transporter City,State,Zip:	Not reported
Transporter Country:	Not reported
Transporter 2 EPA ID:	Not reported
Transporter 2 Name:	Not reported
Transporter 2 Address:	Not reported
Transporter 2 City,State,Zip:	Not reported
Transporter 2 Country:	Not reported
US DOT Description:	Not reported
Number of Containers:	Not reported
Container Type:	Not reported
Quantity/Weight/Volume:	/
Batch Number:	Not reported
EPA Waste Codes:	- Not reported
Copies:	Not reported
Alternate Facility Name:	Not reported
Alternate Facility Address:	Not reported
Alternate Facility State:	Not reported
Alternate Facility Date:	Not reported

Year:	2015
Manifest:	004937449SKS
EPA ID:	CTD047714142

CELLU TISSUE CORP (Continued) **S129122910**

Generator Mailing Address:	Not reported
Generator City,State,Zip:	Not reported
Discrepancies:	Not reported
Date Shipped:	2015-06-03
Date Received:	Not reported
Transporter 2 Date:	Not reported
TSDF EPA ID:	Not reported
TSDF Name:	Not reported
TSDF Address:	Not reported
TSDF City,State,Zip:	Not reported
TSDF Country:	Not reported
Transporter EPA ID:	Not reported
Transporter Name:	Not reported
Transporter Address:	Not reported
Transporter City,State,Zip:	Not reported
Transporter Country:	Not reported
Transporter 2 EPA ID:	Not reported
Transporter 2 Name:	Not reported
Transporter 2 Address:	Not reported
Transporter 2 City,State,Zip:	Not reported
Transporter 2 Country:	Not reported
US DOT Description:	Not reported
Number of Containers:	Not reported
Container Type:	Not reported
Quantity/Weight/Volume:	/
Batch Number:	Not reported
EPA Waste Codes:	- Not reported
Copies:	Not reported
Alternate Facility Name:	Not reported
Alternate Facility Address:	Not reported
Alternate Facility State:	Not reported
Alternate Facility Date:	Not reported

Year:	2015
Manifest:	004920900SKS
EPA ID:	CTD047714142
Generator Mailing Address:	Not reported
Generator City,State,Zip:	Not reported
Discrepancies:	Not reported
Date Shipped:	2015-05-07
Date Received:	Not reported
Transporter 2 Date:	Not reported
TSDF EPA ID:	Not reported
TSDF Name:	Not reported
TSDF Address:	Not reported
TSDF City,State,Zip:	Not reported
TSDF Country:	Not reported
Transporter EPA ID:	Not reported
Transporter Name:	Not reported
Transporter Address:	Not reported
Transporter City,State,Zip:	Not reported
Transporter Country:	Not reported
Transporter 2 EPA ID:	Not reported
Transporter 2 Name:	Not reported
Transporter 2 Address:	Not reported
Transporter 2 City,State,Zip:	Not reported
Transporter 2 Country:	Not reported

CELLU TISSUE CORP (Continued) **S129122910**

US DOT Description:	Not reported
Number of Containers:	Not reported
Container Type:	Not reported
Quantity/Weight/Volume:	/
Batch Number:	Not reported
EPA Waste Codes:	- Not reported
Copies:	Not reported
Alternate Facility Name:	Not reported
Alternate Facility Address:	Not reported
Alternate Facility State:	Not reported
Alternate Facility Date:	Not reported

Year:	2015
Manifest:	005137348SKS
EPA ID:	CTD047714142
Generator Mailing Address:	Not reported
Generator City,State,Zip:	Not reported
Discrepancies:	Not reported
Date Shipped:	2015-09-30
Date Received:	Not reported
Transporter 2 Date:	Not reported
TSDF EPA ID:	Not reported
TSDF Name:	Not reported
TSDF Address:	Not reported
TSDF City,State,Zip:	Not reported
TSDF Country:	Not reported
Transporter EPA ID:	Not reported
Transporter Name:	Not reported
Transporter Address:	Not reported
Transporter City,State,Zip:	Not reported
Transporter Country:	Not reported
Transporter 2 EPA ID:	Not reported
Transporter 2 Name:	Not reported
Transporter 2 Address:	Not reported
Transporter 2 City,State,Zip:	Not reported
Transporter 2 Country:	Not reported
US DOT Description:	Not reported
Number of Containers:	Not reported
Container Type:	Not reported
Quantity/Weight/Volume:	/
Batch Number:	Not reported
EPA Waste Codes:	- Not reported
Copies:	Not reported
Alternate Facility Name:	Not reported
Alternate Facility Address:	Not reported
Alternate Facility State:	Not reported
Alternate Facility Date:	Not reported

Year:	2015
Manifest:	005152547SKS
EPA ID:	CTD047714142
Generator Mailing Address:	Not reported
Generator City,State,Zip:	Not reported
Discrepancies:	Not reported
Date Shipped:	2015-11-25
Date Received:	Not reported
Transporter 2 Date:	Not reported

CELLU TISSUE CORP (Continued) **S129122910**

TSDF EPA ID:	Not reported
TSDF Name:	Not reported
TSDF Address:	Not reported
TSDF City,State,Zip:	Not reported
TSDF Country:	Not reported
Transporter EPA ID:	Not reported
Transporter Name:	Not reported
Transporter Address:	Not reported
Transporter City,State,Zip:	Not reported
Transporter Country:	Not reported
Transporter 2 EPA ID:	Not reported
Transporter 2 Name:	Not reported
Transporter 2 Address:	Not reported
Transporter 2 City,State,Zip:	Not reported
Transporter 2 Country:	Not reported
US DOT Description:	Not reported
Number of Containers:	Not reported
Container Type:	Not reported
Quantity/Weight/Volume:	/
Batch Number:	Not reported
EPA Waste Codes:	- Not reported
Copies:	Not reported
Alternate Facility Name:	Not reported
Alternate Facility Address:	Not reported
Alternate Facility State:	Not reported
Alternate Facility Date:	Not reported

Year:	2015
Manifest:	005170356SKS
EPA ID:	CTD047714142
Generator Mailing Address:	Not reported
Generator City,State,Zip:	Not reported
Discrepancies:	Not reported
Date Shipped:	2015-12-19
Date Received:	Not reported
Transporter 2 Date:	Not reported
TSDF EPA ID:	Not reported
TSDF Name:	Not reported
TSDF Address:	Not reported
TSDF City,State,Zip:	Not reported
TSDF Country:	Not reported
Transporter EPA ID:	Not reported
Transporter Name:	Not reported
Transporter Address:	Not reported
Transporter City,State,Zip:	Not reported
Transporter Country:	Not reported
Transporter 2 EPA ID:	Not reported
Transporter 2 Name:	Not reported
Transporter 2 Address:	Not reported
Transporter 2 City,State,Zip:	Not reported
Transporter 2 Country:	Not reported
US DOT Description:	Not reported
Number of Containers:	Not reported
Container Type:	Not reported
Quantity/Weight/Volume:	/
Batch Number:	Not reported
EPA Waste Codes:	- Not reported

CELLU TISSUE CORP (Continued) **S129122910**

Copies:	Not reported
Alternate Facility Name:	Not reported
Alternate Facility Address:	Not reported
Alternate Facility State:	Not reported
Alternate Facility Date:	Not reported
Year:	2014
Manifest:	011518787JJK
EPA ID:	CTD047714142
Generator Mailing Address:	Not reported
Generator City,State,Zip:	Not reported
Discrepancies:	Not reported
Date Shipped:	2014-05-13
Date Received:	Not reported
Transporter 2 Date:	Not reported
TSDF EPA ID:	Not reported
TSDF Name:	Not reported
TSDF Address:	Not reported
TSDF City,State,Zip:	Not reported
TSDF Country:	Not reported
Transporter EPA ID:	Not reported
Transporter Name:	Not reported
Transporter Address:	Not reported
Transporter City,State,Zip:	Not reported
Transporter Country:	Not reported
Transporter 2 EPA ID:	Not reported
Transporter 2 Name:	Not reported
Transporter 2 Address:	Not reported
Transporter 2 City,State,Zip:	Not reported
Transporter 2 Country:	Not reported
US DOT Description:	Not reported
Number of Containers:	Not reported
Container Type:	Not reported
Quantity/Weight/Volume:	/
Batch Number:	Not reported
EPA Waste Codes:	- Not reported
Copies:	Not reported
Alternate Facility Name:	Not reported
Alternate Facility Address:	Not reported
Alternate Facility State:	Not reported
Alternate Facility Date:	Not reported
Year:	2014
Manifest:	011518787JJK
EPA ID:	CTD047714142
Generator Mailing Address:	Not reported
Generator City,State,Zip:	Not reported
Discrepancies:	Not reported
Date Shipped:	2014-05-13
Date Received:	Not reported
Transporter 2 Date:	Not reported
TSDF EPA ID:	Not reported
TSDF Name:	Not reported
TSDF Address:	Not reported
TSDF City,State,Zip:	Not reported
TSDF Country:	Not reported
Transporter EPA ID:	Not reported

CELLU TISSUE CORP (Continued) **S129122910**

Transporter Name:	Not reported
Transporter Address:	Not reported
Transporter City,State,Zip:	Not reported
Transporter Country:	Not reported
Transporter 2 EPA ID:	Not reported
Transporter 2 Name:	Not reported
Transporter 2 Address:	Not reported
Transporter 2 City,State,Zip:	Not reported
Transporter 2 Country:	Not reported
US DOT Description:	Not reported
Number of Containers:	Not reported
Container Type:	Not reported
Quantity/Weight/Volume:	/
Batch Number:	Not reported
EPA Waste Codes:	- Not reported
Copies:	Not reported
Alternate Facility Name:	Not reported
Alternate Facility Address:	Not reported
Alternate Facility State:	Not reported
Alternate Facility Date:	Not reported

Year:	2013
Manifest:	010742999JJK
EPA ID:	CTD047714142
Generator Mailing Address:	Not reported
Generator City,State,Zip:	Not reported
Discrepancies:	Not reported
Date Shipped:	2013-02-06
Date Received:	Not reported
Transporter 2 Date:	Not reported
TSDF EPA ID:	Not reported
TSDF Name:	Not reported
TSDF Address:	Not reported
TSDF City,State,Zip:	Not reported
TSDF Country:	Not reported
Transporter EPA ID:	Not reported
Transporter Name:	Not reported
Transporter Address:	Not reported
Transporter City,State,Zip:	Not reported
Transporter Country:	Not reported
Transporter 2 EPA ID:	Not reported
Transporter 2 Name:	Not reported
Transporter 2 Address:	Not reported
Transporter 2 City,State,Zip:	Not reported
Transporter 2 Country:	Not reported
US DOT Description:	Not reported
Number of Containers:	Not reported
Container Type:	Not reported
Quantity/Weight/Volume:	/
Batch Number:	Not reported
EPA Waste Codes:	- Not reported
Copies:	Not reported
Alternate Facility Name:	Not reported
Alternate Facility Address:	Not reported
Alternate Facility State:	Not reported
Alternate Facility Date:	Not reported

CELLU TISSUE CORP (Continued) **S129122910**

DEEP Document:

Year:	2017
EPA ID:	CTD047714142
Statuory Program:	Hazardous Waste
Document Number:	008933190JJK
Document:	Hazardous Waste Manifest
File Type:	Written Text
Reference ID:	Ref ID: 008933190JJK Alt ID: CTD047714142

Click Here to view the image from agency website:

Year:	2012
EPA ID:	CTD047714142
Statuory Program:	Hazardous Waste
Document Number:	003455827SKS
Document:	Hazardous Waste Manifest
File Type:	Written Text
Reference ID:	Ref ID: 003455827SKS Alt ID: CTD047714142

Click Here to view the image from agency website:

Year:	2012
EPA ID:	CTD047714142
Statuory Program:	Hazardous Waste
Document Number:	010412777JJK
Document:	Hazardous Waste Manifest
File Type:	Written Text
Reference ID:	Ref ID: 010412777JJK Alt ID: CTD047714142

Click Here to view the image from agency website:

E37 **CELLU TISSUE** **NY MANIFEST** **1009219758**
South **2 FORBES STREET** **N/A**
1/8-1/4 **EAST HARTFORD, CT 06108**
0.210 mi.
1110 ft. **Site 9 of 12 in cluster E**

Relative:
Lower

Actual:
48 ft.

NY MANIFEST:

EPA ID:	CTP000005096
Country:	USA
Name:	Cellu Tissue
Address:	2 FORBES STREET
Address 2:	Not reported
City,State,Zip:	EAST HARTFORD, CT 06108
Zip 4:	Not reported
Location Address 1:	2 FORBES STREET
Location Address 2:	Not reported
Location City,State,Zip:	EAST HARTFORD, CT 06108
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Cellu Tissue
Mailing Contact:	Cellu Tissue
Mailing Address 1:	2 FORBES STREET
Mailing Address 2:	Not reported

CELLU TISSUE (Continued) **1009219758**

Mailing City,State,Zip: EAST HARTFORD, CT 06108
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2032897496

Manifest Data:
Document ID: NYA3534074
Manifest Status: C - Completed copy
Trans1 State ID: RI28895
Year: 1986
Trans2 State ID: Not reported
Generator Ship Date: 860523
Trans1 Recv Date: 860523
Trans2 Recv Date: 860523
TSD Site Recv Date: 860528
Part A Recv Date: 860616
Part B Recv Date: 860604
Generator EPA ID: CTP000005096
Trans1 EPA ID: RID000769711
Trans2 EPA ID: Not reported
TSDF ID 1: NYD043815703
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: Corrosive Waste
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00060
Units: Gallons (liquids only)
Number of Containers: 002
Container Type: Metal drums, barrels, kegs
Handling Method: Treat
Specific Gravity: 100

E38
South
1/8-1/4
0.210 mi.
1110 ft.

Relative:
Lower

Actual:
48 ft.

BIORIGIN SPECIALTY PRODUCTS (DBA DUNN PAPER - EAST
40 FORBES ST
EAST HARTFORD, CT 06108

Site 10 of 12 in cluster E

RCRA-VSQG 1000292853
CT SDADB CTD047714142
CT PROPERTY
CT SPILLS
ICIS
CT CPCS
CT NPDES

RCRA Listings:

Date Form Received by Agency:		20240903
Handler Name:		Biorigin Specialty Products (Dba Dunn Paper - East Hartford)
Handler Address:		Forbes St
Handler City,State,Zip:		EAST HARTFORD, CT 06108
EPA ID:		CTD047714142
Contact Name:		JEFFREY A BRASHICH
Contact Address:		FORBES ST
Contact City,State,Zip:		EAST HARTFORD, CT 06108
Contact Telephone:		860-466-4181
Contact Fax:		Not reported
Contact Email:		BRASHICHJ@BIORIGINSP.COM
Contact Title:		ENVIRONMENTAL ENGINEER
EPA Region:		01
Land Type:		Private
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		FORBES ST
Mailing City,State,Zip:		EAST HARTFORD, CT 06108
Owner Name:	Ct Holdings, Llc	
Owner Type:		Private
Operator Name:	Cellus Tissue Llc	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking

BIORIGIN SPECIALTY PRODUCTS (DBA DUNN PAPER - EAST HARTFORD) (Continued) **1000292853**

Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20240903
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D003
Waste Description:	Reactive Waste

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: CELLU TISSUE CORP	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 8096 2 FORBES ST
Owner/Operator City,State,Zip:	EAST HARTFORD, CT 06108
Owner/Operator Telephone:	203-289-7496
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CELLUS TISSUE LLC	
Legal Status:	Private
Date Became Current:	20030301
Date Ended Current:	Not reported
Owner/Operator Address:	40 FORBES STREET
Owner/Operator City,State,Zip:	EAST HARTFORD, CT 06108
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CELLU TISSUE CORP	

BIORIGIN SPECIALTY PRODUCTS (DBA DUNN PAPER - EAST HARTFORD) (Continued) **1000292853**

Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 8096 2 FORBES ST
Owner/Operator City,State,Zip: EAST HARTFORD, CT 06108
Owner/Operator Telephone: 203-289-7496
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CT HOLDINGS, LLC
Legal Status: Private
Date Became Current: 20221118
Date Ended Current: Not reported
Owner/Operator Address: 40 FORBES STREET
Owner/Operator City,State,Zip: EAST HARTFORD, CT 06108
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CELLU TISSUE HOLDING INC
Legal Status: Private
Date Became Current: 20030301
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CELLUS TISSUE LLC
Legal Status: Private
Date Became Current: 20030301
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19830512
Handler Name: CELLU TISSUE CORP
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No

BIORIGIN SPECIALTY PRODUCTS (DBA DUNN PAPER - EAST HARTFORD) (Continued) 1000292853

Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20031022
Handler Name: CELLU TISSUE LLC
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20240903
Handler Name: BIORIGIN SPECIALTY PRODUCTS (DBA DUNN PAPER - EAST HARTFORD)
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 322121
NAICS Description: Paper (Except Newsprint) Mills

NAICS Code: 322291
NAICS Description: Sanitary Paper Product Manufacturing

Has the Facility Received Notices of Violations:
Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Formal Enforcement Agreement or Order
Date Violation was Determined: 19860106
Actual Return to Compliance Date: 19860507
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported

BIORIGIN SPECIALTY PRODUCTS (DBA DUNN PAPER - EAST HARTFORD) (Continued) **1000292853**

Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported

BIORIGIN SPECIALTY PRODUCTS (DBA DUNN PAPER - EAST HARTFORD) (Continued) **1000292853**

Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Formal Enforcement Agreement or Order
Date Violation was Determined: 19850718
Actual Return to Compliance Date: 19860507
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Formal Enforcement Agreement or Order
Date Violation was Determined: 19850718
Actual Return to Compliance Date: 19860507
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 004
Date of Enforcement Action: 19850904
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported

BIORIGIN SPECIALTY PRODUCTS (DBA DUNN PAPER - EAST HARTFORD) (Continued) **1000292853**

Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: INITIAL CIVIL JUDICIAL ACTION FOR COMPLIANCE AND/OR MONETARY PENALTY
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 19830627
Actual Return to Compliance Date: 19860506
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported

BIORIGIN SPECIALTY PRODUCTS (DBA DUNN PAPER - EAST HARTFORD) (Continued) **1000292853**

Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 19830627
Actual Return to Compliance Date: 19860506
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 007
Date of Enforcement Action: 19830926
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 19830627
Actual Return to Compliance Date: 19860507
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported

BIORIGIN SPECIALTY PRODUCTS (DBA DUNN PAPER - EAST HARTFORD) (Continued) **1000292853**

Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 19860106
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE SCHEDULE EVALUATION
Evaluation Responsible Person Identifier: Not reported
Evaluation Responsible Sub-Organization: Not reported
Actual Return to Compliance Date: 19860507
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 19850719
Evaluation Responsible Agency: State
Found Violation: No
Evaluation Type Description: FOCUSED COMPLIANCE INSPECTION
Evaluation Responsible Person Identifier: Not reported
Evaluation Responsible Sub-Organization: Not reported
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 19850718
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE SCHEDULE EVALUATION
Evaluation Responsible Person Identifier: Not reported
Evaluation Responsible Sub-Organization: Not reported
Actual Return to Compliance Date: 19860507
Scheduled Compliance Date: Not reported

BIORIGIN SPECIALTY PRODUCTS (DBA DUNN PAPER - EAST HARTFORD) (Continued) **1000292853**

Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	19850718
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE SCHEDULE EVALUATION
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	19860507
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	19830627
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	19860506
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	19830627
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	19860506
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	19830627
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	19860507
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

BIORIGIN SPECIALTY PRODUCTS (DBA DUNN PAPER - EAST HARTFORD) (Continued) **1000292853**

Site Discovery and Assessment:

Facility ID:	4081
Rem Master ID:	4036
PTP Id:	2621
WPC Number:	Not reported
Postal District:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Determined By:	Not reported
Ground Water Quality Classification:	GB
Surface Water Quality Classification:	B
Waste Type:	HYDRO/OIL, PEST/HERB
Disposal:	SPILL/DUMP
Sample Data Available:	True
Updated By:	HAMEL, M.
Update Program:	PTP
Updated:	4/2/2000
Date Created:	Not reported
Duplicate:	False

SDA Federal:

EPA CERCLIS Id:	Not reported
Number EPA RCRIS Id:	Not reported
Site on EPA's CERCLIS:	Not reported
Site Archived from CERCLIS:	Not reported
Archive Date:	Not reported
EPA's Removal at Site:	Not reported
Deferred to another EPA Program:	Not reported
EPA Env Priority Initiative Site:	Not reported
Federal Facility:	Not reported
Site on EPA's National Priority List:	Not reported
Part of an NPL site:	Not reported
RCRA Generator Status:	Not reported
RCRA Permit Status:	Not reported

SDA Referral:

Referral Id:	4229
Source of referral:	PTP
Date Received:	1/22/1998
Staff Assigned:	HAMEL, M.
Remediation Program:	PTP
Date dt_assigned:	Not reported
Remediation Complete Approved DEP/Verified by LEP:	1/22/1998
Outcome:	PTP

SDA Remedial:

Remedial Id:	Not reported
PTP Id:	Not reported
Remediation Program:	Not reported
Remediation Program Entered:	Not reported
Staff Assigned:	Not reported
Remediation Program:	Not reported
Date dt_assign:	Not reported
Project Phase:	Not reported
Order issued:	Not reported
Order Number:	Not reported
Date order issued:	Not reported
Remedial Investigation Start:	Not reported

BIORIGIN SPECIALTY PRODUCTS (DBA DUNN PAPER - EAST HARTFORD) (Continued) **1000292853**

Remedial Investigation Completed:	Not reported
Remedial Design Start:	Not reported
Remedial Design complet:	Not reported
Remedial Action Start:	Not reported
Remedial Action Completed:	Not reported
Date Oper/ maintenance Started:	Not reported
GW monitoring:	Not reported
Remediation complete Approved DEP/Verified by LEP:	Not reported

SDA Orders:

Order Id:	Not reported
Order Number:	Not reported
Date order issued:	Not reported
Staff Assigned:	Not reported
Type of Order:	Not reported
Order Respondent:	Not reported
Admin Appeal Date:	Not reported
Date of Admin Appeal Ruling:	Not reported
Date of Admin Appeal Ruling:	Not reported
Date of Final Order:	Not reported
Date of Court Appeal:	Not reported
Date of Court Ruling:	Not reported
Date of Court Ruling:	Not reported
Date Order Modified:	Not reported
Date Referred to AG:	Not reported
Judgement:	Not reported
Date of AGR judgement:	Not reported
Penalty assessed:	Not reported
Order Complete:	Not reported
In compliance:	Not reported
Comments:	Not reported

SDADB:

SDA Waste:

Waste Id:	11
Waste Type:	HYDRO/OIL
Description:	Hydrocarbons and/or Fuel Oil

CT Property:

Name:	CELLU-TISSUE CORP.
Address:	2 FORBES STREET
City,state,zip:	EAST HARTFORD, CT
Seller Name:	Cellu-Tissue Corporation
Buyer Name:	Charter Specialty Paper LLC
Certifying Party:	Edward Foote
Certifying Attention Person:	Not reported
Title Of Certifying Person:	Not reported
Certifying Person Address:	Not reported
Certifying Person City,St,Zip:	Not reported
Property Transfer Forms:	Form III (DEP-PERD-PTP-203) when a discharge, spillage, uncontrolled loss, seepage or filtration of hazardous waste has occurred at the parcel that has not been fully remediated or the environmental conditions at the parcel are unknown. The person signing the Form III certification agrees to investigate and remediate the site in accordance with the remediation standards. The statute does not require completion of remediation before the parcel is transferred.

BIORIGIN SPECIALTY PRODUCTS (DBA DUNN PAPER - EAST HARTFORD) (Continued) **1000292853**

	Any person submitting a Form III shall simultaneously submit a completed Environmental Condition Assessment Form (ECAF)(DEP-PERD-PTP-200).
Date Recieved:	01/22/1998
Ackn Date:	03/30/1998
Determination Date:	04/22/1998
LEP Verified/DEP Approval Date:	Not reported
Rem Id:	3703
Remediation Location Id:	1596
Date Entered:	Not reported
Program:	Property Transfer Program
GAO Site:	False
Staff Full Name:	Maurice Hamel
Super/Date:	Not reported
Stage Of Project:	Not reported
RP Level Of Activity:	Not reported
RP Needed Level Of Activity:	Not reported
Staff Level Of Activity:	Not reported
Staff Needed Level Of Activity:	Not reported
Public Intrest:	Not reported
PRP Cooperation:	Not reported
Enforcement Status:	Not reported
Level Of Complexity:	Not reported
Complex Eng Or Sci:	False
Complex Due To Public Involvement:	False
Politically Complex:	False
Complex Enforcement:	False
Coordination With Other Bureaus:	False
EPA Involvement:	False
Staff Prefrence:	Not reported
Readiness For Transfer:	Not reported
Project Transfer Time:	Not reported
Transfer Comments:	Not reported
Staff As Of July 2000:	Hamel Maurice
Initial Staff:	MRH
Type Of Transfer:	Not reported
Salutation:	Not reported
Relationship To Transfer:	transferor
Audit Date:	Not reported
Verif Type:	Not reported
Audit Outcome:	Not reported
GW:	GA
Basin:	Not reported
1st Payment:	2000
Pay Tag1:	Not reported
2nd Payment:	Not reported
Pay Tag2:	Not reported
RTN:	02/06/1998
Revised:	3/16/1998
ECAF Received:	Not reported
Old Determination Date:	LEP-98/04/22
Redeterminationdate:	Not reported
Previous Determination:	Not reported
Monitoringoption:	Not reported
Postremedialmonitoring:	Not reported
Schedule Of I/R:	05/27/1998
Schedule Overdue:	Not reported

BIORIGIN SPECIALTY PRODUCTS (DBA DUNN PAPER - EAST HARTFORD) (Continued) **1000292853**

Aprvl Sched:	Not reported
Yr 1 Report:	Not reported
Yr 2 Report:	Not reported
Report Overdue:	Not reported
Ext Aprvl Sched:	Not reported
License #:	Not reported
Project Phase:	Not reported
PT Comments:	Not reported
EPA Id Number:	Not reported
GW Class:	Not reported
SW Class:	Not reported
AO/C0:	Not reported
Water Lead(Y Or N):	Not reported
Priority:	Not reported
Project Status(A, I Or D):	Not reported
Last Updated:	Not reported
SR Comments:	Not reported
Priority Or Work-Load:	Not reported
Status:	Not reported
Notes:	Not reported
Special Project Name:	Not reported
Special Project Comments:	Not reported
DOT Project:	Not reported
Pt Counter:	Not reported
Project Complete:	False
Project Inactive:	False
Int Deposit #:	Not reported
Deposit #:	Not reported
Spill Case #:	Not reported
Diversion Id:	Not reported
Public Notice:	Not reported
RAP Received:	Not reported
RAP Approved:	Not reported
Compliance Category:	Not reported
Delete Record:	False
ECAF Reviewed By:	Not reported
Not Locatable:	False
Primary Address:	True
AKA Site Name:	False
Primary Site Name:	True
AKA Site Address:	False
Lead:	LEP

SPILLS:

Name:	Not reported
Address:	2 FORBES ST
City,State,Zip:	EAST HARTFORD, CT
Year of Database:	2003
Case Number:	200305942
Who Took Spill:	933
Assigned To:	No Response
Report Date:	08/12/2003
Report Time:	12:00:00 AM
Date Release:	08/12/2003
Release Time:	12:00:00 AM
Reported By:	anonymous
Phone:	860 1111111

BIORIGIN SPECIALTY PRODUCTS (DBA DUNN PAPER - EAST HARTFORD) (Continued) **1000292853**

Qty:	0.00 (Gallons)
Telephone:	Not reported
Representing:	Self
Facility Status:	Closed
Continuous Spill:	False
Release Substance:	UNKNOWN CHEMICAL
Emergency Measure:	white substance in the hockanum river from the paper mill from 8/12/2003 information given to colette ready from water bureau, they will check the complaint
Discharger:	cellu-tissue
Waterbody Affected:	Not reported
Responsible Party:	false
Responsible Party Address:	Not reported
RP City,St,Zip:	CT
Terminated:	YES
Recovered Total:	0
Total Water:	0
Historic:	False
Waterbody:	Not reported
User Stamp:	Not reported
Stamp Time:	2003-08-13 09:53:15
SR Inspector:	Santacroce, Jim
AT Inspector:	**NO RESPONSE
Corrective Action Taken:	Dissipated
Cause Info:	Dumping
Media Info:	Surface Water
Release Type:	chemical, and other (UNKNOWN)
Incident Description:	Not reported
Cost Recovery Case?:	Not reported
DEMHS Region:	Not reported
Lat/Long:	Not reported
Company Name:	Not reported
Last Updated:	Not reported

Action:

Action:	Dissipated
Other Action:	Not reported

Agency:

Agency ID:	DEP
Other Agency:	Not reported
DEP Bureau:	BUREAU OF WATER MANAGEMENT
DEP Agency:	PERMITTING, ENFORCEMENT & REMEDIATION

Cause:

Cause ID:	Dumping
Other Cause:	Not reported

Media:

Media ID:	Surface Water
Other Media:	Not reported

Release Class:

Class ID:	Industrial
Other Class:	Not reported

BIORIGIN SPECIALTY PRODUCTS (DBA DUNN PAPER - EAST HARTFORD) (Continued) **1000292853**

Release Type:

Release Type:	chemical
Other Release:	Not reported
Release Type:	other
Other Release:	UNKNOWN
Name:	Not reported
Address:	2 FORBES ST
City,State,Zip:	EAST HARTFORD, CT
Year of Database:	2006
Case Number:	200605657
Who Took Spill:	916
Assigned To:	No Response
Report Date:	09/07/2006
Report Time:	12:00:00 AM
Date Release:	09/07/2006
Release Time:	12:00:00 AM
Reported By:	KEN HINES
Phone:	860 2501926
Qty:	2.00 (Gallons)
Telephone:	Not reported
Representing:	CL&P
Facility Status:	CLOSED
Continuous Spill:	False
Release Substance:	TRANSFORMER OIL
Emergency Measure:	PAD MOUNTED TRANSFORMER FAILED, ESI CONTRACTED. NON PCB.
Discharger:	SAA
Waterbody Affected:	Not reported
Responsible Party:	true
Responsible Party Address:	Not reported
RP City,St,Zip:	CT
Terminated:	YES
Recovered Total:	2
Total Water:	0
Historic:	False
Waterbody:	Not reported
User Stamp:	mgranill
Stamp Time:	2006-09-11 10:25:33
SR Inspector:	Stavola, Rosanne
AT Inspector:	**NO RESPONSE
Corrective Action Taken:	Removed, and Contained, and Contracted
Cause Info:	Trans/Capac.
Media Info:	Ground Surface
Release Type:	dielect
Incident Description:	Not reported
Cost Recovery Case?:	Not reported
DEMHS Region:	Not reported
Lat/Long:	Not reported
Company Name:	Not reported
Last Updated:	Not reported

Action:

Action:	Removed
Other Action:	Not reported

BIORIGIN SPECIALTY PRODUCTS (DBA DUNN PAPER - EAST HARTFORD) (Continued) **1000292853**

Action:	Contained
Other Action:	Not reported
Action:	Contracted
Other Action:	Not reported

Cause:

Cause ID:	Trans/Capac.
Other Cause:	Not reported

Media:

Media ID:	Ground Surface
Other Media:	Not reported

Release Class:

Class ID:	Utility
Other Class:	Not reported

Release Type:

Release Type:	dielect
Other Release:	Not reported

Name:	Not reported
Address:	2 FORBES ST
City,State,Zip:	EAST HARTFORD, CT
Year of Database:	2007
Case Number:	200701020
Who Took Spill:	205
Assigned To:	Emanuelson, Brian
Report Date:	02/19/2007
Report Time:	10:00:00 AM
Date Release:	02/19/2007
Release Time:	10:00:00 AM
Reported By:	Jim Smith
Phone:	402 5600408
Qty:	6.00 (Gallons)
Telephone:	Not reported
Representing:	Crete Carrier
Facility Status:	CLOSED
Continuous Spill:	False
Release Substance:	ANTIFREEZE
Emergency Measure:	TT radiator, caller wants to know if ATC can clean up. 912 notified.
Discharger:	saa
Waterbody Affected:	Other (none)
Responsible Party:	true
Responsible Party Address:	130 South Thirtenth St
RP City,St,Zip:	LINCOLN, NE 68508-
Terminated:	YES
Recovered Total:	0
Total Water:	0
Historic:	False
Waterbody:	n/a
User Stamp:	mgranill
Stamp Time:	2007-03-09 08:55:25

BIORIGIN SPECIALTY PRODUCTS (DBA DUNN PAPER - EAST HARTFORD) (Continued) **1000292853**

SR Inspector:	Cox, Michael
AT Inspector:	Emanuelson, Brian
Corrective Action Taken:	Removed, and Sanded, and Pumped Out
Cause Info:	Other (ruptured radiator)
Media Info:	Other (asphalt surface)
Release Type:	chemical
Incident Description:	Not reported
Cost Recovery Case?:	Not reported
DEMHS Region:	Not reported
Lat/Long:	Not reported
Company Name:	Not reported
Last Updated:	Not reported

Action:

Action:	Removed
Other Action:	Not reported
Action:	Sanded
Other Action:	Not reported
Action:	Pumped Out
Other Action:	Not reported

Agency:

Agency ID:	DEP Dispatch
Other Agency:	Not reported
DEP Bureau:	Not reported
DEP Agency:	Not reported

Cause:

Cause ID:	Other
Other Cause:	ruptured radiator

Media:

Media ID:	Other
Other Media:	asphalt surface

Release Class:

Class ID:	Transportation
Other Class:	Not reported
Class ID:	Commercial
Other Class:	Not reported

Release Type:

Release Type:	chemical
Other Release:	Not reported

Waterbody:

Waterbody:	Other
Other Waterbody:	none
Name:	Not reported
Address:	2 FORBES ST.

BIORIGIN SPECIALTY PRODUCTS (DBA DUNN PAPER - EAST HARTFORD) (Continued) **1000292853**

City,State,Zip:	EAST HARTFORD, CT
Year of Database:	2013
Case Number:	201300252
Who Took Spill:	203
Assigned To:	Emanuelson, Brian
Report Date:	01/11/2013
Report Time:	12:00:00 PM
Date Release:	01/11/2013
Release Time:	12:00:00 PM
Reported By:	Chris Fiedler
Phone:	860 8362953
Qty:	0.00 (Gallons)
Telephone:	Not reported
Representing:	CelluTissue (manufacturer of toilet tissue)
Facility Status:	CLOSED
Continuous Spill:	False
Release Substance:	WATER WITH PAPER FIBERS
Emergency Measure:	Leak through wall plugged.
Discharger:	CELLU TISSUE
Waterbody Affected:	River
Responsible Party:	Not reported
Responsible Party Address:	2 FORBES STREET
RP City,St,Zip:	East Hartford, CT 06108
Terminated:	YES
Recovered Total:	0
Total Water:	0
Historic:	False
Waterbody:	Hockanum River
User Stamp:	Granillom
Stamp Time:	2014-08-05 16:07:43
SR Inspector:	SUSAN CAMBELL
AT Inspector:	Emanuelson, Brian
Corrective Action Taken:	Dispersed
Cause Info:	Seepage
Media Info:	Surface Water
Release Type:	chemical
Incident Description:	Not reported
Cost Recovery Case?:	Not reported
DEMHS Region:	Not reported
Lat/Long:	Not reported
Company Name:	Not reported
Last Updated:	Not reported

Action:

Action:	Dispersed
Other Action:	Not reported

Agency:

Agency ID:	Other
Other Agency:	State Water Authority
DEP Bureau:	Not reported
DEP Agency:	Not reported

Cause:

Cause ID:	Seepage
Other Cause:	Not reported

BIORIGIN SPECIALTY PRODUCTS (DBA DUNN PAPER - EAST HARTFORD) (Continued) **1000292853**

Media:
Media ID: Surface Water
Other Media: Not reported

Release Class:
Class ID: Industrial
Other Class: Not reported

Release Type:
Release Type: chemical
Other Release: Not reported

Waterbody:
Waterbody: River
Other Waterbody: Not reported

ICIS:
Enforcement Action ID: CT000A200140886
FRS ID: 110043782127
Action Name: C.O. #2466
Facility Name: CELLU TISSUE CORPORATION
Facility Address: 2 FORBES STREET
EAST HARTFORD, CT 06108
Enforcement Action Type: Administrative Order
Facility County: HARTFORD
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: SCAAAO
Facility SIC Code: 2676
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 41.776267
Longitude in Decimal Degrees: -72.606423
Permit Type Desc: Not reported
Program System Acronym: CT0000000900301558
Facility NAICS Code: 322291
Tribal Land Code: Not reported

Enforcement Action ID: CT000A200140885
FRS ID: 110043782127
Action Name: NOV #17657
Facility Name: CELLU TISSUE CORPORATION
Facility Address: 2 FORBES STREET
EAST HARTFORD, CT 06108
Enforcement Action Type: Notice of Violation
Facility County: HARTFORD
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Informal
EA Type Code: NOV
Facility SIC Code: 2676
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 41.776267
Longitude in Decimal Degrees: -72.606423

BIORIGIN SPECIALTY PRODUCTS (DBA DUNN PAPER - EAST HARTFORD) (Continued) **1000292853**

Permit Type Desc: Not reported
Program System Acronym: CT0000000900301558
Facility NAICS Code: 322291
Tribal Land Code: Not reported

Enforcement Action ID: CT000A0000090030155800009
FRS ID: 110043782127
Action Name: CELLU TISSUE CORPORATION 090030155800009
Facility Name: CELLU TISSUE CORPORATION
Facility Address: 2 FORBES STREET
EAST HARTFORD, CT 06108
Enforcement Action Type: Notice of Violation
Facility County: HARTFORD
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Informal
EA Type Code: NOV
Facility SIC Code: 2676
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 41.776267
Longitude in Decimal Degrees: -72.606423
Permit Type Desc: Not reported
Program System Acronym: CT0000000900301558
Facility NAICS Code: 322291
Tribal Land Code: Not reported

Enforcement Action ID: 01-2011-9045
FRS ID: 110043782127
Action Name: CLEARWATER PAPER CORP
Facility Name: CLEARWATER PAPER CORP
Facility Address: 2 FORBES STREET
EAST HARTFORD, CT 06108
Enforcement Action Type: CAA 113D1 Action For Penalty
Facility County: HARTFORD
Program System Acronym: ICIS
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: 113D1
Facility SIC Code: Not reported
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 41.773
Longitude in Decimal Degrees: -72.60657
Permit Type Desc: Not reported
Program System Acronym: 2600026826
Facility NAICS Code: Not reported
Tribal Land Code: Not reported

Facility Name: CLEARWATER PAPER
Address: 2 FORBES STREET
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: CLEARWATER PAPER
Address: 2 FORBES STREET
Tribal Indicator: N
Fed Facility: No

BIORIGIN SPECIALTY PRODUCTS (DBA DUNN PAPER - EAST HARTFORD) (Continued) **1000292853**

NAIC Code: Not reported
SIC Code: Not reported

Facility Name: CLEARWATER PAPER
Address: 2 FORBES STREET
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: CLEARWATER PAPER
Address: 2 FORBES STREET
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: CLEARWATER PAPER
Address: 2 FORBES STREET
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

CPCS:
Name: Cellu-Tissue Corp.
Address: 2 FORBES STREET
City,State,Zip: EAST HARTFORD, CT 06108
Site Type: Not reported
Lust Status code: Not reported
Lust Status: Not reported
PTP Form: III
Program: Property Transfer Program
Comments: Projects
Site Type Definition: Property Transfer Form III
Invesigation Start: Not reported
Invesigation Start Date: 03/30/1998
Remediation Start: Not reported
Remediation Start Date: Not reported
Remediation Completed: No
ELUR: No
Date Data Updated: Not reported

NPDES:
Name: CELLU TISSUE CORPORATION
Address: 2 FORBES STREET
City: EAST HARTFORD
Town Id: 43
Company Name: CELLU TISSUE CORPORATION
Permit Number: GSW000453
Permit Issued Date: 11/24/1992
Permit Expiration Date: 10/01/1997
Application Received Date: 11/24/1992
Affiliation Type: Not reported
Permit EI Type: Not reported
App Id: Not reported

BIORIGIN SPECIALTY PRODUCTS (DBA DUNN PAPER - EAST HARTFORD) (Continued) **1000292853**

Site Address Description:	Not reported
Site Address Line 2:	Not reported
Permit Description:	Not reported
Status:	Not reported
Affiliate Address Line 1:	Not reported
Affiliate Address Line 2:	Not reported
Affiliate City/State/Zip:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact EMail:	Not reported

Name:	CELLU TISSUE CORPORATION
Address:	2 FORBES STREET
City:	EAST HARTFORD
Town Id:	43
Company Name:	CELLU TISSUE CORPORATION
Permit Number:	SP0002347
Permit Issued Date:	Not reported
Permit Expiration Date:	Not reported
Application Received Date:	08/11/1998
Affiliation Type:	Not reported
Permit EI Type:	Not reported
App Id:	Not reported
Site Address Description:	Not reported
Site Address Line 2:	Not reported
Permit Description:	Not reported
Status:	Not reported
Affiliate Address Line 1:	Not reported
Affiliate Address Line 2:	Not reported
Affiliate City/State/Zip:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact EMail:	Not reported

Name:	CELLU TISSUE CORPORATION
Address:	2 FORBES STREET
City:	EAST HARTFORD
Town Id:	43
Company Name:	CELLU TISSUE CORPORATION
Permit Number:	GSI000309
Permit Issued Date:	12/05/1997
Permit Expiration Date:	10/01/2002
Application Received Date:	11/19/1997
Affiliation Type:	Not reported
Permit EI Type:	Not reported
App Id:	Not reported
Site Address Description:	Not reported
Site Address Line 2:	Not reported
Permit Description:	Not reported
Status:	Not reported
Affiliate Address Line 1:	Not reported
Affiliate Address Line 2:	Not reported
Affiliate City/State/Zip:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact EMail:	Not reported

BIORIGIN SPECIALTY PRODUCTS (DBA DUNN PAPER - EAST HARTFORD) (Continued) **1000292853**

Name:	CELLU TISSUE CORPORATION
Address:	2 FORBES STREET
City:	EAST HARTFORD
Town Id:	43
Company Name:	CELLU TISSUE CORPORATION
Permit Number:	GSI000309
Permit Issued Date:	12/05/1997
Permit Expiration Date:	10/01/2002
Application Received Date:	11/19/1997
Affiliation Type:	Not reported
Permit EI Type:	Not reported
App Id:	Not reported
Site Address Description:	Not reported
Site Address Line 2:	Not reported
Permit Description:	Not reported
Status:	Not reported
Affiliate Address Line 1:	Not reported
Affiliate Address Line 2:	Not reported
Affiliate City/State/Zip:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact EMail:	Not reported

Name:	CELLU TISSUE CORPORATION
Address:	2 FORBES STREET
City:	Not reported
Town Id:	43
Company Name:	CELLU TISSUE CORPORATION
Permit Number:	CT0002127
Permit Issued Date:	04/30/1997
Permit Expiration Date:	04/30/2002
Application Received Date:	04/02/1996
Affiliation Type:	Not reported
Permit EI Type:	Not reported
App Id:	Not reported
Site Address Description:	Not reported
Site Address Line 2:	Not reported
Permit Description:	Not reported
Status:	Not reported
Affiliate Address Line 1:	Not reported
Affiliate Address Line 2:	Not reported
Affiliate City/State/Zip:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact EMail:	Not reported

Name:	CELLU TISSUE CORP
Address:	2 FORBES STREET
City:	EAST HARTFORD
Town Id:	43
Company Name:	CELLU TISSUE CORPORATION
Permit Number:	CT0002127
Permit Issued Date:	10/24/2002
Permit Expiration Date:	10/24/2007
Application Received Date:	10/30/2001
Affiliation Type:	Not reported
Permit EI Type:	Not reported

BIORIGIN SPECIALTY PRODUCTS (DBA DUNN PAPER - EAST HARTFORD) (Continued) **1000292853**

App Id:	Not reported
Site Address Description:	Not reported
Site Address Line 2:	Not reported
Permit Description:	Not reported
Status:	Not reported
Affiliate Address Line 1:	Not reported
Affiliate Address Line 2:	Not reported
Affiliate City/State/Zip:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact EMail:	Not reported

Name:	CELLU TISSUE CORPORATION
Address:	2 FORBES STREET
City:	Not reported
Town Id:	43
Company Name:	CELLU TISSUE CORPORATION
Permit Number:	CT0002127
Permit Issued Date:	09/30/1991
Permit Expiration Date:	09/30/1996
Application Received Date:	05/11/1990
Affiliation Type:	Not reported
Permit EI Type:	Not reported
App Id:	Not reported
Site Address Description:	Not reported
Site Address Line 2:	Not reported
Permit Description:	Not reported
Status:	Not reported
Affiliate Address Line 1:	Not reported
Affiliate Address Line 2:	Not reported
Affiliate City/State/Zip:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact EMail:	Not reported

Name:	CELLU TISSUE CORPORATION
Address:	2 FORBES STREET
City:	Not reported
Town Id:	43
Company Name:	CELLU TISSUE CORPORATION
Permit Number:	CT0002127
Permit Issued Date:	10/14/1985
Permit Expiration Date:	10/14/1990
Application Received Date:	07/17/1985
Affiliation Type:	Not reported
Permit EI Type:	Not reported
App Id:	Not reported
Site Address Description:	Not reported
Site Address Line 2:	Not reported
Permit Description:	Not reported
Status:	Not reported
Affiliate Address Line 1:	Not reported
Affiliate Address Line 2:	Not reported
Affiliate City/State/Zip:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact EMail:	Not reported

BIORIGIN SPECIALTY PRODUCTS (DBA DUNN PAPER - EAST HARTFORD) (Continued) **1000292853**

Name:	CELLU TISSUE CORPORATION
Address:	2 FORBES STREET
City:	Not reported
Town Id:	43
Company Name:	CELLU TISSUE CORPORATION
Permit Number:	CT0002127
Permit Issued Date:	09/05/1979
Permit Expiration Date:	09/05/1984
Application Received Date:	01/01/1979
Affiliation Type:	Not reported
Permit EI Type:	Not reported
App Id:	Not reported
Site Address Description:	Not reported
Site Address Line 2:	Not reported
Permit Description:	Not reported
Status:	Not reported
Affiliate Address Line 1:	Not reported
Affiliate Address Line 2:	Not reported
Affiliate City/State/Zip:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact EMail:	Not reported

Name:	CELLU TISSUE CORPORATION
Address:	2 FORBES STREET
City:	Not reported
Town Id:	43
Company Name:	CELLU TISSUE CORPORATION
Permit Number:	CT0002127
Permit Issued Date:	Not reported
Permit Expiration Date:	Not reported
Application Received Date:	09/17/1984
Affiliation Type:	Not reported
Permit EI Type:	Not reported
App Id:	Not reported
Site Address Description:	Not reported
Site Address Line 2:	Not reported
Permit Description:	Not reported
Status:	Not reported
Affiliate Address Line 1:	Not reported
Affiliate Address Line 2:	Not reported
Affiliate City/State/Zip:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact EMail:	Not reported

Name:	CELLU TISSUE CORPORATION
Address:	2 FORBES STREET
City:	EAST HARTFORD
Town Id:	43
Company Name:	CELLU TISSUE CORPORATION
Permit Number:	CT0002127
Permit Issued Date:	Not reported
Permit Expiration Date:	Not reported
Application Received Date:	10/30/2001
Affiliation Type:	Not reported
Permit EI Type:	Not reported

BIORIGIN SPECIALTY PRODUCTS (DBA DUNN PAPER - EAST HARTFORD) (Continued) **1000292853**

App Id:	Not reported
Site Address Description:	Not reported
Site Address Line 2:	Not reported
Permit Description:	Not reported
Status:	Not reported
Affiliate Address Line 1:	Not reported
Affiliate Address Line 2:	Not reported
Affiliate City/State/Zip:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact EMail:	Not reported

Name:	CELLU TISSUE CORPORATION
Address:	2 FORBES STREET
City:	Not reported
Town Id:	43
Company Name:	CELLU TISSUE CORPORATION
Permit Number:	CT0002127
Permit Issued Date:	04/30/1997
Permit Expiration Date:	04/30/2002
Application Received Date:	04/02/1996
Affiliation Type:	Not reported
Permit EI Type:	Not reported
App Id:	Not reported
Site Address Description:	Not reported
Site Address Line 2:	Not reported
Permit Description:	Not reported
Status:	Not reported
Affiliate Address Line 1:	Not reported
Affiliate Address Line 2:	Not reported
Affiliate City/State/Zip:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact EMail:	Not reported

Name:	CELLU TISSUE CORPORATION
Address:	2 FORBES STREET
City:	EAST HARTFORD
Town Id:	43
Company Name:	CELLU TISSUE CORPORATION
Permit Number:	SP0002347
Permit Issued Date:	08/05/2002
Permit Expiration Date:	08/05/2007
Application Received Date:	08/11/1998
Affiliation Type:	Not reported
Permit EI Type:	Not reported
App Id:	Not reported
Site Address Description:	Not reported
Site Address Line 2:	Not reported
Permit Description:	Not reported
Status:	Not reported
Affiliate Address Line 1:	Not reported
Affiliate Address Line 2:	Not reported
Affiliate City/State/Zip:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact EMail:	Not reported

E39 **CELLU TISSUE LLC** **CT ENF** **S109727069**
South **2 FORBES ST** **CT MANIFEST** **N/A**
1/8-1/4 **EAST HARTFORD, CT 06108**
0.210 mi.
1110 ft. **Site 11 of 12 in cluster E**

Relative:
Lower

Actual:
48 ft.

ENFORCEMENT:

Name:	CELLU TISSUE LLC
Address:	2 FORBES ST
City,State,Zip:	EAST HARTFORD, CT 06108
Enforcement Action ID:	NOVWRIN05036
Enforcement Type Code:	Notice Of Violation
Program Id:	Not reported
Enforcement Action Date:	12/28/2005
Penalty Amount:	$0.00
Sep Amt:	Not reported
Bureau Name:	Materials Management & Compliance Assurance
Program:	Industrial NPDES Enforcement
Status:	Closed
Date of Discovery:	Not reported
Resolution Date:	02/06/2007
Resolution Type:	None
Staff:	Langan Rita
ENF Action Comment:	CT0002127
Number Violations:	Not reported
Civil Penalty:	Not reported
SEP Description:	Not reported
Associated EIs:	Not reported
Client Affiliation Type:	Respondent
Affiliation Name:	DUNN PAPER-EAST HARTFORD, LLC.
Affiliation Address Line1:	2 FORBES ST
Affiliation Address Line2:	Not reported
Affiliation City/State/Zip:	EAST HARTFORD, CT 06108 3727
Contact Title:	Not reported
Contact Name:	Not reported
Contact EMail:	Not reported

CT MANIFEST:

Name:	DUNN PAPER
Address:	2 FORBES STREET
City,State,Zip:	EAST HARTFORD, CT
Phone:	Not reported
Country:	Not reported
Manifest ID:	Not reported
EPA ID:	CTD04771412

Hazardous Waste Manifest:

Year:	2016
Manifest:	014402026JJK
EPA ID:	CTD04771412
Generator Mailing Address:	Not reported
Generator City,State,Zip:	Not reported
Discrepancies:	Not reported
Date Shipped:	2016-07-28
Date Received:	Not reported
Transporter 2 Date:	Not reported
TSDF EPA ID:	Not reported
TSDF Name:	Not reported

CELLU TISSUE LLC (Continued) **S109727069**

TSDF Address:	Not reported
TSDF City,State,Zip:	Not reported
TSDF Country:	Not reported
Transporter EPA ID:	Not reported
Transporter Name:	Not reported
Transporter Address:	Not reported
Transporter City,State,Zip:	Not reported
Transporter Country:	Not reported
Transporter 2 EPA ID:	Not reported
Transporter 2 Name:	Not reported
Transporter 2 Address:	Not reported
Transporter 2 City,State,Zip:	Not reported
Transporter 2 Country:	Not reported
US DOT Description:	Not reported
Number of Containers:	Not reported
Container Type:	Not reported
Quantity/Weight/Volume:	/
Batch Number:	Not reported
EPA Waste Codes:	- Not reported
Copies:	Not reported
Alternate Facility Name:	Not reported
Alternate Facility Address:	Not reported
Alternate Facility State:	Not reported
Alternate Facility Date:	Not reported

DEEP Document:

Year:	2016
EPA ID:	CTD04771412
Statuory Program:	Hazardous Waste
Document Number:	014402026JJK
Document:	Hazardous Waste Manifest
File Type:	Written Text
Reference ID:	Ref ID: 014402026JJK Alt ID: CTD04771412

Click Here to view the image from agency website:

E40 **CELLU TISSUE** **CT SPILLS** **S109735439**
South **2 FORBES ST** **CT MANIFEST** **N/A**
1/8-1/4 **EAST HARTFORD, CT 06108**
0.210 mi.
1110 ft. **Site 12 of 12 in cluster E**

Relative: **Lower**

Actual: **48 ft.**

SPILLS:

Name:	Not reported
Address:	2 FORBES STREET
City,State,Zip:	EAST HARTFORD, CT
Year of Database:	2020
Case Number:	202001654
Who Took Spill:	208
Assigned To:	No Response
Report Date:	04/24/2020
Report Time:	12:00:00 AM
Date Release:	04/24/2020
Release Time:	12:00:00 AM
Reported By:	jared otto
Phone:	860 4664181
Qty:	1.00 (Gallons)

CELLU TISSUE (Continued) **S109735439**

Telephone:	Not reported
Representing:	dunn paper
Facility Status:	CLOSED
Continuous Spill:	False
Release Substance:	GASOLINE
Emergency Measure:	sanded
Discharger:	Not reported
Waterbody Affected:	Not reported
Responsible Party:	Not reported
Responsible Party Address:	Not reported
RP City,St,Zip:	CT
Terminated:	YES
Recovered Total:	0
Total Water:	0
Historic:	False
Waterbody:	Not reported
User Stamp:	Guzmanca
Stamp Time:	2020-04-24 16:39:13
SR Inspector:	Monarca, Vincent
AT Inspector:	**NO RESPONSE
Corrective Action Taken:	Cleaned
Cause Info:	MV Accident
Media Info:	Ground Surface
Release Type:	petroleum
Incident Description:	Not reported
Cost Recovery Case?:	Not reported
DEMHS Region:	Not reported
Lat/Long:	Not reported
Company Name:	Not reported
Last Updated:	Not reported

Action:

Action:	Cleaned
Other Action:	Not reported

Agency:

Agency ID:	DEP Dispatch
Other Agency:	Not reported
DEP Bureau:	Not reported
DEP Agency:	Not reported

Cause:

Cause ID:	MV Accident
Other Cause:	Not reported

Media:

Media ID:	Ground Surface
Other Media:	Not reported

Release Class:

Class ID:	Transportation
Other Class:	Not reported
Class ID:	Commercial
Other Class:	Not reported

CELLU TISSUE (Continued) **S109735439**

Release Type:
Release Type: petroleum
Other Release: Not reported

Name: Not reported
Address: 2 FORBES ST
City,State,Zip: EAST HARTFORD, CT
Year of Database: 2020
Case Number: 202002006
Who Took Spill: 209
Assigned To: No Response
Report Date: 05/19/2020
Report Time: 12:00:00 AM
Date Release: 05/19/2020
Release Time: 12:00:00 AM
Reported By: jared otto
Phone: 860 4664181
Qty: 1.00 (Gallons)
Telephone: Not reported
Representing: Self
Facility Status: CLOSED
Continuous Spill: False
Release Substance: DIESEL FUEL
Emergency Measure: cleaned
Discharger: Not reported
Waterbody Affected: Not reported
Responsible Party: Not reported
Responsible Party Address: Not reported
RP City,St,Zip: CT
Terminated: Not reported
Recovered Total: 0
Total Water: 0
Historic: False
Waterbody: Not reported
User Stamp: GuzmanCa
Stamp Time: 2020-05-20 09:36:59
SR Inspector: WELCH, THOMAS
AT Inspector: **NO RESPONSE
Corrective Action Taken: Not reported
Cause Info: Not reported
Media Info: Ground Surface
Release Type: petroleum
Incident Description: Not reported
Cost Recovery Case?: Not reported
DEMHS Region: Not reported
Lat/Long: Not reported
Company Name: Not reported
Last Updated: Not reported

Media:
Media ID: Ground Surface
Other Media: Not reported

Release Type:
Release Type: petroleum
Other Release: Not reported

CELLU TISSUE (Continued) **S109735439**

CT MANIFEST:

Name:	CELLU TISSUE
Address:	2 FORBES ST
City,State,Zip:	EAST HARTFORD, CT 06108
Phone:	Not reported
Country:	Not reported
Manifest ID:	NYA3534074
EPA ID:	CTP000005096

Hazardous Waste Manifest:

Year:	1986
Manifest:	NYA3534074
EPA ID:	CTP000005096
Generator Mailing Address:	2 FORBES ST
Generator City,State,Zip:	EAST HARTFORD, CT 06108
Discrepancies:	Y
Date Shipped:	1986-05-23
Date Received:	1986-05-28
Transporter 2 Date:	Not reported
TSDF EPA ID:	NYD043815703
TSDF Name:	FRONTIER CHEMICAL WASTE PROCESS INC
TSDF Address:	4626 ROYAL AVE
TSDF City,State,Zip:	NIAGARA FALLS, NY 14303
TSDF Country:	USA
Transporter EPA ID:	RID000769711
Transporter Name:	RS LIQUID WASTE DISPOSAL INC
Transporter Address:	Not reported
Transporter City,State,Zip:	CT
Transporter Country:	USA
Transporter 2 EPA ID:	Not reported
Transporter 2 Name:	Not reported
Transporter 2 Address:	Not reported
Transporter 2 City,State,Zip:	CT
Transporter 2 Country:	USA
US DOT Description:	WASTE PHOSPHORIC ACID
Number of Containers:	002
Container Type:	DM
Quantity/Weight/Volume:	60/G
Batch Number:	999999
EPA Waste Codes:	D002 - CORROSIVE WASTE
Copies:	2
Alternate Facility Name:	Not reported
Alternate Facility Address:	Not reported
Alternate Facility State:	Not reported
Alternate Facility Date:	Not reported

---

41 **CHUCKS AUTOMOTIVE** **RCRA-VSQG** **1016140620**
West **635 BURNSIDE AVE** **FINDS** **CTR000505032**
1/8-1/4 **EAST HARTFORD, CT 06108** **ECHO**
0.238 mi.
1259 ft.

Relative: **Lower**

Actual: **47 ft.**

RCRA Listings:

Date Form Received by Agency:	20041117
Handler Name:	Chucks Automotive
Handler Address:	Burnside Ave
Handler City,State,Zip:	EAST HARTFORD, CT 06108

CHUCKS AUTOMOTIVE (Continued) **1016140620**

EPA ID:		CTR000505032
Contact Name:		CHUCK TISCHOFER
Contact Address:		BURNSIDE AVE
Contact City,State,Zip:		EAST HARTFORD, CT 06108
Contact Telephone:		860-289-0081
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		01
Land Type:		Not reported
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
Non-Notifier:		E
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		BURNSIDE AVE
Mailing City,State,Zip:		EAST HARTFORD, CT 06108
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20041221
Recognized Trader-Importer:		No

CHUCKS AUTOMOTIVE (Continued) **1016140620**

Recognized Trader-Exporter: No
Importer of Spent Lead Acid Batteries: No
Exporter of Spent Lead Acid Batteries: No
Recycler Activity Without Storage: No
Manifest Broker: No
Sub-Part P Indicator: No

Historic Generators:
Receive Date: 20041117
Handler Name: CHUCKS AUTOMOTIVE
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Has the Facility Received Notices of Violations:
Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: State Statute or Regulation
Date Violation was Determined: 20041117
Actual Return to Compliance Date: 20050218
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: 20050223
Enforcement Identifier: 001
Date of Enforcement Action: 20050124
Enforcement Responsible Agency: State
Enforcement Docket Number: Wswdh05008
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: RFGCT
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported

CHUCKS AUTOMOTIVE (Continued) **1016140620**

SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: State Statute or Regulation
Date Violation was Determined: 20041117
Actual Return to Compliance Date: 20050218
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: 20050223
Enforcement Identifier: 001
Date of Enforcement Action: 20050124
Enforcement Responsible Agency: State
Enforcement Docket Number: Wswdh05008
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: RFGCT
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 20041117
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: FOCUSED COMPLIANCE INSPECTION
Evaluation Responsible Person Identifier: RFGCT
Evaluation Responsible Sub-Organization: Not reported
Actual Return to Compliance Date: 20050218
Scheduled Compliance Date: 20050223
Date of Request: Not reported

CHUCKS AUTOMOTIVE (Continued) **1016140620**

Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20041117
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	FOCUSED COMPLIANCE INSPECTION
Evaluation Responsible Person Identifier:	RFGCT
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	20050218
Scheduled Compliance Date:	20050223
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

FINDS:
Registry ID: 110055441213

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016140620
Registry ID:	110055441213
DFR URL:	
Name:	CHUCKS AUTOMOTIVE
Address:	635 Burnside Ave
City,State,Zip:	EAST HARTFORD, CT 06108

---

42 WNW 1/4-1/2 0.254 mi. 1341 ft. **BERNIE BODINE, ESTATE OF LAWRENCE PELITER** **CT LUST** **S105440843**
66 SCHOOL ST. **CT SPILLS** **N/A**
EAST HARTFORD, CT 06108 **CT CPCS**

Relative: Lower
Actual: 55 ft.

LUST:

Name:	BERNIE BODINE, ESTATE OF LAWRENCE PELITER
Name 2:	Not reported
Address:	66 SCHOOL ST.
Address 2:	Not reported
City,State,Zip:	EAST HARTFORD, CT 06108
LUST Case Id:	34294
Release Date:	Not reported
Site Case ID:	9804197

BERNIE BODINE, ESTATE OF LAWRENCE PELITER (Continued) **S105440843**

Substance:	Not reported
Release Source:	Not reported
Release Cause:	Not reported
Release Identified:	Not reported
Case Number:	Not reported
Release Quantity:	Not reported
Facility City Number:	43

Detail As of 06/2020:

Name:	BERNIE BODINE, ESTATE OF LAWRENCE PELITER
Name 2:	Not reported
Address:	66 SCHOOL ST.
City,State,Zip:	EAST HARTFORD, CT 06108
Address 2:	Not reported
LUST Id:	6169
UST Facility Id:	Not reported
LUST Case Id:	34294
Lust Status:	Lust Completed
Processing Status:	Not reported
EPA Reportable:	False
Motor Fuel:	False
Diesel:	False
Gasoline:	False
Other:	False
Other Release:	Not reported
No Release:	False
Leak:	False
Tank:	False
Piping:	False
Overfill:	False
Removal:	False
Incident Date:	07/01/1998
Entry Date:	Not reported
Site Case Id:	9804197
UST Site Id:	Not reported
Cost Recovery Spill Case #:	Not reported
Old SITS Number:	Not reported
Case Log Id:	Not reported
Monthly Report Id:	0
UST Owner Id:	Not reported
LUST Owner Id:	Not reported
UST Event Id:	6284
Contact Info:	Not reported
Contact EMail:	Not reported
Site Contact City,St,Zip:	UNKNOWN
2nd Contact:	Not reported
2nd Contact EMail:	Not reported
2nd Contact Address:	Not reported
2nd Contact City,St,Zip:	UNKNOWN
2nd Contact Address 2:	Not reported
2nd Contact City 2:	Not reported
2nd Contact Phone Number:	Not reported
2nd Contact Fax Number:	Not reported
2nd Contact Type:	Not reported
Facility City Num:	43
Site Contact:	Not reported
Site Contact Address:	Not reported
Site Contact Add 2:	Not reported

BERNIE BODINE, ESTATE OF LAWRENCE PELITER (Continued) **S105440843**

Site Contact City 2:	Not reported
Site Contact Phone:	Not reported
Site Contact Fax:	Not reported
Site Contact Type:	Not reported
Department Contact 1:	Not reported
Department Contact 2:	Not reported
Referral Source:	Not reported
Offsite Source:	False
Date Referred:	Not reported
Emergency:	False
Private Heating Fuel:	False
Commercial Heating Fuel:	True
Commercial HF < 2100 Gal.:	True
Commercial HF > 2100 Gal.:	False
Commercial HF - Size Unk:	False
No LUST Site:	False
Cost Recvry Prgm Candidate:	False
OCSRD Complete:	True
Follow Up Flag:	False
Alternate Water Supply:	False
Relocation:	False
Responsible Party:	False
Responsible EMail:	Not reported
Resp Party Name:	Not reported
Resp Party Address:	Not reported
Resp Party City,St,Zip:	Not reported
Resp Party Town Number:	UNKNOWN
Resp Party Phone:	Not reported
Resp Party Fax:	Not reported
Resp Party Name 2:	Not reported
Resp Party Address 2:	Not reported
Resp Party Phone 2:	Not reported
Investigator Id:	24
Follow Update:	Not reported
Area Lextent:	Not reported
Annual Precipitation:	Not reported
Affected Population:	Not reported
Population Setting:	Not reported
Ground Water Direction:	Not reported
Ground Water Gradient:	Not reported
Hydro Basin:	Not reported
Drastic:	Not reported
Geo Setting:	Not reported
Ground Water Classification:	Not reported
Receptor:	Not reported
Ground Water Flow Direction:	Not reported
Ground Water Depth:	Not reported
Areas Of Concern:	Not reported
Free Product Inches:	Not reported
Fund Date:	Not reported
Fund Planned:	No
Fund Obligated:	No
Fund Outlayed:	No
Fund Judgment:	No
Fund Recovered:	No
Cellar Borings:	False
Install Micro Wells:	False

BERNIE BODINE, ESTATE OF LAWRENCE PELITER (Continued) **S105440843**

Ground Water Sample:	False
Soil Sample:	False
Soil Gas:	False
Site Inspect:	False
Soil Excavate:	False
Geo Probe:	False
Survey:	False
Potable Well Sample:	False
Sample MWS:	False
Ground Water Gauging:	False
Soil Venting:	False
Active:	False
NOV Action:	None
NOV Issued:	Not reported
NOV Due:	Not reported
NOV Received:	Not reported
NOV Closed:	Not reported
NOV Disc Date:	Not reported
NOV Issued Date:	Not reported
NOV Compliance Sched:	Not reported
NOV Admin Order:	Not reported
NOV Referred To Ag:	Not reported
Stop All NOV Actions:	False
Release Invest Rpt:	False
DEP App Letter 1:	False
Correct Action Plan:	False
DEP App Letter 2:	False
Rem Sys Install:	False
Rem Sys Install Date:	Not reported
Closure Date:	Not reported
Rem Sys Monitoring Rpt:	False
Qrtly Gwater Mon Rpts:	False
Closure Req Rpt:	False
DEP Closure Letter:	False
Referred To:	Not reported
No Wells:	Not reported
Lph Wells:	Not reported
User Stamp:	Not reported
Date Stamp:	Not reported
Correspondence:	Not reported
Environmental Impact:	Not reported
FollowUp:	Not reported
GW Comments:	Not reported
Location Desc:	Not reported
NOV Comments:	Not reported
Release Desc:	Not reported
Running Comments:	#2 FUEL OIL, Commercial, tank pulled - 2K LUST FREE PRODUCT IN GRAVE
Work Performed:	Not reported

SPILLS:

Name:	Not reported
Address:	66 SCHOOL ST.
City,State,Zip:	EAST HARTFORD, CT
Year of Database:	1998
Case Number:	9804197
Who Took Spill:	933

BERNIE BODINE, ESTATE OF LAWRENCE PELITER (Continued) **S105440843**

Assigned To:	Emanuelson, Brian
Report Date:	07/01/1998
Report Time:	12:00:00 AM
Date Release:	07/01/1998
Release Time:	12:00:00 AM
Reported By:	david hahn
Phone:	860 2950031
Qty:	0.00 (Gallons)
Telephone:	860 2364501
Representing:	tanks alot
Facility Status:	Closed
Continuous Spill:	False
Release Substance:	#2 FUEL OIL
Emergency Measure:	tank pulled - 2K LUST FREE PRODUCT IN GRAVE
Discharger:	bernie bodine, estate of lawrence peliter
Waterbody Affected:	Not reported
Responsible Party:	true
Responsible Party Address:	Not reported
RP City,St,Zip:	CT
Terminated:	Not reported
Recovered Total:	0
Total Water:	0
Historic:	False
Waterbody:	Not reported
User Stamp:	Not reported
Stamp Time:	1998-07-09 08:08:30
SR Inspector:	Santacroce, Jim
AT Inspector:	Emanuelson, Brian
Corrective Action Taken:	Test Wells, and Removed Tank, and Soil Removed
Cause Info:	Inground Tank Failure
Media Info:	Ground Water
Release Type:	not specified
Incident Description:	Not reported
Cost Recovery Case?:	Not reported
DEMHS Region:	Not reported
Lat/Long:	Not reported
Company Name:	Not reported
Last Updated:	Not reported

Action:

Action:	Test Wells
Other Action:	Not reported
Action:	Removed Tank
Other Action:	Not reported
Action:	Soil Removed
Other Action:	Not reported

Agency:

Agency ID:	Local Fire Marshal
Other Agency:	Not reported
DEP Bureau:	Not reported
DEP Agency:	Not reported

Cause:

Cause ID:	Inground Tank Failure

BERNIE BODINE, ESTATE OF LAWRENCE PELITER (Continued) **S105440843**

Other Cause: Not reported

Media:
Media ID: Ground Water
Other Media: Not reported

Release Class:
Class ID: Commercial
Other Class: Not reported

CPCS:
Name: Bernie Bodine, Estate Of Lawrence Peliter
Address: 66 SCHOOL ST.
City,State,Zip: EAST HARTFORD, CT 06108
Site Type: Not reported
Lust Status code: 4
Lust Status: Lust Completed (DEP's significant hazard definition)
PTP Form: Not reported
Program: LUST
Comments: #2 Fuel Oil, Commercial, Tank Pulled - 2k Lust Free Product In Grave
Site Type Definition: Leaking Underground Storage Tanks Completed
Invesigation Start: Yes
Invesigation Start Date: Not reported
Remediation Start: Yes
Remediation Start Date: Not reported
Remediation Completed: Yes
ELUR: Not reported
Date Data Updated: 07/01/1998

---

43 **POLICE DEPARTMENT** **CT LUST** **S117397246**
WNW **497 TOLLAND STREET** **CT CPCS** **N/A**
1/4-1/2 **EAST HARTFORD, CT 06108**
0.257 mi.
1357 ft.

Relative:
Lower

Actual:
48 ft.

LUST:
Name: POLICE DEPARTMENT
Name 2: Not reported
Address: 497 TOLLAND STREET
Address 2: Not reported
City,State,Zip: EAST HARTFORD, CT 06108
LUST Case Id: 60747
Release Date: Not reported
Site Case ID: 0
Substance: Not reported
Release Source: Not reported
Release Cause: Not reported
Release Identified: Not reported
Case Number: Not reported
Release Quantity: Not reported
Facility City Number: 43

Detail As of 06/2020:
Name: POLICE DEPARTMENT

POLICE DEPARTMENT (Continued) **S117397246**

Name 2:	Not reported
Address:	497 TOLLAND STREET
City,State,Zip:	EAST HARTFORD, CT 06108
Address 2:	Not reported
LUST Id:	0
UST Facility Id:	5005
LUST Case Id:	60747
Lust Status:	Lust Completed
Processing Status:	Not reported
EPA Reportable:	False
Motor Fuel:	True
Diesel:	False
Gasoline:	True
Other:	False
Other Release:	Not reported
No Release:	False
Leak:	False
Tank:	True
Piping:	False
Overfill:	False
Removal:	True
Incident Date:	10/30/2013
Entry Date:	10/29/2014
Site Case Id:	0
UST Site Id:	0
Cost Recovery Spill Case #:	0
Old SITS Number:	0
Case Log Id:	0
Monthly Report Id:	0
UST Owner Id:	6972
LUST Owner Id:	Not reported
UST Event Id:	0
Contact Info:	Not reported
Contact EMail:	Not reported
Site Contact City,St,Zip:	MA 01104
2nd Contact:	Jay Soltis (GeoQuest, Inc.)
2nd Contact EMail:	Not reported
2nd Contact Address:	3 Barnard Lane
2nd Contact City,St,Zip:	11, CT 06002
2nd Contact Address 2:	P.O. Box 85
2nd Contact City 2:	Bloomfield
2nd Contact Phone Number:	8602431757
2nd Contact Fax Number:	8602439414
2nd Contact Type:	Vice President, Environmental Services
Facility City Num:	43
Site Contact:	Evergreen Construction Corporation
Site Contact Address:	39 Sullivan St.
Site Contact Add 2:	Not reported
Site Contact City 2:	Springfield
Site Contact Phone:	Not reported
Site Contact Fax:	Not reported
Site Contact Type:	Not reported
Department Contact 1:	Not reported
Department Contact 2:	Not reported
Referral Source:	Not reported
Offsite Source:	False
Date Referred:	Not reported

POLICE DEPARTMENT (Continued) **S117397246**

Emergency:	False
Private Heating Fuel:	False
Commercial Heating Fuel:	False
Commercial HF < 2100 Gal.:	False
Commercial HF > 2100 Gal.:	False
Commercial HF - Size Unk:	False
No LUST Site:	False
Cost Recvry Prgm Candidate:	False
OCSRD Complete:	False
Follow Up Flag:	False
Alternate Water Supply:	False
Relocation:	False
Responsible Party:	False
Responsible EMail:	mlosty@easthartfordct.gov
Resp Party Name:	Town of East Hartford
Resp Party Address:	740 Main Street
Resp Party City,St,Zip:	East Hartford, CT 061083140
Resp Party Town Number:	43
Resp Party Phone:	8602917379
Resp Party Fax:	8605089575
Resp Party Name 2:	Not reported
Resp Party Address 2:	Not reported
Resp Party Phone 2:	Not reported
Investigator Id:	0
Follow Update:	Not reported
Area Lextent:	Not reported
Annual Precipitation:	Not reported
Affected Population:	Not reported
Population Setting:	Not reported
Ground Water Direction:	Not reported
Ground Water Gradient:	Not reported
Hydro Basin:	Not reported
Drastic:	Not reported
Geo Setting:	Not reported
Ground Water Classification:	GB
Receptor:	Not reported
Ground Water Flow Direction:	Not reported
Ground Water Depth:	Not reported
Areas Of Concern:	Not reported
Free Product Inches:	0
Fund Date:	Not reported
Fund Planned:	No
Fund Obligated:	No
Fund Outlayed:	No
Fund Judgment:	No
Fund Recovered:	No
Cellar Borings:	False
Install Micro Wells:	False
Ground Water Sample:	True
Soil Sample:	True
Soil Gas:	False
Site Inspect:	False
Soil Excavate:	False
Geo Probe:	False
Survey:	False
Potable Well Sample:	False
Sample MWS:	False

POLICE DEPARTMENT (Continued) **S117397246**

Ground Water Gauging:	False
Soil Venting:	False
Active:	True
NOV Action:	None
NOV Issued:	Not reported
NOV Due:	Not reported
NOV Received:	Not reported
NOV Closed:	Not reported
NOV Disc Date:	Not reported
NOV Issued Date:	Not reported
NOV Compliance Sched:	Not reported
NOV Admin Order:	Not reported
NOV Referred To Ag:	Not reported
Stop All NOV Actions:	False
Release Invest Rpt:	False
DEP App Letter 1:	False
Correct Action Plan:	False
DEP App Letter 2:	False
Rem Sys Install:	False
Rem Sys Install Date:	Not reported
Closure Date:	Not reported
Rem Sys Monitoring Rpt:	False
Qrtly Gwater Mon Rpts:	False
Closure Req Rpt:	False
DEP Closure Letter:	False
Referred To:	Not reported
No Wells:	0
Lph Wells:	0
User Stamp:	ForrestA/forrestlaiuppaa
Date Stamp:	08/22/2018
Correspondence:	Not reported
Environmental Impact:	Not reported
FollowUp:	Not reported
GW Comments:	Not reported
Location Desc:	Not reported
NOV Comments:	Not reported
Release Desc:	Not reported
Running Comments:	UST Enforcement Files and FileNet
Work Performed:	Not reported

CPCS:

Name:	Police Department
Address:	497 TOLLAND STREET
City,State,Zip:	EAST HARTFORD, CT
Site Type:	Not reported
Lust Status code:	Not reported
Lust Status:	Not reported
PTP Form:	Not reported
Program:	LUST
Comments:	Not reported
Site Type Definition:	Not reported
Invesigation Start:	Yes
Invesigation Start Date:	Not reported
Remediation Start:	Yes
Remediation Start Date:	Not reported
Remediation Completed:	Yes

POLICE DEPARTMENT (Continued) **S117397246**

ELUR: Not reported
Date Data Updated: 10/30/2013

F44 **CRESTWOOD PRODUCTS (FORMER)** **CT PROPERTY** **S128727781**
North **672 TOLLAND STREET** **CT CPCS** **N/A**
1/4-1/2 **EAST HARTFORD, CT**
0.264 mi.
1396 ft. **Site 1 of 7 in cluster F**

Relative:
Higher

Actual:
76 ft.

CT Property:

Name:	CRESTWOOD PRODUCTS (FORMER)
Address:	672 TOLLAND STREET
City,state,zip:	EAST HARTFORD, CT
Seller Name:	TE Realty Enterprises, LLC
Buyer Name:	T & A Holdings, LLC
Certifying Party:	672 Tolland Street, LLC
Certifying Attention Person:	Johathan M. Keller
Title Of Certifying Person:	Manager
Certifying Person Address:	672 Tolland Street
Certifying Person City,St,Zip:	East Hartford, CT 06108
Property Transfer Forms:	Form III (DEP-PERD-PTP-203) when a discharge, spillage, uncontrolled loss, seepage or filtration of hazardous waste has occurred at the parcel that has not been fully remediated or the environmental conditions at the parcel are unknown. The person signing the Form III certification agrees to investigate and remediate the site in accordance with the remediation standards. The statute does not require completion of remediation before the parcel is transferred. Any person submitting a Form III shall simultaneously submit a completed Environmental Condition Assessment Form (ECAF)(DEP-PERD-PTP-200).
Date Recieved:	03/07/2016
Ackn Date:	04/20/2016
Determination Date:	04/20/2016
LEP Verified/DEP Approval Date:	2018-04-18 00:00:00
Rem Id:	12679
Remediation Location Id:	4641
Date Entered:	04/05/2016
Program:	Property Transfer Program
GAO Site:	False
Staff Full Name:	Robert Robinson
Super/Date:	04/20/2016
Stage Of Project:	Not reported
RP Level Of Activity:	Not reported
RP Needed Level Of Activity:	Not reported
Staff Level Of Activity:	Not reported
Staff Needed Level Of Activity:	Not reported
Public Intrest:	Not reported
PRP Cooperation:	Not reported
Enforcement Status:	Not reported
Level Of Complexity:	Not reported
Complex Eng Or Sci:	False
Complex Due To Public Involvement:	False
Politically Complex:	False
Complex Enforcement:	False
Coordination With Other Bureaus:	False
EPA Involvement:	False
Staff Prefrence:	Not reported
Readiness For Transfer:	Not reported

CRESTWOOD PRODUCTS (FORMER) (Continued) **S128727781**

Project Transfer Time:	Not reported
Transfer Comments:	Not reported
Staff As Of July 2000:	Not reported
Initial Staff:	Not reported
Type Of Transfer:	Real Estate
Salutation:	Mr. Keller
Relationship To Transfer:	indemnitor
Audit Date:	Not reported
Verif Type:	Not reported
Audit Outcome:	Not reported
GW:	GB
Basin:	Not reported
1st Payment:	3000
Pay Tag1:	1108
2nd Payment:	Not reported
Pay Tag2:	Not reported
RTN:	Not reported
Revised:	Not reported
ECAF Received:	Not reported
Old Determination Date:	Not reported
Redeterminationdate:	Not reported
Previous Determination:	Not reported
Monitoringoption:	Not reported
Postremedialmonitoring:	Not reported
Schedule Of I/R:	Not reported
Schedule Overdue:	Not reported
Aprvl Sched:	Not reported
Yr 1 Report:	Not reported
Yr 2 Report:	Not reported
Report Overdue:	Not reported
Ext Aprvl Sched:	Not reported
License #:	Not reported
Project Phase:	Not reported
PT Comments:	Ver1424 applies to 3/7/16
EPA Id Number:	Not reported
GW Class:	Not reported
SW Class:	Not reported
AO/C0:	Not reported
Water Lead(Y Or N):	Not reported
Priority:	Not reported
Project Status(A, I Or D):	Not reported
Last Updated:	Not reported
SR Comments:	Not reported
Priority Or Work-Load:	Not reported
Status:	Not reported
Notes:	Not reported
Special Project Name:	Not reported
Special Project Comments:	Not reported
DOT Project:	Not reported
Pt Counter:	0
Project Complete:	False
Project Inactive:	False
Int Deposit #:	Not reported
Deposit #:	Not reported
Spill Case #:	Not reported
Diversion Id:	0
Public Notice:	Not reported

CRESTWOOD PRODUCTS (FORMER) (Continued) **S128727781**

RAP Received:	Not reported
RAP Approved:	Not reported
Compliance Category:	Not reported
Delete Record:	False
ECAF Reviewed By:	MaryAnne Danyluk
Not Locatable:	False
Primary Address:	False
AKA Site Name:	False
Primary Site Name:	False
AKA Site Address:	False
Lead:	LEP

CPCS:

Name:	Crestwood Products (Former)
Address:	672 TOLLAND STREET
City,State,Zip:	EAST HARTFORD, CT
Site Type:	Not reported
Lust Status code:	Not reported
Lust Status:	Not reported
PTP Form:	Not reported
Program:	Property Transfer Program
Comments:	Not reported
Site Type Definition:	Not reported
Invesigation Start:	Not reported
Invesigation Start Date:	04/20/2016
Remediation Start:	Not reported
Remediation Start Date:	Not reported
Remediation Completed:	Yes
ELUR:	No
Date Data Updated:	Not reported

F45 **CRESTWOOD PRODUCTS** **CT PROPERTY** **S128727783**
North **672 TOLLAND STREET** **CT CPCS** **N/A**
1/4-1/2 **EAST HARTFORD, CT**
0.264 mi.
1396 ft. **Site 2 of 7 in cluster F**

Relative:
Higher

Actual:
76 ft.

CT Property:

Name:	CRESTWOOD PRODUCTS
Address:	672 TOLLAND STREET
City,state,zip:	EAST HARTFORD, CT
Seller Name:	672 Tolland Street, LLC
Buyer Name:	TE Realty Enterprises
Certifying Party:	672 Tolland Street, LLC
Certifying Attention Person:	Jonathan M. Keller
Title Of Certifying Person:	Manager
Certifying Person Address:	65 LaSalle Road, Suite 202
Certifying Person City,St,Zip:	West Hartford, CT 06107
Property Transfer Forms:	Form III (DEP-PERD-PTP-203) when a discharge, spillage, uncontrolled loss, seepage or filtration of hazardous waste has occurred at the parcel that has not been fully remediated or the environmental conditions at the parcel are unknown. The person signing the Form III certification agrees to investigate and remediate the site in accordance with the remediation standards. The statute does not require completion of remediation before the parcel is transferred. Any person submitting a Form III shall simultaneously submit a completed Environmental Condition Assessment Form

CRESTWOOD PRODUCTS (Continued) **S128727783**

	(ECAF)(DEP-PERD-PTP-200).
Date Recieved:	05/25/2012
Ackn Date:	07/19/2012
Determination Date:	07/19/2012
LEP Verified/DEP Approval Date:	Not reported
Rem Id:	11056
Remediation Location Id:	4641
Date Entered:	06/06/2012
Program:	Property Transfer Program
GAO Site:	False
Staff Full Name:	Robert Robinson
Super/Date:	07/19/2012
Stage Of Project:	Not reported
RP Level Of Activity:	Not reported
RP Needed Level Of Activity:	Not reported
Staff Level Of Activity:	Not reported
Staff Needed Level Of Activity:	Not reported
Public Intrest:	Not reported
PRP Cooperation:	Not reported
Enforcement Status:	Not reported
Level Of Complexity:	Not reported
Complex Eng Or Sci:	False
Complex Due To Public Involvement:	False
Politically Complex:	False
Complex Enforcement:	False
Coordination With Other Bureaus:	False
EPA Involvement:	False
Staff Prefrence:	Not reported
Readiness For Transfer:	Not reported
Project Transfer Time:	Not reported
Transfer Comments:	Not reported
Staff As Of July 2000:	Not reported
Initial Staff:	Not reported
Type Of Transfer:	Real Estate
Salutation:	Mr. Keller
Relationship To Transfer:	transferor
Audit Date:	Not reported
Verif Type:	Not reported
Audit Outcome:	Not reported
GW:	GB
Basin:	Not reported
1st Payment:	3000
Pay Tag1:	2081
2nd Payment:	Not reported
Pay Tag2:	Not reported
RTN:	Not reported
Revised:	Not reported
ECAF Received:	Not reported
Old Determination Date:	Not reported
Redeterminationdate:	Not reported
Previous Determination:	Not reported
Monitoringoption:	Not reported
Postremedialmonitoring:	Not reported
Schedule Of I/R:	Not reported
Schedule Overdue:	Not reported
Aprvl Sched:	Not reported
Yr 1 Report:	Not reported

CRESTWOOD PRODUCTS (Continued) **S128727783**

Yr 2 Report:	Not reported
Report Overdue:	Not reported
Ext Aprvl Sched:	Not reported
License #:	Not reported
Project Phase:	Not reported
PT Comments:	Not reported
EPA Id Number:	Not reported
GW Class:	Not reported
SW Class:	Not reported
AO/C0:	Not reported
Water Lead(Y Or N):	Not reported
Priority:	Not reported
Project Status(A, I Or D):	Not reported
Last Updated:	Not reported
SR Comments:	Not reported
Priority Or Work-Load:	Not reported
Status:	Not reported
Notes:	Not reported
Special Project Name:	Not reported
Special Project Comments:	Not reported
DOT Project:	Not reported
Pt Counter:	0
Project Complete:	False
Project Inactive:	False
Int Deposit #:	Not reported
Deposit #:	Not reported
Spill Case #:	Not reported
Diversion Id:	0
Public Notice:	Not reported
RAP Received:	Not reported
RAP Approved:	Not reported
Compliance Category:	Not reported
Delete Record:	False
ECAF Reviewed By:	Michelle Bedson
Not Locatable:	False
Primary Address:	False
AKA Site Name:	False
Primary Site Name:	False
AKA Site Address:	False
Lead:	LEP

CPCS:

Name:	Crestwood Products
Address:	672 TOLLAND STREET
City,State,Zip:	EAST HARTFORD, CT
Site Type:	Not reported
Lust Status code:	Not reported
Lust Status:	Not reported
PTP Form:	Not reported
Program:	Property Transfer Program
Comments:	Not reported
Site Type Definition:	Not reported
Invesigation Start:	Not reported
Invesigation Start Date:	07/19/2012
Remediation Start:	Not reported
Remediation Start Date:	Not reported
Remediation Completed:	Yes

CRESTWOOD PRODUCTS (Continued) **S128727783**

ELUR: No
Date Data Updated: Not reported

F46 **NEWMAN CHRYSLER JEEP (COLLISION CTR)** **CT PROPERTY** **S109721742**
North **630 TOLLAND STREET** **CT CPCS** **N/A**
1/4-1/2 **EAST HARTFORD, CT**
0.267 mi.
1409 ft. **Site 3 of 7 in cluster F**

Relative:
Lower

Actual:
72 ft.

CT Property:

Name:	NEWMAN CHRYSLER JEEP (COLLISION CTR)
Address:	630 TOLLAND STREET
City,state,zip:	EAST HARTFORD, CT
Seller Name:	Shareholders, Janice Rosenthal, etal
Buyer Name:	Gengras Motor Cars Inc.
Certifying Party:	Newman Holdings I LLC
Certifying Attention Person:	William H. Newman
Title Of Certifying Person:	Manager
Certifying Person Address:	c/o William H. Newman, 57 Pheasant Chase
Certifying Person City,St,Zip:	West Hartford, CT 06117
Property Transfer Forms:	Form III (DEP-PERD-PTP-203) when a discharge, spillage, uncontrolled loss, seepage or filtration of hazardous waste has occurred at the parcel that has not been fully remediated or the environmental conditions at the parcel are unknown. The person signing the Form III certification agrees to investigate and remediate the site in accordance with the remediation standards. The statute does not require completion of remediation before the parcel is transferred. Any person submitting a Form III shall simultaneously submit a completed Environmental Condition Assessment Form (ECAF)(DEP-PERD-PTP-200).
Date Recieved:	10/27/2009
Ackn Date:	01/28/2010
Determination Date:	Not reported
LEP Verified/DEP Approval Date:	Not reported
Rem Id:	9577
Remediation Location Id:	8423
Date Entered:	10/27/2009
Program:	Property Transfer Program
GAO Site:	False
Staff Full Name:	Rob Robinson
Super/Date:	01/28/2010
Stage Of Project:	Not reported
RP Level Of Activity:	Not reported
RP Needed Level Of Activity:	Not reported
Staff Level Of Activity:	Not reported
Staff Needed Level Of Activity:	Not reported
Public Intrest:	Not reported
PRP Cooperation:	Not reported
Enforcement Status:	Not reported
Level Of Complexity:	Not reported
Complex Eng Or Sci:	False
Complex Due To Public Involvement:	False
Politically Complex:	False
Complex Enforcement:	False
Coordination With Other Bureaus:	False
EPA Involvement:	False
Staff Prefrence:	Not reported
Readiness For Transfer:	Not reported

NEWMAN CHRYSLER JEEP (COLLISION CTR) (Continued) **S109721742**

Project Transfer Time:	Not reported
Transfer Comments:	Not reported
Staff As Of July 2000:	Not reported
Initial Staff:	Not reported
Type Of Transfer:	Business
Salutation:	Mr. Newman
Relationship To Transfer:	parcel owner
Audit Date:	Not reported
Verif Type:	Not reported
Audit Outcome:	Not reported
GW:	GB
Basin:	Not reported
1st Payment:	3000
Pay Tag1:	3138468
2nd Payment:	Not reported
Pay Tag2:	Not reported
RTN:	Not reported
Revised:	Not reported
ECAF Received:	Not reported
Old Determination Date:	Not reported
Redeterminationdate:	Not reported
Previous Determination:	Not reported
Monitoringoption:	Not reported
Postremedialmonitoring:	Not reported
Schedule Of I/R:	Not reported
Schedule Overdue:	Not reported
Aprvl Sched:	Not reported
Yr 1 Report:	Not reported
Yr 2 Report:	Not reported
Report Overdue:	Not reported
Ext Aprvl Sched:	Not reported
License #:	Not reported
Project Phase:	Not reported
PT Comments:	Not reported
EPA Id Number:	Not reported
GW Class:	Not reported
SW Class:	Not reported
AO/C0:	Not reported
Water Lead(Y Or N):	Not reported
Priority:	Not reported
Project Status(A, I Or D):	Not reported
Last Updated:	Not reported
SR Comments:	Not reported
Priority Or Work-Load:	Not reported
Status:	Not reported
Notes:	Not reported
Special Project Name:	Not reported
Special Project Comments:	Not reported
DOT Project:	Not reported
Pt Counter:	0
Project Complete:	False
Project Inactive:	False
Int Deposit #:	Not reported
Deposit #:	Not reported
Spill Case #:	Not reported
Diversion Id:	0
Public Notice:	Not reported

NEWMAN CHRYSLER JEEP (COLLISION CTR) (Continued) **S109721742**

RAP Received:	Not reported
RAP Approved:	Not reported
Compliance Category:	Not reported
Delete Record:	False
ECAF Reviewed By:	Not reported
Not Locatable:	False
Primary Address:	True
AKA Site Name:	False
Primary Site Name:	True
AKA Site Address:	False
Lead:	LEP
Name:	NEWMAN CHRYSLER JEEP (COLLISION CTR)
Address:	630 TOLLAND STREET
City,state,zip:	EAST HARTFORD, CT
Seller Name:	The Shareholders listed on Attachment 1
Buyer Name:	Gengras Motor Cars Inc.
Certifying Party:	Newman Holdings I LLC
Certifying Attention Person:	William H. Newman
Title Of Certifying Person:	Manager
Certifying Person Address:	c/o William H. Newman, 57 Pheasant Chase
Certifying Person City,St,Zip:	West Hartford, CT 06117
Property Transfer Forms:	Form III (DEP-PERD-PTP-203) when a discharge, spillage, uncontrolled loss, seepage or filtration of hazardous waste has occurred at the parcel that has not been fully remediated or the environmental conditions at the parcel are unknown. The person signing the Form III certification agrees to investigate and remediate the site in accordance with the remediation standards. The statute does not require completion of remediation before the parcel is transferred. Any person submitting a Form III shall simultaneously submit a completed Environmental Condition Assessment Form (ECAF)(DEP-PERD-PTP-200).
Date Recieved:	10/27/2009
Ackn Date:	01/28/2010
Determination Date:	Not reported
LEP Verified/DEP Approval Date:	Not reported
Rem Id:	9578
Remediation Location Id:	8423
Date Entered:	10/27/2009
Program:	Property Transfer Program
GAO Site:	False
Staff Full Name:	Rob Robinson
Super/Date:	01/28/2010
Stage Of Project:	Not reported
RP Level Of Activity:	Not reported
RP Needed Level Of Activity:	Not reported
Staff Level Of Activity:	Not reported
Staff Needed Level Of Activity:	Not reported
Public Intrest:	Not reported
PRP Cooperation:	Not reported
Enforcement Status:	Not reported
Level Of Complexity:	Not reported
Complex Eng Or Sci:	False
Complex Due To Public Involvement:	False
Politically Complex:	False
Complex Enforcement:	False
Coordination With Other Bureaus:	False

NEWMAN CHRYSLER JEEP (COLLISION CTR) (Continued) **S109721742**

EPA Involvement:	False
Staff Prefrence:	Not reported
Readiness For Transfer:	Not reported
Project Transfer Time:	Not reported
Transfer Comments:	Not reported
Staff As Of July 2000:	Not reported
Initial Staff:	Not reported
Type Of Transfer:	Business
Salutation:	Mr. Newman
Relationship To Transfer:	parcel owner
Audit Date:	Not reported
Verif Type:	Not reported
Audit Outcome:	Not reported
GW:	GB
Basin:	Not reported
1st Payment:	3000
Pay Tag1:	3138466
2nd Payment:	Not reported
Pay Tag2:	Not reported
RTN:	Not reported
Revised:	Not reported
ECAF Received:	Not reported
Old Determination Date:	Not reported
Redeterminationdate:	Not reported
Previous Determination:	Not reported
Monitoringoption:	Not reported
Postremedialmonitoring:	Not reported
Schedule Of I/R:	Not reported
Schedule Overdue:	Not reported
Aprvl Sched:	Not reported
Yr 1 Report:	Not reported
Yr 2 Report:	Not reported
Report Overdue:	Not reported
Ext Aprvl Sched:	Not reported
License #:	Not reported
Project Phase:	Not reported
PT Comments:	Not reported
EPA Id Number:	Not reported
GW Class:	Not reported
SW Class:	Not reported
AO/C0:	Not reported
Water Lead(Y Or N):	Not reported
Priority:	Not reported
Project Status(A, I Or D):	Not reported
Last Updated:	Not reported
SR Comments:	Not reported
Priority Or Work-Load:	Not reported
Status:	Not reported
Notes:	Not reported
Special Project Name:	Not reported
Special Project Comments:	Not reported
DOT Project:	Not reported
Pt Counter:	0
Project Complete:	False
Project Inactive:	False
Int Deposit #:	Not reported
Deposit #:	Not reported

NEWMAN CHRYSLER JEEP (COLLISION CTR) (Continued) **S109721742**

Spill Case #:	Not reported
Diversion Id:	0
Public Notice:	Not reported
RAP Received:	Not reported
RAP Approved:	Not reported
Compliance Category:	Not reported
Delete Record:	False
ECAF Reviewed By:	Not reported
Not Locatable:	False
Primary Address:	False
AKA Site Name:	False
Primary Site Name:	False
AKA Site Address:	False
Lead:	LEP
Name:	NEWMAN CHRYSLER JEEP (COLLISION CTR)
Address:	630 TOLLAND STREET
City,state,zip:	EAST HARTFORD, CT
Seller Name:	The Owners listed on Attachment 1
Buyer Name:	Gengras Realty LLC
Certifying Party:	Newman Holdings I LLC
Certifying Attention Person:	William H. Newman
Title Of Certifying Person:	Manager
Certifying Person Address:	c/o William H. Newman, 57 Pheasant Chase
Certifying Person City,St,Zip:	West Hartford, CT 06117
Property Transfer Forms:	Form III (DEP-PERD-PTP-203) when a discharge, spillage, uncontrolled loss, seepage or filtration of hazardous waste has occurred at the parcel that has not been fully remediated or the environmental conditions at the parcel are unknown. The person signing the Form III certification agrees to investigate and remediate the site in accordance with the remediation standards. The statute does not require completion of remediation before the parcel is transferred. Any person submitting a Form III shall simultaneously submit a completed Environmental Condition Assessment Form (ECAF)(DEP-PERD-PTP-200).
Date Recieved:	10/27/2009
Ackn Date:	01/28/2010
Determination Date:	01/28/2010
LEP Verified/DEP Approval Date:	2009-08-12 00:00:00
Rem Id:	9579
Remediation Location Id:	8423
Date Entered:	10/27/2009
Program:	Property Transfer Program
GAO Site:	False
Staff Full Name:	Rob Robinson
Super/Date:	01/28/2010
Stage Of Project:	Not reported
RP Level Of Activity:	Not reported
RP Needed Level Of Activity:	Not reported
Staff Level Of Activity:	Not reported
Staff Needed Level Of Activity:	Not reported
Public Intrest:	Not reported
PRP Cooperation:	Not reported
Enforcement Status:	Not reported
Level Of Complexity:	Not reported
Complex Eng Or Sci:	False
Complex Due To Public Involvement:	False

NEWMAN CHRYSLER JEEP (COLLISION CTR) (Continued) **S109721742**

Politically Complex:	False
Complex Enforcement:	False
Coordination With Other Bureaus:	False
EPA Involvement:	False
Staff Prefrence:	Not reported
Readiness For Transfer:	Not reported
Project Transfer Time:	Not reported
Transfer Comments:	Not reported
Staff As Of July 2000:	Not reported
Initial Staff:	Not reported
Type Of Transfer:	Business
Salutation:	Mr. Newman
Relationship To Transfer:	parcel owner
Audit Date:	Not reported
Verif Type:	F
Audit Outcome:	accepted
GW:	GB
Basin:	Not reported
1st Payment:	3000
Pay Tag1:	3138467
2nd Payment:	Not reported
Pay Tag2:	Not reported
RTN:	Not reported
Revised:	Not reported
ECAF Received:	Not reported
Old Determination Date:	Not reported
Redeterminationdate:	Not reported
Previous Determination:	Not reported
Monitoringoption:	Not reported
Postremedialmonitoring:	Not reported
Schedule Of I/R:	Not reported
Schedule Overdue:	Not reported
Aprvl Sched:	Not reported
Yr 1 Report:	Not reported
Yr 2 Report:	Not reported
Report Overdue:	Not reported
Ext Aprvl Sched:	Not reported
License #:	140
Project Phase:	Not reported
PT Comments:	Property Verif also covers Rem9577 and 9578
EPA Id Number:	Not reported
GW Class:	Not reported
SW Class:	Not reported
AO/C0:	Not reported
Water Lead(Y Or N):	Not reported
Priority:	Not reported
Project Status(A, I Or D):	Not reported
Last Updated:	Not reported
SR Comments:	Not reported
Priority Or Work-Load:	Not reported
Status:	Not reported
Notes:	Not reported
Special Project Name:	Not reported
Special Project Comments:	Not reported
DOT Project:	Not reported
Pt Counter:	0
Project Complete:	False

NEWMAN CHRYSLER JEEP (COLLISION CTR) (Continued) **S109721742**

Project Inactive:	False
Int Deposit #:	Not reported
Deposit #:	Not reported
Spill Case #:	Not reported
Diversion Id:	0
Public Notice:	Not reported
RAP Received:	Not reported
RAP Approved:	Not reported
Compliance Category:	Not reported
Delete Record:	False
ECAF Reviewed By:	Not reported
Not Locatable:	False
Primary Address:	False
AKA Site Name:	False
Primary Site Name:	False
AKA Site Address:	False
Lead:	LEP

CPCS:

Name:	Newman Chrysler Jeep (Collision Ctr)
Address:	630 TOLLAND STREET
City,State,Zip:	EAST HARTFORD, CT
Site Type:	Not reported
Lust Status code:	Not reported
Lust Status:	Not reported
PTP Form:	Not reported
Program:	Property Transfer Program
Comments:	Not reported
Site Type Definition:	Not reported
Invesigation Start:	Not reported
Invesigation Start Date:	01/28/2010
Remediation Start:	Not reported
Remediation Start Date:	Not reported
Remediation Completed:	Yes
ELUR:	No
Date Data Updated:	Not reported

Name:	Newman Chrysler Jeep (Collision Ctr)
Address:	630 TOLLAND STREET
City,State,Zip:	EAST HARTFORD, CT
Site Type:	Not reported
Lust Status code:	Not reported
Lust Status:	Not reported
PTP Form:	Not reported
Program:	Property Transfer Program
Comments:	Not reported
Site Type Definition:	Not reported
Invesigation Start:	Not reported
Invesigation Start Date:	01/28/2010
Remediation Start:	Not reported
Remediation Start Date:	Not reported
Remediation Completed:	Yes
ELUR:	No
Date Data Updated:	Not reported

Name:	Newman Chrysler Jeep (Collision Ctr)
Address:	630 TOLLAND STREET

NEWMAN CHRYSLER JEEP (COLLISION CTR) (Continued) **S109721742**

City,State,Zip:	EAST HARTFORD, CT
Site Type:	Not reported
Lust Status code:	Not reported
Lust Status:	Not reported
PTP Form:	Not reported
Program:	Property Transfer Program
Comments:	Not reported
Site Type Definition:	Not reported
Invesigation Start:	Not reported
Invesigation Start Date:	01/28/2010
Remediation Start:	Not reported
Remediation Start Date:	Not reported
Remediation Completed:	Yes
ELUR:	No
Date Data Updated:	Not reported

F47 **GENGRAS COLLISION CENTER** **CT CPCS** **S128657901**
North **630 TOLLAND ST** **N/A**
1/4-1/2 **EAST HARTFORD, CT**
0.267 mi.
1409 ft. **Site 4 of 7 in cluster F**

Relative: **Lower**
Actual: **72 ft.**

CPCS:

Name:	Gengras Collision Center
Address:	630 TOLLAND ST
City,State,Zip:	EAST HARTFORD, CT
Site Type:	Not reported
Lust Status code:	Not reported
Lust Status:	Not reported
PTP Form:	Not reported
Program:	Property Transfer Program
Comments:	Not reported
Site Type Definition:	Not reported
Invesigation Start:	Not reported
Invesigation Start Date:	02/06/2024
Remediation Start:	Not reported
Remediation Start Date:	Not reported
Remediation Completed:	No
ELUR:	No
Date Data Updated:	Not reported

F48 **CRESTWOOD PRODUCTS** **CT SDADB** **S104942779**
North **654 & 672 TOLLDAND STREET** **N/A**
1/4-1/2 **EAST HARTFORD, CT**
0.295 mi.
1555 ft. **Site 5 of 7 in cluster F**

Relative: **Lower**
Actual: **68 ft.**

Site Discovery and Assessment:

Facility ID:	5562
Rem Master ID:	4915
PTP Id:	0
WPC Number:	Not reported
Postal District:	Not reported
Latitude:	0
Longitude:	0
Lat/Long Determined By:	Not reported

CRESTWOOD PRODUCTS (Continued) **S104942779**

Ground Water Quality Classification:	GB
Surface Water Quality Classification:	Not reported
Waste Type:	CHLR VOC, PCB
Disposal:	SPILL/DUMP
Sample Data Available:	False
Updated By:	BEDSON, M.
Update Program:	Not reported
Updated:	3/7/2001
Date Created:	Not reported
Duplicate:	False

SDA Federal:

EPA CERCLIS Id:	Not reported
Number EPA RCRIS Id:	Not reported
Site on EPA's CERCLIS:	False
Site Archived from CERCLIS:	False
Archive Date:	Not reported
EPA's Removal at Site:	False
Deferred to another EPA Program:	False
EPA Env Priority Initiative Site:	False
Federal Facility:	False
Site on EPA's National Priority List:	False
Part of an NPL site:	False
RCRA Generator Status:	1970 to 1989 SQG
RCRA Permit Status:	Not reported

SDA Referral:

Referral Id:	Not reported
Source of referral:	Not reported
Date Received:	Not reported
Staff Assigned:	Not reported
Remediation Program:	Not reported
Date dt_assigned:	Not reported
Remediation Complete Approved DEP/Verified by LEP:	Not reported
Outcome:	Not reported

SDA Remedial:

Remedial Id:	Not reported
PTP Id:	Not reported
Remediation Program:	Not reported
Remediation Program Entered:	Not reported
Staff Assigned:	Not reported
Remediation Program:	Not reported
Date dt_assign:	Not reported
Project Phase:	Not reported
Order issued:	Not reported
Order Number:	Not reported
Date order issued:	Not reported
Remedial Investigation Start:	Not reported
Remedial Investigation Completed:	Not reported
Remedial Design Start:	Not reported
Remedial Design complet:	Not reported
Remedial Action Start:	Not reported
Remedial Action Completed:	Not reported
Date Oper/ maintenance Started:	Not reported
GW monitoring:	Not reported
Remediation complete Approved DEP/Verified by LEP:	Not reported

SDA Orders:

CRESTWOOD PRODUCTS (Continued) **S104942779**

Order Id:	Not reported
Order Number:	Not reported
Date order issued:	Not reported
Staff Assigned:	Not reported
Type of Order:	Not reported
Order Respondent:	Not reported
Admin Appeal Date:	Not reported
Date of Admin Appeal Ruling:	Not reported
Date of Admin Appeal Ruling:	Not reported
Date of Final Order:	Not reported
Date of Court Appeal:	Not reported
Date of Court Ruling:	Not reported
Date of Court Ruling:	Not reported
Date Order Modified:	Not reported
Date Referred to AG:	Not reported
Judgement:	Not reported
Date of AGR judgement:	Not reported
Penalty assessed:	Not reported
Order Complete:	Not reported
In compliance:	Not reported
Comments:	Not reported

SDADB:

SDA Waste:

Waste Id:	5
Waste Type:	CHLR VOC
Description:	Chlorinated Volatile Organic Compounds

F49 **CRESTWOOD PRODUCTS** **CT PROPERTY S128727782**
North **654 TOLLAND STREET** **CT CPCS N/A**
1/4-1/2 **EAST HARTFORD, CT**
0.295 mi.
1555 ft. **Site 6 of 7 in cluster F**

Relative: **Lower**
Actual: **68 ft.**

CT Property:

Name:	CRESTWOOD PRODUCTS
Address:	654 TOLLAND STREET
City,state,zip:	EAST HARTFORD, CT
Seller Name:	672 Tolland St. LLC c/o Freemont Mgt LLC
Buyer Name:	Gator Realty, LLC
Certifying Party:	672 Tolland Street, LLC
Certifying Attention Person:	Jonathan M. Keller
Title Of Certifying Person:	Manager
Certifying Person Address:	c/o Freemont Grp LLC, 65 LaSalle Rd, Suite 202
Certifying Person City,St,Zip:	West Hartford, CT 06107
Property Transfer Forms:	Form III (DEP-PERD-PTP-203) when a discharge, spillage, uncontrolled loss, seepage or filtration of hazardous waste has occurred at the parcel that has not been fully remediated or the environmental conditions at the parcel are unknown. The person signing the Form III certification agrees to investigate and remediate the site in accordance with the remediation standards. The statute does not require completion of remediation before the parcel is transferred. Any person submitting a Form III shall simultaneously submit a completed Environmental Condition Assessment Form (ECAF)(DEP-PERD-PTP-200).
Date Recieved:	02/05/2008
Ackn Date:	04/07/2008

CRESTWOOD PRODUCTS (Continued) **S128727782**

Determination Date:	04/07/2008
LEP Verified/DEP Approval Date:	Not reported
Rem Id:	8861
Remediation Location Id:	4641
Date Entered:	Not reported
Program:	Property Transfer Program
GAO Site:	False
Staff Full Name:	Michelle Bedson
Super/Date:	04/09/2008
Stage Of Project:	Not reported
RP Level Of Activity:	Not reported
RP Needed Level Of Activity:	Not reported
Staff Level Of Activity:	Not reported
Staff Needed Level Of Activity:	Not reported
Public Intrest:	Not reported
PRP Cooperation:	Not reported
Enforcement Status:	Not reported
Level Of Complexity:	Not reported
Complex Eng Or Sci:	False
Complex Due To Public Involvement:	False
Politically Complex:	False
Complex Enforcement:	False
Coordination With Other Bureaus:	False
EPA Involvement:	False
Staff Prefrence:	Not reported
Readiness For Transfer:	Not reported
Project Transfer Time:	Not reported
Transfer Comments:	Not reported
Staff As Of July 2000:	Not reported
Initial Staff:	Not reported
Type Of Transfer:	Real Estate
Salutation:	Mr. Keller
Relationship To Transfer:	transferor
Audit Date:	Not reported
Verif Type:	Not reported
Audit Outcome:	Not reported
GW:	GB
Basin:	Not reported
1st Payment:	3000
Pay Tag1:	5649629
2nd Payment:	Not reported
Pay Tag2:	Not reported
RTN:	Not reported
Revised:	Not reported
ECAF Received:	Not reported
Old Determination Date:	Not reported
Redeterminationdate:	Not reported
Previous Determination:	Not reported
Monitoringoption:	Not reported
Postremedialmonitoring:	Not reported
Schedule Of I/R:	Not reported
Schedule Overdue:	Not reported
Aprvl Sched:	Not reported
Yr 1 Report:	Not reported
Yr 2 Report:	Not reported
Report Overdue:	Not reported
Ext Aprvl Sched:	Not reported

CRESTWOOD PRODUCTS (Continued) **S128727782**

License #:	Not reported
Project Phase:	Not reported
PT Comments:	Not reported
EPA Id Number:	Not reported
GW Class:	Not reported
SW Class:	Not reported
AO/C0:	Not reported
Water Lead(Y Or N):	Not reported
Priority:	Not reported
Project Status(A, I Or D):	Not reported
Last Updated:	Not reported
SR Comments:	Not reported
Priority Or Work-Load:	Not reported
Status:	Not reported
Notes:	Not reported
Special Project Name:	Not reported
Special Project Comments:	Not reported
DOT Project:	Not reported
Pt Counter:	0
Project Complete:	False
Project Inactive:	False
Int Deposit #:	08-3203
Deposit #:	Not reported
Spill Case #:	Not reported
Diversion Id:	0
Public Notice:	Not reported
RAP Received:	Not reported
RAP Approved:	Not reported
Compliance Category:	Not reported
Delete Record:	False
ECAF Reviewed By:	Michelle Bedson
Not Locatable:	False
Primary Address:	False
AKA Site Name:	False
Primary Site Name:	False
AKA Site Address:	True
Lead:	LEP
Name:	CRESTWOOD PRODUCTS
Address:	654 TOLLAND STREET
City,state,zip:	EAST HARTFORD, CT
Seller Name:	Gator Realty, LLC
Buyer Name:	Rooke Realty, LLC
Certifying Party:	Gator Realty, LLC
Certifying Attention Person:	Matthew J. Egan
Title Of Certifying Person:	Authorized Member
Certifying Person Address:	140 Progress Drive
Certifying Person City,St,Zip:	Manchester, CT 06042
Property Transfer Forms:	Form III (DEP-PERD-PTP-203) when a discharge, spillage, uncontrolled loss, seepage or filtration of hazardous waste has occurred at the parcel that has not been fully remediated or the environmental conditions at the parcel are unknown. The person signing the Form III certification agrees to investigate and remediate the site in accordance with the remediation standards. The statute does not require completion of remediation before the parcel is transferred. Any person submitting a Form III shall simultaneously submit a completed Environmental Condition Assessment Form

CRESTWOOD PRODUCTS (Continued) **S128727782**

	(ECAF)(DEP-PERD-PTP-200).
Date Recieved:	05/03/2018
Ackn Date:	06/01/2018
Determination Date:	06/01/2018
LEP Verified/DEP Approval Date:	Not reported
Rem Id:	13727
Remediation Location Id:	4641
Date Entered:	05/09/2018
Program:	Property Transfer Program
GAO Site:	False
Staff Full Name:	Robert Robinson
Super/Date:	06/04/2018
Stage Of Project:	Not reported
RP Level Of Activity:	Not reported
RP Needed Level Of Activity:	Not reported
Staff Level Of Activity:	Not reported
Staff Needed Level Of Activity:	Not reported
Public Intrest:	Not reported
PRP Cooperation:	Not reported
Enforcement Status:	Not reported
Level Of Complexity:	Not reported
Complex Eng Or Sci:	False
Complex Due To Public Involvement:	False
Politically Complex:	False
Complex Enforcement:	False
Coordination With Other Bureaus:	False
EPA Involvement:	False
Staff Prefrence:	Not reported
Readiness For Transfer:	Not reported
Project Transfer Time:	Not reported
Transfer Comments:	Not reported
Staff As Of July 2000:	Not reported
Initial Staff:	Not reported
Type Of Transfer:	Real Estate
Salutation:	Mr. Egan
Relationship To Transfer:	transferor
Audit Date:	Not reported
Verif Type:	Not reported
Audit Outcome:	Not reported
GW:	GB
Basin:	Not reported
1st Payment:	3000
Pay Tag1:	349180
2nd Payment:	Not reported
Pay Tag2:	Not reported
RTN:	Not reported
Revised:	Not reported
ECAF Received:	Not reported
Old Determination Date:	Not reported
Redeterminationdate:	Not reported
Previous Determination:	Not reported
Monitoringoption:	Not reported
Postremedialmonitoring:	Not reported
Schedule Of I/R:	Not reported
Schedule Overdue:	Not reported
Aprvl Sched:	Not reported
Yr 1 Report:	Not reported

CRESTWOOD PRODUCTS (Continued) **S128727782**

Yr 2 Report:	Not reported
Report Overdue:	Not reported
Ext Aprvl Sched:	Not reported
License #:	Not reported
Project Phase:	Not reported
PT Comments:	Not reported
EPA Id Number:	Not reported
GW Class:	Not reported
SW Class:	Not reported
AO/C0:	Not reported
Water Lead(Y Or N):	Not reported
Priority:	Not reported
Project Status(A, I Or D):	Not reported
Last Updated:	Not reported
SR Comments:	Not reported
Priority Or Work-Load:	Not reported
Status:	Not reported
Notes:	Not reported
Special Project Name:	Not reported
Special Project Comments:	Not reported
DOT Project:	Not reported
Pt Counter:	0
Project Complete:	False
Project Inactive:	False
Int Deposit #:	Not reported
Deposit #:	Not reported
Spill Case #:	Not reported
Diversion Id:	0
Public Notice:	Not reported
RAP Received:	Not reported
RAP Approved:	Not reported
Compliance Category:	Not reported
Delete Record:	False
ECAF Reviewed By:	Not reported
Not Locatable:	False
Primary Address:	False
AKA Site Name:	False
Primary Site Name:	False
AKA Site Address:	False
Lead:	LEP

CPCS:

Name:	Crestwood Products
Address:	654 TOLLAND STREET
City,State,Zip:	EAST HARTFORD, CT
Site Type:	Not reported
Lust Status code:	Not reported
Lust Status:	Not reported
PTP Form:	Not reported
Program:	Property Transfer Program
Comments:	Not reported
Site Type Definition:	Not reported
Invesigation Start:	Not reported
Invesigation Start Date:	04/07/2008
Remediation Start:	Not reported
Remediation Start Date:	Not reported
Remediation Completed:	Yes

CRESTWOOD PRODUCTS (Continued) **S128727782**

ELUR:	No
Date Data Updated:	Not reported
Name:	Crestwood Products
Address:	654 TOLLAND STREET
City,State,Zip:	EAST HARTFORD, CT
Site Type:	Not reported
Lust Status code:	Not reported
Lust Status:	Not reported
PTP Form:	Not reported
Program:	Property Transfer Program
Comments:	Not reported
Site Type Definition:	Not reported
Invesigation Start:	Not reported
Invesigation Start Date:	06/01/2018
Remediation Start:	Not reported
Remediation Start Date:	Not reported
Remediation Completed:	No
ELUR:	No
Date Data Updated:	Not reported

F50 **CRESTWOOD PRODUCTS (FORMER)** **CT PROPERTY** **S128727780**
North **654 & 672 TOLLAND STREET** **CT CPCS** **N/A**
1/4-1/2 **EAST HARTFORD, CT**
0.295 mi.
1555 ft. **Site 7 of 7 in cluster F**

Relative: **Lower**

Actual: **68 ft.**

CT Property:

Name:	CRESTWOOD PRODUCTS (FORMER)
Address:	654 & 672 TOLLAND STREET
City,state,zip:	EAST HARTFORD, CT
Seller Name:	Tolland Enterprises
Buyer Name:	654 Tolland Stree, LLC
Certifying Party:	654 Tolland Street, LLC
Certifying Attention Person:	Jonathan M. Keller
Title Of Certifying Person:	Member
Certifying Person Address:	c/o 654 Tolland St,llc,CityPlace,185 Asylum St
Certifying Person City,St,Zip:	Hartford, CT 06103
Property Transfer Forms:	Form III (DEP-PERD-PTP-203) when a discharge, spillage, uncontrolled loss, seepage or filtration of hazardous waste has occurred at the parcel that has not been fully remediated or the environmental conditions at the parcel are unknown. The person signing the Form III certification agrees to investigate and remediate the site in accordance with the remediation standards. The statute does not require completion of remediation before the parcel is transferred. Any person submitting a Form III shall simultaneously submit a completed Environmental Condition Assessment Form (ECAF)(DEP-PERD-PTP-200).
Date Recieved:	11/06/2000
Ackn Date:	11/17/2000
Determination Date:	02/21/2001
LEP Verified/DEP Approval Date:	Not reported
Rem Id:	1096
Remediation Location Id:	4641
Date Entered:	Not reported
Program:	Property Transfer Program
GAO Site:	False
Staff Full Name:	Michelle Bedson

CRESTWOOD PRODUCTS (FORMER) (Continued) **S128727780**

Super/Date:	Not reported
Stage Of Project:	Not reported
RP Level Of Activity:	Not reported
RP Needed Level Of Activity:	Not reported
Staff Level Of Activity:	Not reported
Staff Needed Level Of Activity:	Not reported
Public Intrest:	Not reported
PRP Cooperation:	Not reported
Enforcement Status:	Not reported
Level Of Complexity:	Not reported
Complex Eng Or Sci:	False
Complex Due To Public Involvement:	False
Politically Complex:	False
Complex Enforcement:	False
Coordination With Other Bureaus:	False
EPA Involvement:	False
Staff Prefrence:	Not reported
Readiness For Transfer:	Not reported
Project Transfer Time:	Not reported
Transfer Comments:	Not reported
Staff As Of July 2000:	Not reported
Initial Staff:	Not reported
Type Of Transfer:	Not reported
Salutation:	Mr. Keller
Relationship To Transfer:	transferee
Audit Date:	Not reported
Verif Type:	Not reported
Audit Outcome:	Not reported
GW:	GB
Basin:	Not reported
1st Payment:	2000
Pay Tag1:	Not reported
2nd Payment:	Not reported
Pay Tag2:	Not reported
RTN:	Not reported
Revised:	Not reported
ECAF Received:	Not reported
Old Determination Date:	Not reported
Redeterminationdate:	Not reported
Previous Determination:	Not reported
Monitoringoption:	Not reported
Postremedialmonitoring:	Not reported
Schedule Of I/R:	03/20/2001
Schedule Overdue:	2001-06-07 00:00:00
Aprvl Sched:	Not reported
Yr 1 Report:	Not reported
Yr 2 Report:	Not reported
Report Overdue:	Not reported
Ext Aprvl Sched:	Not reported
License #:	Not reported
Project Phase:	Not reported
PT Comments:	Not reported
EPA Id Number:	Not reported
GW Class:	Not reported
SW Class:	Not reported
AO/C0:	Not reported
Water Lead(Y Or N):	Not reported

CRESTWOOD PRODUCTS (FORMER) (Continued) **S128727780**

Priority:	Not reported
Project Status(A, I Or D):	Not reported
Last Updated:	Not reported
SR Comments:	Not reported
Priority Or Work-Load:	Not reported
Status:	Not reported
Notes:	Not reported
Special Project Name:	Not reported
Special Project Comments:	Not reported
DOT Project:	Not reported
Pt Counter:	0
Project Complete:	False
Project Inactive:	False
Int Deposit #:	Not reported
Deposit #:	Not reported
Spill Case #:	Not reported
Diversion Id:	Not reported
Public Notice:	Not reported
RAP Received:	Not reported
RAP Approved:	Not reported
Compliance Category:	B
Delete Record:	False
ECAF Reviewed By:	Michelle Bedson
Not Locatable:	False
Primary Address:	True
AKA Site Name:	False
Primary Site Name:	True
AKA Site Address:	False
Lead:	LEP

CPCS:

Name:	Crestwood Products (Former)
Address:	654 & 672 TOLLAND STREET
City,State,Zip:	EAST HARTFORD, CT
Site Type:	Not reported
Lust Status code:	Not reported
Lust Status:	Not reported
PTP Form:	Not reported
Program:	Property Transfer Program
Comments:	Not reported
Site Type Definition:	Not reported
Invesigation Start:	Not reported
Invesigation Start Date:	11/17/2000
Remediation Start:	Not reported
Remediation Start Date:	Not reported
Remediation Completed:	Yes
ELUR:	No
Date Data Updated:	Not reported

51
NNE
1/4-1/2
0.319 mi.
1685 ft.

TOLLAND CORPORATION
676-678 TOLLAND STREET
EAST HARTFORD, CT

CT SDADB
CT PROPERTY
CT CPCS

S104187601
N/A

Relative:
Lower

Actual:
68 ft.

Site Discovery and Assessment:

Facility ID:	4100
Rem Master ID:	4362
PTP Id:	514
WPC Number:	Not reported
Postal District:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Determined By:	Not reported
Ground Water Quality Classification:	Not reported
Surface Water Quality Classification:	Not reported
Waste Type:	Not reported
Disposal:	Not reported
Sample Data Available:	False
Updated By:	Not reported
Update Program:	Not reported
Updated:	Not reported
Date Created:	Not reported
Duplicate:	False

SDA Federal:

EPA CERCLIS Id:	Not reported
Number EPA RCRIS Id:	Not reported
Site on EPA's CERCLIS:	Not reported
Site Archived from CERCLIS:	Not reported
Archive Date:	Not reported
EPA's Removal at Site:	Not reported
Deferred to another EPA Program:	Not reported
EPA Env Priority Initiative Site:	Not reported
Federal Facility:	Not reported
Site on EPA's National Priority List:	Not reported
Part of an NPL site:	Not reported
RCRA Generator Status:	Not reported
RCRA Permit Status:	Not reported

SDA Referral:

Referral Id:	4248
Source of referral:	PTP
Date Received:	1/6/1989
Staff Assigned:	Not reported
Remediation Program:	PTP
Date dt_assigned:	Not reported
Remediation Complete Approved DEP/Verified by LEP:	1/6/1989
Outcome:	PTP

SDA Remedial:

Remedial Id:	Not reported
PTP Id:	Not reported
Remediation Program:	Not reported
Remediation Program Entered:	Not reported
Staff Assigned:	Not reported
Remediation Program:	Not reported
Date dt_assign:	Not reported
Project Phase:	Not reported
Order issued:	Not reported

TOLLAND CORPORATION (Continued) **S104187601**

Order Number:	Not reported
Date order issued:	Not reported
Remedial Investigation Start:	Not reported
Remedial Investigation Completed:	Not reported
Remedial Design Start:	Not reported
Remedial Design complet:	Not reported
Remedial Action Start:	Not reported
Remedial Action Completed:	Not reported
Date Oper/ maintenance Started:	Not reported
GW monitoring:	Not reported
Remediation complete Approved DEP/Verified by LEP:	Not reported

SDA Orders:

Order Id:	Not reported
Order Number:	Not reported
Date order issued:	Not reported
Staff Assigned:	Not reported
Type of Order:	Not reported
Order Respondent:	Not reported
Admin Appeal Date:	Not reported
Date of Admin Appeal Ruling:	Not reported
Date of Admin Appeal Ruling:	Not reported
Date of Final Order:	Not reported
Date of Court Appeal:	Not reported
Date of Court Ruling:	Not reported
Date of Court Ruling:	Not reported
Date Order Modified:	Not reported
Date Referred to AG:	Not reported
Judgement:	Not reported
Date of AGR judgement:	Not reported
Penalty assessed:	Not reported
Order Complete:	Not reported
In compliance:	Not reported
Comments:	Not reported

CT Property:

Name:	TOLLAND CORPORATION
Address:	676-678 TOLLAND STREET
City,state,zip:	EAST HARTFORD, CT
Seller Name:	The Tolland Corporation
Buyer Name:	Tolland St. Partnership
Certifying Party:	Not reported
Certifying Attention Person:	Not reported
Title Of Certifying Person:	Not reported
Certifying Person Address:	Not reported
Certifying Person City,St,Zip:	Not reported
Property Transfer Forms:	Form I (DEP-PERD-PTP-201) when no release of hazardous waste has occurred at the parcel being transferred.
Date Recieved:	01/06/1989
Ackn Date:	04/20/1989
Determination Date:	Not reported
LEP Verified/DEP Approval Date:	Not reported
Rem Id:	1649
Remediation Location Id:	4642
Date Entered:	Not reported
Program:	Property Transfer Program
GAO Site:	False

TOLLAND CORPORATION (Continued) **S104187601**

Staff Full Name:	Not reported
Super/Date:	Not reported
Stage Of Project:	Not reported
RP Level Of Activity:	Not reported
RP Needed Level Of Activity:	Not reported
Staff Level Of Activity:	Not reported
Staff Needed Level Of Activity:	Not reported
Public Intrest:	Not reported
PRP Cooperation:	Not reported
Enforcement Status:	Not reported
Level Of Complexity:	Not reported
Complex Eng Or Sci:	False
Complex Due To Public Involvement:	False
Politically Complex:	False
Complex Enforcement:	False
Coordination With Other Bureaus:	False
EPA Involvement:	False
Staff Prefrence:	Not reported
Readiness For Transfer:	Not reported
Project Transfer Time:	Not reported
Transfer Comments:	Not reported
Staff As Of July 2000:	Not reported
Initial Staff:	Not reported
Type Of Transfer:	Not reported
Salutation:	Not reported
Relationship To Transfer:	Not reported
Audit Date:	Not reported
Verif Type:	Not reported
Audit Outcome:	Not reported
GW:	-
Basin:	Not reported
1st Payment:	Not reported
Pay Tag1:	Not reported
2nd Payment:	Not reported
Pay Tag2:	Not reported
RTN:	Not reported
Revised:	Not reported
ECAF Received:	Not reported
Old Determination Date:	Not reported
Redeterminationdate:	Not reported
Previous Determination:	Not reported
Monitoringoption:	Not reported
Postremedialmonitoring:	Not reported
Schedule Of I/R:	Not reported
Schedule Overdue:	Not reported
Aprvl Sched:	Not reported
Yr 1 Report:	Not reported
Yr 2 Report:	Not reported
Report Overdue:	Not reported
Ext Aprvl Sched:	Not reported
License #:	Not reported
Project Phase:	Not reported
PT Comments:	Not reported
EPA Id Number:	Not reported
GW Class:	Not reported
SW Class:	Not reported
AO/C0:	Not reported

TOLLAND CORPORATION (Continued) **S104187601**

Water Lead(Y Or N):	Not reported
Priority:	Not reported
Project Status(A, I Or D):	Not reported
Last Updated:	Not reported
SR Comments:	Not reported
Priority Or Work-Load:	Not reported
Status:	Not reported
Notes:	Not reported
Special Project Name:	Not reported
Special Project Comments:	Not reported
DOT Project:	Not reported
Pt Counter:	Not reported
Project Complete:	False
Project Inactive:	False
Int Deposit #:	Not reported
Deposit #:	Not reported
Spill Case #:	Not reported
Diversion Id:	Not reported
Public Notice:	Not reported
RAP Received:	Not reported
RAP Approved:	Not reported
Compliance Category:	Not reported
Delete Record:	False
ECAF Reviewed By:	Not reported
Not Locatable:	False
Primary Address:	True
AKA Site Name:	False
Primary Site Name:	True
AKA Site Address:	False
Lead:	LEP

CPCS:

Name:	Tolland Corporation
Address:	676-678 TOLLAND STREET
City,State,Zip:	EAST HARTFORD, CT
Site Type:	Not reported
Lust Status code:	Not reported
Lust Status:	Not reported
PTP Form:	Not reported
Program:	Property Transfer Program
Comments:	Not reported
Site Type Definition:	Not reported
Invesigation Start:	Not reported
Invesigation Start Date:	04/20/1989
Remediation Start:	Not reported
Remediation Start Date:	Not reported
Remediation Completed:	No
ELUR:	No
Date Data Updated:	Not reported

G52 **590 BURNSIDE AVENUE REDEVELOPMENT - SUPPLEMENTAL A** **CT BROWNFIELDS** **S125431680**
West **590 BURNSIDE AVENUE** **N/A**
1/4-1/2 **EAST HARTFORD, CT 06108**
0.363 mi.
1914 ft. **Site 1 of 4 in cluster G**

Relative: **Lower**

Actual: **48 ft.**

BROWNFIELDS:

Address:	590 BURNSIDE AVENUE
Name:	590 BURNSIDE AVENUE REDEVELOPMENT - SUPPLEMENTAL ASSISTANCE 1
City,State,Zip:	EAST HARTFORD, CT 06108
Applicant:	East Hartford, Town of
Applicant Address:	740 Main Street
Applicant Municipality:	East Hartford
Applicant State:	CT
Applicant Zip Code:	06108
Size Acre:	0
Fiscal Year:	2019
Contract Execution Date:	08/06/2018
Grant Amount:	$200,000
Loan Amount:	$ -
Total Assistance:	$200,000
Other Project Funds:	$0.00
Total Project Cost:	$200,000
Funding Source:	Brownfield Municipal Grant Program
Statutory Reference:	C.G.S. Sec. 32-763
New Georeferenced Column:	590 Burnside Avenue East Hartford 06108 (41.77873, -72.61426)

G53 **DALEY COURT** **US BROWNFIELDS** **1025815217**
West **590 BURNSIDE AVE** **FINDS** **N/A**
1/4-1/2 **EAST HARTFORD, CT 06108**
0.363 mi.
1914 ft. **Site 2 of 4 in cluster G**

Relative: **Lower**

Actual: **48 ft.**

US BROWNFIELDS:

Name:	Daley Court
Address:	590 Burnside Ave
City,State,Zip:	EAST HARTFORD, CT 06108
Property ID:	238836
Property Alias:	Not reported
Recipient Name:	East Hartford Town of
Grant Type:	Hazardous
Property Number:	36-118
Parcel Size:	1.42
Latitude:	41.7788569
Longitude:	-72.6142987
Census Tract:	9003510400
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Pre-Demolition HBM Survey
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Asbestos Lead PCBs
Contaminants Found at Actionable Level:	Asbestos Lead PCBs

DALEY COURT (Continued) **1025815217**

Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96196901
Start Date:	Not reported
Ownership Entity:	Government
Additional Institutional Controls Information:	Not reported
Completion Date:	Not reported
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	Y
Indicates Cleanup/Treatment Tech Implemented:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	Not reported
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Asbestos Lead PCBs
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Building Materials
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Building Materials
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported

DALEY COURT (Continued) **1025815217**

RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	RLF Leveraged
Past use greenspace acreage:	1.07
Past use residential acreage:	0.35
RLF Leveraged - Entity Providing Funding:	CTDAS
RLF Leveraged - Funding Amount:	755750
Cleanup Completion Doc - NFA Letter Received:	N
Past use commercial acreage:	Not reported
NFA Letter Date Received:	11/6/2018
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	N
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	920
Below Poverty Percent:	29.46
Meidan Income:	890
Meidan Income Number:	1625
Meidan Income Percent:	52.03
Vacant Housing Number:	183
Vacant Housing Percent:	12.15
Unemployed Number:	275
Unemployed Percent:	8.81

Name:	Daley Court
Address:	590 Burnside Ave
City,State,Zip:	EAST HARTFORD, CT 06108
Property ID:	238836
Property Alias:	Not reported
Recipient Name:	East Hartford Town of
Grant Type:	Hazardous
Property Number:	36-118
Parcel Size:	1.42
Latitude:	41.7788569
Longitude:	-72.6142987
Census Tract:	9003510400
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Pre-Demolition HBM Survey
Start Date:	Not reported
Redev Completition Date:	Not reported

DALEY COURT (Continued) **1025815217**

Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Pre-Demolition HBM Survey
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Asbestos Lead PCBs
Contaminants Found at Actionable Level:	Asbestos Lead PCBs
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96196901
Start Date:	2018-06-03 00:00:00
Ownership Entity:	Government
Additional Institutional Controls Information:	Not reported
Completion Date:	2018-06-22 00:00:00
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	Y
Indicates Cleanup/Treatment Tech Implemented:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	Not reported
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported

DALEY COURT (Continued) **1025815217**

RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Asbestos Lead PCBs
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Building Materials
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Building Materials
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	RLF Leveraged
Past use greenspace acreage:	1.07
Past use residential acreage:	0.35
RLF Leveraged - Entity Providing Funding:	CTDAS
RLF Leveraged - Funding Amount:	755750
Cleanup Completion Doc - NFA Letter Received:	N
Past use commercial acreage:	Not reported
NFA Letter Date Received:	11/6/2018
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	N
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	920
Below Poverty Percent:	29.46
Meidan Income:	890
Meidan Income Number:	1625
Meidan Income Percent:	52.03
Vacant Housing Number:	183
Vacant Housing Percent:	12.15
Unemployed Number:	275
Unemployed Percent:	8.81

Name:	Daley Court
Address:	590 Burnside Ave
City,State,Zip:	EAST HARTFORD, CT 06108
Property ID:	238836
Property Alias:	Not reported
Recipient Name:	East Hartford Town of
Grant Type:	Hazardous
Property Number:	36-118

DALEY COURT (Continued) **1025815217**

Parcel Size:	1.42
Latitude:	41.7788569
Longitude:	-72.6142987
Census Tract:	9003510400
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Not reported
Start Date:	8/24/2018
Redev Completition Date:	Not reported
Completed Date:	10/16/2018
Cleanup Funding:	Not reported
Cleanup Funding Source:	CTDAS
Activity Funded:	Pre-Demolition HBM Survey
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Asbestos Lead PCBs
Contaminants Found at Actionable Level:	Asbestos Lead PCBs
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	State/Tribal Funding (non-section 128(a))
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96196901
Start Date:	Not reported
Ownership Entity:	Government
Additional Institutional Controls Information:	Not reported
Completion Date:	Not reported
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	Y
Indicates Cleanup/Treatment Tech Implemented:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	Not reported
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported

DALEY COURT (Continued) **1025815217**

Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	0.35
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Asbestos Lead PCBs
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Building Materials
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Building Materials
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	RLF Leveraged
Past use greenspace acreage:	1.07
Past use residential acreage:	0.35
RLF Leveraged - Entity Providing Funding:	CTDAS
RLF Leveraged - Funding Amount:	755750
Cleanup Completion Doc - NFA Letter Received:	Not reported
Past use commercial acreage:	Not reported
NFA Letter Date Received:	11/6/2018
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	Y
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	920
Below Poverty Percent:	29.46
Meidan Income:	890
Meidan Income Number:	1625
Meidan Income Percent:	52.03
Vacant Housing Number:	183
Vacant Housing Percent:	12.15
Unemployed Number:	275
Unemployed Percent:	8.81

DALEY COURT (Continued) **1025815217**

FINDS:
Registry ID: 110070556141

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on Brownfields properties assessed or cleaned up with grant funding, as well as information on Targeted Brownfields Assessments (TBA) performed by EPA Regions.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

G54 **DALEY COURT** **CT BROWNFIELDS** **S128966184**
West **590 BURNSIDE AVENUE** **N/A**
1/4-1/2 **EAST HARTFORD, CT**
0.363 mi.
1914 ft. **Site 3 of 4 in cluster G**

Relative:
Lower

Actual:
48 ft.

BROWNFIELDS 2:

Region:	2
Data Source CD:	EPA, DECD GRANT
Data Source:	EPA Funded Brownfields Project, DECD Funded Brownfields Projec GRANT
Parcel ID Number:	1870
Latitude:	41.778788
Longitude:	-72.614039
Site Acreage:	1.42
Program Approval Date:	Not reported

G55 **590 BURNSIDE AVENUE REDEVELOPMENT** **CT BROWNFIELDS** **S125431681**
West **590 BURNSIDE AVENUE** **N/A**
1/4-1/2 **EAST HARTFORD, CT 06108**
0.363 mi.
1914 ft. **Site 4 of 4 in cluster G**

Relative:
Lower

Actual:
48 ft.

BROWNFIELDS:

Address:	590 BURNSIDE AVENUE
Name:	590 BURNSIDE AVENUE REDEVELOPMENT
City,State,Zip:	EAST HARTFORD, CT 06108
Applicant:	East Hartford, Town of
Applicant Address:	740 Main Street
Applicant Municipality:	East Hartford
Applicant State:	CT
Applicant Zip Code:	06108
Size Acre:	1.42
Fiscal Year:	2016
Contract Execution Date:	08/25/2015
Grant Amount:	$175,000
Loan Amount:	$ -
Total Assistance:	$175,000
Other Project Funds:	$0.00
Total Project Cost:	$175,000
Funding Source:	Brownfield Municipal Grant Program
Statutory Reference:	C.G.S. Sec. 32-763
New Georeferenced Column:	590 Burnside Avenue East Hartford 06108 (41.77873, -72.61426)

H56 **SHELL FACILITY #136303** **CT LUST** **S103156178**
NW **123 SCHOOL STREET** **CT PROPERTY** **N/A**
1/4-1/2 **EAST HARTFORD, CT** **CT SPILLS**
0.390 mi. **CT CPCS**
2057 ft. **Site 1 of 3 in cluster H**

Relative:
Lower

Actual:
48 ft.

LUST:

Name:	Not reported
Name 2:	Not reported
Address:	123 SCHOOL STREET
Address 2:	Not reported
City,State,Zip:	EAST HARTFORD, CT
LUST Case Id:	48752
Release Date:	10/01/1987
Site Case ID:	43-5233
Substance:	Gasoline
Release Source:	Unknown
Release Cause:	Unknown
Release Identified:	Removal/Closure
Case Number:	unknown
Release Quantity:	Unknown
Facility City Number:	Not reported

Detail As of 06/2020:

Name:	SHELL SERVICE STATION (FORMER SHELL #136303)
Name 2:	Not reported
Address:	123 SCHOOL STREET
City,State,Zip:	EAST HARTFORD, CT
Address 2:	Not reported
LUST Id:	0
UST Facility Id:	5233
LUST Case Id:	48752
Lust Status:	Lust Completed
Processing Status:	Not reported
EPA Reportable:	True
Motor Fuel:	False
Diesel:	False
Gasoline:	False
Other:	False
Other Release:	Not reported
No Release:	False
Leak:	False
Tank:	False
Piping:	False
Overfill:	False
Removal:	False
Incident Date:	06/06/2009
Entry Date:	08/09/2007
Site Case Id:	200903009
UST Site Id:	0
Cost Recovery Spill Case #:	0
Old SITS Number:	0
Case Log Id:	0
Monthly Report Id:	0
UST Owner Id:	9374
LUST Owner Id:	PCC
UST Event Id:	0
Contact Info:	Not reported
Contact EMail:	Kyle.Kreter@codyehlers.com
Site Contact City,St,Zip:	144, CT 06611

SHELL FACILITY #136303 (Continued) **S103156178**

2nd Contact:	W. Scott Burrus (Sovereign Consulting Inc.)
2nd Contact EMail:	Sburrus@sovcon.com
2nd Contact Address:	1 Tarby Lane
2nd Contact City,St,Zip:	108, CT 06478
2nd Contact Address 2:	Not reported
2nd Contact City 2:	Oxford
2nd Contact Phone Number:	2038281640
2nd Contact Fax Number:	2038281641
2nd Contact Type:	Senior Project Manager, LEP
Facility City Num:	43
Site Contact:	Kyle Kreter (Cody Ehlers Group)
Site Contact Address:	935 White Plains Road
Site Contact Add 2:	Suite 205
Site Contact City 2:	Trumbull
Site Contact Phone:	2032597722
Site Contact Fax:	Not reported
Site Contact Type:	Not reported
Department Contact 1:	Not reported
Department Contact 2:	Not reported
Referral Source:	Not reported
Offsite Source:	False
Date Referred:	Not reported
Emergency:	False
Private Heating Fuel:	False
Commercial Heating Fuel:	False
Commercial HF < 2100 Gal.:	False
Commercial HF > 2100 Gal.:	False
Commercial HF - Size Unk:	False
No LUST Site:	False
Cost Recvry Prgm Candidate:	False
OCSRD Complete:	False
Follow Up Flag:	False
Alternate Water Supply:	False
Relocation:	False
Responsible Party:	False
Responsible EMail:	SHELLSHARP@AOL.COM
Resp Party Name:	123 School Street
Resp Party Address:	P.O. Box 4151
Resp Party City,St,Zip:	Key West, FL 330414151
Resp Party Town Number:	Not reported
Resp Party Phone:	8604468615
Resp Party Fax:	Not reported
Resp Party Name 2:	Not reported
Resp Party Address 2:	Not reported
Resp Party Phone 2:	8605897558
Investigator Id:	0
Follow Update:	Not reported
Area Lextent:	Not reported
Annual Precipitation:	Not reported
Affected Population:	Not reported
Population Setting:	Not reported
Ground Water Direction:	Not reported
Ground Water Gradient:	0.007 to 0.01 ft/ft
Hydro Basin:	Not reported
Drastic:	Not reported
Geo Setting:	Not reported
Ground Water Classification:	GB

SHELL FACILITY #136303 (Continued) **S103156178**

Receptor:	semi-annually-Quarterly
Ground Water Flow Direction:	south-southwest
Ground Water Depth:	6.54-11.99
Areas Of Concern:	Not reported
Free Product Inches:	0
Fund Date:	Not reported
Fund Planned:	No
Fund Obligated:	No
Fund Outlayed:	No
Fund Judgment:	No
Fund Recovered:	No
Cellar Borings:	False
Install Micro Wells:	False
Ground Water Sample:	False
Soil Sample:	False
Soil Gas:	False
Site Inspect:	False
Soil Excavate:	False
Geo Probe:	False
Survey:	False
Potable Well Sample:	False
Sample MWS:	False
Ground Water Gauging:	False
Soil Venting:	False
Active:	True
NOV Action:	None
NOV Issued:	Not reported
NOV Due:	Not reported
NOV Received:	Not reported
NOV Closed:	Not reported
NOV Disc Date:	Not reported
NOV Issued Date:	Not reported
NOV Compliance Sched:	Not reported
NOV Admin Order:	Not reported
NOV Referred To Ag:	Not reported
Stop All NOV Actions:	False
Release Invest Rpt:	False
DEP App Letter 1:	False
Correct Action Plan:	False
DEP App Letter 2:	False
Rem Sys Install:	False
Rem Sys Install Date:	Not reported
Closure Date:	Not reported
Rem Sys Monitoring Rpt:	False
Qrtly Gwater Mon Rpts:	False
Closure Req Rpt:	False
DEP Closure Letter:	False
Referred To:	Not reported
No Wells:	7
Lph Wells:	0
User Stamp:	ForrestA/forrestlaiuppaa
Date Stamp:	07/16/2019
Correspondence:	Not reported
Environmental Impact:	Not reported
FollowUp:	Not reported
GW Comments:	Residential properties located to the S & W of the site may contain basements. 19 residential properties are within 328 feet and contain

SHELL FACILITY #136303 (Continued) **S103156178**

basements. A small pond, likely a storm water retention pond, is 400 feet east. The Hockanum River is 1,800 feet south.

Location Desc:	Active third party service station
NOV Comments:	Not reported
Release Desc:	Not reported
Running Comments:	Spills Files, UST Enforcement Files, and LUST Files
Work Performed:	Not reported

CT Property:

Name:	SHELL FACILITY #136303
Address:	123 SCHOOL STREET
City,state,zip:	EAST HARTFORD, CT
Seller Name:	Motiva Enterprises LL
Buyer Name:	123 School Street, LLC
Certifying Party:	Motiva Enterprises LLC
Certifying Attention Person:	Charles T. Badrick
Title Of Certifying Person:	Manager real estate contracts
Certifying Person Address:	PO Box 4369
Certifying Person City,St,Zip:	Houston, TX 77210
Property Transfer Forms:	Form III (DEP-PERD-PTP-203) when a discharge, spillage, uncontrolled loss, seepage or filtration of hazardous waste has occurred at the parcel that has not been fully remediated or the environmental conditions at the parcel are unknown. The person signing the Form III certification agrees to investigate and remediate the site in accordance with the remediation standards. The statute does not require completion of remediation before the parcel is transferred. Any person submitting a Form III shall simultaneously submit a completed Environmental Condition Assessment Form (ECAF)(DEP-PERD-PTP-200).
Date Recieved:	10/24/2006
Ackn Date:	01/10/2007
Determination Date:	03/28/2007
LEP Verified/DEP Approval Date:	Not reported
Rem Id:	8288
Remediation Location Id:	7606
Date Entered:	11/13/2006
Program:	Property Transfer Program
GAO Site:	False
Staff Full Name:	Michelle Bedson
Super/Date:	01/11/2007
Stage Of Project:	Not reported
RP Level Of Activity:	Not reported
RP Needed Level Of Activity:	Not reported
Staff Level Of Activity:	Not reported
Staff Needed Level Of Activity:	Not reported
Public Intrest:	Not reported
PRP Cooperation:	Not reported
Enforcement Status:	Not reported
Level Of Complexity:	Not reported
Complex Eng Or Sci:	False
Complex Due To Public Involvement:	False
Politically Complex:	False
Complex Enforcement:	False
Coordination With Other Bureaus:	False
EPA Involvement:	False
Staff Prefrence:	Not reported

SHELL FACILITY #136303 (Continued) **S103156178**

Readiness For Transfer:	Not reported
Project Transfer Time:	Not reported
Transfer Comments:	Not reported
Staff As Of July 2000:	Not reported
Initial Staff:	Not reported
Type Of Transfer:	Real Estate
Salutation:	Mr. Badrick
Relationship To Transfer:	transferor
Audit Date:	Not reported
Verif Type:	Not reported
Audit Outcome:	Not reported
GW:	GB
Basin:	Not reported
1st Payment:	3000
Pay Tag1:	Not reported
2nd Payment:	Not reported
Pay Tag2:	Not reported
RTN:	Not reported
Revised:	Not reported
ECAF Received:	Not reported
Old Determination Date:	Not reported
Redeterminationdate:	Not reported
Previous Determination:	Not reported
Monitoringoption:	Not reported
Postremedialmonitoring:	2015-10-19 00:00:00
Schedule Of I/R:	04/06/2007
Schedule Overdue:	Not reported
Aprvl Sched:	Not reported
Yr 1 Report:	2008-01-31 00:00:00
Yr 2 Report:	Not reported
Report Overdue:	Not reported
Ext Aprvl Sched:	Not reported
License #:	Not reported
Project Phase:	Not reported
PT Comments:	Not reported
EPA Id Number:	Not reported
GW Class:	Not reported
SW Class:	Not reported
AO/C0:	Not reported
Water Lead(Y Or N):	Not reported
Priority:	Not reported
Project Status(A, I Or D):	Not reported
Last Updated:	Not reported
SR Comments:	Not reported
Priority Or Work-Load:	Not reported
Status:	Not reported
Notes:	Not reported
Special Project Name:	Not reported
Special Project Comments:	Not reported
DOT Project:	Not reported
Pt Counter:	0
Project Complete:	False
Project Inactive:	False
Int Deposit #:	Not reported
Deposit #:	Not reported
Spill Case #:	Not reported
Diversion Id:	0

SHELL FACILITY #136303 (Continued) **S103156178**

Public Notice:	Not reported
RAP Received:	2011-01-21 00:00:00
RAP Approved:	Not reported
Compliance Category:	B
Delete Record:	False
ECAF Reviewed By:	Michelle Bedson
Not Locatable:	False
Primary Address:	True
AKA Site Name:	False
Primary Site Name:	True
AKA Site Address:	False
Lead:	LEP

SPILLS:

Name:	Not reported
Address:	123 SCHOOL STREET
City,State,Zip:	EAST HARTFORD, CT
Year of Database:	2011
Case Number:	201100750
Who Took Spill:	205
Assigned To:	No Response
Report Date:	02/17/2011
Report Time:	12:00:00 AM
Date Release:	02/17/2011
Release Time:	12:00:00 AM
Reported By:	dispatch
Phone:	860 2917515
Qty:	~ 3.00 (Gallons)
Telephone:	Not reported
Representing:	ehfd
Facility Status:	CLOSED
Continuous Spill:	False
Release Substance:	ANTIFREEZE & TRANSMISSION OIL
Emergency Measure:	Not reported
Discharger:	unk
Waterbody Affected:	Other (none)
Responsible Party:	true
Responsible Party Address:	Not reported
RP City,St,Zip:	CT
Terminated:	YES
Recovered Total:	0
Total Water:	0
Historic:	False
Waterbody:	n/a
User Stamp:	cguzman
Stamp Time:	2011-02-18 12:23:39
SR Inspector:	Cox, Michael
AT Inspector:	**NO RESPONSE
Corrective Action Taken:	Sanded
Cause Info:	MV Accident
Media Info:	Ground Surface
Release Type:	petroleum, and chemical
Incident Description:	Not reported
Cost Recovery Case?:	Not reported
DEMHS Region:	Not reported
Lat/Long:	Not reported
Company Name:	Not reported

SHELL FACILITY #136303 (Continued) **S103156178**

Last Updated: Not reported

Action:
Action: Sanded
Other Action: Not reported

Agency:
Agency ID: DEP Dispatch
Other Agency: Not reported
DEP Bureau: Not reported
DEP Agency: Not reported

Agency ID: LOCAL FIRE DEPARTMENT
Other Agency: Not reported
DEP Bureau: Not reported
DEP Agency: Not reported

Cause:
Cause ID: MV Accident
Other Cause: Not reported

Media:
Media ID: Ground Surface
Other Media: Not reported

Release Class:
Class ID: Transportation
Other Class: Not reported

Class ID: Private
Other Class: Not reported

Release Type:
Release Type: petroleum
Other Release: Not reported

Release Type: chemical
Other Release: Not reported

Waterbody:
Waterbody: Other
Other Waterbody: none

Name: Not reported
Address: 123 SCHOOL ROAD
City,State,Zip: EAST HARTFORD, CT
Year of Database: 1996
Case Number: 9605257
Who Took Spill: 209
Assigned To: No Response
Report Date: 10/14/1996
Report Time: 12:00:00 AM
Date Release: 10/14/1996
Release Time: 12:00:00 AM

SHELL FACILITY #136303 (Continued) **S103156178**

Reported By:	RAYK RIDDEL
Phone:	860 5713138 - 860 5713137
Qty:	4.00 (Gallons)
Telephone:	Not reported
Representing:	SHELL OIL PRODUCTS
Facility Status:	closed
Continuous Spill:	False
Release Substance:	GASOLINE
Emergency Measure:	Not reported
Discharger:	Not reported
Waterbody Affected:	Not reported
Responsible Party:	Not reported
Responsible Party Address:	Not reported
RP City,St,Zip:	CT
Terminated:	YES
Recovered Total:	0
Total Water:	0
Historic:	False
Waterbody:	Not reported
User Stamp:	Not reported
Stamp Time:	1997-01-15 18:39:04
SR Inspector:	RODE, MATT
AT Inspector:	**NO RESPONSE
Corrective Action Taken:	Sanded
Cause Info:	OVERFILL
Media Info:	Ground Surface
Release Type:	petroleum
Incident Description:	Not reported
Cost Recovery Case?:	Not reported
DEMHS Region:	Not reported
Lat/Long:	Not reported
Company Name:	Not reported
Last Updated:	Not reported

Action:

Action:	Sanded
Other Action:	Not reported

Cause:

Cause ID:	Overfill
Other Cause:	Not reported

Media:

Media ID:	Ground Surface
Other Media:	Not reported

Release Type:

Release Type:	petroleum
Other Release:	Not reported

CPCS:

Name:	Shell Facility #136303
Address:	123 SCHOOL STREET

SHELL FACILITY #136303 (Continued) **S103156178**

City,State,Zip:	EAST HARTFORD, CT
Site Type:	Not reported
Lust Status code:	Not reported
Lust Status:	Not reported
PTP Form:	Not reported
Program:	Property Transfer Program
Comments:	Not reported
Site Type Definition:	Not reported
Invesigation Start:	Not reported
Invesigation Start Date:	01/10/2007
Remediation Start:	Not reported
Remediation Start Date:	10/27/2010
Remediation Completed:	No
ELUR:	No
Date Data Updated:	Not reported

H57 **SHELL SERVICE STATION** **CT SPILLS** **S109738934**
NW **123 SCHOOL ST** **CT CPCS** **N/A**
1/4-1/2 **EAST HARTFORD, CT 06108** **CT ENF**
0.390 mi. **CT MANIFEST**
2057 ft. **Site 2 of 3 in cluster H**

Relative: **Lower**
Actual: **48 ft.**

SPILLS:

Name:	Not reported
Address:	123 SCHOOL ST
City,State,Zip:	EAST HARTFORD, CT
Year of Database:	2001
Case Number:	200104043
Who Took Spill:	206
Assigned To:	No Response
Report Date:	06/07/2001
Report Time:	12:00:00 AM
Date Release:	06/07/2001
Release Time:	12:00:00 AM
Reported By:	EAST HARTFORD FIRE
Phone:	860 5284407
Qty:	1.00 (Gallons)
Telephone:	Not reported
Representing:	Self
Facility Status:	Closed
Continuous Spill:	False
Release Substance:	UNKNOWN PETROLEUM
Emergency Measure:	SOME TYPE OF PETROLEUM PRODUCT, SANDED
Discharger:	Not reported
Waterbody Affected:	Other (NA)
Responsible Party:	Not reported
Responsible Party Address:	Not reported
RP City,St,Zip:	CT
Terminated:	YES
Recovered Total:	0
Total Water:	0
Historic:	False
Waterbody:	NA
User Stamp:	Not reported
Stamp Time:	2001-06-08 10:06:38
SR Inspector:	Kinney, Clarence
AT Inspector:	**NO RESPONSE
Corrective Action Taken:	Sanded

SHELL SERVICE STATION (Continued) **S109738934**

Cause Info:	Other (UNKNOWN)
Media Info:	Ground Surface
Release Type:	petroleum
Incident Description:	Not reported
Cost Recovery Case?:	Not reported
DEMHS Region:	Not reported
Lat/Long:	Not reported
Company Name:	Not reported
Last Updated:	Not reported

Action:

Action:	Sanded
Other Action:	Not reported

Agency:

Agency ID:	DEP Dispatch
Other Agency:	Not reported
DEP Bureau:	Not reported
DEP Agency:	Not reported
Agency ID:	LOCAL FIRE DEPARTMENT
Other Agency:	Not reported
DEP Bureau:	Not reported
DEP Agency:	Not reported

Cause:

Cause ID:	Other
Other Cause:	UNKNOWN

Media:

Media ID:	Ground Surface
Other Media:	Not reported

Release Class:

Class ID:	Private
Other Class:	Not reported

Release Type:

Release Type:	petroleum
Other Release:	Not reported

Waterbody:

Waterbody:	Other
Other Waterbody:	NA

Name:	Not reported
Address:	123 SCHOOL ST
City,State,Zip:	EAST HARTFORD, CT
Year of Database:	2007
Case Number:	200700129
Who Took Spill:	205
Assigned To:	No Response
Report Date:	01/08/2007
Report Time:	12:00:00 AM

SHELL SERVICE STATION (Continued) **S109738934**

Date Release:	01/08/2007
Release Time:	12:00:00 AM
Reported By:	#958
Phone:	860 5284401
Qty:	0.00 (Gallons)
Telephone:	Not reported
Representing:	East Hartford FD
Facility Status:	CLOSED
Continuous Spill:	False
Release Substance:	ANTIFREEZE
Emergency Measure:	contents of one radiator, caller stated the rain is washing it away as they are sanding.
Discharger:	Not reported
Waterbody Affected:	Other (none)
Responsible Party:	Not reported
Responsible Party Address:	Not reported
RP City,St,Zip:	CT
Terminated:	YES
Recovered Total:	0
Total Water:	0
Historic:	False
Waterbody:	n/a
User Stamp:	mgranill
Stamp Time:	2007-01-08 14:27:18
SR Inspector:	Cox, Michael
AT Inspector:	**NO RESPONSE
Corrective Action Taken:	Sanded
Cause Info:	MV Accident
Media Info:	Ground Surface
Release Type:	chemical
Incident Description:	Not reported
Cost Recovery Case?:	Not reported
DEMHS Region:	Not reported
Lat/Long:	Not reported
Company Name:	Not reported
Last Updated:	Not reported

Action:

Action:	Sanded
Other Action:	Not reported

Agency:

Agency ID:	DEP Dispatch
Other Agency:	Not reported
DEP Bureau:	Not reported
DEP Agency:	Not reported

Cause:

Cause ID:	MV Accident
Other Cause:	Not reported

Media:

Media ID:	Ground Surface
Other Media:	Not reported

SHELL SERVICE STATION (Continued) **S109738934**

Release Class:
Class ID: Transportation
Other Class: Not reported

Release Type:
Release Type: chemical
Other Release: Not reported

Waterbody:
Waterbody: Other
Other Waterbody: none

Name: Not reported
Address: 123 SCHOOL STREET
City,State,Zip: EAST HARTFORD, CT
Year of Database: 2016
Case Number: 201601273
Who Took Spill: 205
Assigned To: No Response
Report Date: 03/11/2016
Report Time: 12:00:00 AM
Date Release: 03/11/2016
Release Time: 12:00:00 AM
Reported By: dispatch
Phone: 860 5284401
Qty: < 2.00 (Gallons)
Telephone: Not reported
Representing: ehfd
Facility Status: CLOSED
Continuous Spill: False
Release Substance: GASOLINE
Emergency Measure: speedi dry
Discharger: unknown
Waterbody Affected: Other (none)
Responsible Party: true
Responsible Party Address: Not reported
RP City,St,Zip: CT
Terminated: YES
Recovered Total: 0
Total Water: 0
Historic: False
Waterbody: n/a
User Stamp: Guzmanca
Stamp Time: 2016-03-11 16:20:19
SR Inspector: Cox, Michael
AT Inspector: **NO RESPONSE
Corrective Action Taken: Contained
Cause Info: OVERFILL
Media Info: Ground Surface
Release Type: petroleum
Incident Description: Not reported
Cost Recovery Case?: Not reported
DEMHS Region: Not reported
Lat/Long: Not reported
Company Name: Not reported

SHELL SERVICE STATION (Continued) **S109738934**

Last Updated: Not reported

Action:
Action: Contained
Other Action: Not reported

Agency:
Agency ID: DEP Dispatch
Other Agency: Not reported
DEP Bureau: Not reported
DEP Agency: Not reported

Agency ID: LOCAL FIRE DEPARTMENT
Other Agency: Not reported
DEP Bureau: Not reported
DEP Agency: Not reported

Cause:
Cause ID: Overfill
Other Cause: Not reported

Media:
Media ID: Ground Surface
Other Media: Not reported

Release Class:
Class ID: Transportation
Other Class: Not reported

Class ID: Private
Other Class: Not reported

Release Type:
Release Type: petroleum
Other Release: Not reported

Waterbody:
Waterbody: Other
Other Waterbody: none

CPCS:
Name: Shell Service Station (Former Shell #136303)
Address: 123 SCHOOL STREET
City,State,Zip: EAST HARTFORD, CT
Site Type: Not reported
Lust Status code: Not reported
Lust Status: Not reported
PTP Form: Not reported
Program: LUST
Comments: Not reported
Site Type Definition: Not reported

SHELL SERVICE STATION (Continued) **S109738934**

Invesigation Start: Yes
Invesigation Start Date: Not reported
Remediation Start: Yes
Remediation Start Date: Not reported
Remediation Completed: Yes
ELUR: Not reported
Date Data Updated: 06/06/2009

ENFORCEMENT:
Name: SHELL SERVICE STATION
Address: 123 SCHOOL ST
City,State,Zip: EAST HARTFORD, CT 06108
Enforcement Action ID: NOVUST-MC221-0021
Enforcement Type Code: Field Notice of Violation
Program Id: Not reported
Enforcement Action Date: 05/05/2021
Penalty Amount: $0.00
Sep Amt: Not reported
Bureau Name: Materials Management & Compliance Assurance
Program: Underground Storage Tank Enforcement
Status: Closed
Date of Discovery: 05/05/2021
Resolution Date: 05/28/2021
Resolution Type: Closed-Compliance Statement not submitted
Staff: McShea Kelly
ENF Action Comment: The fill cover was broken or missing and must be repaired or replaced.
Number Violations: 1
Civil Penalty: Not reported
SEP Description: Not reported
Associated EIs: Underground Storage Tank Notification (43-5233)
Client Affiliation Type: Respondent
Affiliation Name: 123 SCHOOL STREET, L.L.C.
Affiliation Address Line1: PO BOX 4151
Affiliation Address Line2: Not reported
Affiliation City/State/Zip: KEY WEST, FL 33041 4151
Contact Title: Not reported
Contact Name: Not reported
Contact EMail: Not reported

CT MANIFEST:
Name: SHELL STATION
Address: 123 SCHOOL ST
City,State,Zip: EAST HARTFORD, CT 06108
Phone: Not reported
Country: Not reported
Manifest ID: CTC0215974
EPA ID: CTP000009606

Hazardous Waste Manifest:
Year: 1989
Manifest: CTC0215974
EPA ID: CTP000009606
Generator Mailing Address: 123 SCHOOL ST
Generator City,State,Zip: EAST HARTFORD, CT 06108
Discrepancies: N
Date Shipped: 1989-06-27

SHELL SERVICE STATION (Continued) **S109738934**

Date Received:	1989-06-27
Transporter 2 Date:	Not reported
TSDF EPA ID:	CTD021816889
TSDF Name:	UNITED OIL RECOVERY INC
TSDF Address:	136 GRACEY AVE
TSDF City,State,Zip:	MERIDEN, CT 06450
TSDF Country:	USA
Transporter EPA ID:	CTD004533063
Transporter Name:	KESSLER INSTALLATION CORP
Transporter Address:	Not reported
Transporter City,State,Zip:	CT
Transporter Country:	USA
Transporter 2 EPA ID:	Not reported
Transporter 2 Name:	Not reported
Transporter 2 Address:	Not reported
Transporter 2 City,State,Zip:	CT
Transporter 2 Country:	USA
US DOT Description:	FLAMMABLE LIQUID NOS
Number of Containers:	005
Container Type:	DM
Quantity/Weight/Volume:	225/G
Batch Number:	999999
EPA Waste Codes:	D001 - IGNITABLE WASTE
Copies:	1
Alternate Facility Name:	Not reported
Alternate Facility Address:	Not reported
Alternate Facility State:	Not reported
Alternate Facility Date:	Not reported

H58 **SHELL SERVICE STATION (FORMER SHELL #136303)** **UST FINDER RELEASE** **1029105743**
NW **123 SCHOOL STREET** **N/A**
1/4-1/2 **EAST HARTFORD, CT 0**
0.390 mi.
2057 ft. **Site 3 of 3 in cluster H**

Relative: **Lower**
Actual: **48 ft.**

UST FINDER RELEASE:

Object ID:	85369
Facility ID:	Not reported
Lust ID:	CT48752
Name:	SHELL SERVICE STATION (FORMER SHELL #136303)
Address:	123 SCHOOL STREET
City,State,Zip:	EAST HARTFORD, CT 0
Address Match Type:	PointAddress
Reported Date:	2009/06/06 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	1302
Domestic Wells within 1500ft:	2
Land Use:	Developed, Medium Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported

SHELL SERVICE STATION (FORMER SHELL #136303) (Continued) **1029105743**

WHPA HUC12:	Not reported
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	1
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	Geocode
X Coord:	-72.61268
Y Coord:	41.7831600000001
Latitude:	41.78316
Longitude:	-72.6126799999999

59
WNW
1/4-1/2
0.394 mi.
2079 ft.

STANDARD WELDING **CT SDADB** **S104253721**
470 TOLLAND STREET **N/A**
EAST HARTFORD, CT

Relative:
Lower

Actual:
52 ft.

Site Discovery and Assessment:

Facility ID:	1825
Rem Master ID:	2139
PTP Id:	Not reported
WPC Number:	Not reported
Postal District:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Determined By:	Not reported
Ground Water Quality Classification:	Not reported
Surface Water Quality Classification:	Not reported
Waste Type:	HYDRO/OIL, PCB'S, NCHLR VOC
Disposal:	SPILL/DUMP
Sample Data Available:	False
Updated By:	POST, M.
Update Program:	CORE
Updated:	8/4/1994
Date Created:	Not reported
Duplicate:	False

SDA Federal:

EPA CERCLIS Id:	Not reported
Number EPA RCRIS Id:	Not reported
Site on EPA's CERCLIS:	Not reported
Site Archived from CERCLIS:	Not reported
Archive Date:	Not reported
EPA's Removal at Site:	Not reported
Deferred to another EPA Program:	Not reported
EPA Env Priority Initiative Site:	Not reported
Federal Facility:	Not reported
Site on EPA's National Priority List:	Not reported
Part of an NPL site:	Not reported
RCRA Generator Status:	Not reported
RCRA Permit Status:	Not reported

SDA Referral:

Referral Id:	1689
Source of referral:	REMEDIAL

STANDARD WELDING (Continued) **S104253721**

Date Received:	8/4/1994
Staff Assigned:	Not reported
Remediation Program:	Not reported
Date dt_assigned:	Not reported
Remediation Complete Approved DEP/Verified by LEP:	Not reported
Outcome:	Not reported

SDA Remedial:

Remedial Id:	Not reported
PTP Id:	Not reported
Remediation Program:	Not reported
Remediation Program Entered:	Not reported
Staff Assigned:	Not reported
Remediation Program:	Not reported
Date dt_assign:	Not reported
Project Phase:	Not reported
Order issued:	Not reported
Order Number:	Not reported
Date order issued:	Not reported
Remedial Investigation Start:	Not reported
Remedial Investigation Completed:	Not reported
Remedial Design Start:	Not reported
Remedial Design complet:	Not reported
Remedial Action Start:	Not reported
Remedial Action Completed:	Not reported
Date Oper/ maintenance Started:	Not reported
GW monitoring:	Not reported
Remediation complete Approved DEP/Verified by LEP:	Not reported

SDA Orders:

Order Id:	Not reported
Order Number:	Not reported
Date order issued:	Not reported
Staff Assigned:	Not reported
Type of Order:	Not reported
Order Respondent:	Not reported
Admin Appeal Date:	Not reported
Date of Admin Appeal Ruling:	Not reported
Date of Admin Appeal Ruling:	Not reported
Date of Final Order:	Not reported
Date of Court Appeal:	Not reported
Date of Court Ruling:	Not reported
Date of Court Ruling:	Not reported
Date Order Modified:	Not reported
Date Referred to AG:	Not reported
Judgement:	Not reported
Date of AGR judgement:	Not reported
Penalty assessed:	Not reported
Order Complete:	Not reported
In compliance:	Not reported
Comments:	Not reported

SDADB:

SDA Waste:

Waste Id:	11
Waste Type:	HYDRO/OIL
Description:	Hydrocarbons and/or Fuel Oil

I60 **LTV STEEL CO., INC.** **CT CPCS** **S104942821**
NW **164 SCHOOL STREET** **N/A**
1/4-1/2 **EAST HARTFORD, CT 06108**
0.406 mi.
2145 ft. **Site 1 of 4 in cluster I**

Relative:
Lower

Actual:
53 ft.

CPCS:

Name:	Ltv Steel Co., Inc.
Address:	164 SCHOOL STREET
City,State,Zip:	EAST HARTFORD, CT 06108
Site Type:	Not reported
Lust Status code:	Not reported
Lust Status:	Not reported
PTP Form:	III
Program:	Property Transfer Program
Comments:	Projects
Site Type Definition:	Property Transfer Form III
Invesigation Start:	Not reported
Invesigation Start Date:	02/21/1989
Remediation Start:	Not reported
Remediation Start Date:	Not reported
Remediation Completed:	No
ELUR:	Yes
Date Data Updated:	Not reported

Name:	Ltv Steel
Address:	164 SCHOOL STREET
City,State,Zip:	EAST HARTFORD, CT
Site Type:	Not reported
Lust Status code:	Not reported
Lust Status:	Not reported
PTP Form:	Not reported
Program:	Urban Site Remediation Program
Comments:	Not reported
Site Type Definition:	Not reported
Invesigation Start:	Not reported
Invesigation Start Date:	Not reported
Remediation Start:	Not reported
Remediation Start Date:	Not reported
Remediation Completed:	No
ELUR:	No
Date Data Updated:	Not reported

Name:	Ltv Steel
Address:	164 SCHOOL STREET
City,State,Zip:	EAST HARTFORD, CT
Site Type:	Not reported
Lust Status code:	Not reported
Lust Status:	Not reported
PTP Form:	Not reported
Program:	State Remediation Program
Comments:	Not reported
Site Type Definition:	Not reported
Invesigation Start:	Not reported
Invesigation Start Date:	Not reported
Remediation Start:	Not reported
Remediation Start Date:	Not reported
Remediation Completed:	No
ELUR:	No

LTV STEEL CO., INC. (Continued) **S104942821**

Date Data Updated: Not reported

I61 **UNITED STEEL INC.** **SEMS-ARCHIVE** **1015733064**
NW **164 164 SCHOOL STREET** **RCRA NonGen / NLR** **CTD001159490**
1/4-1/2 **EAST HARTFORD, CT 06108** **E MANIFEST**
0.406 mi. **RI MANIFEST**
2145 ft. **Site 2 of 4 in cluster I** **NY MANIFEST**

Relative: **Lower**
Actual: **53 ft.**

SEMS Archive:

Site ID:	0100050
EPA ID:	CTD001159490
Name:	REPUBLIC STEEL, UNION DRAWN DIVISION
Address:	164 SCHOOL STREET
Address 2:	Not reported
City,State,Zip:	EAST HARTFORD, CT 06108
Cong District:	01
FIPS Code:	09003
FF:	N
NPL:	Not on the NPL
Non NPL Status:	NFRAP-Site does not qualify for the NPL based on existing information

SEMS Archive Detail:

Region:	01
Site ID:	0100050
EPA ID:	CTD001159490
Site Name:	REPUBLIC STEEL, UNION DRAWN DIVISION
NPL:	N
FF:	N
OU:	00
Action Code:	PA
Action Name:	PA
SEQ:	1
Start Date:	Not reported
Finish Date:	1987-09-24 04:00:00
Qual:	L
Current Action Lead:	EPA Perf

Region:	01
Site ID:	0100050
EPA ID:	CTD001159490
Site Name:	REPUBLIC STEEL, UNION DRAWN DIVISION
NPL:	N
FF:	N
OU:	00
Action Code:	DS
Action Name:	DISCVRY
SEQ:	1
Start Date:	1983-12-20 05:00:00
Finish Date:	1983-12-20 05:00:00
Qual:	Not reported
Current Action Lead:	St Perf

Region:	01
Site ID:	0100050
EPA ID:	CTD001159490
Site Name:	REPUBLIC STEEL, UNION DRAWN DIVISION
NPL:	N
FF:	N

UNITED STEEL INC. (Continued) **1015733064**

OU: 00
Action Code: SI
Action Name: SI
SEQ: 1
Start Date: Not reported
Finish Date: 1991-10-10 04:00:00
Qual: N
Current Action Lead: EPA Perf

Region: 01
Site ID: 0100050
EPA ID: CTD001159490
Site Name: REPUBLIC STEEL, UNION DRAWN DIVISION
NPL: N
FF: N
OU: 00
Action Code: VS
Action Name: ARCH SITE
SEQ: 1
Start Date: Not reported
Finish Date: 1996-09-09 04:00:00
Qual: Not reported
Current Action Lead: EPA Perf In-Hse

RCRA Listings:

Date Form Received by Agency:	19800818
Handler Name:	Republic Stl Union Drown Div E Hartford
Handler Address:	School St
Handler City,State,Zip:	EAST HARTFORD, CT 06108
EPA ID:	CTD001159490
Contact Name:	J-B SAYRE
Contact Address:	PO BOX 151
Contact City,State,Zip:	EAST HARTFORD, CT 06108
Contact Telephone:	203-568-3130
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	01
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	PO BOX 151
Mailing City,State,Zip:	EAST HARTFORD, CT 06108
Owner Name: Republic Steel Corporation	
Owner Type:	Private
Operator Name: Not reported	
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No

UNITED STEEL INC. (Continued) **1015733064**

Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	REPUBLIC STEEL CORPORATION
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	OWNERSTREET
Owner/Operator City,State,Zip:	OWNERCITY, CT 99999
Owner/Operator Telephone:	203-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

UNITED STEEL INC. (Continued) **1015733064**

Historic Generators:
Receive Date: 19800818
Handler Name: REPUBLIC STL UNION DROWN DIV E HARTFORD
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 331111
NAICS Description: Iron And Steel Mills

Has the Facility Received Notices of Violations:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

UNITED STEEL INC. (Continued) **1015733064**

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - General
Date Violation was Determined:	19861113
Actual Return to Compliance Date:	19861113
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - General
Date Violation was Determined:	19861113
Actual Return to Compliance Date:	19861113
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported

UNITED STEEL INC. (Continued) **1015733064**

Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 19861113
Evaluation Responsible Agency: State
Found Violation: No
Evaluation Type Description: FOCUSED COMPLIANCE INSPECTION
Evaluation Responsible Person Identifier: Not reported
Evaluation Responsible Sub-Organization: Not reported
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 19861113
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: FOCUSED COMPLIANCE INSPECTION
Evaluation Responsible Person Identifier: Not reported
Evaluation Responsible Sub-Organization: Not reported
Actual Return to Compliance Date: 19861113
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 19861113
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: FOCUSED COMPLIANCE INSPECTION
Evaluation Responsible Person Identifier: Not reported
Evaluation Responsible Sub-Organization: Not reported
Actual Return to Compliance Date: 19861113
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported

UNITED STEEL INC. (Continued) **1015733064**

Former Citation: Not reported

E MANIFEST:

Manifest Tracking Number:	007630058SKS
Last Updated Date:	20200602
Shipped Date:	20200512
Received Date:	20200512
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CVS024248900
Generator Name:	United Steel
Generator Location Street Number:	Not reported
Generator Location Street 1:	164 SCHOOL ST
Generator Location Street 2:	Not reported
Generator Location City:	EAST HARTFORD
Generator Location State:	CT
Generator Location Zip:	06108
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	164 School St
Generator Mail Street 2:	Not reported
Generator Mail City:	East Hartford
Generator Mail Zip:	06108
Generator Mail State:	CT
Generator Contact Company Name:	United Steel
Designated Facility EPA ID:	MAD096287354
Designated Facility Name:	Safety-Kleen Systems, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	224 E. Main Street
Designated Facility Mail City:	West Brookfield
Designated Facility Mail Zip:	01585
Designated Facility Mail State:	MA
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	224 E. Main Street
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	West Brookfield
Designated Facility Location Zip:	01585
Designated Facility Location State:	MA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	007754463SKS
Last Updated Date:	20210409
Shipped Date:	20210319
Received Date:	20210319
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CVS024248900
Generator Name:	United Steel
Generator Location Street Number:	Not reported
Generator Location Street 1:	164 SCHOOL ST
Generator Location Street 2:	Not reported
Generator Location City:	EAST HARTFORD

UNITED STEEL INC. (Continued) **1015733064**

Generator Location State:	CT
Generator Location Zip:	06108
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	164 School St
Generator Mail Street 2:	Not reported
Generator Mail City:	East Hartford
Generator Mail Zip:	06108
Generator Mail State:	CT
Generator Contact Company Name:	United Steel
Designated Facility EPA ID:	MAD096287354
Designated Facility Name:	Safety-Kleen Systems, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	224 E. Main Street
Designated Facility Mail City:	West Brookfield
Designated Facility Mail Zip:	01585
Designated Facility Mail State:	MA
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	224 E. Main Street
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	West Brookfield
Designated Facility Location Zip:	01585
Designated Facility Location State:	MA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	009270213SKS
Last Updated Date:	20241202
Shipped Date:	20241107
Received Date:	20241107
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CVS024248900
Generator Name:	United Steel
Generator Location Street Number:	Not reported
Generator Location Street 1:	164 SCHOOL ST
Generator Location Street 2:	Not reported
Generator Location City:	EAST HARTFORD
Generator Location State:	CT
Generator Location Zip:	06108
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	164 SCHOOL ST
Generator Mail Street 2:	Not reported
Generator Mail City:	EAST HARTFORD
Generator Mail Zip:	06108
Generator Mail State:	CT
Generator Contact Company Name:	UNITED STEEL
Designated Facility EPA ID:	MAD096287354
Designated Facility Name:	Safety-Kleen Systems, Inc.
Designated Facility Mail Street Number:	224
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	E. MAIN STREET
Designated Facility Mail City:	WEST BROOKFIELD
Designated Facility Mail Zip:	01585
Designated Facility Mail State:	MA

UNITED STEEL INC. (Continued) **1015733064**

Designated Facility Location Street Number:	224
Designated Facility Location Street 1:	E. MAIN STREET
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	WEST BROOKFIELD
Designated Facility Location Zip:	01585
Designated Facility Location State:	MA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	008194055SKS
Last Updated Date:	20220217
Shipped Date:	20220127
Received Date:	20220127
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CVS024248900
Generator Name:	United Steel
Generator Location Street Number:	Not reported
Generator Location Street 1:	164 SCHOOL ST
Generator Location Street 2:	Not reported
Generator Location City:	EAST HARTFORD
Generator Location State:	CT
Generator Location Zip:	06108
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	164 School St
Generator Mail Street 2:	Not reported
Generator Mail City:	East Hartford
Generator Mail Zip:	06108
Generator Mail State:	CT
Generator Contact Company Name:	United Steel
Designated Facility EPA ID:	MAD096287354
Designated Facility Name:	Safety-Kleen Systems, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	224 E. Main Street
Designated Facility Mail City:	West Brookfield
Designated Facility Mail Zip:	01585
Designated Facility Mail State:	MA
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	224 E. Main Street
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	West Brookfield
Designated Facility Location Zip:	01585
Designated Facility Location State:	MA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	008669128SKS
Last Updated Date:	20230112
Shipped Date:	20221222
Received Date:	20221222
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service

UNITED STEEL INC. (Continued) **1015733064**

Generator EPA ID:	CVS024248900
Generator Name:	United Steel
Generator Location Street Number:	Not reported
Generator Location Street 1:	164 SCHOOL ST
Generator Location Street 2:	Not reported
Generator Location City:	EAST HARTFORD
Generator Location State:	CT
Generator Location Zip:	06108
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	164 School St
Generator Mail Street 2:	Not reported
Generator Mail City:	East Hartford
Generator Mail Zip:	06108
Generator Mail State:	CT
Generator Contact Company Name:	United Steel
Designated Facility EPA ID:	MAD096287354
Designated Facility Name:	Safety-Kleen Systems, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	224 E. Main Street
Designated Facility Mail City:	West Brookfield
Designated Facility Mail Zip:	01585
Designated Facility Mail State:	MA
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	224 E. Main Street
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	West Brookfield
Designated Facility Location Zip:	01585
Designated Facility Location State:	MA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	022551827JJK
Last Updated Date:	20220126
Shipped Date:	20211129
Received Date:	20211202
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CTD001159490
Generator Name:	United Steel Inc.
Generator Location Street Number:	164
Generator Location Street 1:	164 164 SCHOOL STREET
Generator Location Street 2:	Not reported
Generator Location City:	EAST HARTFORD
Generator Location State:	CT
Generator Location Zip:	06108
Generator Mail Street Number:	164
Generator Mail Street 1:	164 SCHOOL STREET
Generator Mail Street 2:	Not reported
Generator Mail City:	EAST HARTFORD
Generator Mail Zip:	06108
Generator Mail State:	CT
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	IND000646943
Designated Facility Name:	Tradebe Treatment And Recycling Llc

UNITED STEEL INC. (Continued) **1015733064**

Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	4343 KENNEDY AVE
Designated Facility Mail City:	EAST CHICAGO
Designated Facility Mail Zip:	46312
Designated Facility Mail State:	IN
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	4343 KENNEDY AVENUE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	EAST CHICAGO
Designated Facility Location Zip:	46312
Designated Facility Location State:	IN
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	008919697SKS
Last Updated Date:	20231025
Shipped Date:	20231005
Received Date:	20231005
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CVS024248900
Generator Name:	United Steel
Generator Location Street Number:	Not reported
Generator Location Street 1:	164 SCHOOL ST
Generator Location Street 2:	Not reported
Generator Location City:	EAST HARTFORD
Generator Location State:	CT
Generator Location Zip:	06108
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	164 School St
Generator Mail Street 2:	Not reported
Generator Mail City:	East Hartford
Generator Mail Zip:	06108
Generator Mail State:	CT
Generator Contact Company Name:	United Steel
Designated Facility EPA ID:	MAD096287354
Designated Facility Name:	Safety-Kleen Systems, Inc.
Designated Facility Mail Street Number:	224
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	E. Main Street
Designated Facility Mail City:	West Brookfield
Designated Facility Mail Zip:	01585
Designated Facility Mail State:	MA
Designated Facility Location Street Number:	224
Designated Facility Location Street 1:	E. Main Street
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	West Brookfield
Designated Facility Location Zip:	01585
Designated Facility Location State:	MA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	008944036SKS

UNITED STEEL INC. (Continued) **1015733064**

Last Updated Date:	20240222
Shipped Date:	20240126
Received Date:	20240126
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CVS024248900
Generator Name:	United Steel
Generator Location Street Number:	Not reported
Generator Location Street 1:	164 SCHOOL ST
Generator Location Street 2:	Not reported
Generator Location City:	EAST HARTFORD
Generator Location State:	CT
Generator Location Zip:	06108
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	164 School St
Generator Mail Street 2:	Not reported
Generator Mail City:	East Hartford
Generator Mail Zip:	06108
Generator Mail State:	CT
Generator Contact Company Name:	United Steel
Designated Facility EPA ID:	MAD096287354
Designated Facility Name:	Safety-Kleen Systems, Inc.
Designated Facility Mail Street Number:	224
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	E. Main Street
Designated Facility Mail City:	West Brookfield
Designated Facility Mail Zip:	01585
Designated Facility Mail State:	MA
Designated Facility Location Street Number:	224
Designated Facility Location Street 1:	E. Main Street
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	West Brookfield
Designated Facility Location Zip:	01585
Designated Facility Location State:	MA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	008946125SKS
Last Updated Date:	20231229
Shipped Date:	20231201
Received Date:	20231201
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CVS024248900
Generator Name:	United Steel
Generator Location Street Number:	Not reported
Generator Location Street 1:	164 SCHOOL ST
Generator Location Street 2:	Not reported
Generator Location City:	EAST HARTFORD
Generator Location State:	CT
Generator Location Zip:	06108
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	164 School St
Generator Mail Street 2:	Not reported

UNITED STEEL INC. (Continued) **1015733064**

Generator Mail City:	East Hartford
Generator Mail Zip:	06108
Generator Mail State:	CT
Generator Contact Company Name:	United Steel
Designated Facility EPA ID:	MAD096287354
Designated Facility Name:	Safety-Kleen Systems, Inc.
Designated Facility Mail Street Number:	224
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	E. Main Street
Designated Facility Mail City:	West Brookfield
Designated Facility Mail Zip:	01585
Designated Facility Mail State:	MA
Designated Facility Location Street Number:	224
Designated Facility Location Street 1:	E. Main Street
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	West Brookfield
Designated Facility Location Zip:	01585
Designated Facility Location State:	MA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	007691634SKS
Last Updated Date:	20200803
Shipped Date:	20200713
Received Date:	20200713
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CVS024248900
Generator Name:	United Steel
Generator Location Street Number:	Not reported
Generator Location Street 1:	164 SCHOOL ST
Generator Location Street 2:	Not reported
Generator Location City:	EAST HARTFORD
Generator Location State:	CT
Generator Location Zip:	06108
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	164 School St
Generator Mail Street 2:	Not reported
Generator Mail City:	East Hartford
Generator Mail Zip:	06108
Generator Mail State:	CT
Generator Contact Company Name:	United Steel
Designated Facility EPA ID:	MAD096287354
Designated Facility Name:	Safety-Kleen Systems, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	224 E. Main Street
Designated Facility Mail City:	West Brookfield
Designated Facility Mail Zip:	01585
Designated Facility Mail State:	MA
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	224 E. Main Street
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	West Brookfield
Designated Facility Location Zip:	01585

UNITED STEEL INC. (Continued) **1015733064**

Designated Facility Location State:	MA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	009237749SKS
Last Updated Date:	20240801
Shipped Date:	20240712
Received Date:	20240712
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CVS024248900
Generator Name:	United Steel
Generator Location Street Number:	Not reported
Generator Location Street 1:	164 SCHOOL ST
Generator Location Street 2:	Not reported
Generator Location City:	EAST HARTFORD
Generator Location State:	CT
Generator Location Zip:	06108
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	164 SCHOOL ST
Generator Mail Street 2:	Not reported
Generator Mail City:	EAST HARTFORD
Generator Mail Zip:	06108
Generator Mail State:	CT
Generator Contact Company Name:	UNITED STEEL
Designated Facility EPA ID:	MAD096287354
Designated Facility Name:	Safety-Kleen Systems, Inc.
Designated Facility Mail Street Number:	224
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	E. MAIN STREET
Designated Facility Mail City:	WEST BROOKFIELD
Designated Facility Mail Zip:	01585
Designated Facility Mail State:	MA
Designated Facility Location Street Number:	224
Designated Facility Location Street 1:	E. MAIN STREET
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	WEST BROOKFIELD
Designated Facility Location Zip:	01585
Designated Facility Location State:	MA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Rejection:

Manifest Tracking Number:	018254924JJK
Rejection Type Indicator:	FullReject
Rejection Transporter On-site Indicator:	N
Alternate Destination Facility Type:	Not reported
Alternate Designated Facility EPA ID:	Not reported
Alternate Designated Facility Name:	Not reported
Alternate Designated Facility Mail Street Number:	Not reported
Alternate Designated Facility Mail Street 1:	Not reported
Alternate Designated Facility Mail Street 2:	Not reported
Alternate Designated Facility Mail City:	Not reported
Alternate Designated Facility Mail Zip:	Not reported

UNITED STEEL INC. (Continued) **1015733064**

Alternate Designated Facility Mail State: Not reported
Alternate Designated Facility Location Street Number: Not reported
Alternate Designated Facility Location Street 1: Not reported
Alternate Designated Facility Location Street 2: Not reported
Alternate Designated Facility Location City: Not reported
Alternate Designated Facility Location Zip: Not reported
Alternate Designated Facility Location State: Not reported
Alternate Designated Facility Contact Company Name: Not reported

Transporter:
Manifest Tracking Number: 018254924JJK
Transporter Line Number: 1
Transporter EPA ID: CTD021816889
Transporter Name: Tradebe Transportation, Llc

Waste Line:
Manifest Tracking Number: 018254924JJK
Waste Line Number: 1
U.S. DOT Hazardous Indicator: Y
U.S. DOT ID Number: UN1263
U.S. DOT Description: Un1263 Waste Paint Related Material (Ethyl Benzene,Xylene) 3 Ii Rq
Non-Hazardous Waste Description: Not reported
Number of Containers: 1
Container Type Code: DM
Container Type Description: Metal drums, barrels, kegs
Waste Quantity: 55
Quantity Unit of Measure Code: G
Quantity Unit of Measure Description: Gallons
Waste Quantity, in Tons: 0.2293578
Acute Waste Quantity, in Tons: 0
Non-Acute Waste Quantity, in Tons: 0.2293578
Waste Quantity, in Kilograms: 208.03441
Acute Waste Quantity, in Kilograms: 0
Non-Acute Waste Quantity, in Kilorgrams: 208.03441
Management Method Code: H141
Management Method Description: STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator: N
Quantity Discrepancy Indicator: N
Waste Type Discrepancy Indicator: N
Waste Density: Not reported
Waste Density Unit of Measure Code: Not reported
Waste Density Unit of Measure Description: Not reported
Form Code: Not reported
Form Code Description: Not reported
Source Code: Not reported
Source Code Description: Not reported
Waste Minimization Code: Not reported
Waste Minimization Code Description: Not reported
Consent Number: Not reported
EPA Waste Indicator: Y
Federal Waste Codes: D001, F003
Quantity Haz Kg: 208.03441
Quantity Haz Tons: 0.2293578
Quantity Non Haz Kg: 0
Quantity Non Haz Tons: 0
State Waste Codes: Not reported

UNITED STEEL INC. (Continued) **1015733064**

Click this hyperlink while viewing on your computer to access
46 additional US EManifest: record(s) in the EDR Site Report.

RI MANIFEST:

Name:	LTV STEEL
Address:	164 SCHOOL ST
City,State,Zip:	EAST HARTFORD, CT 06108
EPA Id:	CTD001159490
GEN Cert Date:	1/27/1988
Manifest Document Number:	CTC0134204
Waste Description:	CLEANING DETERGENT
TSDF Id:	RID991302407
TSDF Name:	IDI
Qty:	850
WT/Vol Units:	G
TSDF Date:	Not reported
Transporter 2 Id:	Not reported
Item Number:	1
Transporter 2 Name:	Not reported
Transporter Name 2:	TRI-S
Transporter EPAID:	CTD000636498
Transporter Receipt Date:	Not reported
Number Of Containers:	0
Container Type:	Not reported
Waste Code1:	CR04
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Fee Exempt Code:	Not reported
Comment:	Not reported
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
Quarter:	Not reported
Transporter Contact Name:	Not reported
Transporter Contact Email:	Not reported
Filing Date:	Not reported
Total Fee:	Not reported
Billing Name:	Not reported
Paid Date:	Not reported
Paid Time:	Not reported
Facility Receipt Date:	Not reported
Fee:	Not reported
Manifest Created Date:	Not reported
Manifest Updated Date:	Not reported

RI MANIFEST:

Transporter Receipt Date:	Not reported
Number Of Containers:	0
Container Type:	Not reported
Waste Code1:	CR04
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported

UNITED STEEL INC. (Continued) **1015733064**

Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	IDI
TSDF Id:	RID991302407
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	CTD001159490
Manifest Docket Number:	CTC0162227
Quarter:	Not reported
Waste Description:	CLEAN DETERGENT
Transporter Contact Name:	Not reported
Quantity:	110
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	TRI-S
Billing Name:	Not reported
Transporter EPA ID:	CTD000636498
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	3/22/1988
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	Not reported
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported
Transporter Receipt Date:	Not reported
Number Of Containers:	0
Container Type:	Not reported
Waste Code1:	CR04
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	IDI
TSDF Id:	RID991302407
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	CTD001159490
Manifest Docket Number:	CTC0162227
Quarter:	Not reported
Waste Description:	CLEAN DETERGENT
Transporter Contact Name:	Not reported
Quantity:	110
Transporter Contact Email:	Not reported
WT/Vol Units:	G

UNITED STEEL INC. (Continued) **1015733064**

Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	TRI-S
Billing Name:	Not reported
Transporter EPA ID:	CTD000636498
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	3/22/1988
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	Not reported
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported
Transporter Receipt Date:	Not reported
Number Of Containers:	0
Container Type:	Not reported
Waste Code1:	CR05
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	IDI
TSDF Id:	RID991302407
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	CTD001159490
Manifest Docket Number:	CTC0134204
Quarter:	Not reported
Waste Description:	DIRT/PCBS
Transporter Contact Name:	Not reported
Quantity:	5400
Transporter Contact Email:	Not reported
WT/Vol Units:	P
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	2
Transporter Name:	TRI-S
Billing Name:	Not reported
Transporter EPA ID:	CTD000636498
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	1/27/1988
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	Not reported
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported

UNITED STEEL INC. (Continued) **1015733064**

Transporter Receipt Date:	Not reported
Number Of Containers:	0
Container Type:	Not reported
Waste Code1:	CR05
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	IDI
TSDF Id:	RID991302407
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	CTD001159490
Manifest Docket Number:	CTC0134204
Quarter:	Not reported
Waste Description:	DIRT/PCBS
Transporter Contact Name:	Not reported
Quantity:	5400
Transporter Contact Email:	Not reported
WT/Vol Units:	P
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	2
Transporter Name:	TRI-S
Billing Name:	Not reported
Transporter EPA ID:	CTD000636498
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	1/27/1988
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	Not reported
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported

Transporter Receipt Date:	Not reported
Number Of Containers:	0
Container Type:	Not reported
Waste Code1:	CR04
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	IDI
TSDF Id:	RID991302407
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported

UNITED STEEL INC. (Continued) **1015733064**

EPA ID:	CTD001159490
Manifest Docket Number:	CTC0134204
Quarter:	Not reported
Waste Description:	CLEANING DETERGENT
Transporter Contact Name:	Not reported
Quantity:	850
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	TRI-S
Billing Name:	Not reported
Transporter EPA ID:	CTD000636498
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	1/27/1988
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	Not reported
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported
Transporter Receipt Date:	Not reported
Number Of Containers:	0
Container Type:	Not reported
Waste Code1:	CR04
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	IDI
TSDF Id:	RID991302407
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	CTD001159490
Manifest Docket Number:	CTC0134204
Quarter:	Not reported
Waste Description:	CLEANING DETERGENT
Transporter Contact Name:	Not reported
Quantity:	850
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	TRI-S
Billing Name:	Not reported
Transporter EPA ID:	CTD000636498
Date Paid:	Not reported
Time Paid:	Not reported

UNITED STEEL INC. (Continued) **1015733064**

GEN Cert Date:	1/27/1988
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	Not reported
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported

NY MANIFEST:

EPA ID:	CTD001159490
Country:	USA
Name:	Republic Stl Union Drown Div E Hartford
Address:	164 SCHOOL ST
Address 2:	Not reported
City,State,Zip:	EAST HARTFORD, CT 06108
Zip 4:	Not reported
Location Address 1:	164 SCHOOL ST
Location Address 2:	Not reported
Location City,State,Zip:	EAST HARTFORD, CT 06108
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Republic Stl Union Drown Div E Hartford
Mailing Contact:	Robert Bard
Mailing Address 1:	164 SCHOOL ST
Mailing Address 2:	Not reported
Mailing City,State,Zip:	EAST HARTFORD, CT 06108
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	8602892323

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	CTD021816889
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	11/03/2017
Trans1 Recv Date:	11/03/2017
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/07/2017
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	CTD001159490
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD080469935
TSDF ID 2:	Not reported
Manifest Tracking Number:	017047204JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N

UNITED STEEL INC. (Continued) **1015733064**

Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H050
Waste Code a:	Ignitable Waste
Waste Code b:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	15
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	CTD021816889
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	04/30/2013
Trans1 Recv Date:	04/30/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/08/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	CTD001159490
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD080469935
TSDF ID 2:	Not reported
Manifest Tracking Number:	011512076JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N

UNITED STEEL INC. (Continued) **1015733064**

Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H050
Waste Code a:	Ignitable Waste
Waste Code b:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	16
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	CTD021816889
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	06/28/2012
Trans1 Recv Date:	06/28/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/06/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	CTD001159490
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD080469935
TSDF ID 2:	Not reported
Manifest Tracking Number:	010412557JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

UNITED STEEL INC. (Continued) **1015733064**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H050
Waste Code a:	Ignitable Waste
Waste Code b:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	16
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	CTD021816889
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	02/27/2012
Trans1 Recv Date:	02/27/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/01/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	CTD001159490
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD080469935
TSDF ID 2:	Not reported
Manifest Tracking Number:	009522078JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N

UNITED STEEL INC. (Continued) **1015733064**

Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H050
Waste Code a:	Ignitable Waste
Waste Code b:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	15
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	CTD021816889
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	02/10/2016
Trans1 Recv Date:	02/10/2016
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/15/2016
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	CTD001159490
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD080469935
TSDF ID 2:	Not reported
Manifest Tracking Number:	015043186JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N

UNITED STEEL INC. (Continued) **1015733064**

Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H050
Waste Code a:	Ignitable Waste
Waste Code b:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	55
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	CTD021816889
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	02/10/2016
Trans1 Recv Date:	02/10/2016
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/15/2016
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	CTD001159490
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD080469935
TSDF ID 2:	Not reported
Manifest Tracking Number:	015043186JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

UNITED STEEL INC. (Continued) **1015733064**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H050
Waste Code a:	Ignitable Waste
Waste Code b:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	15
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	CTD021816889
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	07/31/2012
Trans1 Recv Date:	07/31/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/06/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	CTD001159490
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD080469935
TSDF ID 2:	Not reported
Manifest Tracking Number:	010412995JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

UNITED STEEL INC. (Continued) **1015733064**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H040
Waste Code a:	Ignitable Waste
Waste Code b:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	16
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	CTD021816889
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	11/30/2012
Trans1 Recv Date:	11/30/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/14/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	CTD001159490
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD080469935
TSDF ID 2:	Not reported
Manifest Tracking Number:	010747134JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported

UNITED STEEL INC. (Continued) **1015733064**

MGMT Method Type Code:	H050
Waste Code a:	Ignitable Waste
Waste Code b:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	16
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	CTD021816889
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	09/26/2017
Trans1 Recv Date:	09/26/2017
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/04/2017
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	CTD001159490
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD080469935
TSDF ID 2:	Not reported
Manifest Tracking Number:	017049190JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H050

UNITED STEEL INC. (Continued) **1015733064**

Waste Code a:	Ignitable Waste
Waste Code b:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	15
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	CTD021816889
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	04/24/2012
Trans1 Recv Date:	04/24/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/27/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	CTD001159490
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD080469935
TSDF ID 2:	Not reported
Manifest Tracking Number:	009955247JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H050
Waste Code a:	Ignitable Waste

UNITED STEEL INC. (Continued) **1015733064**

Waste Code b:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	16
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	CTD021816889
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	10/10/2012
Trans1 Recv Date:	10/10/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/15/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	CTD001159490
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD080469935
TSDF ID 2:	Not reported
Manifest Tracking Number:	010742018JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H050
Waste Code a:	Ignitable Waste
Waste Code b:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl

UNITED STEEL INC. (Continued) **1015733064**

Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	16
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1

Click this hyperlink while viewing on your computer to access
5 additional NY MANIFEST: record(s) in the EDR Site Report.

I62 **LTV STEEL CO., INC.** **CT AUL** **S109723606**
NW **164 SCHOOL STREET** **CT PROPERTY** **N/A**
1/4-1/2 **EAST HARTFORD, CT**
0.406 mi.
2145 ft. **Site 3 of 4 in cluster I**

Relative:
Lower

Actual:
53 ft.

CT AUL:

Name:	FORMER LTC STEEL SITE
Address:	164 SCHOOL STREET
City,State,Zip:	EAST HARTFORD, CT
Facility ID:	1640
Status:	Not reported
DEP Staff Assigned:	Amy Richardson
LEP Lead:	Not reported
LEP Program:	Not reported
Map Link:	Not reported
Date Release Exp Second:	Not reported
Date Release Exp Third:	Not reported

How did the ELUR change the use of the property:	Not reported
Date 1st Waiver Request Received:	Not reported
Date of DEP Comments On The 1st Waiver Request:	Not reported
Date Complete 1st Waiver Request Assembled:	Not reported
Date 2nd Waiver Request Received:	Not reported
Date of DEP Comments On The 2nd Waiver Request:	Not reported
Date Complete 2nd Waiver Request Assembled:	Not reported
Date 3rd Waiver Request Received:	Not reported
Date of DEP Comments On The 3rd Waiver Request:	Not reported
Date Complete 3rd Waiver Request Assembled:	Not reported

LTV STEEL CO., INC. (Continued) **S109723606**

Date of Approval of 3rd Waiver Request:	Not reported
Date 1st ELUR received for review:	2016-08-09
Date of DEP comments for 1st ELUR:	2018-03-02
Date Complete Package for 1st ELUR Assembled:	Not reported
Date 1st ELUR Approved by Commissioner:	Not reported
Date 1st ELUR Received by Grantor:	Not reported
Date 1st ELUR Executed by Grantor:	Not reported
Date 2nd ELUR Received for Review:	Not reported
Date of DEP comments for 2nd ELUR:	Not reported
Date Complete Package for 2nd ELUR Assembled:	Not reported
Date 2nd ELUR Approved by Commissioner:	Not reported
Date 2nd ELUR Received by Grantor:	Not reported
Date 2nd ELUR Executed by Grantor:	Not reported
Date 3rd ELUR Received For Review:	Not reported
Date of DEP Comments For Third ELUR:	Not reported
Date Complete Package For Third ELUR Assembled:	Not reported
Date Third Decision Document Approved by Commissioner:	Not reported
Date Third ELUR Received by Grantor:	Not reported
Date Third ELUR Executed by Grantor:	Not reported
Date 1st ELUR Recorded On The Land Records:	Not reported
Date 2nd ELUR Recorded On The Land Records:	Not reported
Date 3rd ELUR Recorded On The Land Records:	Not reported
Date 1st Certificate of Title Was Received:	Not reported
Date 2nd Certificate of Title Was Received:	Not reported
Date 3rd Certificate of Title Was Received:	Not reported
Date Request For 1st ELUR Release Request Received:	Not reported
Date of DEP Comments on the First ELUR Release Request:	Not reported
Date of Complete Application For 1st ELUR Release Assembled:	Not reported
Date Request For Second ELUR Release Request Received:	Not reported
Date of DEP comments on the 2nd ELUR Release Request:	Not reported
Date of Complete Application for 2nd ELUR Release Assembled:	Not reported
Date Request for Third ELUR Release Request Received:	Not reported
Date of DEP Comments on the third ELUR Release Request:	Not reported
Date of Complete Application for 3rd ELUR Release Assembled:	Not reported
Date of the 1st Release From the ELUR Approved:	Not reported
Date of the 2nd Release From the ELUR Approved:	Not reported
Date of the 3rd Release From the ELUR Approved:	Not reported
Was the 1st Release Recorded on the Land Records:	Not reported
Was the 2nd Release Recorded on the Land Records:	Not reported
Was the 3rd Release Recorded on the Land Records:	Not reported
Date the 1st Release Recorded on the Land Records:	Not reported
Date the 2nd Release Recorded on the Land Records:	Not reported
Date Request for 1st ELUR Restoration Request Received:	Not reported
Date of DEP comments on the 1st ELUR Restoration Request:	Not reported
Date the 1st ELUR Was Restored:	Not reported
Date Request For 2nd ELUR Restoration Request Received:	Not reported
Date of DEP Comments on the 2nd ELUR Restoration Request:	Not reported
Date the 2nd ELUR Restoration Request Was Complete:	Not reported
Date the 2nd ELUR was Restored:	Not reported
Date Request for 3rd ELUR Restoration Request Received:	Not reported
Date of DEP Comments on the 3rd ELUR Restoration Request:	Not reported
Date the 3rd ELUR Restoration Request Was Complete:	Not reported
Date the 3rd ELUR Was Restored:	Not reported
Was the 1st Restoration Recorded on the Land Records:	Not reported
Was the 2nd Restoration Recorded on the Land Records:	Not reported
Was the 3rd Restoration Recorded on the Land Records:	Not reported
Date the 1st Restoration Recorded on the Land Records:	Not reported

LTV STEEL CO., INC. (Continued) **S109723606**

Date the 2nd Restoration Recorded on the Land Records:	Not reported
Date the 3rd Restoration Recorded on the Land Records:	Not reported
Date of NOV:	Not reported
Date NOV in Compliance:	Not reported
Name of Contact Person for ELUR:	Not reported
Contact Firm:	Not reported
Contact Address:	Not reported
Contact City/State/Zip:	Not reported
Request For Waiver Of Subordination Agreement Status:	Not reported
Direct Exposure Inaccessible Soil 22a-133k-2 B 3:	False
Pollutant Mobility Criteria Environ Isola Soil 22a-133k-2 C 4 B:	False
Prevent Disturbance Of Engineered Control 22a-133k-2 F 2 B Iv:	Not reported
NOV Number:	Not reported
Reason for NOV:	Not reported
More Than One ELUR For Site:	Not reported
ELUR Covers All/Part Of Property?:	Not reported
Direct Exposure PCBs Industrial Use Only 22a-133k-2 B 2 B:	False
Use Ind Groundwater Volatilization Criteria 22a-133k-3 C 2:	False
Use Ind Soil Gas Volatilization Criteria 22a-133k-3 C 3 A:	False
Pot Gw Vol Criteria Exceed ELUR No Bldg Const 22a-133k-3 C 5 A:	False
Tech Impract Of GW Remediation 22a-133k-3 E 2 C:	False
ELUR Prior To Reqs:	Not reported
Submittal_ID:	2770
Status and Updated Title Search:	Department Comments Provided
Status Comment:	Admin Review: NOAD 9/15/16; NOAC 5/26/17.
Residential Activity - Clean water lense:	False
Inaccessible Soil and Residential Activity (PCBs):	False
Soil Polluted with Pesticides (Residential):	False
Soil Polluted with Pesticides (I/C):	False
Alternative Release-specific DEC:	False
WSPF (Commissioner):	False
WSPF (LEP Certified):	False
Engineered Control PMC (Commissioner):	False
Engineered Control DEC (Commissioner):	False
Engineered Control DEC (LEP Certified):	False
NAPL:	False
Alternative Release-specific VolC:	False
Alternative Method of Demonstrating Compliance VolC:	False
Vapor Mitigation:	False
Indoor Air Monitoring (VolC):	False
Groundwater Polluted with Pesticides:	False

CT Property:

Name:	LTV STEEL CO., INC.
Address:	164 SCHOOL STREET
City,state,zip:	EAST HARTFORD, CT
Seller Name:	LTV Steel Company, Inc
Buyer Name:	School Street Joint Vent
Certifying Party:	School Street Joint Venture
Certifying Attention Person:	Leonard Ginsberg
Title Of Certifying Person:	President
Certifying Person Address:	68 South Main Street
Certifying Person City,St,Zip:	West Hartford, CT 06107
Property Transfer Forms:	Form III (DEP-PERD-PTP-203) when a discharge, spillage, uncontrolled loss, seepage or filtration of hazardous waste has occurred at the parcel that has not been fully remediated or the environmental conditions at the parcel are unknown. The person signing the Form III

LTV STEEL CO., INC. (Continued) **S109723606**

	certification agrees to investigate and remediate the site in accordance with the remediation standards. The statute does not require completion of remediation before the parcel is transferred. Any person submitting a Form III shall simultaneously submit a completed Environmental Condition Assessment Form (ECAF)(DEP-PERD-PTP-200).
Date Recieved:	10/14/1988
Ackn Date:	02/21/1989
Determination Date:	Not reported
LEP Verified/DEP Approval Date:	Not reported
Rem Id:	1640
Remediation Location Id:	700
Date Entered:	Not reported
Program:	Property Transfer Program
GAO Site:	False
Staff Full Name:	Rob Robinson
Super/Date:	Not reported
Stage Of Project:	Not reported
RP Level Of Activity:	Not reported
RP Needed Level Of Activity:	Not reported
Staff Level Of Activity:	Not reported
Staff Needed Level Of Activity:	Not reported
Public Intrest:	Not reported
PRP Cooperation:	Not reported
Enforcement Status:	Not reported
Level Of Complexity:	Not reported
Complex Eng Or Sci:	False
Complex Due To Public Involvement:	False
Politically Complex:	False
Complex Enforcement:	False
Coordination With Other Bureaus:	False
EPA Involvement:	False
Staff Prefrence:	Not reported
Readiness For Transfer:	Not reported
Project Transfer Time:	Not reported
Transfer Comments:	Not reported
Staff As Of July 2000:	Not reported
Initial Staff:	TWR
Type Of Transfer:	Not reported
Salutation:	Mr. Ginsberg
Relationship To Transfer:	Not reported
Audit Date:	Not reported
Verif Type:	Not reported
Audit Outcome:	Not reported
GW:	GB
Basin:	Not reported
1st Payment:	900
Pay Tag1:	407644
2nd Payment:	Not reported
Pay Tag2:	Not reported
RTN:	11/25/1988
Revised:	Not reported
ECAF Received:	6/8/2018
Old Determination Date:	Not reported
Redeterminationdate:	Not reported
Previous Determination:	Not reported
Monitoringoption:	Not reported

LTV STEEL CO., INC. (Continued) **S109723606**

Postremedialmonitoring:	Not reported
Schedule Of I/R:	Not reported
Schedule Overdue:	Not reported
Aprvl Sched:	Not reported
Yr 1 Report:	Not reported
Yr 2 Report:	Not reported
Report Overdue:	Not reported
Ext Aprvl Sched:	Not reported
License #:	Not reported
Project Phase:	Not reported
PT Comments:	fee ltr sent 5/30/95 FEE & ECAF RCVD 6/8/2018 smt
EPA Id Number:	Not reported
GW Class:	Not reported
SW Class:	Not reported
AO/C0:	Not reported
Water Lead(Y Or N):	Not reported
Priority:	Not reported
Project Status(A, I Or D):	Not reported
Last Updated:	Not reported
SR Comments:	Not reported
Priority Or Work-Load:	Not reported
Status:	Not reported
Notes:	Not reported
Special Project Name:	Not reported
Special Project Comments:	Not reported
DOT Project:	Not reported
Pt Counter:	Not reported
Project Complete:	False
Project Inactive:	False
Int Deposit #:	Not reported
Deposit #:	Not reported
Spill Case #:	Not reported
Diversion Id:	Not reported
Public Notice:	Not reported
RAP Received:	Not reported
RAP Approved:	Not reported
Compliance Category:	Not reported
Delete Record:	False
ECAF Reviewed By:	Not reported
Not Locatable:	False
Primary Address:	False
AKA Site Name:	False
Primary Site Name:	False
AKA Site Address:	False
Lead:	LEP

I63 **UNITED STEEL** **CT SDADB** **1000424124**
NW **164 SCHOOL STREEET** **US BROWNFIELDS** **N/A**
1/4-1/2 **EAST HARTFORD, CT 06108** **ICIS**
0.406 mi. **US AIRS**
2145 ft. **Site 4 of 4 in cluster I** **FINDS**
ECHO

Relative:
Lower

Actual:
53 ft.

Site Discovery and Assessment:

Facility ID:	586
Rem Master ID:	639
PTP Id:	Not reported
WPC Number:	Not reported

UNITED STEEL (Continued) **1000424124**

Postal District:	Not reported
Latitude:	41.7983
Longitude:	-72.625
Lat/Long Determined By:	UNK
Ground Water Quality Classification:	Not reported
Surface Water Quality Classification:	Not reported
Waste Type:	ACID, METALS
Disposal:	LAGOON
Sample Data Available:	False
Updated By:	Not reported
Update Program:	Not reported
Updated:	Not reported
Date Created:	Not reported
Duplicate:	False

SDA Federal:

EPA CERCLIS Id:	Not reported
Number EPA RCRIS Id:	Not reported
Site on EPA's CERCLIS:	True
Site Archived from CERCLIS:	False
Archive Date:	Not reported
EPA's Removal at Site:	False
Deferred to another EPA Program:	False
EPA Env Priority Initiative Site:	False
Federal Facility:	False
Site on EPA's National Priority List:	False
Part of an NPL site:	False
RCRA Generator Status:	Not reported
RCRA Permit Status:	Not reported

SDA Referral:

Referral Id:	573
Source of referral:	CERCLIS
Date Received:	9/1/1989
Staff Assigned:	Not reported
Remediation Program:	Not reported
Date dt_assigned:	Not reported
Remediation Complete Approved DEP/Verified by LEP:	Not reported
Outcome:	Not reported

SDA Remedial:

Remedial Id:	271
PTP Id:	505
Remediation Program:	III
Remediation Program Entered:	Not reported
Staff Assigned:	RISCASSI, T.
Remediation Program:	PTP
Date dt_assign:	Not reported
Project Phase:	GWM
Order issued:	False
Order Number:	Not reported
Date order issued:	Not reported
Remedial Investigation Start:	Not reported
Remedial Investigation Completed:	Not reported
Remedial Design Start:	Not reported
Remedial Design complet:	Not reported
Remedial Action Start:	Not reported
Remedial Action Completed:	Not reported
Date Oper/ maintenance Started:	Not reported

UNITED STEEL (Continued) **1000424124**

GW monitoring: False
Remediation complete Approved DEP/Verified by LEP: Not reported

SDA Orders:
Order Id: Not reported
Order Number: Not reported
Date order issued: Not reported
Staff Assigned: Not reported
Type of Order: Not reported
Order Respondent: Not reported
Admin Appeal Date: Not reported
Date of Admin Appeal Ruling: Not reported
Date of Admin Appeal Ruling: Not reported
Date of Final Order: Not reported
Date of Court Appeal: Not reported
Date of Court Ruling: Not reported
Date of Court Ruling: Not reported
Date Order Modified: Not reported
Date Referred to AG: Not reported
Judgement: Not reported
Date of AGR judgement: Not reported
Penalty assessed: Not reported
Order Complete: Not reported
In compliance: Not reported
Comments: Not reported

US BROWNFIELDS:
Name: United Steel
Address: 164 School Streeet
City,State,Zip: EAST HARTFORD, CT 06108-1867
Property ID: 254260
Property Alias: Not reported
Recipient Name: Capitol Region Council of Governments
Grant Type: Not reported
Property Number: Not reported
Parcel Size: 21.2
Latitude: 41.784274989
Longitude: -72.612258984
Census Tract: 9003511400
State or Tribal Voluntary Response Program: Y
Program Name: BF
AA Activity Funded: Phase II Environmental Assessment
Start Date: Not reported
Redev Completition Date: Not reported
Completed Date: Not reported
Cleanup Funding: Not reported
Cleanup Funding Source: Not reported
Activity Funded: Phase II Environmental Assessment
Assessment Funding: Not reported
Assessment Funding Source: Not reported
Redevelopment Funding: Not reported
Contaminants REC: Other Metals PAHs Pesticides Petroleum Products VOCs
Contaminants Found at Actionable Level: Other Metals PAHs Pesticides Petroleum Products VOCs
Redev. Funding Source: Not reported
Redev. Funding Entity Name: Not reported
Contaminants Found Below Actionable Level: Lead,
Redevelopment Start Date: Not reported

UNITED STEEL (Continued) **1000424124**

Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	00A00586
Start Date:	2022-12-28 00:00:00
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	2023-07-24 00:00:00
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	U
Indicates Cleanup/Treatment Tech Implemented:	Not reported
Institutional Controls Required:	Not reported
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	Not reported
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Ground Water Soil
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported

UNITED STEEL (Continued) **1000424124**

RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	Not reported
Past use commercial acreage:	Not reported
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	Not reported
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	968
Below Poverty Percent:	21.95
Meidan Income:	5786
Meidan Income Number:	1764
Meidan Income Percent:	40
Vacant Housing Number:	125
Vacant Housing Percent:	6.99
Unemployed Number:	378
Unemployed Percent:	8.57

Name:	United Steel
Address:	164 School Streeet
City,State,Zip:	EAST HARTFORD, CT 06108-1867
Property ID:	254260
Property Alias:	Not reported
Recipient Name:	Capitol Region Council of Governments
Grant Type:	Not reported
Property Number:	Not reported
Parcel Size:	21.2
Latitude:	41.784274989
Longitude:	-72.612258984
Census Tract:	9003511400
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase II Environmental Assessment

UNITED STEEL (Continued) **1000424124**

Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Other Metals PAHs Pesticides Petroleum Products VOCs
Contaminants Found at Actionable Level:	Other Metals PAHs Pesticides Petroleum Products VOCs
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Lead,
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	00A00586
Start Date:	Not reported
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	Not reported
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	U
Indicates Cleanup/Treatment Tech Implemented:	Not reported
Institutional Controls Required:	Not reported
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	Not reported
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported

UNITED STEEL (Continued) **1000424124**

Media Affected:	Ground Water Soil
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	Not reported
Past use commercial acreage:	Not reported
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	Not reported
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	968
Below Poverty Percent:	21.95
Meidan Income:	5786
Meidan Income Number:	1764
Meidan Income Percent:	40
Vacant Housing Number:	125
Vacant Housing Percent:	6.99
Unemployed Number:	378
Unemployed Percent:	8.57

Name:	United Steel
Address:	164 School Streeet
City,State,Zip:	EAST HARTFORD, CT 06108-1867
Property ID:	254260
Property Alias:	Not reported
Recipient Name:	Capitol Region Council of Governments
Grant Type:	Not reported
Property Number:	Not reported
Parcel Size:	21.2
Latitude:	41.784274989
Longitude:	-72.612258984
Census Tract:	9003511400

UNITED STEEL (Continued) **1000424124**

State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase II Environmental Assessment
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Other Metals PAHs Pesticides Petroleum Products VOCs
Contaminants Found at Actionable Level:	Other Metals PAHs Pesticides Petroleum Products VOCs
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Lead,
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	00A00586
Start Date:	Not reported
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	Not reported
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	U
Indicates Cleanup/Treatment Tech Implemented:	Not reported
Institutional Controls Required:	Not reported
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	Not reported
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported

UNITED STEEL (Continued) **1000424124**

Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Ground Water Soil
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	N
Past use commercial acreage:	Not reported
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	N
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	968
Below Poverty Percent:	21.95
Meidan Income:	5786
Meidan Income Number:	1764
Meidan Income Percent:	40
Vacant Housing Number:	125
Vacant Housing Percent:	6.99
Unemployed Number:	378
Unemployed Percent:	8.57

ICIS:

Enforcement Action ID:	CT000A0000090030907200003
FRS ID:	110001407807

UNITED STEEL (Continued) **1000424124**

Action Name:	UNITED STEEL, INC 090030907200003
Facility Name:	UNITED STEEL, INC
Facility Address:	164 SCHOOL STREET EAST HARTFORD, CT 06108
Enforcement Action Type:	Notice of Violation
Facility County:	HARTFORD
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Informal
EA Type Code:	NOV
Facility SIC Code:	3441
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	41.78485
Longitude in Decimal Degrees:	-72.61348
Permit Type Desc:	Not reported
Program System Acronym:	CT0000000900309072
Facility NAICS Code:	332312
Tribal Land Code:	Not reported

Enforcement Action ID:	CT000A0000090030907200002
FRS ID:	110001407807
Action Name:	UNITED STEEL, INC 090030907200002
Facility Name:	UNITED STEEL, INC
Facility Address:	164 SCHOOL STREET EAST HARTFORD, CT 06108
Enforcement Action Type:	Notice of Violation
Facility County:	HARTFORD
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Informal
EA Type Code:	NOV
Facility SIC Code:	3441
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	41.78485
Longitude in Decimal Degrees:	-72.61348
Permit Type Desc:	Not reported
Program System Acronym:	CT0000000900309072
Facility NAICS Code:	332312
Tribal Land Code:	Not reported

Enforcement Action ID:	01-2002-0123
FRS ID:	110001407807
Action Name:	UNITED STEEL INC
Facility Name:	UNITED STEEL
Facility Address:	164 SCHOOL ST EAST HARTFORD, CT 06108
Enforcement Action Type:	RCRA 9006 AO For Comp And/Or Pen (UST) - UST Expedited Settlement Program
Facility County:	HARTFORD
Program System Acronym:	ICIS
Enforcement Action Forum Desc:	Administrative - Formal
EA Type Code:	9006E
Facility SIC Code:	Not reported
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	41.784924
Longitude in Decimal Degrees:	-72.613519
Permit Type Desc:	Not reported
Program System Acronym:	1687898
Facility NAICS Code:	Not reported
Tribal Land Code:	Not reported

UNITED STEEL (Continued) **1000424124**

Facility Name: UNITED STEEL, INC.
Address: 164 SCHOOL STREET
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: UNITED STEEL, INC.
Address: 164 SCHOOL STREET
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: UNITED STEEL, INC.
Address: 164 SCHOOL STREET
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: UNITED STEEL, INC.
Address: 164 SCHOOL STREET
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: UNITED STEEL, INC.
Address: 164 SCHOOL STREET
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: UNITED STEEL, INC.
Address: 164 SCHOOL STREET
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: UNITED STEEL, INC.
Address: 164 SCHOOL STREET
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: UNITED STEEL, INC.
Address: 164 SCHOOL STREET
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

UNITED STEEL (Continued) **1000424124**

US AIRS (AFS):
Region Code: 01
County Code: CT003
Programmatic ID: AIR CT0000000900309072
Facility Registry ID: 110001407807
D and B Number: Not reported
Facility Site Name: United Steel, Inc
Primary SIC Code: 3441
NAICS Code: 332312
Default Air Classification Code: SMI
Facility Type of Ownership Code: POF
Air CMS Category Code: SMI
HPV Status: Not reported

US AIRS (AFS):
Region Code: 01
Programmatic ID: AIR CT0000000900309072
Facility Registry ID: 110001407807
Air Operating Status Code: OPR
Default Air Classification Code: SMI

Air Program: Federally-Enforceable State Operating Permit - Non Title V
Activity Date: 2016-02-25 00:00:00
Activity Status Date: 2016-03-11 00:00:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2016-02-25 00:00:00
Activity Status Date: 2016-03-11 00:00:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Air Program: Federally-Enforceable State Operating Permit - Non Title V
Activity Date: 2011-03-04 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2011-03-04 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: Federally-Enforceable State Operating Permit - Non Title V
Activity Date: 2006-06-12 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards

UNITED STEEL (Continued) **1000424124**

Activity Date: 2006-06-12 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2002-09-04 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: Federally-Enforceable State Operating Permit - Non Title V
Activity Date: 2002-09-04 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2000-03-07 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1998-10-09 00:00:00
Activity Status Date: 1998-10-09 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1998-09-08 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

FINDS:
Registry ID: 110001407807

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The National Compliance Database (NCDB) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA).
A suite of Web-based applications designed to allow the Connecticut Department of Environmental Protection (DEP) staff to harmonize environmental interest information from disparate systems into a single agency-wide data repository (known as CFI). The Site Information Management System (SIMS) provides tools for identifying and resolving duplicate data, querying data (using both tabular and

UNITED STEEL (Continued) **1000424124**

geospatial methods), and viewing and maintaining documents associated to the data.
The Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on Brownfields properties assessed or cleaned up with grant funding, as well as information on Targeted Brownfields Assessments (TBA) performed by EPA Regions.
ICIS-Air (AIR) AIR is the modernization of the Air Facility System (AFS) into the Integrated Compliance Information System (ICIS). AIR contains enforcement, compliance, and permit data for stationary sources of air pollution regulated by the EPA, State, and Local air pollution agencies.
The Air Facility System (AFS) contains compliance and permit data for stationary sources of air pollution regulated by the EPA, state, and local air pollution agencies.
The Integrated Compliance Information System (ICIS) provides a database that, when complete, will contain integrated enforcement and compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions and a subset of the Permit Compliance System (PCS), which supports the National Pollutant Discharge Elimination System (NPDES). This information is maintained in ICIS by EPA in the Regional offices and it at Headquarters. A future release of ICIS will completely replace PCS and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities that support compliance and enforcement programs, including incident tracking, compliance assistance, and compliance monitoring.
The National Pollutant Discharge Elimination System (NPDES) module of the Integrated Compliance Information System (ICIS). Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.
The Department of Labor, Occupational Safety and Health Administration information system consists of inspection case detail for approximately 100,000 OSHA inspections conducted annually. The FRS dataset includes facilities that had inspections within the last 7 years within the mining, oil and gas, utilities, and manufacturing sectors.
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000424124
Registry ID: 110001407807

UNITED STEEL (Continued) **1000424124**

DFR URL:
Name: UNITED STEEL, INC
Address: 164 School Street
City,State,Zip: EAST HARTFORD, CT 06108

J64 **EBL PRODUCTS INC** **CT PROPERTY** **1007989163**
NNE **91 PRESTIGE PARK CIRCLE** **RCRA NonGen / NLR** **CTR000505164**
1/4-1/2 **EAST HARTFORD, CT 06108** **E MANIFEST**
0.411 mi. **CT CPCS**
2168 ft. **Site 1 of 2 in cluster J**

Relative: **Lower**

Actual: **65 ft.**

CT Property:

Name:	(FORMER) EBL PRODUCTS, INC.
Address:	91 PRESTIGE PARK CIRCLE
City,state,zip:	EAST HARTFORD, CT
Seller Name:	Fremont 91 PPC, LLC
Buyer Name:	ACG Prestige Acquisitions LLC
Certifying Party:	Fremont Prestige Park, LLC
Certifying Attention Person:	Jonathan Keller
Title Of Certifying Person:	Manager
Certifying Person Address:	65 LaSalle Road, Suite 202
Certifying Person City,St,Zip:	West Hartford, CT 06107
Property Transfer Forms:	Form III (DEP-PERD-PTP-203) when a discharge, spillage, uncontrolled loss, seepage or filtration of hazardous waste has occurred at the parcel that has not been fully remediated or the environmental conditions at the parcel are unknown. The person signing the Form III certification agrees to investigate and remediate the site in accordance with the remediation standards. The statute does not require completion of remediation before the parcel is transferred. Any person submitting a Form III shall simultaneously submit a completed Environmental Condition Assessment Form (ECAF)(DEP-PERD-PTP-200).
Date Recieved:	07/08/2021
Ackn Date:	11/22/2021
Determination Date:	Not reported
LEP Verified/DEP Approval Date:	Not reported
Rem Id:	14713
Remediation Location Id:	10545
Date Entered:	10/20/2021
Program:	Property Transfer Program
GAO Site:	False
Staff Full Name:	Jan Czeczotka
Super/Date:	11/22/2021
Stage Of Project:	Not reported
RP Level Of Activity:	Not reported
RP Needed Level Of Activity:	Not reported
Staff Level Of Activity:	Not reported
Staff Needed Level Of Activity:	Not reported
Public Intrest:	Not reported
PRP Cooperation:	Not reported
Enforcement Status:	Not reported
Level Of Complexity:	Not reported
Complex Eng Or Sci:	Not reported
Complex Due To Public Involvement:	Not reported
Politically Complex:	Not reported
Complex Enforcement:	Not reported
Coordination With Other Bureaus:	Not reported

EBL PRODUCTS INC (Continued) **1007989163**

EPA Involvement:	Not reported
Staff Prefrence:	Not reported
Readiness For Transfer:	Not reported
Project Transfer Time:	Not reported
Transfer Comments:	Not reported
Staff As Of July 2000:	Not reported
Initial Staff:	Not reported
Type Of Transfer:	Real Estate
Salutation:	Mr. Keller
Relationship To Transfer:	Transferor
Audit Date:	Not reported
Verif Type:	Not reported
Audit Outcome:	Not reported
GW:	GB
Basin:	Not reported
1st Payment:	3000
Pay Tag1:	039944
2nd Payment:	Not reported
Pay Tag2:	Not reported
RTN:	Not reported
Revised:	Not reported
ECAF Received:	Not reported
Old Determination Date:	Not reported
Redeterminationdate:	Not reported
Previous Determination:	Not reported
Monitoringoption:	Not reported
Postremedialmonitoring:	Not reported
Schedule Of I/R:	Not reported
Schedule Overdue:	Not reported
Aprvl Sched:	Not reported
Yr 1 Report:	Not reported
Yr 2 Report:	Not reported
Report Overdue:	Not reported
Ext Aprvl Sched:	Not reported
License #:	Not reported
Project Phase:	Not reported
PT Comments:	Not reported
EPA Id Number:	Not reported
GW Class:	Not reported
SW Class:	Not reported
AO/C0:	Not reported
Water Lead(Y Or N):	Not reported
Priority:	Not reported
Project Status(A, I Or D):	Not reported
Last Updated:	Not reported
SR Comments:	Not reported
Priority Or Work-Load:	Not reported
Status:	Not reported
Notes:	Not reported
Special Project Name:	Not reported
Special Project Comments:	Not reported
DOT Project:	Not reported
Pt Counter:	Not reported
Project Complete:	Not reported
Project Inactive:	Not reported
Int Deposit #:	Not reported
Deposit #:	Not reported

EBL PRODUCTS INC (Continued) **1007989163**

Spill Case #:	Not reported
Diversion Id:	Not reported
Public Notice:	Not reported
RAP Received:	Not reported
RAP Approved:	Not reported
Compliance Category:	Not reported
Delete Record:	Not reported
ECAF Reviewed By:	Not reported
Not Locatable:	Not reported
Primary Address:	Not reported
AKA Site Name:	Not reported
Primary Site Name:	Not reported
AKA Site Address:	Not reported
Lead:	LEP

RCRA Listings:

Date Form Received by Agency:		20110818
Handler Name:		E B L Products Inc
Handler Address:		Prestige Park Cir
Handler City,State,Zip:		EAST HARTFORD, CT 06108
EPA ID:		CTR000505164
Contact Name:		WATSON COBURN
Contact Address:		PRESTIGE PARK CIR
Contact City,State,Zip:		EAST HARTFORD, CT 06108
Contact Telephone:		860-290-3737 x344
Contact Fax:		Not reported
Contact Email:		EBLPZT.PAUL@SBCGLOBAL.NET
Contact Title:		QUALITY ASSURANCE ENGINEER
EPA Region:		01
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		PRESTIGE PARK CIR
Mailing City,State,Zip:		EAST HARTFORD, CT 06108
Owner Name:	Fremont Prestige I Llc	
Owner Type:		Private
Operator Name:	Ebl Products Inc.	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---

EBL PRODUCTS INC (Continued) **1007989163**

Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2009

Click Here for Biennial Reporting System Data:
Year: 2007

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D001
Waste Description: Ignitable Waste

Waste Code: D002
Waste Description: Corrosive Waste

Waste Code: D006
Waste Description: Cadmium

Waste Code: D007
Waste Description: Chromium

Waste Code: D008
Waste Description: Lead

Waste Code: D011
Waste Description: Silver

Waste Code: D035
Waste Description: Methyl Ethyl Ketone

EBL PRODUCTS INC (Continued) **1007989163**

Waste Code: F002
Waste Description: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F003
Waste Description: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: E B L PRODUCTS INC
Legal Status: Private
Date Became Current: 20050225
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: EBL PRODUCTS, INC.
Legal Status: Private
Date Became Current: 20050225
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

EBL PRODUCTS INC (Continued) **1007989163**

Owner/Operator Indicator: Operator
Owner/Operator Name: EBL PRODUCTS INC.
Legal Status: Private
Date Became Current: 20050225
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: FREMONT PRESTIGE I LLC
Legal Status: Private
Date Became Current: 20001101
Date Ended Current: Not reported
Owner/Operator Address: 65 LASALLE RD SUITE
Owner/Operator City,State,Zip: WEST HARTFORD, CT 06107
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: FREMONT PRESTIGE I LLC
Legal Status: Private
Date Became Current: 20001101
Date Ended Current: Not reported
Owner/Operator Address: 65 LASALLE RD SUITE
Owner/Operator City,State,Zip: WEST HARTFORD, CT 06107
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: EBL PRODUCTS INC.
Legal Status: Private
Date Became Current: 20050225
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: FREMONT MANAGEMENT LLC
Legal Status: Private
Date Became Current: 20001101
Date Ended Current: Not reported
Owner/Operator Address: 65 LASALLE RD
Owner/Operator City,State,Zip: WEST HARTFORD, CT 06107
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported

EBL PRODUCTS INC (Continued) **1007989163**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: FREMONT PRESTIGE I LLC
Legal Status: Private
Date Became Current: 20001101
Date Ended Current: Not reported
Owner/Operator Address: 65 LASALLE RD SUITE
Owner/Operator City,State,Zip: WEST HARTFORD, CT 06107
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: FREMONT PRESTIGE I, LLC
Legal Status: Private
Date Became Current: 20001101
Date Ended Current: Not reported
Owner/Operator Address: 65 LASALLE ROAD, SUITE 202
Owner/Operator City,State,Zip: WEST HARTFORD, CT 06107
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: EBL PRODUCTS INC.
Legal Status: Private
Date Became Current: 20050225
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20080229
Handler Name: E B L PRODUCTS INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20100519
Handler Name: E B L PRODUCTS INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported

EBL PRODUCTS INC (Continued) **1007989163**

Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20110722
Handler Name: E B L PRODUCTS INC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20110818
Handler Name: E B L PRODUCTS INC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20050304
Handler Name: E B L PRODUCTS INC	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	334419
NAICS Description:	Other Electronic Component Manufacturing

Has the Facility Received Notices of Violations:

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported

EBL PRODUCTS INC (Continued) **1007989163**

Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported

EBL PRODUCTS INC (Continued) **1007989163**

Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General

EBL PRODUCTS INC (Continued) **1007989163**

Date Violation was Determined:	20060403
Actual Return to Compliance Date:	20080501
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	20060726
Enforcement Identifier:	001
Date of Enforcement Action:	20060626
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Wswdh06057
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	KLCCT
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - General
Date Violation was Determined:	20060403
Actual Return to Compliance Date:	20080501
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20070910
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Wswdh07015
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	20080501
Disposition Status:	AS
Disposition Status Description:	ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported

EBL PRODUCTS INC (Continued) **1007989163**

Enforcement Type:	FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person:	KLCCT
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	13325
Paid Amount:	13325
Final Count:	1
Final Amount:	13325
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - General
Date Violation was Determined:	20060403
Actual Return to Compliance Date:	20080501
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	20060726
Enforcement Identifier:	001
Date of Enforcement Action:	20060626
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Wswdh06057
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	KLCCT
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - General

EBL PRODUCTS INC (Continued) **1007989163**

Date Violation was Determined:	20060403
Actual Return to Compliance Date:	20080501
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20070910
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Wswdh07015
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	20080501
Disposition Status:	AS
Disposition Status Description:	ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person:	KLCCT
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	13325
Paid Amount:	13325
Final Count:	1
Final Amount:	13325

Evaluation Action Summary:

Evaluation Date:	20110719
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE SCHEDULE EVALUATION
Evaluation Responsible Person Identifier:	CLHCT
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20070910
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	NO LONGER A SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	KLCCT
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported

EBL PRODUCTS INC (Continued) **1007989163**

Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20061006
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	KLCCT
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20060403
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	DKSCT
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	20080501
Scheduled Compliance Date:	20060726
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20060403
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	DKSCT
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	20080501
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20060403
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	DKSCT
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	20080501
Scheduled Compliance Date:	20060726
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

EBL PRODUCTS INC (Continued) **1007989163**

Evaluation Date:	20060403
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	DKSCT
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	20080501
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

E MANIFEST:

Manifest Tracking Number:	016827533JJK
Last Updated Date:	20190409
Shipped Date:	20190327
Received Date:	20190330
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CTR000509398
Generator Name:	Ebl Products Inc
Generator Location Street Number:	Not reported
Generator Location Street 1:	91 PRESTIGE PARK CIRCLE
Generator Location Street 2:	Not reported
Generator Location City:	EAST HARTFORD
Generator Location State:	CT
Generator Location Zip:	06108
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	91 PRESTIGE PARK CIRCLE
Generator Mail Street 2:	Not reported
Generator Mail City:	EAST HARTFORD
Generator Mail Zip:	06108
Generator Mail State:	CT
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD002200046
Designated Facility Name:	Cycle Chem, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	217 SOUTH FIRST STREET
Designated Facility Mail City:	ELIZABETH
Designated Facility Mail Zip:	07206
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	217 SOUTH FIRST STREET
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	ELIZABETH
Designated Facility Location Zip:	07206
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	018900862JJK
Last Updated Date:	20200331

EBL PRODUCTS INC (Continued) **1007989163**

Shipped Date:	20200304
Received Date:	20200312
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CTR000509398
Generator Name:	Ebl Products Inc
Generator Location Street Number:	Not reported
Generator Location Street 1:	91 PRESTIGE PARK CIRCLE
Generator Location Street 2:	Not reported
Generator Location City:	EAST HARTFORD
Generator Location State:	CT
Generator Location Zip:	06108
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	91 PRESTIGE PARK CIRCLE
Generator Mail Street 2:	Not reported
Generator Mail City:	EAST HARTFORD
Generator Mail Zip:	06108
Generator Mail State:	CT
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD002200046
Designated Facility Name:	Cycle Chem, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	217 SOUTH FIRST STREET
Designated Facility Mail City:	ELIZABETH
Designated Facility Mail Zip:	07206
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	217 SOUTH FIRST STREET
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	ELIZABETH
Designated Facility Location Zip:	07206
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	017357594FLE
Last Updated Date:	20220830
Shipped Date:	20220725
Received Date:	20220808
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CTCESQG99999
Generator Name:	Adaptive Optics
Generator Location Street Number:	Not reported
Generator Location Street 1:	91 PRESTIGE PARK CIRCLE
Generator Location Street 2:	Not reported
Generator Location City:	EAST HARTFORD
Generator Location State:	CT
Generator Location Zip:	06108
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	115 Jackson Road
Generator Mail Street 2:	Not reported
Generator Mail City:	Devons

EBL PRODUCTS INC (Continued) **1007989163**

Generator Mail Zip:	01434
Generator Mail State:	MA
Generator Contact Company Name:	Adaptive Optics
Designated Facility EPA ID:	ARD069748192
Designated Facility Name:	Clean Harbors El Dorado Llc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	309 American Circle
Designated Facility Mail City:	El Dorado
Designated Facility Mail Zip:	71730
Designated Facility Mail State:	AR
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	309 American Circle
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	El Dorado
Designated Facility Location Zip:	71730
Designated Facility Location State:	AR
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	017357595FLE
Last Updated Date:	20220829
Shipped Date:	20220725
Received Date:	20220808
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CTCESQG99999
Generator Name:	Adaptive Optics
Generator Location Street Number:	Not reported
Generator Location Street 1:	91 PRESTIGE PARK CIRCLE
Generator Location Street 2:	Not reported
Generator Location City:	EAST HARTFORD
Generator Location State:	CT
Generator Location Zip:	06108
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	115 Jackson Road
Generator Mail Street 2:	Not reported
Generator Mail City:	Devons
Generator Mail Zip:	01434
Generator Mail State:	MA
Generator Contact Company Name:	Adaptive Optics
Designated Facility EPA ID:	KYD053348108
Designated Facility Name:	Safety-Kleen Systems, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	3700 LaGrange Road
Designated Facility Mail City:	Smithfield
Designated Facility Mail Zip:	40068
Designated Facility Mail State:	KY
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	3700 LaGrange Road
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Smithfield
Designated Facility Location Zip:	40068
Designated Facility Location State:	KY

EBL PRODUCTS INC (Continued) **1007989163**

Designated Facility Contact Company Name: Not reported
Manifest Residue Indicator: N
Rejection Indicator: N

Transporter:
Manifest Tracking Number: 017357595FLE
Transporter Line Number: 1
Transporter EPA ID: MAD039322250
Transporter Name: Clean Harbors Environmental Services, Inc.

Waste Line:
Manifest Tracking Number: 017357595FLE
Waste Line Number: 1
U.S. DOT Hazardous Indicator: Y
U.S. DOT ID Number: UN3175
U.S. DOT Description: Rq, Un3175, Waste Solids Containing Flammable Liquid, N.O.S. (Acetone/Isopropyl Alcohol), 4.1, Pg Ii (D001)
Non-Hazardous Waste Description: Not reported
Number of Containers: 3
Container Type Code: DM
Container Type Description: Metal drums, barrels, kegs
Waste Quantity: 330
Quantity Unit of Measure Code: P
Quantity Unit of Measure Description: Pounds
Waste Quantity, in Tons: 0.165
Acute Waste Quantity, in Tons: 0
Non-Acute Waste Quantity, in Tons: 0.165
Waste Quantity, in Kilograms: 149.65996
Acute Waste Quantity, in Kilograms: 0
Non-Acute Waste Quantity, in Kilorgrams: 149.65996
Management Method Code: H061
Management Method Description: FUEL BLENDING
Waste Residue Indicator: N
Quantity Discrepancy Indicator: N
Waste Type Discrepancy Indicator: N
Waste Density: Not reported
Waste Density Unit of Measure Code: Not reported
Waste Density Unit of Measure Description: Not reported
Form Code: Not reported
Form Code Description: Not reported
Source Code: Not reported
Source Code Description: Not reported
Waste Minimization Code: Not reported
Waste Minimization Code Description: Not reported
Consent Number: Not reported
EPA Waste Indicator: Y
Federal Waste Codes: D001
Quantity Haz Kg: 149.65996
Quantity Haz Tons: 0.165
Quantity Non Haz Kg: 0
Quantity Non Haz Tons: 0
State Waste Codes: Not reported

CPCS:
Name: (Former) Ebl Products, Inc.
Address: 91 PRESTIGE PARK CIRCLE

EBL PRODUCTS INC (Continued) **1007989163**

City,State,Zip:	EAST HARTFORD, CT
Site Type:	Not reported
Lust Status code:	Not reported
Lust Status:	Not reported
PTP Form:	Not reported
Program:	Property Transfer Program
Comments:	Not reported
Site Type Definition:	Not reported
Invesigation Start:	Not reported
Invesigation Start Date:	11/22/2021
Remediation Start:	Not reported
Remediation Start Date:	Not reported
Remediation Completed:	Yes
ELUR:	No
Date Data Updated:	Not reported

J65 **STAVELEY SENSORS, INC.** **CT PROPERTY** **S109756309**
NNE **91 PRESTIGE PARK CIRCLE** **CT CPCS** **N/A**
1/4-1/2 **EAST HARTFORD, CT**
0.411 mi.
2168 ft. **Site 2 of 2 in cluster J**

Relative: **Lower**

Actual: **65 ft.**

CT Property:

Name:	STAVELEY SENSORS, INC.
Address:	91 PRESTIGE PARK CIRCLE
City,state,zip:	EAST HARTFORD, CT
Seller Name:	Stavely Senors, Inc.
Buyer Name:	R/D Tech Corp.
Certifying Party:	Staveley Sensors, Inc.
Certifying Attention Person:	Thomas E. Silva
Title Of Certifying Person:	Executive Vice President
Certifying Person Address:	91 Prestige Park Circle
Certifying Person City,St,Zip:	East Hartford, CT 06108-1918
Property Transfer Forms:	Form I (DEP-PERD-PTP-201) when no release of hazardous waste has occurred at the parcel being transferred.
Date Recieved:	11/12/2004
Ackn Date:	01/21/2005
Determination Date:	Not reported
LEP Verified/DEP Approval Date:	Not reported
Rem Id:	6501
Remediation Location Id:	6284
Date Entered:	11/23/2004
Program:	Property Transfer Program
GAO Site:	False
Staff Full Name:	Kevin Neary
Super/Date:	01/11/2005
Stage Of Project:	Not reported
RP Level Of Activity:	Not reported
RP Needed Level Of Activity:	Not reported
Staff Level Of Activity:	Not reported
Staff Needed Level Of Activity:	Not reported
Public Intrest:	Not reported
PRP Cooperation:	Not reported
Enforcement Status:	Not reported
Level Of Complexity:	Not reported
Complex Eng Or Sci:	False
Complex Due To Public Involvement:	False
Politically Complex:	False

STAVELEY SENSORS, INC. (Continued) **S109756309**

Complex Enforcement:	False
Coordination With Other Bureaus:	False
EPA Involvement:	False
Staff Prefrence:	Not reported
Readiness For Transfer:	Not reported
Project Transfer Time:	Not reported
Transfer Comments:	Not reported
Staff As Of July 2000:	Not reported
Initial Staff:	Not reported
Type Of Transfer:	Business
Salutation:	Mr. Silva
Relationship To Transfer:	transferor
Audit Date:	Not reported
Verif Type:	Not reported
Audit Outcome:	Not reported
GW:	GB
Basin:	Not reported
1st Payment:	200
Pay Tag1:	100023080
2nd Payment:	100
Pay Tag2:	94213
RTN:	12/29/2004
Revised:	1/11/2005
ECAF Received:	Not reported
Old Determination Date:	Not reported
Redeterminationdate:	Not reported
Previous Determination:	Not reported
Monitoringoption:	Not reported
Postremedialmonitoring:	Not reported
Schedule Of I/R:	Not reported
Schedule Overdue:	Not reported
Aprvl Sched:	Not reported
Yr 1 Report:	Not reported
Yr 2 Report:	Not reported
Report Overdue:	Not reported
Ext Aprvl Sched:	Not reported
License #:	Not reported
Project Phase:	Not reported
PT Comments:	Not reported
EPA Id Number:	Not reported
GW Class:	Not reported
SW Class:	Not reported
AO/C0:	Not reported
Water Lead(Y Or N):	Not reported
Priority:	Not reported
Project Status(A, I Or D):	Not reported
Last Updated:	Not reported
SR Comments:	Not reported
Priority Or Work-Load:	Not reported
Status:	Not reported
Notes:	Not reported
Special Project Name:	Not reported
Special Project Comments:	Not reported
DOT Project:	Not reported
Pt Counter:	0
Project Complete:	False
Project Inactive:	False

STAVELEY SENSORS, INC. (Continued) **S109756309**

Int Deposit #:	05-123
Deposit #:	05-177
Spill Case #:	Not reported
Diversion Id:	0
Public Notice:	Not reported
RAP Received:	Not reported
RAP Approved:	Not reported
Compliance Category:	Not reported
Delete Record:	False
ECAF Reviewed By:	Not reported
Not Locatable:	False
Primary Address:	False
AKA Site Name:	False
Primary Site Name:	False
AKA Site Address:	False
Lead:	LEP
Name:	STAVELEY SENSORS, INC.
Address:	91 PRESTIGE PARK CIRCLE
City,state,zip:	EAST HARTFORD, CT
Seller Name:	Staveley Senors Inc.
Buyer Name:	EBL Products Inc.
Certifying Party:	Staveley Sensors Inc.
Certifying Attention Person:	Alain Allard
Title Of Certifying Person:	President
Certifying Person Address:	91 Prestige Park Circle
Certifying Person City,St,Zip:	East Hartford, CT 06108-1918
Property Transfer Forms:	Form I (DEP-PERD-PTP-201) when no release of hazardous waste has occurred at the parcel being transferred.
Date Recieved:	04/11/2005
Ackn Date:	05/10/2005
Determination Date:	Not reported
LEP Verified/DEP Approval Date:	Not reported
Rem Id:	7079
Remediation Location Id:	6284
Date Entered:	04/15/2005
Program:	Property Transfer Program
GAO Site:	False
Staff Full Name:	Kevin Neary
Super/Date:	05/10/2005
Stage Of Project:	Not reported
RP Level Of Activity:	Not reported
RP Needed Level Of Activity:	Not reported
Staff Level Of Activity:	Not reported
Staff Needed Level Of Activity:	Not reported
Public Intrest:	Not reported
PRP Cooperation:	Not reported
Enforcement Status:	Not reported
Level Of Complexity:	Not reported
Complex Eng Or Sci:	False
Complex Due To Public Involvement:	False
Politically Complex:	False
Complex Enforcement:	False
Coordination With Other Bureaus:	False
EPA Involvement:	False
Staff Prefrence:	Not reported
Readiness For Transfer:	Not reported

STAVELEY SENSORS, INC. (Continued) **S109756309**

Project Transfer Time:	Not reported
Transfer Comments:	Not reported
Staff As Of July 2000:	Not reported
Initial Staff:	Not reported
Type Of Transfer:	Business
Salutation:	Mr. Allard
Relationship To Transfer:	transferor
Audit Date:	Not reported
Verif Type:	Not reported
Audit Outcome:	Not reported
GW:	GB
Basin:	Not reported
1st Payment:	300
Pay Tag1:	005250
2nd Payment:	Not reported
Pay Tag2:	Not reported
RTN:	Not reported
Revised:	Not reported
ECAF Received:	Not reported
Old Determination Date:	Not reported
Redeterminationdate:	Not reported
Previous Determination:	Not reported
Monitoringoption:	Not reported
Postremedialmonitoring:	Not reported
Schedule Of I/R:	Not reported
Schedule Overdue:	Not reported
Aprvl Sched:	Not reported
Yr 1 Report:	Not reported
Yr 2 Report:	Not reported
Report Overdue:	Not reported
Ext Aprvl Sched:	Not reported
License #:	Not reported
Project Phase:	Not reported
PT Comments:	Not reported
EPA Id Number:	Not reported
GW Class:	Not reported
SW Class:	Not reported
AO/C0:	Not reported
Water Lead(Y Or N):	Not reported
Priority:	Not reported
Project Status(A, I Or D):	Not reported
Last Updated:	Not reported
SR Comments:	Not reported
Priority Or Work-Load:	Not reported
Status:	Not reported
Notes:	Not reported
Special Project Name:	Not reported
Special Project Comments:	Not reported
DOT Project:	Not reported
Pt Counter:	0
Project Complete:	False
Project Inactive:	False
Int Deposit #:	05-251
Deposit #:	Not reported
Spill Case #:	Not reported
Diversion Id:	0
Public Notice:	Not reported

STAVELEY SENSORS, INC. (Continued) **S109756309**

RAP Received:	Not reported
RAP Approved:	Not reported
Compliance Category:	Not reported
Delete Record:	False
ECAF Reviewed By:	Not reported
Not Locatable:	False
Primary Address:	False
AKA Site Name:	False
Primary Site Name:	False
AKA Site Address:	False
Lead:	LEP
Name:	STAVELEY SENSORS, INC.
Address:	91 PRESTIGE PARK CIRCLE
City,state,zip:	EAST HARTFORD, CT
Seller Name:	Fremont Prestige Park, LLC
Buyer Name:	Fremont Prestige I, LLC
Certifying Party:	Fremont Prestige Park, LLC
Certifying Attention Person:	Jonathan Keller
Title Of Certifying Person:	Managing Member
Certifying Person Address:	65 LaSalle
Certifying Person City,St,Zip:	West Hartford, CT 06107
Property Transfer Forms:	Form I (DEP-PERD-PTP-201) when no release of hazardous waste has occurred at the parcel being transferred.
Date Recieved:	03/22/2006
Ackn Date:	04/28/2006
Determination Date:	Not reported
LEP Verified/DEP Approval Date:	Not reported
Rem Id:	7979
Remediation Location Id:	6284
Date Entered:	04/28/2006
Program:	Property Transfer Program
GAO Site:	False
Staff Full Name:	Kevin Neary
Super/Date:	05/02/2006
Stage Of Project:	Not reported
RP Level Of Activity:	Not reported
RP Needed Level Of Activity:	Not reported
Staff Level Of Activity:	Not reported
Staff Needed Level Of Activity:	Not reported
Public Intrest:	Not reported
PRP Cooperation:	Not reported
Enforcement Status:	Not reported
Level Of Complexity:	Not reported
Complex Eng Or Sci:	False
Complex Due To Public Involvement:	False
Politically Complex:	False
Complex Enforcement:	False
Coordination With Other Bureaus:	False
EPA Involvement:	False
Staff Prefrence:	Not reported
Readiness For Transfer:	Not reported
Project Transfer Time:	Not reported
Transfer Comments:	Not reported
Staff As Of July 2000:	Not reported
Initial Staff:	Not reported
Type Of Transfer:	Real Estate

STAVELEY SENSORS, INC. (Continued) **S109756309**

Salutation:	Mr. Keller
Relationship To Transfer:	transferor
Audit Date:	Not reported
Verif Type:	Not reported
Audit Outcome:	Not reported
GW:	GB
Basin:	Not reported
1st Payment:	300
Pay Tag1:	5750360
2nd Payment:	Not reported
Pay Tag2:	Not reported
RTN:	Not reported
Revised:	Not reported
ECAF Received:	Not reported
Old Determination Date:	Not reported
Redeterminationdate:	Not reported
Previous Determination:	Not reported
Monitoringoption:	Not reported
Postremedialmonitoring:	Not reported
Schedule Of I/R:	Not reported
Schedule Overdue:	Not reported
Aprvl Sched:	Not reported
Yr 1 Report:	Not reported
Yr 2 Report:	Not reported
Report Overdue:	Not reported
Ext Aprvl Sched:	Not reported
License #:	Not reported
Project Phase:	Not reported
PT Comments:	Not reported
EPA Id Number:	Not reported
GW Class:	Not reported
SW Class:	Not reported
AO/C0:	Not reported
Water Lead(Y Or N):	Not reported
Priority:	Not reported
Project Status(A, I Or D):	Not reported
Last Updated:	Not reported
SR Comments:	Not reported
Priority Or Work-Load:	Not reported
Status:	Not reported
Notes:	Not reported
Special Project Name:	Not reported
Special Project Comments:	Not reported
DOT Project:	Not reported
Pt Counter:	0
Project Complete:	False
Project Inactive:	False
Int Deposit #:	Not reported
Deposit #:	Not reported
Spill Case #:	Not reported
Diversion Id:	0
Public Notice:	Not reported
RAP Received:	Not reported
RAP Approved:	Not reported
Compliance Category:	Not reported
Delete Record:	False
ECAF Reviewed By:	Not reported

STAVELEY SENSORS, INC. (Continued) **S109756309**

Not Locatable:	False
Primary Address:	False
AKA Site Name:	False
Primary Site Name:	False
AKA Site Address:	False
Lead:	LEP
Name:	STAVELEY SENSORS, INC.
Address:	91 PRESTIGE PARK CIRCLE
City,state,zip:	EAST HARTFORD, CT
Seller Name:	Tolland Enterprises
Buyer Name:	Fremont Prestige Park, LLC
Certifying Party:	Tolland Enterprises
Certifying Attention Person:	Arthur Beckenstein
Title Of Certifying Person:	Partner
Certifying Person Address:	183 Prestige Park Road
Certifying Person City,St,Zip:	East Hartford, CT 06108
Property Transfer Forms:	Form I (DEP-PERD-PTP-201) when no release of hazardous waste has occurred at the parcel being transferred.
Date Recieved:	11/06/2000
Ackn Date:	02/07/2001
Determination Date:	Not reported
LEP Verified/DEP Approval Date:	Not reported
Rem Id:	1097
Remediation Location Id:	6284
Date Entered:	Not reported
Program:	Property Transfer Program
GAO Site:	False
Staff Full Name:	Not reported
Super/Date:	Not reported
Stage Of Project:	Not reported
RP Level Of Activity:	Not reported
RP Needed Level Of Activity:	Not reported
Staff Level Of Activity:	Not reported
Staff Needed Level Of Activity:	Not reported
Public Intrest:	Not reported
PRP Cooperation:	Not reported
Enforcement Status:	Not reported
Level Of Complexity:	Not reported
Complex Eng Or Sci:	False
Complex Due To Public Involvement:	False
Politically Complex:	False
Complex Enforcement:	False
Coordination With Other Bureaus:	False
EPA Involvement:	False
Staff Prefrence:	Not reported
Readiness For Transfer:	Not reported
Project Transfer Time:	Not reported
Transfer Comments:	Not reported
Staff As Of July 2000:	Not reported
Initial Staff:	Not reported
Type Of Transfer:	Not reported
Salutation:	Mr. Beckenstein
Relationship To Transfer:	transferor
Audit Date:	Not reported
Verif Type:	Not reported
Audit Outcome:	Not reported

STAVELEY SENSORS, INC. (Continued) **S109756309**

GW:	Not reported
Basin:	Not reported
1st Payment:	200
Pay Tag1:	Not reported
2nd Payment:	Not reported
Pay Tag2:	Not reported
RTN:	12/20/2000
Revised:	1/24/2001
ECAF Received:	Not reported
Old Determination Date:	Not reported
Redeterminationdate:	Not reported
Previous Determination:	Not reported
Monitoringoption:	Not reported
Postremedialmonitoring:	Not reported
Schedule Of I/R:	Not reported
Schedule Overdue:	Not reported
Aprvl Sched:	Not reported
Yr 1 Report:	Not reported
Yr 2 Report:	Not reported
Report Overdue:	Not reported
Ext Aprvl Sched:	Not reported
License #:	Not reported
Project Phase:	Not reported
PT Comments:	Not reported
EPA Id Number:	Not reported
GW Class:	Not reported
SW Class:	Not reported
AO/C0:	Not reported
Water Lead(Y Or N):	Not reported
Priority:	Not reported
Project Status(A, I Or D):	Not reported
Last Updated:	Not reported
SR Comments:	Not reported
Priority Or Work-Load:	Not reported
Status:	Not reported
Notes:	Not reported
Special Project Name:	Not reported
Special Project Comments:	Not reported
DOT Project:	Not reported
Pt Counter:	0
Project Complete:	False
Project Inactive:	False
Int Deposit #:	Not reported
Deposit #:	Not reported
Spill Case #:	Not reported
Diversion Id:	Not reported
Public Notice:	Not reported
RAP Received:	Not reported
RAP Approved:	Not reported
Compliance Category:	Not reported
Delete Record:	False
ECAF Reviewed By:	Not reported
Not Locatable:	False
Primary Address:	True
AKA Site Name:	False
Primary Site Name:	True
AKA Site Address:	False

STAVELEY SENSORS, INC. (Continued) **S109756309**

Lead: LEP

CPCS:

Name:	Staveley Sensors, Inc.
Address:	91 PRESTIGE PARK CIRCLE
City,State,Zip:	EAST HARTFORD, CT
Site Type:	Not reported
Lust Status code:	Not reported
Lust Status:	Not reported
PTP Form:	Not reported
Program:	Property Transfer Program
Comments:	Not reported
Site Type Definition:	Not reported
Invesigation Start:	Not reported
Invesigation Start Date:	04/28/2006
Remediation Start:	Not reported
Remediation Start Date:	Not reported
Remediation Completed:	Yes
ELUR:	No
Date Data Updated:	Not reported

Name:	Staveley Sensors, Inc.
Address:	91 PRESTIGE PARK CIRCLE
City,State,Zip:	EAST HARTFORD, CT
Site Type:	Not reported
Lust Status code:	Not reported
Lust Status:	Not reported
PTP Form:	Not reported
Program:	Property Transfer Program
Comments:	Not reported
Site Type Definition:	Not reported
Invesigation Start:	Not reported
Invesigation Start Date:	01/21/2005
Remediation Start:	Not reported
Remediation Start Date:	Not reported
Remediation Completed:	Yes
ELUR:	No
Date Data Updated:	Not reported

Name:	Staveley Sensors, Inc.
Address:	91 PRESTIGE PARK CIRCLE
City,State,Zip:	EAST HARTFORD, CT
Site Type:	Not reported
Lust Status code:	Not reported
Lust Status:	Not reported
PTP Form:	Not reported
Program:	Property Transfer Program
Comments:	Not reported
Site Type Definition:	Not reported
Invesigation Start:	Not reported
Invesigation Start Date:	05/10/2005
Remediation Start:	Not reported
Remediation Start Date:	Not reported
Remediation Completed:	Yes
ELUR:	No
Date Data Updated:	Not reported

STAVELEY SENSORS, INC. (Continued) **S109756309**

Name:	Staveley Sensors, Inc.
Address:	91 PRESTIGE PARK CIRCLE
City,State,Zip:	EAST HARTFORD, CT
Site Type:	Not reported
Lust Status code:	Not reported
Lust Status:	Not reported
PTP Form:	Not reported
Program:	Property Transfer Program
Comments:	Not reported
Site Type Definition:	Not reported
Invesigation Start:	Not reported
Invesigation Start Date:	02/07/2001
Remediation Start:	Not reported
Remediation Start Date:	Not reported
Remediation Completed:	No
ELUR:	No
Date Data Updated:	Not reported

K66 **FORMER BURNSIDE APARTMENTS** **CT BROWNFIELDS** **S128966220**
West **550 BURNSIDE AVENUE/550-560 BURNSIDE AVENUE** **N/A**
1/4-1/2 **EAST HARTFORD, CT**
0.427 mi.
2254 ft. **Site 1 of 2 in cluster K**

Relative: **Lower**
Actual: **48 ft.**

BROWNFIELDS 2:

Region:	2
Data Source CD:	EPA
Data Source:	EPA Funded Brownfields Project
Parcel ID Number:	1863
Latitude:	41.778474
Longitude:	-72.615609
Site Acreage:	3.16
Program Approval Date:	Not reported

K67 **VACANT LOT** **US BROWNFIELDS** **1012126910**
West **550 BURNSIDE AVENUE 560 BURNSIDE AVENUE** **N/A**
1/4-1/2 **EAST HARTFORD, CT 06108**
0.427 mi.
2254 ft. **Site 2 of 2 in cluster K**

Relative: **Lower**
Actual: **48 ft.**

US BROWNFIELDS:

Name:	Vacant Lot
Address:	550 Burnside Avenue 560 Burnside Avenue
City,State,Zip:	EAST HARTFORD, CT 06108
Property ID:	93661
Property Alias:	former Burnside Apartments
Recipient Name:	Capitol Region Council of Governments
Grant Type:	Hazardous
Property Number:	Map/lot: 36/115
Parcel Size:	3.16
Latitude:	41.77915
Longitude:	-72.61633
Census Tract:	9003510400
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Not reported

VACANT LOT (Continued) **1012126910**

Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	97133201
Start Date:	2008-05-30 00:00:00
Ownership Entity:	Government
Additional Institutional Controls Information:	Not reported
Completion Date:	2008-09-24 00:00:00
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	U
Indicates Cleanup/Treatment Tech Implemented:	Not reported
Institutional Controls Required:	Not reported
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	Not reported
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported

VACANT LOT (Continued) **1012126910**

RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Not reported
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	3.16
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	N
Past use commercial acreage:	Not reported
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	N
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	1251
Below Poverty Percent:	27.95
Meidan Income:	2198
Meidan Income Number:	2232
Meidan Income Percent:	49.87
Vacant Housing Number:	219
Vacant Housing Percent:	11.43
Unemployed Number:	441
Unemployed Percent:	9.85

Name:	Vacant Lot
Address:	550 Burnside Avenue 560 Burnside Avenue
City,State,Zip:	EAST HARTFORD, CT 06108
Property ID:	93661
Property Alias:	former Burnside Apartments
Recipient Name:	Capitol Region Council of Governments

VACANT LOT (Continued) **1012126910**

Grant Type:	Hazardous
Property Number:	Map/lot: 36/115
Parcel Size:	3.16
Latitude:	41.77915
Longitude:	-72.61633
Census Tract:	9003510400
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	97133201
Start Date:	Not reported
Ownership Entity:	Government
Additional Institutional Controls Information:	Not reported
Completion Date:	Not reported
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	U
Indicates Cleanup/Treatment Tech Implemented:	Not reported
Institutional Controls Required:	Not reported
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	Not reported
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported

VACANT LOT (Continued) **1012126910**

Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Not reported
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	3.16
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	N
Past use commercial acreage:	Not reported
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	N
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	1251
Below Poverty Percent:	27.95
Meidan Income:	2198
Meidan Income Number:	2232
Meidan Income Percent:	49.87
Vacant Housing Number:	219
Vacant Housing Percent:	11.43

VACANT LOT (Continued) **1012126910**

Unemployed Number:	441
Unemployed Percent:	9.85
Name:	Vacant Lot
Address:	550 Burnside Avenue 560 Burnside Avenue
City,State,Zip:	EAST HARTFORD, CT 06108
Property ID:	93661
Property Alias:	former Burnside Apartments
Recipient Name:	Capitol Region Council of Governments
Grant Type:	Hazardous
Property Number:	Map/lot: 36/115
Parcel Size:	3.16
Latitude:	41.77915
Longitude:	-72.61633
Census Tract:	9003510400
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	97133201
Start Date:	Not reported
Ownership Entity:	Government
Additional Institutional Controls Information:	Not reported
Completion Date:	Not reported
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	U
Indicates Cleanup/Treatment Tech Implemented:	Not reported
Institutional Controls Required:	Not reported
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported

VACANT LOT (Continued) **1012126910**

Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	Not reported
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Not reported
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	3.16
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	Not reported
Past use commercial acreage:	Not reported
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	Not reported
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported

VACANT LOT (Continued) **1012126910**

Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	1251
Below Poverty Percent:	27.95
Meidan Income:	2198
Meidan Income Number:	2232
Meidan Income Percent:	49.87
Vacant Housing Number:	219
Vacant Housing Percent:	11.43
Unemployed Number:	441
Unemployed Percent:	9.85

68
North
1/4-1/2
0.439 mi.
2319 ft.

EBL PRODUCTS INC.
22 PRESTIGE PARK CIR
EAST HARTFORD, CT 06108

CT PROPERTY **S111285719**
CT CPCS **N/A**
CT ENF
CT MANIFEST
CT NPDES

Relative:
Lower

Actual:
62 ft.

CT Property:

Name:	EBL PRODUCTS, INC.
Address:	22 PRESTIGE PARK CIRCLE
City,state,zip:	EAST HARTFORD, CT
Seller Name:	Fremont 22 PPC, LLC
Buyer Name:	ACG Prestige Acquisitions LLC
Certifying Party:	Fremont Prestige Park, LLC
Certifying Attention Person:	Jonathan Keller
Title Of Certifying Person:	Manager
Certifying Person Address:	65 LaSalle Road, Suite 202
Certifying Person City,St,Zip:	West Hartford, CT 06107
Property Transfer Forms:	Form III (DEP-PERD-PTP-203) when a discharge, spillage, uncontrolled loss, seepage or filtration of hazardous waste has occurred at the parcel that has not been fully remediated or the environmental conditions at the parcel are unknown. The person signing the Form III certification agrees to investigate and remediate the site in accordance with the remediation standards. The statute does not require completion of remediation before the parcel is transferred. Any person submitting a Form III shall simultaneously submit a completed Environmental Condition Assessment Form (ECAF)(DEP-PERD-PTP-200).
Date Recieved:	07/09/2021
Ackn Date:	11/22/2021
Determination Date:	Not reported
LEP Verified/DEP Approval Date:	Not reported
Rem Id:	14714
Remediation Location Id:	10546
Date Entered:	10/20/2021
Program:	Property Transfer Program
GAO Site:	False
Staff Full Name:	Jan Czeczotka
Super/Date:	11/22/2021
Stage Of Project:	Not reported
RP Level Of Activity:	Not reported
RP Needed Level Of Activity:	Not reported
Staff Level Of Activity:	Not reported
Staff Needed Level Of Activity:	Not reported
Public Intrest:	Not reported
PRP Cooperation:	Not reported
Enforcement Status:	Not reported

EBL PRODUCTS INC. (Continued) **S111285719**

Level Of Complexity:	Not reported
Complex Eng Or Sci:	Not reported
Complex Due To Public Involvement:	Not reported
Politically Complex:	Not reported
Complex Enforcement:	Not reported
Coordination With Other Bureaus:	Not reported
EPA Involvement:	Not reported
Staff Prefrence:	Not reported
Readiness For Transfer:	Not reported
Project Transfer Time:	Not reported
Transfer Comments:	Not reported
Staff As Of July 2000:	Not reported
Initial Staff:	Not reported
Type Of Transfer:	Real Estate
Salutation:	Mr. Keller
Relationship To Transfer:	Transferor
Audit Date:	Not reported
Verif Type:	Not reported
Audit Outcome:	Not reported
GW:	GB
Basin:	Not reported
1st Payment:	3000
Pay Tag1:	039943
2nd Payment:	Not reported
Pay Tag2:	Not reported
RTN:	Not reported
Revised:	Not reported
ECAF Received:	Not reported
Old Determination Date:	Not reported
Redeterminationdate:	Not reported
Previous Determination:	Not reported
Monitoringoption:	Not reported
Postremedialmonitoring:	Not reported
Schedule Of I/R:	Not reported
Schedule Overdue:	Not reported
Aprvl Sched:	Not reported
Yr 1 Report:	Not reported
Yr 2 Report:	Not reported
Report Overdue:	Not reported
Ext Aprvl Sched:	Not reported
License #:	Not reported
Project Phase:	Not reported
PT Comments:	Not reported
EPA Id Number:	Not reported
GW Class:	Not reported
SW Class:	Not reported
AO/C0:	Not reported
Water Lead(Y Or N):	Not reported
Priority:	Not reported
Project Status(A, I Or D):	Not reported
Last Updated:	Not reported
SR Comments:	Not reported
Priority Or Work-Load:	Not reported
Status:	Not reported
Notes:	Not reported
Special Project Name:	Not reported
Special Project Comments:	Not reported

EBL PRODUCTS INC. (Continued) **S111285719**

DOT Project:	Not reported
Pt Counter:	Not reported
Project Complete:	Not reported
Project Inactive:	Not reported
Int Deposit #:	Not reported
Deposit #:	Not reported
Spill Case #:	Not reported
Diversion Id:	Not reported
Public Notice:	Not reported
RAP Received:	Not reported
RAP Approved:	Not reported
Compliance Category:	Not reported
Delete Record:	Not reported
ECAF Reviewed By:	Not reported
Not Locatable:	Not reported
Primary Address:	Not reported
AKA Site Name:	Not reported
Primary Site Name:	Not reported
AKA Site Address:	Not reported
Lead:	LEP

CPCS:

Name:	Ebl Products, Inc.
Address:	22 PRESTIGE PARK CIRCLE
City,State,Zip:	EAST HARTFORD, CT
Site Type:	Not reported
Lust Status code:	Not reported
Lust Status:	Not reported
PTP Form:	Not reported
Program:	Property Transfer Program
Comments:	Not reported
Site Type Definition:	Not reported
Invesigation Start:	Not reported
Invesigation Start Date:	11/22/2021
Remediation Start:	Not reported
Remediation Start Date:	Not reported
Remediation Completed:	Yes
ELUR:	No
Date Data Updated:	Not reported

ENFORCEMENT:

Name:	EBL PRODUCTS INC.
Address:	22 PRESTIGE PARK CIR
City,State,Zip:	EAST HARTFORD, CT 06108
Enforcement Action ID:	043-1857/1601-0515
Enforcement Type Code:	Notice Of Violation
Program Id:	Not reported
Enforcement Action Date:	06/08/2016
Penalty Amount:	$0.00
Sep Amt:	Not reported
Bureau Name:	Air Management
Program:	Radiation Enforcement
Status:	Closed
Date of Discovery:	04/05/2016
Resolution Date:	11/07/2016
Resolution Type:	Returned to compliance

EBL PRODUCTS INC. (Continued) **S111285719**

Staff:	Zwick Andrew
ENF Action Comment:	Failure to register.
Number Violations:	1
Civil Penalty:	Not reported
SEP Description:	Not reported
Associated EIs:	Not reported
Client Affiliation Type:	Respondent
Affiliation Name:	PINE ENVIRONMENTAL SERVICES LLC
Affiliation Address Line1:	PO Box 943
Affiliation Address Line2:	Not reported
Affiliation City/State/Zip:	Hightstown, NJ 08520 0943
Contact Title:	COO
Contact Name:	KIM DA SILVA
Contact EMail:	KDASILVA@PINE-ENVIRONMENTAL.COM

Name:	EBL PRODUCTS INC.
Address:	22 PRESTIGE PARK CIR
City,State,Zip:	EAST HARTFORD, CT 06108
Enforcement Action ID:	NOVWSWDH11069
Enforcement Type Code:	Notice Of Violation
Program Id:	Not reported
Enforcement Action Date:	09/22/2011
Penalty Amount:	$0.00
Sep Amt:	Not reported
Bureau Name:	Materials Management & Compliance Assurance
Program:	Hazardous Waste Enforcement
Status:	Closed
Date of Discovery:	07/19/2011
Resolution Date:	10/24/2011
Resolution Type:	Returned to compliance
Staff:	Clements Kevin
ENF Action Comment:	Not reported
Number Violations:	4
Civil Penalty:	Not reported
SEP Description:	Not reported
Associated EIs:	Not reported
Client Affiliation Type:	Respondent
Affiliation Name:	EBL PRODUCTS, INC.
Affiliation Address Line1:	22 Prestige Park Cir
Affiliation Address Line2:	Not reported
Affiliation City/State/Zip:	East Hartford, CT 06108 1917
Contact Title:	Not reported
Contact Name:	Not reported
Contact EMail:	Not reported

CT MANIFEST:

Name:	EBL PRODUCTS INC
Address:	22 PRESTIGE PARK CIRCLE
City,State,Zip:	EAST HARTFORD, CT
Phone:	Not reported
Country:	Not reported
Manifest ID:	Not reported
EPA ID:	CTR000509998

Hazardous Waste Manifest:

Year:	2016

EBL PRODUCTS INC. (Continued) **S111285719**

Manifest:	016487711JJK
EPA ID:	CTR000509998
Generator Mailing Address:	Not reported
Generator City,State,Zip:	Not reported
Discrepancies:	Not reported
Date Shipped:	2016-09-13
Date Received:	Not reported
Transporter 2 Date:	Not reported
TSDF EPA ID:	Not reported
TSDF Name:	Not reported
TSDF Address:	Not reported
TSDF City,State,Zip:	Not reported
TSDF Country:	Not reported
Transporter EPA ID:	Not reported
Transporter Name:	Not reported
Transporter Address:	Not reported
Transporter City,State,Zip:	Not reported
Transporter Country:	Not reported
Transporter 2 EPA ID:	Not reported
Transporter 2 Name:	Not reported
Transporter 2 Address:	Not reported
Transporter 2 City,State,Zip:	Not reported
Transporter 2 Country:	Not reported
US DOT Description:	Not reported
Number of Containers:	Not reported
Container Type:	Not reported
Quantity/Weight/Volume:	/
Batch Number:	Not reported
EPA Waste Codes:	- Not reported
Copies:	Not reported
Alternate Facility Name:	Not reported
Alternate Facility Address:	Not reported
Alternate Facility State:	Not reported
Alternate Facility Date:	Not reported

DEEP Document:

Year:	2016
EPA ID:	CTR000509998
Statuory Program:	Hazardous Waste
Document Number:	016487711JJK
Document:	Hazardous Waste Manifest
File Type:	Written Text
Reference ID:	Ref ID: 016487711JJK Alt ID: CTR000509998

Click Here to view the image from agency website:

NPDES:

Name:	EBL PRODUCTS INC.
Address:	22 PRESTIGE PARK CIR
City:	EAST HARTFORD
Town Id:	Not reported
Company Name:	Not reported
Permit Number:	GSI002391
Permit Issued Date:	10/01/2011
Permit Expiration Date:	09/30/2024
Application Received Date:	Not reported

EBL PRODUCTS INC. (Continued) **S111285719**

Affiliation Type:	Permittee
Permit EI Type:	Stormwater Industrial Activities - GP
App Id:	201104803
Site Address Description:	Not reported
Site Address Line 2:	Not reported
Permit Description:	Not reported
Status:	Active
Affiliate Address Line 1:	22 Prestige Park Cir
Affiliate Address Line 2:	Not reported
Affiliate City/State/Zip:	East Hartford, CT 06108-1917
Contact Name:	ANDREW TREMBLAY
Contact Title:	VICE PRESIDENT
Contact EMail:	Not reported

L69 **ENERGY NETWORKS INC DIV OF CNG** **CT PROPERTY** **S125683975**
NNW **111 PRESTIGE PARK RD** **CT CPCS** **N/A**
1/4-1/2 **EAST HARTFORD, CT 06108** **CT MANIFEST**
0.447 mi.
2362 ft. **Site 1 of 4 in cluster L**

Relative: **Lower**
Actual: **58 ft.**

CT Property:

Name:	111 PRESTIGE PARK ROAD
Address:	111 PRESTIGE PARK ROAD
City,state,zip:	EAST HARTFORD, CT
Seller Name:	Fremont Prestige Park, LLC
Buyer Name:	ACG Prestige Acquisitions LLC
Certifying Party:	Fremont Prestige Park, LLC
Certifying Attention Person:	Jonathan Keller
Title Of Certifying Person:	Manager
Certifying Person Address:	65 LaSalle Road, Suite 202
Certifying Person City,St,Zip:	West Hartford, CT
Property Transfer Forms:	Form III (DEP-PERD-PTP-203) when a discharge, spillage, uncontrolled loss, seepage or filtration of hazardous waste has occurred at the parcel that has not been fully remediated or the environmental conditions at the parcel are unknown. The person signing the Form III certification agrees to investigate and remediate the site in accordance with the remediation standards. The statute does not require completion of remediation before the parcel is transferred. Any person submitting a Form III shall simultaneously submit a completed Environmental Condition Assessment Form (ECAF)(DEP-PERD-PTP-200).
Date Recieved:	07/08/2021
Ackn Date:	11/22/2021
Determination Date:	Not reported
LEP Verified/DEP Approval Date:	Not reported
Rem Id:	14712
Remediation Location Id:	10544
Date Entered:	10/20/2021
Program:	Property Transfer Program
GAO Site:	False
Staff Full Name:	Jan Czeczotka
Super/Date:	11/22/2021
Stage Of Project:	Not reported
RP Level Of Activity:	Not reported
RP Needed Level Of Activity:	Not reported
Staff Level Of Activity:	Not reported
Staff Needed Level Of Activity:	Not reported
Public Intrest:	Not reported

ENERGY NETWORKS INC DIV OF CNG (Continued) **S125683975**

PRP Cooperation:	Not reported
Enforcement Status:	Not reported
Level Of Complexity:	Not reported
Complex Eng Or Sci:	Not reported
Complex Due To Public Involvement:	Not reported
Politically Complex:	Not reported
Complex Enforcement:	Not reported
Coordination With Other Bureaus:	Not reported
EPA Involvement:	Not reported
Staff Prefrence:	Not reported
Readiness For Transfer:	Not reported
Project Transfer Time:	Not reported
Transfer Comments:	Not reported
Staff As Of July 2000:	Not reported
Initial Staff:	Not reported
Type Of Transfer:	Real Estate
Salutation:	Mr. Keller
Relationship To Transfer:	Transferor
Audit Date:	Not reported
Verif Type:	Not reported
Audit Outcome:	Not reported
GW:	GB
Basin:	Not reported
1st Payment:	3000
Pay Tag1:	039945
2nd Payment:	Not reported
Pay Tag2:	Not reported
RTN:	Not reported
Revised:	Not reported
ECAF Received:	Not reported
Old Determination Date:	Not reported
Redeterminationdate:	Not reported
Previous Determination:	Not reported
Monitoringoption:	Not reported
Postremedialmonitoring:	Not reported
Schedule Of I/R:	Not reported
Schedule Overdue:	Not reported
Aprvl Sched:	Not reported
Yr 1 Report:	Not reported
Yr 2 Report:	Not reported
Report Overdue:	Not reported
Ext Aprvl Sched:	Not reported
License #:	Not reported
Project Phase:	Not reported
PT Comments:	Not reported
EPA Id Number:	Not reported
GW Class:	Not reported
SW Class:	Not reported
AO/C0:	Not reported
Water Lead(Y Or N):	Not reported
Priority:	Not reported
Project Status(A, I Or D):	Not reported
Last Updated:	Not reported
SR Comments:	Not reported
Priority Or Work-Load:	Not reported
Status:	Not reported
Notes:	Not reported

ENERGY NETWORKS INC DIV OF CNG (Continued) **S125683975**

Special Project Name:	Not reported
Special Project Comments:	Not reported
DOT Project:	Not reported
Pt Counter:	Not reported
Project Complete:	Not reported
Project Inactive:	Not reported
Int Deposit #:	Not reported
Deposit #:	Not reported
Spill Case #:	Not reported
Diversion Id:	Not reported
Public Notice:	Not reported
RAP Received:	Not reported
RAP Approved:	Not reported
Compliance Category:	Not reported
Delete Record:	Not reported
ECAF Reviewed By:	Not reported
Not Locatable:	Not reported
Primary Address:	Not reported
AKA Site Name:	Not reported
Primary Site Name:	Not reported
AKA Site Address:	Not reported
Lead:	LEP

CPCS:

Name:	111 Prestige Park Road
Address:	111 PRESTIGE PARK ROAD
City,State,Zip:	EAST HARTFORD, CT
Site Type:	Not reported
Lust Status code:	Not reported
Lust Status:	Not reported
PTP Form:	Not reported
Program:	Property Transfer Program
Comments:	Not reported
Site Type Definition:	Not reported
Invesigation Start:	Not reported
Invesigation Start Date:	11/22/2021
Remediation Start:	Not reported
Remediation Start Date:	Not reported
Remediation Completed:	Yes
ELUR:	No
Date Data Updated:	Not reported

CT MANIFEST:

Name:	ENERGY NETWORKS INC DIV OF CNG
Address:	111 PRESTIGE PARK RD
City,State,Zip:	EAST HARTFORD, CT 06108
Phone:	Not reported
Country:	Not reported
Manifest ID:	CTF0012035
EPA ID:	CTP000011909

Hazardous Waste Manifest:

Year:	1991
Manifest:	CTF0012035
EPA ID:	CTP000011909
Generator Mailing Address:	111 PRESTIGE PARK RD

ENERGY NETWORKS INC DIV OF CNG (Continued) **S125683975**

Generator City,State,Zip:	EAST HARTFORD, CT 06108
Discrepancies:	N
Date Shipped:	1991-02-11
Date Received:	1991-02-11
Transporter 2 Date:	Not reported
TSDF EPA ID:	CTD021816889
TSDF Name:	UNITED OIL RECOVERY INC
TSDF Address:	136 GRACEY AVE
TSDF City,State,Zip:	MERIDEN, CT 06450
TSDF Country:	USA
Transporter EPA ID:	CTD021816889
Transporter Name:	UNITED OIL RECOVERY INC
Transporter Address:	Not reported
Transporter City,State,Zip:	CT
Transporter Country:	USA
Transporter 2 EPA ID:	Not reported
Transporter 2 Name:	Not reported
Transporter 2 Address:	Not reported
Transporter 2 City,State,Zip:	CT
Transporter 2 Country:	USA
US DOT Description:	WASTE LIQ NOS OIL W/III TRIC
Number of Containers:	001
Container Type:	DM
Quantity/Weight/Volume:	165/G
Batch Number:	999999
EPA Waste Codes:	F002 - THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Copies:	1
Alternate Facility Name:	Not reported
Alternate Facility Address:	Not reported
Alternate Facility State:	Not reported
Alternate Facility Date:	Not reported

L70 **PRESTIGE INDUSTRIAL PARK** **UST FINDER RELEASE** **1029093230**
NNW **121 PRESTIGE PARK ROAD (121 PRESTIGE PARK CIRCLE)** **N/A**
1/4-1/2 **EAST HARTFORD, CT 6108**
0.453 mi.
2391 ft. **Site 2 of 4 in cluster L**

Relative: UST FINDER RELEASE:
Lower

Actual: **58 ft.**

Object ID:	85388
Facility ID:	Not reported
Lust ID:	CT35517
Name:	PRESTIGE INDUSTRIAL PARK
Address:	121 PRESTIGE PARK ROAD (121 PRESTIGE PARK CIRCLE)
City,State,Zip:	EAST HARTFORD, CT 6108
Address Match Type:	PointAddress
Reported Date:	1992/01/09 15:59:59+00
Status:	Open
Substance:	Not reported
Population within 1500ft:	668

PRESTIGE INDUSTRIAL PARK (Continued) **1029093230**

Domestic Wells within 1500ft:	2
Land Use:	Developed, Medium Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	1
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	Geocode
X Coord:	-72.6031
Y Coord:	41.7861
Latitude:	41.7860999999999
Longitude:	-72.6030999999999

L71 **CT LUST** **S118549881**
NNW **121 PRESTIGE PARK ROAD** **N/A**
1/4-1/2 **EAST HARTFORD, CT**
0.453 mi.
2391 ft. **Site 3 of 4 in cluster L**

Relative: **Lower**

Actual: **58 ft.**

LUST:

Name:	Not reported
Name 2:	Not reported
Address:	121 PRESTIGE PARK ROAD
Address 2:	Not reported
City,State,Zip:	EAST HARTFORD, CT
LUST Case Id:	35517
Release Date:	01/09/1992
Site Case ID:	43-5115
Substance:	Gasoline
Release Source:	Other
Release Cause:	Unknown
Release Identified:	Removal/Closure
Case Number:	1992-00125
Release Quantity:	Unknown
Facility City Number:	Not reported

Detail As of 06/2020:

Name:	PRESTIGE INDUSTRIAL PARK
Name 2:	Not reported
Address:	121 PRESTIGE PARK ROAD (121 PRESTIGE PARK CIRCLE)
City,State,Zip:	EAST HARTFORD, CT 06108
Address 2:	Not reported
LUST Id:	7466
UST Facility Id:	5115
LUST Case Id:	35517

(Continued) **S118549881**

Lust Status:	RSRs Reached
Processing Status:	Not reported
EPA Reportable:	True
Motor Fuel:	True
Diesel:	False
Gasoline:	True
Other:	False
Other Release:	Not reported
No Release:	False
Leak:	False
Tank:	False
Piping:	False
Overfill:	False
Removal:	False
Incident Date:	01/09/1992
Entry Date:	Not reported
Site Case Id:	Not reported
UST Site Id:	Not reported
Cost Recovery Spill Case #:	Not reported
Old SITS Number:	9200125
Case Log Id:	Not reported
Monthly Report Id:	0
UST Owner Id:	525
LUST Owner Id:	Not reported
UST Event Id:	7587
Contact Info:	Not reported
Contact EMail:	Not reported
Site Contact City,St,Zip:	UNKNOWN
2nd Contact:	John Adams (Rizzo Associates, a Terta Tech Company)
2nd Contact EMail:	Not reported
2nd Contact Address:	150 Trumbull Street
2nd Contact City,St,Zip:	64, CT 06103
2nd Contact Address 2:	4th Floor
2nd Contact City 2:	Hartford
2nd Contact Phone Number:	8605498430
2nd Contact Fax Number:	8605498422
2nd Contact Type:	LEP
Facility City Num:	43
Site Contact:	Not reported
Site Contact Address:	Not reported
Site Contact Add 2:	Not reported
Site Contact City 2:	Not reported
Site Contact Phone:	Not reported
Site Contact Fax:	Not reported
Site Contact Type:	Not reported
Department Contact 1:	Not reported
Department Contact 2:	Not reported
Referral Source:	Not reported
Offsite Source:	False
Date Referred:	Not reported
Emergency:	False
Private Heating Fuel:	False
Commercial Heating Fuel:	False
Commercial HF < 2100 Gal.:	False
Commercial HF > 2100 Gal.:	False
Commercial HF - Size Unk:	False
No LUST Site:	False

(Continued) **S118549881**

Cost Recvry Prgm Candidate:	False
OCSRD Complete:	False
Follow Up Flag:	False
Alternate Water Supply:	False
Relocation:	False
Responsible Party:	False
Responsible EMail:	Not reported
Resp Party Name:	Beckenstein Enterprises
Resp Party Address:	183 Prestige Park Road
Resp Party City,St,Zip:	East Hartford, CT 061081923
Resp Party Town Number:	43
Resp Party Phone:	8602897924
Resp Party Fax:	Not reported
Resp Party Name 2:	Not reported
Resp Party Address 2:	P.O. Box 8228
Resp Party Phone 2:	Not reported
Investigator Id:	27
Follow Update:	Not reported
Area Lextent:	Not reported
Annual Precipitation:	Not reported
Affected Population:	Not reported
Population Setting:	Not reported
Ground Water Direction:	Not reported
Ground Water Gradient:	Not reported
Hydro Basin:	Not reported
Drastic:	Not reported
Geo Setting:	Not reported
Ground Water Classification:	GB
Receptor:	Not reported
Ground Water Flow Direction:	Not reported
Ground Water Depth:	2.86-4.48 ftbg
Areas Of Concern:	Not reported
Free Product Inches:	Not reported
Fund Date:	Not reported
Fund Planned:	No
Fund Obligated:	No
Fund Outlayed:	No
Fund Judgment:	No
Fund Recovered:	No
Cellar Borings:	False
Install Micro Wells:	False
Ground Water Sample:	False
Soil Sample:	False
Soil Gas:	False
Site Inspect:	False
Soil Excavate:	False
Geo Probe:	False
Survey:	False
Potable Well Sample:	False
Sample MWS:	False
Ground Water Gauging:	False
Soil Venting:	False
Active:	False
NOV Action:	None
NOV Issued:	Not reported
NOV Due:	Not reported
NOV Received:	Not reported

(Continued) **S118549881**

NOV Closed:	Not reported
NOV Disc Date:	Not reported
NOV Issued Date:	Not reported
NOV Compliance Sched:	Not reported
NOV Admin Order:	Not reported
NOV Referred To Ag:	Not reported
Stop All NOV Actions:	False
Release Invest Rpt:	False
DEP App Letter 1:	False
Correct Action Plan:	False
DEP App Letter 2:	False
Rem Sys Install:	False
Rem Sys Install Date:	Not reported
Closure Date:	Not reported
Rem Sys Monitoring Rpt:	False
Qrtly Gwater Mon Rpts:	False
Closure Req Rpt:	False
DEP Closure Letter:	False
Referred To:	Not reported
No Wells:	10
Lph Wells:	Not reported
User Stamp:	forresta/forresta
Date Stamp:	08/30/2016
Correspondence:	Not reported
Environmental Impact:	Not reported
FollowUp:	Not reported
GW Comments:	Site is serviced by public water supply.
Location Desc:	Not reported
NOV Comments:	Not reported
Release Desc:	Not reported
Running Comments:	Spills Files, UST Enforcement Files, Remediation Files, and LUST FilesLetter of No-Audit issued by Remediation Division on 1/22/2015
Work Performed:	Not reported

L72 **PRESTIGE INDUSTRIAL PARK** **CT CPCS** **S130328338**
NNW **121 PRESTIGE PARK ROAD (121 PRESTIGE PARK CIRCLE)** **N/A**
1/4-1/2 **EAST HARTFORD, CT**
0.453 mi.
2391 ft. **Site 4 of 4 in cluster L**

Relative: CPCS:
Lower

Name:	Prestige Industrial Park
Address:	121 PRESTIGE PARK ROAD (121 PRESTIGE PARK CIRCLE)
City,State,Zip:	EAST HARTFORD, CT
Site Type:	Not reported
Lust Status code:	Not reported
Lust Status:	Not reported
PTP Form:	Not reported
Program:	LUST
Comments:	Not reported
Site Type Definition:	Not reported
Invesigation Start:	Yes
Invesigation Start Date:	Not reported
Remediation Start:	Yes
Remediation Start Date:	Not reported
Remediation Completed:	Yes
ELUR:	Not reported

Actual:
58 ft.

PRESTIGE INDUSTRIAL PARK (Continued) **S130328338**

Date Data Updated: 01/09/1992

M73 **ATLAS OIL** **CT SDADB** **S104253700**
WNW **422 TOLLAND STREET** **CT CPCS** **N/A**
1/4-1/2 **EAST HARTFORD, CT**
0.453 mi.
2393 ft. **Site 1 of 2 in cluster M**

Relative: **Lower**
Actual: **52 ft.**

Site Discovery and Assessment:

Facility ID:	2505
Rem Master ID:	2848
PTP Id:	Not reported
WPC Number:	Not reported
Postal District:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Determined By:	Not reported
Ground Water Quality Classification:	Not reported
Surface Water Quality Classification:	Not reported
Waste Type:	HYDRO/OIL
Disposal:	UST
Sample Data Available:	False
Updated By:	MCDANIEL, M.
Update Program:	D&A
Updated:	6/21/1995
Date Created:	Not reported
Duplicate:	False

SDA Federal:

EPA CERCLIS Id:	Not reported
Number EPA RCRIS Id:	Not reported
Site on EPA's CERCLIS:	Not reported
Site Archived from CERCLIS:	Not reported
Archive Date:	Not reported
EPA's Removal at Site:	Not reported
Deferred to another EPA Program:	Not reported
EPA Env Priority Initiative Site:	Not reported
Federal Facility:	Not reported
Site on EPA's National Priority List:	Not reported
Part of an NPL site:	Not reported
RCRA Generator Status:	Not reported
RCRA Permit Status:	Not reported

SDA Referral:

Referral Id:	2322
Source of referral:	SPILLS
Date Received:	5/25/1995
Staff Assigned:	Not reported
Remediation Program:	Not reported
Date dt_assigned:	Not reported
Remediation Complete Approved DEP/Verified by LEP:	Not reported
Outcome:	Not reported

SDA Remedial:

Remedial Id:	Not reported
PTP Id:	Not reported
Remediation Program:	Not reported
Remediation Program Entered:	Not reported
Staff Assigned:	Not reported

ATLAS OIL (Continued) **S104253700**

Remediation Program:	Not reported
Date dt_assign:	Not reported
Project Phase:	Not reported
Order issued:	Not reported
Order Number:	Not reported
Date order issued:	Not reported
Remedial Investigation Start:	Not reported
Remedial Investigation Completed:	Not reported
Remedial Design Start:	Not reported
Remedial Design complet:	Not reported
Remedial Action Start:	Not reported
Remedial Action Completed:	Not reported
Date Oper/ maintenance Started:	Not reported
GW monitoring:	Not reported
Remediation complete Approved DEP/Verified by LEP:	Not reported

SDA Orders:

Order Id:	Not reported
Order Number:	Not reported
Date order issued:	Not reported
Staff Assigned:	Not reported
Type of Order:	Not reported
Order Respondent:	Not reported
Admin Appeal Date:	Not reported
Date of Admin Appeal Ruling:	Not reported
Date of Admin Appeal Ruling:	Not reported
Date of Final Order:	Not reported
Date of Court Appeal:	Not reported
Date of Court Ruling:	Not reported
Date of Court Ruling:	Not reported
Date Order Modified:	Not reported
Date Referred to AG:	Not reported
Judgement:	Not reported
Date of AGR judgement:	Not reported
Penalty assessed:	Not reported
Order Complete:	Not reported
In compliance:	Not reported
Comments:	Not reported

SDADB:

SDA Waste:

Waste Id:	11
Waste Type:	HYDRO/OIL
Description:	Hydrocarbons and/or Fuel Oil

CPCS:

Name:	Atlas Oil
Address:	422 TOLLAND STREET
City,State,Zip:	EAST HARTFORD, CT
Site Type:	Not reported
Lust Status code:	Not reported
Lust Status:	Not reported
PTP Form:	Not reported
Program:	LUST
Comments:	Not reported
Site Type Definition:	Not reported

ATLAS OIL (Continued) **S104253700**

Invesigation Start:	Yes
Invesigation Start Date:	Not reported
Remediation Start:	Yes
Remediation Start Date:	Not reported
Remediation Completed:	No
ELUR:	Not reported
Date Data Updated:	05/22/1995

M74 **CT LUST** **S104098538**
WNW **422 TOLLAND ST** **CT SPILLS** **N/A**
1/4-1/2 **EAST HARTFORD, CT**
0.453 mi.
2393 ft. **Site 2 of 2 in cluster M**

Relative: **Lower**
Actual: **52 ft.**

LUST:

Name:	Not reported
Name 2:	Not reported
Address:	422 TOLLAND STREET
Address 2:	Not reported
City,State,Zip:	EAST HARTFORD, CT
LUST Case Id:	35512
Release Date:	09/22/1995
Site Case ID:	43-5227
Substance:	Gasoline and Diesel
Release Source:	Unknown
Release Cause:	Unknown
Release Identified:	Reported to DEP
Case Number:	1995-02721
Release Quantity:	Unknown
Facility City Number:	Not reported

Detail As of 06/2020:

Name:	ATLAS OIL
Name 2:	Not reported
Address:	422 TOLLAND STREET
City,State,Zip:	EAST HARTFORD, CT 06108
Address 2:	Not reported
LUST Id:	7461
UST Facility Id:	5225
LUST Case Id:	35512
Lust Status:	Cleanup Initiated
Processing Status:	Not reported
EPA Reportable:	False
Motor Fuel:	True
Diesel:	False
Gasoline:	True
Other:	False
Other Release:	Not reported
No Release:	False
Leak:	False
Tank:	False
Piping:	False
Overfill:	False
Removal:	False
Incident Date:	05/22/1995
Entry Date:	Not reported
Site Case Id:	Not reported
UST Site Id:	484

(Continued) **S104098538**

Cost Recovery Spill Case #:	Not reported
Old SITS Number:	199502721
Case Log Id:	Not reported
Monthly Report Id:	0
UST Owner Id:	428
LUST Owner Id:	Not reported
UST Event Id:	7582
Contact Info:	Not reported
Contact EMail:	Not reported
Site Contact City,St,Zip:	UNKNOWN
2nd Contact:	Joseph Santovasi (Advanced Environmental Interface)
2nd Contact EMail:	Not reported
2nd Contact Address:	438 Smith Street
2nd Contact City,St,Zip:	83, CT 06457
2nd Contact Address 2:	Not reported
2nd Contact City 2:	Middletown
2nd Contact Phone Number:	2036357753
2nd Contact Fax Number:	Not reported
2nd Contact Type:	Not reported
Facility City Num:	43
Site Contact:	Not reported
Site Contact Address:	Not reported
Site Contact Add 2:	Not reported
Site Contact City 2:	Not reported
Site Contact Phone:	Not reported
Site Contact Fax:	Not reported
Site Contact Type:	Not reported
Department Contact 1:	Not reported
Department Contact 2:	Not reported
Referral Source:	Not reported
Offsite Source:	False
Date Referred:	Not reported
Emergency:	False
Private Heating Fuel:	False
Commercial Heating Fuel:	False
Commercial HF < 2100 Gal.:	False
Commercial HF > 2100 Gal.:	False
Commercial HF - Size Unk:	False
No LUST Site:	False
Cost Recvry Prgm Candidate:	False
OCSRD Complete:	False
Follow Up Flag:	False
Alternate Water Supply:	False
Relocation:	False
Responsible Party:	False
Responsible EMail:	Not reported
Resp Party Name:	Atlas Oil Company
Resp Party Address:	P.O. Box 380616
Resp Party City,St,Zip:	East Hartford, CT 061380616
Resp Party Town Number:	43
Resp Party Phone:	2032898888
Resp Party Fax:	Not reported
Resp Party Name 2:	Not reported
Resp Party Address 2:	Not reported
Resp Party Phone 2:	Not reported
Investigator Id:	35
Follow Update:	Not reported

(Continued) **S104098538**

Area Lextent:	Not reported
Annual Precipitation:	Not reported
Affected Population:	Not reported
Population Setting:	Not reported
Ground Water Direction:	Not reported
Ground Water Gradient:	Not reported
Hydro Basin:	Not reported
Drastic:	Not reported
Geo Setting:	Not reported
Ground Water Classification:	GB
Receptor:	Not reported
Ground Water Flow Direction:	Not reported
Ground Water Depth:	Not reported
Areas Of Concern:	Not reported
Free Product Inches:	Not reported
Fund Date:	Not reported
Fund Planned:	No
Fund Obligated:	No
Fund Outlayed:	No
Fund Judgment:	No
Fund Recovered:	No
Cellar Borings:	False
Install Micro Wells:	True
Ground Water Sample:	True
Soil Sample:	True
Soil Gas:	False
Site Inspect:	False
Soil Excavate:	False
Geo Probe:	False
Survey:	False
Potable Well Sample:	False
Sample MWS:	True
Ground Water Gauging:	False
Soil Venting:	True
Active:	False
NOV Action:	None
NOV Issued:	Not reported
NOV Due:	Not reported
NOV Received:	Not reported
NOV Closed:	Not reported
NOV Disc Date:	Not reported
NOV Issued Date:	Not reported
NOV Compliance Sched:	Not reported
NOV Admin Order:	Not reported
NOV Referred To Ag:	Not reported
Stop All NOV Actions:	False
Release Invest Rpt:	False
DEP App Letter 1:	False
Correct Action Plan:	False
DEP App Letter 2:	False
Rem Sys Install:	False
Rem Sys Install Date:	Not reported
Closure Date:	Not reported
Rem Sys Monitoring Rpt:	False
Qrtly Gwater Mon Rpts:	False
Closure Req Rpt:	False
DEP Closure Letter:	False

(Continued) **S104098538**

Referred To:	Not reported
No Wells:	Not reported
Lph Wells:	Not reported
User Stamp:	forresta/forresta
Date Stamp:	01/22/2016
Correspondence:	Not reported
Environmental Impact:	Not reported
FollowUp:	Not reported
GW Comments:	Not reported
Location Desc:	Not reported
NOV Comments:	Not reported
Release Desc:	Not reported
Running Comments:	Spills Files, UST Enforcement Files, Cleanup Fund Files, Open LUST Cases:0095-02721 is linked to CF 484 (same spill case # and CF account is also used for release at 414 Tolland Street)
Work Performed:	Not reported

SPILLS:

Name:	Not reported
Address:	422 TOLLAND ST
City,State,Zip:	EAST HARTFORD, CT
Year of Database:	1995
Case Number:	2721
Who Took Spill:	CIASULLO
Assigned To:	Not reported
Report Date:	05/22/1995
Report Time:	1419
Date Release:	Not reported
Release Time:	Not reported
Reported By:	JOE SANTOVASI
Phone:	Not reported
Qty:	. (Gallons)
Telephone:	Not reported
Representing:	Not reported
Facility Status:	Not reported
Continuous Spill:	Not reported
Release Substance:	Not reported
Emergency Measure:	Not reported
Discharger:	Not reported
Waterbody Affected:	POSSIBLE GROUNDWATER
Responsible Party:	Not reported
Responsible Party Address:	Not reported
RP City,St,Zip:	Not reported
Terminated:	Y
Recovered Total:	.
Total Water:	.
Historic:	Not reported
Waterbody:	Not reported
User Stamp:	Not reported
Stamp Time:	Not reported
SR Inspector:	Not reported
AT Inspector:	Not reported
Corrective Action Taken:	Not reported
Cause Info:	Not reported
Media Info:	Not reported
Release Type:	Not reported

(Continued) **S104098538**

Incident Description:	Not reported
Cost Recovery Case?:	Not reported
DEMHS Region:	Not reported
Lat/Long:	Not reported
Company Name:	Not reported
Last Updated:	Not reported

SPILLS:

Year of Database:	1995
Town of Spill:	EAST HARTFORD
Case Number:	2721
OCSRD Inspector:	NR
Spill Date:	05/22/95
Spill Time:	. .
Report Date:	05/22/95
Report Time:	1419
Reported By:	JOE SANTOVASI
Representing:	A E I/ATLAS OIL
Work Telephone:	2036
Home Telephone:	.
Telephone Pole#:	.
Incident Type:	PETROLEUM
Substance:	GASOLINE
Quantity:	. Gallon(s)
Concentration:	.
Action Desc:	Not reported
On Going:	Not reported
Continuous Spill:	Not reported
Release Status:	Terminated, Contained
Misc Info:	(3) 6K GASOLINE 5 YR OLD TANKS - HISTORICAL CONTAM ENCOUNTERED NO SOIL REMOVED SAMPLES TAKEN OF GRAVE BEFORE BACKFILLED
Water Body:	POSSIBLE GROUNDWATER
Other Media:	Not reported
Release Area:	Groundwater, Ground Surface
Total (Water):	.
Recovd (Water):	.
Recovd (Total):	.
Polluter Name:	ATLAS OIL
Polluted Address:	422 TOLLAND ST
Polluted City,St,Zip:	EAST HARTFORD, CT .
Polluter Phone:	.- .- .
Polluter Responisbility:	Polluter accepts financial reponsibility
Unknown Responsibility:	Not reported
Unknown Polluter:	Not reported
Cleanup Action:	Not reported
Dun and Bradst#:	Not reported
UST Unit:	Not reported
Agency Notified:	Not reported
State Agency:	Not reported
Notify Date:	.
Notify Time:	. .
Other Agency:	Not reported
Notify Other:	Not reported
Notify Status:	Not reported
Class1:	Commercial
Class:	9, ., .
Cause:	30, ., ., HISTORIC CONTAM

(Continued) **S104098538**

Actions:	21, 12, .
Cleanup Contractor:	Not reported
Contractor Name:	Not reported
Did DEP Hire Contractor:	Not reported
Date Contractor Hired:	.
When Contractor Requested:	.: .
When Contractor Arrived:	.: .
Who Took Spill:	CIASULLO
Badge # of Who Recieved Spill:	912
Who Assigned Spill:	NR
Badge # of Who Assigned Spill:	.
Date Assigned:	.
Assigned Time:	.: .
Spill Status:	Closed
Case 1136:	Not reported
Federal 311K:	.
Case #1:	Not reported
Case #2:	.
Cost Recovery:	.
Property Owner:	Not reported
Property Other:	.
Property Name:	Not reported
Property Addr:	Not reported
Property CSZ:	.
Polluter:	Not reported
Owner:	Not reported
Operator:	Not reported
Vehicle Make:	Not reported
Vehicle Model:	Not reported
Truck Reg:	Not reported
Trail Reg:	Not reported
Additional Info:	REFERRED TO WATER MNGMNT
Updated:	Not reported
Update Date:	.

N75 **ADAPTIVE OPTICS ASSOCIATES** **CT PROPERTY** **1000380776**
NNE **121 PRESTIGE PARK CIRCLE** **RCRA NonGen / NLR** **CTD010160513**
1/4-1/2 **EAST HARTFORD, CT 06108** **FINDS**
0.455 mi. **ECHO**
2400 ft. **Site 1 of 3 in cluster N** **E MANIFEST**
CT CPCS

Relative:
Lower

Actual:
71 ft.

CT Property:

Name:	JERSEY TAB CARD CORP. (FORMER)
Address:	121 PRESTIGE PARK CIRCLE
City,state,zip:	EAST HARTFORD, CT
Seller Name:	Tolland Enterprises
Buyer Name:	Fremont Prestige Park LLC
Certifying Party:	Freemont Prestige Park, LLC
Certifying Attention Person:	Jonathan M. Keller
Title Of Certifying Person:	Member
Certifying Person Address:	c/o Fremont Group,CityPlace II,185 Asylum St
Certifying Person City,St,Zip:	Hartford, CT 06103
Property Transfer Forms:	Form III (DEP-PERD-PTP-203) when a discharge, spillage, uncontrolled loss, seepage or filtration of hazardous waste has occurred at the

ADAPTIVE OPTICS ASSOCIATES (Continued) **1000380776**

	parcel that has not been fully remediated or the environmental conditions at the parcel are unknown. The person signing the Form III certification agrees to investigate and remediate the site in accordance with the remediation standards. The statute does not require completion of remediation before the parcel is transferred. Any person submitting a Form III shall simultaneously submit a completed Environmental Condition Assessment Form (ECAF)(DEP-PERD-PTP-200).
Date Recieved:	11/06/2000
Ackn Date:	11/17/2000
Determination Date:	01/26/2001
LEP Verified/DEP Approval Date:	2015-01-22 00:00:00
Rem Id:	1095
Remediation Location Id:	6283
Date Entered:	Not reported
Program:	Property Transfer Program
GAO Site:	False
Staff Full Name:	Not reported
Super/Date:	Not reported
Stage Of Project:	Not reported
RP Level Of Activity:	Not reported
RP Needed Level Of Activity:	Not reported
Staff Level Of Activity:	Not reported
Staff Needed Level Of Activity:	Not reported
Public Intrest:	Not reported
PRP Cooperation:	Not reported
Enforcement Status:	Not reported
Level Of Complexity:	Not reported
Complex Eng Or Sci:	False
Complex Due To Public Involvement:	False
Politically Complex:	False
Complex Enforcement:	False
Coordination With Other Bureaus:	False
EPA Involvement:	False
Staff Prefrence:	Not reported
Readiness For Transfer:	Not reported
Project Transfer Time:	Not reported
Transfer Comments:	Not reported
Staff As Of July 2000:	Not reported
Initial Staff:	Not reported
Type Of Transfer:	Not reported
Salutation:	Mr. Keller
Relationship To Transfer:	transferee
Audit Date:	Not reported
Verif Type:	Not reported
Audit Outcome:	Not reported
GW:	GB
Basin:	Not reported
1st Payment:	2000
Pay Tag1:	Not reported
2nd Payment:	Not reported
Pay Tag2:	Not reported
RTN:	Not reported
Revised:	Not reported
ECAF Received:	Not reported
Old Determination Date:	Not reported
Redeterminationdate:	Not reported

ADAPTIVE OPTICS ASSOCIATES (Continued) **1000380776**

Previous Determination:	Not reported
Monitoringoption:	Not reported
Postremedialmonitoring:	Not reported
Schedule Of I/R:	02/22/2001
Schedule Overdue:	Not reported
Aprvl Sched:	Not reported
Yr 1 Report:	2002-08-20 00:00:00
Yr 2 Report:	2005-03-04 00:00:00
Report Overdue:	Not reported
Ext Aprvl Sched:	Not reported
License #:	Not reported
Project Phase:	6
PT Comments:	Not reported
EPA Id Number:	Not reported
GW Class:	Not reported
SW Class:	Not reported
AO/C0:	Not reported
Water Lead(Y Or N):	Not reported
Priority:	Not reported
Project Status(A, I Or D):	Not reported
Last Updated:	Not reported
SR Comments:	Not reported
Priority Or Work-Load:	Not reported
Status:	Not reported
Notes:	Not reported
Special Project Name:	Not reported
Special Project Comments:	Not reported
DOT Project:	Not reported
Pt Counter:	0
Project Complete:	False
Project Inactive:	False
Int Deposit #:	Not reported
Deposit #:	Not reported
Spill Case #:	Not reported
Diversion Id:	Not reported
Public Notice:	Not reported
RAP Received:	Not reported
RAP Approved:	Not reported
Compliance Category:	O
Delete Record:	False
ECAF Reviewed By:	Not reported
Not Locatable:	False
Primary Address:	True
AKA Site Name:	False
Primary Site Name:	True
AKA Site Address:	False
Lead:	LEP

RCRA Listings:

Date Form Received by Agency:	19800619
Handler Name:	Jersey Tab Card Corp
Handler Address:	Prestige Park Cir
Handler City,State,Zip:	EAST HARTFORD, CT 06108
EPA ID:	CTD010160513
Contact Name:	Not reported
Contact Address:	Not reported
Contact City,State,Zip:	Not reported

ADAPTIVE OPTICS ASSOCIATES (Continued) **1000380776**

Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		01
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		PRESTIGE PARK CIR
Mailing City,State,Zip:		EAST HARTFORD, CT 06108
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20150414
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No

ADAPTIVE OPTICS ASSOCIATES (Continued) **1000380776**

Manifest Broker: No
Sub-Part P Indicator: No

Historic Generators:
Receive Date: 19800619
Handler Name: JERSEY TAB CARD CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110003011204

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000380776
Registry ID: 110003011204

DFR URL:
Name: JERSEY TAB CARD CORP
Address: 121 Prestige Park Cir
City,State,Zip: EAST HARTFORD, CT 06108

E MANIFEST:
Manifest Tracking Number: 018330653FLE

ADAPTIVE OPTICS ASSOCIATES (Continued) **1000380776**

Last Updated Date:	20230410
Shipped Date:	20230306
Received Date:	20230316
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CTCESQG99999
Generator Name:	Adaptive Optics
Generator Location Street Number:	Not reported
Generator Location Street 1:	121 PRESTIGE PARK CIRCLE
Generator Location Street 2:	Not reported
Generator Location City:	EAST HARTFORD
Generator Location State:	CT
Generator Location Zip:	06108
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	121 Prestige Park Circle
Generator Mail Street 2:	Not reported
Generator Mail City:	East Hartford
Generator Mail Zip:	06108
Generator Mail State:	CT
Generator Contact Company Name:	Adaptive Optics
Designated Facility EPA ID:	KYD053348108
Designated Facility Name:	Safety-Kleen Systems, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	3700 LaGrange Road
Designated Facility Mail City:	Smithfield
Designated Facility Mail Zip:	40068
Designated Facility Mail State:	KY
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	3700 LaGrange Road
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Smithfield
Designated Facility Location Zip:	40068
Designated Facility Location State:	KY
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	015373040FLE
Last Updated Date:	20210611
Shipped Date:	20210427
Received Date:	20210515
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CTCESQGXXXXX
Generator Name:	Adaptive Optics Associates
Generator Location Street Number:	Not reported
Generator Location Street 1:	121 PRESTIGE PARK CIRCLE
Generator Location Street 2:	Not reported
Generator Location City:	EAST HARTFORD
Generator Location State:	CT
Generator Location Zip:	06108
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	115 JACKSON ROAD
Generator Mail Street 2:	Not reported

ADAPTIVE OPTICS ASSOCIATES (Continued) **1000380776**

Generator Mail City:	DEVENS
Generator Mail Zip:	01434
Generator Mail State:	MA
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	OHD048415665
Designated Facility Name:	Ross Incineration Services Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	36790 GILES RD
Designated Facility Mail Street 2:	ROSS INCINERATION SERVICES, IN
Designated Facility Mail City:	GRAFTON
Designated Facility Mail Zip:	44044
Designated Facility Mail State:	OH
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	36790 GILES RD
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	GRAFTON
Designated Facility Location Zip:	44044
Designated Facility Location State:	OH
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	015373799FLE
Last Updated Date:	20211011
Shipped Date:	20210907
Received Date:	20210925
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CTCESQGXXXXX
Generator Name:	Adaptive Optics Associates
Generator Location Street Number:	Not reported
Generator Location Street 1:	121 PRESTIGE PARK CIRCLE
Generator Location Street 2:	Not reported
Generator Location City:	EAST HARTFORD
Generator Location State:	CT
Generator Location Zip:	06108
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	115 JACKSON ROAD
Generator Mail Street 2:	Not reported
Generator Mail City:	DEVENS
Generator Mail Zip:	01434
Generator Mail State:	MA
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	OHD048415665
Designated Facility Name:	Ross Incineration Services Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	36790 GILES RD
Designated Facility Mail Street 2:	ROSS INCINERATION SERVICES, IN
Designated Facility Mail City:	GRAFTON
Designated Facility Mail Zip:	44044
Designated Facility Mail State:	OH
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	36790 GILES RD
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	GRAFTON
Designated Facility Location Zip:	44044

ADAPTIVE OPTICS ASSOCIATES (Continued) **1000380776**

Designated Facility Location State:	OH
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N
Manifest Tracking Number:	017797512FLE
Last Updated Date:	20230411
Shipped Date:	20230306
Received Date:	20230318
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CTCESQG99999
Generator Name:	Adaptive Optics
Generator Location Street Number:	Not reported
Generator Location Street 1:	121 PRESTIGE PARK CIRCLE
Generator Location Street 2:	Not reported
Generator Location City:	EAST HARTFORD
Generator Location State:	CT
Generator Location Zip:	06108
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	121 Prestige Park Circle
Generator Mail Street 2:	Not reported
Generator Mail City:	East Hartford
Generator Mail Zip:	06108
Generator Mail State:	CT
Generator Contact Company Name:	Adaptive Optics
Designated Facility EPA ID:	NCD000648451
Designated Facility Name:	Clean Harbors Reidsville Llc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	208 Watlington Industrial Drive
Designated Facility Mail City:	Reidsville
Designated Facility Mail Zip:	27320
Designated Facility Mail State:	NC
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	208 Watlington Industrial Drive
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Reidsville
Designated Facility Location Zip:	27320
Designated Facility Location State:	NC
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N
Manifest Tracking Number:	011110835FLE
Last Updated Date:	20181101
Shipped Date:	20181017
Received Date:	20181023
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CTCESQGXXXXX
Generator Name:	Adaptive Optics Associates
Generator Location Street Number:	Not reported
Generator Location Street 1:	121 PRESTIGE PARK CIRCLE
Generator Location Street 2:	Not reported

ADAPTIVE OPTICS ASSOCIATES (Continued) **1000380776**

Generator Location City:	EAST HARTFORD
Generator Location State:	CT
Generator Location Zip:	06108
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	10 Wilson Road
Generator Mail Street 2:	Not reported
Generator Mail City:	Cambridge
Generator Mail Zip:	06108
Generator Mail State:	MA
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD980536593
Designated Facility Name:	Veolia Es Technical Solutions Llc
Designated Facility Mail Street Number:	1
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	1 EDEN LANE
Designated Facility Mail City:	FLANDERS
Designated Facility Mail Zip:	07836
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	1
Designated Facility Location Street 1:	1 EDEN LANE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	FLANDERS
Designated Facility Location Zip:	07836
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	013312326FLE
Last Updated Date:	20200225
Shipped Date:	20200122
Received Date:	20200208
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CTCESQGXXXXX
Generator Name:	Adaptive Optics Associates
Generator Location Street Number:	Not reported
Generator Location Street 1:	121 PRESTIGE PARK CIRCLE
Generator Location Street 2:	Not reported
Generator Location City:	EAST HARTFORD
Generator Location State:	CT
Generator Location Zip:	06108
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	121 PRESTIGE PARK CIRCLE
Generator Mail Street 2:	Not reported
Generator Mail City:	EAST HARTFORD
Generator Mail Zip:	06108
Generator Mail State:	CT
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	OHD048415665
Designated Facility Name:	Ross Incineration Services Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	36790 GILES RD
Designated Facility Mail City:	GRAFTON
Designated Facility Mail Zip:	44044

ADAPTIVE OPTICS ASSOCIATES (Continued) **1000380776**

Designated Facility Mail State:	OH
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	36790 GILES RD
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	GRAFTON
Designated Facility Location Zip:	44044
Designated Facility Location State:	OH
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	018844230FLE
Last Updated Date:	20230630
Shipped Date:	20230531
Received Date:	20230609
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CTCESQG99999
Generator Name:	Adaptive Optics
Generator Location Street Number:	Not reported
Generator Location Street 1:	121 PRESTIGE PARK CIRCLE
Generator Location Street 2:	Not reported
Generator Location City:	EAST HARTFORD
Generator Location State:	CT
Generator Location Zip:	06108
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	121 Prestige Park Circle
Generator Mail Street 2:	Not reported
Generator Mail City:	East Hartford
Generator Mail Zip:	06108
Generator Mail State:	CT
Generator Contact Company Name:	Adaptive Optics
Designated Facility EPA ID:	RID084802842
Designated Facility Name:	Safety-Kleen Systems, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	167 Mill Street
Designated Facility Mail City:	Cranston
Designated Facility Mail Zip:	02905
Designated Facility Mail State:	RI
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	167 Mill Street
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Cranston
Designated Facility Location Zip:	02905
Designated Facility Location State:	RI
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	018844230FLE
Transporter Line Number:	1
Transporter EPA ID:	MAD039322250
Transporter Name:	Clean Harbors Environmental Services, Inc.

ADAPTIVE OPTICS ASSOCIATES (Continued) **1000380776**

Waste Line:

Manifest Tracking Number:	018844230FLE
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	UN1993
U.S. DOT Description:	Un1993, Waste Flammable Liquids, N.O.S. (Isopropanol, Acetone), 3, Pg Ii
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	CF
Container Type Description:	Fiber or plastic boxes, cartons, cases
Waste Quantity:	46
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.023
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.023
Waste Quantity, in Kilograms:	20.86169
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	20.86169
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D001, D035
Quantity Haz Kg:	20.86169
Quantity Haz Tons:	0.023
Quantity Non Haz Kg:	Not reported
Quantity Non Haz Tons:	Not reported
State Waste Codes:	Not reported

Manifest Tracking Number:	018844230FLE
Waste Line Number:	2
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	UN3264
U.S. DOT Description:	Un3264, Waste Corrosive Liquid, Acidic, Inorganic, N.O.S. (Nitric Acid, Chromic Acid), 8, Pg Ii
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	DF
Container Type Description:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	9
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.0045

ADAPTIVE OPTICS ASSOCIATES (Continued) **1000380776**

Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.0045
Waste Quantity, in Kilograms:	4.081635
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	4.081635
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D002, D007
Quantity Haz Kg:	4.081635
Quantity Haz Tons:	0.0045
Quantity Non Haz Kg:	Not reported
Quantity Non Haz Tons:	Not reported
State Waste Codes:	Not reported

Manifest Tracking Number:	018844230FLE
Waste Line Number:	3
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	UN2790
U.S. DOT Description:	Un2790, Waste Acetic Acid Solution, Not Less Than 50 Percent But Not More Than 80 Percent Acid, By Mass, 8, Pg Ii
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	DF
Container Type Description:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	3
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.0015
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.0015
Waste Quantity, in Kilograms:	1.360545
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	1.360545
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported

ADAPTIVE OPTICS ASSOCIATES (Continued) **1000380776**

Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D002
Quantity Haz Kg:	1.360545
Quantity Haz Tons:	0.0015
Quantity Non Haz Kg:	Not reported
Quantity Non Haz Tons:	Not reported
State Waste Codes:	Not reported
Manifest Tracking Number:	018844230FLE
Waste Line Number:	4
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	UN3262
U.S. DOT Description:	Un3262, Corrosive Solid, Basic, Inorganic, N.O.S. (Calcium Hydroxide), 8, Pg Ii
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	CF
Container Type Description:	Fiber or plastic boxes, cartons, cases
Waste Quantity:	52
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.026
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.026
Waste Quantity, in Kilograms:	23.58278
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	23.58278
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	N
Federal Waste Codes:	Not reported
Quantity Haz Kg:	Not reported
Quantity Haz Tons:	Not reported
Quantity Non Haz Kg:	23.58278
Quantity Non Haz Tons:	0.026
State Waste Codes:	CT-CR05
Manifest Tracking Number:	018844230FLE
Waste Line Number:	5

ADAPTIVE OPTICS ASSOCIATES (Continued) **1000380776**

U.S. DOT Hazardous Indicator:	N
U.S. DOT ID Number:	Not reported
U.S. DOT Description:	Not reported
Non-Hazardous Waste Description:	None, Non Dot Regulated Material, N/A, None, (Non Pcb Ballast)
Number of Containers:	1
Container Type Code:	DF
Container Type Description:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	50
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.025
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.025
Waste Quantity, in Kilograms:	22.67575
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	22.67575
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	N
Federal Waste Codes:	Not reported
Quantity Haz Kg:	Not reported
Quantity Haz Tons:	Not reported
Quantity Non Haz Kg:	22.67575
Quantity Non Haz Tons:	0.025
State Waste Codes:	CT-CR05

CPCS:

Name:	Jersey Tab Card Corp. (Former)
Address:	121 PRESTIGE PARK CIRCLE
City,State,Zip:	EAST HARTFORD, CT
Site Type:	Not reported
Lust Status code:	Not reported
Lust Status:	Not reported
PTP Form:	Not reported
Program:	Property Transfer Program
Comments:	Not reported
Site Type Definition:	Not reported
Invesigation Start:	Not reported
Invesigation Start Date:	11/17/2000
Remediation Start:	Not reported
Remediation Start Date:	Not reported
Remediation Completed:	Yes
ELUR:	No
Date Data Updated:	Not reported

O76 **CHESTER/FORBES PROPERTIES** **US BROWNFIELDS** **1025442191**
SSE **10 CHESTER STREET AND 192A FORBES STREET** **N/A**
1/4-1/2 **EAST HARTFORD, CT 06108**
0.458 mi.
2416 ft. **Site 1 of 2 in cluster O**

Relative:
Higher

Actual:
75 ft.

US BROWNFIELDS:

Name:	Chester/Forbes Properties
Address:	10 Chester Street And 192a Forbes Street
City,State,Zip:	EAST HARTFORD, CT 06108
Property ID:	236794
Property Alias:	Not reported
Recipient Name:	East Hartford Town of
Grant Type:	Hazardous
Property Number:	Not reported
Parcel Size:	1.04
Latitude:	41.7722443
Longitude:	-72.6029532
Census Tract:	9003510500
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase I
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	No Contaminants
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96196901
Start Date:	Not reported
Ownership Entity:	Not reported
Additional Institutional Controls Information:	Not reported
Completion Date:	Not reported
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	N
Indicates Cleanup/Treatment Tech Implemented:	Not reported
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported

CHESTER/FORBES PROPERTIES (Continued) **1025442191**

Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	Not reported
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Other Media
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	N
Past use commercial acreage:	Not reported
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	N
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported

CHESTER/FORBES PROPERTIES (Continued) **1025442191**

Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	496
Below Poverty Percent:	19.54
Meidan Income:	3829
Meidan Income Number:	1162
Meidan Income Percent:	45.77
Vacant Housing Number:	61
Vacant Housing Percent:	5.82
Unemployed Number:	173
Unemployed Percent:	6.81

Name:	Chester/Forbes Properties
Address:	10 Chester Street And 192a Forbes Street
City,State,Zip:	EAST HARTFORD, CT 06108
Property ID:	236794
Property Alias:	Not reported
Recipient Name:	East Hartford Town of
Grant Type:	Hazardous
Property Number:	Not reported
Parcel Size:	1.04
Latitude:	41.7722443
Longitude:	-72.6029532
Census Tract:	9003510500
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Phase I
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase I
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	No Contaminants
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96196901
Start Date:	2018-01-24 00:00:00
Ownership Entity:	Not reported
Additional Institutional Controls Information:	Not reported
Completion Date:	2018-04-13 00:00:00
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	N
Indicates Cleanup/Treatment Tech Implemented:	Not reported
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported

CHESTER/FORBES PROPERTIES (Continued) **1025442191**

Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	Not reported
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Other Media
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	N
Past use commercial acreage:	Not reported
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported

CHESTER/FORBES PROPERTIES (Continued) **1025442191**

Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	N
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	496
Below Poverty Percent:	19.54
Meidan Income:	3829
Meidan Income Number:	1162
Meidan Income Percent:	45.77
Vacant Housing Number:	61
Vacant Housing Percent:	5.82
Unemployed Number:	173
Unemployed Percent:	6.81

Name:	Chester/Forbes Properties
Address:	10 Chester Street And 192a Forbes Street
City,State,Zip:	EAST HARTFORD, CT 06108
Property ID:	236794
Property Alias:	Not reported
Recipient Name:	East Hartford Town of
Grant Type:	Hazardous
Property Number:	Not reported
Parcel Size:	1.04
Latitude:	41.7722443
Longitude:	-72.6029532
Census Tract:	9003510500
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase I
Assessment Funding:	420000
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	No Contaminants
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Habitat for Humanity
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	10/1/2020
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96196901

CHESTER/FORBES PROPERTIES (Continued) **1025442191**

Start Date:	Not reported
Ownership Entity:	Not reported
Additional Institutional Controls Information:	Not reported
Completion Date:	Not reported
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	N
Indicates Cleanup/Treatment Tech Implemented:	Not reported
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	Not reported
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Other Media
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported

CHESTER/FORBES PROPERTIES (Continued) **1025442191**

RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	Not reported
Past use commercial acreage:	Not reported
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	Not reported
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	496
Below Poverty Percent:	19.54
Meidan Income:	3829
Meidan Income Number:	1162
Meidan Income Percent:	45.77
Vacant Housing Number:	61
Vacant Housing Percent:	5.82
Unemployed Number:	173
Unemployed Percent:	6.81

Name:	Chester/Forbes Properties
Address:	10 Chester Street And 192a Forbes Street
City,State,Zip:	EAST HARTFORD, CT 06108
Property ID:	236794
Property Alias:	Not reported
Recipient Name:	East Hartford Town of
Grant Type:	Hazardous
Property Number:	Not reported
Parcel Size:	1.04
Latitude:	41.7722443
Longitude:	-72.6029532
Census Tract:	9003510500
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase I
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported

CHESTER/FORBES PROPERTIES (Continued) **1025442191**

Contaminants Found at Actionable Level:	No Contaminants
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96196901
Start Date:	Not reported
Ownership Entity:	Not reported
Additional Institutional Controls Information:	Not reported
Completion Date:	Not reported
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	N
Indicates Cleanup/Treatment Tech Implemented:	Not reported
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	Not reported
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Other Media
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported

CHESTER/FORBES PROPERTIES (Continued) **1025442191**

RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	Not reported
Past use commercial acreage:	Not reported
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	Not reported
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	496
Below Poverty Percent:	19.54
Meidan Income:	3829
Meidan Income Number:	1162
Meidan Income Percent:	45.77
Vacant Housing Number:	61
Vacant Housing Percent:	5.82
Unemployed Number:	173
Unemployed Percent:	6.81

O77 **CHESTER/FORBES PROPERTIES** **CT BROWNFIELDS** **S128966171**
SSE **10 CHESTER STREET AND 192A FORBES STREET** **N/A**
1/4-1/2 **EAST HARTFORD, CT**
0.458 mi.
2416 ft. **Site 2 of 2 in cluster O**

Relative:
Higher

Actual:
75 ft.

BROWNFIELDS 2:

Region:	2
Data Source CD:	EPA
Data Source:	EPA Funded Brownfields Project
Parcel ID Number:	0920-0010
Latitude:	41.772344
Longitude:	-72.602417
Site Acreage:	0.69
Program Approval Date:	Not reported

P78
NNE
1/4-1/2
0.478 mi.
2522 ft.

QUALEX, INC.
88 PRESTIGE PARK CIRCLE
EAST HARTFORD, CT 06108

Site 1 of 2 in cluster P

CT CPCS **S104876744**
N/A

Relative:
Lower

Actual:
62 ft.

CPCS:

Name:	Qualex, Inc.
Address:	88 PRESTIGE PARK CIRCLE
City,State,Zip:	EAST HARTFORD, CT 06108
Site Type:	Not reported
Lust Status code:	Not reported
Lust Status:	Not reported
PTP Form:	III
Program:	Property Transfer Program
Comments:	Projects
Site Type Definition:	Property Transfer Form III
Invesigation Start:	Not reported
Invesigation Start Date:	04/21/2006
Remediation Start:	Not reported
Remediation Start Date:	Not reported
Remediation Completed:	No
ELUR:	No
Date Data Updated:	Not reported

Name:	Qualex, Inc.
Address:	88 PRESTIGE PARK CIRCLE
City,State,Zip:	EAST HARTFORD, CT 06108
Site Type:	Not reported
Lust Status code:	Not reported
Lust Status:	Not reported
PTP Form:	III
Program:	Property Transfer Program
Comments:	Projects
Site Type Definition:	Property Transfer Form III
Invesigation Start:	Not reported
Invesigation Start Date:	11/17/2000
Remediation Start:	Not reported
Remediation Start Date:	Not reported
Remediation Completed:	No
ELUR:	No
Date Data Updated:	Not reported

Name:	Qualex, Inc.
Address:	88 PRESTIGE PARK CIRCLE
City,State,Zip:	EAST HARTFORD, CT 06108
Site Type:	Not reported
Lust Status code:	Not reported
Lust Status:	Not reported
PTP Form:	III
Program:	Property Transfer Program
Comments:	Projects
Site Type Definition:	Property Transfer Form III
Invesigation Start:	Not reported
Invesigation Start Date:	10/03/2014
Remediation Start:	Not reported
Remediation Start Date:	Not reported
Remediation Completed:	No
ELUR:	No

QUALEX, INC. (Continued) **S104876744**

Date Data Updated: Not reported

P79 **QUALEX INC.** **CT SDADB** **S104942771**
NNE **88 PRESTIGE PARK CIRCLE** **N/A**
1/4-1/2 **EAST HARTFORD, CT**
0.478 mi.
2522 ft. **Site 2 of 2 in cluster P**

Relative: **Lower**
Actual: **62 ft.**

Site Discovery and Assessment:

Facility ID:	5551
Rem Master ID:	4904
PTP Id:	0
WPC Number:	Not reported
Postal District:	Not reported
Latitude:	0
Longitude:	0
Lat/Long Determined By:	Not reported
Ground Water Quality Classification:	GB
Surface Water Quality Classification:	B
Waste Type:	CHLR VOC, SEMI VOC, METALS
Disposal:	Not reported
Sample Data Available:	True
Updated By:	Not reported
Update Program:	Not reported
Updated:	Not reported
Date Created:	Not reported
Duplicate:	False

SDA Federal:

EPA CERCLIS Id:	Not reported
Number EPA RCRIS Id:	Not reported
Site on EPA's CERCLIS:	Not reported
Site Archived from CERCLIS:	Not reported
Archive Date:	Not reported
EPA's Removal at Site:	Not reported
Deferred to another EPA Program:	Not reported
EPA Env Priority Initiative Site:	Not reported
Federal Facility:	Not reported
Site on EPA's National Priority List:	Not reported
Part of an NPL site:	Not reported
RCRA Generator Status:	Not reported
RCRA Permit Status:	Not reported

SDA Referral:

Referral Id:	Not reported
Source of referral:	Not reported
Date Received:	Not reported
Staff Assigned:	Not reported
Remediation Program:	Not reported
Date dt_assigned:	Not reported
Remediation Complete Approved DEP/Verified by LEP:	Not reported
Outcome:	Not reported

SDA Remedial:

Remedial Id:	Not reported
PTP Id:	Not reported
Remediation Program:	Not reported
Remediation Program Entered:	Not reported
Staff Assigned:	Not reported

QUALEX INC. (Continued) **S104942771**

Remediation Program:	Not reported
Date dt_assign:	Not reported
Project Phase:	Not reported
Order issued:	Not reported
Order Number:	Not reported
Date order issued:	Not reported
Remedial Investigation Start:	Not reported
Remedial Investigation Completed:	Not reported
Remedial Design Start:	Not reported
Remedial Design complet:	Not reported
Remedial Action Start:	Not reported
Remedial Action Completed:	Not reported
Date Oper/ maintenance Started:	Not reported
GW monitoring:	Not reported
Remediation complete Approved DEP/Verified by LEP:	Not reported

SDA Orders:

Order Id:	Not reported
Order Number:	Not reported
Date order issued:	Not reported
Staff Assigned:	Not reported
Type of Order:	Not reported
Order Respondent:	Not reported
Admin Appeal Date:	Not reported
Date of Admin Appeal Ruling:	Not reported
Date of Admin Appeal Ruling:	Not reported
Date of Final Order:	Not reported
Date of Court Appeal:	Not reported
Date of Court Ruling:	Not reported
Date of Court Ruling:	Not reported
Date Order Modified:	Not reported
Date Referred to AG:	Not reported
Judgement:	Not reported
Date of AGR judgement:	Not reported
Penalty assessed:	Not reported
Order Complete:	Not reported
In compliance:	Not reported
Comments:	Not reported

SDADB:

SDA Waste:

Waste Id:	5
Waste Type:	CHLR VOC
Description:	Chlorinated Volatile Organic Compounds

N80 **CT BUSINESS SYSTEMS** **CT PROPERTY** **1000165351**
NNE **265 PRESTIGE PARK RD** **RCRA NonGen / NLR** **CTD124038266**
1/4-1/2 **EAST HARTFORD, CT 06108** **FINDS**
0.489 mi. **ECHO**
2581 ft. **Site 2 of 3 in cluster N** **CT CPCS**

Relative: CT Property:
Lower

Name:	CT BUSINESS SYSTEMS & JD OFFICE FURNITURE
Address:	265 PRESTIGE PARK ROAD
City,state,zip:	EAST HARTFORD, CT
Seller Name:	Tolland Enterprises
Buyer Name:	Fremont Prestige Park, LLC

Actual:
72 ft.

CT BUSINESS SYSTEMS (Continued) **1000165351**

Certifying Party:	Tolland Enterprises
Certifying Attention Person:	Arthur Beckenstein
Title Of Certifying Person:	Partner
Certifying Person Address:	183 Prestige Park Road
Certifying Person City,St,Zip:	East Hartford, CT 06108
Property Transfer Forms:	Form I (DEP-PERD-PTP-201) when no release of hazardous waste has occurred at the parcel being transferred.
Date Recieved:	11/06/2000
Ackn Date:	02/07/2001
Determination Date:	Not reported
LEP Verified/DEP Approval Date:	Not reported
Rem Id:	1098
Remediation Location Id:	6285
Date Entered:	Not reported
Program:	Property Transfer Program
GAO Site:	False
Staff Full Name:	Jan Czeczotka
Super/Date:	02/16/2001
Stage Of Project:	Not reported
RP Level Of Activity:	Not reported
RP Needed Level Of Activity:	Not reported
Staff Level Of Activity:	Not reported
Staff Needed Level Of Activity:	Not reported
Public Intrest:	Not reported
PRP Cooperation:	Not reported
Enforcement Status:	Not reported
Level Of Complexity:	Not reported
Complex Eng Or Sci:	False
Complex Due To Public Involvement:	False
Politically Complex:	False
Complex Enforcement:	False
Coordination With Other Bureaus:	False
EPA Involvement:	False
Staff Prefrence:	Not reported
Readiness For Transfer:	Not reported
Project Transfer Time:	Not reported
Transfer Comments:	Not reported
Staff As Of July 2000:	Not reported
Initial Staff:	Not reported
Type Of Transfer:	Real Estate
Salutation:	Mr. Beckenstein
Relationship To Transfer:	transferor
Audit Date:	Not reported
Verif Type:	Not reported
Audit Outcome:	Not reported
GW:	Not reported
Basin:	Not reported
1st Payment:	200
Pay Tag1:	Not reported
2nd Payment:	Not reported
Pay Tag2:	Not reported
RTN:	12/20/2000
Revised:	1/24/2001
ECAF Received:	Not reported
Old Determination Date:	Not reported
Redeterminationdate:	Not reported
Previous Determination:	Not reported

CT BUSINESS SYSTEMS (Continued) **1000165351**

Monitoringoption:	Not reported
Postremedialmonitoring:	Not reported
Schedule Of I/R:	Not reported
Schedule Overdue:	Not reported
Aprvl Sched:	Not reported
Yr 1 Report:	Not reported
Yr 2 Report:	Not reported
Report Overdue:	Not reported
Ext Aprvl Sched:	Not reported
License #:	Not reported
Project Phase:	Not reported
PT Comments:	Not reported
EPA Id Number:	Not reported
GW Class:	Not reported
SW Class:	Not reported
AO/C0:	Not reported
Water Lead(Y Or N):	Not reported
Priority:	Not reported
Project Status(A, I Or D):	Not reported
Last Updated:	Not reported
SR Comments:	Not reported
Priority Or Work-Load:	Not reported
Status:	Not reported
Notes:	Not reported
Special Project Name:	Not reported
Special Project Comments:	Not reported
DOT Project:	Not reported
Pt Counter:	0
Project Complete:	False
Project Inactive:	False
Int Deposit #:	Not reported
Deposit #:	Not reported
Spill Case #:	Not reported
Diversion Id:	Not reported
Public Notice:	Not reported
RAP Received:	Not reported
RAP Approved:	Not reported
Compliance Category:	Not reported
Delete Record:	False
ECAF Reviewed By:	Not reported
Not Locatable:	False
Primary Address:	True
AKA Site Name:	False
Primary Site Name:	True
AKA Site Address:	False
Lead:	LEP

RCRA Listings:

Date Form Received by Agency:	19871115
Handler Name:	Ct Business Systems
Handler Address:	Prestige Park Rd
Handler City,State,Zip:	EAST HARTFORD, CT 06108
EPA ID:	CTD124038266
Contact Name:	PETER-O WENZKE
Contact Address:	265 PRESTIGE PARK RD
Contact City,State,Zip:	EAST HARTFORD, CT 06108
Contact Telephone:	203-289-7972

CT BUSINESS SYSTEMS (Continued) **1000165351**

Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		01
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		PRESTIGE PARK RD
Mailing City,State,Zip:		EAST HARTFORD, CT 06108
Owner Name:	Tolland Enterprises	
Owner Type:		Private
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20150414
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No

CT BUSINESS SYSTEMS (Continued) **1000165351**

Sub-Part P Indicator: No

Hazardous Waste Summary:
Waste Code: D000
Waste Description: Not Defined

Waste Code: D001
Waste Description: Ignitable Waste

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: TOLLAND ENTERPRISES
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: OWNERSTREET
Owner/Operator City,State,Zip: OWNERCITY, CT 99999
Owner/Operator Telephone: 203-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19871115
Handler Name: CT BUSINESS SYSTEMS
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110003020640

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System

CT BUSINESS SYSTEMS (Continued) **1000165351**

(RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000165351
Registry ID:	110003020640

DFR URL:

Name:	CT BUSINESS SYSTEMS
Address:	265 Prestige Park Rd
City,State,Zip:	EAST HARTFORD, CT 06108

CPCS:

Name:	Ct Business Systems & Jd Office Furniture
Address:	265 PRESTIGE PARK ROAD
City,State,Zip:	EAST HARTFORD, CT
Site Type:	Not reported
Lust Status code:	Not reported
Lust Status:	Not reported
PTP Form:	Not reported
Program:	Property Transfer Program
Comments:	Not reported
Site Type Definition:	Not reported
Invesigation Start:	Not reported
Invesigation Start Date:	02/07/2001
Remediation Start:	Not reported
Remediation Start Date:	Not reported
Remediation Completed:	No
ELUR:	No
Date Data Updated:	Not reported

N81 **BAUSCH & LOMB ASTRONOMICAL TELESCOPES** **CT PROPERTY** **1000145987**
NNE **135 PRESTIGE PK CIR** **RCRA NonGen / NLR** **CTD001149665**
1/4-1/2 **EAST HARTFORD, CT 06108** **FINDS**
0.489 mi. **ECHO**
2581 ft. **Site 3 of 3 in cluster N** **CT CPCS**

Relative:
Lower

Actual:
72 ft.

CT Property:

Name:	DYNAGE, INC. (FORMER)
Address:	135 PRESTIGE PARK CIRCLE
City,state,zip:	EAST HARTFORD, CT
Seller Name:	Tolland Enterprises
Buyer Name:	Fremont Prestige Park, LLC
Certifying Party:	Tolland Enterprises
Certifying Attention Person:	Arthur Beckenstein
Title Of Certifying Person:	Partner
Certifying Person Address:	183 Prestige Park Road
Certifying Person City,St,Zip:	East Hartford, CT 06108
Property Transfer Forms:	Form I (DEP-PERD-PTP-201) when no release of hazardous waste has occurred at the parcel being transferred.
Date Recieved:	11/06/2000
Ackn Date:	02/07/2001

BAUSCH & LOMB ASTRONOMICAL TELESCOPES (Continued) **1000145987**

Determination Date:	Not reported
LEP Verified/DEP Approval Date:	Not reported
Rem Id:	1100
Remediation Location Id:	6287
Date Entered:	Not reported
Program:	Property Transfer Program
GAO Site:	False
Staff Full Name:	Jan Czeczotka
Super/Date:	02/16/2001
Stage Of Project:	Not reported
RP Level Of Activity:	Not reported
RP Needed Level Of Activity:	Not reported
Staff Level Of Activity:	Not reported
Staff Needed Level Of Activity:	Not reported
Public Intrest:	Not reported
PRP Cooperation:	Not reported
Enforcement Status:	Not reported
Level Of Complexity:	Not reported
Complex Eng Or Sci:	False
Complex Due To Public Involvement:	False
Politically Complex:	False
Complex Enforcement:	False
Coordination With Other Bureaus:	False
EPA Involvement:	False
Staff Prefrence:	Not reported
Readiness For Transfer:	Not reported
Project Transfer Time:	Not reported
Transfer Comments:	Not reported
Staff As Of July 2000:	Not reported
Initial Staff:	Not reported
Type Of Transfer:	Real Estate
Salutation:	Mr. Beckenstein
Relationship To Transfer:	transferor
Audit Date:	Not reported
Verif Type:	Not reported
Audit Outcome:	Not reported
GW:	Not reported
Basin:	Not reported
1st Payment:	200
Pay Tag1:	Not reported
2nd Payment:	Not reported
Pay Tag2:	Not reported
RTN:	12/20/2000
Revised:	1/24/2001
ECAF Received:	Not reported
Old Determination Date:	Not reported
Redeterminationdate:	Not reported
Previous Determination:	Not reported
Monitoringoption:	Not reported
Postremedialmonitoring:	Not reported
Schedule Of I/R:	Not reported
Schedule Overdue:	Not reported
Aprvl Sched:	Not reported
Yr 1 Report:	Not reported
Yr 2 Report:	Not reported
Report Overdue:	Not reported
Ext Aprvl Sched:	Not reported

BAUSCH & LOMB ASTRONOMICAL TELESCOPES (Continued) **1000145987**

License #:	Not reported
Project Phase:	Not reported
PT Comments:	Not reported
EPA Id Number:	Not reported
GW Class:	Not reported
SW Class:	Not reported
AO/C0:	Not reported
Water Lead(Y Or N):	Not reported
Priority:	Not reported
Project Status(A, I Or D):	Not reported
Last Updated:	Not reported
SR Comments:	Not reported
Priority Or Work-Load:	Not reported
Status:	Not reported
Notes:	Not reported
Special Project Name:	Not reported
Special Project Comments:	Not reported
DOT Project:	Not reported
Pt Counter:	0
Project Complete:	False
Project Inactive:	False
Int Deposit #:	Not reported
Deposit #:	Not reported
Spill Case #:	Not reported
Diversion Id:	Not reported
Public Notice:	Not reported
RAP Received:	Not reported
RAP Approved:	Not reported
Compliance Category:	Not reported
Delete Record:	False
ECAF Reviewed By:	Not reported
Not Locatable:	False
Primary Address:	True
AKA Site Name:	False
Primary Site Name:	True
AKA Site Address:	False
Lead:	LEP

RCRA Listings:

Date Form Received by Agency:	19830708
Handler Name:	Dynage Inc
Handler Address:	Prestige Park Cir
Handler City,State,Zip:	EAST HARTFORD, CT 06108
EPA ID:	CTD001149665
Contact Name:	JACK WILLARD
Contact Address:	135 PRESTIGE PARK CIR
Contact City,State,Zip:	EAST HARTFORD, CT 06108
Contact Telephone:	203-289-6831
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	01
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported

BAUSCH & LOMB ASTRONOMICAL TELESCOPES (Continued) **1000145987**

Active Site Indicator:		Not reported
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		PRESTIGE PARK CIR
Mailing City,State,Zip:		EAST HARTFORD, CT 06108
Owner Name:	Oakleaf Sid	
Owner Type:		Private
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20150414
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No
Sub-Part P Indicator:		No

Hazardous Waste Summary:

Waste Code:	F001
Waste Description:	The Following Spent Halogenated Solvents Used In Degreasing: Tetrachloroethylene, Trichlorethylene, Methylene Chloride, 1,1,1-Trichloroethane, Carbon Tetrachloride And Chlorinated Fluorocarbons; All Spent Solvent Mixtures/Blends Used In Degreasing

BAUSCH & LOMB ASTRONOMICAL TELESCOPES (Continued) **1000145987**

Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: OAKLEAF SID	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	OWNERSTREET
Owner/Operator City,State,Zip:	OWNERCITY, CT 99999
Owner/Operator Telephone:	203-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19830708
Handler Name: DYNAGE INC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Has the Facility Received Notices of Violations:

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported

BAUSCH & LOMB ASTRONOMICAL TELESCOPES (Continued) **1000145987**

Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

BAUSCH & LOMB ASTRONOMICAL TELESCOPES (Continued) **1000145987**

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	19980526
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	FOCUSED COMPLIANCE INSPECTION
Evaluation Responsible Person Identifier:	R1CMG
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19980526
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	FOCUSED COMPLIANCE INSPECTION
Evaluation Responsible Person Identifier:	R1CMG

BAUSCH & LOMB ASTRONOMICAL TELESCOPES (Continued) **1000145987**

Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19870204
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

FINDS:
Registry ID: 110006178858

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.
Registry ID: 110002479719

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000145987
Registry ID: 110006178858

DFR URL:
Name: DYNAGE INCORPORATED
Address: 135 Prestige Park Circle
City,State,Zip: EAST HARTFORD, CT 06108

BAUSCH & LOMB ASTRONOMICAL TELESCOPES (Continued) **1000145987**

Envid: 1000145987
Registry ID: 110002479719

DFR URL:
Name: BAUSCH & LOMB ASTRONOMICAL TELESCOPES
Address: 135 Prestige Pk Cir
City,State,Zip: EAST HARTFORD, CT 06108

CPCS:
Name: Dynage, Inc. (Former)
Address: 135 PRESTIGE PARK CIRCLE
City,State,Zip: EAST HARTFORD, CT
Site Type: Not reported
Lust Status code: Not reported
Lust Status: Not reported
PTP Form: Not reported
Program: Property Transfer Program
Comments: Not reported
Site Type Definition: Not reported
Invesigation Start: Not reported
Invesigation Start Date: 02/07/2001
Remediation Start: Not reported
Remediation Start Date: Not reported
Remediation Completed: No
ELUR: No
Date Data Updated: Not reported

Q82 **ATLAS OIL** **UST FINDER RELEASE** **1028943040**
WNW **414 TOLLAND STREET** **N/A**
1/4-1/2 **EAST HARTFORD, CT 61082**
0.496 mi.
2619 ft. **Site 1 of 2 in cluster Q**

Relative: **Lower**
Actual: **49 ft.**

UST FINDER RELEASE:
Object ID: 85357
Facility ID: CT484
Lust ID: CT35511
Name: ATLAS OIL
Address: 414 TOLLAND STREET
City,State,Zip: EAST HARTFORD, CT 61082559
Address Match Type: PointAddress
Reported Date: 1995/05/22 15:59:59+00
Status: No Further Action
Substance: Not reported
Population within 1500ft: 2053
Domestic Wells within 1500ft: 2
Land Use: Developed, Medium Intensity
Within SPA: No
SPA PWS Facility ID: Not reported
SPA Water Type: Not reported
SPA Facility Type: Not reported
SPA HUC12: Not reported
Within WHPA: No
WHPA PWS Facility ID: Not reported
WHPA Water Type: Not reported
WHPA Facility Type: Not reported
WHPA HUC12: Not reported

ATLAS OIL (Continued) **1028943040**

Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	1
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	Geocode
X Coord:	-72.6165799999999
Y Coord:	41.7810400000001
Latitude:	41.7810399999999
Longitude:	-72.6165799999999

Q83 **THE ATLAS OIL CO.** **CT LUST** **S105458606**
WNW **414 TOLLAND ST** **CT SPILLS** **N/A**
1/4-1/2 **EAST HARTFORD, CT 06108** **CT CPCS**
0.496 mi. **CT ENF**
2619 ft. **Site 2 of 2 in cluster Q**

Relative: **Lower**
Actual: **49 ft.**

LUST:

Name:	Not reported
Name 2:	Not reported
Address:	414 TOLLAND STREET
Address 2:	Not reported
City,State,Zip:	EAST HARTFORD, CT
LUST Case Id:	35511
Release Date:	09/22/1995
Site Case ID:	43-5227
Substance:	Gasoline and Diesel
Release Source:	Unknown
Release Cause:	Unknown
Release Identified:	Reported to DEP
Case Number:	0095-02721
Release Quantity:	Unknown
Facility City Number:	Not reported

Detail As of 06/2020:

Name:	ATLAS OIL
Name 2:	Not reported
Address:	414 TOLLAND STREET
City,State,Zip:	EAST HARTFORD, CT 061082559
Address 2:	Not reported
LUST Id:	7460
UST Facility Id:	5227
LUST Case Id:	35511
Lust Status:	Lust Completed
Processing Status:	Not reported
EPA Reportable:	True
Motor Fuel:	True
Diesel:	True
Gasoline:	True
Other:	False
Other Release:	Not reported
No Release:	False
Leak:	False
Tank:	True
Piping:	False

THE ATLAS OIL CO. (Continued) **S105458606**

Overfill:	False
Removal:	True
Incident Date:	05/22/1995
Entry Date:	Not reported
Site Case Id:	Not reported
UST Site Id:	484
Cost Recovery Spill Case #:	Not reported
Old SITS Number:	9502721
Case Log Id:	Not reported
Monthly Report Id:	0
UST Owner Id:	3230
LUST Owner Id:	Not reported
UST Event Id:	7581
Contact Info:	Not reported
Contact EMail:	Not reported
Site Contact City,St,Zip:	UNKNOWN
2nd Contact:	Not reported
2nd Contact EMail:	Not reported
2nd Contact Address:	Not reported
2nd Contact City,St,Zip:	UNKNOWN
2nd Contact Address 2:	Not reported
2nd Contact City 2:	Not reported
2nd Contact Phone Number:	Not reported
2nd Contact Fax Number:	Not reported
2nd Contact Type:	Not reported
Facility City Num:	43
Site Contact:	Not reported
Site Contact Address:	Not reported
Site Contact Add 2:	Not reported
Site Contact City 2:	Not reported
Site Contact Phone:	Not reported
Site Contact Fax:	Not reported
Site Contact Type:	Not reported
Department Contact 1:	Not reported
Department Contact 2:	Not reported
Referral Source:	Not reported
Offsite Source:	False
Date Referred:	Not reported
Emergency:	False
Private Heating Fuel:	False
Commercial Heating Fuel:	False
Commercial HF < 2100 Gal.:	False
Commercial HF > 2100 Gal.:	False
Commercial HF - Size Unk:	False
No LUST Site:	False
Cost Recvry Prgm Candidate:	False
OCSRD Complete:	False
Follow Up Flag:	False
Alternate Water Supply:	False
Relocation:	False
Responsible Party:	False
Responsible EMail:	Not reported
Resp Party Name:	Irwin Singer
Resp Party Address:	414 Tolland Street
Resp Party City,St,Zip:	East Hartford, CT 061082559
Resp Party Town Number:	43
Resp Party Phone:	2032898888

THE ATLAS OIL CO. (Continued) **S105458606**

Resp Party Fax:	Not reported
Resp Party Name 2:	Not reported
Resp Party Address 2:	Not reported
Resp Party Phone 2:	Not reported
Investigator Id:	35
Follow Update:	Not reported
Area Lextent:	Not reported
Annual Precipitation:	Not reported
Affected Population:	Not reported
Population Setting:	Not reported
Ground Water Direction:	Not reported
Ground Water Gradient:	Not reported
Hydro Basin:	Not reported
Drastic:	Not reported
Geo Setting:	Not reported
Ground Water Classification:	GB
Receptor:	Not reported
Ground Water Flow Direction:	Not reported
Ground Water Depth:	Not reported
Areas Of Concern:	Not reported
Free Product Inches:	Not reported
Fund Date:	Not reported
Fund Planned:	No
Fund Obligated:	No
Fund Outlayed:	No
Fund Judgment:	No
Fund Recovered:	No
Cellar Borings:	False
Install Micro Wells:	False
Ground Water Sample:	False
Soil Sample:	False
Soil Gas:	False
Site Inspect:	False
Soil Excavate:	False
Geo Probe:	False
Survey:	False
Potable Well Sample:	False
Sample MWS:	False
Ground Water Gauging:	False
Soil Venting:	False
Active:	False
NOV Action:	None
NOV Issued:	Not reported
NOV Due:	Not reported
NOV Received:	Not reported
NOV Closed:	Not reported
NOV Disc Date:	Not reported
NOV Issued Date:	Not reported
NOV Compliance Sched:	Not reported
NOV Admin Order:	Not reported
NOV Referred To Ag:	Not reported
Stop All NOV Actions:	False
Release Invest Rpt:	False
DEP App Letter 1:	False
Correct Action Plan:	False
DEP App Letter 2:	False
Rem Sys Install:	False

THE ATLAS OIL CO. (Continued) **S105458606**

Rem Sys Install Date:	Not reported
Closure Date:	Not reported
Rem Sys Monitoring Rpt:	False
Qrtly Gwater Mon Rpts:	False
Closure Req Rpt:	False
DEP Closure Letter:	False
Referred To:	Not reported
No Wells:	Not reported
Lph Wells:	Not reported
User Stamp:	allison forrest/ForrestA
Date Stamp:	03/08/2013
Correspondence:	Not reported
Environmental Impact:	Not reported
FollowUp:	Not reported
GW Comments:	Not reported
Location Desc:	Not reported
NOV Comments:	Not reported
Release Desc:	Not reported
Running Comments:	Spills Files, UST Enforcement Files, Cleanup Fund Files, and LUST Files
Work Performed:	Not reported

SPILLS:

Name:	Not reported
Address:	414 TOLLAND ST
City,State,Zip:	EAST HARTFORD, CT
Year of Database:	2017
Case Number:	201700034
Who Took Spill:	204
Assigned To:	No Response
Report Date:	01/03/2017
Report Time:	12:00:00 AM
Date Release:	01/03/2017
Release Time:	12:00:00 AM
Reported By:	joe santovasi
Phone:	860 3493559
Qty:	0.00 (Gallons)
Telephone:	860 2898888
Representing:	aei
Facility Status:	CLOSED
Continuous Spill:	False
Release Substance:	#2 FUEL OIL
Emergency Measure:	2000 ust soil test came back 7 test nd and 1 @ 4300 pm
Discharger:	atlas oil co/ john singer
Waterbody Affected:	Not reported
Responsible Party:	Not reported
Responsible Party Address:	Not reported
RP City,St,Zip:	CT
Terminated:	Not reported
Recovered Total:	0
Total Water:	0
Historic:	False
Waterbody:	Not reported
User Stamp:	Guzmanca
Stamp Time:	2017-01-04 10:37:21
SR Inspector:	therrien, adam

THE ATLAS OIL CO. (Continued) **S105458606**

AT Inspector:	**NO RESPONSE
Corrective Action Taken:	Removed Tank
Cause Info:	OVERFILL
Media Info:	Ground Surface
Release Type:	petroleum
Incident Description:	Not reported
Cost Recovery Case?:	Not reported
DEMHS Region:	Not reported
Lat/Long:	Not reported
Company Name:	Not reported
Last Updated:	Not reported

Action:

Action:	Removed Tank
Other Action:	Not reported

Agency:

Agency ID:	Local Fire Marshal
Other Agency:	Not reported
DEP Bureau:	Not reported
DEP Agency:	Not reported

Agency ID:	DEP Dispatch
Other Agency:	Not reported
DEP Bureau:	Not reported
DEP Agency:	Not reported

Cause:

Cause ID:	Overfill
Other Cause:	Not reported

Media:

Media ID:	Ground Surface
Other Media:	Not reported

Release Class:

Class ID:	Commercial
Other Class:	Not reported

Release Type:

Release Type:	petroleum
Other Release:	Not reported

CPCS:

Name:	Atlas Oil
Address:	414 TOLLAND STREET
City,State,Zip:	EAST HARTFORD, CT
Site Type:	Not reported
Lust Status code:	Not reported
Lust Status:	Not reported
PTP Form:	Not reported
Program:	LUST

THE ATLAS OIL CO. (Continued) **S105458606**

Comments:	Not reported
Site Type Definition:	Not reported
Invesigation Start:	Yes
Invesigation Start Date:	Not reported
Remediation Start:	Yes
Remediation Start Date:	Not reported
Remediation Completed:	Yes
ELUR:	Not reported
Date Data Updated:	05/22/1995

ENFORCEMENT:

Name:	THE ATLAS OIL CO.
Address:	414 TOLLAND ST
City,State,Zip:	EAST HARTFORD, CT 06108
Enforcement Action ID:	COAR1369--94007
Enforcement Type Code:	Consent Order
Program Id:	Not reported
Enforcement Action Date:	02/04/1994
Penalty Amount:	$0.00
Sep Amt:	Not reported
Bureau Name:	Air Management
Program:	Air Enforcement
Status:	Closed
Date of Discovery:	01/01/1994
Resolution Date:	11/09/2001
Resolution Type:	Closed-No further action required
Staff:	Jacobs Wendy
ENF Action Comment:	22A-174-30(B)(3) | PAMS Penalty Amount: $45000.00. Closed 11/9/2001.
Number Violations:	Not reported
Civil Penalty:	Not reported
SEP Description:	Not reported
Associated EIs:	Not reported
Client Affiliation Type:	Respondent
Affiliation Name:	ATLAS OIL CO.
Affiliation Address Line1:	Not reported
Affiliation Address Line2:	Not reported
Affiliation City/State/Zip:	Not reported
Contact Title:	Not reported
Contact Name:	Not reported
Contact EMail:	Not reported

Count: 0 records.

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
		NO SITES FOUND			

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal NPL (Superfund) sites

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 06/26/2025
Date Data Arrived at EDR: 07/01/2025
Date Made Active in Reports: 07/17/2025
Number of Days to Update: 16

Source: EPA
Telephone: N/A
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 01/05/2026
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 6
Telephone: 214-655-6659

EPA Region 3
Telephone 215-814-5418

EPA Region 7
Telephone: 913-551-7247

EPA Region 4
Telephone 404-562-8033

EPA Region 8
Telephone: 303-312-6774

EPA Region 5
Telephone 312-886-6686

EPA Region 9
Telephone: 415-947-4246

EPA Region 10
Telephone 206-553-8665

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 06/26/2025
Date Data Arrived at EDR: 07/01/2025
Date Made Active in Reports: 07/17/2025
Number of Days to Update: 16

Source: EPA
Telephone: N/A
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 01/05/2026
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

Lists of Federal Delisted NPL sites

Delisted NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 06/26/2025
Date Data Arrived at EDR: 07/01/2025
Date Made Active in Reports: 07/17/2025
Number of Days to Update: 16

Source: EPA
Telephone: N/A
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 01/05/2026
Data Release Frequency: Quarterly

Lists of Federal sites subject to CERCLA removals and CERCLA orders

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 05/05/2025
Date Data Arrived at EDR: 06/20/2025
Date Made Active in Reports: 08/27/2025
Number of Days to Update: 68

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 09/23/2025
Next Scheduled EDR Contact: 01/05/2026
Data Release Frequency: Varies

SEMS: Superfund Enterprise Management System

SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 06/26/2025
Date Data Arrived at EDR: 07/01/2025
Date Made Active in Reports: 07/17/2025
Number of Days to Update: 16

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 01/19/2026
Data Release Frequency: Quarterly

Lists of Federal CERCLA sites with NFRAP

SEMS-ARCHIVE: Superfund Enterprise Management System Archive

SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

Date of Government Version: 06/26/2025
Date Data Arrived at EDR: 07/01/2025
Date Made Active in Reports: 07/17/2025
Number of Days to Update: 16

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 01/19/2026
Data Release Frequency: Quarterly

Lists of Federal RCRA facilities undergoing Corrective Action

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 06/02/2025
Date Data Arrived at EDR: 06/03/2025
Date Made Active in Reports: 06/16/2025
Number of Days to Update: 13

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 12/29/2025
Data Release Frequency: Quarterly

Lists of Federal RCRA TSD facilities

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 06/02/2025
Date Data Arrived at EDR: 06/04/2025
Date Made Active in Reports: 06/16/2025
Number of Days to Update: 12

Source: Environmental Protection Agency
Telephone: (888) 372-7341
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 12/29/2025
Data Release Frequency: Quarterly

Lists of Federal RCRA generators

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 06/02/2025
Date Data Arrived at EDR: 06/04/2025
Date Made Active in Reports: 06/16/2025
Number of Days to Update: 12

Source: Environmental Protection Agency
Telephone: (888) 372-7341
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 12/29/2025
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 06/02/2025
Date Data Arrived at EDR: 06/04/2025
Date Made Active in Reports: 06/16/2025
Number of Days to Update: 12

Source: Environmental Protection Agency
Telephone: (888) 372-7341
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 12/29/2025
Data Release Frequency: Quarterly

RCRA-VSQG: RCRA - Very Small Quantity Generators (Formerly Conditionally Exempt Small Quantity Generators)

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 06/02/2025
Date Data Arrived at EDR: 06/04/2025
Date Made Active in Reports: 06/16/2025
Number of Days to Update: 12

Source: Environmental Protection Agency
Telephone: (888) 372-7341
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 12/29/2025
Data Release Frequency: Quarterly

Federal institutional controls / engineering controls registries

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 03/11/2025
Date Data Arrived at EDR: 04/02/2025
Date Made Active in Reports: 06/24/2025
Number of Days to Update: 83

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 07/29/2025
Next Scheduled EDR Contact: 11/17/2025
Data Release Frequency: Varies

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 05/19/2025
Date Data Arrived at EDR: 05/20/2025
Date Made Active in Reports: 07/29/2025
Number of Days to Update: 70

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 12/02/2024
Data Release Frequency: Varies

US INST CONTROLS: Institutional Controls Sites List

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 05/19/2025
Date Data Arrived at EDR: 05/20/2025
Date Made Active in Reports: 07/29/2025
Number of Days to Update: 70

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 12/01/2025
Data Release Frequency: Varies

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 06/10/2025
Date Data Arrived at EDR: 06/12/2025
Date Made Active in Reports: 06/16/2025
Number of Days to Update: 4

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 12/29/2025
Data Release Frequency: Quarterly

Lists of state- and tribal hazardous waste facilities

SHWS: Inventory of Hazardous Disposal Sites

State Hazardous Waste Sites. State hazardous waste site records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. Available information varies by state.

Date of Government Version: 04/23/2010
Date Data Arrived at EDR: 04/23/2010
Date Made Active in Reports: 05/25/2010
Number of Days to Update: 32

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3705
Last EDR Contact: 09/16/2025
Next Scheduled EDR Contact: 01/05/2026
Data Release Frequency: No Update Planned

SDADB: Site Discovery and Assessment Database

All sites reported to Permitting, Enforcement, and Remediation Division where it is suspected that hazardous waste may have been disposed or sites that are eligible for listing on the State Inventory of Hazardous Waste Disposal Sites.

Date of Government Version: 04/23/2010
Date Data Arrived at EDR: 04/23/2010
Date Made Active in Reports: 05/25/2010
Number of Days to Update: 32

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3705
Last EDR Contact: 09/16/2025
Next Scheduled EDR Contact: 01/05/2026
Data Release Frequency: No Update Planned

Lists of state and tribal landfills and solid waste disposal facilities

SWF/LF: List of Landfills/Transfer Stations

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 06/01/2025
Date Data Arrived at EDR: 07/16/2025
Date Made Active in Reports: 10/03/2025
Number of Days to Update: 79

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3366
Last EDR Contact: 10/07/2025
Next Scheduled EDR Contact: 01/26/2026
Data Release Frequency: Annually

Lists of state and tribal leaking storage tanks

LUST: Leaking Underground Storage Tank List

Leaking Underground Storage Tank Incident Reports. LUST records contain an inventory of reported leaking underground storage tank incidents. Not all states maintain these records, and the information stored varies by state.

Date of Government Version: 06/13/2025
Date Data Arrived at EDR: 06/18/2025
Date Made Active in Reports: 09/10/2025
Number of Days to Update: 84

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3376
Last EDR Contact: 09/23/2025
Next Scheduled EDR Contact: 01/05/2026
Data Release Frequency: Semi-Annually

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 04/21/2025
Date Data Arrived at EDR: 07/10/2025
Date Made Active in Reports: 10/02/2025
Number of Days to Update: 84

Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 10/15/2025
Next Scheduled EDR Contact: 01/26/2026
Data Release Frequency: Varies

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 05/27/2025
Date Data Arrived at EDR: 07/10/2025
Date Made Active in Reports: 10/02/2025
Number of Days to Update: 84

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 10/15/2025
Next Scheduled EDR Contact: 01/26/2026
Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 04/21/2025
Date Data Arrived at EDR: 07/10/2025
Date Made Active in Reports: 10/02/2025
Number of Days to Update: 84

Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 10/15/2025
Next Scheduled EDR Contact: 01/26/2026
Data Release Frequency: Varies

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land
Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 04/21/2025
Date Data Arrived at EDR: 07/10/2025
Date Made Active in Reports: 10/02/2025
Number of Days to Update: 84

Source: EPA, Region 5
Telephone: 312-886-7439
Last EDR Contact: 10/15/2025
Next Scheduled EDR Contact: 01/26/2026
Data Release Frequency: Varies

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 04/21/2025
Date Data Arrived at EDR: 07/10/2025
Date Made Active in Reports: 10/02/2025
Number of Days to Update: 84

Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 10/15/2025
Next Scheduled EDR Contact: 01/26/2026
Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 04/21/2025
Date Data Arrived at EDR: 07/10/2025
Date Made Active in Reports: 10/02/2025
Number of Days to Update: 84

Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 10/15/2025
Next Scheduled EDR Contact: 01/26/2026
Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 05/22/2025
Date Data Arrived at EDR: 07/10/2025
Date Made Active in Reports: 10/02/2025
Number of Days to Update: 84

Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 10/15/2025
Next Scheduled EDR Contact: 01/26/2026
Data Release Frequency: Varies

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 05/22/2025
Date Data Arrived at EDR: 07/10/2025
Date Made Active in Reports: 10/02/2025
Number of Days to Update: 84

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 10/15/2025
Next Scheduled EDR Contact: 01/26/2026
Data Release Frequency: Varies

Lists of state and tribal registered storage tanks

FEMA UST: Underground Storage Tank Listing
A listing of all FEMA owned underground storage tanks.

Date of Government Version: 04/08/2025
Date Data Arrived at EDR: 04/23/2025
Date Made Active in Reports: 04/24/2025
Number of Days to Update: 1

Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 10/16/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Varies

UST: Underground Storage Tank Data
Registered Underground Storage Tanks. UST's are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA) and must be registered with the state department responsible for administering the UST program. Available information varies by state program.

Date of Government Version: 05/13/2025
Date Data Arrived at EDR: 05/16/2025
Date Made Active in Reports: 08/11/2025
Number of Days to Update: 87

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3376
Last EDR Contact: 08/15/2025
Next Scheduled EDR Contact: 09/01/2025
Data Release Frequency: Semi-Annually

AST: Marine Terminals and Tank Information
A listing of bulk petroleum facilities that receive petroleum by a vessel.

Date of Government Version: 07/01/2024
Date Data Arrived at EDR: 09/18/2024
Date Made Active in Reports: 12/04/2024
Number of Days to Update: 77

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3233
Last EDR Contact: 07/22/2025
Next Scheduled EDR Contact: 11/10/2025
Data Release Frequency: Varies

INDIAN UST R7: Underground Storage Tanks on Indian Land
The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 05/22/2025
Date Data Arrived at EDR: 07/10/2025
Date Made Active in Reports: 10/02/2025
Number of Days to Update: 84

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 10/15/2025
Next Scheduled EDR Contact: 01/26/2026
Data Release Frequency: Varies

INDIAN UST R1: Underground Storage Tanks on Indian Land
The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 04/21/2025
Date Data Arrived at EDR: 07/10/2025
Date Made Active in Reports: 10/02/2025
Number of Days to Update: 84

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 10/15/2025
Next Scheduled EDR Contact: 01/26/2026
Data Release Frequency: Varies

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 04/21/2025
Date Data Arrived at EDR: 07/10/2025
Date Made Active in Reports: 10/02/2025
Number of Days to Update: 84

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 10/15/2025
Next Scheduled EDR Contact: 01/26/2026
Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 04/21/2025
Date Data Arrived at EDR: 07/10/2025
Date Made Active in Reports: 10/02/2025
Number of Days to Update: 84

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 10/15/2025
Next Scheduled EDR Contact: 01/26/2026
Data Release Frequency: Varies

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 05/27/2025
Date Data Arrived at EDR: 07/10/2025
Date Made Active in Reports: 10/02/2025
Number of Days to Update: 84

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 10/15/2025
Next Scheduled EDR Contact: 01/26/2026
Data Release Frequency: Varies

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 04/21/2025
Date Data Arrived at EDR: 07/10/2025
Date Made Active in Reports: 10/02/2025
Number of Days to Update: 84

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 10/15/2025
Next Scheduled EDR Contact: 01/26/2026
Data Release Frequency: Varies

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 04/21/2025
Date Data Arrived at EDR: 07/10/2025
Date Made Active in Reports: 10/02/2025
Number of Days to Update: 84

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 10/15/2025
Next Scheduled EDR Contact: 01/26/2026
Data Release Frequency: Varies

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 05/22/2025
Date Data Arrived at EDR: 07/10/2025
Date Made Active in Reports: 10/02/2025
Number of Days to Update: 84

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 10/15/2025
Next Scheduled EDR Contact: 01/26/2026
Data Release Frequency: Varies

State and tribal institutional control / engineering control registries

ENG CONTROLS: Engineering Controls Listing

An Engineered Control is a permanent physical structure designed to safely isolate pollutants which would otherwise not comply with the self-implementing remedial options allowed in the Connecticut Remediation Standard Regulations (RSRs). The ECGD includes a description of what is eligible to be considered as an Engineered Control under section 22a-133k-2(f)(2) of the RSRs, a description of the information necessary for the preparation of complete and approvable applications, a step-by-step outline of the review and approval process, and supplemental resources provided in the appendices.

Date of Government Version: 06/03/2025
Date Data Arrived at EDR: 07/23/2025
Date Made Active in Reports: 10/15/2025
Number of Days to Update: 84

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3000
Last EDR Contact: 07/22/2025
Next Scheduled EDR Contact: 11/10/2025
Data Release Frequency: Varies

AUL: ELUR Sites

Environmental Land Use Restriction sites.

Date of Government Version: 06/03/2025
Date Data Arrived at EDR: 07/23/2025
Date Made Active in Reports: 10/15/2025
Number of Days to Update: 84

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3912
Last EDR Contact: 07/22/2025
Next Scheduled EDR Contact: 11/10/2025
Data Release Frequency: Varies

Lists of state and tribal voluntary cleanup sites

INDIAN VCP R1: Voluntary Cleanup Priority Listing

A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 07/27/2015
Date Data Arrived at EDR: 09/29/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 142

Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 09/09/2025
Next Scheduled EDR Contact: 12/29/2025
Data Release Frequency: Varies

VCP: Voluntary Remediation Sites

Sites involved in the Voluntary Remediation Program.

Date of Government Version: 06/03/2025
Date Data Arrived at EDR: 07/23/2025
Date Made Active in Reports: 10/15/2025
Number of Days to Update: 84

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3705
Last EDR Contact: 07/22/2025
Next Scheduled EDR Contact: 11/10/2025
Data Release Frequency: Varies

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng

A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 07/08/2021
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

Lists of state and tribal brownfield sites

BROWNFIELDS: Brownfields Inventory

CBRA has identified over 200 brownfield sites eligible for redevelopment. In most cases these are prime properties for commercial or industrial use. CBRA's grants, assistance and financing lower the financial risks and eliminate the legal, regulatory and environmental risks of redevelopment.

Date of Government Version: 02/11/2025
Date Data Arrived at EDR: 03/11/2025
Date Made Active in Reports: 05/23/2025
Number of Days to Update: 73

Source: Connecticut Brownfields Redevelopment Authority
Telephone: 860-258-7833
Last EDR Contact: 09/11/2025
Next Scheduled EDR Contact: 12/22/2025
Data Release Frequency: No Update Planned

BROWNFIELDS 2: Brownfields Inventory

A brownfield site is generally defined as "real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant or contaminanta?|"

Date of Government Version: 06/11/2024
Date Data Arrived at EDR: 06/13/2024
Date Made Active in Reports: 09/06/2024
Number of Days to Update: 85

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3705
Last EDR Contact: 09/11/2025
Next Scheduled EDR Contact: 12/22/2025
Data Release Frequency: Varies

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 09/09/2024
Date Data Arrived at EDR: 09/11/2024
Date Made Active in Reports: 12/06/2024
Number of Days to Update: 86

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 12/22/2025
Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

SWRCY: Recycling Facilities

A listing of recycling facilities.

Date of Government Version: 09/05/2025
Date Data Arrived at EDR: 09/12/2025
Date Made Active in Reports: 10/15/2025
Number of Days to Update: 33

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3223
Last EDR Contact: 08/26/2025
Next Scheduled EDR Contact: 12/15/2025
Data Release Frequency: Varies

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands

Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52

Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 10/15/2025
Next Scheduled EDR Contact: 02/02/2026
Data Release Frequency: Varies

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137

Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 10/07/2025
Next Scheduled EDR Contact: 01/26/2026
Data Release Frequency: No Update Planned

IHS OPEN DUMPS: Open Dumps on Indian Land

A listing of all open dumps located on Indian Land in the United States.

Date of Government Version: 02/07/2024
Date Data Arrived at EDR: 11/13/2024
Date Made Active in Reports: 11/19/2024
Number of Days to Update: 6

Source: Department of Health & Human Serivces, Indian Health Service
Telephone: 301-443-1452
Last EDR Contact: 07/17/2025
Next Scheduled EDR Contact: 11/03/2025
Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations that have been removed from the DEAs National Clandestine Laboratory Register.

Date of Government Version: 04/04/2025
Date Data Arrived at EDR: 06/02/2025
Date Made Active in Reports: 08/12/2025
Number of Days to Update: 71

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 08/21/2025
Next Scheduled EDR Contact: 12/01/2025
Data Release Frequency: No Update Planned

CDL: Clandestine Drug Lab Listing

A listing of clandestine drug lab locations included in the Spills database.

Date of Government Version: 06/03/2025
Date Data Arrived at EDR: 06/20/2025
Date Made Active in Reports: 09/17/2025
Number of Days to Update: 89

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3361
Last EDR Contact: 09/23/2025
Next Scheduled EDR Contact: 01/05/2026
Data Release Frequency: Quarterly

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 04/04/2025
Date Data Arrived at EDR: 06/02/2025
Date Made Active in Reports: 08/12/2025
Number of Days to Update: 71

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 08/21/2025
Next Scheduled EDR Contact: 12/01/2025
Data Release Frequency: Quarterly

Local Land Records

CT PROPERTY: Property Transfer Filings

A listing of sites that meet the definition of a hazardous waste establishment. They can be generators, dry cleaners, furniture strippers, etc. These sites have been sold to another owner.

Date of Government Version: 06/03/2025
Date Data Arrived at EDR: 07/23/2025
Date Made Active in Reports: 10/15/2025
Number of Days to Update: 84

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3705
Last EDR Contact: 07/22/2025
Next Scheduled EDR Contact: 11/10/2025
Data Release Frequency: Semi-Annually

LIENS: Environmental Liens Listing

A listing of environmental liens placed by the Cost Recovery Program.

Date of Government Version: 03/18/2024
Date Data Arrived at EDR: 04/24/2024
Date Made Active in Reports: 07/17/2024
Number of Days to Update: 84

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3120
Last EDR Contact: 07/29/2025
Next Scheduled EDR Contact: 11/17/2025
Data Release Frequency: Varies

LIENS 2: CERCLA Lien Information

A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 06/26/2025
Date Data Arrived at EDR: 07/01/2025
Date Made Active in Reports: 07/17/2025
Number of Days to Update: 16

Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 01/05/2026
Data Release Frequency: Semi-Annually

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 06/11/2025
Date Data Arrived at EDR: 06/12/2025
Date Made Active in Reports: 06/16/2025
Number of Days to Update: 4

Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 12/29/2025
Data Release Frequency: Quarterly

SPILLS: Oil & Chemical Spill Database

Oil and Chemical Spill Data.

Date of Government Version: 06/03/2025
Date Data Arrived at EDR: 06/20/2025
Date Made Active in Reports: 09/17/2025
Number of Days to Update: 89

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3024
Last EDR Contact: 09/23/2025
Next Scheduled EDR Contact: 01/05/2026
Data Release Frequency: Semi-Annually

SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 10/15/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 02/11/2013
Number of Days to Update: 39

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 06/02/2025
Date Data Arrived at EDR: 06/04/2025
Date Made Active in Reports: 06/16/2025
Number of Days to Update: 12

Source: Environmental Protection Agency
Telephone: (888) 372-7341
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 12/29/2025
Data Release Frequency: Quarterly

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 07/23/2025
Date Data Arrived at EDR: 07/23/2025
Date Made Active in Reports: 07/29/2025
Number of Days to Update: 6

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 07/23/2025
Next Scheduled EDR Contact: 11/24/2025
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 06/07/2021
Date Data Arrived at EDR: 07/13/2021
Date Made Active in Reports: 03/09/2022
Number of Days to Update: 239

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 10/07/2025
Next Scheduled EDR Contact: 01/19/2026
Data Release Frequency: Varies

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 04/02/2018
Date Data Arrived at EDR: 04/11/2018
Date Made Active in Reports: 11/06/2019
Number of Days to Update: 574

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 10/02/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: N/A

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 07/30/2021
Date Data Arrived at EDR: 02/03/2023
Date Made Active in Reports: 02/10/2023
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 08/07/2025
Next Scheduled EDR Contact: 11/17/2025
Data Release Frequency: Varies

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 06/02/2025
Date Data Arrived at EDR: 06/03/2025
Date Made Active in Reports: 06/16/2025
Number of Days to Update: 13

Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 12/29/2025
Data Release Frequency: Quarterly

EPA WATCH LIST: EPA Watch List

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 08/30/2013
Date Data Arrived at EDR: 03/21/2014
Date Made Active in Reports: 06/17/2014
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 07/24/2025
Next Scheduled EDR Contact: 11/10/2025
Data Release Frequency: No Update Planned

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 09/30/2017
Date Data Arrived at EDR: 05/08/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 73

Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 07/31/2025
Next Scheduled EDR Contact: 11/10/2025
Data Release Frequency: Varies

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 06/14/2022
Date Made Active in Reports: 03/24/2023
Number of Days to Update: 283

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 09/11/2025
Next Scheduled EDR Contact: 12/22/2025
Data Release Frequency: Every 4 Years

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2023
Date Data Arrived at EDR: 02/11/2025
Date Made Active in Reports: 02/18/2025
Number of Days to Update: 7

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 08/11/2025
Next Scheduled EDR Contact: 11/24/2025
Data Release Frequency: Annually

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 07/14/2025
Date Data Arrived at EDR: 07/14/2025
Date Made Active in Reports: 10/13/2025
Number of Days to Update: 91

Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 10/14/2025
Next Scheduled EDR Contact: 01/26/2026
Data Release Frequency: Annually

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 07/29/2025
Date Data Arrived at EDR: 08/04/2025
Date Made Active in Reports: 08/12/2025
Number of Days to Update: 8

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 12/08/2025
Data Release Frequency: Annually

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 04/05/2025
Date Data Arrived at EDR: 04/11/2025
Date Made Active in Reports: 07/08/2025
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 202-564-8600
Last EDR Contact: 10/08/2025
Next Scheduled EDR Contact: 01/26/2026
Data Release Frequency: Varies

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

PRP: Potentially Responsible Parties

A listing of verified Potentially Responsible Parties

Date of Government Version: 06/26/2025
Date Data Arrived at EDR: 07/01/2025
Date Made Active in Reports: 07/29/2025
Number of Days to Update: 28

Source: EPA
Telephone: 202-564-6023
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 11/10/2025
Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 07/01/2024
Date Data Arrived at EDR: 10/02/2024
Date Made Active in Reports: 01/10/2025
Number of Days to Update: 100

Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 09/30/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 11/18/2016
Date Data Arrived at EDR: 11/23/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 79

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 09/23/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Quarterly

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25

Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25

Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

MLTS: Material Licensing Tracking System

MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 05/07/2025
Date Data Arrived at EDR: 05/07/2025
Date Made Active in Reports: 06/03/2025
Number of Days to Update: 27

Source: Nuclear Regulatory Commission
Telephone: 301-415-0717
Last EDR Contact: 10/08/2025
Next Scheduled EDR Contact: 01/26/2026
Data Release Frequency: Quarterly

COAL ASH DOE: Steam-Electric Plant Operation Data

A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2023
Date Data Arrived at EDR: 10/16/2024
Date Made Active in Reports: 01/14/2025
Number of Days to Update: 90

Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 08/28/2025
Next Scheduled EDR Contact: 12/08/2025
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List
A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 01/12/2017
Date Data Arrived at EDR: 03/05/2019
Date Made Active in Reports: 11/11/2019
Number of Days to Update: 251
Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 08/21/2025
Next Scheduled EDR Contact: 12/08/2025
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database
The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 09/13/2019
Date Data Arrived at EDR: 11/06/2019
Date Made Active in Reports: 02/10/2020
Number of Days to Update: 96
Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 07/31/2025
Next Scheduled EDR Contact: 11/10/2025
Data Release Frequency: Varies

RADINFO: Radiation Information Database
The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 07/01/2019
Date Data Arrived at EDR: 07/01/2019
Date Made Active in Reports: 09/23/2019
Number of Days to Update: 84
Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 09/17/2025
Next Scheduled EDR Contact: 01/05/2026
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing
A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40
Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing
A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40
Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

DOT OPS: Incident and Accident Data
Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 06/30/2025
Date Data Arrived at EDR: 07/17/2025
Date Made Active in Reports: 10/13/2025
Number of Days to Update: 88

Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 07/17/2025
Next Scheduled EDR Contact: 11/03/2025
Data Release Frequency: Quarterly

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 03/31/2025
Date Data Arrived at EDR: 05/02/2025
Date Made Active in Reports: 07/17/2025
Number of Days to Update: 76

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 09/23/2025
Next Scheduled EDR Contact: 01/13/2026
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2023
Date Data Arrived at EDR: 02/19/2025
Date Made Active in Reports: 03/07/2025
Number of Days to Update: 16

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 12/29/2025
Data Release Frequency: Biennially

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 07/14/2015
Date Made Active in Reports: 01/10/2017
Number of Days to Update: 546

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 09/29/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Semi-Annually

FUSRAP: Formerly Utilized Sites Remedial Action Program

DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

Date of Government Version: 03/03/2023
Date Data Arrived at EDR: 03/03/2023
Date Made Active in Reports: 06/09/2023
Number of Days to Update: 98

Source: Department of Energy
Telephone: 202-586-3559
Last EDR Contact: 07/28/2025
Next Scheduled EDR Contact: 11/10/2025
Data Release Frequency: Varies

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 05/15/2025
Date Data Arrived at EDR: 05/15/2025
Date Made Active in Reports: 07/29/2025
Number of Days to Update: 75

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 08/11/2025
Next Scheduled EDR Contact: 11/24/2025
Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites
A listing of former lead smelter site locations.

Date of Government Version: 06/26/2025
Date Data Arrived at EDR: 07/01/2025
Date Made Active in Reports: 07/17/2025
Number of Days to Update: 16
Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 01/05/2026
Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites
A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36
Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)
The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100
Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US AIRS MINOR: Air Facility System Data
A listing of minor source facilities.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100
Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

MINES VIOLATIONS: MSHA Violation Assessment Data
Mines violation and assessment information. Department of Labor, Mine Safety & Health Administration.

Date of Government Version: 07/01/2025
Date Data Arrived at EDR: 07/01/2025
Date Made Active in Reports: 09/24/2025
Number of Days to Update: 85
Source: DOL, Mine Safety & Health Admi
Telephone: 202-693-9424
Last EDR Contact: 07/01/2025
Next Scheduled EDR Contact: 12/01/2025
Data Release Frequency: Quarterly

US MINES: Mines Master Index File
Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 05/01/2025
Date Data Arrived at EDR: 05/20/2025
Date Made Active in Reports: 07/29/2025
Number of Days to Update: 70
Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 08/18/2025
Next Scheduled EDR Contact: 12/01/2025
Data Release Frequency: Semi-Annually

US MINES 2: Ferrous and Nonferrous Metal Mines Database Listing

This map layer includes ferrous (ferrous metal mines are facilities that extract ferrous metals, such as iron ore or molybdenum) and nonferrous (Nonferrous metal mines are facilities that extract nonferrous metals, such as gold, silver, copper, zinc, and lead) metal mines in the United States.

Date of Government Version: 04/08/2025
Date Data Arrived at EDR: 05/20/2025
Date Made Active in Reports: 08/12/2025
Number of Days to Update: 84

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 08/21/2025
Next Scheduled EDR Contact: 12/01/2025
Data Release Frequency: Varies

US MINES 3: Active Mines & Mineral Plants Database Listing

Active Mines and Mineral Processing Plant operations for commodities monitored by the Minerals Information Team of the USGS.

Date of Government Version: 04/14/2011
Date Data Arrived at EDR: 06/08/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 97

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 08/21/2025
Next Scheduled EDR Contact: 12/01/2025
Data Release Frequency: Varies

MINES MRDS: Mineral Resources Data System

Mineral Resources Data System

Date of Government Version: 06/04/2024
Date Data Arrived at EDR: 11/22/2024
Date Made Active in Reports: 02/18/2025
Number of Days to Update: 88

Source: USGS
Telephone: 703-648-6533
Last EDR Contact: 08/21/2025
Next Scheduled EDR Contact: 12/01/2025
Data Release Frequency: Varies

ABANDONED MINES: Abandoned Mines

An inventory of land and water impacted by past mining (primarily coal mining) is maintained by OSMRE to provide information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The inventory contains information on the location, type, and extent of AML impacts, as well as, information on the cost associated with the reclamation of those problems. The inventory is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed.

Date of Government Version: 05/28/2025
Date Data Arrived at EDR: 05/28/2025
Date Made Active in Reports: 06/03/2025
Number of Days to Update: 6

Source: Department of Interior
Telephone: 202-208-2609
Last EDR Contact: 09/09/2025
Next Scheduled EDR Contact: 12/15/2025
Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 04/22/2025
Date Data Arrived at EDR: 05/05/2025
Date Made Active in Reports: 05/21/2025
Number of Days to Update: 16

Source: EPA
Telephone: (617) 918-1111
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 12/08/2025
Data Release Frequency: Quarterly

UXO: Unexploded Ordnance Sites

A listing of unexploded ordnance site locations

Date of Government Version: 02/14/2025
Date Data Arrived at EDR: 03/11/2025
Date Made Active in Reports: 06/03/2025
Number of Days to Update: 84

Source: Department of Defense
Telephone: 703-704-1564
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 01/19/2026
Data Release Frequency: Varies

DOCKET HWC: Hazardous Waste Compliance Docket Listing

A complete list of the Federal Agency Hazardous Waste Compliance Docket Facilities.

Date of Government Version: 05/06/2021
Date Data Arrived at EDR: 05/21/2021
Date Made Active in Reports: 08/11/2021
Number of Days to Update: 82

Source: Environmental Protection Agency
Telephone: 202-564-0527
Last EDR Contact: 08/12/2025
Next Scheduled EDR Contact: 12/01/2025
Data Release Frequency: Varies

ECHO: Enforcement & Compliance History Information

ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

Date of Government Version: 06/22/2025
Date Data Arrived at EDR: 06/25/2025
Date Made Active in Reports: 08/27/2025
Number of Days to Update: 63

Source: Environmental Protection Agency
Telephone: 202-564-2280
Last EDR Contact: 09/26/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Quarterly

FUELS PROGRAM: EPA Fuels Program Registered Listing

This listing includes facilities that are registered under the Part 80 (Code of Federal Regulations) EPA Fuels Programs. All companies now are required to submit new and updated registrations.

Date of Government Version: 05/07/2025
Date Data Arrived at EDR: 05/13/2025
Date Made Active in Reports: 07/29/2025
Number of Days to Update: 77

Source: EPA
Telephone: 800-385-6164
Last EDR Contact: 08/07/2025
Next Scheduled EDR Contact: 11/24/2025
Data Release Frequency: Quarterly

PFAS NPL: Superfund Sites with PFAS Detections Information

EPA's Office of Land and Emergency Management and EPA Regional Offices maintain data describing what is known about site investigations, contamination, and remedial actions under the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) where PFAS is present in the environment.

Date of Government Version: 06/23/2025
Date Data Arrived at EDR: 06/26/2025
Date Made Active in Reports: 08/27/2025
Number of Days to Update: 62

Source: Environmental Protection Agency
Telephone: 703-603-8895
Last EDR Contact: 09/26/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Varies

PFAS FEDERAL SITES: Federal Sites PFAS Information

Several federal entities, such as the federal Superfund program, Department of Defense, National Aeronautics and Space Administration, Department of Transportation, and Department of Energy provided information for sites with known or suspected detections at federal facilities.

Date of Government Version: 06/23/2025
Date Data Arrived at EDR: 06/26/2025
Date Made Active in Reports: 08/27/2025
Number of Days to Update: 62

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 09/26/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Varies

PFAS TRIS: List of PFAS Added to the TRI

Section 7321 of the National Defense Authorization Act for Fiscal Year 2020 (NDAA) immediately added certain per- and polyfluoroalkyl substances (PFAS) to the list of chemicals covered by the Toxics Release Inventory (TRI) under Section 313 of the Emergency Planning and Community Right-to-Know Act (EPCRA) and provided a framework for additional PFAS to be added to TRI on an annual basis.

Date of Government Version: 06/23/2025
Date Data Arrived at EDR: 06/26/2025
Date Made Active in Reports: 08/27/2025
Number of Days to Update: 62

Source: Environmental Protection Agency
Telephone: 202-566-0250
Last EDR Contact: 09/26/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Varies

PFAS TSCA: PFAS Manufacture and Imports Information

EPA issued the Chemical Data Reporting (CDR) Rule under the Toxic Substances Control Act (TSCA) and requires chemical manufacturers and facilities that manufacture or import chemical substances to report data to EPA. EPA publishes non-confidential business information (non-CBI) and includes descriptive information about each site, corporate parent, production volume, other manufacturing information, and processing and use information.

Date of Government Version: 06/23/2025
Date Data Arrived at EDR: 06/26/2025
Date Made Active in Reports: 08/27/2025
Number of Days to Update: 62

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 09/26/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Varies

PFAS RCRA MANIFEST: PFAS Transfers Identified In the RCRA Database Listing

To work around the lack of PFAS waste codes in the RCRA database, EPA developed the PFAS Transfers dataset by mining e-Manifest records containing at least one of these common PFAS keywords: PFAS, PFOA, PFOS, PERFL, AFFF, GENX, GEN-X (plus the VT waste codes). These keywords were searched for in the following text fields: Manifest handling instructions (MANIFEST_HANDLING_INSTR), Non-hazardous waste description (NON_HAZ_WASTE_DESCRIPTION), DOT printed information (DOT_PRINTED_INFORMATION), Waste line handling instructions (WASTE_LINE_HANDLING_INSTR), Waste residue comments (WASTE_RESIDUE_COMMENTS).

Date of Government Version: 06/23/2025
Date Data Arrived at EDR: 06/26/2025
Date Made Active in Reports: 09/24/2025
Number of Days to Update: 90

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 09/26/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Varies

PFAS ATSDR: PFAS Contamination Site Location Listing

PFAS contamination site locations from the Department of Health & Human Services, Center for Disease Control & Prevention. ATSDR is involved at a number of PFAS-related sites, either directly or through assisting state and federal partners. As of now, most sites are related to drinking water contamination connected with PFAS production facilities or fire training areas where aqueous film-forming firefighting foam (AFFF) was regularly used.

Date of Government Version: 11/12/2024
Date Data Arrived at EDR: 07/21/2025
Date Made Active in Reports: 10/13/2025
Number of Days to Update: 84

Source: Department of Health & Human Services
Telephone: 202-741-5770
Last EDR Contact: 10/15/2025
Next Scheduled EDR Contact: 02/02/2026
Data Release Frequency: Varies

PFAS WQP: Ambient Environmental Sampling for PFAS

The Water Quality Portal (WQP) is a part of a modernized repository storing ambient sampling data for all environmental media and tissue samples. A wide range of federal, state, tribal and local governments, academic and non-governmental organizations and individuals submit project details and sampling results to this public repository. The information is commonly used for research and assessments of environmental quality.

Date of Government Version: 06/23/2025
Date Data Arrived at EDR: 06/26/2025
Date Made Active in Reports: 08/27/2025
Number of Days to Update: 62

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 09/26/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Varies

PFAS PROJECT: NORTHEASTERN UNIVERSITY PFAS PROJECT

The PFAS Contamination Site Tracker records qualitative and quantitative data from each site in a chart, specifically examining discovery, contamination levels, government response, litigation, health impacts, media coverage, and community characteristics. All data presented in the chart were extracted from government websites, such as state health departments or the Environmental Protection Agency, and news articles.

Date of Government Version: 05/15/2024
Date Data Arrived at EDR: 03/06/2025
Date Made Active in Reports: 06/03/2025
Number of Days to Update: 89

Source: Social Science Environmental Health Research Institute
Telephone: N/A
Last EDR Contact: 09/02/2025
Next Scheduled EDR Contact: 12/15/2025
Data Release Frequency: Varies

PFAS NPDES: Clean Water Act Discharge Monitoring Information

Any discharger of pollutants to waters of the United States from a point source must have a National Pollutant Discharge Elimination System (NPDES) permit. The process for obtaining limits involves the regulated entity (permittee) disclosing releases in a NPDES permit application and the permitting authority (typically the state but sometimes EPA) deciding whether to require monitoring or monitoring with limits. Caveats and Limitations: Less than half of states have required PFAS monitoring for at least one of their permittees and fewer states have established PFAS effluent limits for permittees. New rulemakings have been initiated that may increase the number of facilities monitoring for PFAS in the future.

Date of Government Version: 06/23/2025
Date Data Arrived at EDR: 06/26/2025
Date Made Active in Reports: 08/27/2025
Number of Days to Update: 62

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 09/26/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Varies

PFAS ECHO: Facilities in Industries that May Be Handling PFAS Listing

Regulators and the public have expressed interest in knowing which regulated entities may be using PFAS. EPA has developed a dataset from various sources that show which industries may be handling PFAS. Approximately 120,000 facilities subject to federal environmental programs have operated or currently operate in industry sectors with processes that may involve handling and/or release of PFAS.

Date of Government Version: 06/23/2025
Date Data Arrived at EDR: 06/26/2025
Date Made Active in Reports: 08/27/2025
Number of Days to Update: 62

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 09/26/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Varies

PFAS ECHO FIRE TRAIN: Facilities in Industries that May Be Handling PFAS Listing

A list of fire training sites was added to the Industry Sectors dataset using a keyword search on the permitted facilitys name to identify sites where fire-fighting foam may have been used in training exercises. Additionally, you may view an example spreadsheet of the subset of fire training facility data, as well as the keywords used in selecting or deselecting a facility for the subset. as well as the keywords used in selecting or deselecting a facility for the subset. These keywords were tested to maximize accuracy in selecting facilities that may use fire-fighting foam in training exercises, however, due to the lack of a required reporting field in the data systems for designating fire training sites, this methodology may not identify all fire training sites or may potentially misidentify them.

Date of Government Version: 06/23/2025
Date Data Arrived at EDR: 06/26/2025
Date Made Active in Reports: 08/27/2025
Number of Days to Update: 62

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 09/26/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Varies

PFAS PT 139 AIRPORT: All Certified Part 139 Airports PFAS Information Listing

Since July 1, 2006, all certified part 139 airports are required to have fire-fighting foam onsite that meet military specifications (MIL-F-24385) (14 CFR 139.317). To date, these military specification fire-fighting foams are fluorinated and have been historically used for training and extinguishing. The 2018 FAA Reauthorization Act has a provision stating that no later than October 2021, FAA shall not require the use of fluorinated AFFF. This provision does not prohibit the use of fluorinated AFFF at Part 139 civilian airports; it only prohibits FAA from mandating its use. The Federal Aviation Administration?s document AC 150/5210-6D - Aircraft Fire Extinguishing Agents provides guidance on Aircraft Fire Extinguishing Agents, which includes Aqueous Film Forming Foam (AFFF).

Date of Government Version: 06/23/2025
Date Data Arrived at EDR: 06/26/2025
Date Made Active in Reports: 08/27/2025
Number of Days to Update: 62

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 09/26/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Varies

AQUEOUS FOAM NRC: Aqueous Foam Related Incidents Listing

The National Response Center (NRC) serves as an emergency call center that fields initial reports for pollution and railroad incidents and forwards that information to appropriate federal/state agencies for response. The spreadsheets posted to the NRC website contain initial incident data that has not been validated or investigated by a federal/state response agency. Response center calls from 1990 to the most recent complete calendar year where there was indication of Aqueous Film Forming Foam (AFFF) usage are included in this dataset. NRC calls may reference AFFF usage in the ?Material Involved? or ?Incident Description? fields.

Date of Government Version: 06/23/2025
Date Data Arrived at EDR: 06/26/2025
Date Made Active in Reports: 08/27/2025
Number of Days to Update: 62

Source: Environmental Protection Agency
Telephone: 202-267-2675
Last EDR Contact: 09/26/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Varies

PCS ENF: Enforcement data

No description is available for this data

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 02/05/2015
Date Made Active in Reports: 03/06/2015
Number of Days to Update: 29

Source: EPA
Telephone: 202-564-2497
Last EDR Contact: 09/24/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Varies

PCS: Permit Compliance System

PCS is a computerized management information system that contains data on National Pollutant Discharge Elimination System (NPDES) permit holding facilities. PCS tracks the permit, compliance, and enforcement status of NPDES facilities.

Date of Government Version: 12/16/2016
Date Data Arrived at EDR: 01/06/2017
Date Made Active in Reports: 03/10/2017
Number of Days to Update: 63

Source: EPA, Office of Water
Telephone: 202-564-2496
Last EDR Contact: 09/24/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: No Update Planned

BIOSOLIDS: ICIS-NPDES Biosolids Facility Data

The data reflects compliance information about facilities in the biosolids program.

Date of Government Version: 07/06/2025
Date Data Arrived at EDR: 07/10/2025
Date Made Active in Reports: 10/02/2025
Number of Days to Update: 84

Source: Environmental Protection Agency
Telephone: 202-564-4700
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 01/26/2026
Data Release Frequency: Varies

UST FINDER RELEASE: UST Finder Releases Database

US EPA's UST Finder data is a national composite of leaking underground storage tanks. This data contains information about, and locations of, leaking underground storage tanks. Data was collected from state sources and standardized into a national profile by EPA's Office of Underground Storage Tanks, Office of Research and Development, and the Association of State and Territorial Solid Waste Management Officials.

Date of Government Version: 06/08/2023
Date Data Arrived at EDR: 10/31/2023
Date Made Active in Reports: 01/18/2024
Number of Days to Update: 79

Source: Environmental Protecton Agency
Telephone: 202-564-0394
Last EDR Contact: 08/13/2025
Next Scheduled EDR Contact: 11/17/2025
Data Release Frequency: Semi-Annually

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

UST FINDER: UST Finder Database

EPA developed UST Finder, a web map application containing a comprehensive, state-sourced national map of underground storage tank (UST) and leaking UST (LUST) data. It provides the attributes and locations of active and closed USTs, UST facilities, and LUST sites from states and from Tribal lands and US territories . UST Finder contains information about proximity of UST facilities and LUST sites to: surface and groundwater public drinking water protection areas; estimated number of private domestic wells and number of people living nearby; and flooding and wildfires.

Date of Government Version: 06/08/2023
Date Data Arrived at EDR: 10/04/2023
Date Made Active in Reports: 01/18/2024
Number of Days to Update: 106

Source: Environmental Protection Agency
Telephone: 202-564-0394
Last EDR Contact: 08/13/2025
Next Scheduled EDR Contact: 11/17/2025
Data Release Frequency: Varies

E MANIFEST: Hazardous Waste Electronic Manifest System

EPA established a national system for tracking hazardous waste shipments electronically. This system, known as ?e-Manifest,? will modernize the nation?s cradle-to-grave hazardous waste tracking process while saving valuable time, resources, and dollars for industry and states.

Date of Government Version: 06/02/2025
Date Data Arrived at EDR: 06/04/2025
Date Made Active in Reports: 08/13/2025
Number of Days to Update: 70

Source: Environmental Protection Agency
Telephone: 833-501-6826
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 12/29/2025
Data Release Frequency: Varies

PFAS: PFAS Contamination Site Listing

A listing of spills reported to the department between 1996 and the present that have substance released, such as ?foam? or other materials associated with PFAS.

Date of Government Version: 06/03/2025
Date Data Arrived at EDR: 06/20/2025
Date Made Active in Reports: 09/17/2025
Number of Days to Update: 89

Source: Department of Energy and Environmental Protection
Telephone: 860-424-3705
Last EDR Contact: 09/23/2025
Next Scheduled EDR Contact: 01/05/2026
Data Release Frequency: Quarterly

AIRS: Permitted Air Sources Listing

A listing of permitted air sources in Connecticut.

Date of Government Version: 05/26/2025
Date Data Arrived at EDR: 07/29/2025
Date Made Active in Reports: 10/16/2025
Number of Days to Update: 79

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3026
Last EDR Contact: 07/22/2025
Next Scheduled EDR Contact: 11/10/2025
Data Release Frequency: Varies

ASBESTOS: Asbestos Notification Listing

A listing of asbestos notification site locations.

Date of Government Version: 04/04/2025
Date Data Arrived at EDR: 04/22/2025
Date Made Active in Reports: 07/09/2025
Number of Days to Update: 78

Source: Department of Public Health
Telephone: 860-509-7371
Last EDR Contact: 07/22/2025
Next Scheduled EDR Contact: 11/10/2025
Data Release Frequency: Varies

COI: Completion of Investigation

The COI must be signed and submitted by the Certifying Party to document that the investigation of the parcel has been completed in accordance with CGS Section 22a-134a(g)(1).

Date of Government Version: 06/06/2025
Date Data Arrived at EDR: 07/29/2025
Date Made Active in Reports: 10/15/2025
Number of Days to Update: 78

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3000
Last EDR Contact: 09/09/2025
Next Scheduled EDR Contact: 12/29/2025
Data Release Frequency: Varies

CPCS: Contaminated or Potentially Contaminated Sites

A list of Contaminated or Potentially Contaminated Sites within Connecticut. This list represents the "Hazardous Waste Facilities," as defined in Section 22a-134f of the Connecticut General Statutes (CGS). The list contains the following types of sites: Sites listed on the Inventory of Hazardous Waste Disposal Sites; Sites subject to the Property Transfer Act; Sites at which underground storage tanks are known to have leaked; Sites at which hazardous waste subject to the RCRA; Sites that are included in EPA's (CERCLIS); Sites that are the subject of an order issued by the Commissioner of DEP that requires investigation and remediation of a potential or known source of pollution; and Sites that have entered into one of the Department's Voluntary Remediation Programs.

Date of Government Version: 07/21/2025
Date Data Arrived at EDR: 07/24/2025
Date Made Active in Reports: 10/15/2025
Number of Days to Update: 83

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3766
Last EDR Contact: 07/24/2025
Next Scheduled EDR Contact: 11/10/2025
Data Release Frequency: Quarterly

DRYCLEANERS: Drycleaner Facilities

A listing of drycleaner facility locations.

Date of Government Version: 07/18/2008
Date Data Arrived at EDR: 08/08/2008
Date Made Active in Reports: 08/27/2008
Number of Days to Update: 19

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3026
Last EDR Contact: 08/19/2025
Next Scheduled EDR Contact: 12/08/2025
Data Release Frequency: Varies

DRYCLEANERS 2: Dry Cleaning Remediation Fund Listing

The Dry Cleaning Establishment Remediation Fund provides grants to eligible dry cleaning business operators and landlords for the assessment, cleanup, containment or mitigation of pollution resulting from releases of chemicals used in dry cleaning. The grants may also be used for measures undertaken to prevent such pollution, and for providing potable drinking water when necessary. Grant funds may work as a reimbursement program as well.

Date of Government Version: 02/11/2025
Date Data Arrived at EDR: 03/04/2025
Date Made Active in Reports: 05/20/2025
Number of Days to Update: 77

Source: Department of Energy and Environmental Protection
Telephone: 860-500-2455
Last EDR Contact: 09/18/2025
Next Scheduled EDR Contact: 12/15/2025
Data Release Frequency: Varies

ENFORCEMENT: Enforcement Case Listing

The types of enforcement actions included are administrative consent orders, final unilateral orders and final dispositions of civil cases through the Attorney General's Office.

Date of Government Version: 03/03/2025
Date Data Arrived at EDR: 04/09/2025
Date Made Active in Reports: 06/27/2025
Number of Days to Update: 79

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3265
Last EDR Contact: 10/06/2025
Next Scheduled EDR Contact: 01/19/2026
Data Release Frequency: Varies

FIN ASSURANCE 1: Financial Assurance Information Listing

A listing containing RCRA financial assurance information submitted on behalf of the CT DEP's Program Analysis Group of the Waste Engineering and Enforcement Division.

Date of Government Version: 03/10/2025
Date Data Arrived at EDR: 03/12/2025
Date Made Active in Reports: 03/28/2025
Number of Days to Update: 16

Source: Department of Energy & Environmental Protection
Telephone: 860-418-5930
Last EDR Contact: 09/03/2025
Next Scheduled EDR Contact: 12/22/2025
Data Release Frequency: Varies

FIN ASSURANCE 2: Financial Assurance Information Listing

A listing of financial assurance information for solid waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 09/11/2025
Date Data Arrived at EDR: 09/17/2025
Date Made Active in Reports: 10/15/2025
Number of Days to Update: 28

Source: Department of Energy & Environmental Protection
Telephone: 860-418-5930
Last EDR Contact: 09/03/2025
Next Scheduled EDR Contact: 12/22/2025
Data Release Frequency: Varies

LEAD: Lead Inspection Database

The Lead Poisoning Prevention and Control Program lead inspection database.

Date of Government Version: 03/26/2014
Date Data Arrived at EDR: 03/27/2014
Date Made Active in Reports: 05/08/2014
Number of Days to Update: 42

Source: Department of Public Health
Telephone: 860-509-7299
Last EDR Contact: 08/19/2025
Next Scheduled EDR Contact: 12/08/2025
Data Release Frequency: Varies

LWDS: Connecticut Leachate and Wastewater Discharge Sites

The Leachate and Waste Water Discharge Inventory Data Layer (LWDS) includes point locations digitized from Leachate and Wastewater Discharge Source maps compiled by the Connecticut DEP. These maps locate surface and groundwater discharges that (1) have received a waste water discharge permit from the state or (2) are historic and now defunct waste sites or (3) are locations of accidental spills, leaks, or discharges of a variety of liquid or solid wastes.

Date of Government Version: 07/17/2009
Date Data Arrived at EDR: 10/21/2009
Date Made Active in Reports: 10/30/2009
Number of Days to Update: 9

Source: Department of Energy & Environmental Protection
Telephone: N/A
Last EDR Contact: 10/15/2014
Next Scheduled EDR Contact: 01/26/2015
Data Release Frequency: Varies

CT MANIFEST: Hazardous Waste Manifest Data

Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 07/30/2025
Date Data Arrived at EDR: 07/31/2025
Date Made Active in Reports: 10/16/2025
Number of Days to Update: 77

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 07/31/2025
Next Scheduled EDR Contact: 11/17/2025
Data Release Frequency: No Update Planned

NPDES: Wastewater Permit Listing

A listing of permits issued by the DEP.

Date of Government Version: 08/02/2024
Date Data Arrived at EDR: 09/18/2024
Date Made Active in Reports: 11/22/2024
Number of Days to Update: 65

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3832
Last EDR Contact: 09/09/2025
Next Scheduled EDR Contact: 12/29/2025
Data Release Frequency: Varies

SEH: List of Significant Environmental Hazards Report to DEEP

The Significant Environmental Hazard Statute is intended to identify and abate short-term risks associated with specific environmental conditions identified in the statute. After abatement of short-term risks (meaning abatement of the significant environmental hazard condition), there may still be potential long-term risks associated with the release. However, a significant environmental hazard can be considered abated under the statute even though potential long-term risks may not have been addressed.

Date of Government Version: 03/31/2025
Date Data Arrived at EDR: 05/14/2025
Date Made Active in Reports: 08/04/2025
Number of Days to Update: 82

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3766
Last EDR Contact: 10/09/2025
Next Scheduled EDR Contact: 01/19/2026
Data Release Frequency: Varies

UIC: Underground Injection Control Listing
A list of of subsurface disposal permits and their locations.

Date of Government Version: 03/27/2024
Date Data Arrived at EDR: 03/28/2024
Date Made Active in Reports: 06/18/2024
Number of Days to Update: 82

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3058
Last EDR Contact: 10/07/2025
Next Scheduled EDR Contact: 01/26/2026
Data Release Frequency: Varies

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants
The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR Hist Auto: EDR Exclusive Historical Auto Stations
EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR Hist Cleaner: EDR Exclusive Historical Cleaners
EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA HWS: Recovered Government Archive State Hazardous Waste Facilities List

The EDR Recovered Government Archive State Hazardous Waste database provides a list of SHWS incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Energy & Environmental Protection formerly know as the DEP which changes in July 2011 in Connecticut.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/02/2014
Number of Days to Update: 185

Source: Department of Energy & Environmental Protection
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA LUST: Recovered Government Archive Leaking Underground Storage Tank

The EDR Recovered Government Archive Leaking Underground Storage Tank database provides a list of LUST incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Energy & Environmental Protection formerly know as the DEP which changes in July 2011 in Connecticut.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/02/2014
Number of Days to Update: 185

Source: Department of Energy & Environmental Protection
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

NJ MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 04/10/2019
Date Made Active in Reports: 05/16/2019
Number of Days to Update: 36

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 09/24/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Annually

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 12/31/2019
Date Data Arrived at EDR: 11/30/2023
Date Made Active in Reports: 12/01/2023
Number of Days to Update: 1

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 07/17/2025
Next Scheduled EDR Contact: 11/03/2025
Data Release Frequency: Quarterly

PA MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 06/30/2018
Date Data Arrived at EDR: 07/19/2019
Date Made Active in Reports: 09/10/2019
Number of Days to Update: 53

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 01/19/2026
Data Release Frequency: Annually

RI MANIFEST: Manifest information
Hazardous waste manifest information

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 11/30/2021
Date Made Active in Reports: 02/18/2022
Number of Days to Update: 80

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 08/06/2025
Next Scheduled EDR Contact: 11/24/2025
Data Release Frequency: Annually

VT MANIFEST: Hazardous Waste Manifest Data
Hazardous waste manifest information.

Date of Government Version: 10/28/2019
Date Data Arrived at EDR: 10/29/2019
Date Made Active in Reports: 01/09/2020
Number of Days to Update: 72

Source: Department of Environmental Conservation
Telephone: 802-241-3443
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 01/19/2026
Data Release Frequency: Annually

WI MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 05/31/2018
Date Data Arrived at EDR: 06/19/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 76

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 08/27/2025
Next Scheduled EDR Contact: 12/15/2025
Data Release Frequency: Annually

Oil/Gas Pipelines
Source: Endeavor Business Media
Petroleum Bundle (Crude Oil, Refined Products, Petrochemicals, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)) N = Natural Gas Bundle (Natural Gas, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)). This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Electric Power Transmission Line Data
Source: Endeavor Business Media
This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.
Daycare Centers: Licensed Child Care Facilities
Source: Department of Public Health
Telephone: 860-509-8045

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005, 2010 and 2015 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Tidal Wetlands
Source: Department of Energy & Environmental Protection
Telephone: 860-424-4054

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

STONE ACADEMY
745 BURNSIDE AVENUE
EAST HARTFORD, CT 06108

TARGET PROPERTY COORDINATES

Latitude (North):	41.7792 - 41° 46' 45.12''
Longitude (West):	72.606685 - 72° 36' 24.07''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	698904.4
UTM Y (Meters):	4627817.0
Elevation:	75 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	20024050 MANCHESTER, CT
Version Date:	2021
Northwest Map:	20024046 HARTFORD NORTH, CT
Version Date:	2021

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principle investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).


TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General SSW

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Target Property Elevation: 75 ft.

Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Flood Plain Panel at Target Property	FEMA Source Type
09003C0388F	FEMA FIRM Flood data

Additional Panels in search area:	FEMA Source Type
09003C0387F	FEMA FIRM Flood data
09003C0367G	FEMA FIRM Flood data
09003C0386F	FEMA FIRM Flood data
09003C0389F	FEMA FIRM Flood data
09003C0369G	FEMA FIRM Flood data

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
MANCHESTER	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius:	1.25 miles
Location Relative to TP:	1 - 2 Miles WSW
Site Name:	EAST HARTFORD MUNICIPAL LANDFILL
Site EPA ID Number:	CTD980521124
Groundwater Flow Direction:	S TOWARD THE HOCKANUM RIVER ON THE EASTERN SECTION OF THE SITE AND W AND N ON THE WESTERN AND NORTHERN SECTIONS OF THE SITE. THE GROUND WATER FLOW VELOCITY IS APPROXIMATELY 1.37 FEET PER DAY.
Measured Depth to Water:	4.42 to 20.95 feet.
Hydraulic Connection:	The site is underlain by 50 to 100 feet of clay. Ground water at the site is classified as GB by the Connecticut DEP.
Sole Source Aquifer:	No information about a sole source aquifer is available
Data Quality:	Information based on site-specific subsurface investigations is documented in the CERCLIS investigation report(s)

* ©1996 Site--specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT


Era:	Mesozoic
System:	Triassic
Series:	Triassic
Code:	Tr *(decoded above as Era, System & Series)*

GEOLOGIC AGE IDENTIFICATION

Category: Stratified Sequence

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

SSURGO SOIL MAP - 8145281.2s



SITE NAME:	Stone Academy	CLIENT:	HRP Associates, Inc.
ADDRESS:	745 Burnside Avenue East Hartford CT 06108	CONTACT:	Joy Waters
		INQUIRY #:	8145281.2s
LAT/LONG:	41.7792 / 72.606685	DATE:	October 20, 2025 1:40 pm

Copyright © 2025 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. The following information is based on Soil Conservation Service SSURGO data.

Soil Map ID: 1

Soil Component Name: Windsor

Soil Surface Texture: moderately decomposed plant material

Hydrologic Group: Class A - High infiltration rates. Soils are deep, well drained to excessively drained sands and gravels.

Soil Drainage Class: Excessively drained

Hydric Status: Unknown

Corrosion Potential - Uncoated Steel: Low

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	1 inches	moderately decomposed plant material	A-8	COARSE-GRAINED SOILS, Sands, Clean Sands, Well-graded sand. COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 703 Min: 42	Max: 6.5 Min: 4.5
2	1 inches	3 inches	loamy sand	A-8	COARSE-GRAINED SOILS, Sands, Clean Sands, Well-graded sand. COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 703 Min: 42	Max: 6.5 Min: 4.5
3	3 inches	9 inches	loamy sand	A-8	COARSE-GRAINED SOILS, Sands, Clean Sands, Well-graded sand. COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 703 Min: 42	Max: 6.5 Min: 4.5

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
4	9 inches	20 inches	loamy sand	A-8	COARSE-GRAINED SOILS, Sands, Clean Sands, Well-graded sand. COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 703 Min: 42	Max: 6.5 Min: 4.5
5	20 inches	25 inches	sand	A-8	COARSE-GRAINED SOILS, Sands, Clean Sands, Well-graded sand. COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 703 Min: 42	Max: 6.5 Min: 4.5
6	25 inches	64 inches	sand	A-8	COARSE-GRAINED SOILS, Sands, Clean Sands, Well-graded sand. COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 703 Min: 42	Max: 6.5 Min: 4.5

Soil Map ID: 2

Soil Component Name: Udorthents

Soil Surface Texture: loam

Hydrologic Group: Class C - Slow infiltration rates. Soils with layers impeding downward movement of water, or soils with moderately fine or fine textures.

Soil Drainage Class: Well drained

Hydric Status: Unknown

Corrosion Potential - Uncoated Steel: Moderate

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	5 inches	loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 703 Min: 0.01	Max: 7.8 Min: 4.5
2	5 inches	21 inches	gravelly loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 703 Min: 0.01	Max: 7.8 Min: 4.5
3	21 inches	79 inches	very gravelly sandy loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 703 Min: 0.01	Max: 7.8 Min: 4.5

Soil Map ID: 3

Soil Component Name: Ninigret

Soil Surface Texture: fine sandy loam

Hydrologic Group: Class B - Moderate infiltration rates. Deep and moderately deep, moderately well and well drained soils with moderately coarse textures.

Soil Drainage Class: Moderately well drained

Hydric Status: Partially hydric

Corrosion Potential - Uncoated Steel: Moderate

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 61 inches

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	7 inches	fine sandy loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 703 Min: 42	Max: 6.5 Min: 4.5
2	7 inches	16 inches	fine sandy loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 703 Min: 42	Max: 6.5 Min: 4.5
3	16 inches	25 inches	fine sandy loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 703 Min: 42	Max: 6.5 Min: 4.5
4	25 inches	64 inches	stratified very gravelly coarse sand to loamy fine sand	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 703 Min: 42	Max: 6.5 Min: 4.5

Soil Map ID: 4

Soil Component Name: Merrimac

Soil Surface Texture: sandy loam

Hydrologic Group: Class B - Moderate infiltration rates. Deep and moderately deep, moderately well and well drained soils with moderately coarse textures.

Soil Drainage Class: Somewhat excessively drained

Hydric Status: Partially hydric

Corrosion Potential - Uncoated Steel: Low

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	9 inches	sandy loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	COARSE-GRAINED SOILS, Sands, Clean Sands, Poorly graded sand. COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 703 Min: 42	Max: 6 Min: 5.1
2	9 inches	16 inches	sandy loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	COARSE-GRAINED SOILS, Sands, Clean Sands, Poorly graded sand. COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 703 Min: 42	Max: 6 Min: 5.1
3	16 inches	24 inches	gravelly sandy loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	COARSE-GRAINED SOILS, Sands, Clean Sands, Poorly graded sand. COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 703 Min: 42	Max: 6 Min: 5.1
4	24 inches	59 inches	stratified very gravelly coarse sand to gravelly sand	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	COARSE-GRAINED SOILS, Sands, Clean Sands, Poorly graded sand. COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 703 Min: 42	Max: 6 Min: 5.1

Soil Map ID: 5

Soil Component Name: Water

Soil Surface Texture: sandy loam

Hydrologic Group: Class B - Moderate infiltration rates. Deep and moderately deep, moderately well and well drained soils with moderately coarse textures.

Soil Drainage Class:

Hydric Status: Unknown

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

No Layer Information available.

Soil Map ID: 6

Soil Component Name: Windsor

Soil Surface Texture: moderately decomposed plant material

Hydrologic Group: Class A - High infiltration rates. Soils are deep, well drained to excessively drained sands and gravels.

Soil Drainage Class: Excessively drained

Hydric Status: Unknown

Corrosion Potential - Uncoated Steel: Low

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	1 inches	moderately decomposed plant material	A-8	COARSE-GRAINED SOILS, Sands, Clean Sands, Well-graded sand. COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 703 Min: 42	Max: 6.5 Min: 4.5
2	1 inches	3 inches	loamy sand	A-8	COARSE-GRAINED SOILS, Sands, Clean Sands, Well-graded sand. COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 703 Min: 42	Max: 6.5 Min: 4.5

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
3	3 inches	9 inches	loamy sand	A-8	COARSE-GRAINED SOILS, Sands, Clean Sands, Well-graded sand. COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 703 Min: 42	Max: 6.5 Min: 4.5
4	9 inches	20 inches	loamy sand	A-8	COARSE-GRAINED SOILS, Sands, Clean Sands, Well-graded sand. COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 703 Min: 42	Max: 6.5 Min: 4.5
5	20 inches	25 inches	sand	A-8	COARSE-GRAINED SOILS, Sands, Clean Sands, Well-graded sand. COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 703 Min: 42	Max: 6.5 Min: 4.5
6	25 inches	64 inches	sand	A-8	COARSE-GRAINED SOILS, Sands, Clean Sands, Well-graded sand. COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 703 Min: 42	Max: 6.5 Min: 4.5

Soil Map ID: 7

Soil Component Name: Urban land

Soil Surface Texture: material

Hydrologic Group: Class A - High infiltration rates. Soils are deep, well drained to excessively drained sands and gravels.

Soil Drainage Class:
Hydric Status: Unknown

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	5 inches	material	Not reported	Not reported	Max: 141 Min: 0.07	Max: Min:

Soil Map ID: 8

Soil Component Name: Windsor

Soil Surface Texture: moderately decomposed plant material

Hydrologic Group: Class A - High infiltration rates. Soils are deep, well drained to excessively drained sands and gravels.

Soil Drainage Class: Excessively drained

Hydric Status: Unknown

Corrosion Potential - Uncoated Steel: Low

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	1 inches	moderately decomposed plant material	A-8	COARSE-GRAINED SOILS, Sands, Clean Sands, Well-graded sand. COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 703 Min: 42	Max: 6.5 Min: 4.5
2	1 inches	3 inches	loamy sand	A-8	COARSE-GRAINED SOILS, Sands, Clean Sands, Well-graded sand. COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 703 Min: 42	Max: 6.5 Min: 4.5

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
3	3 inches	9 inches	loamy sand	A-8	COARSE-GRAINED SOILS, Sands, Clean Sands, Well-graded sand. COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 703 Min: 42	Max: 6.5 Min: 4.5
4	9 inches	20 inches	loamy sand	A-8	COARSE-GRAINED SOILS, Sands, Clean Sands, Well-graded sand. COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 703 Min: 42	Max: 6.5 Min: 4.5
5	20 inches	25 inches	sand	A-8	COARSE-GRAINED SOILS, Sands, Clean Sands, Well-graded sand. COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 703 Min: 42	Max: 6.5 Min: 4.5
6	25 inches	64 inches	sand	A-8	COARSE-GRAINED SOILS, Sands, Clean Sands, Well-graded sand. COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 703 Min: 42	Max: 6.5 Min: 4.5

Soil Map ID: 9

Soil Component Name: Ninigret

Soil Surface Texture: fine sandy loam

Hydrologic Group: Class B - Moderate infiltration rates. Deep and moderately deep, moderately well and well drained soils with moderately coarse textures.

Soil Drainage Class: Moderately well drained

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Hydric Status: Partially hydric

Corrosion Potential - Uncoated Steel: Moderate

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 61 inches

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	7 inches	fine sandy loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 703 Min: 42	Max: 6.5 Min: 4.5
2	7 inches	16 inches	fine sandy loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 703 Min: 42	Max: 6.5 Min: 4.5
3	16 inches	25 inches	fine sandy loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 703 Min: 42	Max: 6.5 Min: 4.5
4	25 inches	64 inches	stratified very gravelly coarse sand to loamy fine sand	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 703 Min: 42	Max: 6.5 Min: 4.5

Soil Map ID: 10

Soil Component Name: Agawam

Soil Surface Texture: fine sandy loam

Hydrologic Group: Class B - Moderate infiltration rates. Deep and moderately deep, moderately well and well drained soils with moderately coarse textures.

Soil Drainage Class: Well drained

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Hydric Status: Partially hydric

Corrosion Potential - Uncoated Steel: Low

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	7 inches	fine sandy loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	COARSE-GRAINED SOILS, Sands, Clean Sands, Poorly graded sand. COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 703 Min: 141	Max: 6.5 Min: 4.5
2	7 inches	14 inches	fine sandy loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	COARSE-GRAINED SOILS, Sands, Clean Sands, Poorly graded sand. COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 703 Min: 141	Max: 6.5 Min: 4.5
3	14 inches	24 inches	fine sandy loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	COARSE-GRAINED SOILS, Sands, Clean Sands, Poorly graded sand. COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 703 Min: 141	Max: 6.5 Min: 4.5
4	24 inches	59 inches	stratified very gravelly coarse sand to fine sand	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	COARSE-GRAINED SOILS, Sands, Clean Sands, Poorly graded sand. COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 703 Min: 141	Max: 6.5 Min: 4.5

Soil Map ID: 11

Soil Component Name: Udorthents

Soil Surface Texture: loam

Hydrologic Group: Class C - Slow infiltration rates. Soils with layers impeding downward movement of water, or soils with moderately fine or fine textures.

Soil Drainage Class: Well drained

Hydric Status: Partially hydric

Corrosion Potential - Uncoated Steel: Moderate

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	5 inches	loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 703 Min: 0.01	Max: 7.8 Min: 4.5
2	5 inches	21 inches	gravelly loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 703 Min: 0.01	Max: 7.8 Min: 4.5
3	21 inches	79 inches	very gravelly sandy loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 703 Min: 0.01	Max: 7.8 Min: 4.5

Soil Map ID: 12

Soil Component Name: Limerick

Soil Surface Texture: silt loam

Hydrologic Group: Class D - Very slow infiltration rates. Soils are clayey, have a high water table, or are shallow to an impervious layer.

Soil Drainage Class: Poorly drained

Hydric Status: Partially hydric

Corrosion Potential - Uncoated Steel: High

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 23 inches

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	7 inches	silt loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), silt.	Max: 14 Min: 4	Max: 7.3 Min: 5.6
2	7 inches	20 inches	silt loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), silt.	Max: 14 Min: 4	Max: 7.3 Min: 5.6
3	20 inches	35 inches	silt loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), silt.	Max: 14 Min: 4	Max: 7.3 Min: 5.6
4	35 inches	53 inches	silt loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), silt.	Max: 14 Min: 4	Max: 7.3 Min: 5.6
5	53 inches	64 inches	silt loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), silt.	Max: 14 Min: 4	Max: 7.3 Min: 5.6

Soil Map ID: 13

Soil Component Name: Elmridge

Soil Surface Texture: fine sandy loam

Hydrologic Group: Class C - Slow infiltration rates. Soils with layers impeding downward movement of water, or soils with moderately fine or fine textures.

Soil Drainage Class: Moderately well drained

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Hydric Status: Partially hydric

Corrosion Potential - Uncoated Steel: High

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 61 inches

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	5 inches	fine sandy loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 0.42 Min: 0.01	Max: 7.8 Min: 5.6
2	5 inches	9 inches	fine sandy loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 0.42 Min: 0.01	Max: 7.8 Min: 5.6
3	9 inches	18 inches	fine sandy loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 0.42 Min: 0.01	Max: 7.8 Min: 5.6
4	18 inches	25 inches	sandy loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 0.42 Min: 0.01	Max: 7.8 Min: 5.6
5	25 inches	64 inches	silty clay	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 0.42 Min: 0.01	Max: 7.8 Min: 5.6

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 1 mile
State Database	1.000

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
1	USGS40000228535	1/4 - 1/2 Mile SSW
3	USGS40000228550	1/4 - 1/2 Mile West
4	USGS40000228572	1/4 - 1/2 Mile WNW
5	USGS40000228576	1/2 - 1 Mile WNW
6	USGS40000228577	1/2 - 1 Mile ENE
7	USGS40000228470	1/2 - 1 Mile SSW
8	USGS40000228608	1/2 - 1 Mile NE
9	USGS40000228492	1/2 - 1 Mile SE

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION


MAP ID	WELL ID	LOCATION FROM TP
2	CT0430022	1/4 - 1/2 Mile NW

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No Wells Found		

PHYSICAL SETTING SOURCE MAP - 8145281.2s



- County Boundary
- Major Roads
- Contour Lines
- Earthquake epicenter, Richter 5 or greater
- Water Wells
- Public Water Supply Wells
- Cluster of Multiple Icons
- Groundwater Flow Direction
- Indeterminate Groundwater Flow at Location
- Groundwater Flow Varies at Location
- Closest Hydrogeological Data
- EPA Designated Sole Src. Aq.

SITE NAME:	Stone Academy	CLIENT:	HRP Associates, Inc.
ADDRESS:	745 Burnside Avenue East Hartford CT 06108	CONTACT:	Joy Waters
		INQUIRY #:	8145281.2s
LAT/LONG:	41.7792 / 72.606685	DATE:	October 20, 2025 1:40 pm

Copyright © 2025 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

1
SSW
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000228535**

Organization ID:	USGS-CT		
Organization Name:	USGS Connecticut Water Science Center		
Monitor Location:	CT-EH 22	Type:	Well
Description:	Not Reported	HUC:	01080205
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Early Mesozoic basin aquifers		
Formation Type:	Not Reported	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	447
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

2
NW
1/4 - 1/2 Mile
Lower

FRDS PWS **CT0430022**

Epa region:	01	State:	CT
Pwsid:	CT0430022	Pwsname:	BOHEMIAN SOCIETY OF LODGE POLA
Cityserved:	Not Reported	Stateserved:	CT
Zipserved:	Not Reported	Fipscounty:	09003
Status:	Closed	Retpopsrvd:	25
Pwssvcconn:	1	Psource longname:	Groundwater
Pwstype:	TNCWS	Owner:	unknown
Contact:	BOHEMIAN SOCIETY OF LODGE POLA		
Contactorgname:	Not Reported	Contactphone:	Not Reported
Contactaddress1:	Not Reported	Contactaddress2:	FOREST ST
Contactcity:	EAST HARTFORD	Contactstate:	CT
Contactzip:	06108	Pwsactivitycode:	I
PWS ID:	CT0430022	PWS type:	Not Reported
PWS name:	Not Reported	PWS address:	Not Reported
PWS city:	Not Reported	PWS state:	Not Reported
PWS zip:	Not Reported	PWS ID:	CT0430022
Activity status:	Active	Date system activated:	7706
Date system deactivated:	Not Reported	Retail population:	00000030
System name:	BOHEMIAN SOCIETY OF LODGE POLA		
System address:	Not Reported	System address:	FOREST ST
System city:	EAST HARTFORD	System state:	CT
System zip:	06108		
Population served:	Under 101 Persons	Treatment:	Untreated
Latitude:	414655	Longitude:	0723645

3
West
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000228550**

Organization ID:	USGS-CT
Organization Name:	USGS Connecticut Water Science Center

Monitor Location:	CT-EH 36	Type:	Well
Description:	Not Reported	HUC:	01080205
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Early Mesozoic basin aquifers		
Formation Type:	Not Reported	Aquifer Type:	Not Reported
Construction Date:	1949	Well Depth:	600
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Ground water levels,Number of Measurements:	1	Level reading date:	1949-01-01
Feet below surface:	30.00	Feet to sea level:	Not Reported
Note:	Not Reported		

4
WNW **FED USGS** **USGS40000228572**
1/4 - 1/2 Mile
Lower

Organization ID:	USGS-CT		
Organization Name:	USGS Connecticut Water Science Center		
Monitor Location:	CT-EH 161	Type:	Well
Description:	Not Reported	HUC:	01080205
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Early Mesozoic basin aquifers		
Formation Type:	Not Reported	Aquifer Type:	Not Reported
Construction Date:	1961	Well Depth:	740
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Ground water levels,Number of Measurements:	1	Level reading date:	1961-10-01
Feet below surface:	73.00	Feet to sea level:	Not Reported
Note:	Not Reported		

5
WNW **FED USGS** **USGS40000228576**
1/2 - 1 Mile
Lower

Organization ID:	USGS-CT		
Organization Name:	USGS Connecticut Water Science Center		
Monitor Location:	CT-EH 162	Type:	Well
Description:	Not Reported	HUC:	01080205
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Early Mesozoic basin aquifers		
Formation Type:	Not Reported	Aquifer Type:	Not Reported
Construction Date:	1963	Well Depth:	195
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Ground water levels,Number of Measurements:	1	Level reading date:	1963-11-01
Feet below surface:	35.00	Feet to sea level:	Not Reported
Note:	Not Reported		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

6
ENE **FED USGS** **USGS40000228577**
1/2 - 1 Mile
Lower

Organization ID:	USGS-CT		
Organization Name:	USGS Connecticut Water Science Center		
Monitor Location:	CT-EH 3	Type:	Well
Description:	Not Reported	HUC:	01080205
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Early Mesozoic basin aquifers		
Formation Type:	Not Reported	Aquifer Type:	Not Reported
Construction Date:	1922	Well Depth:	85
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Ground water levels,Number of Measurements:	1	Level reading date:	1922-03-01
Feet below surface:	10.00	Feet to sea level:	Not Reported
Note:	Not Reported		

7
SSW **FED USGS** **USGS40000228470**
1/2 - 1 Mile
Lower

Organization ID:	USGS-CT		
Organization Name:	USGS Connecticut Water Science Center		
Monitor Location:	CT-EH 163	Type:	Well
Description:	Not Reported	HUC:	01080205
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Early Mesozoic basin aquifers		
Formation Type:	Not Reported	Aquifer Type:	Not Reported
Construction Date:	1959	Well Depth:	702
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Ground water levels,Number of Measurements:	1	Level reading date:	1959-12-01
Feet below surface:	23.00	Feet to sea level:	Not Reported
Note:	Not Reported		

8
NE **FED USGS** **USGS40000228608**
1/2 - 1 Mile
Higher

Organization ID:	USGS-CT		
Organization Name:	USGS Connecticut Water Science Center		
Monitor Location:	CT-EH 26	Type:	Well
Description:	Not Reported	HUC:	01080205
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Early Mesozoic basin aquifers		
Formation Type:	Not Reported	Aquifer Type:	Not Reported
Construction Date:	1946	Well Depth:	140

Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

9
SE
1/2 - 1 Mile
Higher

FED USGS **USGS40000228492**

Organization ID:	USGS-CT		
Organization Name:	USGS Connecticut Water Science Center		
Monitor Location:	CT-EH 160	Type:	Well
Description:	Not Reported	HUC:	01080205
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Early Mesozoic basin aquifers		
Formation Type:	Sedimentary Bedrock	Aquifer Type:	Not Reported
Construction Date:	1968	Well Depth:	197
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

State Database: CT Radon

Radon Test Results

City	# Sites	< 4 Pci/L	4 < 10 Pci/L	10 < 20 Pci/L	20 < 50 Pci/L	50 < 100 Pci/L	> 100 Pci/L
Southington	27	12 (44.4)	11 (40.7)	4 (14.8)	0 (0)	0 (0)	0 (0)
Suffield	12	10 (83.3)	2 (16.7)	0 (0)	0 (0)	0 (0)	0 (0)
Unionville	5	5 (100)	0 (0)	0 (0)	0 (0)	0 (0)	0 (0)
Weatogue	6	6 (100)	0 (0)	0 (0)	0 (0)	0 (0)	0 (0)
West Hartford	55	46 (83.6)	7 (12.7)	1 (1.8)	1 (1.8)	0 (0)	0 (0)
West Simsbury	13	12 (92.3)	1 (7.7)	0 (0)	0 (0)	0 (0)	0 (0)
West Suffield	5	5 (100)	0 (0)	0 (0)	0 (0)	0 (0)	0 (0)
Wethersfield	33	27 (81.8)	5 (15.2)	1 (3)	0 (0)	0 (0)	0 (0)
Windsor	19	15 (78.9)	4 (21.1)	0 (0)	0 (0)	0 (0)	0 (0)
Windsor Locks	8	8 (100)	0 (0)	0 (0)	0 (0)	0 (0)	0 (0)
Tariffville	2	1 (50)	0 (0)	0 (0)	1 (50)	0 (0)	0 (0)
East Hampton	110	83 (100)	19 (0)	8 (0)	0 (0)	0 (0)	0 (0)
Manchester	34	24 (70.6)	10 (29.4)	0 (0)	0 (0)	0 (0)	0 (0)
Avon	15	8 (53.3)	6 (50)	1 (6.7)	0 (0)	0 (0)	0 (0)
Berlin	11	7 (63.6)	1 (9.1)	4 (36.4)	0 (0)	0 (0)	0 (0)
Bloomfield	7	7 (100)	0 (0)	0 (0)	0 (0)	0 (0)	0 (0)
Bristol	17	10 (58.8)	4 (23.5)	3 (17.6)	0 (0)	0 (0)	0 (0)
Broad Brook	3	1 (33.3)	2 (66.7)	0 (0)	0 (0)	0 (0)	0 (0)
Burlington	125	125 (100)	0 (0)	0 (0)	0 (0)	0 (0)	0 (0)
Canton	8	6 (75)	2 (25)	0 (0)	0 (0)	0 (0)	0 (0)
Collinsville	1	0 (0)	1 (100)	0 (0)	0 (0)	0 (0)	0 (0)
East Berlin	6	4 (66.7)	2 (33.3)	0 (0)	0 (0)	0 (0)	0 (0)
East Granby	13	8 (61.5)	0 (0)	1 (7.7)	0 (0)	4 (30.8)	0 (0)
East Hartford	20	20 (100)	0 (0)	0 (0)	0 (0)	0 (0)	0 (0)
East Hartland	1	1 (100)	0 (0)	0 (0)	0 (0)	0 (0)	0 (0)
East Windsor	4	3 (75)	1 (25)	0 (0)	0 (0)	0 (0)	0 (0)
Enfield	2	2 (100)	0 (0)	0 (0)	0 (0)	0 (0)	0 (0)
Farmington	34	31 (91.2)	1 (2.9)	0 (5.9)	2 (0)	0 (0)	0 (0)
Forestville	3	3 (100)	0 (0)	0 (0)	0 (0)	0 (0)	0 (0)
Glastonbury	152	120 (78.9)	22 (14.5)	5 (3.3)	4 (2.6)	0 (0)	1 (.7)
Granby	10	8 (80)	2 (20)	0 (0)	0 (0)	0 (0)	0 (0)
Hartford	99	95 (96)	5 (4)	0 (0)	0 (0)	0 (0)	0 (0)
Kensington	7	6 (85.7)	1 (14.3)	0 (0)	0 (0)	0 (0)	0 (0)
Marion	1	1 (100)	0 (0)	0 (0)	0 (0)	0 (0)	0 (0)
Marlborough	16	12 (75)	4 (25)	0 (0)	0 (0)	0 (0)	0 (0)
New Britain	20	13 (65)	5 (25)	2 (10)	0 (0)	0 (0)	0 (0)
Newington	45	26 (57.8)	12 (26.7)	6 (13.3)	1 (2.2)	0 (0)	0 (0)
North Canton	2	2 (100)	0 (0)	0 (0)	0 (0)	0 (0)	0 (0)
Plainville	2	2 (100)	0 (0)	0 (0)	0 (0)	0 (0)	0 (0)
Plantsville	3	3 (100)	0 (0)	0 (0)	0 (0)	0 (0)	0 (0)
Rocky Hill	24	19 (79.2)	3 (12.5)	2 (8.3)	0 (0)	0 (0)	0 (0)
Simsbury	13	12 (92.3)	1 (7.7)	0 (0)	0 (0)	0 (0)	0 (0)
South Glastonbury	13	10 (76.9)	0 (0)	1 (7.7)	1 (7.7)	0 (0)	1 (7.7)
South Windsor	23	23 (100)	0 (0)	0 (0)	0 (0)	0 (0)	0 (0)

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

Federal EPA Radon Zone for HARTFORD County: 3

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for Zip Code: 06108

Number of sites tested: 2

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area - 1st Floor	Not Reported	Not Reported	Not Reported	Not Reported
Living Area - 2nd Floor	Not Reported	Not Reported	Not Reported	Not Reported
Basement	1.550 pCi/L	100%	0%	0%

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

HYDROLOGIC INFORMATION

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005, 2010 and 2015 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Tidal Wetlands
Source: Department of Energy & Environmental Protection
Telephone: 860-424-4054

HYDROGEOLOGIC INFORMATION

AQUIFLOW^{R} Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Service, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

Community and Non-Community Water System Wells
Source: Department of Public Health, Water Supplies Section
Telephone: 860-509-7333
Active, emergency and inactive wells used for potable purposes that are owned and operated by active community and non-community water systems in Connecticut.

Wells in Connecticut Listing
Department of Consumer Protection
Telephone: 860-713-6022
Water wells located in the state of Connecticut.

OTHER STATE DATABASE INFORMATION

Connecticut Leachate and Wastewater Discharge Sites
Source: Department of Environmental Protection
Telephone:
The Leachate and Waste Water Discharge Inventory Data Layer (LWDS) includes point locations digitized from Leachate and Wastewater Discharge Source maps compiled by the Connecticut DEP. These maps locate surface and groundwater discharges that (1) have received a waste water discharge permit from the state or (2) are historic and now defunct waste sites or (3) are locations of accidental spills, leaks, or discharges of a variety of liquid or solid wastes.

EPA-Approved Sole Source Aquifers in Connecticut
Source: EPA
Telephone:
Sole source aquifers are defined as an aquifer designated as the sole or principal source of drinking water for a given aquifer service area; that is, an aquifer which is needed to supply 50% or more of the drinking water for the area and for which there are no reasonable alternative sources should the aquifer become contaminated.

RADON

State Database: CT Radon
Source: Department of Public Health
Telephone: 860-509-7367
Radon Statistical Summary

PHYSICAL SETTING SOURCE RECORDS SEARCHED

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary faultlines, prepared in 1975 by the United State Geological Survey

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

APPENDIX E
Supporting Documentation

745 BURNSIDE AVE.
763 BURNSIDE AVE.

SHEET TITLE: SITE LAYOUT PLAN

JOB NAME

SCALE: 1"=40'

JOB NO.

DRAWN

CHECKED: E.J.A


DATE: C.P.S. 11-4-88


REVISION DATE : MARCH 3, 1988

TYP. HANDICAP PARKING DETAIL

NOT TO SCALE

NOTE : CROSS HATCH TO BE 3' WIDE BETWEEN TWO HP SPACES.





LEGEND

- ○ EXIST. IRON PIN
- ● IRON PIN TO BE SET
- ⊡ EXIST. MONUMENT
- ■ MONUMENT TO BE SET
- PROPOSED GRADE

763 BURNSIDE AVE.

ZONING INFORMATION
ZONE R - 4
SPECIAL PERMIT REQUIRED

ORIGINAL APPROVAL
DECEMBER 14, 1985

YARD REQUIREMENTS

REQUIRED	PROVIDED
F.Y. 25'	F.Y. 122'±
R.Y. 25'	R.Y. 84'±
S.Y. 20'/8' MIN.	S.Y. 125'/60' MIN.*

(CORNER LOT)

LOT COVERAGE

25% MAX.	ACTUAL 10.1%

PARKING

12 TEACHING STATIONS

REQUIRED	PROVIDED
60 SPACES	61 SPACES
57 9x18	57 9x18
3 HP	3 HP

* 60' IS MEASURED TO FUTURE PROPERTY LINE AFTER 15' IS DEEDED TO TOWN.

745 BURNSIDE AVE.

ZONING INFORMATION
ZONE R - 4
SPECIAL PERMIT REQUIRED

ORIGINAL APPROVAL
DECEMBER 14, 1985

YARD REQUIREMENTS

REQUIRED	PROVIDED
F.Y. 25'	F.Y. 150'±
R.Y. 25'	R.Y. 157'±
S.Y. 20'/8' MIN.	S.Y. 78'/20' MIN.

LOT COVERAGE


25% MAX.	ACTUAL 4.8%±

PARKING

REQUIRED	PROVIDED
13 9x18	17 9x18
1 HP	1 HP

LEGEND

- ○ EXIST. IRON PIN
- ● IRON PIN TO BE SET
- ⊡ EXIST. MONUMENT
- ■ MONUMENT TO BE SET
- PROPOSED GRADE



CERTIFICATION

1. I hereby declare that this map is substantially correct. This map and survey were prepared in accordance with the standards of a Class A-2 survey as defined in the "Recommended Standards for Surveys and Maps in the State of Connecticut" as prepared and adopted by the Connecticut Association of Land Surveyors, Inc., on September 10, 1984.
2. Topographic features, shown hereon, were prepared in accordance with CGS 7-31.

CHARLES P. SHEEHAN, L.S.
Reg. No. 10840

GREGORY J. LASSITER, P.E.
Reg. No. 17441

Parsons Brinckerhoff
Engineers · Architects · Planners
GLASTONBURY, CT 06033

80 Lupes Drive
Stratford, CT 06615

COMPLETE ENVIRONMENTAL TESTING, INC.

Tel: (203) 377-9984
Fax: (203) 377-9952
e-mail: cetl@cetlabs.com

Client: Mr. Dan Pinho
Zuvic-Carr and Associates, Inc
40 Cold Spring Road
Rocky Hill, CT 06067

Analytical Report

CET# 0030699

745 Burnside Ave

Report Date:April 01, 2020
Project: Stone Academy, 745 Burnside Ave, East Hartford
Project Number: 2016

Connecticut Laboratory Certificate: PH 0116
Massachusetts Laboratory Certificate: M-CT903
Rhode Island Laboratory Certificate: 199

NELAP ACCREDITED TNI LABORATORY

New York NELAP Accreditation: 11982
Pennsylvania Laboratory Certificate: 68-02927

SAMPLE SUMMARY

The sample(s) were received at 4.0°C.

This report contains analytical data associated with following samples only.

Sample ID	Laboratory ID	Matrix	Collection Date/Time	Receipt Date
Bottom 5.5-6ft	0030699-01	Soil	3/25/2020 11:30	03/26/2020

Analyte: Percent Solids [SM 2540 G] **Analyst: KWM / MTL**

Matrix: Soil

Laboratory ID	Client Sample ID	Result	RL	Units	Dilution	Batch	Prepared	Date/Time Analyzed	Notes
0030699-01	Bottom 5.5-6ft	80	1.0	%	1	B0C3015	03/30/2020	03/30/2020 15:40	

Client Sample ID Bottom 5.5-6ft

Lab ID: 0030699-01

Conn. Extractable TPH **Analyst: ACS**

Method: CT-ETPH **Matrix: Soil**

Analyte	Result (mg/kg dry)	RL (mg/kg dry)	Dilution	Prep Method	Batch	Prepared	Date/Time Analyzed	Notes
ETPH	ND	62	1	EPA 3550C	B0C2640	03/26/2020	03/27/2020 22:26	
Surrogate: Octacosane	*92.2 %*	*50 - 150*			B0C2640	03/26/2020	*03/27/2020 22:26*	

Semivolatile Organics **Analyst: JTS**

Method: EPA 8270D **Matrix: Soil**

Analyte	Result (ug/kg dry)	RL (ug/kg dry)	Dilution	Prep Method	Batch	Prepared	Date/Time Analyzed	Notes
Naphthalene	ND	370	1	EPA 3545A	B0C3002	03/30/2020	03/31/2020 17:17	
2-Methyl Naphthalene	ND	370	1	EPA 3545A	B0C3002	03/30/2020	03/31/2020 17:17	
Acenaphthylene	ND	370	1	EPA 3545A	B0C3002	03/30/2020	03/31/2020 17:17	
Acenaphthene	ND	370	1	EPA 3545A	B0C3002	03/30/2020	03/31/2020 17:17	
Fluorene	ND	370	1	EPA 3545A	B0C3002	03/30/2020	03/31/2020 17:17	
Phenanthrene	ND	370	1	EPA 3545A	B0C3002	03/30/2020	03/31/2020 17:17	
Anthracene	ND	370	1	EPA 3545A	B0C3002	03/30/2020	03/31/2020 17:17	
Fluoranthene	ND	370	1	EPA 3545A	B0C3002	03/30/2020	03/31/2020 17:17	
Pyrene	ND	370	1	EPA 3545A	B0C3002	03/30/2020	03/31/2020 17:17	
Benzo[a]anthracene	ND	370	1	EPA 3545A	B0C3002	03/30/2020	03/31/2020 17:17	
Chrysene	ND	370	1	EPA 3545A	B0C3002	03/30/2020	03/31/2020 17:17	
Benzo[b]fluoranthene	ND	370	1	EPA 3545A	B0C3002	03/30/2020	03/31/2020 17:17	
Benzo[k]fluoranthene	ND	370	1	EPA 3545A	B0C3002	03/30/2020	03/31/2020 17:17	
Benzo[a]pyrene	ND	370	1	EPA 3545A	B0C3002	03/30/2020	03/31/2020 17:17	
Indeno[1,2,3-cd]pyrene	ND	370	1	EPA 3545A	B0C3002	03/30/2020	03/31/2020 17:17	
Dibenz[a,h]anthracene	ND	370	1	EPA 3545A	B0C3002	03/30/2020	03/31/2020 17:17	
Benzo[g,h,i]perylene	ND	370	1	EPA 3545A	B0C3002	03/30/2020	03/31/2020 17:17	
Surrogate: Nitrobenzene-d5	*64.2 %*	*30 - 130*			B0C3002	03/30/2020	*03/31/2020 17:17*	
Surrogate: 2-Fluorobiphenyl	*79.9 %*	*30 - 130*			B0C3002	03/30/2020	*03/31/2020 17:17*	
Surrogate: Terphenyl-d14	*82.0 %*	*30 - 130*			B0C3002	03/30/2020	*03/31/2020 17:17*	

Client Sample ID Bottom 5.5-6ft

Lab ID: 0030699-01

Volatile Organics **Analyst: TWF**

Method: EPA 8260C **Matrix: Soil**

Analyte	Result (ug/kg dry)	RL (ug/kg dry)	Dilution	Prep Method	Batch	Prepared	Date/Time Analyzed	Notes
Dichlorodifluoromethane	ND	17	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
Chloromethane	ND	11	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
Vinyl Chloride	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
Bromomethane	ND	11	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
Chloroethane	ND	11	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
Trichlorofluoromethane	ND	46	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
Acetone	ND	170	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
Acrylonitrile	ND	9.1	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
Trichlorotrifluoroethane	ND	46	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
1,1-Dichloroethene	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
Methylene Chloride	ND	68	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
Carbon Disulfide	ND	11	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
Methyl-t-Butyl Ether (MTBE)	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
trans-1,2-Dichloroethene	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
1,1-Dichloroethane	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
2-Butanone (MEK)	ND	29	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
2,2-Dichloropropane	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
cis-1,2-Dichloroethene	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
Bromochloromethane	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
Chloroform	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
Tetrahydrofuran	ND	29	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
1,1,1-Trichloroethane	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
Carbon Tetrachloride	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
1,1-Dichloropropene	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
Benzene	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
1,2-Dichloroethane	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
Trichloroethene	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
1,2-Dichloropropane	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
Dibromomethane	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
Bromodichloromethane	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
Methyl Isobutyl Ketone	ND	29	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
cis-1,3-Dichloropropene	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
Toluene	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
trans-1,3-Dichloropropene	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
2-Hexanone	ND	29	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
1,1,2-Trichloroethane	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
Tetrachloroethene	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
1,3-Dichloropropane	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
Dibromochloromethane	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
1,2-Dibromoethane	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
trans-1,4-Dichloro-2-Butene	ND	29	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	

Client Sample ID Bottom 5.5-6ft

Lab ID: 0030699-01

Volatile Organics **Analyst: TWF**

Method: EPA 8260C **Matrix: Soil**

Analyte	Result (ug/kg dry)	RL (ug/kg dry)	Dilution	Prep Method	Batch	Prepared	Date/Time Analyzed	Notes
Chlorobenzene	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
1,1,1,2-Tetrachloroethane	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
Ethylbenzene	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
m+p Xylenes	ND	11	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
o-Xylene	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
Styrene	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
Bromoform	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
Isopropylbenzene	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
1,1,2,2-Tetrachloroethane	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
Bromobenzene	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
1,2,3-Trichloropropane	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
n-Propylbenzene	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
2-Chlorotoluene	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
4-Chlorotoluene	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
1,3,5-Trimethylbenzene	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
tert-Butylbenzene	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
1,2,4-Trimethylbenzene	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
sec-Butylbenzene	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
1,3-Dichlorobenzene	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
4-Isopropyltoluene	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
1,4-Dichlorobenzene	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
1,2-Dichlorobenzene	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
n-Butylbenzene	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	*I
1,2-Dibromo-3-Chloropropane	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
1,2,4-Trichlorobenzene	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
Hexachlorobutadiene	ND	5.7	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	*I
Naphthalene	ND	11	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
1,2,3-Trichlorobenzene	ND	11	1.83	EPA 5035A-L	B0C3037	03/30/2020	03/30/2020 16:48	
Surrogate: 1,2-Dichloroethane-d4	*97.4 %*		*70 - 130*		B0C3037	03/30/2020	*03/30/2020 16:48*	
Surrogate: Toluene-d8	*98.2 %*		*70 - 130*		B0C3037	03/30/2020	*03/30/2020 16:48*	
Surrogate: 4-Bromofluorobenzene	*102 %*		*70 - 130*		B0C3037	03/30/2020	*03/30/2020 16:48*	

QUALITY CONTROL SECTION

Batch B0C2640 - CT-ETPH

Analyte	Result (mg/kg)	RL (mg/kg)	Spike Level	Source Result	% Rec	% Rec Limits	RPD	RPD Limit	Notes
Blank (B0C2640-BLK1)					Prepared 3/26/2020 Analyzed 3/27/2020				
ETPH	ND	50							
Surrogate: Octacosane					*98.1*	*50 - 150*			
LCS (B0C2640-BS1)					Prepared 3/26/2020 Analyzed 3/27/2020				
ETPH	998	50	1,500.000		66.5	60 - 120			
Surrogate: Octacosane					*92.4*	*50 - 150*			

Batch B0C3002 - EPA 8270D

Analyte	Result (ug/kg)	RL (ug/kg)	Spike Level	Source Result	% Rec	% Rec Limits	RPD	RPD Limit	Notes
Blank (B0C3002-BLK1)					Prepared: 3/30/2020 Analyzed: 3/31/2020				
Naphthalene	ND	300							
2-Methyl Naphthalene	ND	300							
Acenaphthylene	ND	300							
Acenaphthene	ND	300							
Fluorene	ND	300							
Phenanthrene	ND	300							
Anthracene	ND	300							
Fluoranthene	ND	300							
Pyrene	ND	300							
Benzo[a]anthracene	ND	300							
Chrysene	ND	300							
Benzo[b]fluoranthene	ND	300							
Benzo[k]fluoranthene	ND	300							
Benzo[a]pyrene	ND	300							
Indeno[1,2,3-cd]pyrene	ND	300							
Dibenz[a,h]anthracene	ND	300							
Benzo[g,h,i]perylene	ND	300							
Surrogate: Nitrobenzene-d5					*66.1*	*30 - 130*			
Surrogate: 2-Fluorobiphenyl					*73.5*	*30 - 130*			
Surrogate: Terphenyl-d14					*68.2*	*30 - 130*			
LCS (B0C3002-BS1)					Prepared: 3/30/2020 Analyzed: 3/31/2020				
Naphthalene	2410	300	4,000.000		60.2	40 - 140			
2-Methyl Naphthalene	2620	300	4,000.000		65.6	40 - 140			
Acenaphthylene	2530	300	4,000.000		63.3	40 - 140			
Acenaphthene	2690	300	4,000.000		67.3	40 - 140			
Fluorene	2760	300	4,000.000		68.9	40 - 140			
Phenanthrene	2780	300	4,000.000		69.5	40 - 140			
Anthracene	2820	300	4,000.000		70.6	40 - 140			
Fluoranthene	2960	300	4,000.000		74.0	40 - 140			
Pyrene	3030	300	4,000.000		75.7	40 - 140			
Benzo[a]anthracene	2870	300	4,000.000		71.8	40 - 140			
Chrysene	2950	300	4,000.000		73.9	40 - 140			
Benzo[b]fluoranthene	2770	300	4,000.000		69.1	40 - 140			
Benzo[k]fluoranthene	2860	300	4,000.000		71.6	40 - 140			
Benzo[a]pyrene	2820	300	4,000.000		70.6	40 - 140			
Indeno[1,2,3-cd]pyrene	3190	300	4,000.000		79.8	40 - 140			
Dibenz[a,h]anthracene	3140	300	4,000.000		78.6	40 - 140			
Benzo[g,h,i]perylene	3340	300	4,000.000		83.6	40 - 140			
Surrogate: Nitrobenzene-d5					*71.7*	*30 - 130*			
Surrogate: 2-Fluorobiphenyl					*76.2*	*30 - 130*			
Surrogate: Terphenyl-d14					*68.1*	*30 - 130*			

Batch B0C3037 - EPA 8260C

Analyte	Result (ug/kg)	RL (ug/kg)	Spike Level	Source Result	% Rec	% Rec Limits	RPD	RPD Limit	Notes
Blank (B0C3037-BLK1)					Prepared: 3/30/2020 Analyzed: 3/30/2020				
Dichlorodifluoromethane	ND	7.5							
Chloromethane	ND	5.0							
Vinyl Chloride	ND	2.5							
Bromomethane	ND	5.0							
Chloroethane	ND	5.0							
Trichlorofluoromethane	ND	20							
Acetone	ND	75							
Acrylonitrile	ND	4.0							
Trichlorotrifluoroethane	ND	20							
1,1-Dichloroethene	ND	2.5							
Methylene Chloride	ND	30							
Carbon Disulfide	ND	5.0							
Methyl-t-Butyl Ether (MTBE)	ND	2.5							
trans-1,2-Dichloroethene	ND	2.5							
1,1-Dichloroethane	ND	2.5							
2-Butanone (MEK)	ND	13							
2,2-Dichloropropane	ND	2.5							
cis-1,2-Dichloroethene	ND	2.5							
Bromochloromethane	ND	2.5							
Chloroform	ND	2.5							
Tetrahydrofuran	ND	13							
1,1,1-Trichloroethane	ND	2.5							
Carbon Tetrachloride	ND	2.5							
1,1-Dichloropropene	ND	2.5							
Benzene	ND	2.5							
1,2-Dichloroethane	ND	2.5							
Trichloroethene	ND	2.5							
1,2-Dichloropropane	ND	2.5							
Dibromomethane	ND	2.5							
Bromodichloromethane	ND	2.5							
Methyl Isobutyl Ketone	ND	13							
cis-1,3-Dichloropropene	ND	2.5							
Toluene	ND	2.5							
trans-1,3-Dichloropropene	ND	2.5							
2-Hexanone	ND	13							
1,1,2-Trichloroethane	ND	2.5							
Tetrachloroethene	ND	2.5							
1,3-Dichloropropane	ND	2.5							
Dibromochloromethane	ND	2.5							
1,2-Dibromoethane	ND	2.5							
trans-1,4-Dichloro-2-Butene	ND	13							
Chlorobenzene	ND	2.5							
1,1,1,2-Tetrachloroethane	ND	2.5							
Ethylbenzene	ND	2.5							
m+p Xylenes	ND	5.0							
o-Xylene	ND	2.5							
Styrene	ND	2.5							
Bromoform	ND	2.5							
Isopropylbenzene	ND	2.5							
1,1,2,2-Tetrachloroethane	ND	2.5							
Bromobenzene	ND	2.5							
1,2,3-Trichloropropane	ND	2.5							

: 0030699
ject: Stone Academy, 745 Burnside Ave, East Hartford
Project Number: 2016

Analyte	Result (ug/kg)	RL (ug/kg)	Spike Level	Source Result	% Rec	% Rec Limits	RPD	RPD Limit	Notes
Blank (B0C3037-BLK1) - Continued					Prepared: 3/30/2020 Analyzed: 3/30/2020				
n-Propylbenzene	ND	2.5							
2-Chlorotoluene	ND	2.5							
4-Chlorotoluene	ND	2.5							
1,3,5-Trimethylbenzene	ND	2.5							
tert-Butylbenzene	ND	2.5							
1,2,4-Trimethylbenzene	ND	2.5							
sec-Butylbenzene	ND	2.5							
1,3-Dichlorobenzene	ND	2.5							
4-Isopropyltoluene	ND	2.5							
1,4-Dichlorobenzene	ND	2.5							
1,2-Dichlorobenzene	ND	2.5							
n-Butylbenzene	ND	2.5							
1,2-Dibromo-3-Chloropropane	ND	2.5							
1,2,4-Trichlorobenzene	ND	2.5							
Hexachlorobutadiene	ND	5.0							
Naphthalene	ND	5.0							
1,2,3-Trichlorobenzene									
Surrogate: 1,2-Dichloroethane-d4					*106*	*70 - 130*			
Surrogate: Toluene-d8					*98.1*	*70 - 130*			
Surrogate: 4-Bromofluorobenzene					*105*	*70 - 130*			
LCS (B0C3037-BS1)					Prepared: 3/30/2020 Analyzed: 3/30/2020				
Dichlorodifluoromethane	44.3	7.5	50.000		88.7	70 - 130			
Chloromethane	46.4	5.0	50.000		92.8	70 - 130			
Vinyl Chloride	46.7	2.5	50.000		93.5	70 - 130			
Bromomethane	52.3	5.0	50.000		105	70 - 130			
Chloroethane	50.0	5.0	50.000		100	70 - 130			
Trichlorofluoromethane	50.6	20	50.000		101	70 - 130			
Acetone	80.6	75	100.000		80.6	70 - 130			
Acrylonitrile	56.7	4.0	50.000		113	70 - 130			
Trichlorotrifluoroethane	47.2	20	50.000		94.4	70 - 130			
1,1-Dichloroethene	48.0	2.5	50.000		95.9	70 - 130			
Methylene Chloride	57.8	30	50.000		116	70 - 130			
Carbon Disulfide	43.9	5.0	50.000		87.7	70 - 130			
Methyl-t-Butyl Ether (MTBE)	56.8	2.5	50.000		114	70 - 130			
trans-1,2-Dichloroethene	50.3	2.5	50.000		101	70 - 130			
1,1-Dichloroethane	52.3	2.5	50.000		105	70 - 130			
2-Butanone (MEK)	105	13	100.000		105	70 - 130			
2,2-Dichloropropane	53.3	2.5	50.000		107	70 - 130			
cis-1,2-Dichloroethene	53.6	2.5	50.000		107	70 - 130			
Bromochloromethane	53.3	2.5	50.000		107	70 - 130			
Chloroform	53.6	2.5	50.000		107	70 - 130			
Tetrahydrofuran	59.8	13	50.000		120	70 - 130			
1,1,1-Trichloroethane	54.5	2.5	50.000		109	70 - 130			
Carbon Tetrachloride	54.0	2.5	50.000		108	70 - 130			
1,1-Dichloropropene	53.5	2.5	50.000		107	70 - 130			
Benzene	53.6	2.5	50.000		107	70 - 130			
1,2-Dichloroethane	56.2	2.5	50.000		112	70 - 130			
Trichloroethene	56.7	2.5	50.000		113	70 - 130			
1,2-Dichloropropane	54.2	2.5	50.000		108	70 - 130			
Dibromomethane	58.0	2.5	50.000		116	70 - 130			
Bromodichloromethane	55.7	2.5	50.000		111	70 - 130			
Methyl Isobutyl Ketone	118	13	100.000		118	70 - 130			

Analyte	Result (ug/kg)	RL (ug/kg)	Spike Level	Source Result	% Rec	% Rec Limits	RPD	RPD Limit	Notes
LCS (B0C3037-BS1) - Continued					Prepared: 3/30/2020 Analyzed: 3/30/2020				
cis-1,3-Dichloropropene	56.6	2.5	50.000		113	70 - 130			
Toluene	53.5	2.5	50.000		107	70 - 130			
trans-1,3-Dichloropropene	56.4	2.5	50.000		113	70 - 130			
2-Hexanone	109	13	100.000		109	70 - 130			
1,1,2-Trichloroethane	55.2	2.5	50.000		110	70 - 130			
Tetrachloroethene	53.6	2.5	50.000		107	70 - 130			
1,3-Dichloropropane	55.1	2.5	50.000		110	70 - 130			
Dibromochloromethane	54.9	2.5	50.000		110	70 - 130			
1,2-Dibromoethane	54.8	2.5	50.000		110	70 - 130			
trans-1,4-Dichloro-2-Butene	53.4	13	50.000		107	70 - 130			
Chlorobenzene	51.3	2.5	50.000		103	70 - 130			
1,1,1,2-Tetrachloroethane	52.5	2.5	50.000		105	70 - 130			
Ethylbenzene	50.2	2.5	50.000		100	70 - 130			
m+p Xylenes	102	5.0	100.000		102	70 - 130			
o-Xylene	51.0	2.5	50.000		102	70 - 130			
Styrene	52.8	2.5	50.000		106	70 - 130			
Bromoform	54.9	2.5	50.000		110	70 - 130			
Isopropylbenzene	49.6	2.5	50.000		99.1	70 - 130			
1,1,2,2-Tetrachloroethane	51.1	2.5	50.000		102	70 - 130			
Bromobenzene	47.9	2.5	50.000		95.7	70 - 130			
1,2,3-Trichloropropane	51.7	2.5	50.000		103	70 - 130			
n-Propylbenzene	46.3	2.5	50.000		92.7	70 - 130			
2-Chlorotoluene	47.3	2.5	50.000		94.5	70 - 130			
4-Chlorotoluene	47.4	2.5	50.000		94.8	70 - 130			
1,3,5-Trimethylbenzene	46.7	2.5	50.000		93.4	70 - 130			
tert-Butylbenzene	46.4	2.5	50.000		92.7	70 - 130			
1,2,4-Trimethylbenzene	47.0	2.5	50.000		93.9	70 - 130			
sec-Butylbenzene	45.6	2.5	50.000		91.1	70 - 130			
1,3-Dichlorobenzene	47.3	2.5	50.000		94.7	70 - 130			
4-Isopropyltoluene	46.2	2.5	50.000		92.4	70 - 130			
1,4-Dichlorobenzene	47.5	2.5	50.000		95.0	70 - 130			
1,2-Dichlorobenzene	48.3	2.5	50.000		96.7	70 - 130			
n-Butylbenzene	45.5	2.5	50.000		91.0	70 - 130			
1,2-Dibromo-3-Chloropropane	53.0	2.5	50.000		106	70 - 130			
1,2,4-Trichlorobenzene	48.4	2.5	50.000		96.8	70 - 130			
Hexachlorobutadiene	44.9	2.5	50.000		89.7	70 - 130			
Naphthalene	50.8	5.0	50.000		102	70 - 130			
1,2,3-Trichlorobenzene	49.1	5.0	50.000		98.2	70 - 130			
Surrogate: 1,2-Dichloroethane-d4					*103*	*70 - 130*			
Surrogate: Toluene-d8					*99.9*	*70 - 130*			
Surrogate: 4-Bromofluorobenzene					*103*	*70 - 130*			

Job #: 0030699
Project: Stone Academy, 745 Burnside Ave, East Hartford
Project Number: 2016

All questions related to this report should be directed to David Ditta, Timothy Fusco, or Robert Blake at 203-377-9984.

This technical report was reviewed by Robert Blake

Sincerely,

David Ditta

R Blake Jr.

Project Manager

David Ditta
Laboratory Director

Report Comments:

Sample Result Flags:
E- The result is estimated, above the calibration range.
H- The surrogate recovery is above the control limits.
L- The surrogate recovery is below the control limits.
B- The compound was detected in the laboratory blank.
P- The Relative Percent Difference (RPD) of dual column analyses exceeds 40%.
D- The RPD between the sample and the sample duplicate is high. Sample Homogeneity may be a problem.
+- The Surrogate was diluted out.
*C1- The Continuing Calibration did not meet method specifications and was biased low for this analyte. Increased uncertainty is associated with the reported value which is likely to be biased low.
*C2- The Continuing Calibration did not meet method specifications and was biased high for this analyte. Increased uncertainty is associated with the reported value which is likely to be biased high.
*F1- The Laboratory Control Sample recovery is outside of control limits. Reported value for this analyte is likely to be biased on the low side.
*F2- The Laboratory Control Sample recovery is outside of control limits. Reported value for this analyte is likely to be biased on the high side.
*I- Analyte exceeds method limits from second source standard in Initial Calibration Verification (ICV). No directional bias.

All results met standard operating procedures unless indicated by a data qualifier next to a sample result, or a narration in the QC report.

For Percent Solids, if any of the following prep methods (3050B, 3540C, 3545A, 3550C, 5035 and 9013A) were used for samples pertaining to this report, the percent solids procedure is within that prep method.

Complete Environmental Testing is only responsible for the certified testing and is not directly responsible for the integrity of the sample before laboratory receipt.

ND is None Detected at or above the specified reporting limit
Reporting Limit (RL) is the limit of detection for an analyte after any adjustment made for dilution or percent moisture.
All analyses were performed in house unless a Reference Laboratory is listed.
Samples will be disposed of 30 days after the report date.

80 Lupes Drive
Stratford, CT 06615

COMPLETE ENVIRONMENTAL TESTING, INC.

Tel: (203) 377-9984
Fax: (203) 377-9952
email: cet1@cetlabs.com

Quality Control Definitions and Abbreviations

Internal Standard (IS)	An Analyte added to each sample or sample extract. An internal standard is used to monitor retention time, calculate relative response, and quantify analytes of interest.
Surrogate Recovery	The % recovery for non-target organic compounds that are spiked into all samples. Used to determine method performance.
Continuing Calibration	An analytical standard analyzed with each set of samples to verify initial calibration of the system.
Batch	Samples that are analyzed together with the same method, sequence and lot of reagents within the same time period.
ND	Not detected at or above the specified reporting limit.
RL	RL is the limit of detection for an analyte after any adjustment made for dilution or percent moisture.
Dilution	Multiplier added to detection levels (MDL) and/or sample results due to interferences and/or high concentration of target compounds.
Duplicate	Result from the duplicate analysis of a sample.
Result	Amount of analyte found in a sample.
Spike Level	Amount of analyte added to a sample
Matrix Spike Result	Amount of analyte found including amount that was spiked.
Matrix Spike Dup	Amount of analyte found in duplicate spikes including amount that was spike.
Matrix Spike % Recovery	% Recovery of spiked amount in sample.
Matrix Spike Dup % Recovery	% Recovery of spiked duplicate amount in sample.
RPD	Relative percent difference between Matrix Spike and Matrix Spike Duplicate.
Blank	Method Blank that has been taken through all steps of the analysis.
LCS % Recovery	Laboratory Control Sample percent recovery. The amount of analyte recovered from a fortified sample.
Recovery Limits	A range within which specified measurements results must fall to be compliant.
CC	Calibration Verification

Flags:

- H- Recovery is above the control limits
- L- Recovery is below the control limits
- B- Compound detected in the Blank
- P- RPD of dual column results exceeds 40%
- #- Sample result too high for accurate spike recovery.

NELAP ACCREDITED TNI LABORATORY

Connecticut Laboratory Certification PH0116
Massachussets Laboratory Certification M-CT903
Pennsylvania NELAP Accreditation 68-02927

New York NELAP Accreditation 11982
Rhode Island Certification 199

REASONABLE CONFIDENCE PROTOCOL
LABORATORY ANALYSIS QA/QC CERTIFICATION FORM

Laboratory Name: Complete Environmental Testing, Inc. ***Client:*** Zuvic-Carr & Associates, Inc

Project Location: Stone Academy, 745 Burnside Ave, East Hartford ***Project Number:*** 2016

Laboratory Sample ID(s): 0030699-01

Sample Date(s): 03/25/2020


List RCP Methods Used: CT-ETPH, EPA 8260C, EPA 8270D

CET #: 0030699

1	For each analytical method referenced in this laboratory report package, were all specified QA/QC performance criteria followed, including the requirement to explain any criteria falling outside of acceptable guidelines, as specified in the CTDEP method-specific Reasonable Confidence Protocol documents?	☑ Yes ☐ No
1A	Were the method specified preservation and holding time requirements met?	☑ Yes ☐ No
1B	VPH and EPH Methods only: Was the VPH and EPH method conducted without significant modifications (see Section 11.3 of respective RCP methods)?	☐ Yes ☐ No ☑ N/A
2	Were all samples received by the laboratory in a condition consistent with that described on the associated chain-of-custody document(s)?	☑ Yes ☐ No
3	Were samples received at an appropriate temperature (< 6 degrees C.)?	☑ Yes ☐ No ☐ N/A
4	Were all QA/QC performance criteria specified in the CT DEP Reasonable Confidence Protocol documents achieved?	☐ Yes ☑ No
5a	a) Were reporting limits specified or referenced on the chain-of-custody?	☑ Yes ☐ No
5b	b) Were these reporting limits met?	☑ Yes ☐ No
6	For each analytical method referenced in this laboratory report package, were results reported for all constituents identified in the method-specific analyte lists presented in the Reasonable Confidence Protocol documents?	☐ Yes ☑ No
7	Are project specific matrix spikes and laboratory duplicates included with this data set?	☐ Yes ☑ No

Notes: For all questions to which the response was "No" (with the exception of question #7), additional information must be provided in an attached narrative. If the answer to question #1, #1A, or #1B is "No", the data package does not meet the requirements for "Reasonable Confidence."
This form may not be altered and all questions must be answered.

I, the undersigned, attest under the pains and penalties of perjury that, to the best of my knowledge and belief and based upon my personal inquiry of those responsible for providing the information contained in this analytical report, such information is accurate and complete.

Authorized Signature:  **Position:** Laboratory Director

Printed Name: David Ditta **Date:** 04/01/2020

Name of Laboratory: Complete Environmental Testing, Inc.

This certification form is to be used for RCP methods only.

RCP Case Narrative

4- See Exceptions Report Below

6- Client requested a subset of the RCP 8270 list.

7- Project specific QC was not requested by the client.

4- Exceptions Report

Analyte	QC Type	Exception	Result	RPD	Recovery (%)	Batch/Sequence Sample ID
Hexachlorobutadiene	ICV	Analyte exceeds method limit of second source standard. Non-directional bias				
n-Butylbenzene	ICV	Analyte exceeds method limit of second source standard. Non-directional bias				

QC Batch/Sequence Report

Batch	Sequence	CET ID	Sample ID	Specific Method	Matrix	Collection Date
B0C2640	S0C3015	0030699-01	Bottom 5.5-6ft	CT-ETPH	Soil	03/25/2020
B0C3037	S0C3107	0030699-01	Bottom 5.5-6ft	EPA 8260C	Soil	03/25/2020
B0C3002	S0D0110	0030699-01	Bottom 5.5-6ft	EPA 8270D	Soil	03/25/2020

CERTIFICATIONS

Analyses included in this Report | **Certifications**

in Soil	CT
8260C in Soil	
Dichlorodifluoromethane	CT,NY,PA
Chloromethane	CT,NY,PA
Vinyl Chloride	CT,NY,PA
Bromomethane	CT,NY,PA
Chloroethane	CT,NY,PA
Trichlorofluoromethane	CT,NY,PA
Acetone	CT,NY,PA
Acrylonitrile	CT
Trichlorotrifluoroethane	CT,NY,PA
1,1-Dichloroethene	CT,NY,PA
Methylene Chloride	CT,NY,PA
Carbon Disulfide	CT,NY,PA
Methyl-t-Butyl Ether (MTBE)	CT,NY,PA
trans-1,2-Dichloroethene	CT,NY,PA
1,1-Dichloroethane	CT,NY,PA
2-Butanone (MEK)	CT,NY,PA
2,2-Dichloropropane	CT,NY,PA
cis-1,2-Dichloroethene	CT,NY,PA
Bromochloromethane	CT,NY,PA
Chloroform	CT,NY,PA
Tetrahydrofuran	CT
1,1,1-Trichloroethane	CT,NY,PA
Carbon Tetrachloride	CT,NY,PA
1,1-Dichloropropene	CT,NY,PA
Benzene	CT,NY,PA
1,2-Dichloroethane	CT,NY,PA
Trichloroethene	CT,NY,PA
1,2-Dichloropropane	CT,NY,PA
Dibromomethane	CT,NY,PA
Bromodichloromethane	CT,NY,PA
Methyl Isobutyl Ketone	CT,NY,PA
cis-1,3-Dichloropropene	CT,NY,PA
Toluene	CT,NY,PA
trans-1,3-Dichloropropene	CT,NY,PA
2-Hexanone	CT,NY,PA
1,1,2-Trichloroethane	CT,NY,PA
Tetrachloroethene	CT,NY,PA
1,3-Dichloropropane	CT,NY,PA
Dibromochloromethane	CT,NY,PA
1,2-Dibromoethane	CT,NY,PA
trans-1,4-Dichloro-2-Butene	CT,NY,PA
Chlorobenzene	CT,NY,PA
1,1,1,2-Tetrachloroethane	CT,NY,PA
Ethylbenzene	CT,NY,PA
m+p Xylenes	CT,NY,PA
o-Xylene	CT,NY,PA
Styrene	CT,NY,PA

Analytes included in this Report

	Certifications
in Soil	
Chloroform	CT,NY,PA
Isopropylbenzene	CT,NY,PA
1,1,2,2-Tetrachloroethane	CT,NY,PA
Bromobenzene	CT,NY,PA
1,2,3-Trichloropropane	CT,NY,PA
n-Propylbenzene	CT,NY,PA
2-Chlorotoluene	CT,NY,PA
4-Chlorotoluene	CT,NY,PA
1,3,5-Trimethylbenzene	CT,NY,PA
tert-Butylbenzene	CT,NY,PA
1,2,4-Trimethylbenzene	CT,NY,PA
sec-Butylbenzene	CT,NY,PA
1,3-Dichlorobenzene	CT,NY,PA
4-Isopropyltoluene	CT,NY,PA
1,4-Dichlorobenzene	CT,NY,PA
1,2-Dichlorobenzene	CT,NY,PA
n-Butylbenzene	CT,NY,PA
1,2-Dibromo-3-Chloropropane	CT,NY,PA
1,2,4-Trichlorobenzene	CT,NY,PA
Hexachlorobutadiene	CT,NY,PA
Naphthalene	CT,NY,PA
1,2,3-Trichlorobenzene	CT
EPA 8270D in Soil	
Naphthalene	CT,NY,PA
2-Methyl Naphthalene	CT,NY,PA
Acenaphthylene	CT,NY,PA
Acenaphthene	CT,NY,PA
Fluorene	CT,NY,PA
Phenanthrene	CT,NY,PA
Anthracene	CT,NY,PA
Fluoranthene	CT,NY,PA
Pyrene	CT,NY,PA
Benzo[a]anthracene	CT,NY,PA
Chrysene	CT,NY,PA
Benzo[b]fluoranthene	CT,NY,PA
Benzo[k]fluoranthene	CT,NY,PA
Benzo[a]pyrene	CT,NY,PA
Indeno[1,2,3-cd]pyrene	CT,NY,PA
Dibenz[a,h]anthracene	CT,NY,PA
Benzo[g,h,i]perylene	CT,NY,PA
SM 2540 G in Soil	
Percent Solids	CT

...ronmental Testing operates under the following certifications and accreditations:

Description	Number	Expires
Connecticut Public Health	PH0116	09/30/2020
New York Certification (NELAC)	11982	04/01/2020
Pennsylvania DEP	68-02927	05/31/2020

0030699

CET

COMPLETE ENVIRONMENTAL TESTING, INC.

CHAIN OF CUSTODY

Volatile Soils Only:
Date and Time in Freezer
Client:
CET:

80 Lupes Drive
Stratford, CT 06615
Tel: (203) 377-9984
Fax: (203) 377-9952
e-mail: cet1@cetlabs.com
Bottle Request e-mail: bottleorders@cetlabs.com

Matrix: A=Air, S=Soil, W=Water, DW=Drinking Water, C=Cassette, Solid, Wipe, Other (Specify)

Turnaround Time ** (check one): Same Day *, Next Day *, Two Day *, Three Day *, Std (5-7 Days)

Sample ID/Sample Depths (Include Units for any sample depths provided)	Collection Date/Time	Matrix	8260 CT List	8260 Aromatics	8260 Halogens	CT ETPH	8270 CT List	8270 PNAs	PCBs ☐ SOX ☐ ASE	Pesticides	Metals: 8 RCRA	13 Priority Poll	15 CT DEP	Total	SPLP	TCLP	Dissolved	Field Filtered	Lab to Filter	Additional Analysis	TOTAL # OF CONT.	NOTE #
Bottom 5.5-6'	3/25/20 11:30	S	X	X		X		X													5	
Bottom 6-6.5'	↓ 11:45	S	X																		5	1
PRESERVATIVE (Cl–HCl, N–HNO_3, S–H_2SO_4, Na–NaOH, C=Cool, O–Other)						C		C														
CONTAINER TYPE (P–Plastic, G–Glass, V–Vial, O–Other)						G		G													10	

Soil VOCs Only (M=MeOH, B=Sodium Bisulfate, W=Water, F=Empty Vial, E=Encore)

RELINQUISHED BY: DATE/TIME: 3/26/20 0945 RECEIVED BY:
RELINQUISHED BY: DATE/TIME: 3/26/20 1515 RECEIVED BY:
RELINQUISHED BY: DATE/TIME: RECEIVED BY:

NOTES: 1, Please Hold until further notice.

Client / Reporting Information

Company Name: Zurich, Carr and Associates, Inc
Address: 40 Cold Spring Rd, Rocky Hill, CT- 06067
City / State / Zip
Report To: Tony Man tonya@zurich.com; Dan Pinho danjpinho@zurich.com
E-mail
Phone #: 860-436-4901 Fax #: 860-436-4953

Project Information

Project: Stone Academy 745 Burnside Ave. PO #: —
Location: E. Hartford, CT Project #: 2016
CET Quote #: — Collector(s): DP
QA/QC ☐ Std ☐ Site Specific (MS/MSD) * ☒ RCP Pkg * ☒ DQAW *
Data Report ☒ PDF ☒ EDD - Specify Format Zurich Other
RSR Reporting Limits (check one) ☒ GA ☐ GB ☐ SWP ☒ Other RDEC
Laboratory Certification Needed (check one) ☒ CT ☐ NY ☐ RI ☐ MA
Temp Upon Receipt 4 °C Evidence of Cooling: ☒ N

PAGE 1 OF 1

* additional charge may apply. ** TAT begins when the samples are received at the Lab and all issues are resolved. TAT for samples received after 3 p.m. will be next business day. All samples picked up by courier service will be considered next business day receipt for TAT purposes.

REV. 10/16

Photos Obtained from the East Hartford Fire Marshal Office
Tank Abandonment
March 25, 2020









APPENDIX F
Aerial Photographs

Stone Academy

745 Burnside Avenue

East Hartford, CT 06108

Inquiry Number: 8145281.8

October 21, 2025

The EDR Aerial Photo Decade Package

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Aerial Photo Decade Package

10/21/25

Site Name:

Stone Academy
745 Burnside Avenue
East Hartford, CT 06108
EDR Inquiry # 8145281.8

Client Name:

HRP Associates, Inc.
197 Scott Swamp Road
Farmington, CT 06032-0000
Contact: Joy Waters

Environmental Data Resources, Inc. (EDR) Aerial Photo Decade Package is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's professional researchers provide digitally reproduced historical aerial photographs, and when available, provide one photo per decade.

Search Results:

Year	Scale	Details	Source
2023	1"=500'	Flight Year: 2023	USDA/NAIP
2018	1"=500'	Flight Year: 2018	USDA/NAIP
2014	1"=500'	Flight Year: 2014	USDA/NAIP
2010	1"=500'	Flight Year: 2010	USDA/NAIP
2006	1"=500'	Flight Year: 2006	USDA/NAIP
1995	1"=500'	Flight Date: April 20, 1995	Magic
1990	1"=500'	Acquisition Date: April 23, 1990	USGS/DOQQ
1985	1"=500'	Flight Date: April 17, 1985	USDA
1972	1"=500'	Flight Date: April 26, 1972	USGS
1970	1"=500'	Flight Date: April 06, 1970	CTMAGIC
1968	1"=500'	Flight Date: April 18, 1968	USGS
1962	1"=500'	Flight Date: March 22, 1962	USGS
1957	1"=500'	Flight Date: June 09, 1957	CTMAGIC
1952	1"=500'	Flight Date: May 05, 1952	CTMAGIC
1943	1"=500'	Flight Date: October 13, 1943	USGS
1934	1"=500'	Flight Date: May 08, 1934	FAIR

When delivered electronically by EDR, the aerial photo images included with this report are for ONE TIME USE ONLY. Further reproduction of these aerial photo images is prohibited without permission from EDR. For more information contact your EDR Account Executive.


Disclaimer - Copyright and Trademark Notice


This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT.

Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2025 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.


INQUIRY #: 8145281.8
YEAR: 2023
= 500'
N
EDR


INQUIRY #: 8145281.8
YEAR: 2018
= 500'
N
EDR


INQUIRY #: 8145281.8
YEAR: 2014
= 500'
N
EDR


INQUIRY #: 8145281.8
YEAR: 2010
= 500'
N
EDR


INQUIRY #: 8145281.8
YEAR: 2006
= 500'
N
EDR


INQUIRY #: 8145281.8
YEAR: 1995
= 500'
N
EDR
Subject boundary not shown because it exceeds image extent or image is not .georeferenced


INQUIRY #: 8145281.8
YEAR: 1990
= 500'
N
EDR


INQUIRY #: 8145281.8
YEAR: 1985
= 500'
N
EDR


INQUIRY #: 8145281.8
YEAR: 1972
= 500'
N
EDR


INQUIRY #: 8145281.8
YEAR: 1970
= 500'
N
EDR


INQUIRY #: 8145281.8
YEAR: 1968
= 500'
N
EDR


INQUIRY #: 8145281.8
YEAR: 1962
= 500'
N
EDR


INQUIRY #: 8145281.8
YEAR: 1957
= 500'
N
EDR



INQUIRY #: 8145281.8

YEAR: 1952

= 500'

N

EDR


INQUIRY #: 8145281.8
YEAR: 1943
= 500'
N
EDR



INQUIRY #: 8145281.8

YEAR: 1934

= 500'

N

EDR

APPENDIX G
Topographic Maps

Stone Academy
745 Burnside Avenue
East Hartford, CT 06108

Inquiry Number: 8145281.4
October 20, 2025

EDR Historical Topo Map Report

with QuadMatch™

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Historical Topo Map Report

10/20/25

Site Name:

Stone Academy
745 Burnside Avenue
East Hartford, CT 06108
EDR Inquiry # 8145281.4

Client Name:

HRP Associates, Inc.
197 Scott Swamp Road
Farmington, CT 06032-0000
Contact: Joy Waters

EDR Topographic Map Library has been searched by EDR and maps covering the target property location as provided by HRP Associates, Inc. were identified for the years listed below. EDR's Historical Topo Map Report is designed to assist professionals in evaluating potential liability on a target property resulting from past activities. EDRs Historical Topo Map Report includes a search of a collection of public and private color historical topographic maps, dating back to the late 1800s.

Search Results:

P.O.# COL4100.P2

Project: Stone Academy

Coordinates:

Latitude:	41.7792 41° 46' 45" North
Longitude:	-72.606685 -72° 36' 24" West
UTM Zone:	Zone 18 North
UTM X Meters:	698898.98
UTM Y Meters:	4628030.12
Elevation:	75.44' above sea level

Maps Provided:

2021	1952
2018	1944, 1945
2015	1928
2012	1906
1992	1892
1984	
1968	
1963, 1964	

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT. Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.


Copyright 2025 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

2021 Source Sheets



Manchester
2021
7.5-minute, 24000




Hartford North
2021
7.5-minute, 24000

2018 Source Sheets



Manchester
2018
7.5-minute, 24000




Hartford North
2018
7.5-minute, 24000

2015 Source Sheets



Manchester
2015
7.5-minute, 24000




Hartford North
2015
7.5-minute, 24000

2012 Source Sheets



Manchester
2012
7.5-minute, 24000



Hartford North
2012
7.5-minute, 24000

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

1992 Source Sheets



Manchester
1992
7.5-minute, 24000
Aerial Photo Revised 1991



Hartford North
1992
7.5-minute, 24000
Aerial Photo Revised 1991

1984 Source Sheets



Hartford North
1984
7.5-minute, 24000
Aerial Photo Revised 1982



Manchester
1984
7.5-minute, 24000
Aerial Photo Revised 1982

1968 Source Sheets




Manchester
1968
7.5-minute, 24000
Aerial Photo Revised 1968

1963, 1964 Source Sheets



Manchester
1963
7.5-minute, 24000



Hartford North
1964
7.5-minute, 24000
Aerial Photo Revised 1941

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

1952 Source Sheets



Hartford North
1952
7.5-minute, 24000
Aerial Photo Revised 1952



Manchester
1952
7.5-minute, 24000

1944, 1945 Source Sheets



Manchester
1944
7.5-minute, 31680



Hartford North
1945
7.5-minute, 31680

1928 Source Sheets




Windsor
1928
7.5-minute, 24000
Aerial Photo Revised 1928



Manchester
1928
7.5-minute, 24000
Aerial Photo Revised 1928

1906 Source Sheets




Farmington
1906
30-minute, 125000

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.


1892 Source Sheets



Hartford
1892
15-minute, 62500

Historical Topo Map

2021



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE


TP, Manchester, 2021, 7.5-minute
NW, Hartford North, 2021, 7.5-minute

SITE NAME: Stone Academy
ADDRESS: 745 Burnside Avenue
East Hartford, CT 06108
CLIENT: HRP Associates, Inc.

N

Historical Topo Map

2018



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE


TP, Manchester, 2018, 7.5-minute
NW, Hartford North, 2018, 7.5-minute

SITE NAME: Stone Academy
ADDRESS: 745 Burnside Avenue
East Hartford, CT 06108
CLIENT: HRP Associates, Inc.

N

Historical Topo Map

2015



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE


TP, Manchester, 2015, 7.5-minute
NW, Hartford North, 2015, 7.5-minute

SITE NAME: Stone Academy
ADDRESS: 745 Burnside Avenue
East Hartford, CT 06108
CLIENT: HRP Associates, Inc.

N

Historical Topo Map

2012



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Manchester, 2012, 7.5-minute
NW, Hartford North, 2012, 7.5-minute

SITE NAME: Stone Academy
ADDRESS: 745 Burnside Avenue
East Hartford, CT 06108
CLIENT: HRP Associates, Inc.

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Manchester, 1992, 7.5-minute
NW, Hartford North, 1992, 7.5-minute

SITE NAME: Stone Academy
ADDRESS: 745 Burnside Avenue
East Hartford, CT 06108
CLIENT: HRP Associates, Inc.

N




This report includes information from the following map sheet(s).

NW N NE
W E
SW S SE

TP, Manchester, 1984, 7.5-minute
NW, Hartford North, 1984, 7.5-minute

SITE NAME: Stone Academy
ADDRESS: 745 Burnside Avenue
East Hartford, CT 06108
CLIENT: HRP Associates, Inc.

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Manchester, 1968, 7.5-minute

SITE NAME: Stone Academy
ADDRESS: 745 Burnside Avenue
East Hartford, CT 06108
CLIENT: HRP Associates, Inc.

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Manchester, 1963, 7.5-minute
NW, Hartford North, 1964, 7.5-minute

SITE NAME: Stone Academy
ADDRESS: 745 Burnside Avenue
East Hartford, CT 06108
CLIENT: HRP Associates, Inc.

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Manchester, 1952, 7.5-minute
NW, Hartford North, 1952, 7.5-minute

SITE NAME: Stone Academy
ADDRESS: 745 Burnside Avenue
East Hartford, CT 06108
CLIENT: HRP Associates, Inc.

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE


TP, Manchester, 1944, 7.5-minute
NW, Hartford North, 1945, 7.5-minute

SITE NAME: Stone Academy
ADDRESS: 745 Burnside Avenue
East Hartford, CT 06108
CLIENT: HRP Associates, Inc.

N

Historical Topo Map

1928



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Manchester, 1928, 7.5-minute
NW, Windsor, 1928, 7.5-minute

SITE NAME: Stone Academy
ADDRESS: 745 Burnside Avenue
East Hartford, CT 06108
CLIENT: HRP Associates, Inc.

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Farmington, 1906, 30-minute

SITE NAME: Stone Academy
ADDRESS: 745 Burnside Avenue
East Hartford, CT 06108
CLIENT: HRP Associates, Inc.

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Hartford, 1892, 15-minute

SITE NAME: Stone Academy
ADDRESS: 745 Burnside Avenue
East Hartford, CT 06108
CLIENT: HRP Associates, Inc.

N

APPENDIX H
Sanborn Fire Insurance Maps

Stone Academy
745 Burnside Avenue
East Hartford, CT 06108

Inquiry Number: 8145281.3
October 20, 2025

Certified Sanborn® Map Report

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

Certified Sanborn® Map Report

10/20/25

Site Name:

Stone Academy
745 Burnside Avenue
East Hartford, CT 06108
EDR Inquiry # 8145281.3

Client Name:

HRP Associates, Inc.
197 Scott Swamp Road
Farmington, CT 06032-0000
Contact: Joy Waters

The Sanborn Library has been searched by EDR and maps covering the target property location as provided by HRP Associates, Inc. were identified for the years listed below. The Sanborn Library is the largest, most complete collection of fire insurance maps. The collection includes maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow, and others. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by the Sanborn Library LLC, the copyright holder for the collection. Results can be authenticated by visiting www.edrnet.com/sanborn.

The Sanborn Library is continually enhanced with newly identified map archives. This report accesses all maps in the collection as of the day this report was generated.

Certified Sanborn Results:

Certification # 1C28-4C21-9BB7

PO # COL4100.P2

Project Stone Academy

Maps Provided:

1968
1949
1927
1920

Sanborn® Library search results

Certification #: 1C28-4C21-9BB7

The Sanborn Library includes more than 1.2 million fire insurance maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow and others which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ☑ Library of Congress
- ☑ University Publications of America
- ☑ EDR Private Collection

The Sanborn Library LLC Since 1866™

Limited Permission To Make Copies

HRP Associates, Inc. (the client) is permitted to make up to FIVE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT. Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2025 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1968 Source Sheets



Volume 1, Sheet 24
1968



Volume 1, Sheet 26
1968




Volume 1, Sheet 25
1968



Volume 1, Sheet 35
1968

1949 Source Sheets



Volume 1, Sheet 26
1949



Volume 1, Sheet 25
1949



Volume 1, Sheet 24
1949

1927 Source Sheets



Volume 1, Sheet 24
1927




Volume 1, Sheet 26
1927



Volume 1, Sheet 25
1927


1920 Source Sheets



Volume 1, Sheet 21
1920

Certified Sanborn® Map

1968




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #1C28-4C21-9BB7

Site Name:	Stone Academy
Address:	745 Burnside Avenue
City, ST, ZIP:	East Hartford, CT 06108
Client:	HRP Associates, Inc.
EDR Inquiry:	8145281.3
Order Date:	10/20/2025
Certification #:	1C28-4C21-9BB7
Copyright	1968

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 35
Volume 1, Sheet 25
Volume 1, Sheet 26
Volume 1, Sheet 24

0 Feet 150 300 600

N

Certified Sanborn® Map

1949





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #1C28-4C21-9BB7

Site Name:	Stone Academy
Address:	745 Burnside Avenue
City, ST, ZIP:	East Hartford, CT 06108
Client:	HRP Associates, Inc.
EDR Inquiry:	8145281.3
Order Date:	10/20/2025
Certification #	1C28-4C21-9BB7
Copyright	1949

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 24
Volume 1, Sheet 25
Volume 1, Sheet 26

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #1C28-4C21-9BB7

Site Name:	Stone Academy
Address:	745 Burnside Avenue
City, ST, ZIP:	East Hartford, CT 06108
Client:	HRP Associates, Inc.
EDR Inquiry:	8145281.3
Order Date:	10/20/2025
Certification #	1C28-4C21-9BB7
Copyright	1927

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 25
Volume 1, Sheet 26
Volume 1, Sheet 24

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #1C28-4C21-9BB7

Site Name:	Stone Academy
Address:	745 Burnside Avenue
City, ST, ZIP:	East Hartford, CT 06108
Client:	HRP Associates, Inc.
EDR Inquiry:	8145281.3
Order Date:	10/20/2025
Certification #:	1C28-4C21-9BB7
Copyright	1920

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 1, Sheet 21

0 Feet 150 300 600

N

APPENDIX I
City Directories

Stone Academy
745 Burnside Avenue
East Hartford, CT 06108

Inquiry Number: 8145281.5
October 22, 2025

The EDR-City Directory Image Report

EDR® Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION

Executive Summary

Findings

City Directory Images

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. **NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT.** Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2023 by Environmental Data Resources, LLC. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, LLC, or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

DESCRIPTION

Environmental Data Resources, Inc.'s (EDR) City Directory Report is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's City Directory Report includes a search of available business directory data at approximately five year intervals.

RECORD SOURCES

The EDR City Directory Report accesses a variety of business directory sources, including Haines, InfoUSA, Polk, Cole, Bresser, and Stewart. Listings marked as EDR Digital Archive access Cole and InfoUSA records. The various directory sources enhance and complement each other to provide a more thorough and accurate report.

EDR is licensed to reproduce certain City Directory works by the copyright holders of those works. The purchaser of this EDR City Directory Report may include it in report(s) delivered to a customer.

RESEARCH SUMMARY

The following research sources were consulted in the preparation of this report. A check mark indicates where information was identified in the source and provided in this report.

Year	*Target Street*	*Cross Street*	*Source*
2022	☑	☑	EDR Digital Archive
2017	☑	☑	Cole Information
2014	☑	☑	Cole Information
2010	☑	☑	Cole Information
2005	☑	☑	Cole Information
2000	☑	☑	Cole Information
1995	☑	☑	Cole Information
1992	☑	☑	Cole Information
1977	☑	☑	Price & Lee's City Directory
1971	☑	☑	Price & Lee's City Directory
1965	☑	☑	Price & Lee's City Directory
1960	☑	☑	Price & Lee's City Directory
1951	☑	☐	Price & Lee's City Directory
1946	☑	☐	Price & Lee's City Directory
1941	☑	☐	Price & Lee's City Directory
1936	☑	☐	Price & Lee's City Directory
1925	☑	☐	Price & Lee's City Directory

FINDINGS

TARGET PROPERTY STREET

745 Burnside Avenue
East Hartford, CT 06108

Year	*CD Image*	*Source*
BURNSIDE AVE		
2022	pg A2	EDR Digital Archive
2017	pg A6	Cole Information
2014	pg A9	Cole Information
2010	pg A12	Cole Information
2005	pg A15	Cole Information
2000	pg A19	Cole Information
1995	pg A22	Cole Information
1992	pg A25	Cole Information
1977	pg A28	Price & Lee's City Directory
1977	pg A29	Price & Lee's City Directory
1971	pg A31	Price & Lee's City Directory
1965	pg A33	Price & Lee's City Directory
1960	pg A35	Price & Lee's City Directory
1951	pg A37	Price & Lee's City Directory
1946	pg A38	Price & Lee's City Directory
1941	pg A39	Price & Lee's City Directory
1936	pg A40	Price & Lee's City Directory
1925	pg A41	Price & Lee's City Directory

FINDINGS

CROSS STREETS

Year	*CD Image*	*Source*	
SCOTLAND RD			
2022	pg. A5	EDR Digital Archive	
2017	pg. A8	Cole Information	
2014	pg. A11	Cole Information	
2010	pg. A14	Cole Information	
2005	pg. A18	Cole Information	
2000	pg. A21	Cole Information	
1995	pg. A24	Cole Information	
1992	pg. A27	Cole Information	
1977	pg. A30	Price & Lee's City Directory	
1971	pg. A32	Price & Lee's City Directory	
1965	pg. A34	Price & Lee's City Directory	
1960	pg. A36	Price & Lee's City Directory	
1951	-	Price & Lee's City Directory	Street not listed in Source
1946	-	Price & Lee's City Directory	Street not listed in Source
1941	-	Price & Lee's City Directory	Street not listed in Source
1936	-	Price & Lee's City Directory	Street not listed in Source
1925	-	Price & Lee's City Directory	Street not listed in Source

City Directory Images

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

BURNSIDE AVE 2022

669	UNITED TAE KWON DO LLC
	WILLIAM VIVEIROS
700	10KLIFE LLC
	ASHLEY WILLIAMS
	AW PRODUCTIONS
	BROTHERS HOME IMPROVEMENT LLC
	CARIBBEAN CORNER
	DION MYRIE
	DUTCH POT JAMAICAN RESTAURANT
	EAST HARTFORD CHURCH OF CHRIST
	EMPOWERMENT CATHEDRAL INTERNATIONAL MINISTRIES
	MADD DOGG LLC
	MAIN WAH KITCHEN
	ONE TOUCH SCRUBS
	QIAOMEI CHUO
	RUKHAIYA KASLIWALA
	SEARS SECURITY SYSTEMS
	SEVEN PUFF
	SHANTEL DECASTA
	TAX PREPARATION SVS INC
	ZOOM ZOOM TRADING
711	CITOS BARBERSHOP
	WILBERT LOVOS
715	AFRICAN FABRICS LLC
	EXPRESS CONVENIENCE & DELI
	VIDA KWOFIE
717	VARIEDADES LATINOS LLC
719	BELEN LOPEZ
721	RACHEL FLOOD
725	A1 DISTRIBUTION LLC
726	KHAILANI DIAZ
	KHALIMA ESPEJO-DIAZ
	SAI DIAZ
	SATHIA DIAZ
	SHATERANY DIAZ
727	ALEXANDER FOLSON
	ASIA MEADOWS
	PATRICIA MARSH
	RUTH CASTILLO
729	BARBARA ORTIZ
	DARLENE CARDONA
	FREDERICK RYAN
	GEORGINA WILLIAMSON
	MILAGRO ZUK
730	ANA DIAZ
	PEDRO DIAZ
731	ELANA GREENE
	LATASHA KNIGHTON
	MARIA GONZALEZ
	SONIA GONZALEZ

BURNSIDE AVE 2022 (Cont'd)

733	CHAN BOUNMANY
	JENNY ARRINGTON
	KARINA HERNANDEZ
	KYESHA VANOVER
	PRASEUTH LUANG
	RICHARD CASOLLA
	SAMUEL YEBOAH
735	JACK HOLDER
736	MELINDA MONTES-LUCRE
738	DONNA THOMAS
	FRED PEDEMONTI
	SAFE HOME SECURITY INC
744	DAVE ALEXANDER
745	BREAKTHROUGH ENTERTAINMENT MEDIA LLC
	DONNA LARSON
	ERIKA PARRIS
	GOODWIN COLLEGE
	KAREN KRUGER
	STONE ACADEMY
	STONE ACADEMY-EH
750	SANDRA ORTIZ
	SERGIO PARRA
	STEPHANIE HUNT
754	EDUARDO GONZALEZ
	JAMES GIULIETTI
	LAURIE TREMBLAY
	MARIA ZUNIGA
	NOEMI RIVERA
	STERGOS MIKKIOU
756	ALBERT SANCHEZ
	BARBARA KARZAR
	DANISHA RODRIGUEZ
	DAVID TRUESDALE
	DEBORAH JOHNSON
	KEVIN FOGG
	MATTHEW BUCKLER
	RONALD BARTON
	WARREN MARSH
	ZBIGNIEW MAJDA
762	AMAREA GOMEZ
	AMY DUCHESNE
	STEVEN JORDAN
763	DEBORAH POERIO
	INTEGRATED HEALTH SERVICES INC
777	EAST HARTFORD HIGH SCHOOL
	EAST HARTFORD MIDDLE SCHOOL
	EAST HARTFORD PUBLIC SCHOOLS
	EAST HARTFORD SCHOOL DISTRICT
	JOAN OLSEN
	JORGE LIMERES

BURNSIDE AVE 2022 (Cont'd)

777	KATHRYN PENTORE
	LANGFORD ELEMENTARY SCHOOL
	SHANNON CARLSON
	THERESE MARCELYNAS
784	JOSHUA GARCIA
	NORMA GARCIA
	STUART GARCIA
786	ERICA ORTIZ
788	ERICA PEREIRA
	JOSE CALDERON CASTRO
	MINISTERIO BAJO EL PODER DE DIOS Y ARREBATANDOLE LAS ALMAS AL
	ROBERTO RAMON
793	KATISHA MATOS
800	ARTHUR DAVIES
	ELOUISE COPELAND
802	LATISHA COYLE
803	GUADALUPE MARTINEZ
	MIGUEL MARTINEZ
	NELSON MARTINEZ
809	VALERIE OMEALLY
	WALTER OMEALLY
	WILLIAM O'MEALLY
810	MIRNA CARRERO
815	ALEX LENGSAVATH
	ANOUPHONE LENGSAVATH
	ARNOLD LENGSAVATH
	CHANSOUK LENGSAVATH
	KATIE LENGSAVATH
	LORI LENGSAVATH
	NOE LENGSAVATH
816	JUAN DERAS
819	MARILYN AGOSTO
820	MARY BORA
822	GANDHY ARIAS
	JOAN KIDD
827	D DOIS
	DELLROY REID
	DOIS REID
832	AMAGALIS HOLLOWAY
	ASHLEY HOLLOWAY
	EBONY HOLLOWAY

Target Street	Cross Street	Source
-	✓	EDR Digital Archive

SCOTLAND RD 2022

50	ALICE LEMBRICK
	ALICIA JOHNSON
	ARNOLD CUYLER
	ATHENA SMITH
	BARBARA BENSON
	BONNIE SMITH
	CARLISHA BARFIELD
	CONSTANCE LAMOUREUX
	DAN RHODES
	DEBBIE LEMBRICK
	DEBORAH AUSTIN
	DEIDRA SMITH
	DWAYNE AUSTIN
	ELIZABETH TAYLOR
	JEAN SPALLA
	JESSICA LEONE
	JULIO COLON
	LAURA OLINATZ
	LENA MCCRAY
	LESIA RETCHIE
	LUIS ROSS
	MANUEL SILVA
	MARIA COLON
	MARITSA MORALES
	MAXINE MILLER
	MICHAEL COULOUTE
	REGINA MCCRAY
	ROBERTA VANHORNE
	SUSIE RHODES
	T MARCELLES
	THOMAS SARTORI
	TIMOTHY MAZZUCCHI
	TYSHAWN WELBORN
	WENDY WHITT
51	LUIS CASTILLO
57	CARMEN RESENDIZ
	CORNELIO RESENDIZ
153	RICARDO ARAGON
161	KENE BANJAMIN

Target Street	Cross Street	Source
✓	-	Cole Information

BURNSIDE AVE 2017

669	JOANNA FASHIONS LLC
	REISS, KENNETH A
700	AW PRODUCTIONS
	BURNSIDE CONVIENCE
	BURNSIDE TRADING
	BURNSIDE TRADING CO
	DUTCH POT JAMAICAN RESTAURANT
	INDEPENDENT FOODS LLC
	MAIN WAH KITCHEN
	MECCA PROPERTIES
	MOTHERS AGAINST DRUNK DRIVING
	RAHN OI & ASSPCOATES
	TAX PREPARATION SVS INC
711	SMITH, MISTY
713	NEGRON, KARRY L
715	AFRICAN FABRICS
	EXPRESS CONVENIENCE & DELI
717	METROPCS
	TAX PREPARATION SERVICES
	VARIEDADES LATINOS LLC
719	LOPEZ, BELEN
721	CARDENAS, CASIMIRO
725	RESTO, NAOMI
726	ESPEJO, ROSIRIS
727	TUTTLE, CHRISTIN
730	DIAZ, PEDRO
731	KNIGHTON, LATASHA D
733	ARRINGTON, JINNIE D
	BOWENS, RAENETTE E
	YEBOAH, RITA
735	ESPINAL, JOSE D
738	LUCRE, SAMANTHA
	MULLINGS, RASHANAH L
744	ALEXANDER, DAVE
745	CONNECTICUT TRAINING CENTER INC
	STONE ACADEMY
748	PARRA, SERGIO
750	ORTIZ, SANDRA
754	CROSS, SHANIQUA
	MENDEZ, KIMBERLY A
	TREMBLAY, LAURIE A
756	BARTON, RONALD
	JOHNSON, DEBORAH D
	JOHNSON, NICOLE
	THOMPSON, SHIRLEY
763	INTEGRATED HEALTH SERVICES INC
784	GARCIA, JOSHUA
786	ALICEA, ALFREDO
793	FIGUEROA, RAFAEL M
802	COYLE, LATISHA

Target Street	Cross Street	Source
✓	-	Cole Information

BURNSIDE AVE 2017 (Cont'd)

803	BEZZINI, RONALD J
809	ARCHAGA, ROBERTO
810	MENDEZ, WILSON
815	LENGSAVATH, ALEX J
816	MARTINEZ-SANCHEZ, OLIDANIO
819	WOOD, JOSHUA V
820	BORA, MARY C
822	ARIAS, GANDHY S
827	REID, DOIS D
832	HOLLOWAY, AMAGALIS

Target Street	Cross Street	Source
-	✓	Cole Information

SCOTLAND RD 2017

50	AUSTIN, DWAYNE
	BENSON, HAROLD D
	COULOUTE, MICHAEL A
	CUYLER, ARNOLD T
	HENNEQUIN, ROBERT L
	JAMES, MARCELLES T
	JOHNSON, PATRICK O
	LAMOUREUX, LOUIS F
	LAWRENCE, AISHA
	LEMBRICK, GENE C
	LEWIS, KAREN
	MAZZUCCHI, TIMOTHY H
	MCCRAY, REGINA R
	MORALES, MARITSA
	ODONNELL, MARK
	RACKLIFFE, EVERETT R
	RHODES, SUZIE M
	SARTORI, THOMAS C
	SMITH, BONNIE K
	SPALLA, JEAN M
	TAYLOR, MICHAEL H
	VANHORNE, ROBERTA E
	WHITAKER, JOHN H
	WHITT, WENDY E
	WOMACK, ENITH M
51	LOPEZ, ROSA E
57	RESENDIZ, CORNELIO

Target Street	Cross Street	Source
✓	-	Cole Information

BURNSIDE AVE 2014

669	JOANNA FASHIONS LLC
	OCCUPANT UNKNOWN,
700	99 CENTS PLUS SUPER DISCOUNTS
	BURNSIDE TRADING CO
	DUTCH POT JAMAICAN RESTAURANT
	HAIR LAND 3
	INDEPENDENT FOODSLLC
	MADD DOGG LLC
	MAIN WAH KITCHEN
	MECCA PROPERTIES
	WOLK, WALTER R
711	FLORES, PEDRO C
	TORRES, KATHY L
713	FERRANTE, NANCY A
	NEGRON, KARRY L
715	EXPRESS CONVENIENCE & DELI
	YAN, XIA
717	AFRICAN FABRICS
	VARIEDADES LATINOS LLC
719	OWENS, SHEVONE
725	MONROE, AUBET
726	BRAND, FABIAN
	DIAZ, SHATERANY
	ESPEJO, ROSIRIS
	MARTINEZ, REYNA
	VARGAS, JOSE S
727	ANTWI, ERIC
	ELEZYA, KEIARA T
	MARSH, ANDRE A
	ROBLES, VICTOR
	TUTTLE, CHRISTIN
729	MARTINEZ, ANIBAL
	RODRIGUEZ, MILAGROS
	RODRIQUEZ, SAMANTHA
730	DIAZ, PEDRO
731	BILL, SAMUEL P
733	BOWENS, RAENETTE
	FOSTER, ROLANDA T
	YEBOAH, SAMUEL
735	ESPINAL, JOSE D
736	VELASQUEZ, ROSELEEN
738	LUCRE, SAMANTHA
	MULLINGS, RASHANAH L
	VELAZQUEZ, JOSE
744	MARTINEZ, VICTOR
745	CONNECTICUT TRAINING CENTER INC
	GOODWIN COLLEGE
	STONE ACADEMY
746	MARTINEZ, VELMA I
748	HEADRICK, LAURIE

Target Street	Cross Street	Source
✓	-	Cole Information

BURNSIDE AVE 2014 (Cont'd)

748	HUNT, STEPHANY J
	PARRA, SERGIO
754	CROSS, SHANIQUA
	EASON, BRANDON
	GIULIETTI, JAMES D
	WARNER, ALLISON
756	BARTON, RONALD
	BUCKLER, MATTHEW J
	GONZALES, EASON
	ORELLANA, HECTOR
	THOMPSON, SHIRLEY
763	INTEGRATED HEALTH SERVICES INC
784	GARCIA, NORMA
786	ALICEA, MINERVA
	ARROYO, LUIS
	PEREZ, MARY A
788	COLON, DIAZ
793	FIGUEROA, RAFAEL M
800	DIXON, GUY
802	KENYON, JENNIFER L
803	BEZZINI, RONALD J
809	ARCHAGA, ROBERTO
810	ANDORE, KAREN
	MEYERS, MYRON A
	NELSON, MICHELLE
815	LENGSAVATH, CHANSOOK
816	DILONE, ANGELINA C
	GALLARDO, JESSICA
	SANTOS, FERNANDO
819	WOOD, JOSHUA V
820	OCCUPANT UNKNOWN,
822	THOMAS-BROWN, ROSEMARIE
827	REID, DOIS D

Target Street	Cross Street	Source
-	✓	Cole Information

SCOTLAND RD 2014

37	RICHARDS, GARY S
50	AUSTIN, DWAYNE
	BALL, BELINDA
	BENSON, HAROLD D
	BURNHAM, BRIAN P
	COULOUTE, MICHAEL A
	CUYLER, ARNOLD T
	HENNEQUIN, ROBERT L
	JAMES, MARCEL
	JOHNSON, ALICIA M
	LAMOUREUX, LOUIS F
	LEMBRICK, GENE C
	MARTEL, LEONARD A
	MCCRAY, REGINA Y
	MILLER, EUGENE
	MORALES, MARITSA
	ODONNELL, MARK
	RABB, MONIQUA L
	RACKLIFFE, EVERETT R
	RHODES, SUZIE M
	SARTORI, CHARLES
	SMITH, BONNIE K
	TAYLOR, MICHAEL H
	WHITAKER, JOHN H
	WOMACK, BRENDA L
	WYNTER, ANDRE
51	LOPEZ, ROSA E
57	RESENDIZ, CORNELIO

Target Street	Cross Street	Source
✓	-	Cole Information

BURNSIDE AVE 2010

669 AGE, E H
JOANNA
UNITED TAE KWON DO
673 MEANS, DAVID
694 BAUM, KEARNEY K
WHOLE DONUT
700 99 CENTS PLUS SUPER DISCOUNT
BURNSIDE CONVENIENCE STORE
DATA INSTITUTE BUSINESS SCHOOL
DON JUAN INC
KENNADY FRIED CHICKEN
MAINWAH KITCHEN IV
NEW ALLIANCE BANK
SENTEK SECURITY ENGINEERING
SUNSET CLEANERS & TAILORS
U PAWN LLC
WALTER R WOLK PC
WOLK, WALTER R
711 ACEVEDO, JOSE
ARNSON, LENA M
BURNSIDE HAIR DESIGNS
JEWELRY EXCHANGE
LOPEZ, BELEN
713 DIAZ, ROSA
GARCIA, JUDITH
VALENCIA, JASON J
715 AFRICAN FABRICS
VALENCIA, MARTA A
YAN, XIA
717 HARDWARE DEPOT
718 MEDINA, JENNIFER
719 MELENDEZ, MILTON
MELENEDZ, M
721 FLOOD, RACHEL
725 IRIZARRY, MARIA E
726 ESPEJO, ROSIRIS
727 MARSH, PATRICIA I
SPIVEY, CARRIE
729 FRENCH, CHEKESHA
LOPEZ, JULIA
MARTINEZ, ANIBAL
730 DIAZ, PEDRO
731 BILL, SAMUEL P
RODRIQUEZ, J
SHELTON, S
733 ALLEN, ERIC
PANNHAVONG, KEUTMY
SPIVEY, CARRIE
735 ESPINAL, JOSE
736 VELASQUEZ, ROSALYN

Target Street	Cross Street	Source
✓	-	Cole Information

BURNSIDE AVE 2010 (Cont'd)

738	LUCRE, MELINDA
	VELAZQUEZ, JOSE
744	MAYNARD, KAYE D
745	STONE ACADEMY
746	MARTINEZ, VICTOR M
748	HUNT, STEPHANY J
	PARRA, SERGIO
750	ORTIZ, SANDRA
754	BRUNDAGE, RAYMOND
	CYR, SHERYL
	WALLACE, JUDY C
756	BUCKLER, MATTHEW J
	CAPUTO, ANTHONY L
	CARTWRIGHT, DEBBIE
	CORNISH, MICHAEL A
	FOGG, KEVIN M
	GORING, TEREVA
	LATA, GARY
	MARSH, WARREN M
	WARNER, ALLISON
	WILKERSON, ELIZABETH C
763	INTEGRATED HEALTH SVC INC
777	EAST HARTFORD MIDDLE SCHOOL
784	GARCIA, JOVITA
786	ALICEA, ALFREDO
	ARROYO, LUIS
	IRIZARRY, EILEEN
788	ALICEA, CHARLENE
793	WEBER, JOSEPH J
800	COPELAND, ELOUISE
802	BROWN, SHAMEEKA
809	GAYLE, ALSTON
815	LENGSAVATH, CHANSOUK C
816	DILOAE, ALEXIS
	GALLARDO, JESSICA
	OBRIEN, SEAN
	RIVERA, PROVIDENCIA
	VARGAS, MORELIS
818	VARGAS, MANUEL
820	BORA, ROBERT E
822	THOMAS-BROWN, ROSEMARIE
827	COLEMAN, CHARLES L
832	HOLLOWAY, AMAGALIS

Target Street	Cross Street	Source
-	✓	Cole Information

SCOTLAND RD 2010

37	RICHARDS, GARY S
50	AUSTIN, DWAYNE
	BENSON, BARBARA A
	BROWN, ELIZABETH N
	CUYLER, ARNOLD T
	FORGETTA, MARY V
	HENNEQUIN, ROBERT L
	JAMES, MARCELLES T
	JOHNSON, ALICIA M
	LAMOUREUX, LOUIS F
	LEMBRICK, GENE C
	LITTLE, MONIQUA
	MAZZUCCHI, TIMOTHY H
	MCCRAY, REGINA Y
	MILLER, EUGENE
	MORALES, MARITSA
	NELSON, ANNA
	RACKLIFFE, EVERETT R
	SARTORI, THOMAS C
	SMITH, DEIDRA L
	TAYLOR, MICHAEL H
	VANHORNE, ROBERTA E
	WELBORN, TYSHAWN R
	WHITAKER, JOHN H
	WOMACK, BRET W
51	LOPEZ, RAMON
57	RESENDEZ, CARMEN

Target Street	Cross Street	Source
✓	-	Cole Information

BURNSIDE AVE 2005

669	AGE, E H
	JOANNA FASHIONS LLC
	UNITED TAE KWON DO
671	ROBERTS, MARTIN
673	MEANS, DAVID
694	BAUM, KEARNEY K
	GANESH CORP
700	99 CENTS PLUS SUPER DISCOUNT STORE
	BURNSIDE CHIROPRACTIC CENTER
	BURNSIDE CONVENIENCE STORE
	CONNECTICUT TRAINING CENTER INC
	IGLESIA FUENTE SALVACION MISIONERA O
	MAIN WAH KITCHEN IV
	MARINAN BRENDAN DR
	MARINAN, BRENDAN
	MECCA, LEONARD J
	SENTEK SECURITY ENGINEERING
	SUNSET CLEANERS & TAILORS
	U PAWN LLC
	US EXECUTIVE BOARD
	WOLK WALTER R DDS
	WOLK, WALTER R
	ZDANIS WILLIAM J JR
	ZDANIS, WILLIAM J
711	ACEVEDO, LUZ
	ARNOLDS BARBER SHOP
	HAIR NOOK
713	FERRANTE, BRUCE A
	VALENCIA, JASON J
715	ACHEAMPONG WILSON CFP EA
	ACHEAMPONG, WILSON K
	ADOMAKO, KENNETH
	AFRICAN FABRICS
	EX HALE JASLER LLC
717	BURNSIDE HARDWARE
718	MEDINA, JENNIFER
719	EVANS, HERBERT C
721	EVANS, MARY V
725	MONROE, AUBET
726	ESPEJO, ROSIRIS
727	GARCIA, CARMEN G
	MCCRAY, CAROLYN A
	RODRIGUEZ, ADIEL
	WARE, PAULA
729	HENRY, DONOVAN
	ODEN, JOHN W
	PALMER, A
	PHILIP, JUNE
730	DIAZ, PEDRO
731	COLON, ANGELO L

BURNSIDE AVE 2005 (Cont'd)

731 GONZALEZ, MARIA E
KISSI-YEBOAH, JOHN
ROBINSON, LASHAWN
SANTIAGO, TINA
VICENS, BEATRIZ
733 ALLEN, ERIC
FOSTER, ROLANDA T
SPIVEY, CARRIE
735 MACHADO, JOSE
736 QUINTIANA, HECTOR
738 LUCRE, MELINDA
744 MAYNARD, KAYE D
745 211 RIVERSIDE LLC
GOODWIN COLLEGE
RIVER CAMPUS INC
STEEL BUILDING SYSTEMS LLC
746 MARTINEZ, VICTOR M
748 TEODORCZYK, D
750 NUNEZ, ROY
754 DONOFRIO, NADEEN
FOLEY, KEVIN
JONES, AARON W
756 BUCKLER, MATTHEW J
CAPUTO, ANTHONY L
COONEY, S
FLAGG, PAMELA M
FOGG, RALPH B
GOLZIO, S
GREGOIRE, JUSTIN A
HETHERINGTON, MARINA
KARZAR, DICK
KARZAR, MARIBETH B
LATA, THEODORE R
MARCH, ROBERT
MARSH, WARREN M
OLSZEWSKI, LAURA L
STOUTNAR, ALLAN N
WESTAD, K
763 INTERFACE COUNSELING CENTER
MELLOW, RICHARD
SCHEINBERG, MARK
786 GALLNOT, LYNN M
KING, STEVEN J
PEREIRA, LUIS
788 RIZZA, SHARON A
793 WAKEFIELD, JACK C
800 KENYON, DIANE L
802 BASSETT, KRISTINA
809 ALPHA TO OMEGA ENTERPRISES LLC
DACOSTA, JOSE S

Target Street	Cross Street	Source
✓	-	Cole Information

BURNSIDE AVE 2005 (Cont'd)

810	KOLOSKI, JAMES
815	LENGSAVATH, CHANSOUK C
816	BURGOS, MADELINE
818	BURGOS, MIGDALIA
819	TAYLOR, BRIAN R
820	BORA, ROBERT
822	HARRISON, CHESTER
827	MITCHELL, CLIFFORD D
832	JEPSEN, DAVID G

Target Street	Cross Street	Source
-	✓	Cole Information

SCOTLAND RD 2005

37	RICHARDS WILLIAM T JR REV
	WHETSTONE, JOYCE M
50	ANDRUSIS, SUSAN
	AUSTIN, DWAYNE
	BENSON, BARBARA A
	COULOUTE, MICHAEL A
	CRUZ, SAL
	DEBRICK, TIA D
	FORGELTA, MARY
	FUNCHES, JACQUELINE G
	HAYES, MARCUS
	HENNEQUIN, ROBERT L
	JAMES, MARCELLES T
	LAMOUREUX, LOUIS F
	LANDERFIN, RITA M
	LAUZIER, EILEEN M
	LEMXRICK, GENE E
	MATTHEWS, MARGUERETTE F
	MCCRAY, REGINA Y
	MEAGHER, ALLISON
	MILLER, EUGENE
	ODONNELL, MARK
	PETER, PRISCA E
	RACKLIFFE, EVERETT R
	REGIS, JOHN C
	RHODES, SUZIE
	SARTORI, THOMAS C
	SMITH, BONNIE K
	VANHORNE, ROBERTA E
	WELBORN, TYSHAWN R
	WHITAKER, JOHN H
	WOMACK, BRET W
51	LOPEZ-VALAIQUEZ, ROSA E
57	RESENDIZ, CORNELIO

Target Street	Cross Street	Source
✓	-	Cole Information

BURNSIDE AVE 2000

669	UNITED TAE KWON DO
	US TAE KWON DO INSTRUCTORS UNION
671	BURNSIDE PACKAGE STORE
	NEW ENGLAND ACOUSTIC & PARTITION INCORPORATED
673	MEANS, DAVID
678	PIZZA TIME
694	PREFERRED LABOR LLC
	WHOLE DONUT THE STORES
700	BURNSIDE CHIROPRACTIC CENTER
	BURNSIDE CONVENIENCE STORE
	DJL SECURITY SYSTEMS
	EAST HARTFORD POLICE UNION
	IGLESIA FUENTE SALVACION MISIONERA OF EAST HARTFO
	MARINAN, BRENDAN
	MECCA PROPERTIES
	PRICE, LEONARD
	SENTEK SECURITY ENGINEERING
	SUNSET CLEANERS & TAILORS
	U PAWN
	UNIVERSAL PAWN CORPORATION
	WOLK WALTER R DDS
	ZDANIS WILLIAM J JR CPA
711	ARNOLDS BARBER SHOP
	HAIR NOOK THE
713	AUGUSTYNIAK, JOHN L
	BECHARD, V A
715	ACHEAMPONG WILSON CFP EA
	CLARION, PETER
	EAST HARTFORD EDUCATION ASSOCIATION
	TIERNAN, PHILIP F
717	BURNSIDE HARDWARE
	HARDWARE DEPOT
719	EVANS, JEANNE
721	EVANS, MARY V
725	MONROE, A
726	OCCUPANT UNKNOWN,
727	BAGLEY, LENA
	ORTEGA, CIRILO
	PARE, C
	ROBINSON, JAVON
729	DIAZ, M
	ODEN, JOHN
730	GOUPIL, LEONARD
731	BAILEY, CECIARE C
	HARRIS, LEKISHA A
	RODRIGUEZ, IRIS N
733	LOWRIE, JANET M
	MAZIARZ, S M
	MILLINGS, DONOVAN G
	ODEN, P

Target Street	Cross Street	Source
✓	-	Cole Information

BURNSIDE AVE 2000 (Cont'd)

735	ELLINGTON, VALDA
736	LONG, TIFFANY
738	LOUREIRO, H
744	MARTINEZ, VICTOR
745	BS SERVICES
	CONNECTICUT TRAINING CENTER
	DATA INSTITUTE BUSINESS SCHOOL
	DATA INSTITUTE CAREER LINE
	EAST HARTFORD CHILD CARE CENTER DATA INSTITUTE
	YWCA OF THE HARTFORD REGN INCORPORATED EAST HARTFORD CHILD
746	MARTINEZ, VELMA
748	MAYNARD, KAYE
750	NUNEZ, K
754	FLOYD, GARY
	LACHANCE, J
	MARTUCCI, ROBERT D
	REPASS, B
756	CAPUTO, ANTHONY L
	ELLIS, L
	GREBLA, TED
	GREGOIRE, JUSTIN
	KARZAR, DICK
	KARZAR, M B
	LACHANCE, PAUL C
	MARSH, WARREN M
	MARTIN, D L
	PENHA, JULIE B
	SHEA, WILLIAM P
	STOUTNAR, ALLAN
	WHITTLES, LAURA
763	EAST HARTFORD CHAMBER OF COMMERCE
	INTERFACE COUNSELING CENTER
	MELLOW, RICHARD
	SBS BUILDING SYSTEMS
777	EAST HARTFORD TOWN OF EDUCATION DEPARTMENT
	TOWN OF EAST HARTFORD EDUCATION DEPARTMENT
784	SANTOS, M M
786	LAGASSE, ARLENE J
793	WEBER, JOSEPH
803	BEZZINI, PETER M
809	FERZACCA, ELISA L
810	KOLOSKI, EDWARD M
815	OCCUPANT UNKNOWN,
816	MARTINS, FERNAND L
818	QUINTERO, F
819	COLLIER, J M
822	HARRISON, C
827	MITCHELL, WILLIAM

Target Street	Cross Street	Source
-	✓	Cole Information

SCOTLAND RD 2000

5	SMITH, BONNIE K
37	WHETSTONE, JOYCE M
50	ADAMS, LUBERTA
	AUSTIN, DEBORAH
	BANKS, DONNA M
	BENSON, B A
	BENSON, H
	FLOYD, ADDIE B
	HASMAT, AAMIR
	IONEVA, M
	KAMAROWSKI, B
	LAMOUREUX, LOUIS
	LANDERFIN, RITA
	LEMBRICK, ALICE R
	MCKIRDY, SEAN L
	MORSE, EARL S
	NELSON, AMIEL D
	ODONNELL, MARK
	RACKLIFFE, EVERETT
	REGIS, JOHN
	ROBINSON, GLENDA
	SANDBERGH, E B
	SMITH, BONNIE K
	SONGDAHL, C
	TOZIER, CHARLES W
	WATKINS, G
51	OLIVA, ROY A
57	OLIVA, NICHOLA T

Target Street	Cross Street	Source
✓	-	Cole Information

BURNSIDE AVE 1995

669	AAA BLACK BELT ACADEMY
	UNITED TAE KWON DO
671	BURNSIDE PACKAGE STORE
672	BURNSIDE GULF
678	DOMINOS PIZZA
	OCCUPANT UNKNOWNN
694	BURNSIDES PIZZA
	WHOLE DONUT
700	ALTRNTV COUNSLNG SV
	BRENNAN, JOHN D III
	BURNSIDE CHIROPRACTIC CTR
	BURNSIDE DRUG STORE
	LADY IN WAITING
	MORENTSENS B J
	PETER L BRENNAN
	SAVINGS BANK OF MANCHESTER
	SEARS ROEBUCK & CO
	SUNSET CLEANERS & TAILORS
	TECH COMM
	WALTER R WOLK DDS
	WILLIAM J ZDANIS JR
	WOLK, WALTER R
711	ARNOLDS BARBER SHOP
	HEIDIS HAIR DESIGN
	LANTIERI, ANGELO S
713	OCCUPANT UNKNOWNN
715	AMERICAN HM RL EST
	AMERICAN HOME REAL ESTATE
	HRTFRD EDUCATN ASSN
	NICHOLS INSTITUTE
	STEARNS, LYLE
717	HARDWARE DEPOT
	OCCUPANT UNKNOWNN
719	CRUZ, DAISY
721	OCCUPANT UNKNOWNN
725	OCCUPANT UNKNOWNN
726	MANKUS, JOHN JR
727	ERDELY, GLADYS
	FIELDS, ANDREA L
	ORTIZ, MARIA
	RITUCCI, NICK
729	LEVESQUE, K
730	GOUPIL, LEONARD
731	JACKSON, MARION
	JOHNSON, WANDA
733	PERKINS, AGNES T
	POVLOSKY, RONALD M
736	OCCUPANT UNKNOWNN
738	LOUREIRO, H
744	COTE, RALPH

Target Street	Cross Street	Source
✓	-	Cole Information

BURNSIDE AVE 1995 (Cont'd)

745	BS SERVICES
	CAREER LINE
	DATA INSTITUTE BUSINESS SCHOOL
	OCCUPANT UNKNOWNN
	YWCA CHILD CARE
746	OCCUPANT UNKNOWNN
747	LYONS, LISA
748	COUTURE, E
750	LEONE, ANNA
754	MARTUCCI, THOMAS A
	PECOR, W E
	REPASS, B
756	BRUNELLE, P
	CYR, ARLENE
	DAVIES, NORMAN E
	DUBAY, A
	GODDARD, JAMES
	KARZAR, DICK
	KARZAR, M B
	KICE, C A
	LACHANCE, VINCENT
	MARTIN, D L
	SHEA, WILLIAM P
763	CHAMBER OF COMMERCE
	INTERFACE COUNSELING CTR
	LITERACY VOLUNTEERS
	MELLOW, RICHARD
777	EAST HARTFORD MIDDLE SCHOOL
	EH SCH MEDIA SVCS
786	DESJARDNS, DIANE
788	OCCUPANT UNKNOWNN
793	OCCUPANT UNKNOWNN
800	OCCUPANT UNKNOWNN
803	OCCUPANT UNKNOWNN
809	FERZACCA, NICOLA D
810	KOLOSKI, EDWARD M
814	OCCUPANT UNKNOWNN
815	OCCUPANT UNKNOWNN
816	MARTINS, F L
818	STRANGE, STEVEN
819	HETHERMAN, JAMES R
820	OCCUPANT UNKNOWNN
827	OCCUPANT UNKNOWNN
832	SKEHAM, TIMOTHY

Target Street	Cross Street	Source
-	✓	Cole Information

SCOTLAND RD 1995

37	GOAD, MARK
	RICHARDS, WILLIAM T JR
	WILLIAM T RICHARDS
50	APPLIED INVESTIGATIVE GROUP
	BENSON, B A
	BENSON, H
	CRAMER, MARK R
	CRUZ, SAL
	DUMAS, DEAN
	EDWARDS, JEROME
	EGAZARIAN, M
	ENMAN, LLOYD
	KAMAROWSKI, B
	KELLY, EUGENE
	LAMOUREUX, LOUIS
	LANDERFIN, RITA
	LEONARDI, S
	MAZZUCCHI, ROBERT L
	MCCABE, MICHAEL
	RACKLIFFE, EVERETT JR
	ROBINSON, GLENDA M
	SANDBERGH, E B
	SOLOMONSON, A B
	STEBBINS, STACEY
	STEUERNAGEL, CHRIS
	TOZIER, CHARLES W
	WEISENBERG, ALAN
51	OLIVA, ROY A
57	OLIVA, N T JR

Target Street	Cross Street	Source
✓	-	Cole Information

BURNSIDE AVE 1992

669	A A A BLCK BLT ACAD
	KOREA GINSENG CO
	UNITED TAE KWON DO
671	ANDREWS, T
	BURNSIDE PKG STORE
672	BURNSIDE GULF
678	DOMINO'S PIZZA
680	GROCERY BARN THE
694	NEW U THE
	SAMS PIZZA HOUSE
	WHOLE DONUT THE
696	A & J MINIMART
700	ARTHUR DRUG
	BRENNAN & BRENNAN
	BRENNAN JOHN D 3RD
	BRENNAN PETER L ATY
	BURNSIDE CHIROPRACT
	BURNSIDE DRUG STORE
	BURNSIDE QUICK COPY
	MARINAN BRENDAN DR
	MORENTSEN'S B J
	MORTENSEN'S RESTRNT
	N A L C BRANCH 86
	NATIONAL APPRAISAL
	PYRAMID FINL SERV
	RANDOMEX INC
	SAVINGS BANK OF MAN
	SUNSET CLNRS&TAILRS
	TECH COMM
	WOLK WALTER R DDS
	ZDANIS WILLIAM J JR
711	ARNOLDS BARBER SHOP
	LANTIERI, ANGELO S
	SCISSOR, WIZZARD
713	GAGNON, ADRIEN G
715	AMER HOME REAL EST
	DIBACCO'S DRIVING
	EAST HART EDUCATION
	MAURER, JAMES
	NICHOLS INSTITUTE
717	BURNSIDE HARDWARE
721	NIEVES, ALICE
725	STUBBS, B J
727	RITUCCI, NICK
729	DECENSI, E
	RUSSO, R
	WRIGHT, ROSE
730	GOUPIL, LEONARD
731	BAKER, STEPEHN C
733	BOLSTER, T M

Target Street	Cross Street	Source
✓	-	Cole Information

BURNSIDE AVE 1992 (Cont'd)

733	HAUCK, CHRIS
	HEENE, MICHAEL
	REYNOLDS, B D
736	CANNISTRARO, F
744	LOOMIS, JUANITA M
745	BS SERVICES
	CAREER LINE
	DATA INST DAYCARE
	DATA INSTITUTE SCHL
746	MCCREARY, CARL W
750	LEONE, ANNA
754	DAVIES, D
	DEVLIN, S A
756	ABRAMOWICZ, DONNA
	BLAZINSKI, EDWARD JR
	CYR, A
	KARZAR, DICK
	KARZAR, M B
	LACHANCE, VINCENT
763	CONN SEXUAL ASSAULT
	INTERFACE COUNSELNG
777	TOWN MEDIA SVCES
786	GOODWIN, ALBERT
788	GOUSSE, I I
809	FERZACCA, NICOLA D
815	LENGSAVATH, C
816	MARTINS, F L
818	STRANGE, STEVEN
819	HETHERMAN, JAMES R
832	DAHLEM, STEPHEN P
7543	PECOR, W E
7544	CASTRO, D M
7563	SHEA, WILLIAM P
7566	BRODEUR, ANNETTE
	KICE, C A
7567	MARTIN, D L

Target Street	Cross Street	Source
-	✓	Cole Information


SCOTLAND RD 1992

37 GOAD, MARK
RICHARDS, WILLIAM T JR

50 APPLIED INVESTIGATI
BENSON, B A
LAMOUREUX, LOUIS
LANDERFIN, RITA
RACKLIFFE, EVERETT JR
SHAH, SAMIR

Target Street	Cross Street	Source
✓	-	Price & Lee's City Directory

BURNSIDE AVE 1977



647 R LENGYEL LOUIS J 289-3536
653 CHARLIES TIRE & ARCO SERVICE 289-2034
656 WICKHAM MEMORIAL LIBRARY 528-4664
657 659 JOLLY RESTAURANT 289-6229
RIZZIE VERNON J 289-7223
663 COLLI & WAGNER AGENCY INC REAL EST 289-0241
665 ELLIOTTE GUN SHOP 289-5741
667 BURNSIDE MUSIC LAND 528-1360

- 668 SCHOOL ST BEGINS

669 GENERAL BINDING 285-2151
A ALBERTS SANDWICH SHOP 289-9944
A UNITED TAE KWON DO INC 289-8008
671 BURNSIDE PACKAGE 528-0547
STAKEY GREGORY 528-7953
672 DAGONS SERVICE STATION 289-9906
673 PAULS MENS HAIR STYLING 289-1691
678 LEONE PHARMACY INC 528-4131
680 682 SAVAGE FOOD MARKET INC 289-6859

- 691 CHURCH ST BEGINS

694 SAMS PIZZA HOUSE 528-7811
A HAPPY HAIR BEAUTY SHOP 289-6183
B BESS EATON DONUTS REST 289-4766
696 CUMBERLAND FARMS INC 289-9771

- 696 1/2 HANMER ST BEGINS


700 KOCUM JOHN R BUILDING
BURNSIDE DRUG 289-3488
SAVINGS BANK OF MANCHESTER BURNSIDE OFFICE 289-8214
700 EAST OF THE BORDER GIFTS 289-0401
HIGHLANDER CENTER LAUNDRY
SUNSET CLEANERS 289-1302
JENSENS RESTAURANT 289-3514
700 1 VACANT
2-4 WOLK W R DENTIST 289-5322
700 3 POWERS ELAINE FIGURE SALON BEAUTY SHOP 289-8253
5 VACANT
700 6 VACANT
7 VACANT
700 8 VACANT
9-11 VACANT
10 VACANT
11A VACANT
700 12 VACANT
13 GENERAL DIGITAL CORPORATION DATA PROCESSING 289-7391
14 DANCE SHACK THE 528-8140
15A VACANT
16 VACANT
700 17 DEPT OF ADULT PROBATION 289-6049
18 VACANT
19 VACANT
700 20 VACANT
711 ARNOLDS BARBER SHOP 528-4218
LANTIERI ANGELO S 528-4656
OAK LEE REALTY CO 289-3804
713 MELGAREJO SERGIA 289-6278
2 SOSA ARMANDO
715 1-2 CURRIER LEO
3 ELKO GEORGE P
4 EAST HARTFORD EDUCATION ASSN 289-9234
5 HOCKANUM VALLEY UNISERV-CEA 528-7548
6 VACANT
7 BUILDERS REALTY REAL ESTATE 528-4121

- 716 1/2 WILLIAM ST BEGINS

717 BURNSIDE HARDWARE & SUPPLY 528-7625
719 VACANT
721 NIEVES ALICE 289-3255
725 735 SCOTLAND APARTMENTS
A CUCUZZA JOSEPH 289-0695
726 VACANT
727 SCOTLAND A APTMENTS

Target Street	Cross Street	Source
✓	-	Price & Lee's City Directory

BURNSIDE AVE 1977



A VACANT
B GREENWOOD CLYDE L 289-4091
C VACANT
D FLEMING MARIE C MRS 528-3452
729 SCOTLAND APARTMENTS
A POWLING R
B WRIGHT ROSE MRS 528-1325
C MONROE E
D PURUSHOTHAM SAMUEL 289-5868
730 RIPOLONE 528-5010
BEATRICE M MRS
731 SCOTLAND APARTMENTS
A SIGMAN JOHN R 289-2690
B CRANE HOWARD H JR 289-8972
C JOHNDROW C 289-7380
D JAMES KATHERINE C 528-0903
733 SCOTLAND APARTMENTS
A VACANT
B DAIGLE PETER 289-0454
733 C VACANT
D GUBIS FELIX A 528-0274
735 SCOTLAND APARTMENTS
PATTEN JOYCE MRS 289-2153
736 MURPHY MABEL P MRS * 289-4435

- 737 SCOTLAND RD BEGINS

738 MURPHY EMMA F MRS * 289-0897

- 740 FRANCIS ST BEGINS

744 LONG MARGE 289-4662
745 OLMSTED MARY E G MRS * 528-3095
746 MC CREARY CLAUDE W 528-6368
748 BARACCHI JOHN T JR * 289-1330
750 LEONE ANNE MRS * 528-1201
754 DEROMA CONSTANCE 528-8478
ARMENTROUT EDWARD G 528-8753
MILLER RAYMOND 289-5122
PLAMONDON HARVEY J 528-3035
756 WOOD STEPHEN S 239-1224
A1 LA CHANCE R
A2 CICHASKI JOHN S 289-8896
A3 O BRIGHT G 289-7532
A4 STRIEDER F D 289-4061
A5 GRANES ARNOLD JR
A6 MAHER M 289-5243
A7 MAXWELL JIMMIE 289-4114
B1 MESCHINI MARIO 528-8490
B2 MORAITIS L
B3 NEUMAYER RICHARD 528-8157
B4 DURKIN J N 528-8571
B5 BORKIEWICZ C 289-4419
B6 KICE C A 528-0431
B7 SAURINS L

- 760 LARRABEE ST BEGINS

763 GOODWIN GEORGE * 528-2952
777 EAST HARTFORD 289-7411
HIGH SCHOOL
EAST HARTFORD 289-7411
HIGH SCHOOL LIBRARY
784 VACANT
VACANT
786 GOODWIN ALBERT 528-1324
788 GOUSSE IRENE MRS 528-2493
793 VACANT
800 HUNTER ROBERT R * 528-1127
802 BIELFAU REED
803 BEZZINI PETER M * 528-1723
809 PENNY GREGG L * 528-7143
810 COULOMBE PAULINE MRS * 528-5428
BIALY STANLEY V 528-0686
815 NEUMANN ALBERT G * 528-7073
816 MARTINS FERNANDO * 289-5362
818 MARTINO FRED
819 HETHERMAN JAMES R * 528-6064
820 PHILLIPS BRADFORD K 528-2682
822 AHERN ANNE S MRS * 528-0769
827 BROCK NORMAN G * 528-2762
834 MICHAUD I T NURSE * 528-7911
835 HANLEY JOAN M * 528-2088
840 MODUGNO NICOLA * 289-8430
841 NEWSOM K ROBERT * 528-5989
842 CORSO JOHN W * 528-3080
844 GODREAU LEO J 289-4975
VACANT
846 MORRIS SENDA C MRS 528-3495
KROPF LILLIAN M MRS * 528-4340
847 GUERTIN ORTA C 289-2165

Target Street	Cross Street	Source
-	✓	Price & Lee's City Directory

SCOTLAND RD 1977

DISTRIBUTORS INC RUGS
434 LOVELL GENEVIEVE * 528-7242
R MRS H
- 443 RUMSEY RD BEGINS

444 FRASCA ANDREW A * 528-1830
451 WELLES TEXACO 289-6694
GASOLINE
469 EASTERN TOOL CO 289-5481
INC MACH
474 VACANT
479 WARNER MARY E MRS
* 528-4611
WARNER WILLIAM 289-1466
480 HOPKINS ELEANOR MRS
486 MC DONALD JAMES A
528-8900

- 501 CON RAIL CROSSES

- - - - - - - - - - - - - - - - - - -

SCOTLAND RD FR 737 BURNSIDE AV SE
TO 178 FORBES AV /RIGHT ODD/
ZIP CODE 06108

37 SCHERER HENRYJ JR REV
528-0550

- 131 GOODWIN LA ENDS
- 143 THOMAS F SHEA
- CAUSEWAY CROSSES

145 RHODIS ALLANO * 528-0833
153 KUZNIAR PAUL * 289-1830
161 SAGAN JOSEPHINE J
289-3078

- 171 HUDSON ST ENDS

Target Street	Cross Street	Source
✓	-	Price & Lee's City Directory

BURNSIDE AVE 1971

@ Pongratz Joseph M 528-2327
602 Lyman Vera I 528-5253
603 Twentieth Century Television Inc 528-1554
604@ Leavitt Charles E 528-0893
606 Klug Walter
Mantello John 289-1207
607 Galeotas La Pizza & Grinders Inc 289-4225
608 LaBonte Maurice J 289-5659
Pierce Eugene E 289-3819
609r Vacant

610 ELMER ST begins

612 Fire Co No 3 528-4173
613 Morin Gerard G 289-1306
615 Wawer Michael 528-1872
Sander Joseph M 528-0667
616 Kilpatrick Susan 289-6910
Fink Herman 528-3581
617 Patelli John Jr 289-5020
619@ Kamm Walter A 528-1443
621 Boffe Roger P 289-3130
623 Martinelli Victor
627 Friendly Ice Cream Restaurant 528-6780
635 Salem Apartments
(1A) Vacant
(2A) Vacant
(3A) Vacant
(4A) LaClaire John T
(5A) Valiquette Robert A 289-5505
(6A) Pizzuto Russell 528-7697
(7A) Martin Henry
(8A) Vacant
(1B) Panteleckas Charles 528-3522
(2B) Gunther Herman
(3B) Willey Edward T 289-3582
(4B) Sulsane Louis
(5B) Izzi Jane 232-6087
(6B) DeCoske Thomas
(7B) Taylor Marilyn
(8B) Vacant
637 Salem Apartments
(1C) Kraft Carlos A 528-1916
(2C) Green Robert
(3C) Johnson Wesley 528-2370
(4C) Strogoff Myra Mrs 528-4502
(5C) O'Malley Robert E 528-4317
(1D) Icone Laura Mrs
(2D) Miceli Jo-Ann 528-8889
(3D) Vacant
(4D) Vacant
(5D) Chopis George
643 Miller Benjamin
Appleton H G lwyr 528-5119
Kovacs Albert
Genaris James
Caserio Jesse
Tucker Leon
645 Generis Caterers Inc 289-7756
Generis Vending Co Inc 289-7756
Gentile Patricia
647r@ Lengyel Louis J 2893536
653 Tischofer Charles Jr & Sons Inc gasoline 289-2034
656 Wickham Memorial Library 528-4664
657 Jolly Restaurant 289-9759
Wawer Michael S 528-3774
663 Dairy Mart 289-2386
665 Colli & Wagner Agency Inc real est 289-0241
667 Burnside Music Land 528-1360

668 SCHOOL ST begins

669 H & G Discount 289-2682
669 1/2 Tones Cozy Hut rest 289-6548
671 Burnside Package 528-0547
Hearn Robert C 289-3185
672 Dagons Service Station 289-9906
673 Modern Barber Shop 289-9636
Loris Beauty Salon 528-7161
678 Leone Pharmacy Inc 528-4131
680 Savage Food Market Inc 289-6859

691 CHURCH ST begins

694 Burnside Finer Shoe Store 289-5283
694A Adriennes Coiffure Beauty Shop 289-6183
694B Vacant
696 Cumberland Farms Inc 289-9771

696 1/2 HANMER ST begins

700 Kocum John R Building
Burnside Drug 289-3488
Savings Bank Of Manchester
Burnside Office 289-8214
Holly Coiffures 289-3069
Highlander Center Laundry
Sunset Cleaners 289-1302
Jensens Restaurant 289-3514
Vacant
(1) Kocum John R Co real est 289-2444
(2-4) Wolk W R dentist 289-5322
(3) Powers Elaine Figure Salon Beauty Shop 289-8253
(5) Vacant
(6) Dial-Data Inc 528-4474
(7) Vacant
(8) Vacant
(9) Vacant
9-11) Keane Associates Inc 528-9221
(10) Vacant
(11A) Vacant
(12) Vacant
(13) Forbes Street Realty Corp builders 528-4186
P J Corporation builders 528-4186
H J Contractors Inc builders 528-4186
(14) Vacant
(15) Commerical Stenofax Corp office supplies 528-9341
(15A) Vacant
(16) Kennedy Auto Driving School
(17) Vacant
(18) Vacant
(20) Lublin R K lwyr 289-8625
Lublin G R lwyr 289-8625
711 Arnolds Barber Shop 528-4218
Vacant
Lantieri Angelo S 528-4656
713 Sosa Armando
Vacant
715 (1) Vacant
(3) Balesano Frank E
(4) Vacant
(5) Elko George
715 1/2 Jane & Leo Restaurant 289-9781

716 1/2 William St begins

717 Burnside Hardware & Supply 528-7265
719 Sheffield Ada V Mrs 528-1886
721@ Shaw Gordon M 528-0087
725 Scotland Apartments 233-4431
(A) Montavani Robert W 289-6201
726 Doby Dale A
Pasek Real Estate Co 289-7475
Pasek Insurance Agency 289-7475
727 Scotland Apartments
(A) Cleary James P 289-2149
(B) Greenwood Clyde L 528-7642
(C) Miller Anne Mrs
(D) Fleming Marie C Mrs 528-3452
729 Scotland Apartments
(A) Tan Wen Sung A 528-7179
(B) Leveaque Michael
(C) Purushotham D P 528-3946
(D) Gustaferro Anthony
730@ Ripolone Nicholas P 528-5010
731 Scotland Apartments
(A) Sigman John R 528-4030
(B) Vacant
(C) Lite Scott W 289-8588
(D) McKeen William M 242-0025
733 Scotland Apartments
(A) Cappa Frank R
(B) Daigle Peter 289-0454
(C) Semanski Richard 528-4993
(D) O'Gren Orrin M 289-9035
735 Scotland Apartments
Perruccia Paul P 528-8369
736@ Murphy Mabel P Mrs 289-4435

737 SCOTLAND RD begins

738@ Murphy Emma F Mrs 289-0897

740 FRANCIS ST begins

744 Girard Armand A 528-4688
745@ Olmsted Mary E G Mrs 528-3095
746 McCreary Claude W 528-6468
748 Vacant
750@ Leone Anne Mrs 528-1201
754 Hatella Robert 289-4426
Pollnow Gus 528-0532
Miller Raymond 289-5122
Plamondon Harvey J 528-3035

760 LARRABEE ST begins

763@ Goodwin George 528-2952
777 East Hartford High School 289-7411
784 Ference Harriet S 528-5531
Turning Donald M 289-2917
786 Goodwin Albert 528-1324
788 Spinney Mary F Mrs 528-3454
793@ Jergensen H M printer 528-3370
800@ Hunter Robert R 528-1127
802 Brett Frances E 528-4303
803@ Rezzini Peter M 528-1723
809@ Penny Gregg L 528-7143
810@ Coulombe John 528-5428
Bailey Stanley 528-4405
815@ Neumann Albert G 528-7073
816@ Martins Fernando 289-5362
818 Gorka Edward W 289-7838
819@ Hetherman James R 528-6064
820@ Rumley Mary A Mrs 289-0470
822@ Ahern Anne S Mrs 528-0769
827@ Brock Norman G 528-2762
834 Michaud Irene T 528-7911
Michaud I T nurse
835@ Hawley Joan M 528-2088
840@ Modugno Nicola 528-5380
841@ Helm Mary E Mrs 289-7675
842 Corso John W 528-3080
844 Godreau Leo J 289-4975
Pinkham George E 289-7052
846 Morris Senda C Mrs 528-3495
@ Kropf Lillian M Mrs 528-4340
847 Guertin Orta C 289-4404
854@ Teixeira Joseph R 289-4286
855 Lockwood William E 289-1349
Fagan Marion E 528-2558

856 PRICE CT begins

858@ Trahan Deas 528-0718
860 Bates David J
Tessier Marie D Mrs 528-8220
864@ McCarron Clarence M 528-5468
870 Burnside Convaleacent Home
873@ Osbeck Hugo O 289-1708

SCOTLAND RD 1971

469 Eastern Tool Co Inc mach 289-5481
Etco Mfg Corp The mach 289-5491
474 Sculli Machine Co Inc tool mfrs 289-1524
479◎ Warner Mary E Mrs 528-4611
Warner William 289-1466
486◎ McDonald Allen J 528-1066

501 PC RR crosses

SCOTLAND RD FR 737 BURNSIDE AV SE TO 178 FORBES AV (RIGHT ODD) ZIP CODE 06108

37 O'Brien R Lawrence N Rev 528-0550

131 GOODWIN LA ends
143 THOMAS F SHEA CAUSEWAY crosses

145 Rhodes Alan O 528-0833
153◎ Kuzniar Paul 289-1830
161◎ Sagan John 289-3078

171 HUDSON ST ends

SCOTT FR 89 WASHINGTON AV NW AND W BEY RAYMOND THEN S TO DEAD END (RIGHT EVEN) ZIP CODE 06118

7◎ Eliasson Roger C 568-0102

8 SCOTT CIR begins

Target Street	Cross Street	Source
✓	-	Price & Lee's City Directory

BURNSIDE AVE 1965



ΔKilpatrick Susan
ΔAmado Sandra
617ΔPatelli John
619ΔKamm Walter A ©
621ΔMirucki Josephine H Mrs ©
623ΔSlowik Stasia R Mrs
627ΔFriendly Ice Cream
635 Broderson Copley
ΔHenry George M
637ΔDickman Albert A
643ΔFinkel N F dentist
643ΔAkers Woodrow
645ΔGraveline T J ©
ΔColorama Wallpaper & Paint
Lajoie Maurice R
647rΔLengyel R Mrs ©
653ΔTischofer Charles Jr & Sons Inc gasoline
656ΔWickham Memorial Library
657ΔJolly Restaurant
ΔThoms Arthur
663ΔButler H M dentist
665ΔColli & Wagner Agency Inc real est
667ΔBurnside Laundromat
668 SCHOOL ST begins
669ΔCalano's Furniturama Inc
669½Δ Al's Grinder Shop rest
671ΔArcari Louis D
ΔJohnny V's Package Store
672ΔDagon's Service Station gasoline
673ΔGullota A P
ΔModern Barber Shop
ΔLori's Beauty Salon
678ΔPeople's Drug Store
680ΔSavage Food Market Inc
684r Vacant
686ΔMainerre A F Store grocer
690ΔPeterson's Package Store
691 CHARLES ST begins
692ΔRambler Tavern
694ΔBurnside Restaurant
694aΔAdrienne's Coiffure
694b Howard's Cleaners branch
696ΔBurnside Drug
696½ HANMER ST begins
704 Vacant
711 Arnold's Barber Shop
Vacant
ΔLantieri A S
713 Vacant
Jones James T
714 Vacant
715 (1)Vacant
(2)Vacant
(3)McElroy Vincent
(4)Vacant
Δ(6)National Automobile Dealers Service
715½ΔM & M Restaurant
716 Vacant
716½ WILLIAM ST begins
717ΔSuperior Hardware & Supply
719ΔTardscio Anthony A Jr
Rogers W William
721ΔShaw Gordon M ©
726ΔPasek Realty
Belanger Leonard W
730ΔRipolone Nicholas ©
731ΔMcCarty Felix J
735 SCOTLAND RD begins
736ΔMurphy Mabel P Mrs ©
738ΔMurphy Paul J ©
740 FRANCIS ST begins
744ΔBoardman Gloria Mrs
745ΔOlmsted Mary E G Mrs ©
746ΔMcCreary Claude W
748ΔNash Charles R Jr ©
750ΔLeon Anne Mrs ©
Vacant
754ΔMason Thomas R
ΔJohnson Kenneth T
ΔSenereth Marion Mrs
Plamondon Harvey J ©
Metcalf Thomas R
Vacant
ΔBarnhart Daniel C
760 LARRABEE ST begins
763ΔGoodwin George ©
777ΔHigh School
784ΔCague Margaret G
Mastrangelo William J
786ΔGoodwin Albert H
788 Spinney Mary F Mrs
793ΔJergensen H M painter
800ΔHunter Robert R ©
802ΔThoresen Merrill ©
803ΔBezzini Peter M ©
809ΔPenny Gregg L ©
810ΔCoulombe John ©
ΔBoudreau Anna Mrs
815ΔNeumann Albert G ©
816ΔMartins Fernando L ©
818ΔGrant Charles E

SCOTLAND RD 1965

451ΔDonlin's Texaco Service
469ΔEastern Tool Co Inc machs
ΔEtco Mfg Corp The machs
474ΔSculli Machine Co Inc tool mfrs
479ΔWarner Mary E Mrs ◎
Warner William
486ΔMcDonald A J ◎
501 NH RR crosses
550ΔCox Dorothy C ◎

SCOTLAND RD

Fr 735 Brunside av SE and S to 178 Forbes (Right odd) Zone 8

37ΔPost John E Rev ◎
131 GOODWIN LA ends
143 THOMAS F SHEA CAUSEWAY crosses
153ΔKuzniar Paul ◎
161ΔSagan John ◎
171 HUDSON ST ends


SCOTT

Fr 89 Washington av NW and W bey Raymond then S to dead end (Right even) Zone 8

7ΔWhite Edda M Mrs
8 SCOTT CIR begins
9 Main Stanley ◎
21ΔSullivan George V ◎
22ΔTanquay Neil L ◎
25ΔO'Keefe James F ◎
28ΔShanahan Eugene T ◎
29ΔHill David H
31 Dowling Howard F ◎
42 Vacant

Target Street	Cross Street	Source
✓	-	Price & Lee's City Directory

BURNSIDE AVE 1960



BURNSIDE AVE (CONTINUED)

ΔKosler W dentist
589ΔBlass Carl E
591ΔKeenan John J
593ΔMcMullin E S Mrs ®
596ΔTully John J ®
597ΔPorter Charles A ®
Vacant
598 Hernsdorf Charlotte Mrs
ΔBurnside Express Co
ΔHolland John H ®
ΔWeeks A S tel answering service
601ΔIntravia S A lwyr
ΔIntravia J lwyr
ΔIntravia J J lwyr
ΔPongrat Joseph M ®
602ΔBruckner Werner
603ΔTwentieth Century Television Inc
604ΔLeavitt Charles E ®
605 Vacant
606ΔNorosky Hubert J
607ΔGaleota's La Pizza & Grinders Inc rest
608ΔAllard Roger K
Michaud Joseph N R
609rΔMcClellan Randolph A ®

610 ELMER ST begins

612ΔFire Co No 3
613ΔCowden John Jr
615ΔHansen Peter G
ΔSander Joseph M
616ΔFink Herman J ®
Vacant
617ΔPatelli John
619ΔKamm Walter A ®
621ΔMirucki Josephine H Mrs ®
623ΔSlowik Stasia R Mrs
627ΔFriendly Ice Cream
635 Vacant
637ΔDickman Albert A
643ΔFinkel N F dentist
645ΔGraveline T J ®
ΔBurnside Paint Center
647rΔLengyel R Mrs ®
653ΔTischofer C Jr gasoline
656ΔWickham Memorial Branch Library
657ΔMoran Gerard G
ΔJolly Restaurant
663ΔButler H M dentist
665 Vacant
667ΔBurnside Laundromat

668 SCHOOL ST begins

669ΔCalano V J tile
ΔCalano's Furniturama Inc
ΔShanty Diner The
671ΔArcari Louis D
ΔHorn N bev
672ΔDagon's Service Station gasoline
673ΔGullotta A P
Gullotta J barber
ΔLori's Beauty Salon
678ΔPeople's Drug Store
680ΔFirst Nat Stores Inc grocers
684r Vacant
686ΔManierre A F Mrs grocer
688 Taddeo Dominick
ΔTrivigno John J
690ΔPeterson's Package Store

691 CHURCH ST begins

692ΔRambler Tavern
694ΔBurnside Restaurant
694a Vacant
694b Howard's Cleaners branch
696ΔBurnside Drug Co

696½ HANMER ST begins

698ΔMacGibbon Stuart G Jr
700ΔChesky Edward Jr
702ΔRisley Wells M
704ΔBelyea Ernest W
711 Tine S barber
ΔArnita Beauty Salon
ΔLantieri A S
712ΔGrivois George E
ΔVeal Elton A
713ΔPhillips Edwin
ΔRavalese Harry ®
714 Incandela V B shoe repr
715Δ(1)Grolier Society Inc publishers
(2)Vacant
(3)Gustafson W E MD
(4)Vacant
(6)Gerber Products Co food products
715½ΔTony's Pizza Palace rest
716ΔLet & Gene cleaners

716½ WILLIAM ST begins

717ΔSuperior Hardware & Supply
719ΔWardwell Marion D Mrs
721ΔShaw Gordon M ®
726ΔDettenborn Emil A
730ΔRipolone Nicholas ®
731 Vacant

735 SCOTLAND RD begins

736ΔMurphy Mabel P Mrs ®
738ΔMurphy Paul J ®

740 FRANCIS ST begins

744ΔWallace Milton A
745ΔOlmsted Mary E G Mrs ®
746ΔMcCreary Claude W
748ΔNash Charles R Jr ®
750ΔLeone Anne Mrs ®
754ΔPelletier Gerald R
Vacant

760 LARRABEE ST begins

763ΔGoodwin George ®
777ΔHigh School
784ΔCague Leonard J ®
786ΔDegen George E
788ΔGoodwin Albert ®
793ΔJergensen J M painter®
800ΔHunter Robert R ®
802ΔHunter Robert V ®
803ΔBezzini Peter M ®
809ΔPenny Gregg L ®
810ΔCoulombe John ®
ΔO'Connor Edward
815ΔMcClellan E L Mrs ®
816ΔMartins Fernando L ®
818 Vacant
819ΔHetherman James R ®
820ΔRumley Michael E ®
822ΔAhern John J ®
827ΔBrock Norman G ®
834ΔCarlton M J Mrs ®
835ΔHawley John S ®
840ΔNeumann A G ®
841ΔHelm Stanley R ®
842 Vacant
844 Vacant
846ΔMorris Senda C Mrs
847ΔSmith Harold L
848ΔKropf Lillian M Mrs ®
Vacant
854ΔRini Paul C ®
855 Vacant
ΔBurns Alfred J ®

856 PRICE CT begins

858ΔTrahan Deas ®
860ΔBerube Emil Jr
Vacant
864ΔMcCarron C M ®
870 Rush Patrick J ®
873ΔOsbeck Hugo O ®
874ΔSpellman George A ®
877ΔCataldi Frances M Mrs ®
878ΔEsada Peter ®
880ΔRauchle George C
881ΔFeather Gilbert R ®
884ΔDesautels Ovila A ®
885ΔHinchberger Edward P
886 Vacant
888ΔCoppinger Thomas M
ΔNolan William J ®


888½ HOWARD CT begins

890ΔMeyer Max J ®
891ΔSmith Frank R
892 Vacant
893 Vacant
896ΔAttenborough Fred A ®
902ΔScott Einar S ®
903ΔFox Lewis J Jr
904ΔMajkowski Edward S
905ΔTimbrell Edward H ®
906ΔGarrity George R
907ΔBrown Davis D ®
908ΔKaczmarczyk T W ®
909 Kiernan Edward
910ΔSalisbury John K
Hunt Peter A
911ΔAgent Charles ®
913ΔEvans Frank
ΔEvans R A Mrs nurse
915ΔHutt Grace M ®
917ΔHutt William J
919ΔSheridan Catherine J Mrs
921ΔOakes Raymond
ΔBadard Anthony A
923ΔBengston R N
925ΔBengston Nils B ®
927ΔArcari Michael ®
929ΔPanabry Richard J ®
930 St Mary's Cemetery

970 LONG HILL DR begins

Target Street	Cross Street	Source
-	✓	Price & Lee's City Directory

SCOTLAND RD 1960



960

ΔShonio Gardiner
486ΔMcDonald A J ◎
501 NH RR crosses
550ΔCox M W Mrs

SCOTLAND ROAD
From 735 Burnside av SE
and S to 178 Forbes Zone 8
131 GOODWIN LA ends
143 THOMAS F SHEA
CAUSEWAY crosses
153ΔPodisadlo Wanda Mrs
161ΔSagan John ◎
171 HUDSON ST ends

SCOTT
From 89 Washington av NW
and W bey Raymond rd then
S to dead end (Right odd)
Zone 8
7ΔWhite George ◎
8 SCOTT CIR begins
9 Main Stanley ◎
21 Vacant
22ΔTanquay Neil L ◎
25ΔO'Keefe James F ◎
28ΔShanahan Eugene T ◎
29ΔRobertson William A ◎
31 Dowling Howard F ◎
42 Vacant
48ΔKohan Michael ◎

Target Street	Cross Street	Source
✓	-	Price & Lee's City Directory

BURNSIDE AVE 1951



577 Cavanaugh P C
580 Burnside Theatre
585 Schaff Anna Mrs
589 Blass Carl E
Plant Kenneth A
591 Vacant
593 McMullin E S Mrs
596 Tully John J
597 Porter Charles A
Vacant
598 Barber Myrtle M
Holland John H
Watson Elmer E
599 Gold William
601 Hinkleman R S
602 Kennedy Harold W
603 Hartford Kirby Co Inc The elec appliances
604 Leavitt Charles E
606 Massicotte E W
607 Galeota's La Pizza & Grinders rest
608 Burnham Leslie F
609r McClellan Randolph A
610 ELMER ST begins
613 Cowden John Jr
614 Fire Co No 3
615 Bigelow Lillian C
Sander Joseph M
616 Fink Herman J
617 Pongratz Joseph M
619 Sander William J
621 Miruckl Joseph F
623 Slowik Peter J
629 Plenke Harold A
MacDonald E B Mrs
635 Imeln Leo Jr
637 Lauridsen M Mrs
643 Finkel N F dentist
Brindley R H
Stone Mason W
645 Merrill David R
Loon Clayton
Graselle T J plumber
647r Lengyel R Mrs
653 Tischofer C Jr gasoline
656 Wickham Memorial Library
657 Batchelor M I Mrs
Jolly Restaurant
663 Coan B T dentist
665 Falcone S shoe repr
667 Vacant
668 SCHOOL ST begins
669 Alexander's Diner
Stop & Shop grocers
671 Arcari Louis D
Comp C W ber
672 Dagon J J gasoline
673 Gullotta A P
Gullotta J barber
Rin's Beauty Salon
678 People's Drug Store
680 First Nat Stores Inc grocers
684r Vacant
686 Manlerre A F Mrs grocer
686r Vacant
688 Palumbo Antonio
Trivigno John J
690 Peterson's Package Store
691 CHURCH ST begins
692 Rambler Tavern
694 Burnside Restaurant
694a Pardy F E variety store
694b Vacant
Burnside Drug Co
696½ HANMER ST begins
698 Chambers Frank W
700 Bergstrom L B Mrs
702 Lawliss George R
704 Boyes Grandin M
711 Tine S barber
Amita Beauty Salon
Lantieri A S
712 Bailey Harriet E Mrs
Hardy Mary E Mrs
713 Guinta Alma H
Ravalese Harry
715 Hartford Superette grocers
716 Let & Gene cleaners
716½ WILLIAM ST begins
717 Superior Hardware & Supply
719 Keifel K Mrs
721 Shaw Gordon M
726 LaChapelle E L
730 Ripolone Nicholas
731 Mullaney Charles F
736 Strehlan Frank F
738 Meunier J Frank
740 FRANCIS ST begins
744 Ashe W L trucking
745 Olmsted C Henry
746 Rondeau W R
748 Leone Anthony V
750 Leone D J
Leone V and Son artesian wells
Aero Company sheet metal wkrs
754 Hedlin George H
Vacant
Holland Charles J
760 LARRABEE ST begins

763 Goodwin George
784 Cague Leonard J
786 Sikora A J
788 Goodwin Albert
793 Jergensen H M
800 Hunter Robert R
802 Hunter Robert V
803 Bezzini Peter M
809 Penny Thomas P
810 Vacant
815 McClellan E L Mrs
816 White Percy M
818 Mesnier Harold E
819 Hetherman James R
820 Hyman Herbert
822 Ahern John J
827 Brock Norman G
834 Carlton M J Mrs
835 Hawley John S
840 Neumann A G
841 Helm Stanley R
842 Brewer Clare P
844 Carruthers Robert
Dane May C Mrs
846 Morris Senda C Mrs
847 Butler William F
848 Kropf Lillian M
Arbus Ida Mrs
854 Rini Paul C
855 Fagan Edward J
Mitchell Phillip
856 PRICE CT begins
858 Trahan Deas
860 Zingle John J
McNulty John
Vacant
864 McCarron C M
870 Rush Patrick J
873 Carter Anna Mrs
874 Spellman George A
877 Cataldi George A
878 Esada Peter
880 Lurette Prosper
881 Feather Gilbert R
884 Hawksworth L C Mrs
885 Kilby Raymond L
886 Hawksworth G F
887 Micoletti Anthony
888 Carroll John F
Nolan William J
888½ HOWARD CT begins
890 Meyer Max J
891 Bilodeau J A
892 Merrill M C Mrs
893 Aleria Antonio
896 Attenborough Fred A
902 Scott Einar S
903 Johnson F O
904 Lazeren Nellie Mrs
905 Timbrell Edward H
906 Majkowski E S
907 Brown Davis D
908 Holmstrom Arthur C
909 Blanchard Louis J
910 Mather Charles S
911 Agent Charles
913 Evans Frank
Evans R A Mrs nurse
915 Hutt William J
917 Hutt Ernest J
919 Sheridan Timothy
921 Jellen J A
Oakes Raymond
923 Bengston R N
925 Bengston Nils B
927 Pinerest Convalescent Home
Almandinger V G
929 Cockburn P R plumber
930 St Mary's Cemetery
1016 LONG HILL DR begins
1024 Polowitzer A W
Thoms Ernest C
Polowitzer's Package Store
1067 Mayberry Village Barber Shop
1069 Andy's Package Store
Brooks A H grocer
Vacant
1073 Hartford Auto Body and Welding Co
Joe The Tire Expert
1075 WALNUT ST begins
1083 Molinski F D gasoline
—off Mayberry Village Housing Project
1084 Bergren John A
1090 Bergren Arthur W
1100 Bergren J A Dairy Farms
1110 Hansen John F
Emerson's Service Station
1112 MARY ST begins
1120 Goba J J
1130 Otis Frank M Jr
1140 Norman P P
—off Stankevicus Matthew
—Stetson James
— Lee James A Jr
— Lee James A
—Nordgren Alfred
—Velta Anthony W
—Cosnover W G Mrs

Target Street	Cross Street	Source
✓	-	Price & Lee's City Directory

BURNSIDE AVE 1946




1760 1946—7

Burnside Av—continued
488 Sexton Thomas M
490 Hausmann Henry A
494 Romaczwicz W meat
496 Romaczwicz William
498 Wiebe's Restaurant
500 Bid-Well Pharmacy
501 McCauley John E
502 Bidwell av begins
503 Shubert Frederick H
508 Shaughnessy John W
508 Sotting Charles A
509 Molaison Gustave H
510 Sullivan E D
511 Forbes Lloyd C
512 Grant Theodore Q
Kampfman Eva M Mrs
513 Maguire C Mrs
Lyons M E Mrs
514 Paynter S E grocer
516 Fagan John J
Torpey Richard M
Vicki Allo P
516½ Bartley W J
Jean Soda Shop conf
517 Meguire John F
518 (A2) Ralston Robert H
(B2) Donlon James
(C2) Dube Armand J
519 Brace William P
520 (A1) Sheridan W T
(B1) Lavigne S Mrs
(C1) Doms Carleton W
522 Reesor Harold L
Goldberg Irving
523 Schlatter Alfred F
Titus Howard W
523r Fox Albert L
Fox Fred M
524 Carlson Ralph F
526 Lord's Super Service Station & Garage
526½ Moore av begins
541 Flynn John L
Hollister Horace T
546 Lubin Raymond D
547 Hennessey John R
549 Stone Charles J
551 Rolston W James
553 Vacant
554 Ellard C J
557 Wind rd begins
564 Deinckt A A Mrs
572 Stager M A Mrs
573 Terry rd begins
577 Cavanaugh Mary E
585 Scharf Anna Mrs
589 Gatten Richard T
591 Yoo William A
593 McMullin E S Mrs
596 Tully John J
597 Smith M C Mrs
598 Barber Myrtle M
Holland John H
599 Grinshaw E C
601 Hinkleman R S
602 Smith R R Mrs
602 Clark Lewis E
604 DeLorme Alfred C
606 Massicotte E W
608 Weiss Clyde H
609r McClellan Randolph A
610 Elmer st begins
613 Cowden John Jr
614 Fire Co No 3
615 Langer Joseph P
Sander Joseph M
616 Fink Herman J
617 Sander William J
619 Bigelow Frank E
621 Mirski Joseph F
623 Slowik Peter
629 Flenke Harold A
MacDonald James A
635 Imein Leo Jr
637 Fentiman L E
643 Breen Joseph P
Johnson Leonard C
645 Anderson John W
Plant Kenneth A radio repr
647r Lauridsen M Mrs
653 McMahon T J gasoline
656 Wickham Memorial Library
657 Batchelor Dearden A
Jolly Restaurant
663 Coan B T dentist
665 Falcone S shoe repr
667 Lloyd's Electrical Service
668 School st begins
669 Alexander's Diner
Economy Grocery Stores Inc
671 Guilotta J bar
Paul Anthony R
672 Dugon J J gasoline
673 Guilotta J barber
Guilotta Frank C
678 People's Drug Store
680 First Nat Stores Inc grocers
684r Vacant
686 Manierre A F Mrs grocer
688r Vacant
688 Palumbo Antonio
Trivigno John J
690 Peterson's Package Store
691 Church st begins
692 Rambler Tavern
694 Burnside Restaurant
694a Burnside Home Bakery
696 Reynolds G M variety store
696½ Hanmer st begins
698 Chambers Frank W
700 Morlock Edward C
702 Lawlor George R
704 Boyes Grandin M
Franko Rose Mrs
711 Tine S barber
711 Harriett Mae's Beauty Salon
712 Bailey Clifford
Tomlin Edward A
Vacant
715 Hartford Superette grocers
716 Conn Valley Farms
716½ William st begins
717 Superior Hardware Co
719 Keitel K Mrs
721 Simpson Robert L
726 Vacant
730 Rigolone Nicholas
731 Mullaney Charles F
736 Streolan Frank F
738 Meunier J Frank
740 Francis st begins
744 Larson Walter H
745 Olmsted C Henry
740 Streolan Frank F Jr
748 Liberty Alfred J
750 Carroll Stephen J
754 LaChapelle Annie M Mrs
Blake John
Holland Charles J
760 Larrabee st begins
763 Goodwin George
784 Cague Leonard J
786 Robertson J Franklin
788 Goodwin Albert
800 Hunter Robert R
802 Waltham Charles H
802 Hunter Robert V
Vacant
803 Rezzini Peter M
809 Lapointe J W
815 McClellan E L Mrs
816 White Percy M
818 Messler Harold E
819 Tomlin Edward A Jr
820 Hyman Herbert
822 Ahern John J
827 Vacant
834 Carlton M J Mrs
835 Hawley John S
840 McDonough J P
841 Helm Stanley R
842 Carruthers Robert
844 Brewer Clare P
Whittaker Joseph J
846 Morris Senda C Mrs
847 Bresnahan G H
848 Kropf Lillian M
Arbus Ida Mrs
854 Rini Paul
855 Fagan Edward J
Gladwish Robert L
856 Price ct begins
858 Wallace E K
860 Zingle John J
Johnson Lester B
861 Vacant
864 McCarron C M
870 Rush Patrick J
873 Carter Anna Mrs
874 Spellman George A
877 Carlton F L Jr
878 Burkhardt G H
880 Lurette Prosper
881 Feather Gilbert R
884 Hawksworth F M
885 Kilby Raymond L
886 O'Connell D T
887 Micoletti Anthony
888 Nolan William J
Thompson Lester G
888½ Howard ct begins
890 Meyer Max J
891 LaBonte Otila
892 Merrill Benjamin B
893 Aleris Antonio
896 Attenborough Fred A
902 Scott Elmer S
903 Johnson F O
904 Sessions F M
905 Timbrell Edward H
906 Lazeren Michael
907 Brown Doris D
908 Pitkin Bernard K
909 Castellini J A
910 Mather Charles S
911 Agent Charles
913 Evans Frank
915 Dowden Andrew F
917 Hutt Ernest J
919 Wormstedt E F

Target Street	Cross Street	Source
✓	-	Price & Lee's City Directory

BURNSIDE AVE 1941



668 School st begins
671 Gullotta J bev
Paul Anthony R
671r Vacant
672 Dagon J A gasoline
673 Δ Cuan B T dentist
Gullotta J barber
Gullotta Frank C
674 Vacant
678 Δ Peoples Drug Store
680 Δ First Nat Stores Inc grocers
684r Vacant
686 Δ Manierre A F Mrs grocer
686r Vacant
688 Trivigno John J
Δ Taddeo C M Mrs ®
690 Δ Radom M bev
691 Church st begins
692 Rambler Tavern Inc The
694 Kwesell Julius R
Δ Burnside Hardware Store
694a Chester A Mrs baker
696 Δ Post Office sub station
Δ Lerner Drug
696½ Hanmer st begins
698 Chambers Frank W
700 Morlock Edward C
702 Lawliss George R
704 Boyes Grandin M
711 Franko Rose Mrs
Vacant store
712 Nolan Louis E
Δ McCauley J E gasoline
Δ Swasey Raymond C
716 Sal's Barber Shop
716½ William st begins
719 Keifel K Mrs ®
721 Δ Simpson Robert L
726 Δ Burton Nathan B Rev
730 Δ Cruickshanks S R
731 Risley Clifford E
Risley J A Mrs
735 Goodwin la ends
736 Δ Strehlan Frank F
738 Δ Meunier J Frank
740 Francis st begins
744 MacIntosh Richard
745 Δ Olmsted C Henry ®
746 Padowitz Louis
748 Mannella A J
750 Moore W J Jr
754 Δ McQuarrie Frank J
Holland Charles J
O'Hurley James A
760 Larrabee st begins
763 Δ Goodwin George ®
784 Cague Leonard J ®
786 Robertson J Franklin
788 Sanden Eric F
800 Δ Hunter Robert R ®

Target Street	Cross Street	Source
✓	-	Price & Lee's City Directory

BURNSIDE AVE 1936



CO.'S

517 Maxner James A
518 Leone Sebastian P
West Lisle H
Shattuck M L
519 Boyes Grandin M
520 △ Ripiline George A
Haskell Audrey L
Clancy John F
522 △ Lord Moreland E
523 Maynard Glen W
△ Wenisch Frank J
523r △ Davis Richard K
Sullivan Eugene D
524 △ Lord Moreland J
526 Moore av begins
530 △ Lord M J gasoline
541 △ Flynn John L
Hollister Horace T
541 Briggs Harlan A
547 Clark Claude E
549 △ Buckley W H
561 △ Dresser Wilfred C
555 △ Olin Clara W Mrs
551 Brouillard George L
557 Wind rd begins
561 Santone Joseph
Bebricki Thomas A
572 Gordon M A Mrs dressmkr
△ Stager M A Mrs
573 Terry rd begins
577 △ Cavanaugh Mary E
585 △ Gosch John
589 Johnson Martin
591 △ Brown John M
593 △ McMullin Herbert G
596 Scanlon John
597 △ Smith M C Mrs
598 Holland John M
Quence Homer
601 △ Herr John M
Ritter Emilie
602 Kahanen A M
604 △ Williams Alfred
605 △ King William
608 △ Massiratte Edward W
609r Aitkin James E
610 Elmer st begins
613 Johnson T A
615 △ McNamara George E
616 △ Fresher George S
617 △ Bigelow Frank E
619 Peterson Emil H
621 Hasselbrack L W
623 Neuman Lewis A
629 Holt William
Holt H M furn rms
MacDonald James A
635 △ Lewis S D MD
637 △ Meyer Albert J
643 Imelin Leo Jr
Hlinn R W
645 Anderson John W
Plant Kenneth A
647r △ Lauritsen Soren L
657 Despard William H
Hanson A W tavern
662 Oberschmidt C H
665 Ebly Amelia A Mrs
668 School st begins
671 Caserio A M shoe repr
Gulliotta Frank F
672 △ Woods Filling Station
673 Cram R T dentist
Gulliotta J barber
Gulliotta Alexander P
674 △ Nasbiner M rest
676 Lagan T F tavern
678 Vacant store
680 △ First Nat Stores Inc grocers
681r Vacant store
686 △ Manderre A E Mrs grocer
686r Vacant store
688 Trivigno John J
△ Taddeo Joseph R
690 △ Kutner M G druggist
691 Church st begins
692 Rambler Tavern Inc The
694 △ Great A & P Tea Co The
694a Vacant store
696 △ Burnside Post Office
△ Powell Drug Co
696½ Hanmer st begins
698 Foran Henry A
700 Clark Coit C
702 Lawless George R
704 Laraia John A
711 Franko F tailor
712 Nolan Louis E
Malne Irving S
△ Swasey R C gasoline
712r Malne I S auto repr
716 Vacant store
716½ William st begins
719 △ Conwell K H Mrs
721 △ Flydal Arne O
726 Burton Nathan B Rev
731 Whitaker Howard
735 Goodwin la ends
736 △ Piller George L
738 △ Meunier J Frank
740 Francis st begins
741 Cloudman R R
745 Olmsted C Henry
746 Hawkins Edgar M
748 △ Finnerty James W
750 △ Mannella Alexander F
754 △ Demars A G
760 Larrabee st begins
763 △ Goodwin George
784 △ Cameron John H
786 Sanden Eric F
788 Vacant
800 △ Butryman S A
802 Hunter Robert R
803 △ Tyler Roy C
809 Stevens Edward R
815 △ Mctlellan E L Mrs
816 Smith Willis C
818 Rapp Arthur E
819 △ Carver John H
820 △ Plumridge E F
822 Ahearn John J
827 △ Sakea Joseph M
834 Sheedy John J
835 △ Hawley John S
840 △ Golec William T
841 Nowak Stanley
842 △ Alford Franklin R
844 Gerard F J
△ Foley Michael J
846 Morris Gertrude C Mrs
847 Shaw John
848 △ Kropf Lillian M
Arbus Ida Mrs
851 Vacant
854 △ Keeney R D Mrs
Rini P painter
856 Price ct begins
858 △ Pfau Sherwood H
860 Pearson O Mrs
Lata John
861 △ Stiefel Joseph C
870 Adam Robert
873 △ Carter Anna Mrs
874 Vacant
877 △ Carlton F L Jr
878 Burkhardt G H
880 Vacant
881 Feather Gilbert R
△ Stewart L A T Mrs
884 △ Martin Jack W
885 Vacant
886 Thompson A R
887 Schoenborn W E
888 Blackstone Edward H
Garlinghouse J S
888½ Howard ct begins
890 Churchill H P
891 Lassen Ida H Mrs
892 △ Calverley A S
893 △ Bowden John E
896 △ Attenborough Fred A
902 △ Scott Elmer S
903 △ Johnson F O
904 △ Blackburn Richard K
905 Rice Harry G
906 △ Truax Arthur J
907 △ Brown Davis D
908 △ Dalgleish Andrew
909 △ Kopkas James
910 Mather Charles F
911 Agent Charles
913 △ Johnson Henry E
915 Bowden Andrew F
917 △ Hult Ernest J
919 Liben Charles R
921 Snow Edwin L
923 △ Bjorklund Anton T
925 △ Bergston Nils R
927 △ Kibbe Clayton W
929 △ Corkburn P R plumber
930 St Mary's Cemetery
958 Ashwell Charles E
1016 Long Hill dr begins
1021 Smith W C gasoline
1023r Hayes A J auto repr
1028 △ Gorden James E
Vacant store
1069 Grisel William L
1075 Walnut st begins
1076 △ Bodey George W
1198 Bergren Arthur W
1200 Bergren John A
△ Bergren J A Dairy Inc
Woodland Farm Dairy
△ Hansen J F gasoline
— Mary st begins
Lata E B Mrs grocer
1120 △ Goba J J auto repr
Otis Frank M
Clifford Albert
Haraghey Patrick F
Stankevich Matthew
Connaver John M
Pierce Arthur H
Kolbus Alexander
Zukauskas Charles F
Vacant
Valentine Nicholas
— N Y N H & H RR crosses
△ Case Bros Inc paper mfrs
1500 Woodland Auto Painting Co
1550 Gartenhaus rest
Wimmer Alois
— Delmont rd begins
△ Redmer Albert A

Target Street	Cross Street	Source
✓	-	Price & Lee's City Directory

BURNSIDE AVE 1925

Burnside Ave., continued

303 Burnham, Edw. J.
303 Gibbons, Edw. P.
305 Heritage, Thomas
325 Ravalise, Michael
327 Damour, Louis J.
369 Baker, Donald J.
369 Root, Frank C.
375 Hoffman, William
375 Martin, John W.
377 Derrick, George S., Mrs.
377 Derrick, George S.
377 Merriman, Raymond F.
403 Hanson, Hans O.
413 Nungasser, Susan Mrs.
419 Hunt, Landon E.
423 Schwerdtfeger, Otto M.
425 Cronin, Joseph
427 Murphy, John A.
429 Lewis, Frederick T.
433 Mattesen, A. C.
433 Vanderburgh, Chas. M.
441 Brainerd, Clifton E.
445 Laffan, John
445 Stuart, Willard S.
447 Stowell, Henry
449 Koshefsky, Henry
449 Watt, David
453 Bevier, Benjamin
457 Trinks, Wm. H.
459 Lafferty, Leo B.
459 Zaikarite, August
461 Wright, Bert H.
463 Wright, Bert H.
465 Odenkirchen, Addison
467 Morin, Daniel
471 King, Robert C.
471 Weiman, Ebbie B.
473 Karalius, Charles
475 Trieschman, L. Geo.
475 Ulm, Frank
477 Fleming, William
483 Murphy, Lawrence A.
485 Britton, Reuben J.
485 Connor, Susan Mrs.
485 Driscoll, Wm. L.
485 Lockwood, Leslie H.
485 Lucy, L. Mrs.
485 Papillion, Geo. F.
501 Rockwell, Agnes Mrs.
503 Slater, ———
509 Eddy, A. Mrs.
511 Sorensen, Henry H. C.
513 Lyons, Wm.
517 McGuire, Anthony
519 Arrison, Paul W.
519 Twiss, George L.
523 Cheney, Watson
523 Tully, Owen
r523 Sullivan, Eugene D.
541 Flynn, John L.
541 Hollister, Horace T.
549 Osgood, Henry W.
551 Dresser, Wilfred C.
553 Flanagan, Francis J.
577 Cavanaugh, Mary Mrs.
585 Gosch, John
589 Johnson, Herbert A.
591 Johnson, Martin
593 Coleman, Daniel C.
597 Smith, Niels J.
601 Foley, William J.
613 Aitken, James E.
615 Revani, Lawrence
617 Morton, Hubert
619 McMullen, Herbert G.
621 Carleton, Dudley
623 Broucek, J.
629 Aitken, Alexander
629 Butlin, Howard E.
629 MacDonald, James A.
635 Clouden, Frank E.
637 Bjarkman, John
643 Harrison, Robert
643 Walker, Daniel Jr.
645 Generous, Arthur G.
673 Carnelli, Oscar
645 Winchell, Henry A.
647 Lauridsen, Soren
657 Tarascio, Anthony
711 Friedman, Fannie Mrs.
731 Cornwall, Francis
745 Olmsted, C. Henry
763 Goodwin, George
803 Onderdonk, H. Jay
805 Winther, Jens C.
873 Carter, Burton D.
881 Downs, Roy Y.
885 Gorris, Anna
885 Gorris, Victor
887 Mathiason, Chas. C.
893 Cannon, Clarence J.
905 Johnson, Frederick O.
907 Agent, Charles D.
907 Eccles, William F.
909 Dowden, Andrew
909 Dowden, Mary T. Mrs.
911 Hutt, Ernest J.
913 Schindler, Clinton G.
915 Thorngran, Carl E.
919 Bjorklund, A. T.
921 Bengtson, Neils B.
925 Dunne, Wm. T.
925 Dunne, Catherine E. Mrs.

12 Littlefield, Ambrose B.
18 Ledwith, Thos. J.
18 Nagle, Thomas F.
20 Condon, William J.
24 Curtin, David
24 Davieau, A. J.
24 Summers, Carrie, Mrs.
24 Summers, Frank
36 White, David C.
36 Walker, Elizabeth Mrs.
38 Pullon, Thomas
38 Smith, Anthony
44 Cooper, Emily
44 Cooper, Thomas
46 Enes, George Mrs.
50 Cunningham, Wm.
50 Shea, Elizabeth Mrs.
52 Post, Herbert
52 Post, Jeannette
52 Shuckerow, William
54 Paine, Wilbur V.
56 Quintal, Wilfred
58 Edwards, George L.
60 Bernard, Wm.
66 Miner, Annie C. Mrs.
74 Brown, Charles C.
74 Kiernan, Elizabeth, Mrs.
74 Kiernan, John F.
78 Chapin, E. C.
78 Hickey, Michael J.
78 Randall, Whitman B.
86 Brooks, Geo. E.
88 Doty, Geo.
90 Nemerow, Samuel
92 Austin, Elwin L.
94 Antos, Anthony F.
102 Bishop, Daniel
104 Kelcher, E. J.
114 Clune, Ellen A. Mrs.
114 Mulligan, Arthur J.
116 Sorokin, Louis
116 Falcone, Sam
124 Colpitts, Bessie G.
128 Scanlon, Michael
128 Whitaker, Anna
130 Gross, James L.
150 Rosenthal, Emil
170 Brennan, Margaret Mrs.
170 Brown, Joseph
170 Costello, Theresa
170 Shepherd, William
176 Fuller, Wm. H.
180 Battistoni, Joe
186 Sullivan, James
190 Landers, Maurice P.
194 Burnham, George D.
206a La Poll, Frank
208 Coulthard, William
222 Signor, Oswald J.
228 Delmore, Helen Mrs.
228 Delmore, Wayne
228 Shuckerow, Wm.
228 Tiemann, Herman
232 Elliot, H. B.
232 Fraise, A. H. Mrs.
232 Lagel, Charles
246 Banning, George G.
254 Waterhouse, Clarence A.
260 Styler, H. F.
262 Gallotti, Thomas
266 Miller, Gustave A.
270 Brown, Victor
274 Haselman, Alonzo W.
276 Rival, John
280 Cooper, Robert
284 Lewis, Wm. B.
290 Foley, John H.
290 West, Harold F.
298 Noble, Richard H.
300 Westbrook, George
318 Bidwell, Daniel D.
318 Bidwell, Samuel A.
376 McKinney, Amos H.
378 Lafferty, Edw.
382 Clarke, Emma R. Mrs.
386 Weakley, John P.
386 Ostrout, Louis J.
388 Canfield, Mitchell
390 O'Brien, Hugh J.
392 Griggs, Claude
394 Noonan, Walter F.
396 Quinn, Owen W.
398 Randall, Clayton C.
398 Randall, Clayton Mrs.
400 Hirn, John E.
402 Curtin, John G.
416 Tolisano, Tony
420 Becker, R. F.
424 Hyde, Fred W.
426 Foley, Alberta R.
426 Foley, William J.
428 Calnan, Catherine Mrs.
430 Chiarizia, Louis
430 Lo Vine, Fred'k H.
430 Tully, Thomas A.
438 Baker, Chas. C.
442 Hyde, Harold A.
444 Dooley, Patrick J.
448 Brown, Frank
448 Hahn, Henry O.
450 Hatfield, Owen J.
460 Phoenix, Wilfred
464 Rogers, Bertha Mrs.
478 Wind, Peter J.
480 Volz, Peter W.
484 Claflin, Chas. R.
484 Moran, Patrick F.
488 Green, Samuel W.
490 Spink, Thomas, Jr.
506 Chapman, William
508 Comstock, Charles H.
510 Fogil, Leon C.
510 Fogil, Leon C., Mrs.
512 Moore, Everett G.
512 Murphy, John R.
522 Foley, Edw. J.
524 Lord, Moreland E.
544 Gibson, James
554 Kilner, Sarah A. Mrs.
564 Bidwell, Lawrence E.
572 Stager, Mary A. Mrs.
596 Scanlon, John Jr.
598 Holland, John H.
598 Thrall, Frank N.
598 Thrall, Norman B.
602 Robinson, Albert
604 Williams, Lois P. Mrs.
604 Williams, Alfred
606 King, William
606 Pearce, Joseph
608 Day, Benj. F.
616 Willis, Edwin A.
688 Ludwig, Edward
688 Taddeo, Joseph
700 Fallon, George J.
712 Kaminsky, Benjamin
736 Beaupre, Wm. J.
726 Dunnack, W. H. Rev.
738 Meunier, Frank
754 Hanmer, Franklin H.
784 Barker, Charles L.
784 Barker, Harriet E. Mrs.
786 Larock, F. N.
788 Higbie, John R.
800 Hunter, Robert H.
802 Peck, Arthur N.
816 Reynolds, Kenneth J.
818 Scoery, Edward J.
820 Bartlett, Harry M.
822 MacDonald, R. W.
842 Cross, Thomas K.
844 Dannaher, Margaret J. Mrs
844 Waterhouse, Melville L.
846 Schindler, Henry J.
848 Erickson, Anders P.
854 Keeney, Ernest A.
858 Higbie, Wallace W.
860 Young, William A.
864 Reising, E. G.
874 Lawrence, James F.

APPENDIX J
Qualifications of Assessors

PRINCIPAL, REGIONAL MANAGER

JASON A. BEACH, NY PG, CPG, LEP

Mr. Beach has 24 years of progressive experience in the management of environmental, health, and safety projects, due diligence, remediation, engineering, solid waste management, TSCA, RCRA corrective action, hazardous building materials, and natural resources projects. He has led an array of projects in the public utility, municipal, state, commercial, and educational sectors, as well as countless due diligence and investigation assignments. Mr. Beach manages two offices in Connecticut with average gross revenues exceeding $10 million. Mr. Beach leads a team of skilled environmental professionals, which have grown to more than 50 individuals providing consulting expertise to clients throughout North America. Mr. Beach also provides consulting expertise and expert witness support to a myriad of private industry, manufacturing, legal, government, and financial/private equity clients throughout the east coast states. Notably, many of Mr. Beach's current clients include global utility companies, government agencies, attorneys, real estate managers and developers, and high-end manufacturers.

EXPERIENCE

Connecticut Judicial Branch Diesel Fuel Release, Stamford Courthouse, Stamford, CT
Served as Principal-in-Charge for the investigation and remediation of polluted soils that resulted from a diesel fuel spill from an above-ground storage tank associated with an emergency generator. Mr. Beach provided project leadership, client and stakeholder interfacing, coordination with environmental regulators, and ensured that the project had the necessary resources to be completed in a timely and cost-effective manner. Despite the emergency nature of the spill, Mr. Beach and the project team were able to complete the investigation and remediation activities in a manner that allowed the courthouse to remain open throughout the project. Services were completed in 2024.

Wesleyan University Central Power Plant Underground Storage Tank Closure, Middletown, CT
Served as Principal-in-Charge for the in-ground closure of two 30,000-gallon fuel oil underground storage tanks. Mr. Beach collaborated with the project team, university representatives, and other stakeholders to develop and implement a scope of work for the proper abandonment of the tank system. Services were completed in 2024.

Mercer Coal Towers and Bulk Fuel Storage Facility Remedial Investigation/Remedial Feasibility, Demolition, and Remediation, Stratford, CT
Served as Project Manager for the environmental assessment, abatement, demolition, and cleanup of a former rail-side bulk fuel and coal silo storage facility. The site was historically used to store various petroleum products in underground storage tanks and coal in a row of rail-side silos. The municipality acquired the property through tax foreclosure and plans to redevelop the site into a mixed-use commercial facility. Mr. Beach managed Phase I, Phase II, Phase III, QAPP, and hazardous building materials surveys of the site. The coal silos and other structures were demolished under Mr. Beach's supervision in 2015 and physical soil remediation of the site was completed in 2016. In 2021, Mr. Beach assisted the town with projecting future environmental tasks and associated costs in support of redeveloping the site into a more productive use.

EDUCATION

- Executive MBA, University of New Haven College of Business, 2017
- Graduate Studies,
- Environmental Geoscience, University of New Haven, 2004-2007
- BA, Geology, Hartwick College, 2001

PROFESSIONAL REGISTRATIONS/ CERTIFICATIONS

- Licensed Professional Geologist (New York), PG #000743-1, 2018 - Present
- Licensed Environmental Professional, LEP #512, CT, 2010 - Present
- Certified Professional Geologist, C.P.G. #11334, CT/US, 2010 - Present
- Connecticut Licensed Asbestos Consultant-Inspector, License #000544, CT, 2003 - Present

TRAINING

- OSHA 40HR Hazardous Waste Operations & Emergency Response (HAZWOPER),
- OSHA Annual 8HR HAZWOPER Refresher 2002 to Present, most recent refresher
- CPR – Adult Training Certificate Recognized by the American Red Cross
- Standard First Aid Training Certificate Recognized by the American Red Cross
- Asbestos Inspector 4HR Refresher
- Effective Supervision & Management Training, Quality Leadership Network
- Branch Office Optimization Course (2-days), PSMJ Associates, Boston, MA,
- Process Safety Management, OSHA (4-day course), Keene State University,

PROJECT MANAGER

CASSANDRA GEORGE

Cassandra George serves as Project Manager at HRP Associates, Inc. residing in the New York office. She is primarily responsible for overseeing projects associated with the EPA Brownfields program. Ms. George is experienced in performing Phase I and II Environmental Site Assessments and is a certified New York State Department of Conservation site monitor at Norlite in Cohoes, New York. Duties include acting as a liaison between clients, team members, and stake holders; writing Phase I Environmental Site Assessment reports; planning and scheduling field work; writing project proposals and preparing budgets; and performing report reviews.

EXPERIENCE

Safe Harbors of the Hudson Phase I Environmental Site Assessments, Newburgh, NY
Served as Associate Project Manager for a portfolio of Phase I Environmental Site Assessments that were performed for Safe Harbors of the Hudson. Responsibilities included oversight of staff completing the report, budgeting, and communication with the client.

EPA Grant Closeout Package
Served as Associate Project Manager for the EPA grant closeout package preparation completed for Mohawk Valley Economic Development Growth Enterprises. Responsibilities included preparation of a final technical report of the project and completion of financial and other project related required federal forms. Services were completed in 2024.

Assemblage Site Phase I Environmental Site Assessment, Troy, NY
Served as Associate Project Manager for the Phase I Environmental Site Assessment completed for the City of Troy. Responsibilities included site reconnaissance visit, review of historical documents, and preparation of a report. Services were completed in 2024.

Former Glory Days Phase I Environmental Site Assessment, Herkimer, NY
Served as Senior Project Consultant for the Phase I Environmental Site Assessment completed for the Herkimer County Industrial Development Agency. Responsibilities included site reconnaissance visit, review of historical documents, and preparation of a report. Services were completed in 2024.

Commerce Street Parcel Phase I Environmental Site Assessment, Ilion, NY
Served as Senior Project Consultant for the Phase I Environmental Site Assessment completed for the Herkimer County Industrial Development Agency. Responsibilities included site reconnaissance visit, review of historical documents, and preparation of a report. Services were completed in 2024.

Highland Avenue Parcel Phase I Environmental Site Assessment, Ilion, NY
Served as Senior Project Consultant for the Phase I Environmental Site Assessment completed for the Herkimer County Industrial Development Agency. Responsibilities included site reconnaissance visit, review of historical documents, and preparation of a report. Services were completed in 2024.

EDUCATION

- BS, Geology, University at Albany, 2007
- AS, Environmental Science, Hudson Community College, 2002

PROFESSIONAL CERTIFICATIONS

- Certified NYSDEC Monitor at Norlite, Cohoes, New York, August 2022
- Certified Professional in Erosion and Sediment Control-NY

TRAININGS

- 40-Hour OSHA HAZWOPER, July 2022
- American Heart Association First Aid/CPR/AED, September 2022

CONTINUING EDUCATION

- ITRC, Optimizing Injection Strategies and In-Situ Remediation Performance, September 2022

Remington Avenue Parcel Phase I Environmental Site Assessment, Ilion, NY
Served as Senior Project consultant for the Phase I Environmental Site Assessment completed for the Herkimer County Industrial Development Agency. Responsibilities included site reconnaissance visit, review of historical documents, and preparation of a report. Services were completed in 2024.

510-514 West Liberty Street Phase II Environmental Site Assessment, Rome, NY
Served as Project Consultant for the Phase II Environmental Site Assessment completed for the Mohawk Valley Economic Development Growth Enterprises at the 510-514 West Liberty Street site. Responsibilities included soil screening, logging, sampling, surveying wells, and Phase II report writing. Services were completed in 2023.

103-109 Whitesboro Street Phase I Environmental Site Assessment, Utica, NY
Served as Project Consultant for the Phase I Environmental Site Assessment completed for the Mohawk Valley Economic Development Growth Enterprises. Responsibilities included site reconnaissance visit, review of historical documents, and preparation of a report. Services were completed in 2023.

Seaway Gas Phase I Environmental Site Assessment, Sherrill, NY
Served as Project Consultant for the Phase I Environmental Site Assessment completed for the Mohawk Valley Economic Development Growth Enterprises. Responsibilities included site reconnaissance visit, review of historical documents, and preparation of a report. Services were completed in 2022.

Casa Imports Phase I Environmental Site Assessment, Utica, NY
Served as Project Consultant for the Phase I Environmental Site Assessment completed for the Mohawk Valley Economic Development Growth Enterprises. Responsibilities included site reconnaissance visit, review of historical documents, and preparation of a report. Services were completed in 2022.

Former Chip's Service Station Phase II Environmental Site Assessment, Frankfort, NY
Served as Project Consultant for the Phase II Environmental Site Assessment completed for the Herkimer County Industrial Development Agency at the Former Chip's Service Station site. Responsibilities included soil screening, logging, sampling, surveying wells, and Phase II report writing. Services were completed in 2022.

SENIOR CONSULTANT, ENVIRONMENTAL SCIENTIST

A. SASHA ISENBERG

A. Sasha Isenberg serves as a Senior Consultant in HRP Associates, Inc.'s Farmington, Connecticut office. Sasha has 14 years of experience in the environmental consulting industry. Her project experience includes environmental site assessments, subsurface investigations, site remediation, and environmental compliance. She has performed these services for a number of client sectors, including attorneys, municipal government, lending institutions, real estate development, manufacturing, and utilities. Ms. Isenberg served as the lead project scientist for the investigation and remediation of soils contaminated with petroleum products and chlorinated solvents. Ms. Isenberg's responsibilities included in-depth background research, identification of Areas of Concern, design and implementation of subsurface investigations, lateral and vertical delineation of contaminant impact to the soil and groundwater; design and implementation of localized soil remediation activities via excavation; project coordination, communications and reporting.

EXPERIENCE

Phase I Environmental Site Assessments

- Performance of Phase I Environmental Site Assessments in accordance with current ASTM Standards
- Data and Records Search
- Preparation of reports presenting information gathered with respect to current/historical site operations, environmental setting, and waste generation and handling
- Identification of recognized environmental conditions (RECs) and areas of concern (AOCs)
- Evaluation with respect to the Connecticut's Transfer Act

Phase II & III Subsurface Investigations

- Development of subsurface investigations to evaluate RECs and AOCs at sites based on contaminants of concern, release mechanisms, migration pathways, and exposure routes.
- Performance of field investigations using various drilling and soil sample collection technologies to evaluate site-specific constituents of concern (COCs) and subsurface conditions. Completing field forms (i.e., soil boring log, well construction logs, groundwater monitoring logs, etc). Soil gas sampling and data evaluation. Design, installation, and sampling of groundwater monitoring wells to evaluate hydrogeologic conditions and contaminant transport.
- Evaluation of potential receptors and exposure routes.
- Interpretation of subsurface conditions based on collected data, data analysis and evaluation. Preparation of technical reports detailing the fate and transport of contaminants through subsurface media. Evaluation of data for reclassification/delisting or continuation of site characterization.

Remedial Actions

- Experienced with sites subject to various federal and state programs including RCRA Corrective Action, Connecticut's Transfer Act, and Voluntary Remediation Programs
- Implementation of various remedial technologies based on the Conceptual Site Model including excavation and off-site disposal
- Underground Storage Tank Removal and Cleanups

EDUCATION

- Environmental Science with Concentration in Environmental Health, University of Connecticut, 2008

PROFESSIONAL ORGANIZATIONS

- Environmental Professionals' Organization of Connecticut, Member

TRAINING

- OSHA Hazardous Waste Operations and Emergency Response 8-hour Refresher
- RCRA Hazardous Waste Management
- OSHA 10-hour Construction Safety
- OSHA 40-hour Hazardous Waste Operations and Emergency Response

PROJECT CONSULTANT

JOY WATERS

Joy Waters is a Project Consultant at HRP Associates, Inc. in the Farmington, CT office, and has more than one year of experience in the environmental consulting industry. Joy graduated from Southern New Hampshire University in June 2024 with a bachelor's degree in Environmental Science with a concentration in Natural Resources and Conservation. Technical responsibilities include report writing, site inspections, remedial oversight, and general field work including groundwater sampling, soil sampling, and vapor sampling. Examples of project-specific work include writing Phase I, II and III Environmental Site Assessments, remedial oversight of contaminated sites, installation of monitoring wells and soil boring installation, groundwater monitoring, and soil vapor intrusion sampling.

EXPERIENCE

Pullman & Comley, LLC, Newington, CT, Phase I
Served as an associate consultant for the Phase I ESA of a commercial masonry property. Responsibilities included report writing, environmental database research, reviewing historical resources (aerials, Sanborn maps, topographic map, city directories), state and local agency document review, site reconnaissance, and identification of any Recognized Environmental Conditions (RECs) and Areas of Concern (AOCs). This Phase I ESA was completed in accordance with ASTM standards and Connecticut's Site Characterization Guidance Document. Services were completed in 2024.

Botero Property Management, Westport, CT, Phase I
Served as an associate consultant for the Phase I ESA of a commercial office property. Responsibilities included report writing, environmental database research, reviewing historical resources (aerials, Sanborn maps, topographic map, city directories), state and local agency document review, site reconnaissance, and identification of any Recognized Environmental Conditions (RECs) and Areas of Concern (AOCs). This Phase I ESA was completed in accordance with ASTM standards and Connecticut's Site Characterization Guidance Document. Services were completed in 2024.

NYSDEC Remediation Projects, New Rochelle, New York
Served as a project consultant for the environmental investigations related to a groundwater plume from a NYSDEC Superfund Site. Responsibilities included logging soil, installation of bedrock monitoring wells utilizing a sonic drill, well development and sampling. Services were conducted in 2024 and the project is ongoing.

Safe Harbors of the Hudson, Newburgh, NY, 2 Phase IIs
Served as an associate consultant author for 2 Phase II subsurface investigations in Newburgh, NY. Responsibilities included data analysis, summarization, and report writing. Services were completed in 2024.

Vine Properties, LLC, Southington, CT, Phase I
Served as a project consultant for the Phase I ESA of a furniture showroom and warehouse property. Responsibilities included report writing, environmental database research, reviewing historical resources (aerials, Sanborn maps, topographic map, city directories), state and local agency document review, site reconnaissance, and identification of any Recognized Environmental Conditions (RECs) and Areas of Concern (AOCs). This Phase I ESA was completed in accordance with ASTM standards and Connecticut's Site Characterization Guidance Document. Services were completed in 2025.

EDUCATION

- BS, Environmental Science, Southern New Hampshire University, 2024

TRAINING

- OSHA 40HR Hazardous Waste Operations & Emergency Response, July 2025
- OSHA 10-hour Construction, August 2023
- Resource Conservation and Recovery Act Waste Management, August 2024
- Amtrak Engineering Contractor Training, August 2023
- Metro-North Railroad Contractor Employee Safety Training, August 2023
- EPA Construction General Permit Site Inspector Training, September 2023
- USDOT Hazardous Materials Training, October 2023